```
{
  "typeOfReport": {
    "value": "Land_and_Building",
    "label": "Land and Building"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_
Enforcement_Of_Security_Interest_Act,_2002",
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And
Enforcement Of Security Interest Act, 2002"
  },
  "masterTypeOfPurpose": {
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_
Enforcement_Of_Security_Interest_Act,_2002",
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And
Enforcement Of Security Interest Act, 2002"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "646dc536b05e530fb6c47b3b"
    },
    "type": "CREDITOFFICER",
    "_id": "64cb7e0add0a6d4cc439286c",
    "firstName": "Pushpa",
    "lastName": "Potinde",
    "mobileNo": "",
    "workMobileNo": "9403511861",
    "email": "cs.ho@bankofbaroda.com"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
```

```
  "discussWithPerson": "",
  "expectedFees": null,
  "quotedAmount": "2950"
},
"organization": {
  "_id": "643a5bee108b68389ed736e5",
  "name": "Nashik Branch",
  "shortName": "NSK",
  "email": "nashik@vastukala.org",
  "address": "4, 1st Floor, Mashusha Elite, Vrundavan Naka Link Road, Adgaon, ",
  "city": "Nashik"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180c",
  "type": "BANK",
  "name": "Bank Of Baroda",
  "displayName": "Bank Of Baroda",
  "initial": "BOB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "646dc536b05e530fb6c47b3b",
  "name": "RO Nashik\t",
  "branchCode": "",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "email": "rlf.nasik@bankofbaroda.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "BSN Building, Data Mandir Road, Nashik Road, Nashik 422101\n"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "63fda060ce84bf289baace4c",
  "zoneName": "Nashik Zone"
},
"staff": {
```

```
    "pickupPerson": {
      "type": "EMPLOYEE",
      "_id": "63f9ed37ce84bf289ba991ac",
      "role": "FRONTDESK",
      "firstName": "Rushikesh",
      "email": "rushipingle2201@gmail.com",
      "lastName": "Pingle",
      "mobileNo": "8788210361",
      "shortName": "RUP",
      "workWithDocumentMaker": "",
      "profilePhoto": "users/63f9ed37ce84bf289ba991ac/
profilePhoto_1690263811066_image.jpeg"
    },
    "siteEngineer": {
      "type": "EMPLOYEE",
      "_id": "636a29b64d42487767af43ea",
      "role": "NASHIK (LEAD + VISIT + RATE)",
      "firstName": "Sachin",
      "email": "sachinraundal9021@gmail.com",
      "lastName": "Raundal",
      "mobileNo": "9021337843",
      "designation": "Site Engg",
      "shortName": "Sachin",
      "workWithDocumentMaker": "62724142afd7d55eddede405",
      "profilePhoto": "users/636a29b64d42487767af43ea/
profilePhoto_1688819202426_image.jpeg"
    },
    "rateVerifier": {
      "type": "EMPLOYEE",
      "_id": "636a1ad14d42487767af3f91",
      "role": "MAKER + RATE VERFIER",
      "firstName": "Chintamani",
      "email": "chintamanichaudhari099@gmail.com",
      "lastName": "Chaudhari",
      "mobileNo": "8007230780",
      "designation": "",
      "shortName": "Chintamani",
      "workWithDocumentMaker": "62724142afd7d55eddede405",
      "profilePhoto": "users/63f9ebf9ce84bf289ba990ff/
profilePhoto_1677323257433_Chintamani_Chaudhari_Photo_2.jpg"
    },
    "maker": {
      "type": "EMPLOYEE",
      "_id": "647ed1960ab64c23c9fcf71d",
      "role": "FRONTDESK",
      "firstName": "Rishidatt",
```

```
      "email": "rishiyadav44444@gamil.com",
      "lastName": "Yadav",
      "mobileNo": "9404341081",
      "designation": "",
      "shortName": "RV",
      "workWithDocumentMaker": ""
    },
    "checker": {
      "type": "EMPLOYEE",
      "_id": "64dc7184ccaf1e7b7f637f47",
      "role": "FRONTDESK",
      "firstName": "Binumon",
      "email": "binu@vastukala.org",
      "lastName": "Moozhickal",
      "mobileNo": "9930252906",
      "designation": "Back Office Team Leader",
      "shortName": "BS",
      "workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
      "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
    },
    "valuers": [
      {
        "valuersRegistrationNumber": [
          {
            "value": "[N]C.C.I.T/I -14/52/2008-09",
            "label": "Wealth Tax"
          }
        ],
        "type": "EMPLOYEE",
        "_id": "6084131a13f01f158c6ea1f3",
        "PANNo": "AEAPC7114Q",
        "role": "VALUER",
        "firstName": "Sharadkumar",
        "fatherName": "Baburao",
        "email": "cmd@vastukala.org",
        "lastName": " Chalikwar",
        "mobileNo": "9422171100",
        "designation": "CMD",
        "registrationNo": [
          {
            "title": {
              "value": "Wealth_Tax",
              "label": "Wealth Tax"
            },
            "_id": "6084131a13f01f158c6ea1f4",
```

```
            "number": "[N]C.C.I.T/I -14/52/2008-09"
          }
        ],
        "shortName": "SBC",
        "workWithDocumentMaker": "",
        "profilePhoto": "users\\6084131a13f01f158c6ea1f3\
\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
      }
    ]
  },
  "clientType": {
    "value": "BANK",
    "label": "BANK"
  },
  "location": {
    "latitude": "20.020778",
    "longitude": "73.742083"
  },
  "geo": {
    "type": "Point",
    "coordinates": [
      0,
      0
    ]
  },
  "siteVisit": {
    "siteVisitStatus": false,
    "schedule": [
      {
        "dateTime": "12/02/2024 05:03 pm"
      },
      {
        "dateTime": "12/02/2024 12:00 am"
      },
      {
        "dateTime": "12/02/2024 12:00 am"
      }
    ],
    "visitedDate": []
  },
  "marketAnalysisAndRemark": {
    "audioNotes": []
  },
  "externalReportDetails": {
    "finalAreaType": "Built_Up",
    "finalMeasurementType": "Sq. Ft.",
```

```
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Jalalpur",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "1",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": false,
    "name": "District",
    "key": "district",
    "value": "",
    "label": true
  },
  "city": {
```

```
    "status": true,
    "name": "City",
    "key": "city",
    "value": "Nashik",
    "label": false
  },
  "tahasilNo": {
    "status": false,
    "name": "Tahasil",
    "key": "tahasilNo",
    "value": "",
    "label": true
  },
  "taluka": {
    "status": false,
    "name": "Taluka",
    "key": "taluka",
    "value": "",
    "label": true
  },
  "plotNo": {
    "status": true,
    "name": "Plot No.",
    "key": "plotNo",
    "value": "27+ 28",
    "label": true
  },
  "buildingName": {
    "status": true,
    "name": "Building Name",
    "key": "buildingName",
    "value": "Goda Prestige ",
    "label": false
  },
  "selectArea": {
    "status": false,
    "name": "Sector",
    "key": "selectArea",
    "value": "",
    "label": true
  },
  "street1": {
    "status": false,
    "name": "Street 1",
    "key": "street1",
    "value": "",
```

```
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Near Hotel Madhuban",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "338/ 340/ 341",
  "label": true
},
"hissaNo": {
  "status": false,
```

```
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "102",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
```

```
  },
  "SRO": {
    "status": false,
    "name": "SRO",
    "key": "SRO",
    "value": "",
    "label": false
  },
  "policeStation": {
    "status": false,
    "name": "Police Station(P.S)",
    "key": "policeStation",
    "value": "",
    "label": false
  },
  "GUTNo": {
    "status": false,
    "name": "Gut No.",
    "key": "GUTNo",
    "value": "",
    "label": true
  },
  "postalCode": {
    "status": true,
    "name": "Postal Code",
    "key": "postalCode",
    "value": "422003",
    "label": false
  },
  "suburb": {
    "status": false,
    "name": "Suburb",
    "key": "suburb",
    "value": "",
    "label": false
  }
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
```

```
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
```

```
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
```

```
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
    "isHideFloor": true,
    "status": true
  }
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
```

```
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
```

```
    "potentialValue": {
      "title": "Potential value, if any",
      "quantity": "0.00",
      "ratePerUnit": "0.00",
      "estimatedValue": "0.00",
      "status": true,
      "isEditable": true
    },
    "others": {
      "title": "Others / Car Parking",
      "quantity": "0.00",
      "ratePerUnit": "0.00",
      "estimatedValue": "0.00",
      "status": true,
      "isEditable": true
    },
    "totalValues": {
      "title": "Total",
      "quantity": "",
      "ratePerUnit": "",
      "estimatedValue": "0.00",
      "status": true,
      "isEditable": false
    }
  },
  "taskStatus": {
    "SITE_INSPECTION": false,
    "RATE_VERIFY": false,
    "MAKER": false,
    "CHECKER": false,
    "PREPARE_INVOICE": false,
    "PRINT": false,
    "SIGN": false,
    "SIGNED_REPORT_UPLOAD": false,
    "DELIVERY": false,
    "PAYMENT_COLLECT": false,
    "COMPLETED": false
  },
  "createCase": "true",
  "type": "CASE",
  "leadType": {
    "label": "Lead",
    "value": "LEAD"
  },
  "siteVisitType": "FULL",
  "isSiteMeasurementAllowed": true,
```

```
  "finalValuationArea": "0",
  "empanelmentNo": [],
  "isAdvanceInvoice": false,
  "status": true,
  "caseStatus": "REMAININGSITEVISIT",
  "invoices": [],
  "paymentId": [],
  "_id": "65ca03a4d93fe4510d4c1463",
  "ownerName": "Shri. Bharat Sambhaji Ingole &                    Sau. Rekha
Bharat Ingole",
  "ownerPhoneNo": "9011663889",
  "ownershipShare": "",
  "email": "",
  "siteVisitContactNo": "9011663889",
  "contactPersonName": "Shri. Bharat Sambhaji Ingole &                    Sau.
Rekha Bharat Ingole",
  "purchaseValueAsPerDocument": "1550000",
  "owners": [
    {
      "name": "Shri. Bharat Sambhaji Ingole &                    Sau. Rekha
Bharat Ingole",
      "phone": "9011663889",
      "ownershipShare": "",
      "email": "",
      "id": "288697"
    }
  ],
  "caseReferredBy": "643a91f233d16f6b1237a4ee",
  "relationWithOwner": "self",
  "fullAddress": "Residential Land and Building No. 102, 1st Floor, Goda Prestige , Near
Hotel Madhuban, Plot No. 27+ 28, New/Current Survey No. 338/ 340/ 341, Village -
Jalalpur, Nashik, 422003, State - Maharashtra, India",
  "remark": "",
  "documents": [
    {
      "documentType": {
        "value": "60ae12adaa6d152c1801b4bf",
        "label": "Notarized Agreement for Sale"
      },
      "inputs": {
        "documentDate": "08/02/2024",
        "amount": "1550000",
        "from": {
          "value": "Owner",
          "label": "Owner"
        },
```

```
        "Owner": "Shri. Atul Bhausaheb Kale &  Shri. Shashikant Vaman Khule",
        "to": {
          "value": "purchaser",
          "label": "purchaser"
        },
        "purchaser": "Shri. Bharat Sambhaji Ingole &  Sau. Rekha Bharat Ingole"
      },
      "isHardCopy": false,
      "displayStatus": false,
      "fileName": "document_1707737740330_FIVE_HUNDRED.pdf",
      "path": "cases/65ca03a4d93fe4510d4c1463/
document_1707737740330_FIVE_HUNDRED.pdf",
      "id": "497108",
      "uploadedBy": "63f9ed37ce84bf289ba991ac",
      "createdAt": "Mon Feb 12 2024 17:10:20 GMT+0530 (India Standard Time)"
    },
    {
      "documentType": {
        "value": "60ae124baa6d152c1801b2fd",
        "label": "Occupancy Certificate"
      },
      "inputs": {
        "documentDate": "05/02/2024",
        "number": {
          "value": "Document_No",
          "label": "Document No"
        },
        "Document_No": "239853 "
      },
      "isHardCopy": false,
      "displayStatus": false,
      "fileName": "document_1707737779696_COMPLETION_01.pdf",
      "path": "cases/65ca03a4d93fe4510d4c1463/
document_1707737779696_COMPLETION_01.pdf",
      "id": "732554",
      "uploadedBy": "63f9ed37ce84bf289ba991ac",
      "createdAt": "Mon Feb 12 2024 17:10:20 GMT+0530 (India Standard Time)"
    },
    {
      "documentType": {
        "value": "60ae1277aa6d152c1801b3cc",
        "label": "Approved Building Plan"
      },
      "inputs": {
        "documentDate": "30/09/2022",
        "number": {
```

```
          "value": "Document_No",
          "label": "Document No"
        },
        "Document_No": "235"
      },
      "isHardCopy": false,
      "displayStatus": false,
      "fileName": "document_1707737896180_152531.pdf",
      "path": "cases/65ca03a4d93fe4510d4c1463/
document_1707737896180_152531.pdf",
      "id": "398861",
      "uploadedBy": "63f9ed37ce84bf289ba991ac",
      "createdAt": "Mon Feb 12 2024 17:10:20 GMT+0530 (India Standard Time)"
    },
    {
      "documentType": {
        "value": "60ae12a0aa6d152c1801b483",
        "label": "site Details"
      },
      "isHardCopy": false,
      "displayStatus": false,
      "fileName": "document_1707738274105_103904.pdf",
      "path": "cases/65ca03a4d93fe4510d4c1463/
document_1707738274105_103904.pdf",
      "id": "707205",
      "uploadedBy": "63f9ed37ce84bf289ba991ac",
      "createdAt": "Mon Feb 12 2024 17:14:34 GMT+0530 (India Standard Time)"
    }
  ],
  "isUrgent": "false",
  "isExternal": "false",
  "proposePurchaserName": "",
  "assignmentType": {
    "value": "Commercial",
    "label": "Commercial"
  },
  "scheduleSiteVisitDate": "Invalid date",
  "caseNumber": "006913",
  "createdBy": "63f9ed37ce84bf289ba991ac",
  "caseHistory": [
    {
      "id": "441689",
      "title": "Create Case",
      "description": "Create Case",
      "datetime": "Mon Feb 12 2024 17:10:20 GMT+0530 (India Standard Time)"
    }
```

```
  ],
  "proposePurchasers": [],
  "siteInspection": [],
  "composition": [],
  "otherComposition": [],
  "externalReport": [],
  "documentPerArea": [],
  "images": [],
  "indicatorArr": [],
  "externalImages": [],
  "externalDocuments": [],
  "processingDocuments": [],
  "leadRemarks": [],
  "audioRemarks": [],
  "remarks": [],
  "createdAt": "2024-02-12T11:40:20.993Z",
  "updatedAt": "2024-02-12T11:44:34.279Z",
  "__v": 0,
  "addressForMap": "",
  "updatedBy": "63f9ed37ce84bf289ba991ac"
}
```


Name	Length	Width	Total
Composition :			
Other Composition :			