

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7f7"
    },
    "type": "CREDITOFFICER",
    "_id": "63fd9434ce84bf289baab0e9",
    "firstName": "Sharmila",
    "lastName": "Mahto",
    "mobileNo": "",
    "workMobileNo": "9521405151",
    "email": "sharmila.mahto@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "5000000",
    "discussWithPerson": "Sharmila",
    "expectedFees": 2500,
    "quotedAmount": "2500"
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7f7",
  "branchCode": "000064",
  "type": "BRANCH",
  "name": "RACPC Ghatkopar (West)",
  "email": "racpcghatkopar.sanctions@sbi.co.in",
  "mobileNo": "022-25009143",
  "alternateMobileNo": "",
  "address": "Retail Assets Centralised Processing Centre, 1st Floor, Ashok Silk Mills
Compound, LBS Marg, Ghatkopar (West), Mumbai - 400 086, State - Maharashtra,
Country - India.\r\n\r\n\r\n\r\n",
  "ledgerName": "STATE BANK OF INDIA - RACPC GHATKOPAR",
  "fax": "022-25009010",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "60b7177d2ffdf65bcd65882a",
  "role": "PICKUPPERSON",
  "firstName": "Saurabh",
  "email": "saurabhvelonde143@gmail.com",
  "lastName": "Velonde",
  "mobileNo": "8691048846",
  "shortName": "SSV",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1686816492317_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "63fc4680ce84bf289ba9c7fc",
  "role": "SITEENGINEER",
  "firstName": "Nikhil ",
  "email": "valtechnical2022@gmail.com",
  "lastName": "Sonawane",
  "mobileNo": "9819470709",
  "designation": "",
  "shortName": "NS",
  "workWithDocumentMaker": "6006d4ce5080a310ac1fdfc2",
  "profilePhoto": "users/63fc4680ce84bf289ba9c7fc/
profilePhoto_1681380664371_WhatsApp_Image_20230413_at_33801_PM.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "64cde526dc9f3034f3fefa49",
  "role": "FRONTDESK",
  "firstName": "Rashmi",
  "email": "rashmijadhav14feb@gmail.com",
  "lastName": "Jadhav",
  "mobileNo": "7738144625",
  "designation": "Back Office Coordinatiion",
  "shortName": "RJ",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "62fe044a48a26047e6552796",
  "role": "MAKER",
  "firstName": "Pradnya ",
```

```
"email": "pradnya@vastukala.org",
"lastName": "Rasam",
"mobileNo": "9529385821",
"designation": "",
"shortName": "PR",
"workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
"profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "64cde526dc9f3034f3fefa49",
  "role": "FRONTDESK",
  "firstName": "Rashmi",
  "email": "rashmijadhav14feb@gmail.com",
  "lastName": "Jadhav",
  "mobileNo": "7738144625",
  "designation": "Back Office Coordination",
  "shortName": "RJ",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ]
  }
]
```

```
    },
    {
      "title": {
        "value": "FIIV",
        "label": "FIIV"
      },
      "_id": "60af80072ffdf65bcd658652",
      "number": "CAT-I-F-1763"
    },
    {
      "title": {
        "value": "Chartered_Engineer",
        "label": "Chartered Engineer"
      },
      "_id": "60af80072ffdf65bcd658653",
      "number": "AM161706-3"
    },
    {
      "title": {
        "value": "Registered_Valuer",
        "label": "Registered Valuer"
      },
      "_id": "60af80072ffdf65bcd658654",
      "number": "IBBI/RV/07/2018/10366"
    }
  ],
  "shortName": "MBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
  "PANNo": "AERPC9086P",
  "fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.248265462751853",
  "longitude": "73.15157592857162"
},
"geo": {
  "type": "Point",
  "coordinates": [
```

```
73.15157592857162,
19.248265462751853
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "13/02/2024 01:28 pm"
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-02-13",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "2BHK",
  "label": "2 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "Country - India",
    "label": false
  },
},
```

```
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Gauripada ",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "7",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "B1, Opal ",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane ",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Kalyan (West)",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
```

```
"value": "Kalyan",
"label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Yogidham B-1 Opal Co-Op. Hsg. Soc. Ltd. ",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Opp KDMT Bus Depot",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Murbad Road",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
```



```
"status": false,
"name": "Wing",
"key": "wing",
"value": "",
"label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Yogi Dham Phase - III",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "22, 24, 25, 26 & Hissa No. 1,2,3,4, 5, 6, 8",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
```

```
"label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "702",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
```

```
"name": "Gut No.",
"key": "GUTNo",
"value": "",
"label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 421 301",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows_with_M._S._Grills",
    "label": "Powder coated Aluminum sliding windows with M. S. Grills"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering_+_POP_Finish",
    "label": "Cement Plastering + POP Finish"
  }
}
```

```
},
"general": {
  "ownership": {
    "value": "Sole_Ownership",
    "label": "Sole Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "Kalyan_Dombivali_Municipal_Corporation",
    "label": "Kalyan Dombivali Municipal Corporation"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Open Plot ",
    "west": "Internal Road ",
    "south": "Onxy Building ",
    "east": "Internal Road "
  },
  "asPerDocumentAgreement": {
    "north": "Details not available ",
    "west": "Details not available ",
    "south": "Details not available ",
    "east": "Details not available "
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "Details not available ",
      "east": "Details not available ",
      "south": "Details not available ",
      "west": "Details not available "
    },
    "asPerDocument": {
      "north": "Details not available ",
      "east": "Details not available ",
      "south": "Details not available ",
      "west": "Details not available "
    }
  }
}
```

```
    },
    "isDisplay": false,
    "title": "Boundaries of The Flat"
  },
  "extraDetailOfProperty": "",
  "dateOfIssusApprovePlan": "As Part Building Completion Certificate is available it
may be assumed that the construction is as per Sanctioned Plan.\n",
  "approvePlanVerified": "N.A",
  "empanelledOfApprovePlan": "N.A",
  "unauthorizedConstruction": ""
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "16.5",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "buildingServicesDepreciatedRate": "412.5",
  "depreciatedCostOfConstruction": "10087.50",
  "depreciatedBuildingRate": "2087.5"
},
"igrRate": {
  "propertyName": "Residential Flat",
  "rate": "72900",
  "landRate": "20400",
  "igrImage": "cases/65cb19dcd93fe4510d4d786d/igr_1707976097145_Image.png",
  "squareMeterGuideLineRate": "76545.00",
  "squareFeetGuideLineRate": "7111.00"
},
"igrFinalRate": {
  "floorRatePercentage": "5",
  "depreciationPercentage": "89",
  "rate": "6538.00",
  "squareFeetGuideLineRate": "6538.00",
  "squareMeterGuideLineRate": "70369.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Owner_Occupied",
```

```
"label": "Owner Occupied"
},
"monthlyRent": "N.A",
"assessmentNo": "Details not available ",
"taxPaidHolderName": "Details not available ",
"taxAmount": "Details not available ",
"electricityServiceConnectionNo": "Details not available ",
"meterCardHolderName": "Details not available ",
"undividedAreaOfLandAsPerSaleDeed": "Details not available ",
"floorSpaceIndex": "As per VVCMC norms ",
"tenantName": "",
"maintenanceOfFlat": "Good "
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area ",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Stilt Car Parking Space ",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  }
}
```

```
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2013",
  "fullDate": "1/1/2013"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
}
```

```
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenanceIssues": {
  "value": "1",
  "label": "Yes"
},
"visibleDamageInBuilding": {
  "value": "1",
  "label": "Yes"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "stilt",
  "label": "Stilt"
},
"yearOfConstructionAsPer": {
  "value": "Part_Building_Completion_Certificate",
  "label": "Part Building Completion Certificate"
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "11",
"totalLifeBuilding": "60",
"estimatedAge": "49",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "19",
"flatFloorNo": "7",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "5"
},
"finalPlinthArea": {
```



```
"area": "723.40",
"measurementType": "Sq. Ft.",
"areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/65cb19dcd93fe4510d4d786d/
routeMap_1707975617856_Image.png",
    "routeLat": "19.247775",
    "routeLng": "73.151540",
    "stationName": "Shahad ",
    "routeDistance": "1.9 Km. "
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "l60h19",
      "name": "l60h19",
      "image": "cases/65cb19dcd93fe4510d4d786d/
routeMap_1707975113150_Image.png"
    }
  ]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
```

```
"totalKitchenArrangementsRate": "0",
"superfineFinishQty": "0",
"superfineFinishRate": "0",
"totalSuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalInteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalElectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalExtraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalPotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalOthersRate": "0",
"finalTotal": "6910280.00",
"finalValue": "6910280.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValueDocument": null,
"purchaseValueDocument": null,
"bookValue": "0"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Thu Feb 15 2024 12:49:42 GMT+0530 (India Standard Time)",
  "number": "2304982",
  "dayCount": "2",
  "monthCount": "204",
  "generatedBy": "64cde526dc9f3034f3fefa49"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  }
}
```

```
},
"rccPlinth": {
  "label": "RCC Plinth",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
>window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
```

```
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "5374236.00",
  "selectedBuildUpValue": "822.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "65cca9d4d93fe4510d4fe868",
      "name":
"externalImg_1707911636749_WhatsApp_Image_20240214_at_114140_AM.jpeg",
      "path": "cases/65cb19dcd93fe4510d4d786d/
externalImg_1707911636749_WhatsApp_Image_20240214_at_114140_AM.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": [
    {
      "status": false,
```

```
    "_id": "65cca9d4d93fe4510d4fe867",
    "name": "Living Room",
    "path": "cases/65cb19dcd93fe4510d4d786d/
externallmg_1707911636744_WhatsApp_Image_20240214_at_114140_AM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "65cca9d4d93fe4510d4fe86c",
    "name": "Living Room",
    "path": "cases/65cb19dcd93fe4510d4d786d/
externallmg_1707911636781_WhatsApp_Image_20240214_at_114142_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65cca9d4d93fe4510d4fe86d",
    "name": "Living Room",
    "path": "cases/65cb19dcd93fe4510d4d786d/
externallmg_1707911636785_WhatsApp_Image_20240214_at_114142_AM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65cca9ded93fe4510d4fe89a",
    "name": "Living Room",
    "path": "cases/65cb19dcd93fe4510d4d786d/
externallmg_1707911646672_WhatsApp_Image_20240214_at_114143_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65cca9ded93fe4510d4fe89b",
    "name": "Living Room",
    "path": "cases/65cb19dcd93fe4510d4d786d/
externallmg_1707911646675_WhatsApp_Image_20240214_at_114144_AM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "65cca9ded93fe4510d4fe899",
    "name": "Living Room",
    "path": "cases/65cb19dcd93fe4510d4d786d/
externallmg_1707911646668_WhatsApp_Image_20240214_at_114143_AM_2.jpeg",
    "orientation": "portrait"
  },
}
```

```
{
  "status": false,
  "_id": "65cca9ded93fe4510d4fe89f",
  "name": "Living Room",
  "path": "cases/65cb19dcd93fe4510d4d786d/
externallmg_1707911646686_WhatsApp_Image_20240214_at_114145_AM.jpeg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "65cca9d4d93fe4510d4fe868",
  "name": "Living Room",
  "path": "cases/65cb19dcd93fe4510d4d786d/
externallmg_1707911636749_WhatsApp_Image_20240214_at_114140_AM.jpeg",
  "orientation": "portrait"
}
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "10236",
    "max": "12429"
  },
  "builtUpRateRange": {
    "min": "8531",
    "max": "10358"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
```

```
"title": "Showcases",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```



```
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
```

```
"isSiteMeasurementAllowed": true,
"finalValuationArea": "685.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3",
  "SME/TCC/221/13"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"invoices": [],
"paymentId": [],
"_id": "65cb19dcd93fe4510d4d786d",
"ownerName": "Mr. Narendra K. Verma",
"ownerPhoneNo": "9920357439",
"appAddress": "Flat no. 702, 7th Floor, Wing - B1, Opal, Yogidham, Gauripada, Kalyan West",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "13/01/2011",
      "from": {
        "value": "Seller",
        "label": "Seller"
      },
      "Seller": "M/s. Yogi Developers Corporation ",
      "to": {
        "value": "Purchaser",
        "label": "Purchaser"
      },
      "Purchaser": "Mr. Narendra K. Verma",
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "896 / 2011"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "356022",
    "path": "cases/65cb19dcd93fe4510d4d786d/document_1707809178539_1707809324141_Racpc_GHatkopar_Narendra_Verma.pdf",
```

```
"fileName": "document_1707809178539_1707809324141_Racpc_GHatkopar_Nare  
ndra_Verma.pdf"  
},  
{  
  "documentType": {  
    "value": "60ae12a8aa6d152c1801b4a8",  
    "label": "Part Building Completion Certificate"  
  },  
  "inputs": {  
    "documentDate": "31/05/2013",  
    "nameOfApprovingAuthority": {  
      "value": "Kalyan_Dombivli_Municipal_Corporation",  
      "label": "Kalyan Dombivli Municipal Corporation"  
    },  
    "number": {  
      "value": "Document_No",  
      "label": "Document No"  
    },  
    "Document_No": "KDMC / NRV / CC / KV / 69"  
  },  
  "isHardCopy": false,  
  "displayStatus": false,  
  "fileName": "document_1707969863056_606138.pdf",  
  "path": "cases/65cb19dcd93fe4510d4d786d/  
document_1707969863056_606138.pdf",  
  "id": "432643",  
  "uploadedBy": "62fe044a48a26047e6552796",  
  "createdAt": "Thu Feb 15 2024 09:34:23 GMT+0530 (India Standard Time)"  
},  
{  
  "documentType": {  
    "value": "60ae126aaa6d152c1801b38b",  
    "label": "Property Tax Bill"  
  },  
  "inputs": {  
    "documentDate": "01/05/2023",  
    "nameOfApprovingAuthority": {  
      "value": "Kalyan_Dombivli_Municipal_Corporation",  
      "label": "Kalyan Dombivli Municipal Corporation"  
    },  
    "to": {  
      "value": "Purchaser",  
      "label": "Purchaser"  
    },  
    "Purchaser": "Mr. Narendra K. Verma",  
    "number": {
```

```
    "value": "property_no",
    "label": "property no"
  },
  "property_no": "B05014967900"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1707969976690_787659.pdf",
"path": "cases/65cb19dcd93fe4510d4d786d/
document_1707969976690_787659.pdf",
"id": "398674",
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Thu Feb 15 2024 09:36:16 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "6077c791395bc80714864a30",
    "label": "Electricity Bill"
  },
  "inputs": {
    "number": {
      "value": "Consumer_No",
      "label": "Consumer No"
    },
    "Consumer_No": "020260340795 dated 17.01.2024 in the name of Mr. Narendra
K. Verma issued by MSEDCL"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "id": "484974",
  "path": "cases/65cb19dcd93fe4510d4d786d/
document_1707970064832_1082594.pdf",
  "fileName": "document_1707970064832_1082594.pdf"
}
],
"caseNumber": "006941",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "687607",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Feb 13 2024 12:57:24 GMT+0530 (India Standard Time)"
  }
],
"owners": [
```

```
{
  "name": "Mr. Narendra K. Verma",
  "phone": "9920357439",
  "ownershipShare": "",
  "email": "",
  "id": "955703"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "574478",
    "name": "Living Room",
    "length": "10.00",
    "length1": "10",
    "length2": "00",
    "width": "18.00",
    "width1": "18",
    "width2": "00",
    "totalArea": "180.00",
    "images": [],
    "extraAreas": [],
    "finalArea": "180.00"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "7",
    "name": "Bedroom",
    "length": "9.42",
    "length1": "9",
    "length2": "5",
    "width": "12.50",
    "width1": "12",
    "width2": "6",
    "totalArea": "117.71",
    "images": [],
    "finalArea": "117.71",
    "extraAreas": []
  }
]
```

```
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Bedroom",
  "length": "9.67",
  "length1": "9",
  "length2": "8",
  "width": "11.42",
  "width1": "11",
  "width2": "5",
  "totalArea": "110.36",
  "images": [],
  "extraAreas": [],
  "finalArea": "110.36"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Kitchen",
  "length": "9.00",
  "length1": "9",
  "length2": "00",
  "width": "7.50",
  "width1": "7",
  "width2": "6",
  "totalArea": "67.50",
  "images": [],
  "extraAreas": [],
  "finalArea": "67.50"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Toilet",
  "length": "7.00",
  "length1": "7",
```

```
"length2": "00",
"width": "4.25",
"width1": "4",
"width2": "3",
"totalArea": "29.75",
"images": [],
"extraAreas": [],
"finalArea": "29.75"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Toilet",
  "length": "7.00",
  "length1": "7",
  "length2": "00",
  "width": "4.50",
  "width1": "4",
  "width2": "6",
  "totalArea": "31.50",
  "images": [],
  "extraAreas": [],
  "finalArea": "31.50"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Passage",
  "length": "3.17",
  "length1": "3",
  "length2": "2",
  "width": "7.00",
  "width1": "7",
  "width2": "00",
  "totalArea": "22.17",
  "images": [],
  "extraAreas": [
    {
      "measurementType": {
        "value": "Square_Feet",
```

```
    "label": "Square Feet"
  },
  "_id": "65cd9cc3d93fe4510d505723",
  "name": "Extra ",
  "extraAreaType": "Add",
  "length": "3.42",
  "length1": "3",
  "length2": "5",
  "width": "10.25",
  "width1": "10",
  "width2": "3",
  "totalArea": "35.02"
}
],
"finalArea": "57.190000000000005"
}
],
"otherComposition": [
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Cupboard",
    "value": "Cupboard"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "0",
  "length": "7.58",
  "length1": "7",
  "length2": "7",
  "width": "2.00",
  "width1": "2",
  "width2": "00",
  "totalArea": "15.17",
  "images": [],
  "extraAreas": [
    {
      "measurementType": {
        "value": "Square_Feet",
        "label": "Square Feet"
      },
    }
  ],
}
```



```
    "_id": "65cd9d08d93fe4510d505879",
    "name": "Extra ",
    "extraAreaType": "Add",
    "length": "2.00",
    "length1": "2",
    "length2": "00",
    "width": "4.67",
    "width1": "4",
    "width2": "8",
    "totalArea": "9.33"
  }
],
"finalArea": "24.5",
"percentageBeforeTotal": "24.50",
"percentage": "100"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Flower Bed Area",
    "value": "Flower_Bed_Area"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "length": "7.42",
  "length1": "7",
  "length2": "5",
  "width": "2.08",
  "width1": "2",
  "width2": "1",
  "totalArea": "15.45",
  "images": [],
  "extraAreas": [],
  "finalArea": "15.45",
  "percentageBeforeTotal": "15.45",
  "percentage": "100"
},
{
  "toBeAdded": {
    "label": "Carpet",
```

```
"value": "Carpet"
},
"name": {
  "label": "Dry Balcony Area",
  "value": "Dry_Balcony_Area"
},
"measurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"length": "4.58",
"length1": "4",
"length2": "7",
"width": "5.17",
"width1": "5",
"width2": "2",
"totalArea": "23.68",
"images": [],
"extraAreas": [],
"finalArea": "23.68",
"percentageBeforeTotal": "23.68",
"percentage": "100"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Balcony Area",
    "value": "Balcony_Area"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "length": "10.00",
  "length1": "10",
  "length2": "00",
  "width": "4.58",
  "width1": "4",
  "width2": "7",
  "totalArea": "45.83",
  "images": [],
```

```
"extraAreas": [],
"finalArea": "45.83",
"percentageBeforeTotal": "45.83",
"percentage": "100"
}
],
"externalReport": [],
"documentPerArea": [
{
"typeOfDocument": {
"value": "60af48bf2ffdf65bcd6585fa",
"label": "Agreement for sale"
},
"docMeasurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
"id": "384392",
"selectAreaTypeDocument": "Carpet",
"totalAreaDocument": "685",
"squareMeterArea": "63.64",
"docFinalBuiltUp": "822",
"docFinalBuiltUpSquareMeter": "76.368",
"docBuiltupPercentage": "20",
"docSaleablePercentage": "0",
"docFinalSaleable": "0",
"docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
{
"printlnReport": true,
"_id": "65cda5c4d93fe4510d507a15",
"property": "Residential Flat",
"area": "460",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"source": "Nobroker.com",
"expectedPrice": "5051000",
"expectedRate": "10980.43",
"builtUpExpectedRate": "9150.36",
"image": "cases/65cb19dcd93fe4510d4d786d/
indicator_1707975866950_Image.png",
```

```
"squareMeter": "42.74",
"id": "160002"
},
{
  "printlnReport": true,
  "_id": "65cda5c4d93fe4510d507a16",
  "property": "Residential Flat",
  "area": "700",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "Nobroker.com",
  "expectedPrice": "8700000",
  "expectedRate": "12428.57",
  "builtUpExpectedRate": "10357.14",
  "image": "cases/65cb19dcd93fe4510d4d786d/
indicator_1707975907315_Image.png",
  "squareMeter": "65.03",
  "id": "600665"
},
{
  "printlnReport": true,
  "_id": "65cda5c4d93fe4510d507a17",
  "property": "Residential Flat",
  "area": "635",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "source": "Index_no.2",
  "expectedPrice": "6500000",
  "expectedRate": "10236.22",
  "builtUpExpectedRate": "8530.18",
  "image": "cases/65cb19dcd93fe4510d4d786d/
indicator_1707975945006_Image.png",
  "squareMeter": "58.99",
  "id": "701259"
}
],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65cca9d4d93fe4510d4fe864",
    "name":
"externallmg_1707911636723_WhatsApp_Image_20240214_at_114139_AM_1.jpeg",
```

```
    "path": "cases/65cb19dcd93fe4510d4d786d/
externallmg_1707911636723_WhatsApp_Image_20240214_at_114139_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65cca9d4d93fe4510d4fe865",
    "name":
"externallmg_1707911636730_WhatsApp_Image_20240214_at_114139_AM.jpeg",
    "path": "cases/65cb19dcd93fe4510d4d786d/
externallmg_1707911636730_WhatsApp_Image_20240214_at_114139_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65cca9d4d93fe4510d4fe866",
    "name":
"externallmg_1707911636739_WhatsApp_Image_20240214_at_114140_AM_1.jpeg",
    "path": "cases/65cb19dcd93fe4510d4d786d/
externallmg_1707911636739_WhatsApp_Image_20240214_at_114140_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65cca9d4d93fe4510d4fe867",
    "name":
"externallmg_1707911636744_WhatsApp_Image_20240214_at_114140_AM_2.jpeg",
    "path": "cases/65cb19dcd93fe4510d4d786d/
externallmg_1707911636744_WhatsApp_Image_20240214_at_114140_AM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65cca9d4d93fe4510d4fe868",
    "name":
"externallmg_1707911636749_WhatsApp_Image_20240214_at_114140_AM.jpeg",
    "path": "cases/65cb19dcd93fe4510d4d786d/
externallmg_1707911636749_WhatsApp_Image_20240214_at_114140_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "65cca9d4d93fe4510d4fe869",
  "name":
"externallmg_1707911636766_WhatsApp_Image_20240214_at_114141_AM_1.jpeg",
  "path": "cases/65cb19dcd93fe4510d4d786d/
externallmg_1707911636766_WhatsApp_Image_20240214_at_114141_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65cca9d4d93fe4510d4fe86a",
  "name":
"externallmg_1707911636772_WhatsApp_Image_20240214_at_114141_AM_2.jpeg",
  "path": "cases/65cb19dcd93fe4510d4d786d/
externallmg_1707911636772_WhatsApp_Image_20240214_at_114141_AM_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65cca9d4d93fe4510d4fe86b",
  "name":
"externallmg_1707911636776_WhatsApp_Image_20240214_at_114141_AM.jpeg",
  "path": "cases/65cb19dcd93fe4510d4d786d/
externallmg_1707911636776_WhatsApp_Image_20240214_at_114141_AM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65cca9d4d93fe4510d4fe86c",
  "name":
"externallmg_1707911636781_WhatsApp_Image_20240214_at_114142_AM_1.jpeg",
  "path": "cases/65cb19dcd93fe4510d4d786d/
externallmg_1707911636781_WhatsApp_Image_20240214_at_114142_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65cca9d4d93fe4510d4fe86d",
  "name":
"externallmg_1707911636785_WhatsApp_Image_20240214_at_114142_AM_2.jpeg",
  "path": "cases/65cb19dcd93fe4510d4d786d/
externallmg_1707911636785_WhatsApp_Image_20240214_at_114142_AM_2.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65cca9ded93fe4510d4fe897",
    "name":
"externallmg_1707911646662_WhatsApp_Image_20240214_at_114142_AM.jpeg",
    "path": "cases/65cb19dcd93fe4510d4d786d/
externallmg_1707911646662_WhatsApp_Image_20240214_at_114142_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65cca9ded93fe4510d4fe898",
    "name":
"externallmg_1707911646665_WhatsApp_Image_20240214_at_114143_AM_1.jpeg",
    "path": "cases/65cb19dcd93fe4510d4d786d/
externallmg_1707911646665_WhatsApp_Image_20240214_at_114143_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65cca9ded93fe4510d4fe899",
    "name":
"externallmg_1707911646668_WhatsApp_Image_20240214_at_114143_AM_2.jpeg",
    "path": "cases/65cb19dcd93fe4510d4d786d/
externallmg_1707911646668_WhatsApp_Image_20240214_at_114143_AM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65cca9ded93fe4510d4fe89a",
    "name":
"externallmg_1707911646672_WhatsApp_Image_20240214_at_114143_AM.jpeg",
    "path": "cases/65cb19dcd93fe4510d4d786d/
externallmg_1707911646672_WhatsApp_Image_20240214_at_114143_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65cca9ded93fe4510d4fe89b",
```

```
    "name":
"externallmg_1707911646675_WhatsApp_Image_20240214_at_114144_AM_1.jpeg",
  "path": "cases/65cb19dcd93fe4510d4d786d/
externallmg_1707911646675_WhatsApp_Image_20240214_at_114144_AM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65cca9ded93fe4510d4fe89c",
  "name":
"externallmg_1707911646678_WhatsApp_Image_20240214_at_114144_AM.jpeg",
  "path": "cases/65cb19dcd93fe4510d4d786d/
externallmg_1707911646678_WhatsApp_Image_20240214_at_114144_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65cca9ded93fe4510d4fe89d",
  "name":
"externallmg_1707911646682_WhatsApp_Image_20240214_at_114145_AM_1.jpeg",
  "path": "cases/65cb19dcd93fe4510d4d786d/
externallmg_1707911646682_WhatsApp_Image_20240214_at_114145_AM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65cca9ded93fe4510d4fe89e",
  "name":
"externallmg_1707911646685_WhatsApp_Image_20240214_at_114145_AM_2.jpeg",
  "path": "cases/65cb19dcd93fe4510d4d786d/
externallmg_1707911646685_WhatsApp_Image_20240214_at_114145_AM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65cca9ded93fe4510d4fe89f",
  "name":
"externallmg_1707911646686_WhatsApp_Image_20240214_at_114145_AM.jpeg",
  "path": "cases/65cb19dcd93fe4510d4d786d/
externallmg_1707911646686_WhatsApp_Image_20240214_at_114145_AM.jpeg",
  "orientation": "portrait"
},
}
```



```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65cca9ded93fe4510d4fe8a0",
  "name":
"externalImg_1707911646694_WhatsApp_Image_20240214_at_114146_AM.jpeg",
  "path": "cases/65cb19dcd93fe4510d4d786d/
externalImg_1707911646694_WhatsApp_Image_20240214_at_114146_AM.jpeg",
  "orientation": "landscape"
}
],
"externalDocuments": [],
"processingDocuments": [
{
  "originalname": "Calculation Sheet NEW.xlsx",
  "filename": "1707976129909_Calculation_Sheet_NEW.xlsx",
  "path": "cases/65cb19dcd93fe4510d4d786d/
processingDocuments/1707976129909_Calculation_Sheet_NEW.xlsx",
  "size": "3688593",
  "createdAt": "Thu Feb 15 2024 11:18:50 GMT+0530 (India Standard Time)",
  "uploadedBy": "64cde526dc9f3034f3fefa49"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-02-13T07:27:24.345Z",
"updatedAt": "2024-02-15T07:34:17.492Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 702, 7th Floor, Building No B1, Opal , Yogidham
B-1 Opal Co-Op. Hsg. Soc. Ltd. , Yogi Dham Phase - III, Opp KDMT Bus Depot, Murbad
Road, Village - Gauripada , Taluka - Kalyan, District - Thane , Kalyan (West), PIN - 421
301, State - Maharashtra, Country - India",
"updatedBy": "64cde526dc9f3034f3fefa49",
"addressForMap": "",
"caseReferredBy": "60b7177d2ffdf65bcd65882a",
"contactPersonName": "Mrs. Amita Verma ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
```

```
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Owner's Wife",
"siteVisitContactNo": "9920357439",
"builtupPercentage": "10",
"carpetTotal": "594.01",
"extendOfSiteRemark": "",
"finalBuiltupArea": "773.82",
"finalCarpetArea": "703.47",
"finalSalableArea": "851.20",
"otherCarpetTotal": "109.96",
"salablePercentage": "10",
"siteMeasurementRemark": "Carpet Area in Sq. Ft. = 594.00\nCup Board Area in Sq.
Ft. = 24.00\nFlower Bed Area in Sq. Ft. = 15.00\nDry Balcony Area in Sq. Ft. =
24.00\nBalcony Area in Sq. Ft. = 46.00\n\n",
"toBeAdded": "",
"briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + 2 Toilet + Passage",
"finalMeasurementType": "Sq. Ft.",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "109.46",
"otherCompositionSaleableTotal": "0.00",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalSaleablePercentage": "10",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 685.00",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"reportGeneratedDate": "Thu Feb 15 2024 10:35:41 GMT+0530 (India Standard
Time)",
"siteVisitDate": "2024-02-13",
```

```

"buildingServicesRate": "2500",
"flatRate": "10500",
"landOtherRate": "8000",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  },
  "roadFacing": false,
  "mall": false
}
}

```

Name	Length	Width	Total
Composition :			
Living Room	10'00"	18'00"	180.00
Bedroom	9'5"	12'6"	117.71
Bedroom	9'8"	11'5"	110.36
Kitchen	9'00"	7'6"	67.50
Toilet	7'00"	4'3"	29.75
Toilet	7'00"	4'6"	31.50
Passage	3'2"	7'00"	22.17
Other Composition :			
Cupboard	7'7"	2'00"	15.17
Flower Bed Area	7'5"	2'1"	15.45
Dry Balcony Area	4'7"	5'2"	23.68
Balcony Area	10'00"	4'7"	45.83