

```
{
  "typeOfReport": {
    "value": "Shop",
    "label": "Shop"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Bank_Loan",
    "label": "Bank Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b9e6"
    },
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b94230f5a",
    "firstName": "Amruta ",
    "email": "amruta.pathak@cosmosbank.in",
    "mobileNo": "-",
    "workMobileNo": "9769900929",
    "lastName": "Pathak"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "6418456a96b58848585f8cb2",
  "name": "Thane",
  "email": "thane@vastukala.com",
  "phone": "1234567890",
  "address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
  "city": "Thane",
  "shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1820",
  "type": "BANK",
  "name": "Cosmos Bank",
  "displayName": "Cosmos Bank",
  "initial": "CB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b9e6",
  "branchCode": "000014",
  "type": "BRANCH",
  "name": "Dombivali (East) Branch",
  "email": "dombivali@cosmosbank.in",
  "mobileNo": "02512435618",
  "alternateMobileNo": "",
  "address": "Sindhudurg C.H.S., Ground Floor, Tilak Chowk, Tilak Nagar, Dombivali
(East), Taluka Kalyan, District Thane - 400605, State - Maharashtra, Country - India.",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Commercial",
  "value": "Commercial"
},
"zone": {
  "_id": "60f919bff3dd69653a5926b8",
  "zoneName": "Mumbai & Aurangabad Zone"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "656aa949cebbe1714411d21b",
  "role": "FRONTDESK",
  "firstName": "Priyanka",
  "email": "thane@vastukala.org",
  "lastName": "Pawar",
  "mobileNo": "8928414480",
  "shortName": "PCP",
  "workWithDocumentMaker": "627222afafd7d55eddeddd82"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "64e5a649daae6a1c98101989",
  "role": "SITEENGINEER",
  "firstName": "Sameer",
  "email": "sameeryp2010@gmail.com",
  "lastName": "Parab",
  "mobileNo": "8291009567",
  "designation": "Site Engineer",
  "shortName": "Sameer",
  "workWithDocumentMaker": "62ea09ea4e679b264caf07d7"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627222afafd7d55eddeddd82",
  "role": "FRONTDESK",
  "firstName": "Pratibha",
  "email": "shilvanta_pratibha@yahoo.co.in",
  "lastName": "Shilvantha",
  "mobileNo": "9821518537",
  "designation": ""
}
```

```

    "shortName": "PS",
    "workWithDocumentMaker": "60f915d3f3dd69653a592199",
    "profilePhoto": "users/627222afafd7d55eddeddd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
  },
  "checker": null,
  "valuers": [
    {
      "valuersRegistrationNumber": [
        {
          "value": "IBBI/RV/07/2018/10366",
          "label": "Registered Valuer"
        }
      ],
      "type": "EMPLOYEE",
      "_id": "5ffe92d27737ca4d986b6453",
      "role": "VALUER",
      "firstName": "Manoj",
      "email": "manoj@vastukala.org",
      "lastName": "Chalikwar",
      "mobileNo": "9819597579",
      "designation": "Registered Valuer",
      "registrationNo": [
        {
          "title": {
            "label": "IBBI"
          },
          "_id": "60af80072ffdf65bcd658651",
          "number": "IBBI/RV/07/2018/10366"
        },
        {
          "title": {
            "value": "FIIV",
            "label": "FIIV"
          },
          "_id": "60af80072ffdf65bcd658652",
          "number": "CAT-I-F-1763"
        }
      ],
      {
        "title": {
          "value": "Chartered_Engineer",
          "label": "Chartered Engineer"
        },
        "_id": "60af80072ffdf65bcd658653",
        "number": "AM161706-3"
      },
    },
  ],

```

```
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
},
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.192675619992375",
  "longitude": "73.0915779992938"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.0915779992938,
    19.192675619992375
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-02-16",
      "remark": ""
    }
  ]
},
"schedule": [],
"marketAnalysisAndRemark": {
  "audioNotes": []
}
```

```
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Nandivli ",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "Ground",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": true,
    "name": "District",
    "key": "district",
```

```
"value": "Thane",
"label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Kalyan",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": false,
  "name": "Building Name",
  "key": "buildingName",
  "value": "",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
```

```
"status": false,
"name": "Street 1",
"key": "street1",
"value": "",
"label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "D. P. Road",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "71 Part",
```



```
"label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "Shop No. 33 A",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
```

```
"name": "Mouza",
"key": "mouza",
"value": "",
"label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
}
},
```

```
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
}
```

```
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
  }
}
```

```
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
```



```
"value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"invoices": [],
"paymentId": [],
"_id": "65cdbd11d93fe4510d50cc44",
"ownerName": "Mr. Ashish M Dutiya & Mrs. Dimpal Ashish Dutiya",
"ownerPhoneNo": "9702644999",
"fullAddress": "Commercial Shop No. Shop No. 33 A, Ground Floor, D. P. Road, New/
Current Survey No. 71 Part, Village - Nandivli , Taluka - Kalyan, District - Thane, State -
Maharashtra, India",
"remark": "",
"documents": [
{
  "documentType": {
    "value": "60af48bf2ffdf65bcd6585fa",
    "label": "Agreement for sale"
  },
  "inputs": {
    "documentDate": "17/02/2004",
    "from": {
      "value": "The_Assignor",
      "label": "The Assignor"
    },
    "The_Assignor": "M/s. Suparshwa Earthen Builders Private Limited",
    "to": {
      "value": "purchaser",
      "label": "purchaser"
    },
    "purchaser": "Mr. Aashish M Dutiya & Mrs. Dimpal Aashish Dutiya",
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "635/2004"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1707982032420_68158.pdf",
  "path": "cases/65cdbd11d93fe4510d50cc44/
document_1707982032420_68158.pdf",
```

```
"id": "965937",
"uploadedBy": "656aa949cebbe1714411d21b",
"createdAt": "Thu Feb 15 2024 12:58:17 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "inputs": {
    "number": {
      "value": "Document_No",
      "label": "Document No"
    }
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1707982093769_Ashish_Dutiya_Index_II.pdf",
  "path": "cases/65cdbd11d93fe4510d50cc44/
document_1707982093769_Ashish_Dutiya_Index_II.pdf",
  "id": "618662",
  "uploadedBy": "656aa949cebbe1714411d21b",
  "createdAt": "Thu Feb 15 2024 12:58:17 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "17/07/2002",
    "nameOfApprovingAuthority": {
      "value": "Kalyan_Dombivli_Municipal_Corporation",
      "label": "Kalyan Dombivli Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "KDMC / NRV / BP / DOM / 226 - 56 "
},
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1708148627518_136757.pdf",
  "path": "cases/65cdbd11d93fe4510d50cc44/
document_1708148627518_136757.pdf",
```

```
    "id": "951203",
    "uploadedBy": "627222afafd7d55eddeddd82",
    "createdAt": "Sat Feb 17 2024 11:13:47 GMT+0530 (India Standard Time)"
  }
],
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"caseNumber": "006984",
"createdBy": "656aa949cebbe1714411d21b",
"caseHistory": [
  {
    "id": "314970",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Feb 15 2024 12:58:17 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Ashish M Dutiya & Mrs. Dimpal Ashish Dutiya",
    "phone": "9702644999",
    "ownershipShare": "",
    "email": "",
    "id": "447870"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65cf04c419837c7e5fdcd31c",
    "name": "externalImg_1708065983869_1708066109732_image_0.jpeg",
    "path": "cases/65cbbd11d93fe4510d50cc44/externalImg_1708065983869_1708066109732_image_0.jpeg",
    "orientation": "portrait"
  }
],
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65cf04c419837c7e5fdcd31d",
  "name": "externallmg_1708065984257_1708066109732_image_1.jpeg",
  "path": "cases/65cxbd11d93fe4510d50cc44/
externallmg_1708065984257_1708066109732_image_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65cf04c419837c7e5fdcd31e",
  "name": "externallmg_1708065984277_1708066109732_image_2.jpeg",
  "path": "cases/65cxbd11d93fe4510d50cc44/
externallmg_1708065984277_1708066109732_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65cf04c419837c7e5fdcd31f",
  "name": "externallmg_1708065984588_1708066109732_image_3.jpeg",
  "path": "cases/65cxbd11d93fe4510d50cc44/
externallmg_1708065984588_1708066109732_image_3.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65cf04c419837c7e5fdcd320",
  "name": "externallmg_1708065984668_1708066109733_image_4.jpeg",
  "path": "cases/65cxbd11d93fe4510d50cc44/
externallmg_1708065984668_1708066109733_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65cf04c419837c7e5fdcd321",
  "name": "externallmg_1708065984981_1708066109733_image_5.jpeg",
  "path": "cases/65cxbd11d93fe4510d50cc44/
externallmg_1708065984981_1708066109733_image_5.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65cf04c419837c7e5fdcd322",
    "name": "externallmg_1708065985282_1708066109733_image_6.jpeg",
    "path": "cases/65cdbd11d93fe4510d50cc44/
externallmg_1708065985282_1708066109733_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65cf04c419837c7e5fdcd323",
    "name": "externallmg_1708065985913_1708066109733_image_7.jpeg",
    "path": "cases/65cdbd11d93fe4510d50cc44/
externallmg_1708065985913_1708066109733_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65cf04c419837c7e5fdcd324",
    "name": "externallmg_1708065986256_1708066109733_image_8.jpeg",
    "path": "cases/65cdbd11d93fe4510d50cc44/
externallmg_1708065986256_1708066109733_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65cf04c419837c7e5fdcd325",
    "name": "externallmg_1708065986782_1708066109733_image_9.jpeg",
    "path": "cases/65cdbd11d93fe4510d50cc44/
externallmg_1708065986782_1708066109733_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65cf04c419837c7e5fdcd326",
    "name": "externallmg_1708065986937_1708066109733_image_10.jpeg",
    "path": "cases/65cdbd11d93fe4510d50cc44/
externallmg_1708065986937_1708066109733_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "65cf04c419837c7e5fdcd327",
  "name": "externallmg_1708065987552_1708066109733_image_11.jpeg",
  "path": "cases/65cdbc11d93fe4510d50cc44/
externallmg_1708065987552_1708066109733_image_11.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65cf04c419837c7e5fdcd328",
  "name": "externallmg_1708065987788_1708066109733_image_12.jpeg",
  "path": "cases/65cdbc11d93fe4510d50cc44/
externallmg_1708065987788_1708066109733_image_12.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65cf04c419837c7e5fdcd329",
  "name": "externallmg_1708065987897_1708066109733_image_13.jpeg",
  "path": "cases/65cdbc11d93fe4510d50cc44/
externallmg_1708065987897_1708066109733_image_13.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65cf04c419837c7e5fdcd32a",
  "name": "externallmg_1708065988022_1708066109733_image_14.jpeg",
  "path": "cases/65cdbc11d93fe4510d50cc44/
externallmg_1708065988022_1708066109733_image_14.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "65cf047f19837c7e5fdcd252",
  "name": "externallmg_1708065919053_1708066069578_image_0.jpeg",
  "path": "cases/65cdbc11d93fe4510d50cc44/
externallmg_1708065919053_1708066069578_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
```

```
    "_id": "65cf047f19837c7e5fdcd253",
    "name": "externalimg_1708065919179_1708066069578_image_1.jpeg",
    "path": "cases/65cbbd11d93fe4510d50cc44/
externalimg_1708065919179_1708066069578_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65cf047f19837c7e5fdcd254",
    "name": "externalimg_1708065919238_1708066069578_image_2.jpeg",
    "path": "cases/65cbbd11d93fe4510d50cc44/
externalimg_1708065919238_1708066069578_image_2.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname":
"1707727533548_1703238797922_1701350330944_Calculation_123_2.xlsx",
    "filename": "1708084671238_1707727533548_1703238797922_1701350330944_C
alculation_123_2.xlsx",
    "path": "cases/65cbbd11d93fe4510d50cc44/processingDocuments/1708084671238
_1707727533548_1703238797922_1701350330944_Calculation_123_2.xlsx",
    "size": "3410237",
    "createdAt": "Fri Feb 16 2024 17:27:52 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f915d3f3dd69653a592199"
  }
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-02-15T07:28:17.219Z",
"updatedAt": "2024-02-17T05:43:47.613Z",
"__v": 0,
"updatedBy": "627222afafd7d55eddedd82",
"addressForMap": "",
"caseReferredBy": "6410199a140f140ffc59b58c",
"contactPersonName": "Mr. Ashish M Dutiya & Mrs. Dimpal Ashish Dutiya",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
```

"relationWithOwner": "self",  
"siteVisitContactNo": "9702644999"

}

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
-------------	---------------	--------------	--------------

---

Composition :

---

Other

Composition :

---