

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7fb"
    },
    "type": "CREDITOFFICER",
    "_id": "64d1d9dad9f3034f301dcff",
    "firstName": "Prabhat Bhajbai",
    "lastName": "Bhajbai",
    "mobileNo": "",
    "workMobileNo": "9820021086",
    "email": "Prabhat@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "4999000",
    "discussWithPerson": "Prabhat Bhajbai",
    "expectedFees": 2499.5,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7fb",
  "branchCode": "000068",
  "type": "BRANCH",
  "name": "RBO Sanpada",
  "email": "sme.navimum@sbi.co.in",
  "mobileNo": "022-27759215",
  "alternateMobileNo": "",
  "address": "SMEC VASHI, E/202, 2nd Floor, Sanpada Rly. Station Complex, Navi
Mumbai - 400 705, State - Maharashtra, Country - India.\n\n",
  "ledgerName": "STATE BANK OF INDIA - RBO SANPADA",
  "fax": "022-27752206",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60b7189d2ffdf65bcd65882b",
  "role": "PICKUPPERSON",
  "firstName": "Ravindra",
  "email": "ravindrakasare186@gmail.com",
  "lastName": "Kasare",
  "mobileNo": "9167204055",
  "shortName": "RBK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60b7189d2ffdf65bcd65882b\\
\\profilePhoto_1622701555488_WhatsApp Image 2021-06-03 at 11.46.40 AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "60f9343b45132d6a6bdd96e8",
  "role": "SITEENGINEER",
  "firstName": "Rajesh",
  "email": "rajeshb.ghadi@gmail.com",
  "lastName": "Ghadi",
  "mobileNo": "8652092666",
  "designation": "",
  "shortName": "RHG",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": "",
  "shortName": "SK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Sh Yam_Photo.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "62fe044a48a26047e6552796",
  "role": "MAKER",
  "firstName": "Pradnya ",
  "email": "pradnya@vastukala.org",
  "lastName": "Rasam",
  "mobileNo": "9529385821",
```

```
"designation": "",
"shortName": "PR",
"workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
"profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": {
"type": "EMPLOYEE",
"_id": "60eeaeddf3dd69653a581316",
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Shyam",
"email": "shyam@vastukala.org",
"lastName": "Kajvilkar",
"mobileNo": "9765074720",
"designation": "",
"shortName": "SK",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Sh Yam_Photo.jpg"
},
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
}
],
{
"title": {
```

```
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.03580289341502",
  "longitude": "73.07315210924939"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.07315210924939,
    19.03580289341502
  ]
}
```

```
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "15/02/2024 04:44 pm"
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-02-16",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "Country - India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
```

```
"key": "village",
"value": "Kharghar",
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "7",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Raigad ",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Navi Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Panvel ",
  "label": true
},
}
```

```
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "189, Sector - 10",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Hare Krishna Co-Op. Hsg. Soc. Ltd. ",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Kopra ",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
```



```
"value": "A",
"label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
```

```
"status": true,
"name": "Flat / Unit / Office / Gala No.",
"key": "selectNo",
"value": "A-703",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
```

```
"label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 410 210",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows_with_M._S._Grills",
    "label": "Powder coated Aluminum sliding windows with M. S. Grills"
  },
  "fittings": {
    "value": "Concealed_plumbing_with_C.P._fittings._Concealed_Electrical_wiring",
    "label": "Concealed plumbing with C.P. fittings. Concealed Electrical wiring"
  },
  "finishing": {
    "value": "Cement_Plastering_+_POP_Finish",
    "label": "Cement Plastering + POP Finish"
  }
},
"general": {
  "ownership": {
    "value": "Sole_Ownership",
```

```
"label": "Sole Ownership"
},
"populationClassList": {
  "value": "MiddleClass",
  "label": "Middle Class"
},
"populationGroupList": {
  "value": "Urban",
  "label": "Urban"
},
"townplanApprovedByList": {
  "value": "CIDCO",
  "label": "CIDCO"
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Internal Road ",
  "west": "Kopra Road ",
  "south": "Shivam CHSL ",
  "east": "Jewel Heights "
},
"asPerDocumentAgreement": {
  "north": "Details not available ",
  "west": "Details not available ",
  "south": "Details not available ",
  "east": "Details not available "
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Details not available ",
    "east": "Details not available ",
    "south": "Details not available ",
    "west": "Details not available "
  },
  "asPerDocument": {
    "north": "Details not available ",
    "east": "Details not available ",
    "south": "Details not available ",
    "west": "Details not available "
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
```

```
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "As Occupancy Certificate is available it may be
assumed that the construction is as per Sanctioned Plan.",
"approvePlanVerified": "N.A",
"empanelledOfApprovePlan": "N.A",
"unauthorizedConstruction": ""
},
"compositeRate": {
"remark": "",
"depreciationPercentage": "19.5",
"depreciationRatioOfBuilding": "",
"salvageValue": "10",
"depreciatedCostOfConstruction": "13612.5",
"depreciatedBuildingRate": "2012.5"
},
"igrRate": {
"propertyName": "Residential Flat",
"rate": "108700",
"landRate": "45400",
"igrImage": "cases/65cdec72d93fe4510d5187f9/igr_1708147813901_Image.png",
"squareMeterGuideLineRate": "114135.00",
"squareFeetGuideLineRate": "10604.00"
},
"igrFinalRate": {
"floorRatePercentage": "5",
"depreciationPercentage": "87",
"rate": "9773.00",
"squareFeetGuideLineRate": "9773.00",
"squareMeterGuideLineRate": "105199.00"
},
"outgoingDetail": {
"areaStatusList": {
"value": "Medium",
"label": "Medium"
},
"propertyTypeOfUseList": {
"value": "Residential_Purpose",
"label": "Residential Purpose"
},
"propertyOccupiedByList": {
"value": "Owner_Occupied",
"label": "Owner Occupied"
},
"monthlyRent": "N.A",
"assessmentNo": "Details not available ",
"taxPaidHolderName": "Details not available ",
```

```
"taxAmount": "Details not available ",
"electricityServiceConnectionNo": "Details not available ",
"meterCardHolderName": "Details not available ",
"undividedAreaOfLandAsPerSaleDeed": "Details not available ",
"floorSpaceIndex": "As per CIDCO norms ",
"tenantName": "",
"maintenanceOfFlat": "Good "
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area ",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Stilt Car Parking Space ",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "2011",
```

```
"fullDate": "1/1/2011"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C.",
  "label": "R.C.C. Framed"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
}
```

```
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "1",
  "label": "Yes"
},
"visibleDamageInBuilding": {
  "value": "1",
  "label": "Yes"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "stilt",
  "label": "Stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "47",
"ageOfBuilding": "13",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "7",
"flatFloorNo": "7",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "3"
},
"finalPlinthArea": {
  "area": "511.20",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 20%"
},
```



```
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Metro_Station",
      "label": "Metro Station"
    },
    "routeMapImg": "cases/65cdec72d93fe4510d5187f9/
routeMap_1708150802343_Image.png",
    "routeLat": "19.034111",
    "routeLng": "73.073333",
    "stationName": "Kendriy Vihar ",
    "routeDistance": "1.7 Km. "
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "w0dogaf",
      "name": "w0dogaf",
      "image": "cases/65cdec72d93fe4510d5187f9/
routeMap_1708150583016_Image.png"
    }
  ]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
```

```
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "5799138.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "5799138.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": true,
"status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "4995958.00",
  "selectedBuildUpValue": "511.20",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "65d03d1352bb6a0e76c5c62e",
      "name": "externallmg_r_1708145939441_JKFantasy___20240216Fri_010026PM_
__xrddrrxz2223murism___1922_N_73422_E___map.jpg",
      "path": "cases/65cdec72d93fe4510d5187f9/externallmg_r_1708145939441_JKFan
tasy___20240216Fri_010026PM___xrddrrxz2223murism___1922_N_73422_E___map
.jpg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": [
    {
      "status": false,
      "_id": "65d03d1352bb6a0e76c5c62f",
      "name": "Living Room",
      "path": "cases/65cdec72d93fe4510d5187f9/externallmg_r_1708145939460_JKFan
tasy___20240216Fri_125456PM___xrddrrxz2223murism___1922_N_73424_E___map
.jpg",
      "orientation": "portrait"
    }
  ],
  {
    "status": false,
    "_id": "65d03d1352bb6a0e76c5c637",
```

```
    "name": "Living Room",
    "path": "cases/65cdec72d93fe4510d5187f9/externallmg_r_1708145939531_JKFantasy__20240216Fri_125433PM__xrrdrrxz2223murism__1922_N_73424_E__map.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65d03d1352bb6a0e76c5c63a",
    "name": "Living Room",
    "path": "cases/65cdec72d93fe4510d5187f9/externallmg_r_1708145939556_JKFantasy__20240216Fri_125443PM__xrrdrrxz2223murism__1922_N_73424_E__map.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65d03d1352bb6a0e76c5c636",
    "name": "Living Room",
    "path": "cases/65cdec72d93fe4510d5187f9/externallmg_r_1708145939524_JKFantasy__20240216Fri_125405PM__xrrdrrxz2223murism__1921_N_73424_E__map.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65d03d1352bb6a0e76c5c635",
    "name": "Living Room",
    "path": "cases/65cdec72d93fe4510d5187f9/externallmg_r_1708145939517_JKFantasy__20240216Fri_125403PM__xrrdrrxz2223murism__1921_N_73424_E__map.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65d03d1352bb6a0e76c5c62d",
    "name": "Living Room",
    "path": "cases/65cdec72d93fe4510d5187f9/externallmg_r_1708145939451_JKFantasy__20240216Fri_124929PM__xrrdrrxz2223murism__1921_N_73424_E__map.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65d03d1352bb6a0e76c5c631",
    "name": "Living Room",
```

```
    "path": "cases/65cdec72d93fe4510d5187f9/externallmg_r_1708145939490_JKFan
tasy___20240216Fri_124858PM___xrddrrxz2223murism___1921_N_73424_E___map
.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65d03d1352bb6a0e76c5c62e",
    "name": "Living Room",
    "path": "cases/65cdec72d93fe4510d5187f9/externallmg_r_1708145939441_JKFan
tasy___20240216Fri_010026PM___xrddrrxz2223murism___1922_N_73422_E___map
.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65d03d1352bb6a0e76c5c632",
    "name": "Living Room",
    "path": "cases/65cdec72d93fe4510d5187f9/externallmg_r_1708145939499_JKFan
tasy___20240216Fri_125021PM___xrddrrxz2223murism___1923_N_73423_E___map
.jpg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "15000",
    "max": "17333"
  },
  "builtUpRateRange": {
    "min": "12500",
    "max": "14445"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
```



```
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
```

```
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "426.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3",
  "SME/TCC/221/13"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"invoices": [],
"paymentId": [],
"_id": "65cdec72d93fe4510d5187f9",
"ownerName": "Mr. Pankaj Vasanta Khalode ",
"ownerPhoneNo": "9324403087",
"appAddress": "flat no. 703 . 7 th floor A wing Hare krishna co. op hgh Ltd plot no. 189
sector no. 10 khargahr",
"remark": "ssl swapnil kamble\n8080463318",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "inputs": {
      "documentDate": "25/05/2022",
      "from": {
        "value": "Transferor",
        "label": "Transferor"
      },
      "Transferor": "Mr. Laxman Nagappa Borra & Mrs. Chandra Laxman Borra",
      "to": {
        "value": "Transferee",
        "label": "Transferee"
      },
      "Transferee": "Mr. Pankaj Vasanta Khalode ",
      "number": {
        "value": "No",
        "label": "No"
      }
    }
  }
],
```

```
    "No": "7555 / 2022"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "831408",
  "path": "cases/65cdec72d93fe4510d5187f9/
document_1707994218133_1707994365574_pankaj_khalode.pdf",
  "fileName": "document_1707994218133_1707994365574_pankaj_khalode.pdf"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "03/10/2011",
    "nameOfApprovingAuthority": {
      "value": "CIDCO",
      "label": "CIDCO"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "CIDCO / ATPO (BP) / 2011 / 1278"
},
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1708147626374_313048.pdf",
  "path": "cases/65cdec72d93fe4510d5187f9/
document_1708147626374_313048.pdf",
  "id": "545618",
  "uploadedBy": "62fe044a48a26047e6552796",
  "createdAt": "Sat Feb 17 2024 10:57:06 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "006992",
"createdBy": "60b7189d2ffdf65bcd65882b",
"caseHistory": [
  {
    "id": "341384",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Feb 15 2024 16:20:26 GMT+0530 (India Standard Time)"
  }
],
```

```
"owners": [
  {
    "name": "Mr. Pankaj Vasanta Khalode ",
    "phone": "9324403087",
    "ownershipShare": "",
    "email": "",
    "id": "757270"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "150676",
    "name": "Living Room",
    "length": "14.33",
    "length1": "14",
    "length2": "4",
    "width": "9.42",
    "width1": "9",
    "width2": "5",
    "totalArea": "134.97",
    "images": [],
    "extraAreas": [],
    "finalArea": "134.97"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "4",
    "name": "Passage",
    "length": "",
    "length1": "8",
    "length2": "2",
    "width": "",
    "width1": "3",
    "width2": "2",
    "totalArea": "25.86",
    "images": [],
    "finalArea": "31.86",
```

```
"extraAreas": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "_id": "65d047e552bb6a0e76c5ea65",
    "name": "Extra ",
    "extraAreaType": "Add",
    "length": "1.50",
    "length1": "1",
    "length2": "6",
    "width": "4.00",
    "width1": "4",
    "width2": "00",
    "totalArea": "6.00"
  }
],
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Kitchen",
  "length": "8.42",
  "length1": "8",
  "length2": "5",
  "width": "7.33",
  "width1": "7",
  "width2": "4",
  "totalArea": "61.72",
  "images": [],
  "extraAreas": [],
  "finalArea": "61.72"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Bedroom",
  "length": "10.00",
  "length1": "10",
```

```
"length2": "0",
"width": "9.67",
"width1": "9",
"width2": "8",
"totalArea": "96.67",
"images": [],
"finalArea": "96.67",
"extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "WC",
  "length": "3.00",
  "length1": "3",
  "length2": "00",
  "width": "4.00",
  "width1": "4",
  "width2": "00",
  "totalArea": "12.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "12.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Bathroom",
  "length": "4.00",
  "length1": "4",
  "length2": "00",
  "width": "4.00",
  "width1": "4",
  "width2": "00",
  "totalArea": "16.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "16.00"
}
],
```

```
"otherComposition": [
  {
    "toBeAdded": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "name": {
      "label": "Terrace Area",
      "value": "Terrace_Area"
    },
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "2",
    "length": "",
    "length1": "4",
    "length2": "8",
    "width": "",
    "width1": "9",
    "width2": "6",
    "totalArea": "44.33",
    "images": [],
    "extraAreas": [
      {
        "measurementType": {
          "value": "Square_Feet",
          "label": "Square Feet"
        },
        "_id": "65d0486752bb6a0e76c5ebbd",
        "name": "Extra ",
        "extraAreaType": "Add",
        "length": "4.00",
        "length1": "4",
        "length2": "00",
        "width": "5.00",
        "width1": "5",
        "width2": "00",
        "totalArea": "20.00"
      }
    ],
    "finalArea": "64.33",
    "percentageBeforeTotal": "44.33",
    "percentage": "100"
  },
  {
```

```
"toBeAdded": {
  "label": "Carpet",
  "value": "Carpet"
},
"name": {
  "label": "Flower Bed Area",
  "value": "Flower_Bed_Area"
},
"measurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"id": "1",
"length": "2.00",
"length1": "2",
"length2": "00",
"width": "10.00",
"width1": "10",
"width2": "00",
"totalArea": "20.00",
"images": [],
"extraAreas": [],
"finalArea": "20",
"percentageBeforeTotal": "20.00",
"percentage": "100"
}
],
"externalReport": [],
"documentPerArea": [
{
  "typeOfDocument": {
    "label": "Agreement For Sale",
    "value": "60ae1254aa6d152c1801b326"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "109461",
  "selectAreaTypeDocument": "Carpet",
  "totalAreaDocument": "426",
  "squareMeterArea": "39.58",
  "docFinalBuiltUp": "511.2",
  "docFinalBuiltUpSquareMeter": "47.495999999999995",
  "docBuiltupPercentage": "20",
  "docSaleablePercentage": "0",
```



```
"docFinalSaleable": "0",
"docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
{
  "printlnReport": true,
  "_id": "65d0447052bb6a0e76c5dd55",
  "property": "Residential Flat",
  "area": "450",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "https://www.99acres.com/",
  "expectedPrice": "7500000",
  "expectedRate": "16666.67",
  "builtUpExpectedRate": "13888.89",
  "image": "cases/65cdec72d93fe4510d5187f9/
indicator_1708147699288_Image.png",
  "squareMeter": "41.81",
  "id": "968673"
},
{
  "printlnReport": true,
  "_id": "65d0447052bb6a0e76c5dd57",
  "property": "Residential Flat",
  "area": "380",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "magic_bricks",
  "expectedPrice": "6200000",
  "expectedRate": "16315.79",
  "builtUpExpectedRate": "13596.49",
  "image": "cases/65cdec72d93fe4510d5187f9/
indicator_1708147728311_Image.png",
  "squareMeter": "35.30",
  "id": "833951"
},
{
  "printlnReport": true,
  "_id": "65d0447052bb6a0e76c5dd58",
  "property": "Residential Flat",
```

```
"area": "400",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"source": "magic_bricks",
"expectedPrice": "6000000",
"expectedRate": "15000.00",
"builtUpExpectedRate": "12500.00",
"image": "cases/65cdec72d93fe4510d5187f9/
indicator_1708147746576_Image.png",
"squareMeter": "37.16",
"id": "113670"
},
{
  "printInReport": false,
  "_id": "65d04ebc52bb6a0e76c5ff67",
  "property": "Flat ",
  "area": "450",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "4th ",
  "source": "https://www.99acres.com/",
  "expectedPrice": "6100000",
  "expectedRate": "13555.56",
  "builtUpExpectedRate": "11296.30",
  "image": "cases/65cdec72d93fe4510d5187f9/
indicator_1708150460508_Image.png",
  "squareMeter": "41.81",
  "id": "336112"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d03d1352bb6a0e76c5c62d",
    "name": "externalImg_r_1708145939451_JKFantasy____20240216Fri_124929PM____
_xrrddrrxz2223murism____1921_N_73424_E____map.jpg",
    "path": "cases/65cdec72d93fe4510d5187f9/externalImg_r_1708145939451_JKFant
asy____20240216Fri_124929PM____xrrddrrxz2223murism____1921_N_73424_E____map.
jpg",
    "orientation": "portrait"
  },
  ],
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65d03d1352bb6a0e76c5c62e",
  "name": "externallmg_r_1708145939441_JKFantasy___20240216Fri_010026PM___xrrddrrxz2223murism___1922_N_73422_E___map.jpg",
  "path": "cases/65cdec72d93fe4510d5187f9/externallmg_r_1708145939441_JKFantasy___20240216Fri_010026PM___xrrddrrxz2223murism___1922_N_73422_E___map.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65d03d1352bb6a0e76c5c62f",
  "name": "externallmg_r_1708145939460_JKFantasy___20240216Fri_125456PM___xrrddrrxz2223murism___1922_N_73424_E___map.jpg",
  "path": "cases/65cdec72d93fe4510d5187f9/externallmg_r_1708145939460_JKFantasy___20240216Fri_125456PM___xrrddrrxz2223murism___1922_N_73424_E___map.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65d03d1352bb6a0e76c5c630",
  "name": "externallmg_r_1708145939471_JKFantasy___20240216Fri_010029PM___xrrddrrxz2223murism___1922_N_73422_E___map.jpg",
  "path": "cases/65cdec72d93fe4510d5187f9/externallmg_r_1708145939471_JKFantasy___20240216Fri_010029PM___xrrddrrxz2223murism___1922_N_73422_E___map.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65d03d1352bb6a0e76c5c631",
  "name": "externallmg_r_1708145939490_JKFantasy___20240216Fri_124858PM___xrrddrrxz2223murism___1921_N_73424_E___map.jpg",
  "path": "cases/65cdec72d93fe4510d5187f9/externallmg_r_1708145939490_JKFantasy___20240216Fri_124858PM___xrrddrrxz2223murism___1921_N_73424_E___map.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "65d03d1352bb6a0e76c5c632",
  "name": "externallmg_r_1708145939499_JKFantasy___20240216Fri_125021PM___
_xrrddrrxz2223murism___1923_N_73423_E___map.jpg",
  "path": "cases/65cdec72d93fe4510d5187f9/externallmg_r_1708145939499_JKFant
asy___20240216Fri_125021PM___xrrddrrxz2223murism___1923_N_73423_E___map.
jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65d03d1352bb6a0e76c5c633",
  "name": "externallmg_r_1708145939481_JKFantasy___20240216Fri_010032PM___
_xrrddrrxz2223murism___1922_N_73422_E___map.jpg",
  "path": "cases/65cdec72d93fe4510d5187f9/externallmg_r_1708145939481_JKFant
asy___20240216Fri_010032PM___xrrddrrxz2223murism___1922_N_73422_E___map.
jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65d03d1352bb6a0e76c5c634",
  "name": "externallmg_r_1708145939509_JKFantasy___20240216Fri_125401PM___
_xrrddrrxz2223murism___1921_N_73424_E___map.jpg",
  "path": "cases/65cdec72d93fe4510d5187f9/externallmg_r_1708145939509_JKFant
asy___20240216Fri_125401PM___xrrddrrxz2223murism___1921_N_73424_E___map.
jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65d03d1352bb6a0e76c5c635",
  "name": "externallmg_r_1708145939517_JKFantasy___20240216Fri_125403PM___
_xrrddrrxz2223murism___1921_N_73424_E___map.jpg",
  "path": "cases/65cdec72d93fe4510d5187f9/externallmg_r_1708145939517_JKFant
asy___20240216Fri_125403PM___xrrddrrxz2223murism___1921_N_73424_E___map.
jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65d03d1352bb6a0e76c5c636",
```

```
    "name": "externalimg_r_1708145939524_JKFantasy___20240216Fri_125405PM___
_xrrddrrxz2223murism___1921_N_73424_E___map.jpg",
    "path": "cases/65cdec72d93fe4510d5187f9/externalimg_r_1708145939524_JKFant
asy___20240216Fri_125405PM___xrrddrrxz2223murism___1921_N_73424_E___map.
jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d03d1352bb6a0e76c5c637",
    "name": "externalimg_r_1708145939531_JKFantasy___20240216Fri_125433PM___
_xrrddrrxz2223murism___1922_N_73424_E___map.jpg",
    "path": "cases/65cdec72d93fe4510d5187f9/externalimg_r_1708145939531_JKFant
asy___20240216Fri_125433PM___xrrddrrxz2223murism___1922_N_73424_E___map.
jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d03d1352bb6a0e76c5c638",
    "name": "externalimg_r_1708145939538_JKFantasy___20240216Fri_125438PM___
_xrrddrrxz2223murism___1922_N_73424_E___map.jpg",
    "path": "cases/65cdec72d93fe4510d5187f9/externalimg_r_1708145939538_JKFant
asy___20240216Fri_125438PM___xrrddrrxz2223murism___1922_N_73424_E___map.
jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d03d1352bb6a0e76c5c639",
    "name": "externalimg_r_1708145939549_JKFantasy___20240216Fri_125441PM___
_xrrddrrxz2223murism___1922_N_73424_E___map.jpg",
    "path": "cases/65cdec72d93fe4510d5187f9/externalimg_r_1708145939549_JKFant
asy___20240216Fri_125441PM___xrrddrrxz2223murism___1922_N_73424_E___map.
jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d03d1352bb6a0e76c5c63a",
    "name": "externalimg_r_1708145939556_JKFantasy___20240216Fri_125443PM___
_xrrddrrxz2223murism___1922_N_73424_E___map.jpg",
```

```
    "path": "cases/65cdec72d93fe4510d5187f9/externallmg_r_1708145939556_JKFantasy____20240216Fri_125443PM____xrrddrrxz2223murism____1922_N_73424_E____map.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d03d1352bb6a0e76c5c63b",
    "name": "externallmg_r_1708145939563_JKFantasy____20240216Fri_125454PM____xrrddrrxz2223murism____1922_N_73424_E____map.jpg",
    "path": "cases/65cdec72d93fe4510d5187f9/externallmg_r_1708145939563_JKFantasy____20240216Fri_125454PM____xrrddrrxz2223murism____1922_N_73424_E____map.jpg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "AGR.pdf",
    "filename": "1708147840517_AGR.pdf",
    "path": "cases/65cdec72d93fe4510d5187f9/processingDocuments/1708147840517_AGR.pdf",
    "size": "1799347",
    "createdAt": "Sat Feb 17 2024 11:00:42 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "IMG_20240217_082737.jpg",
    "filename": "1708147841983_IMG_20240217_082737.jpg",
    "path": "cases/65cdec72d93fe4510d5187f9/processingDocuments/1708147841983_IMG_20240217_082737.jpg",
    "size": "5671549",
    "createdAt": "Sat Feb 17 2024 11:00:42 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "IMG_20240217_082749.jpg",
    "filename": "1708147842099_IMG_20240217_082749.jpg",
    "path": "cases/65cdec72d93fe4510d5187f9/processingDocuments/1708147842099_IMG_20240217_082749.jpg",
    "size": "3151018",
    "createdAt": "Sat Feb 17 2024 11:00:42 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  }
],
```

```
{
  "originalname": "IMG_20240217_082856.jpg",
  "filename": "1708147842164_IMG_20240217_082856.jpg",
  "path": "cases/65cdec72d93fe4510d5187f9/
processingDocuments/1708147842164_IMG_20240217_082856.jpg",
  "size": "3575850",
  "createdAt": "Sat Feb 17 2024 11:00:42 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "IMG_20240217_082858.jpg",
  "filename": "1708147842230_IMG_20240217_082858.jpg",
  "path": "cases/65cdec72d93fe4510d5187f9/
processingDocuments/1708147842230_IMG_20240217_082858.jpg",
  "size": "2877646",
  "createdAt": "Sat Feb 17 2024 11:00:42 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "Screenshot_20240217_082539.jpg",
  "filename": "1708147842285_Screenshot_20240217_082539.jpg",
  "path": "cases/65cdec72d93fe4510d5187f9/
processingDocuments/1708147842285_Screenshot_20240217_082539.jpg",
  "size": "1169519",
  "createdAt": "Sat Feb 17 2024 11:00:42 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "1708147842314_Summary_NewPANKAJ.xlsx",
  "filename": "1708151196359_1708147842314_Summary_NewPANKAJ.xlsx",
  "path": "cases/65cdec72d93fe4510d5187f9/
processingDocuments/1708151196359_1708147842314_Summary_NewPANKAJ.xlsx",
  "size": "1543460",
  "createdAt": "Sat Feb 17 2024 11:56:36 GMT+0530 (India Standard Time)",
  "uploadedBy": "62fe044a48a26047e6552796"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-02-15T10:50:26.677Z",
"updatedAt": "2024-02-17T07:19:08.341Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
}
```

```
},
"fullAddress": "Residential Flat No. A-703, 7th Floor, Wing - A, Hare Krishna Co-Op.
Hsg. Soc. Ltd. , Plot No. 189, Sector - 10, Kopra , Village - Kharghar, Taluka - Panvel ,
District - Raigad , Navi Mumbai, PIN - 410 210, State - Maharashtra, Country - India",
"updatedBy": "60eeaeddf3dd69653a581316",
"addressForMap": "",
"caseReferredBy": "60b7189d2ffdf65bcd65882b",
"contactPersonName": "Mr. Pankaj Vasanta Khalode ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Owner",
"siteVisitContactNo": "9324403087",
"buildingServicesRate": "2500",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement For Sale",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 426.00",
"flatRate": "14100",
"landOtherRate": "11600",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  }
},
"roadFacing": false,
"mall": false
},
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + Passage + WC +
Bathroom",
"carpetTotal": "353.21999999999997",
"otherCarpetTotal": "84.33",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "84.33",
"otherCompositionSaleableTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "481.30",
"finalCarpetArea": "437.55",
"finalSalableArea": "529.44",
"salablePercentage": "10",
"toBeAdded": "",
```



```

"extendOfSiteRemark": "Carpet Area in Sq. Ft. = 361.00\nOpen Terrace Area in Sq. Ft. = 65.00\n\n",
"siteMeasurementRemark": "Carpet Area in Sq. Ft. = 353.00\nTerrace Area in Sq. Ft. = 64.00\nFlower Bed Area in Sq. Ft. = 20.00\n\n",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"reportGeneratedDate": "Sat Feb 17 2024 11:12:26 GMT+0530 (India Standard Time)",
"siteVisitDate": "2024-02-16"
}

```

Name	Length	Width	Total
Composition :			
Living Room	14'4"	9'5"	134.97
Passage	8'2"	3'2"	25.86
Kitchen	8'5"	7'4"	61.72
Bedroom	10'0"	9'8"	96.67
WC	3'00"	4'00"	12.00
Bathroom	4'00"	4'00"	16.00
Other Composition :			
Terrace Area	4'8"	9'6"	44.33
Flower Bed Area	2'00"	10'00"	20.00