

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b9f4"
    },
    "type": "CREDITOFFICER",
    "_id": "64d483a687258203eab0dd0f",
    "firstName": "Rohan ",
    "lastName": "Raut ",
    "mobileNo": "",
    "workMobileNo": "8097138369",
    "email": "Rohan.racpc.sion@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "10000000",
    "discussWithPerson": "Rohan ",
    "expectedFees": 5000,
    "quotedAmount": "2500"
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b9f4",
  "branchCode": "000215",
  "type": "BRANCH",
  "name": "RACPC Sion ",
  "email": "racpc.sion@sbi.co.in",
  "mobileNo": "02225046265",
  "alternateMobileNo": "",
  "address": "B-603 & 604, Kohinoor City, Commercial-1, 6th Floor, Kirol Road, Off
L.B.S. Marg, Kurla (West), Mumbai, Pin Code - 400 070, State - Maharashtra, Country -
India.",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "60b7177d2ffdf65bcd65882a",
  "role": "PICKUPPERSON",
  "firstName": "Saurabh",
  "email": "saurabhvelonde143@gmail.com",
  "lastName": "Velonde",
  "mobileNo": "8691048846",
  "shortName": "SSV",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1686816492317_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "648fcad91b499c2d52dc86f3",
  "role": "SITEENGINEER",
  "firstName": "Barkat",
  "email": "barkathodekar68@gmail.com",
  "lastName": "Hodekar",
  "mobileNo": "8879011615",
  "designation": "Site Engg",
  "shortName": "Barkat",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/648fcad91b499c2d52dc86f3/
profilePhoto_1687758876977_image.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "64cde526dc9f3034f3fefa49",
  "role": "FRONTDESK",
  "firstName": "Rashmi",
  "email": "rashmijadhav14feb@gmail.com",
  "lastName": "Jadhav",
  "mobileNo": "7738144625",
  "designation": "Back Office Coordination",
  "shortName": "RJ",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "62fe044a48a26047e6552796",
  "role": "MAKER",
  "firstName": "Pradnya ",
```

```
"email": "pradnya@vastukala.org",
"lastName": "Rasam",
"mobileNo": "9529385821",
"designation": "",
"shortName": "PR",
"workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
"profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "64cde526dc9f3034f3fefa49",
  "role": "FRONTDESK",
  "firstName": "Rashmi",
  "email": "rashmijadhav14feb@gmail.com",
  "lastName": "Jadhav",
  "mobileNo": "7738144625",
  "designation": "Back Office Coordination",
  "shortName": "RJ",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ]
  }
]
```

```
    },
    {
      "title": {
        "value": "FIIV",
        "label": "FIIV"
      },
      "_id": "60af80072ffdf65bcd658652",
      "number": "CAT-I-F-1763"
    },
    {
      "title": {
        "value": "Chartered_Engineer",
        "label": "Chartered Engineer"
      },
      "_id": "60af80072ffdf65bcd658653",
      "number": "AM161706-3"
    },
    {
      "title": {
        "value": "Registered_Valuer",
        "label": "Registered Valuer"
      },
      "_id": "60af80072ffdf65bcd658654",
      "number": "IBBI/RV/07/2018/10366"
    }
  ],
  "shortName": "MBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
  "PANNo": "AERPC9086P",
  "fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.03002003029238",
  "longitude": "72.88843151181936"
},
"geo": {
  "type": "Point",
  "coordinates": [
```

```
72.88843151181936,
19.03002003029238
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-02-18",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-02-18",
      "remark": "MANUAL_IN_TASK"
    }
  ],
  "schedule": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "2BHK",
  "label": "2 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "Country - India",
    "label": false
  }
}
```

```
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Anik",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "6",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Suburban",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Chembur ",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
```

```
"key": "taluka",
"value": "Kurla ",
"label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "217",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Mithul Enclave Co-Op. Hsg. Soc. Ltd. ",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Near Mysore Colony ",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Mehul Road ",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
}
```



```
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "A",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "183(Part)",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "218, 219 & 220",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
```

```
"value": "",
"label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "26",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
```

```
"status": false,
"name": "Gut No.",
"key": "GUTNo",
"value": "",
"label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 074",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows_with_M._S._Grills",
    "label": "Powder coated Aluminum sliding windows with M. S. Grills"
  },
  "fittings": {
    "value": "Concealed_plumbing_with_C.P._fittings._Concealed_Electrical_wiring",
    "label": "Concealed plumbing with C.P. fittings. Concealed Electrical wiring"
  },
  "finishing": {
    "value": "Cement_Plastering_+_POP_Finish",
    "label": "Cement Plastering + POP Finish"
  }
}
```

```
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "MCGM",
    "label": "Municipal Corporation of Greater Mumbai (MCGM)"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Wing - B",
    "west": "Vitta Sanchay CHSL ",
    "south": "Internal Road ",
    "east": "Wing - G"
  },
  "asPerDocumentAgreement": {
    "north": "Details not available ",
    "west": "Details not available ",
    "south": "Details not available ",
    "east": "Details not available "
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "Details not available ",
      "east": "Details not available ",
      "south": "Details not available ",
      "west": "Details not available "
    },
    "asPerDocument": {
      "north": "Details not available ",
      "east": "Details not available ",
      "south": "Details not available ",
      "west": "Details not available "
    }
  }
}
```

```
    },
    "isDisplay": false,
    "title": "Boundaries of The Flat"
  },
  "extraDetailOfProperty": "",
  "dateOfIssusApprovePlan": "As Occupancy Certificate is available it may be
assumed that the construction is as per Sanctioned Plan.",
  "approvePlanVerified": "N.A",
  "empanelledOfApprovePlan": "N.A",
  "unauthorizedConstruction": ""
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "36",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "buildingServicesDepreciatedRate": "900",
  "depreciatedCostOfConstruction": "20600.00",
  "depreciatedBuildingRate": "1600"
},
"igrRate": {
  "propertyName": "Residential Flat",
  "rate": "84680",
  "landRate": "40170",
  "igrImage": "cases/65cf293a19837c7e5fdd52d9/igr_1708334221180_Image.png",
  "squareMeterGuideLineRate": "88914.00",
  "squareFeetGuideLineRate": "8260.00"
},
"igrFinalRate": {
  "floorRatePercentage": "5",
  "depreciationPercentage": "76",
  "rate": "7174.00",
  "squareFeetGuideLineRate": "7174.00",
  "squareMeterGuideLineRate": "77215.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Tenant_Occupied",
```

```
"label": "Tenant Occupied"
},
"monthlyRent": "30,000/- Present rental income per month",
"assessmentNo": "Details not available ",
"taxPaidHolderName": "Details not available ",
"taxAmount": "Details not available ",
"electricityServiceConnectionNo": "Details not available ",
"meterCardHolderName": "Details not available ",
"undividedAreaOfLandAsPerSaleDeed": "Details not available ",
"floorSpaceIndex": " As per MCGM norms ",
"tenantName": "Mr. Ankit Das<br /> Occupied Since - Last 9 months ",
"maintenanceOfFlat": "Good "
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area ",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Stilt / Open Car Parking Space ",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  }
}
```

```
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2000",
  "fullDate": "1/1/2000"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
}
```

```
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenanceIssues": {
  "value": "1",
  "label": "Yes"
},
"visibleDamageInBuilding": {
  "value": "1",
  "label": "Yes"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "Part_Ground_and_Part_Stilt",
  "label": "Part Ground + Part Stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "24",
"totalLifeBuilding": "60",
"estimatedAge": "36",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "6",
"flatFloorNo": "6",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
```



```
"area": "784.80",
"areaType": "Built Up",
"measurementType": "Sq. Ft.",
"areaAsPer": "Carpet Area + 20%"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/65cf293a19837c7e5fdd52d9/
routeMap_1708342737017_Image.png",
    "routeLat": "19.030028",
    "routeLng": "72.888444",
    "stationName": "Wadala",
    "routeDistance": "4.7 Km. "
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "ed6don",
      "name": "ed6don",
      "image": "cases/65cf293a19837c7e5fdd52d9/
routeMap_1708342594367_Image.png"
    }
  ]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
```

```
"kitchenArrangementsRate": "0",
"totalkitchenArrangementsRate": "0",
"superfineFinishQty": "0",
"superfineFinishRate": "0",
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "13472400.00",
"finalValue": "13472400.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValueDocument": null,
"purchaseValueDocument": null,
"bookValue": "0"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Mon Feb 19 2024 17:13:43 GMT+0530 (India Standard Time)",
  "number": "2305044",
  "dayCount": "6",
  "monthCount": "266",
  "generatedBy": "64cde526dc9f3034f3fefa49"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": true
},
"rccPlinth": {
  "label": "RCC Plinth",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "5630155.00",
  "selectedBuildUpValue": "784.80",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "65d24b4a52bb6a0e76c75b06",
      "name": "externalImg_1708280648694_1708280793503_image_7.jpeg",
      "path": "cases/65cf293a19837c7e5fdd52d9/
externalImg_1708280648694_1708280793503_image_7.jpeg",
      "orientation": "landscape"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": [
    {
      "status": false,
```

```
    "_id": "65d24b4a52bb6a0e76c75b02",
    "name": "Living Room",
    "path": "cases/65cf293a19837c7e5fdd52d9/
externallmg_1708280646830_1708280793503_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65d24b7252bb6a0e76c75b5a",
    "name": "Living Room",
    "path": "cases/65cf293a19837c7e5fdd52d9/
externallmg_1708280686958_1708280834926_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65d24b7252bb6a0e76c75b59",
    "name": "Living Room",
    "path": "cases/65cf293a19837c7e5fdd52d9/
externallmg_1708280686349_1708280834926_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65d24b7252bb6a0e76c75b5d",
    "name": "Living Room",
    "path": "cases/65cf293a19837c7e5fdd52d9/
externallmg_1708280687735_1708280834926_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65d24b7252bb6a0e76c75b61",
    "name": "Living Room",
    "path": "cases/65cf293a19837c7e5fdd52d9/
externallmg_1708280689320_1708280834926_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65d24b7252bb6a0e76c75b62",
    "name": "Living Room",
    "path": "cases/65cf293a19837c7e5fdd52d9/
externallmg_1708280689680_1708280834926_image_13.jpeg",
    "orientation": "portrait"
  },
}
```

```
{
  "status": false,
  "_id": "65d24b7252bb6a0e76c75b60",
  "name": "Living Room",
  "path": "cases/65cf293a19837c7e5fdd52d9/
externallmg_1708280689048_1708280834926_image_11.jpeg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "65d24b9152bb6a0e76c75b9e",
  "name": "Living Room",
  "path": "cases/65cf293a19837c7e5fdd52d9/
externallmg_1708280719931_1708280868324_image_4.jpeg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "65d24b9152bb6a0e76c75ba0",
  "name": "Living Room",
  "path": "cases/65cf293a19837c7e5fdd52d9/
externallmg_1708280720447_1708280868324_image_6.jpeg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "65d24b9152bb6a0e76c75ba1",
  "name": "Living Room",
  "path": "cases/65cf293a19837c7e5fdd52d9/
externallmg_1708280720951_1708280868324_image_7.jpeg",
  "orientation": "landscape"
},
{
  "status": false,
  "_id": "65d24b7252bb6a0e76c75b58",
  "name": "Living Room",
  "path": "cases/65cf293a19837c7e5fdd52d9/
externallmg_1708280686040_1708280834926_image_3.jpeg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "65d24b4a52bb6a0e76c75b06",
  "name": "Living Room",
  "path": "cases/65cf293a19837c7e5fdd52d9/
externallmg_1708280648694_1708280793503_image_7.jpeg",
```

```
    "orientation": "landscape"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "18426",
    "max": "23566"
  },
  "builtUpRateRange": {
    "min": "15356",
    "max": "19638"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  }
}
```



```
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD",
  "Name": "Lead",
  "Value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "654.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3",
  "SME/TCC/221/13"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"invoices": [],
"paymentId": [],
"_id": "65cf293a19837c7e5fdd52d9",
```

```
"ownerName": "Mr. Prithviraj Anil Kumar Chavan, Mrs. Shweta Prithviraj Chavan & Smt. Shobha Anil Kumar Chavan ",
"ownerPhoneNo": "7873506151",
"appAddress": "Flat no. 26, 6th Floor, Wing - A, Mithun Enclave, Anik Village, Chembur",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "18/05/2023",
      "from": {
        "value": "Transferor",
        "label": "Transferor"
      },
      "Transferor": "Mr. Yogiraj S. Vohra & Mrs. Neeru Yogiraj Vohra ",
      "to": {
        "value": "Transferee",
        "label": "Transferee"
      },
      "Transferee": "Mr. Prithviraj Anil Kumar Chavan, Mrs. Shweta Prithviraj Chavan & Smt. Shobha Anil Kumar Chavan ",
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "10155 / 2023"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "258004",
    "path": "cases/65cf293a19837c7e5fdd52d9/document_1708075306955_1708075456219_20240216_1415.pdf",
    "fileName": "document_1708075306955_1708075456219_20240216_1415.pdf"
  },
  {
    "documentType": {
      "value": "60ae124baa6d152c1801b2fd",
      "label": "Occupancy Certificate"
    },
    "inputs": {
      "remark": " in the year 2000 issued by Municipal Corporation of Greater Mumbai",
      "number": {
```

```
    "value": "No",
    "label": "No"
  },
  "No": "not legible"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1708338085193_403737.pdf",
"path": "cases/65cf293a19837c7e5fdd52d9/
document_1708338085193_403737.pdf",
"id": "371303",
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Mon Feb 19 2024 15:51:25 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "007007",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "776431",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Feb 16 2024 14:52:02 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Prithviraj Anil Kumar Chavan, Mrs. Shweta Prithviraj Chavan & Smt.
Shobha Anil Kumar Chavan ",
    "phone": "7873506151",
    "ownershipShare": "",
    "email": "",
    "id": "748424"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "487130",
    "name": "Living Room",
    "length": "14.58",
```

```
"length1": "14",
"length2": "7",
"width": "10.00",
"width1": "10",
"width2": "00",
"totalArea": "145.83",
"images": [],
"extraAreas": [],
"finalArea": "145.83"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Kitchen",
  "length": "10.33",
  "length1": "10",
  "length2": "4",
  "width": "7.92",
  "width1": "7",
  "width2": "11",
  "totalArea": "81.81",
  "images": [],
  "extraAreas": [],
  "finalArea": "81.81"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Passage",
  "length": "4.67",
  "length1": "4",
  "length2": "8",
  "width": "6.33",
  "width1": "6",
  "width2": "4",
  "totalArea": "29.56",
  "images": [],
  "extraAreas": [
    {
      "measurementType": {
```

```
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "_id": "65d337654125726f901632f3",
  "name": "Extra ",
  "extraAreaType": "Add",
  "length": "14.58",
  "length1": "14",
  "length2": "7",
  "width": "3.50",
  "width1": "3",
  "width2": "6",
  "totalArea": "51.04"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "_id": "65d337844125726f9016339e",
  "name": "Extra ",
  "extraAreaType": "Add",
  "length": "4.42",
  "length1": "4",
  "length2": "5",
  "width": "4.00",
  "width1": "4",
  "width2": "00",
  "totalArea": "17.67"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "_id": "65d339654125726f90163594",
  "name": "EXtra ",
  "extraAreaType": "Add",
  "length": "7.58",
  "length1": "7",
  "length2": "7",
  "width": "3.50",
  "width1": "3",
  "width2": "6",
  "totalArea": "26.54"
}
```

```
],
"finalArea": "124.81"
},
{
"measurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
"id": "3",
"name": "Bedroom",
"length": "12.00",
"length1": "12",
"length2": "00",
"width": "10.08",
"width1": "10",
"width2": "1",
"totalArea": "121.00",
"images": [],
"extraAreas": [],
"finalArea": "121.00"
},
{
"measurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
"id": "4",
"name": "Bedroom",
"length": "13.17",
"length1": "13",
"length2": "2",
"width": "10.00",
"width1": "10",
"width2": "00",
"totalArea": "131.67",
"images": [],
"extraAreas": [],
"finalArea": "131.67"
},
{
"measurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
"id": "5",
"name": "Toilet",
```

```
"length": "7.00",
"length1": "7",
"length2": "00",
"width": "3.50",
"width1": "3",
"width2": "6",
"totalArea": "24.50",
"images": [],
"extraAreas": [],
"finalArea": "24.50"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Toilet",
  "length": "7.67",
  "length1": "7",
  "length2": "8",
  "width": "4.00",
  "width1": "4",
  "width2": "00",
  "totalArea": "30.67",
  "images": [],
  "extraAreas": [],
  "finalArea": "30.67"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "label": " Agreement",
      "value": "652d16a0316e1359cebd3c15"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "selectAreaTypeDocument": "Carpet",
    "squareMeterArea": "60.76",
    "totalAreaDocument": "654",
    "docBuiltpPercentage": "20",
```



```
"docFinalBuiltUp": "784.80",
"docFinalBuiltUpSquareMeter": "72.91",
"docSaleablePercentage": "",
"docFinalSaleable": "0.00",
"docFinalSaleableSquareMeter": "0.00",
"id": "256738"
}
],
"images": [],
"indicatorArr": [
{
  "printlnReport": true,
  "_id": "65d31ce8ddc2ef120ed2a716",
  "property": "Residential Flat",
  "area": "488",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "Nobroker.com",
  "expectedPrice": "11500000",
  "expectedRate": "23565.57",
  "builtUpExpectedRate": "19637.98",
  "image": "cases/65cf293a19837c7e5fdd52d9/
indicator_1708333734220_Image.png",
  "squareMeter": "45.34",
  "id": "370426"
},
{
  "printlnReport": true,
  "_id": "65d31ce8ddc2ef120ed2a717",
  "property": "Residential Flat",
  "area": "450",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "Nobroker.com",
  "expectedPrice": "9000000",
  "expectedRate": "20000.00",
  "builtUpExpectedRate": "16666.67",
  "image": "cases/65cf293a19837c7e5fdd52d9/
indicator_1708333972835_Image.png",
  "squareMeter": "41.81",
  "id": "469167"
},
}
```

```
{
  "printlnReport": true,
  "_id": "65d31ce8ddc2ef120ed2a718",
  "property": "Residential Flat",
  "area": "521",
  "builtUpPercentage": "0",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Built_Up",
  "source": "Index_no.2",
  "expectedPrice": "8000000",
  "expectedRate": "15355.09",
  "builtUpExpectedRate": "8000000",
  "image": "cases/65cf293a19837c7e5fdd52d9/
indicator_1708334016950_Image.png",
  "squareMeter": "48.40",
  "id": "856108"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d24b4a52bb6a0e76c75aff",
    "name": "externalImg_1708280644969_1708280793503_image_0.jpeg",
    "path": "cases/65cf293a19837c7e5fdd52d9/
externalImg_1708280644969_1708280793503_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d24b4a52bb6a0e76c75b00",
    "name": "externalImg_1708280645520_1708280793503_image_1.jpeg",
    "path": "cases/65cf293a19837c7e5fdd52d9/
externalImg_1708280645520_1708280793503_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d24b4a52bb6a0e76c75b01",
    "name": "externalImg_1708280646071_1708280793503_image_2.jpeg",
    "path": "cases/65cf293a19837c7e5fdd52d9/
externalImg_1708280646071_1708280793503_image_2.jpeg",
    "orientation": "portrait"
  }
]
```

```
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d24b4a52bb6a0e76c75b02",
    "name": "externallmg_1708280646830_1708280793503_image_3.jpeg",
    "path": "cases/65cf293a19837c7e5fdd52d9/
externallmg_1708280646830_1708280793503_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d24b4a52bb6a0e76c75b03",
    "name": "externallmg_1708280647353_1708280793503_image_4.jpeg",
    "path": "cases/65cf293a19837c7e5fdd52d9/
externallmg_1708280647353_1708280793503_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d24b4a52bb6a0e76c75b04",
    "name": "externallmg_1708280647731_1708280793503_image_5.jpeg",
    "path": "cases/65cf293a19837c7e5fdd52d9/
externallmg_1708280647731_1708280793503_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d24b4a52bb6a0e76c75b05",
    "name": "externallmg_1708280648192_1708280793503_image_6.jpeg",
    "path": "cases/65cf293a19837c7e5fdd52d9/
externallmg_1708280648192_1708280793503_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d24b4a52bb6a0e76c75b06",
    "name": "externallmg_1708280648694_1708280793503_image_7.jpeg",
    "path": "cases/65cf293a19837c7e5fdd52d9/
externallmg_1708280648694_1708280793503_image_7.jpeg",
    "orientation": "landscape"
  },
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65d24b4a52bb6a0e76c75b07",
  "name": "externallmg_1708280649360_1708280793503_image_8.jpeg",
  "path": "cases/65cf293a19837c7e5fdd52d9/
externallmg_1708280649360_1708280793503_image_8.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65d24b4a52bb6a0e76c75b08",
  "name": "externallmg_1708280649663_1708280793503_image_9.jpeg",
  "path": "cases/65cf293a19837c7e5fdd52d9/
externallmg_1708280649663_1708280793503_image_9.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65d24b7252bb6a0e76c75b55",
  "name": "externallmg_1708280685270_1708280834926_image_0.jpeg",
  "path": "cases/65cf293a19837c7e5fdd52d9/
externallmg_1708280685270_1708280834926_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65d24b7252bb6a0e76c75b56",
  "name": "externallmg_1708280685586_1708280834926_image_1.jpeg",
  "path": "cases/65cf293a19837c7e5fdd52d9/
externallmg_1708280685586_1708280834926_image_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65d24b7252bb6a0e76c75b57",
  "name": "externallmg_1708280685955_1708280834926_image_2.jpeg",
  "path": "cases/65cf293a19837c7e5fdd52d9/
externallmg_1708280685955_1708280834926_image_2.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d24b7252bb6a0e76c75b58",
    "name": "externallmg_1708280686040_1708280834926_image_3.jpeg",
    "path": "cases/65cf293a19837c7e5fdd52d9/
externallmg_1708280686040_1708280834926_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d24b7252bb6a0e76c75b59",
    "name": "externallmg_1708280686349_1708280834926_image_4.jpeg",
    "path": "cases/65cf293a19837c7e5fdd52d9/
externallmg_1708280686349_1708280834926_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d24b7252bb6a0e76c75b5a",
    "name": "externallmg_1708280686958_1708280834926_image_5.jpeg",
    "path": "cases/65cf293a19837c7e5fdd52d9/
externallmg_1708280686958_1708280834926_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d24b7252bb6a0e76c75b5b",
    "name": "externallmg_1708280687026_1708280834926_image_6.jpeg",
    "path": "cases/65cf293a19837c7e5fdd52d9/
externallmg_1708280687026_1708280834926_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d24b7252bb6a0e76c75b5c",
    "name": "externallmg_1708280687389_1708280834926_image_7.jpeg",
    "path": "cases/65cf293a19837c7e5fdd52d9/
externallmg_1708280687389_1708280834926_image_7.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "65d24b7252bb6a0e76c75b5d",
  "name": "externalimg_1708280687735_1708280834926_image_8.jpeg",
  "path": "cases/65cf293a19837c7e5fdd52d9/
externalimg_1708280687735_1708280834926_image_8.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65d24b7252bb6a0e76c75b5e",
  "name": "externalimg_1708280688112_1708280834926_image_9.jpeg",
  "path": "cases/65cf293a19837c7e5fdd52d9/
externalimg_1708280688112_1708280834926_image_9.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65d24b7252bb6a0e76c75b5f",
  "name": "externalimg_1708280688608_1708280834926_image_10.jpeg",
  "path": "cases/65cf293a19837c7e5fdd52d9/
externalimg_1708280688608_1708280834926_image_10.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65d24b7252bb6a0e76c75b60",
  "name": "externalimg_1708280689048_1708280834926_image_11.jpeg",
  "path": "cases/65cf293a19837c7e5fdd52d9/
externalimg_1708280689048_1708280834926_image_11.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65d24b7252bb6a0e76c75b61",
  "name": "externalimg_1708280689320_1708280834926_image_12.jpeg",
  "path": "cases/65cf293a19837c7e5fdd52d9/
externalimg_1708280689320_1708280834926_image_12.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "65d24b7252bb6a0e76c75b62",
    "name": "externallmg_1708280689680_1708280834926_image_13.jpeg",
    "path": "cases/65cf293a19837c7e5fdd52d9/
externallmg_1708280689680_1708280834926_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d24b7252bb6a0e76c75b63",
    "name": "externallmg_1708280689992_1708280834926_image_14.jpeg",
    "path": "cases/65cf293a19837c7e5fdd52d9/
externallmg_1708280689992_1708280834926_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d24b9152bb6a0e76c75b9a",
    "name": "externallmg_1708280718394_1708280868324_image_0.jpeg",
    "path": "cases/65cf293a19837c7e5fdd52d9/
externallmg_1708280718394_1708280868324_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d24b9152bb6a0e76c75b9b",
    "name": "externallmg_1708280718566_1708280868324_image_1.jpeg",
    "path": "cases/65cf293a19837c7e5fdd52d9/
externallmg_1708280718566_1708280868324_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d24b9152bb6a0e76c75b9c",
    "name": "externallmg_1708280719223_1708280868324_image_2.jpeg",
    "path": "cases/65cf293a19837c7e5fdd52d9/
externallmg_1708280719223_1708280868324_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d24b9152bb6a0e76c75b9d",
```

```
    "name": "externallmg_1708280719517_1708280868324_image_3.jpeg",
    "path": "cases/65cf293a19837c7e5fdd52d9/
externallmg_1708280719517_1708280868324_image_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d24b9152bb6a0e76c75b9e",
    "name": "externallmg_1708280719931_1708280868324_image_4.jpeg",
    "path": "cases/65cf293a19837c7e5fdd52d9/
externallmg_1708280719931_1708280868324_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d24b9152bb6a0e76c75b9f",
    "name": "externallmg_1708280720224_1708280868324_image_5.jpeg",
    "path": "cases/65cf293a19837c7e5fdd52d9/
externallmg_1708280720224_1708280868324_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d24b9152bb6a0e76c75ba0",
    "name": "externallmg_1708280720447_1708280868324_image_6.jpeg",
    "path": "cases/65cf293a19837c7e5fdd52d9/
externallmg_1708280720447_1708280868324_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d24b9152bb6a0e76c75ba1",
    "name": "externallmg_1708280720951_1708280868324_image_7.jpeg",
    "path": "cases/65cf293a19837c7e5fdd52d9/
externallmg_1708280720951_1708280868324_image_7.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65d24b2352bb6a0e76c75adc",
    "name": "externallmg_1708280610392_1708280746452_image_0.jpeg",
```



```
    "path": "cases/65cf293a19837c7e5fdd52d9/
externallmg_1708280610392_1708280746452_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65d24b2352bb6a0e76c75add",
    "name": "externallmg_1708280610557_1708280746452_image_1.jpeg",
    "path": "cases/65cf293a19837c7e5fdd52d9/
externallmg_1708280610557_1708280746452_image_1.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "Calculation Sheet NEW.xlsx",
    "filename": "1708334265988_Calculation_Sheet_NEW.xlsx",
    "path": "cases/65cf293a19837c7e5fdd52d9/
processingDocuments/1708334265988_Calculation_Sheet_NEW.xlsx",
    "size": "5410263",
    "createdAt": "Mon Feb 19 2024 14:47:46 GMT+0530 (India Standard Time)",
    "uploadedBy": "64cde526dc9f3034f3fefa49"
  },
  {
    "originalname": "WhatsApp Image 2024-02-19 at 12.32.29 PM.jpeg",
    "filename": "1708334266086_WhatsApp_Image_20240219_at_123229_PM.jpeg",
    "path": "cases/65cf293a19837c7e5fdd52d9/processingDocuments/1708334266086_
WhatsApp_Image_20240219_at_123229_PM.jpeg",
    "size": "132243",
    "createdAt": "Mon Feb 19 2024 14:47:46 GMT+0530 (India Standard Time)",
    "uploadedBy": "64cde526dc9f3034f3fefa49"
  },
  {
    "originalname": "WhatsApp Image 2024-02-19 at 12.32.30 PM.jpeg",
    "filename": "1708334266092_WhatsApp_Image_20240219_at_123230_PM.jpeg",
    "path": "cases/65cf293a19837c7e5fdd52d9/processingDocuments/1708334266092_
WhatsApp_Image_20240219_at_123230_PM.jpeg",
    "size": "403737",
    "createdAt": "Mon Feb 19 2024 14:47:46 GMT+0530 (India Standard Time)",
    "uploadedBy": "64cde526dc9f3034f3fefa49"
  }
],
"leadRemarks": [],
"audioRemarks": [],
```

```
"remarks": [],
"createdAt": "2024-02-16T09:22:02.094Z",
"updatedAt": "2024-02-19T11:55:18.176Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 26, 6th Floor, Wing - A, Mithul Enclave Co-Op. Hsg.
Soc. Ltd. , Plot No. 217, Near Mysore Colony , Mehul Road , Village - Anik, Taluka -
Kurla , District - Mumbai Suburban, Chembur , PIN - 400 074, State - Maharashtra,
Country - India",
"updatedBy": "64cde526dc9f3034f3fefa49",
"uniqueNo": "",
"addressForMap": "",
"caseReferredBy": "60b7177d2ffdf65bcd65882a",
"contactPersonName": "Mr. Ankit Das ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Tenant ",
"siteVisitContactNo": "7873506151",
"buildingServicesRate": "2500",
"finalAreaType": "Carpet Area",
"finalAsPerArea": " Agreement",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 654.00",
"flatRate": "21500",
"landOtherRate": "19000",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  },
  "roadFacing": false,
  "mall": false
},
"builtupPercentage": "10",
"carpetTotal": "660.29",
"extendOfSiteRemark": "",
"finalBuiltupArea": "726.32",
```

```

"finalCarpetArea": "660.29",
"finalSalableArea": "798.95",
"otherCarpetTotal": "0.00",
"salablePercentage": "10",
"siteMeasurementRemark": "\n",
"toBeAdded": "",
"briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + Passage + 2 Toilet",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"reportGeneratedDate": "Mon Feb 19 2024 15:17:48 GMT+0530 (India Standard Time)",
"siteVisitDate": "2024-02-18",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "0.00",
"otherCompositionSaleableTotal": "0.00"
}

```

Name	Length	Width	Total
Composition :			
Living Room	14'7"	10'00"	145.83
Kitchen	10'4"	7'11"	81.81
Passage	4'8"	6'4"	29.56
Bedroom	12'00"	10'1"	121.00
Bedroom	13'2"	10'00"	131.67
Toilet	7'00"	3'6"	24.50

Toilet	7'8"	4'00"	30.67
--------	------	-------	-------

Other
Composition :
