

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "6273b00bafd7d55eddee5f69"
    },
    "type": "CREDITOFFICER",
    "_id": "62789cf4b0d7f32a7ac19e1c",
    "firstName": "Naman Agarwal",
    "lastName": "Agarwal",
    "mobileNo": "",
    "email": "naman.agarwal@sbi.co.in",
    "workMobileNo": "9160388615"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "00",
    "discussWithPerson": "Naman Agarwal",
    "expectedFees": null,
    "quotedAmount": "2500"
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "6273b00bafd7d55eddee5f69",
  "name": "SPL PBB Fort",
  "branchCode": "4205 ",
  "mobileNo": "02223662641",
  "alternateMobileNo": "",
  "email": "sbi.04205@sbi.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Mumbai Main Branch Building, Gate no 1 Horniman Circle Mumbai
samachar marg Fort."
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
    "_id": "60af3d172ffdf65bcd6585cd",
    "role": "PICKUPPERSON",
    "firstName": "Sachin",
    "email": "sachin.joshi@vastukala.org",
    "lastName": "Joshi",
    "mobileNo": "9167204063",
    "shortName": "SJ",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\60af3d172ffdf65bcd6585cd\\
\\profilePhoto_1622372567671_Sachin Joshi Photo 3 (2).jpg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "648fcad91b499c2d52dc86f3",
    "role": "SITEENGINEER",
    "firstName": "Barkat",
    "email": "barkathodekar68@gmail.com",
    "lastName": "Hodekar",
    "mobileNo": "8879011615",
    "designation": "Site Engg",
    "shortName": "Barkat",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/648fcad91b499c2d52dc86f3/
profilePhoto_1687758876977_image.jpeg"
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
    "_id": "60f915d3f3dd69653a592199",
    "role": "MAKER + RATE VERFIER + CHEAKER",
    "firstName": "Shobha",
    "email": "shobha@vastukala.org",
    "lastName": "Kuperkar",
    "mobileNo": "9004134140",
    "designation": "",
    "shortName": "SH",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
  },
  "maker": null,
  "checker": null,
  "valuers": [
    {
      "valuersRegistrationNumber": [
        {
          "value": "IBBI/RV/07/2018/10366",
```

```
    "label": "Registered Valuer"
  }
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
```

```
    "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
    "PANNo": "AERPC9086P",
    "fatherName": "Baburao"
  }
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.10706946718335",
  "longitude": "72.92357683181763"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.92357683181763,
    19.10706946718335
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "19/02/2024 10:54 am"
    },
    {
      "dateTime": "19/02/2024 12:00 am"
    },
    {
      "dateTime": "19/02/2024 12:00 am"
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
```

```
"state": {
  "status": true,
  "name": "State",
  "key": "state",
  "value": "Maharashtra",
  "label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Vikroli",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "11",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
```

```
"value": "",
"label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Vikhroli ASPI Project 1",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
```

```
"status": false,
"name": "Street 2",
"key": "street2",
"value": "",
"label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "A2",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
```



```
"label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "1104",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
```

```
"name": "SRO",
"key": "SRO",
"value": "",
"label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
}
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "0",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "buildingServicesDepreciatedRate": "0",
  "depreciatedCostOfConstruction": "32000.00",
```

```
"depreciatedBuildingRate": "3000"
},
"igrRate": {
  "propertyName": "Residential",
  "rate": "160690",
  "landRate": "73730",
  "igrImage": "cases/65d2df1052bb6a0e76c77b65/igr_1708343266036_Image.png",
  "squareMeterGuideLineRate": "176759.00",
  "squareFeetGuideLineRate": "16421.00"
},
"igrFinalRate": {
  "floorRatePercentage": "10",
  "depreciationPercentage": "0",
  "rate": "160690.00",
  "squareMeterGuideLineRate": "176759.00",
  "squareFeetGuideLineRate": "16421.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "constructionWorkStatus": {
    "value": "InProgress",
    "label": "Under Construction"
  },
  "dateOfConstruction": {
    "fullDate": "1/1/2026",
    "date": "1",
    "month": "1",
    "year": "2026"
  },
  "typeOfStructure": {
    "value": "Proposed_R.C.C_Framed_Structure",
    "label": "Proposed R.C.C Framed Structure"
  },
  "yearOfConstructionAsPer": {
    "value": "as_per_site_information",
    "label": "As per site information"
  },
  "isSiteVisitAllowed": true,
  "ageOfBuilding": "",
  "totalLifeBuilding": "60",
  "estimatedAge": "",
  "noOfLifts": "1"
},
"finalPlinthArea": {
```

```
"area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "20971259.00",
```

```
"selectedBuildUpValue": "1277.10",
"selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "30261",
    "max": "34196"
  },
  "builtUpRateRange": {
    "min": "27510",
    "max": "31088"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  }
},
```

```
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
}
```



```
"isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "1161.00",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"invoices": [],
```

```
"paymentId": [],
"_id": "65d2df1052bb6a0e76c77b65",
"ownerName": "Anupa Shailesh Chaphekar ",
"ownerPhoneNo": "0000000000",
"appAddress": "Flat no A-2-1104,11Floor,Wing-A-2,Vikroli ASPI Project-1,LBS
Marg,Vikroli west",
"remark": "Contact person Archit Bangera +91 86553 41832\nVastukala +Yogesh
Vankar ",
"documents": [
  {
    "documentType": {
      "label": "Draft Agreement",
      "value": "60ae124aaa6d152c1801b2f8"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/65d2df1052bb6a0e76c77b65/
document_1708318390966_1708318541783_NON_RTMI_B_DRAFT_1.pdf",
    "fileName":
"document_1708318390966_1708318541783_NON_RTMI_B_DRAFT_1.pdf",
    "id": "291838",
    "uploadedBy": "60af3d172ffdf65bcd6585cd",
    "createdAt": "Mon Feb 19 2024 10:24:40 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "label": "Any Other Document",
      "value": "60ae124aaa6d152c1801b2f7"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/65d2df1052bb6a0e76c77b65/document_1708318408701_17083185
9764_Vikhroli_ASPI_Project_1P51800053072_5.pdf",
    "fileName": "document_1708318408701_1708318559764_Vikhroli_ASPI_Project_1
P51800053072_5.pdf",
    "id": "530348",
    "uploadedBy": "60af3d172ffdf65bcd6585cd",
    "createdAt": "Mon Feb 19 2024 10:24:40 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "label": "Commencement Certificate",
      "value": "60ae1247aa6d152c1801b2ea"
    },
    "isHardCopy": false,
    "displayStatus": false,
```

```
    "path": "cases/65d2df1052bb6a0e76c77b65/
document_1708318443055_1708318594406_20231228_Sale_bldg5.pdf",
    "fileName":
"document_1708318443055_1708318594406_20231228_Sale_bldg5.pdf",
    "id": "902316",
    "uploadedBy": "60af3d172ffdf65bcd6585cd",
    "createdAt": "Mon Feb 19 2024 10:24:40 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "label": "Draft Agreement",
      "value": "60ae124aaa6d152c1801b2f8"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/65d2df1052bb6a0e76c77b65/document_1708319168682_17083193
18349_2238404___Anupa_Shailesh_Chaphekar.doc",
    "fileName": "document_1708319168682_1708319318349_2238404___Anupa_Shail
esh_Chaphekar.doc",
    "id": "176470",
    "uploadedBy": "60af3d172ffdf65bcd6585cd",
    "createdAt": "Mon Feb 19 2024 10:36:12 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "007048",
"createdBy": "60af3d172ffdf65bcd6585cd",
"caseHistory": [
  {
    "id": "601842",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Mon Feb 19 2024 10:24:40 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Anupa Shailesh Chaphekar ",
    "phone": "0000000000",
    "ownershipShare": "",
    "email": "",
    "id": "359588"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
```

```
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "label": "Draft Agreement",
      "value": "60ae124aaa6d152c1801b2f8"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "selectAreaTypeDocument": "Carpet",
    "squareMeterArea": "107.86",
    "totalAreaDocument": "1161",
    "docBultupPercentage": "10",
    "docFinalBultUp": "1277.10",
    "docFinalBultUpSquareMeter": "118.65",
    "docSaleablePercentage": "",
    "docFinalSaleable": "0.00",
    "docFinalSaleableSquareMeter": "0.00",
    "id": "223152"
  }
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "65d3401c4125726f901642f1",
    "property": "Lodha Vikhroli ASPI Project 1",
    "area": "932",
    "bultUpPercentage": "10",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "floor": "Higher",
    "source": "Housing.Com",
    "expectedPrice": "31800000",
    "expectedRate": "34120.17",
    "bultUpExpectedRate": "31018.34",
    "image": "cases/65d2df1052bb6a0e76c77b65/
indicator_1708342824559_Image.png",
    "squareMeter": "86.59",
    "id": "615863"
  },
  {
```

```
"printlnReport": true,
  "_id": "65d3401c4125726f901642f2",
  "property": "Lodha Vikhroli ASPI Project 1",
  "area": "1074",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "12",
  "source": "magic_bricks",
  "expectedPrice": "32500000",
  "expectedRate": "30260.71",
  "builtUpExpectedRate": "27509.73",
  "image": "cases/65d2df1052bb6a0e76c77b65/
indicator_1708342908427_Image.png",
  "squareMeter": "99.78",
  "id": "830878"
},
{
  "printlnReport": true,
  "_id": "65d3401c4125726f901642f3",
  "property": "Lodha Vikhroli ASPI Project 1",
  "area": "1161",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "Middle",
  "source": "https://www.99acres.com/",
  "expectedPrice": "35400000",
  "expectedRate": "30490.96",
  "builtUpExpectedRate": "27719.05",
  "image": "cases/65d2df1052bb6a0e76c77b65/
indicator_1708342964714_Image.png",
  "squareMeter": "107.86",
  "id": "425398"
},
{
  "printlnReport": true,
  "_id": "65d3401c4125726f901642f4",
  "property": "Lodha Vikhroli ASPI Project 1",
  "area": "1120",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
```

```
"floor": "Higher",
"source": "https://www.proptiger.com/",
"expectedPrice": "38300000",
"expectedRate": "34196.43",
"builtUpExpectedRate": "31087.66",
"image": "cases/65d2df1052bb6a0e76c77b65/
indicator_1708343043665_Image.png",
"squareMeter": "104.05",
"id": "594648"
},
{
  "printlnReport": true,
  "_id": "65d3401c4125726f901642f5",
  "property": "Lodha Vikhroli ASPI Project 1",
  "area": "1161",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "floor": "27",
  "source": "Index_no.2",
  "expectedPrice": "35753353",
  "expectedRate": "30795.31",
  "builtUpExpectedRate": "27995.73",
  "image": "cases/65d2df1052bb6a0e76c77b65/
indicator_1708343154317_Image.png",
  "squareMeter": "107.86",
  "id": "648646"
}
],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d78c08cf7ad63a0afc2ca7",
    "name": "externallmg_1708624901209_1708625051963_image_0.jpeg",
    "path": "cases/65d2df1052bb6a0e76c77b65/
externallmg_1708624901209_1708625051963_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d78c08cf7ad63a0afc2ca8",
    "name": "externallmg_1708624901735_1708625051963_image_1.jpeg",
    "path": "cases/65d2df1052bb6a0e76c77b65/
externallmg_1708624901735_1708625051963_image_1.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65d78c08cf7ad63a0afc2ca9",
  "name": "externalImg_1708624902566_1708625051963_image_2.jpeg",
  "path": "cases/65d2df1052bb6a0e76c77b65/
externalImg_1708624902566_1708625051963_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65d78c08cf7ad63a0afc2caa",
  "name": "externalImg_1708624902995_1708625051963_image_3.jpeg",
  "path": "cases/65d2df1052bb6a0e76c77b65/
externalImg_1708624902995_1708625051963_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65d78c08cf7ad63a0afc2cab",
  "name": "externalImg_1708624903717_1708625051963_image_4.jpeg",
  "path": "cases/65d2df1052bb6a0e76c77b65/
externalImg_1708624903717_1708625051963_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "65d78ca8cf7ad63a0afc2d03",
  "name": "externalImg_1708625064074_1708625213548_image_0.jpeg",
  "path": "cases/65d2df1052bb6a0e76c77b65/
externalImg_1708625064074_1708625213548_image_0.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
```

```
    "_id": "60f915d3f3dd69653a592199",
    "role": "MAKER + RATE VERIFIER + CHEAKER",
    "firstName": "Shobha",
    "lastName": "Kuperkar",
    "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
  },
  "workType": "RATE_VERIFY",
  "display": true,
  "status": true,
  "_id": "65d33d974125726f90163cf6",
  "note": "Rate verification done",
  "taskId": "65d2e56452bb6a0e76c78da8",
  "createdAt": "2024-02-19T11:37:59.357Z"
},
{
  "createdBy": {
    "_id": "60f915d3f3dd69653a592199",
    "role": "MAKER + RATE VERIFIER + CHEAKER",
    "firstName": "Shobha",
    "lastName": "Kuperkar",
    "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
  },
  "workType": "RATE_VERIFY",
  "display": true,
  "status": true,
  "_id": "65d340224125726f901642fb",
  "note": "Rate verification done",
  "taskId": "65d2e56452bb6a0e76c78da8",
  "createdAt": "2024-02-19T11:48:50.969Z"
}
],
"createdAt": "2024-02-19T04:54:40.360Z",
"updatedAt": "2024-02-22T18:04:24.321Z",
"__v": 0,
"uniqueNo": "",
"updatedBy": "648fcad91b499c2d52dc86f3",
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"fullAddress": "Residential Flat No. 1104, 11th Floor, Wing - A2, Vikhroli ASPI Project
1, Village - Vikroli, State - Maharashtra, India",
"addressForMap": "",
"caseReferredBy": "60af3d172ffdf65bcd6585cd",
```



```

"contactPersonName": "Anupa Shailesh Chaphekar ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "0000000000",
"buildingServicesRate": "3000",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Draft Agreement",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 1161.00",
"flatRate": "32000",
"landOtherRate": "29000",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
}
}

```

Name	Length	Width	Total
Composition :			
Other Composition :			