

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b80a"
    },
    "type": "CREDITOFFICER",
    "_id": "63d11f65be948726cc1419a7",
    "email": "kaushik.datta@sbi.co.in",
    "firstName": "KAUSHUIK",
    "mobileNo": "",
    "workMobileNo": "9757023640",
    "lastName": " DATTA"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "10300000",
    "discussWithPerson": "KAUSHUIK",
    "expectedFees": 5150,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b80a",
  "branchCode": "000088",
  "type": "BRANCH",
  "name": "RACPC- Chinchpokli ",
  "email": "sbi.17889@sbi.co.in",
  "mobileNo": "022-23707514",
  "alternateMobileNo": "",
  "address": "Retail Assets Centralised Processing Centre, Mumbai South Voltas
House, 'A', 1st Floor, Dr. Ambedkar Road, Chinchpokli (East), Mumbai - 400 033, State
- Maharashtra, Country - India.\r\n",
  "ledgerName": "STATE BANK OF INDIA - CHINCHPOKALI",
  "fax": "022-23707512 / 13",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "62727444afd7d55eddee092c",
  "role": "PICKUPPERSON",
  "firstName": "Shantilal",
  "email": "shantilal@vastukala.org",
  "lastName": "Patel",
  "mobileNo": "9969039853",
  "shortName": "SHP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62727444afd7d55eddee092c/
profilePhoto_1668057663775_WhatsApp_Image_20221110_at_104853_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "60f9462345132d6a6bddb9d5",
  "role": "SITEENGINEER",
  "firstName": "Dashrath ",
  "email": "dasrat.jaiswar1234@gmail.com",
  "lastName": "Jaiswar",
  "mobileNo": "9987305468",
  "designation": "",
  "shortName": "DFJ",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": "",
  "shortName": "SK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Shym_Photo.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
```

```
"mobileNo": "9765074720",
"designation": "",
"shortName": "SK",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Shymam_Photo.jpg"
},
"checker": {
  "_id": "5fc78e26625ecd20ec1f88e9",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "firstName": "Vaishali",
  "lastName": "Sarmalkar",
  "shortName": "VS",
  "email": "v.sarmalkar@vastukala.org",
  "designation": "",
  "mobileNo": "9004437379",
  "role": "MAKER+CHECKER",
  "type": "EMPLOYEE",
  "workWithDocumentMaker": "1"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
  }
]
```

```
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "18.998783516386904",
  "longitude": "72.81987765791924"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.81987765791924,
    18.998783516386904
  ]
}
```

```
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-02-27",
      "remark": "loan amount 1.03.00.000"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-02-25",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-02-25",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
```

```
"key": "country",
"value": "India",
"label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Lower Parel",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "10",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "2",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Main",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
}
```

```
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Sai Milan Co-op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Ganpatrao Kadam Marg",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
```



```
"value": "",
"label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "B",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "295",
  "label": true
},
"blockNo": {
```

```
"status": false,
"name": "Block No",
"key": "blockNo",
"value": "",
"label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "1005",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
```

```
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "400018",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Worli",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Aluminium_Sliding_Window_",
    "label": "Aluminium Sliding Window "
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
}
```

```
"finishing": {
  "value": "Cement_Plastering",
  "label": "Cement Plastering"
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "MCGM",
    "label": "Municipal Corporation of Greater Mumbai (MCGM)"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Ganpatrao Kadam Marg",
    "west": "Victoria Tower",
    "south": "Residential Building",
    "east": "Indiabulls Blue Tower"
  },
  "asPerDocumentAgreement": {
    "north": "Details not available",
    "west": "Details not available",
    "south": "Details not available",
    "east": "Details not available"
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "Details not available",
      "east": "Details not available",
      "south": "Details not available",
      "west": "Details not available"
    },
    "asPerDocument": {
```

```
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "As Occupancy Certificate is available, we assumed that
the construction is as per approved plan.",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "N.A.",
"unauthorizedConstruction": ""
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "18",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "buildingServicesDepreciatedRate": "486",
  "depreciatedCostOfConstruction": "39014.00",
  "depreciatedBuildingRate": "2214"
},
"igrRate": {
  "propertyName": "Residential Flat",
  "rate": "283440",
  "landRate": "119060",
  "igrImage": "cases/65d4ce4dcf7ad63a0af86671/igr_1710408861586_Image.png",
  "squareMeterGuideLineRate": "297612.00",
  "squareFeetGuideLineRate": "27649.00"
},
"igrFinalRate": {
  "floorRatePercentage": "5",
  "depreciationPercentage": "88",
  "rate": "25659.00",
  "squareFeetGuideLineRate": "25659.00",
  "squareMeterGuideLineRate": "276186.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Posh",
    "label": "Posh"
  }
},
"propertyTypeOfUseList": {
  "value": "Residential_Purpose",
```

```
"label": "Residential Purpose"
},
"propertyOccupiedByList": {
  "value": "Tenant_Occupied",
  "label": "Tenant Occupied"
},
"monthlyRent": "36,000/- Present rental income per month",
"assessmentNo": "Details not available",
"taxPaidHolderName": "Details not available",
"taxAmount": "Details not available",
"electricityServiceConnectionNo": "Details not available",
"meterCardHolderName": "Details not available",
"undividedAreaOfLandAsPerSaleDeed": "N.A.",
"floorSpaceIndex": "As per MCGM norms",
"tenantName": "Arpita Avasthi",
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "N.A."
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "No",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  }
}
```

```
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2012",
  "fullDate": "1/1/2012"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C.",
  "label": "R.C.C. Framed"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
```

```
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "1",
  "label": "Yes"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "stilt",
  "label": "Stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "48",
"ageOfBuilding": "12",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "20",
"flatFloorNo": "10",
```



```
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "8"
},
"finalPlinthArea": {
  "area": "360.00",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 20%"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/65d4ce4dcf7ad63a0af86671/
routeMap_1710410904350_Image.png",
    "routeLat": "18.998091",
    "routeLng": "72.820004",
    "stationName": "Lower Parel",
    "routeDistance": "2.3 Km."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "9cp17",
      "name": "9cp17",
      "image": "cases/65d4ce4dcf7ad63a0af86671/
routeMap_1710410832767_Image.png"
    }
  ]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
```

```
"showcasesQty": "0",
"showcasesRate": "0",
"totalshowcasesRate": "0",
"kitchenArrangementsQty": "0",
"kitchenArrangementsRate": "0",
"totalkitchenArrangementsRate": "0",
"superfineFinishQty": "0",
"superfineFinishRate": "0",
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "11704200.00",
"finalValue": "11704200.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValueDocument": null,
"purchaseValueDocument": null,
"bookValue": "0"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  }
}
```

```
},
"rccPlinth": {
  "label": "RCC Plinth",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
>window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
```

```
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "9237240.00",
  "selectedBuildUpValue": "360.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "65dd51bfd99cf0e73622e23",
      "name": "externallmg_1709003197286_1709003219452_image_8.jpeg",
      "path": "cases/65d4ce4dcf7ad63a0af86671/
externallmg_1709003197286_1709003219452_image_8.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [
    {
      "status": false,
      "_id": "65dd51e8df99cf0e73622e64",
      "name": "externallmg_1709003239296_1709003392974_image_5.jpeg",
      "path": "cases/65d4ce4dcf7ad63a0af86671/
externallmg_1709003239296_1709003392974_image_5.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65dd51e8df99cf0e73622e63",
    "name": "externallmg_1709003238371_1709003392974_image_4.jpeg",
    "path": "cases/65d4ce4dcf7ad63a0af86671/
externallmg_1709003238371_1709003392974_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65dd51e8df99cf0e73622e62",
    "name": "externallmg_1709003236659_1709003392974_image_3.jpeg",
    "path": "cases/65d4ce4dcf7ad63a0af86671/
externallmg_1709003236659_1709003392974_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65dd51bfd99cf0e73622e1f",
    "name": "externallmg_1709003196717_1709003219451_image_4.jpeg",
    "path": "cases/65d4ce4dcf7ad63a0af86671/
externallmg_1709003196717_1709003219451_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65dd51bfd99cf0e73622e1c",
    "name": "externallmg_1709003196329_1709003219451_image_1.jpeg",
    "path": "cases/65d4ce4dcf7ad63a0af86671/
externallmg_1709003196329_1709003219451_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65dd51bfd99cf0e73622e27",
    "name": "externallmg_1709003197841_1709003219452_image_12.jpeg",
    "path": "cases/65d4ce4dcf7ad63a0af86671/
externallmg_1709003197841_1709003219452_image_12.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": [
```

```
{
  "status": false,
  "_id": "65dd51bdfd99cf0e73622e2c",
  "name": "Living Room",
  "path": "cases/65d4ce4dcf7ad63a0af86671/
externallmg_1709003198683_1709003219452_image_17.jpeg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "65dd51bdfd99cf0e73622e2a",
  "name": "Living Room",
  "path": "cases/65d4ce4dcf7ad63a0af86671/
externallmg_1709003198361_1709003219452_image_15.jpeg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "65dd51bdfd99cf0e73622e1e",
  "name": "Living Room",
  "path": "cases/65d4ce4dcf7ad63a0af86671/
externallmg_1709003196691_1709003219451_image_3.jpeg",
  "orientation": "portrait"
}
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "32500",
    "max": "40000"
  },
  "builtUpRateRange": {
    "min": "27084",
    "max": "33334"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
```

```
"title": "Wardrobes",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```



```
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
}
```

```
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "300.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3",
  "SME/TCC/221/13"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"invoices": [],
"paymentIds": [],
"_id": "65d4ce4dcf7ad63a0af86671",
"paymentId": [],
"ownerName": "Mr. Manan Vinodbhai Maru & Mr. Vinodkumar Premjibhai Maru",
"ownerPhoneNo": "7867307617",
"appAddress": "1095\nB wing Sai Milan co operative Housing society\nworli\nMumbai",
"remark": "loan amount 1.03.00.000",
"documents": [
  {
    "documentType": {
      "value": "60ae1246aa6d152c1801b2e4",
      "label": "Index- II"
    },
    "inputs": {
      "documentDate": "18/02/2024",
      "from": {
        "value": "Seller",
        "label": "Seller"
      },
      "Seller": "Mr. Bhawarlal Babulal Jain",
      "to": {
        "value": "Purchaser",
        "label": "Purchaser"
      },
      "Purchaser": "Mr. Manan Vinodbhai Maru & Mr. Vinodkumar Premjibhai Maru",
      "number": {
        "value": "No",
```

```
    "label": "No"
  },
  "No": "4154/2024"
},
"isHardCopy": false,
"displayStatus": true,
"id": "558207",
"path": "cases/65d4ce4dcf7ad63a0af86671/
document_1710409793239_INDEX.pdf",
"fileName": "document_1710409793239_INDEX.pdf"
},
{
  "documentType": {
    "value": "60ae1258aa6d152c1801b337",
    "label": "Full Occupation Certificate"
  },
  "inputs": {
    "documentDate": "29/05/2012",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_of_Greater_Mumbai",
      "label": "Municipal Corporation of Greater Mumbai"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "EB/2849/GS/A"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1710409973404_127103.pdf",
"path": "cases/65d4ce4dcf7ad63a0af86671/
document_1710409973404_127103.pdf",
"id": "208121",
"uploadedBy": "60eeaeddf3dd69653a581316",
"createdAt": "Thu Mar 14 2024 15:22:53 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "11/09/2008",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_of_Greater_Mumbai",
```

```
    "label": "Municipal Corporation of Greater Mumbai"
  },
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "EEBPC/2849/GS/A"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1710410035985_144832.pdf",
"path": "cases/65d4ce4dcf7ad63a0af86671/
document_1710410035985_144832.pdf",
"id": "417666",
"uploadedBy": "60eeaeddf3dd69653a581316",
"createdAt": "Thu Mar 14 2024 15:23:56 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "007088",
"createdBy": "62727444afd7d55eddee092c",
"caseHistory": [
  {
    "id": "928842",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Feb 20 2024 21:37:41 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Manan Vinodbhai Maru & Mr. Vinodkumar Premjibhai Maru",
    "phone": "7867307617",
    "ownershipShare": "",
    "email": "",
    "id": "221101"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    }
  },
  "id": "589979",
```

```
"name": "Living Room",
"length": "10.83",
"length1": "10",
"length2": "10",
"width": "10.58",
"width1": "10",
"width2": "7",
"totalArea": "114.65",
"images": [],
"extraAreas": [],
"finalArea": "114.65"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Kitchen",
  "length": "6.83",
  "length1": "6",
  "length2": "10",
  "width": "5.83",
  "width1": "5",
  "width2": "10",
  "totalArea": "39.86",
  "images": [],
  "extraAreas": [],
  "finalArea": "39.86"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Passage",
  "length": "2.83",
  "length1": "2",
  "length2": "10",
  "width": "5.17",
  "width1": "5",
  "width2": "2",
  "totalArea": "14.64",
  "images": [],
  "extraAreas": [],
```

```
"finalArea": "14.64"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Bathroom",
  "length": "3.50",
  "length1": "3",
  "length2": "6",
  "width": "4.50",
  "width1": "4",
  "width2": "6",
  "totalArea": "15.75",
  "images": [],
  "extraAreas": [],
  "finalArea": "15.75"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "WC",
  "length": "3.25",
  "length1": "3",
  "length2": "3",
  "width": "3.75",
  "width1": "3",
  "width2": "9",
  "totalArea": "12.19",
  "images": [],
  "extraAreas": [],
  "finalArea": "12.19"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Bedroom",
  "length": "8.58",
```

```
"length1": "8",
"length2": "7",
"width": "10.67",
"width1": "10",
"width2": "8",
"totalArea": "91.56",
"images": [],
"extraAreas": [],
"finalArea": "91.56"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
{
  "typeOfDocument": {
    "value": "60ae1246aa6d152c1801b2e4",
    "label": "Index- II"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "642161",
  "selectAreaTypeDocument": "Carpet",
  "totalAreaDocument": "300",
  "squareMeterArea": "27.87",
  "docFinalBuiltUp": "360",
  "docFinalBuiltUpSquareMeter": "33.444",
  "docBuiltupPercentage": "20",
  "docSaleablePercentage": "0",
  "docFinalSaleable": "0",
  "docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
{
  "printlnReport": true,
  "_id": "65f2c4a3857bdc098a9eec50",
  "property": "Residential Flat",
  "area": "300",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
```

```
"source": "Index_no.2",
"expectedPrice": "9750000",
"expectedRate": "32500.00",
"builtUpExpectedRate": "27083.33",
"image": "cases/65d4ce4dcf7ad63a0af86671/
indicator_1710408744875_Image.jpeg",
"squareMeter": "27.87",
"id": "321701"
},
{
"printlnReport": true,
"_id": "65f2c4a3857bdc098a9eec51",
"property": "Residential Flat",
"area": "300",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"source": "magic_bricks",
"expectedPrice": "12000000",
"expectedRate": "40000.00",
"builtUpExpectedRate": "33333.33",
"image": "cases/65d4ce4dcf7ad63a0af86671/
indicator_1710408761668_Image.png",
"squareMeter": "27.87",
"id": "926413"
},
{
"printlnReport": true,
"_id": "65f2c4a3857bdc098a9eec52",
"property": "Residential Flat",
"area": "310",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"source": "magic_bricks",
"expectedPrice": "12000000",
"expectedRate": "38709.68",
"builtUpExpectedRate": "32258.06",
"image": "cases/65d4ce4dcf7ad63a0af86671/
indicator_1710408776687_Image.png",
"squareMeter": "28.80",
"id": "543775"
}
],
```



```
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65dd51bdfd99cf0e73622e1b",
    "name": "externalImg_1709003196247_1709003219451_image_0.jpeg",
    "path": "cases/65d4ce4dcf7ad63a0af86671/
externalImg_1709003196247_1709003219451_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65dd51bdfd99cf0e73622e1c",
    "name": "externalImg_1709003196329_1709003219451_image_1.jpeg",
    "path": "cases/65d4ce4dcf7ad63a0af86671/
externalImg_1709003196329_1709003219451_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65dd51bdfd99cf0e73622e1d",
    "name": "externalImg_1709003196486_1709003219451_image_2.jpeg",
    "path": "cases/65d4ce4dcf7ad63a0af86671/
externalImg_1709003196486_1709003219451_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65dd51bdfd99cf0e73622e1e",
    "name": "externalImg_1709003196691_1709003219451_image_3.jpeg",
    "path": "cases/65d4ce4dcf7ad63a0af86671/
externalImg_1709003196691_1709003219451_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65dd51bdfd99cf0e73622e1f",
    "name": "externalImg_1709003196717_1709003219451_image_4.jpeg",
    "path": "cases/65d4ce4dcf7ad63a0af86671/
externalImg_1709003196717_1709003219451_image_4.jpeg",
    "orientation": "portrait"
  },
]
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65dd51bdf99cf0e73622e20",
  "name": "externallmg_1709003196862_1709003219451_image_5.jpeg",
  "path": "cases/65d4ce4dcf7ad63a0af86671/
externallmg_1709003196862_1709003219451_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65dd51bdf99cf0e73622e21",
  "name": "externallmg_1709003196957_1709003219452_image_6.jpeg",
  "path": "cases/65d4ce4dcf7ad63a0af86671/
externallmg_1709003196957_1709003219452_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65dd51bdf99cf0e73622e22",
  "name": "externallmg_1709003197166_1709003219452_image_7.jpeg",
  "path": "cases/65d4ce4dcf7ad63a0af86671/
externallmg_1709003197166_1709003219452_image_7.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65dd51bdf99cf0e73622e23",
  "name": "externallmg_1709003197286_1709003219452_image_8.jpeg",
  "path": "cases/65d4ce4dcf7ad63a0af86671/
externallmg_1709003197286_1709003219452_image_8.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65dd51bdf99cf0e73622e24",
  "name": "externallmg_1709003197516_1709003219452_image_9.jpeg",
  "path": "cases/65d4ce4dcf7ad63a0af86671/
externallmg_1709003197516_1709003219452_image_9.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65dd51bdf99cf0e73622e25",
    "name": "externallmg_1709003197634_1709003219452_image_10.jpeg",
    "path": "cases/65d4ce4dcf7ad63a0af86671/
externallmg_1709003197634_1709003219452_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65dd51bdf99cf0e73622e26",
    "name": "externallmg_1709003197791_1709003219452_image_11.jpeg",
    "path": "cases/65d4ce4dcf7ad63a0af86671/
externallmg_1709003197791_1709003219452_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65dd51bdf99cf0e73622e27",
    "name": "externallmg_1709003197841_1709003219452_image_12.jpeg",
    "path": "cases/65d4ce4dcf7ad63a0af86671/
externallmg_1709003197841_1709003219452_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65dd51bdf99cf0e73622e28",
    "name": "externallmg_1709003198106_1709003219452_image_13.jpeg",
    "path": "cases/65d4ce4dcf7ad63a0af86671/
externallmg_1709003198106_1709003219452_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65dd51bdf99cf0e73622e29",
    "name": "externallmg_1709003198197_1709003219452_image_14.jpeg",
    "path": "cases/65d4ce4dcf7ad63a0af86671/
externallmg_1709003198197_1709003219452_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "65dd51bdfd99cf0e73622e2a",
  "name": "externalimg_1709003198361_1709003219452_image_15.jpeg",
  "path": "cases/65d4ce4dcf7ad63a0af86671/
externalimg_1709003198361_1709003219452_image_15.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65dd51bdfd99cf0e73622e2b",
  "name": "externalimg_1709003198454_1709003219452_image_16.jpeg",
  "path": "cases/65d4ce4dcf7ad63a0af86671/
externalimg_1709003198454_1709003219452_image_16.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65dd51bdfd99cf0e73622e2c",
  "name": "externalimg_1709003198683_1709003219452_image_17.jpeg",
  "path": "cases/65d4ce4dcf7ad63a0af86671/
externalimg_1709003198683_1709003219452_image_17.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65dd51bdfd99cf0e73622e2d",
  "name": "externalimg_1709003198806_1709003219452_image_18.jpeg",
  "path": "cases/65d4ce4dcf7ad63a0af86671/
externalimg_1709003198806_1709003219452_image_18.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65dd51bdfd99cf0e73622e2e",
  "name": "externalimg_1709003199066_1709003219452_image_19.jpeg",
  "path": "cases/65d4ce4dcf7ad63a0af86671/
externalimg_1709003199066_1709003219452_image_19.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "65dd51e8df99cf0e73622e5f",
    "name": "externallmg_1709003233164_1709003392974_image_0.jpeg",
    "path": "cases/65d4ce4dcf7ad63a0af86671/
externallmg_1709003233164_1709003392974_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65dd51e8df99cf0e73622e60",
    "name": "externallmg_1709003234109_1709003392974_image_1.jpeg",
    "path": "cases/65d4ce4dcf7ad63a0af86671/
externallmg_1709003234109_1709003392974_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65dd51e8df99cf0e73622e61",
    "name": "externallmg_1709003235395_1709003392974_image_2.jpeg",
    "path": "cases/65d4ce4dcf7ad63a0af86671/
externallmg_1709003235395_1709003392974_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65dd51e8df99cf0e73622e62",
    "name": "externallmg_1709003236659_1709003392974_image_3.jpeg",
    "path": "cases/65d4ce4dcf7ad63a0af86671/
externallmg_1709003236659_1709003392974_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65dd51e8df99cf0e73622e63",
    "name": "externallmg_1709003238371_1709003392974_image_4.jpeg",
    "path": "cases/65d4ce4dcf7ad63a0af86671/
externallmg_1709003238371_1709003392974_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65dd51e8df99cf0e73622e64",
```

```
    "name": "externalImg_1709003239296_1709003392974_image_5.jpeg",
    "path": "cases/65d4ce4dcf7ad63a0af86671/
externalImg_1709003239296_1709003392974_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65dd51e8df99cf0e73622e65",
    "name": "externalImg_1709003239840_1709003392974_image_6.jpeg",
    "path": "cases/65d4ce4dcf7ad63a0af86671/
externalImg_1709003239840_1709003392974_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65dd50dfdf99cf0e73622ddd",
    "name": "externalImg_1709002973649_1709003133476_image_0.jpeg",
    "path": "cases/65d4ce4dcf7ad63a0af86671/
externalImg_1709002973649_1709003133476_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65dd50dfdf99cf0e73622dde",
    "name": "externalImg_1709002974209_1709003133476_image_1.jpeg",
    "path": "cases/65d4ce4dcf7ad63a0af86671/
externalImg_1709002974209_1709003133476_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65dd50dfdf99cf0e73622ddf",
    "name": "externalImg_1709002974852_1709003133476_image_2.jpeg",
    "path": "cases/65d4ce4dcf7ad63a0af86671/
externalImg_1709002974852_1709003133476_image_2.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "externalImg_1709002973649_1709003133476_image_0.jpeg",
```

```
  "filename":
"1710408891644_externallmg_1709002973649_1709003133476_image_0.jpeg",
  "path": "cases/65d4ce4dcf7ad63a0af86671/processingDocuments/1710408891644_
externallmg_1709002973649_1709003133476_image_0.jpeg",
  "size": "497141",
  "createdAt": "Thu Mar 14 2024 15:04:51 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "externallmg_1709002974209_1709003133476_image_1.jpeg",
  "filename":
"1710408891658_externallmg_1709002974209_1709003133476_image_1.jpeg",
  "path": "cases/65d4ce4dcf7ad63a0af86671/processingDocuments/1710408891658_
externallmg_1709002974209_1709003133476_image_1.jpeg",
  "size": "932121",
  "createdAt": "Thu Mar 14 2024 15:04:51 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "externallmg_1709002974852_1709003133476_image_2.jpeg",
  "filename":
"1710408891690_externallmg_1709002974852_1709003133476_image_2.jpeg",
  "path": "cases/65d4ce4dcf7ad63a0af86671/processingDocuments/1710408891690_
externallmg_1709002974852_1709003133476_image_2.jpeg",
  "size": "303618",
  "createdAt": "Thu Mar 14 2024 15:04:51 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "IGR-01.pdf",
  "filename": "1710408891707_IGR01.pdf",
  "path": "cases/65d4ce4dcf7ad63a0af86671/
processingDocuments/1710408891707_IGR01.pdf",
  "size": "155362",
  "createdAt": "Thu Mar 14 2024 15:04:51 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "IGR-02.pdf",
  "filename": "1710408891713_IGR02.pdf",
  "path": "cases/65d4ce4dcf7ad63a0af86671/
processingDocuments/1710408891713_IGR02.pdf",
  "size": "162926",
  "createdAt": "Thu Mar 14 2024 15:04:51 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
}
```

```
{
  "originalname": "IGR-03.pdf",
  "filename": "1710408891718_IGR03.pdf",
  "path": "cases/65d4ce4dcf7ad63a0af86671/
processingDocuments/1710408891718_IGR03.pdf",
  "size": "162592",
  "createdAt": "Thu Mar 14 2024 15:04:51 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "IGR-04.pdf",
  "filename": "1710408891724_IGR04.pdf",
  "path": "cases/65d4ce4dcf7ad63a0af86671/
processingDocuments/1710408891724_IGR04.pdf",
  "size": "162106",
  "createdAt": "Thu Mar 14 2024 15:04:51 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "IGR-05.pdf",
  "filename": "1710408891730_IGR05.pdf",
  "path": "cases/65d4ce4dcf7ad63a0af86671/
processingDocuments/1710408891730_IGR05.pdf",
  "size": "153996",
  "createdAt": "Thu Mar 14 2024 15:04:51 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "INDEX.pdf",
  "filename": "1710408891735_INDEX.pdf",
  "path": "cases/65d4ce4dcf7ad63a0af86671/
processingDocuments/1710408891735_INDEX.pdf",
  "size": "158785",
  "createdAt": "Thu Mar 14 2024 15:04:51 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "Summary New=MARU.xlsx",
  "filename": "1710408891741_Summary_NewMARU.xlsx",
  "path": "cases/65d4ce4dcf7ad63a0af86671/
processingDocuments/1710408891741_Summary_NewMARU.xlsx",
  "size": "2206010",
  "createdAt": "Thu Mar 14 2024 15:04:51 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
```



```
"originalname": "CC.jpeg",
"filename": "1710410994561_CC.jpeg",
"path": "cases/65d4ce4dcf7ad63a0af86671/
processingDocuments/1710410994561_CC.jpeg",
"size": "144832",
"createdAt": "Thu Mar 14 2024 15:39:54 GMT+0530 (India Standard Time)",
"uploadedBy": "60eeaeddf3dd69653a581316"
},
{
"originalname": "OC.jpeg",
"filename": "1710410994567_OC.jpeg",
"path": "cases/65d4ce4dcf7ad63a0af86671/
processingDocuments/1710410994567_OC.jpeg",
"size": "127103",
"createdAt": "Thu Mar 14 2024 15:39:54 GMT+0530 (India Standard Time)",
"uploadedBy": "60eeaeddf3dd69653a581316"
},
{
"originalname": "WhatsApp Image 2024-03-14 at 15.20.51.jpeg",
"filename": "1710410994576_WhatsApp_Image_20240314_at_152051.jpeg",
"path": "cases/65d4ce4dcf7ad63a0af86671/
processingDocuments/1710410994576_WhatsApp_Image_20240314_at_152051.jpeg",
"size": "85981",
"createdAt": "Thu Mar 14 2024 15:39:54 GMT+0530 (India Standard Time)",
"uploadedBy": "60eeaeddf3dd69653a581316"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
{
"createdBy": {
"_id": "60eeaeddf3dd69653a581316",
"role": "MAKER + RATE VERIFIER + CHEAKER",
"firstName": "Shyam",
"lastName": "Kajvilkar",
"profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Shym_Photo.jpg"
},
"workType": "RATE_VERIFY",
"display": true,
"status": true,
"_id": "65dd8da1e333566c7d303938",
"note": "Given Approx Value Rs. 1.17 Crs..... Hold for legal report.....",
"taskId": "65d56c44cf7ad63a0af86d07",
"createdAt": "2024-02-27T07:22:09.208Z"
```

```
    },
    {
      "createdBy": {
        "_id": "6006d4ce5080a310ac1fdcf2",
        "role": "ADMIN",
        "firstName": "Jagdish ",
        "lastName": "Bhatt",
        "profilePhoto": "users\\6006d4ce5080a310ac1fdcf2\\
\\profilePhoto_1622372166238_Jagdish Photo (2).jpg"
      },
      "workType": "SITE_INSPECTION",
      "display": true,
      "status": true,
      "_id": "65f2c404857bdc098a9ee8ab",
      "note": "reopen (Task Reopen)",
      "taskId": "65d56c44cf7ad63a0af86d0e",
      "createdAt": "2024-03-14T09:31:48.890Z"
    }
  ],
  "createdAt": "2024-02-20T16:07:41.229Z",
  "updatedAt": "2024-03-14T10:22:16.286Z",
  "__v": 0,
  "uniqueNo": "",
  "updatedBy": "5fc78e26625ecd20ec1f88e9",
  "assignmentType": {
    "value": "Retail",
    "label": "Retail"
  },
  "fullAddress": "Residential Flat No. 1005, 10th Floor, Building No 2, Wing - B, Sai
Milan Co-op. Hsg. Soc. Ltd., Ganpatrao Kadam Marg, Village - Lower Parel, Worli,
District - Mumbai Main, Mumbai, 400018, State - Maharashtra, India",
  "addressForMap": "",
  "caseReferredBy": "62727444afd7d55eddee092c",
  "contactPersonName": "Arpita Avasthi",
  "email": "",
  "isExternal": "false",
  "isUrgent": "false",
  "ownershipShare": "",
  "proposePurchaserName": "",
  "purchaseValueAsPerDocument": "",
  "relationWithOwner": "Tenant",
  "siteVisitContactNo": "9140124957",
  "siteVisitDate": "2024-02-25",
  "buildingServicesRate": "2700",
  "finalAreaType": "Carpet Area",
  "finalAsPerArea": "Index- II",
```

```
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 300.00",
"flatRate": "39500",
"landOtherRate": "36800",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  },
  "roadFacing": false,
  "mall": false
},
"reportGeneratedDate": "Thu Mar 14 2024 15:12:45 GMT+0530 (India Standard
Time)",
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + Passage + Bathroom +
WC",
"carpetTotal": "184.90",
"otherCarpetTotal": "0.00",
"builtupPercentage": "20",
"finalBuiltupArea": "346.38",
"finalCarpetArea": "288.65",
"finalSalableArea": "381.02",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
}
```

"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "0.00",
"otherCompositionSaleableTotal": "0.00"

}

Name	Length	Width	Total
Composition :			
Living Room	10'10"	10'7"	114.65
Kitchen	6'10"	5'10"	39.86
Passage	2'10"	5'2"	14.64
Bathroom	3'6"	4'6"	15.75
WC	3'3"	3'9"	12.19
Bedroom	8'7"	10'8"	91.56
Other Composition :			