

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856bb50"
    },
    "type": "CREDITOFFICER",
    "_id": "658679075b664a64c315b2b3",
    "firstName": "Rupesh",
    "lastName": "Juvekar",
    "mobileNo": "",
    "workMobileNo": "8169226574",
    "email": "sbi.08586@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "8500000",
    "discussWithPerson": "Rupesh",
    "expectedFees": 4250,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856bb50",
  "branchCode": "000346",
  "type": "BRANCH",
  "name": "Madam Cama Road Branch Mumabi",
  "email": "sbi.30203@sbi.co.in",
  "mobileNo": "1800 4253800",
  "alternateMobileNo": "",
  "address": "Ground Floor State Bank Annexe Madam Kama Road, Nariman Point,
Mumbai, Maharashtra 400021",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "62727444afd7d55eddee092c",
  "role": "PICKUPPERSON",
  "firstName": "Shantilal",
  "email": "shantilal@vastukala.org",
  "lastName": "Patel",
  "mobileNo": "9969039853",
  "shortName": "SHP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62727444afd7d55eddee092c/
profilePhoto_1668057663775_WhatsApp_Image_20221110_at_104853_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62ea09ea4e679b264caf07d7",
  "role": "SITEENGINEER",
  "firstName": "Suraj",
  "email": "suraj@vastukala.org",
  "lastName": "Zore",
  "mobileNo": "8652448654",
  "designation": "",
  "shortName": "SZ",
  "workWithDocumentMaker": "60092304a16fab0f2af9b0c2",
  "profilePhoto": "users/62ea09ea4e679b264caf07d7/
profilePhoto_1685629394240_image.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60f91b6f344e052188ffd1fc",
  "role": "MAKER",
  "firstName": "Jayaraja",
  "email": "jayaraja@vastukala.org",
```

```
"lastName": "Acharya",
"mobileNo": "9867664219",
"designation": "",
"shortName": "JA",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91b6f344e052188ffd1fc/
profilePhoto_1678780588416_Profile_Photo.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  {
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ]
  }
],
```

```
{
  "title": {
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.2349053384398",
  "longitude": "72.98918588368508"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.98918588368508,
```

```
19.2349053384398
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-02-23",
      "remark": "other number\n7738354640"
    }
  ],
  "schedule": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Balkum & Kolshet",
    "label": true
  },
  "floorNo": {
    "status": true,
```

```
"name": "Floor No",
"key": "floorNo",
"value": "30",
"label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "W50",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Thane",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
}
```

```
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Lodha Amara",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Clariant Compound",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Kolshet Road",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
```



```
"key": "projectName",
"value": "Lodha Amara 49 & 50",
"label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "65/1 & 51/3",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "3002",
  "label": false
},
}
```

```
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
```

```
"value": "PIN - 400 067",
"label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Thane (West)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "Proposed_R.C.C._Slab",
    "label": "Proposed R.C.C. Slab"
  },
  "flooring": {
    "value": "Proposed_Vitrified_tiles_flooring",
    "label": "Proposed Vitrified tiles flooring"
  },
  "doors": {
    "value": "Proposed_Teak_wood_door_frame_with_flush_doors",
    "label": "Proposed Teak wood door frame with flush doors"
  },
  "windows": {
    "value": "Proposed_Powder_coated_aluminium_sliding_windows",
    "label": "Proposed Powder coated aluminium sliding windows"
  },
  "fittings": {
    "value": "Proposed_Concealed_plumbing_with_C.P._fittings._Proposed_Electrical_wiring_with_Concealed.",
    "label": "Proposed Concealed plumbing with C.P. fittings. Proposed Electrical wiring with Concealed."
  },
  "finishing": {
    "value": "Proposed_Cement_Plastering",
    "label": "Proposed Cement Plastering"
  }
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
```

```
"label": "Middle Class"
},
"populationGroupList": {
  "value": "Urban",
  "label": "Urban"
},
"townplanApprovedByList": {
  "value": "Thane_Municipal_Corporation",
  "label": "Thane Municipal Corporation"
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Exit Gate / Internal Road",
  "west": "Building No. W49",
  "south": "Internal Road",
  "east": "Internal Road"
},
"asPerDocumentAgreement": {
  "north": "Information not available",
  "west": "Information not available",
  "south": "Information not available",
  "east": "Information not available"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "asPerDocument": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "As per Approved Building Plan, the composition of residential flat is Living Dining + 3 Bedrooms + Kitchen + 2 Toilets + Open Balcony + Service Area (i.e. 3 BHK with 2 Toilets)",
"dateOfIssusApprovePlan": "Copy of Approved Building Plan No. S05 / 0083 / 14 /
```

TMC / TD-DP / TPS / 4442 / 23 Dated 14.07.2023 issued by Thane Municipal Corporation.",

"approvePlanVerified": "Yes",  
"empanelledOfApprovePlan": "No",  
"unauthorizedConstruction": ""

},

"compositeRate": {

"remark": "As building is under construction, Internal visit not allowed at site. The details about the work progress status has been provided by CRM, Mr. Yogesh (Mob. No. 9004356910)",

"depreciationPercentage": "",  
"depreciationRatioOfBuilding": "",  
"salvageValue": "",  
"depreciatedCostOfConstruction": "",  
"depreciatedBuildingRate": ""

},

"igrRate": {

"propertyName": "Residential",  
"rate": "103600",  
"landRate": "33200",  
"igrImage": "cases/65d4d3ddcf7ad63a0af866fd/igr\_1708754139656\_Image.png",  
"squareMeterGuideLineRate": "119140.00",  
"squareFeetGuideLineRate": "11068.00"

},

"igrFinalRate": {

"floorRatePercentage": "15",  
"depreciationPercentage": "0",  
"rate": "103600.00",  
"squareMeterGuideLineRate": "119140.00",  
"squareFeetGuideLineRate": "11068.00"

},

"outgoingDetail": {

"areaStatusList": {  
"value": "Medium",  
"label": "Medium"

},

"propertyTypeOfUseList": {  
"value": "Residential\_Purpose",  
"label": "Residential Purpose"

},

"propertyOccupiedByList": {  
"value": "Building\_Under\_Construction",  
"label": "Building Under Construction"

},

"monthlyRent": "47,000/- Expected rental income per month after completion",  
"assessmentNo": "Information not available",

```
"taxPaidHolderName": "Information not available",
"taxAmount": "Information not available",
"electricityServiceConnectionNo": "Information not available",
"meterCardHolderName": "Information not available",
"undividedAreaOfLandAsPerSaleDeed": "Information not available",
"floorSpaceIndex": "As per TMC norms",
"tenantName": "",
"maintenanceOfFlat": "Building Under Construction"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "Proposed_R.C.C._Slab",
    "label": "Proposed R.C.C. Slab"
  },
  "partitions": {
    "value": "Proposed_6\"_Thk._Brick_Masonry",
    "label": "Proposed 6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "Proposed_Municipal_Water_Supply",
    "label": "Proposed Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Proposed,_Yes",
    "label": "Proposed, Yes"
  },
  "carParking": "Two Car Parking Space",
  "constructionWorkStatus": {
    "value": "InProgress",
    "label": "Under Construction"
  },
  "asthetikLook": {
    "value": "Proposed_Plain_Looking",
    "label": "Proposed Plain Looking"
  },
  "dateOfConstruction": {
    "date": "",
    "month": "1",
```

```
"year": "2025",
"fullDate": "1/1/2025"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"buildingSpecification": {
  "value": "Proposed_Standard",
  "label": "Proposed Standard"
},
"structuralSafety": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"protAgainstNatDis": {
  "value": "Designed_as_per_I.S._codes",
  "label": "Designed as per I.S. codes"
},
"sewerageSystem": {
  "value": "Proposed_Connected_to_Municipal_Sewerage_System_",
  "label": "Proposed Connected to Municipal Sewerage System "
},
"walls": {
  "value": "Proposed,_Yes",
  "label": "Proposed, Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
}
```

```
},
"maintenanceOfTheBuilding": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"maintenanceIssues": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"visibleDamageInBuilding": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"systemOfAirConditioning": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"provisionOfFirefighting": {
  "value": "Proposed,_Yes",
  "label": "Proposed, Yes"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "as_per_site_information",
  "label": "As per site information"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "0",
"ageOfBuilding": "0",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "40",
"flatFloorNo": "30",
"noOfLifts": "4",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
  "area": "1042.80",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 10%"
}
```



```
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/65d4d3ddcf7ad63a0af866fd/
routeMap_1708756236455_Image.png",
    "routeLat": "19.234944",
    "routeLng": "72.990833",
    "stationName": "Thane (Kopri Bridge)",
    "routeDistance": "7.9 km."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "b2umck",
      "name": "b2umck",
      "image": "cases/65d4d3ddcf7ad63a0af866fd/
routeMap_1708755966738_Image.png"
    }
  ]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",

```

```
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "18960000.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "18960000.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
```

```
"floorsCompleted": "42",
"percentage": "40",
"isHideFloor": false,
"status": true
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "42",
  "percentage": "7.00",
  "isHideFloor": false,
  "status": true
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "42",
  "percentage": "7.00",
  "isHideFloor": false,
  "status": true
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "42",
  "percentage": "3.50",
  "isHideFloor": false,
  "status": true
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "42",
  "percentage": "3.50",
  "isHideFloor": false,
  "status": true
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
}
```

```
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": true,
"status": true
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "71.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "11541710.00",
  "selectedBuildUpValue": "1042.80",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "65d8b417df99cf0e735e2000",
      "name": "externalImg_r_1708700685911_1708700766869_image_7.jpg",
      "path": "cases/65d4d3ddcf7ad63a0af866fd/
externalImg_r_1708700685911_1708700766869_image_7.jpg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "65d8b417df99cf0e735e2002",
      "name": "externalImg_r_1708700684125_1708700766869_image_6.jpg",
      "path": "cases/65d4d3ddcf7ad63a0af866fd/
externalImg_r_1708700684125_1708700766869_image_6.jpg",
      "orientation": "landscape"
    }
  ],
  "externalPhotos": [
    {
      "status": false,
      "_id": "65d8b417df99cf0e735e1ffc",
      "name": "externalImg_r_1708700677687_1708700766869_image_3.jpg",
      "path": "cases/65d4d3ddcf7ad63a0af866fd/
externalImg_r_1708700677687_1708700766869_image_3.jpg",
      "orientation": "portrait"
    }
  ]
}
```

```
    },
    {
      "status": false,
      "_id": "65d8b417df99cf0e735e1ffe",
      "name": "externallmg_r_1708700672418_1708700766869_image_1.jpg",
      "path": "cases/65d4d3ddcf7ad63a0af866fd/
externallmg_r_1708700672418_1708700766869_image_1.jpg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "65d8b417df99cf0e735e2005",
      "name": "externallmg_r_1708700691395_1708700766869_image_10.jpg",
      "path": "cases/65d4d3ddcf7ad63a0af866fd/
externallmg_r_1708700691395_1708700766869_image_10.jpg",
      "orientation": "portrait"
    }
  ],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "19561",
    "max": "21399"
  },
  "builtUpRateRange": {
    "min": "17783",
    "max": "19454"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
```



```
"label": "Lead",
"value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": false,
"finalValuationArea": "948.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3",
  "SME/TCC/221/13"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"invoices": [],
"paymentId": [],
"_id": "65d4d3ddcf7ad63a0af866fd",
"ownerName": "Savita Singh",
"ownerPhoneNo": "9004356910",
"appAddress": "3002\nLodha Amara\nkolset Road\nBalkum\nThane",
"remark": "other number\n7738354640",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "15/01/2024",
      "remark": "(5 Pages from Agreement)",
      "from": {
        "value": "Company",
        "label": "Company"
      },
      "Company": "Macrotech Developers Limited",
      "to": {
        "value": "Purchaser",
        "label": "Purchaser"
      },
      "Purchaser": "Savita Singh & Pravin Kumar Singh",
      "number": {
        "value": "Registration_No",
        "label": "Registration No"
      },
      "Registration_No": "1483/2024"
    },
    "isHardCopy": false,
```

```
    "displayStatus": true,
    "id": "634271",
    "path": "cases/65d4d3ddcf7ad63a0af866fd/
document_1708446650529_1708446801253_New_Doc_02202024_1927.pdf",
    "fileName":
"document_1708446650529_1708446801253_New_Doc_02202024_1927.pdf"
  },
  {
    "documentType": {
      "value": "60ae129faa6d152c1801b47d",
      "label": "RERA Certificate"
    },
    "inputs": {
      "documentDate": "29/03/2019",
      "nameOfApprovingAuthority": {
        "value": "Maharashtra_Real_Estate_Regulatory_Authority",
        "label": "Maharashtra Real Estate Regulatory Authority"
      },
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "P51700020157"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "fileName": "document_1708758971308_P51700020157.pdf",
    "path": "cases/65d4d3ddcf7ad63a0af866fd/
document_1708758971308_P51700020157.pdf",
    "id": "842866",
    "uploadedBy": "60f91b6f344e052188ffd1fc",
    "createdAt": "Sat Feb 24 2024 12:46:11 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae1247aa6d152c1801b2ea",
      "label": "Commencement Certificate"
    },
    "inputs": {
      "documentDate": "14/07/2023",
      "nameOfApprovingAuthority": {
        "value": "Thane_Municipal_Corporation",
        "label": "Thane Municipal Corporation"
      },
      "number": {
        "value": "No",
```

```
    "label": "No"
  },
  "No": "New S05 / 0083 / 14 / TMC / TDD / 4442 / 23"
},
"isHardCopy": false,
"displayStatus": true,
"id": "743925",
"path": "cases/65d4d3ddcf7ad63a0af866fd/document_1708759180383_5_Commencement_Certificates___NA_Order_for_plotted_development.pdf",
"fileName": "document_1708759180383_5_Commencement_Certificates___NA_Order_for_plotted_development.pdf"
},
{
  "documentType": {
    "value": "60ae1277aa6d152c1801b3cc",
    "label": "Approved Building Plan"
  },
  "inputs": {
    "documentDate": "14/07/2023",
    "nameOfApprovingAuthority": {
      "value": "Thane_Municipal_Corporation",
      "label": "Thane Municipal Corporation"
    },
    "remark": "(Downloaded from RERA Site)",
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "S05 / 0083 / 14 / TMC / TD-DP / TPS / 4442 / 23"
},
"isHardCopy": false,
"displayStatus": true,
"id": "957798",
"path": "cases/65d4d3ddcf7ad63a0af866fd/document_1708759862157_16_Building_Plan_Approval_IOD.pdf",
"fileName": "document_1708759862157_16_Building_Plan_Approval_IOD.pdf"
}
],
"caseNumber": "007089",
"createdBy": "62727444afd7d55eddee092c",
"caseHistory": [
  {
    "id": "867168",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Feb 20 2024 22:01:25 GMT+0530 (India Standard Time)"
  }
]
```

```
}
],
"owners": [
  {
    "name": "Savita Singh",
    "phone": "9004356910",
    "ownershipShare": "",
    "email": "",
    "id": "323216"
  },
  {
    "name": "Pravin Kumar Singh",
    "phone": "",
    "email": "",
    "ownershipShare": "",
    "id": "831264"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "selectAreaTypeDocument": "Carpet",
    "squareMeterArea": "88.07",
    "totalAreaDocument": "948",
    "docBuiltpupPercentage": "10",
    "docFinalBuiltpup": "1042.80",
    "docFinalBuiltpupSquareMeter": "96.88",
    "docSaleablePercentage": "",
    "docFinalSaleable": "0.00",
    "docFinalSaleableSquareMeter": "0.00",
    "id": "257171"
  }
],
"images": [],
```

```
"indicatorArr": [  
  {  
    "printlnReport": true,  
    "_id": "65d98516df99cf0e735eac6e",  
    "property": "Lodha Amara, Thane West",  
    "area": "950",  
    "builtUpPercentage": "10",  
    "saleablePercentage": "0",  
    "rateType": "price_Indicator",  
    "areaType": "Carpet",  
    "floor": "24",  
    "source": "magic_bricks",  
    "expectedPrice": "18800000",  
    "expectedRate": "19789.47",  
    "builtUpExpectedRate": "17990.43",  
    "image": "cases/65d4d3ddcf7ad63a0af866fd/  
indicator_1708753822693_Image.png",  
    "squareMeter": "88.26",  
    "id": "504408"  
  },  
  {  
    "printlnReport": true,  
    "_id": "65d98516df99cf0e735eac6f",  
    "property": "Lodha Amara, Thane West",  
    "area": "958",  
    "builtUpPercentage": "10",  
    "saleablePercentage": "0",  
    "rateType": "price_Indicator",  
    "areaType": "Carpet",  
    "floor": "15",  
    "source": "magic_bricks",  
    "expectedPrice": "20500000",  
    "expectedRate": "21398.75",  
    "builtUpExpectedRate": "19453.41",  
    "image": "cases/65d4d3ddcf7ad63a0af866fd/  
indicator_1708753872812_Image.png",  
    "squareMeter": "89.00",  
    "id": "539171"  
  },  
  {  
    "printlnReport": true,  
    "_id": "65d98516df99cf0e735eac70",  
    "property": "Lodha Amara, Thane West",  
    "area": "955",  
    "builtUpPercentage": "10",  
    "saleablePercentage": "0",
```

```
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "24",
"source": "https://www.99acres.com/",
"expectedPrice": "19800000",
"expectedRate": "20732.98",
"builtUpExpectedRate": "18848.17",
"image": "cases/65d4d3ddcf7ad63a0af866fd/
indicator_1708753937064_Image.png",
"squareMeter": "88.72",
"id": "773972"
},
{
  "printlnReport": true,
  "_id": "65d98516df99cf0e735eac71",
  "property": "Lodha Amara, Thane West",
  "area": "955",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "floor": "2",
  "source": "Index_no.2",
  "expectedPrice": "18680637",
  "expectedRate": "19560.88",
  "builtUpExpectedRate": "17782.61",
  "image": "cases/65d4d3ddcf7ad63a0af866fd/
indicator_1708754046518_Image.png",
  "squareMeter": "88.72",
  "id": "139398"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d8b417df99cf0e735e1ffc",
    "name": "externalImg_r_1708700677687_1708700766869_image_3.jpg",
    "path": "cases/65d4d3ddcf7ad63a0af866fd/
externalImg_r_1708700677687_1708700766869_image_3.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d8b417df99cf0e735e1ffd",
```

```
    "name": "externallmg_r_1708700670122_1708700766869_image_0.jpg",
    "path": "cases/65d4d3ddcf7ad63a0af866fd/
externallmg_r_1708700670122_1708700766869_image_0.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d8b417df99cf0e735e1ffe",
    "name": "externallmg_r_1708700672418_1708700766869_image_1.jpg",
    "path": "cases/65d4d3ddcf7ad63a0af866fd/
externallmg_r_1708700672418_1708700766869_image_1.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d8b417df99cf0e735e1fff",
    "name": "externallmg_r_1708700675450_1708700766869_image_2.jpg",
    "path": "cases/65d4d3ddcf7ad63a0af866fd/
externallmg_r_1708700675450_1708700766869_image_2.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d8b417df99cf0e735e2000",
    "name": "externallmg_r_1708700685911_1708700766869_image_7.jpg",
    "path": "cases/65d4d3ddcf7ad63a0af866fd/
externallmg_r_1708700685911_1708700766869_image_7.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d8b417df99cf0e735e2001",
    "name": "externallmg_r_1708700679974_1708700766869_image_4.jpg",
    "path": "cases/65d4d3ddcf7ad63a0af866fd/
externallmg_r_1708700679974_1708700766869_image_4.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d8b417df99cf0e735e2002",
    "name": "externallmg_r_1708700684125_1708700766869_image_6.jpg",
```

```
    "path": "cases/65d4d3ddcf7ad63a0af866fd/
externallmg_r_1708700684125_1708700766869_image_6.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d8b417df99cf0e735e2003",
    "name": "externallmg_r_1708700682206_1708700766869_image_5.jpg",
    "path": "cases/65d4d3ddcf7ad63a0af866fd/
externallmg_r_1708700682206_1708700766869_image_5.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d8b417df99cf0e735e2004",
    "name": "externallmg_r_1708700687023_1708700766869_image_8.jpg",
    "path": "cases/65d4d3ddcf7ad63a0af866fd/
externallmg_r_1708700687023_1708700766869_image_8.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d8b417df99cf0e735e2005",
    "name": "externallmg_r_1708700691395_1708700766869_image_10.jpg",
    "path": "cases/65d4d3ddcf7ad63a0af866fd/
externallmg_r_1708700691395_1708700766869_image_10.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d8b417df99cf0e735e2006",
    "name": "externallmg_r_1708700689329_1708700766869_image_9.jpg",
    "path": "cases/65d4d3ddcf7ad63a0af866fd/
externallmg_r_1708700689329_1708700766869_image_9.jpg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65d8b420df99cf0e735e201d",
    "name": "externallmg_r_1708700703789_1708700736199_image_1.png",
    "path": "cases/65d4d3ddcf7ad63a0af866fd/
externallmg_r_1708700703789_1708700736199_image_1.png",
```



```
"orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "65d8b420df99cf0e735e201e",
  "name": "externallmg_r_1708700702373_1708700736199_image_0.jpg",
  "path": "cases/65d4d3ddcf7ad63a0af866fd/
externallmg_r_1708700702373_1708700736199_image_0.jpg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "1703485696220_Calculation_1_2.xlsx",
    "filename": "1708754218379_1703485696220_Calculation_1_2.xlsx",
    "path": "cases/65d4d3ddcf7ad63a0af866fd/
processingDocuments/1708754218379_1703485696220_Calculation_1_2.xlsx",
    "size": "3170546",
    "createdAt": "Sat Feb 24 2024 11:26:59 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f915d3f3dd69653a592199"
  },
  {
    "originalname": "5 Commencement Certificates _ NA Order for plotted
development.pdf",
    "filename": "1708761294800_5_Commencement_Certificates___NA_Order_for_plot
ted_development.pdf",
    "path": "cases/65d4d3ddcf7ad63a0af866fd/processingDocuments/1708761294800_
5_Commencement_Certificates___NA_Order_for_plotted_development.pdf",
    "size": "1339854",
    "createdAt": "Sat Feb 24 2024 13:24:54 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
  {
    "originalname": "16 Building Plan Approval (IOD).pdf",
    "filename": "1708761294820_16_Building_Plan_Approval_IOD.pdf",
    "path": "cases/65d4d3ddcf7ad63a0af866fd/
processingDocuments/1708761294820_16_Building_Plan_Approval_IOD.pdf",
    "size": "1052478",
    "createdAt": "Sat Feb 24 2024 13:24:54 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
  {
    "originalname": "Google Location.png",
    "filename": "1708761294835_Google_Location.png",
```

```
    "path": "cases/65d4d3ddcf7ad63a0af866fd/
processingDocuments/1708761294835_Google_Location.png",
    "size": "3250853",
    "createdAt": "Sat Feb 24 2024 13:24:54 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
  {
    "originalname": "Sale Dee - 2024.pdf",
    "filename": "1708761294874_Sale_Deer__2024.pdf",
    "path": "cases/65d4d3ddcf7ad63a0af866fd/
processingDocuments/1708761294874_Sale_Deer__2024.pdf",
    "size": "5752934",
    "createdAt": "Sat Feb 24 2024 13:24:54 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
  {
    "originalname": "Site Details.jpg",
    "filename": "1708761294943_Site_Details.jpg",
    "path": "cases/65d4d3ddcf7ad63a0af866fd/
processingDocuments/1708761294943_Site_Details.jpg",
    "size": "1673028",
    "createdAt": "Sat Feb 24 2024 13:24:54 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  }
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "60f915d3f3dd69653a592199",
      "role": "MAKER + RATE VERIFIER + CHEAKER",
      "firstName": "Shobha",
      "lastName": "Kuperkar",
      "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "65d7191fcf7ad63a0afb6a9e",
    "note": "Rate verification done, visit pending",
    "taskId": "65d56b54cf7ad63a0af86ba6",
    "createdAt": "2024-02-22T09:51:27.159Z"
  },
  {
```

```
"createdBy": {
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Shobha",
  "lastName": "Kuperkar",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"workType": "RATE_VERIFY",
"display": true,
"status": true,
"_id": "65d98558df99cf0e735ead83",
"note": "Please report making Yogesh Vankar also",
"taskId": "65d56b54cf7ad63a0af86ba6",
"createdAt": "2024-02-24T05:57:44.615Z"
}
],
"createdAt": "2024-02-20T16:31:25.786Z",
"updatedAt": "2024-02-24T09:42:47.117Z",
"__v": 0,
"uniqueNo": "",
"updatedBy": "60f915d3f3dd69653a592199",
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 3002, 30th Floor, Building No W50, Lodha Amara,
Lodha Amara 49 & 50, Clariant Compound, Kolshet Road, Village - Balkum & Kolshet,
Thane (West), Taluka - Thane, District - Thane, PIN - 400 067, State - Maharashtra,
India",
"addressForMap": "",
"caseReferredBy": "62727444afd7d55eddee092c",
"contactPersonName": "Mr. Yogesh",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Customer Relationship Manager",
"siteVisitContactNo": "9004356910",
"buildingServicesRate": "2800",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement For Sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
```

```

"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 948.00",
"flatRate": "20000",
"landOtherRate": "17200",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
"builtupPercentage": "10",
"carpetTotal": "0",
"extendOfSiteRemark": "Carpet Area in Sq. Ft. = 865.00\nEBVT Area in Sq. Ft. =
83.00",
"finalBuiltupArea": "0.00",
"finalCarpetArea": "0.00",
"finalSalableArea": "0.00",
"otherCarpetTotal": "0",
"salablePercentage": "10",
"siteMeasurementRemark": "",
"toBeAdded": "",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
}
}

```

Name	Length	Width	Total
Composition :			

Other  
Composition :

---