

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "MSME Loan",
    "value": "MSME_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7cc"
    },
    "type": "CREDITOFFICER",
    "_id": "655c87b25586e008158f7000",
    "firstName": "Anju",
    "lastName": "Rajdev",
    "mobileNo": "",
    "workMobileNo": "7291316555",
    "email": "anju.rajdev@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "10000000",
    "discussWithPerson": "Anju",
    "expectedFees": 5000,
    "quotedAmount": "5000"
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7cc",
  "branchCode": "13340",
  "type": "BRANCH",
  "name": "SME Chembur Branch",
  "email": "sbi.13340@sbi.co.in",
  "mobileNo": "02225273906",
  "alternateMobileNo": "02225273907",
  "address": "Unit No. 11, (BLDG NO. 11), Ground Floor, Corporate Park, Sion-
Trombay Road, Chembur, Mumbai – 400 071, State – Maharashtra, Country – India.",
  "ledgerName": "",
  "fax": "02225274524",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60b7177d2ffdf65bcd65882a",
  "role": "PICKUPPERSON",
  "firstName": "Saurabh",
  "email": "saurabhvelonde143@gmail.com",
  "lastName": "Velonde",
  "mobileNo": "8691048846",
  "shortName": "SSV",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1686816492317_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62ea09ea4e679b264caf07d7",
  "role": "SITEENGINEER",
  "firstName": "Suraj",
  "email": "suraj@vastukala.org",
  "lastName": "Zore",
  "mobileNo": "8652448654",
  "designation": "",
  "shortName": "SZ",
  "workWithDocumentMaker": "60092304a16fab0f2af9b0c2",
  "profilePhoto": "users/62ea09ea4e679b264caf07d7/
profilePhoto_1685629394240_image.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "9004437379",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "62fe044a48a26047e6552796",
  "role": "MAKER",
  "firstName": "Pradnya ",
  "email": "pradnya@vastukala.org",
```

```
"lastName": "Rasam",
"mobileNo": "9529385821",
"designation": "",
"shortName": "PR",
"workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
"profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "9004437379",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
  },

```

```
{
  "title": {
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.21682809825011",
  "longitude": "72.98106492389068"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.98106492389068,
```

```
19.21682809825011
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-02-23",
      "remark": "Vastukala + Vankar"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-02-23",
      "remark": "MANUAL_IN_TASK"
    }
  ],
  "schedule": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "Country - India",
    "label": false
  },
}
```

```
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Panchpakhadi ",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "5",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane ",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Thane (West)",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
```

```
"value": "Thane ",
"label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "464",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Parijat Sundervan Co-Op. Hsg. Soc. Ltd. ",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Ramchandra Nagar No. 3, Off. Samata Nagar Road ",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Wagle Estate ",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
```



```
"status": true,
"name": "Wing",
"key": "wing",
"value": "C",
"label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Sundervan Park ",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
```

```
"label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "502",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
```

```
"name": "Gut No.",
"key": "GUTNo",
"value": "",
"label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 604",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows_with_M._S._Grills",
    "label": "Powder coated Aluminum sliding windows with M. S. Grills"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering_+_POP_Finish",
    "label": "Cement Plastering + POP Finish"
  }
}
```

```
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "Thane_Municipal_Corporation",
    "label": "Thane Municipal Corporation"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "New Gulmohar CHSL ",
    "west": "Gagangiri Park Building ",
    "south": "Road No. 33Z",
    "east": "Jasmin Building "
  },
  "asPerDocumentAgreement": {
    "north": "Details not available ",
    "west": "Details not available ",
    "south": "Details not available ",
    "east": "Details not available "
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "Details not available ",
      "east": "Details not available ",
      "south": "Details not available ",
      "west": "Details not available "
    },
    "asPerDocument": {
      "north": "Details not available ",
      "east": "Details not available ",
      "south": "Details not available ",
      "west": "Details not available "
    }
  }
}
```

```
    },
    "isDisplay": false,
    "title": "Boundaries of The Flat"
  },
  "extraDetailOfProperty": "",
  "dateOfIssusApprovePlan": "As Occupancy Certificate is available it may be
assumed that the construction is as per Sanctioned Plan.",
  "approvePlanVerified": "N.A",
  "empanelledOfApprovePlan": "N.A",
  "unauthorizedConstruction": ""
},
"compositeRate": {
  "remark": "As per actual site measurement, the Carpet Area is 472.00 Sq. Ft. & Built-
up Area mentioned is the agreement is 615.00 Sq. Ft. The loading on carpet to built-up
is 30%, hence, we have adjusted the rate accordingly.",
  "depreciationPercentage": "45",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "14375",
  "depreciatedBuildingRate": "1375"
},
"igrRate": {
  "propertyName": "Flat",
  "rate": "101800",
  "landRate": "46000",
  "igrImage": "cases/65d5963ecf7ad63a0af8d181/igr_1709021199190_Image.png",
  "squareMeterGuideLineRate": "106890.00",
  "squareFeetGuideLineRate": "9930.00"
},
"igrFinalRate": {
  "floorRatePercentage": "5",
  "depreciationPercentage": "70",
  "rate": "8233.00",
  "squareFeetGuideLineRate": "8233.00",
  "squareMeterGuideLineRate": "88623.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
```

```
"value": "Tenant_Occupied",
"label": "Tenant Occupied"
},
"monthlyRent": "26,000/- Present Rental income per month ",
"assessmentNo": "Details not available ",
"taxPaidHolderName": "Details not available ",
"taxAmount": "Details not available ",
"electricityServiceConnectionNo": "Details not available ",
"meterCardHolderName": "Details not available ",
"undividedAreaOfLandAsPerSaleDeed": "Details not available ",
"floorSpaceIndex": "As per TMC norms ",
"tenantName": "Miss. Priyalla Pinto<br /> Occupied Since - Last 13 Months ",
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area ",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Stilt Car Parking Space ",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
```

```
"label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "1994",
  "fullDate": "1/1/1994"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
```

```
"label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "1",
  "label": "Yes"
},
"visibleDamageInBuilding": {
  "value": "1",
  "label": "Yes"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "Part_Ground_and_Part_Stilt",
  "label": "Part Ground + Part Stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "30",
"ageOfBuilding": "30",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "6",
"flatFloorNo": "5",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "6"
},
```



```
"finalPlinthArea": {
  "area": "615.00",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area as per Agreement"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/65d5963ecf7ad63a0af8d181/
routeMap_1709028076824_Image.png",
    "routeLat": "19.203861",
    "routeLng": "72.961167",
    "stationName": "Thane ",
    "routeDistance": "4.7 Km. "
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "s4tt5c",
      "name": "s4tt5c",
      "image": "cases/65d5963ecf7ad63a0af8d181/
routeMap_1709027991074_Image.png"
    }
  ]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
```

```
"kitchenArrangementsQty": "0",
"kitchenArrangementsRate": "0",
"totalkitchenArrangementsRate": "0",
"superfineFinishQty": "0",
"superfineFinishRate": "0",
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "8840625.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "8840625.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Tue Feb 27 2024 15:50:34 GMT+0530 (India Standard Time)",
  "number": "2305182",
  "dayCount": "13",
  "monthCount": "404",
  "generatedBy": "5fc78e26625ecd20ec1f88e9"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  }
}
```

```
},
"rccPlinth": {
  "label": "RCC Plinth",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
>window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
```

```
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "5063295.00",
  "selectedBuildUpValue": "615.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "65d8bc80df99cf0e735e2131",
      "name": "externalImg_r_1708702842147_1708702953101_image_12.jpg",
      "path": "cases/65d5963ecf7ad63a0af8d181/
externalImg_r_1708702842147_1708702953101_image_12.jpg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": [
    {
      "status": false,
      "_id": "65d8bc80df99cf0e735e2125",
```

```
    "name": "Living Room",
    "path": "cases/65d5963ecf7ad63a0af8d181/
externallmg_r_1708702829300_1708702953101_image_2.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65d8bc80df99cf0e735e2124",
    "name": "Living Room",
    "path": "cases/65d5963ecf7ad63a0af8d181/
externallmg_r_1708702830600_1708702953101_image_3.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65d8bc80df99cf0e735e2126",
    "name": "Living Room",
    "path": "cases/65d5963ecf7ad63a0af8d181/
externallmg_r_1708702826950_1708702953101_image_0.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65d8bc80df99cf0e735e212a",
    "name": "Living Room",
    "path": "cases/65d5963ecf7ad63a0af8d181/
externallmg_r_1708702835996_1708702953101_image_7.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65d8bc80df99cf0e735e212b",
    "name": "Living Room",
    "path": "cases/65d5963ecf7ad63a0af8d181/
externallmg_r_1708702834226_1708702953101_image_6.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65d8bc80df99cf0e735e2128",
    "name": "Living Room",
    "path": "cases/65d5963ecf7ad63a0af8d181/
externallmg_r_1708702831664_1708702953101_image_4.jpg",
    "orientation": "portrait"
  },
  {
```

```
    "status": false,
    "_id": "65d8bc80df99cf0e735e212e",
    "name": "Living Room",
    "path": "cases/65d5963ecf7ad63a0af8d181/
externallmg_r_1708702837143_1708702953101_image_8.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65d8bc80df99cf0e735e212c",
    "name": "Living Room",
    "path": "cases/65d5963ecf7ad63a0af8d181/
externallmg_r_1708702838439_1708702953101_image_9.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65d8bc80df99cf0e735e212f",
    "name": "Living Room",
    "path": "cases/65d5963ecf7ad63a0af8d181/
externallmg_r_1708702840639_1708702953101_image_11.jpg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "65d8bc80df99cf0e735e2131",
    "name": "Living Room",
    "path": "cases/65d5963ecf7ad63a0af8d181/
externallmg_r_1708702842147_1708702953101_image_12.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65d8bc80df99cf0e735e2132",
    "name": "Living Room",
    "path": "cases/65d5963ecf7ad63a0af8d181/
externallmg_r_1708702844665_1708702953101_image_14.jpg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "1556",
    "max": "18750"
  }
},
```

```
"builtUpRateRange": {
  "min": "14142",
  "max": "15625"
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
}
```



```
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
```

```
    "isEditable": false
  }
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "615.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3",
  "SME/TCC/221/13"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"invoices": [],
"paymentId": [],
"_id": "65d5963ecf7ad63a0af8d181",
"ownerName": "Mr. Krushnath Vishnu Deokar & Mrs. Chanda Krushnath Deokar ",
"ownerPhoneNo": "9892176676",
"appAddress": "Unit no. C-502, 5th Floor, Parijat Building, Sundervan Park,
Panchpakhadi, Thane ",
"remark": "Vastukala + Vankar",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    }
  },

```

```
"inputs": {
  "documentDate": "07/04/2002",
  "from": {
    "value": "Vendor",
    "label": "Vendor"
  },
  "Vendor": "Mr. Raman Arunachalam Iyer & Mrs. Leela Raman Iyer ",
  "to": {
    "value": "Purchaser",
    "label": "Purchaser"
  },
  "Purchaser": "Mr. Krushnath Vishnu Deokar & Mrs. Chanda Krushnath Deokar ",
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "21941 / 2000"
},
"isHardCopy": false,
"displayStatus": true,
"id": "863748",
"path": "cases/65d5963ecf7ad63a0af8d181/
document_1708496342649_1708496496540_Krishnat_Deokar__C502.pdf",
"fileName":
"document_1708496342649_1708496496540_Krishnat_Deokar__C502.pdf"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "21/10/1994",
    "nameOfApprovingAuthority": {
      "value": "Thane_Municipal_Corporation",
      "label": "Thane Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "T.M.C / TBD / 2092"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1709026252230_260529.pdf",
```

```
"path": "cases/65d5963ecf7ad63a0af8d181/
document_1709026252230_260529.pdf",
"id": "301482",
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Tue Feb 27 2024 15:00:52 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1248aa6d152c1801b2ef",
    "label": "Society Share Certificate"
  },
  "inputs": {
    "documentDate": "18/06/2004",
    "remark": " issued by Parijat Sundervan Co-Op. Hsg. Soc. Ltd",
    "to": {
      "value": "Purchasers",
      "label": "Purchasers"
    },
    "Purchasers": "Mr. Krushnath Vishnu Deokar & Mrs. Chanda Krushnath Deokar ",
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "30"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "id": "253245",
  "path": "cases/65d5963ecf7ad63a0af8d181/document_1709026370581_document_
1708496342649_1708496496540_Krishnat_Deokar__C502.pdf",
  "fileName": "document_1709026370581_document_1708496342649_17084964965
40_Krishnat_Deokar__C502.pdf"
}
],
"caseNumber": "007094",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "897979",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Feb 21 2024 11:50:46 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
```

```
"name": "Mr. Krushnath Vishnu Deokar & Mrs. Chanda Krushnath Deokar ",
"phone": "9892176676",
"ownershipShare": "",
"email": "",
"id": "615739"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
{
"measurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
"id": "697719",
"name": "Living Room",
"length": "10.17",
"length1": "10",
"length2": "2",
"width": "17.25",
"width1": "17",
"width2": "3",
"totalArea": "175.37",
"images": [],
"extraAreas": [],
"finalArea": "175.37"
},
{
"measurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
"id": "1",
"name": "Kitchen",
"length": "10.42",
"length1": "10",
"length2": "5",
"width": "8.17",
"width1": "8",
"width2": "2",
"totalArea": "85.07",
"images": [],
"extraAreas": [],
"finalArea": "85.07"
},
}
```

```
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Bedroom",
  "length": "13.17",
  "length1": "13",
  "length2": "2",
  "width": "9.83",
  "width1": "9",
  "width2": "10",
  "totalArea": "129.47",
  "images": [],
  "extraAreas": [],
  "finalArea": "129.47"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Passage",
  "length": "4.42",
  "length1": "4",
  "length2": "5",
  "width": "7.42",
  "width1": "7",
  "width2": "5",
  "totalArea": "32.76",
  "images": [],
  "extraAreas": [],
  "finalArea": "32.76"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "WC",
  "length": "2.75",
  "length1": "2",
  "length2": "9",
```

```
"width": "5.50",
"width1": "5",
"width2": "6",
"totalArea": "15.12",
"images": [],
"extraAreas": [],
"finalArea": "15.12"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Bathroom",
  "length": "3.75",
  "length1": "3",
  "length2": "9",
  "width": "5.42",
  "width1": "5",
  "width2": "5",
  "totalArea": "20.31",
  "images": [],
  "extraAreas": [],
  "finalArea": "20.31"
}
],
"otherComposition": [
  {
    "toBeAdded": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "name": {
      "label": "Cupboard",
      "value": "Cupboard"
    },
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "0",
    "length": "6.67",
    "length1": "6",
    "length2": "8",
    "width": "2.17",
```

```
"width1": "2",
"width2": "2",
"totalArea": "14.44",
"images": [],
"extraAreas": [],
"finalArea": "14.44",
"percentageBeforeTotal": "14.44",
"percentage": "100"
}
],
"externalReport": [],
"documentPerArea": [
{
  "typeOfDocument": {
    "label": " Agreement",
    "value": "652d16a0316e1359cebd3c15"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "selectAreaTypeDocument": "Built_Up",
  "squareMeterArea": "57.14",
  "totalAreaDocument": "615",
  "docBUILTUPPercentage": "",
  "docFinalBUILTUP": "0.00",
  "docFinalBUILTUPSquareMeter": "0.00",
  "docSaleablePercentage": "0",
  "docFinalSaleable": "0.00",
  "docFinalSaleableSquareMeter": "0.00",
  "id": "264205"
}
],
"images": [],
"indicatorArr": [
{
  "printlnReport": true,
  "_id": "65dd9848e333566c7d30685a",
  "property": "Flat",
  "area": "615",
  "builtUpPercentage": "0",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Built_Up",
  "floor": "3",
  "source": "Index_no.2",
```



```
    "expectedPrice": "8697000.00",
    "expectedRate": "14141.46",
    "builtUpExpectedRate": "8697000.00",
    "image": "cases/65d5963ecf7ad63a0af8d181/
indicator_1709021015001_Image.png",
    "squareMeter": "57.14",
    "id": "594705"
  },
  {
    "printlnReport": true,
    "_id": "65dd9848e333566c7d30685b",
    "property": "Flat",
    "area": "480",
    "builtUpPercentage": "20",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "source": "Nobroker.com",
    "expectedPrice": "9000000",
    "expectedRate": "18750.00",
    "builtUpExpectedRate": "15625.00",
    "image": "cases/65d5963ecf7ad63a0af8d181/
indicator_1709021045487_Image.png",
    "squareMeter": "44.59",
    "id": "955528"
  },
  {
    "printlnReport": true,
    "_id": "65dd9848e333566c7d30685c",
    "property": "Flat",
    "area": "370",
    "builtUpPercentage": "20",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "source": "square_yards",
    "expectedPrice": "6500000",
    "expectedRate": "17567.57",
    "builtUpExpectedRate": "14639.64",
    "image": "cases/65d5963ecf7ad63a0af8d181/
indicator_1709021077199_Image.png",
    "squareMeter": "34.37",
    "id": "954986"
  }
],
"externallImages": [
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65d8bc80df99cf0e735e2124",
  "name": "externallmg_r_1708702830600_1708702953101_image_3.jpg",
  "path": "cases/65d5963ecf7ad63a0af8d181/
externallmg_r_1708702830600_1708702953101_image_3.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65d8bc80df99cf0e735e2125",
  "name": "externallmg_r_1708702829300_1708702953101_image_2.jpg",
  "path": "cases/65d5963ecf7ad63a0af8d181/
externallmg_r_1708702829300_1708702953101_image_2.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65d8bc80df99cf0e735e2126",
  "name": "externallmg_r_1708702826950_1708702953101_image_0.jpg",
  "path": "cases/65d5963ecf7ad63a0af8d181/
externallmg_r_1708702826950_1708702953101_image_0.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65d8bc80df99cf0e735e2127",
  "name": "externallmg_r_1708702828227_1708702953101_image_1.jpg",
  "path": "cases/65d5963ecf7ad63a0af8d181/
externallmg_r_1708702828227_1708702953101_image_1.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65d8bc80df99cf0e735e2128",
  "name": "externallmg_r_1708702831664_1708702953101_image_4.jpg",
  "path": "cases/65d5963ecf7ad63a0af8d181/
externallmg_r_1708702831664_1708702953101_image_4.jpg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d8bc80df99cf0e735e2129",
    "name": "externallmg_r_1708702833027_1708702953101_image_5.jpg",
    "path": "cases/65d5963ecf7ad63a0af8d181/
externallmg_r_1708702833027_1708702953101_image_5.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d8bc80df99cf0e735e212a",
    "name": "externallmg_r_1708702835996_1708702953101_image_7.jpg",
    "path": "cases/65d5963ecf7ad63a0af8d181/
externallmg_r_1708702835996_1708702953101_image_7.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d8bc80df99cf0e735e212b",
    "name": "externallmg_r_1708702834226_1708702953101_image_6.jpg",
    "path": "cases/65d5963ecf7ad63a0af8d181/
externallmg_r_1708702834226_1708702953101_image_6.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d8bc80df99cf0e735e212c",
    "name": "externallmg_r_1708702838439_1708702953101_image_9.jpg",
    "path": "cases/65d5963ecf7ad63a0af8d181/
externallmg_r_1708702838439_1708702953101_image_9.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d8bc80df99cf0e735e212d",
    "name": "externallmg_r_1708702839531_1708702953101_image_10.jpg",
    "path": "cases/65d5963ecf7ad63a0af8d181/
externallmg_r_1708702839531_1708702953101_image_10.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "65d8bc80df99cf0e735e212e",
    "name": "externallmg_r_1708702837143_1708702953101_image_8.jpg",
    "path": "cases/65d5963ecf7ad63a0af8d181/
externallmg_r_1708702837143_1708702953101_image_8.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d8bc80df99cf0e735e212f",
    "name": "externallmg_r_1708702840639_1708702953101_image_11.jpg",
    "path": "cases/65d5963ecf7ad63a0af8d181/
externallmg_r_1708702840639_1708702953101_image_11.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d8bc80df99cf0e735e2130",
    "name": "externallmg_r_1708702843476_1708702953101_image_13.jpg",
    "path": "cases/65d5963ecf7ad63a0af8d181/
externallmg_r_1708702843476_1708702953101_image_13.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d8bc80df99cf0e735e2131",
    "name": "externallmg_r_1708702842147_1708702953101_image_12.jpg",
    "path": "cases/65d5963ecf7ad63a0af8d181/
externallmg_r_1708702842147_1708702953101_image_12.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d8bc80df99cf0e735e2132",
    "name": "externallmg_r_1708702844665_1708702953101_image_14.jpg",
    "path": "cases/65d5963ecf7ad63a0af8d181/
externallmg_r_1708702844665_1708702953101_image_14.jpg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
```

```
    "_id": "65d8bc34df99cf0e735e2113",
    "name": "externalimg_r_1708702770451_1708702925548_image_1.png",
    "path": "cases/65d5963ecf7ad63a0af8d181/
externalimg_r_1708702770451_1708702925548_image_1.png",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65d8bc34df99cf0e735e2114",
    "name": "externalimg_r_1708702770695_1708702925548_image_2.jpg",
    "path": "cases/65d5963ecf7ad63a0af8d181/
externalimg_r_1708702770695_1708702925548_image_2.jpg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65d8bc34df99cf0e735e2115",
    "name": "externalimg_r_1708702768029_1708702925548_image_0.jpg",
    "path": "cases/65d5963ecf7ad63a0af8d181/
externalimg_r_1708702768029_1708702925548_image_0.jpg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "Calculation (2)- deokar.xlsx",
    "filename": "1709021297705_Calculation_2_deokar.xlsx",
    "path": "cases/65d5963ecf7ad63a0af8d181/
processingDocuments/1709021297705_Calculation_2_deokar.xlsx",
    "size": "16012",
    "createdAt": "Tue Feb 27 2024 13:38:18 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "igr1.pdf",
    "filename": "1709021297708_igr1.pdf",
    "path": "cases/65d5963ecf7ad63a0af8d181/
processingDocuments/1709021297708_igr1.pdf",
    "size": "435426",
    "createdAt": "Tue Feb 27 2024 13:38:18 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
```

```
    "originalname": "igr2.pdf",
    "filename": "1709021297739_igr2.pdf",
    "path": "cases/65d5963ecf7ad63a0af8d181/
processingDocuments/1709021297739_igr2.pdf",
    "size": "563060",
    "createdAt": "Tue Feb 27 2024 13:38:18 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "igr3.pdf",
    "filename": "1709021297786_igr3.pdf",
    "path": "cases/65d5963ecf7ad63a0af8d181/
processingDocuments/1709021297786_igr3.pdf",
    "size": "385550",
    "createdAt": "Tue Feb 27 2024 13:38:18 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "OC.jpeg",
    "filename": "1709021297819_OC.jpeg",
    "path": "cases/65d5963ecf7ad63a0af8d181/
processingDocuments/1709021297819_OC.jpeg",
    "size": "260529",
    "createdAt": "Tue Feb 27 2024 13:38:18 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "Summary - deokar.xlsx",
    "filename": "1709021297841_Summary__deokar.xlsx",
    "path": "cases/65d5963ecf7ad63a0af8d181/
processingDocuments/1709021297841_Summary__deokar.xlsx",
    "size": "2233946",
    "createdAt": "Tue Feb 27 2024 13:38:18 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  }
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-02-21T06:20:46.354Z",
"updatedAt": "2024-02-27T11:54:20.530Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
}
```

"fullAddress": "Residential Flat No. 502, 5th Floor, Wing - C, Parijat Sundervan Co-Op. Hsg. Soc. Ltd. , Sundervan Park , Plot No. 464, Ramchandra Nagar No. 3, Off. Samata Nagar Road , Wagle Estate , Village - Panchpakhadi , Taluka - Thane , District - Thane , Thane (West), PIN - 400 604, State - Maharashtra, Country - India",
"updatedBy": "5fc78e26625ecd20ec1f88e9",
"addressForMap": "",
"caseReferredBy": "60b7177d2ffdf65bcd65882a",
"contactPersonName": "Miss. Priyalla Pinto ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Tenant ",
"siteVisitContactNo": "9892176676",
"buildingServicesRate": "2500",
"finalAreaType": "Built Up Area",
"finalAsPerArea": " Agreement",
"finalBuiltUpPercentage": "0",
"finalCarpetConvertToBuiltUpPer": "0",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 615.00",
"flatRate": "15500",
"landOtherRate": "13000",
"shopDetails": {
 "typeOfShops": null,
 "roadFacing": false,
 "mall": false
},
"builtupPercentage": "10",
"carpetTotal": "458.10",
"extendOfSiteRemark": "",
"finalBuiltupArea": "519.79",
"finalCarpetArea": "472.54",
"finalSalableArea": "571.77",
"otherCarpetTotal": "14.44",
"salablePercentage": "10",
"siteMeasurementRemark": "Carpet Area in Sq. Ft. = 458.00\nCup Board Area in Sq. Ft. = 14.00",
"toBeAdded": "",
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + Passage + WC + Bathroom",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "14.44",
"otherCompositionSaleableTotal": "0.00",

```

"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"reportGeneratedDate": "Tue Feb 27 2024 13:43:45 GMT+0530 (India Standard Time)",
"siteVisitDate": "2024-02-23"
}

```

Name	Length	Width	Total
Composition :			
Living Room	10'2"	17'3"	175.37
Kitchen	10'5"	8'2"	85.07
Bedroom	13'2"	9'10"	129.47
Passage	4'5"	7'5"	32.76
WC	2'9"	5'6"	15.12
Bathroom	3'9"	5'5"	20.31
Other Composition :			
Cupboard	6'8"	2'2"	14.44