

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "65d5cf3ccf7ad63a0af97598"
    },
    "type": "CREDITOFFICER",
    "_id": "65d5cf3ccf7ad63a0af9759a",
    "firstName": "Sagar",
    "lastName": "Harane",
    "mobileNo": "",
    "workMobileNo": "7715029159",
    "email": "sagar.harane@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "65d5cf3ccf7ad63a0af97598",
  "name": "Racpc Wkadewadi ",
  "branchCode": "",
  "mobileNo": "020-25618207",
  "alternateMobileNo": "",
  "email": "sagar.harane@sbi.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "\"Tara Chambers\", Wakdewadi, Pune-Mumbai Road, Pune - 411 003,
State - Maharashtra, Country - India.\n"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
  "_id": "6006d4ce5080a310ac1fd2",
  "role": "ADMIN",
  "firstName": "Jagdish ",
  "email": "jagdish.bhatt@vastukala.org",
  "lastName": "Bhatt",
  "mobileNo": "8425864014",
  "shortName": "JB",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\6006d4ce5080a310ac1fd2\\
\\profilePhoto_1622372166238_Jagdish Photo (2).jpg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62ea09ea4e679b264caf07d7",
  "role": "SITEENGINEER",
  "firstName": "Suraj",
  "email": "suraj@vastukala.org",
  "lastName": "Zore",
  "mobileNo": "8652448654",
  "designation": "",
  "shortName": "SZ",
  "workWithDocumentMaker": "60092304a16fab0f2af9b0c2",
  "profilePhoto": "users/62ea09ea4e679b264caf07d7/
profilePhoto_1685629394240_image.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "9004437379",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\\
\\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60f91b6f344e052188ffd1fc",
  "role": "MAKER",
  "firstName": "Jayaraja",
  "email": "jayaraja@vastukala.org",
  "lastName": "Acharya",
```

```
"mobileNo": "9867664219",
"designation": "",
"shortName": "JA",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91b6f344e052188ffd1fc/
profilePhoto_1678780588416_Profile_Photo.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "9004437379",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\\
\\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  {
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ]
  }
]
```

```
"title": {
  "value": "FIIV",
  "label": "FIIV"
},
"_id": "60af80072ffdf65bcd658652",
"number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.131083011594527",
  "longitude": "72.9310716236384"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
}
```

```
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-02-22",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-02-22",
      "remark": "MANUAL_IN_TASK"
    }
  ],
  "schedule": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Kanjur",
  }
}
```

```
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "39",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Suburban",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Mulund",
  "label": true
},
"plotNo": {
  "status": false,
```

```
"name": "Plot No.",
"key": "plotNo",
"value": "",
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Tower - F, Sunflower Runwal Bliss",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Crompton Greaves Compound",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Kanjurmarg Station Road",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
}
```



```
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "676, 1004(pt), 1005(pt), 1005/1, 1006, 1007(pt), 1007/1-4(pt), 1008(pt),
1008/1, 1009(pt), 1009/1-6(pt), 1010(pt), 1011(pt), 1013(pt), 1014(pt), 1014/1-6(pt),
1017(pt), 1017/1-6(pt), 1018(pt), 1018/1-9(pt)",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
```

```
"status": true,
"name": "Flat / Unit / Office / Gala No.",
"key": "selectNo",
"value": "F-3904",
"label": false
},
"municipalityWardNo": {
  "status": true,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "S",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
```

```
"label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 042",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Kanjurmarg (East)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "Proposed_R.C.C._Slab",
    "label": "Proposed R.C.C. Slab"
  },
  "flooring": {
    "value": "Proposed_Vitrified_tiles_flooring",
    "label": "Proposed Vitrified tiles flooring"
  },
  "doors": {
    "value": "Proposed_Teak_wood_door_frame_with_flush_doors",
    "label": "Proposed Teak wood door frame with flush doors"
  },
  "windows": {
    "value": "Proposed_Powder_coated_aluminium_sliding_windows",
    "label": "Proposed Powder coated aluminium sliding windows"
  },
  "fittings": {
    "value": "Proposed_Concealed_plumbing_with_C.P._fittings._Proposed_Electrical_wiring_with_Concealed.",
    "label": "Proposed Concealed plumbing with C.P. fittings. Proposed Electrical wiring with Concealed."
  },
  "finishing": {
    "value": "Proposed_Cement_Plastering",
    "label": "Proposed Cement Plastering"
  }
}
},
"general": {
```

```
"ownership": {
  "value": "Joint_Ownership",
  "label": "Joint Ownership"
},
"populationClassList": {
  "value": "MiddleClass",
  "label": "Middle Class"
},
"populationGroupList": {
  "value": "Urban",
  "label": "Urban"
},
"townplanApprovedByList": {
  "value": "MCGM",
  "label": "Municipal Corporation of Greater Mumbai (MCGM)"
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Runwal Bliss - A Wing, IVY Tower / Veer Savarkar Road",
  "west": "'G' Wing of Sunflower Runwal Bliss",
  "south": "Slum Area",
  "east": "Runwal Bliss E Wing Jasmine"
},
"asPerDocumentAgreement": {
  "north": "Dattar Colony / Municipal Road",
  "west": "Land belongs to Railways and proposed DP Road",
  "south": "Land belongs to Susneh Infrapark Pvt. Ltd.",
  "east": "Dattar Colony / Municipal Road"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "asPerDocument": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  }
},
"isDisplay": false,
```

```
"title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "As per Approved Building Plan, the composition of
residential flat is Living Room + 2 Bedrooms + 2 Study Room + Kitchen + 3 Toilets +
Utility + Passage (i.e. 3 BHK with 3 Toilets)",
"dateOfIssusApprovePlan": "Copy of Approved Building Plan No. CHE / ES / 1699 /
S / 337 (NEW) / 337/ / 16 / Amend Dated 27.03.2023 issued by Municipal Corporation
of Greater Mumbai (Downloaded from RERA site)",
"approvePlanVerified": "Yes",
"empanelledOfApprovePlan": "No",
"unauthorizedConstruction": ""
},
"compositeRate": {
"remark": "",
"depreciationPercentage": "0",
"depreciationRatioOfBuilding": "",
"salvageValue": "",
"buildingServicesDepreciatedRate": "0",
"depreciatedCostOfConstruction": "26200.00",
"depreciatedBuildingRate": "3000"
},
"igrRate": {
"propertyName": "Flat",
"rate": "161790",
"landRate": "70480",
"igrImage": "cases/65d5d1a9cf7ad63a0af9818f/igr_1708597351241_Image.png",
"squareMeterGuideLineRate": "129432.00",
"squareFeetGuideLineRate": "12025.00"
},
"igrFinalRate": {
"floorRatePercentage": "80",
"depreciationPercentage": "0",
"rate": "161790.00",
"squareMeterGuideLineRate": "129432.00",
"squareFeetGuideLineRate": "12025.00"
},
"outgoingDetail": {
"areaStatusList": {
"value": "Medium",
"label": "Medium"
},
"propertyTypeOfUseList": {
"value": "Residential_Purpose",
"label": "Residential Purpose"
},
"propertyOccupiedByList": {
```

```
"value": "Building_Under_Construction",
"label": "Building Under Construction"
},
"monthlyRent": "76,000/- Expected rental income per month after completion",
"assessmentNo": "Information not available",
"taxPaidHolderName": "Information not available",
"taxAmount": "Information not available",
"electricityServiceConnectionNo": "Information not available",
"meterCardHolderName": "Information not available",
"undividedAreaOfLandAsPerSaleDeed": "Information not available",
"floorSpaceIndex": "As per MCGM norms",
"tenantName": "",
"maintenanceOfFlat": "Building Under Construction"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "Proposed_R.C.C._Slab",
    "label": "Proposed R.C.C. Slab"
  },
  "partitions": {
    "value": "Proposed_6\"_Thk._Brick_Masonry",
    "label": "Proposed 6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "Proposed_Municipal_Water_Supply",
    "label": "Proposed Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Proposed,_Yes",
    "label": "Proposed, Yes"
  },
  "carParking": "Proposed 2 Car Parking Space",
  "constructionWorkStatus": {
    "value": "InProgress",
    "label": "Under Construction"
  },
  "asthetikLook": {
    "value": "Proposed_Plain_Looking",
```

```
"label": "Proposed Plain Looking"
},
"dateOfConstruction": {
  "date": "",
  "month": "1",
  "year": "2026",
  "fullDate": "1/1/2026"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "Proposed_R.C.C_Framed_Structure",
  "label": "Proposed R.C.C Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"materialUsedList": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"buildingSpecification": {
  "value": "Proposed_Standard",
  "label": "Proposed Standard"
},
"structuralSafety": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "Proposed_Connected_to_Municipal_Sewerage_System_",
  "label": "Proposed Connected to Municipal Sewerage System "
},
"walls": {
  "value": "Proposed,_Yes",
```

```
"label": "Proposed, Yes"
},
"appearanceOfTheBuilding": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"maintenanceOfTheBuilding": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"maintenanceIssues": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"visibleDamageInBuilding": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"systemOfAirConditioning": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"provisionOfFirefighting": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"groundStilt": {
  "value": "stilt",
  "label": "Stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_site_information",
  "label": "As per site information"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "0",
"ageOfBuilding": "0",
"noOfBasement": "2",
"noOfPodium": "4",
"noOfAmenityFloors": "",
"noOfFloors": "47",
"flatFloorNo": "39",
"noOfLifts": "5",
"noOfDwellingUnitsInBuilding": "6"
},
```



```
"finalPlinthArea": {
  "area": "1271.60",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/65d5d1a9cf7ad63a0af9818f/
routeMap_1708598731190_Image.png",
    "routeLat": "19.132812",
    "routeLng": "72.934632",
    "stationName": "Kanjurmarg",
    "routeDistance": "900m"
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "sk4hw",
      "name": "sk4hw",
      "image": "cases/65d5d1a9cf7ad63a0af9818f/
routeMap_1708598550646_Image.png"
    }
  ]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
```

```
"kitchenArrangementsQty": "0",
"kitchenArrangementsRate": "0",
"totalkitchenArrangementsRate": "0",
"superfineFinishQty": "0",
"superfineFinishRate": "0",
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "30287200.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "30287200.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Thu Feb 22 2024 17:46:03 GMT+0530 (India Standard Time)",
  "number": "2305111",
  "dayCount": "24",
  "monthCount": "333",
  "generatedBy": "5fc78e26625ecd20ec1f88e9"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  }
}
```

```
},
"rccPlinth": {
  "label": "RCC Plinth",
  "floorsCompleted": "Complete",
  "percentage": "5",
  "isHideFloor": false,
  "status": true
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "5",
  "percentage": "3.6363636363636367",
  "isHideFloor": false,
  "status": true
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
>window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
```

```
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "13.64",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "22935849.00",
  "selectedBuildUpValue": "1271.60",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "65d71b16cf7ad63a0afb75fb",
      "name": "externallmg_r_1708595985412_1708596134308_image_3.jpg",
      "path": "cases/65d5d1a9cf7ad63a0af9818f/
externallmg_r_1708595985412_1708596134308_image_3.jpg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "65d71b16cf7ad63a0afb75fe",
      "name": "externallmg_r_1708595988652_1708596134308_image_5.jpg",
      "path": "cases/65d5d1a9cf7ad63a0af9818f/
externallmg_r_1708595988652_1708596134308_image_5.jpg",
      "orientation": "landscape"
    }
  ]
}
```

```
}
],
"externalPhotos": [
  {
    "status": false,
    "_id": "65d71b16cf7ad63a0afb75fa",
    "name": "externallmg_r_1708595979817_1708596134308_image_0.jpg",
    "path": "cases/65d5d1a9cf7ad63a0af9818f/
externallmg_r_1708595979817_1708596134308_image_0.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65d71b16cf7ad63a0afb75fc",
    "name": "externallmg_r_1708595983290_1708596134308_image_2.jpg",
    "path": "cases/65d5d1a9cf7ad63a0af9818f/
externallmg_r_1708595983290_1708596134308_image_2.jpg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "25105",
    "max": "27622"
  },
  "builtUpRateRange": {
    "min": "22824",
    "max": "25111"
  }
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
```

```
"title": "Extra collapsible gates / grill works etc",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "true",
```



```
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "1156.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3",
  "SME/TCC/221/13"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"invoices": [],
"paymentId": [],
"_id": "65d5d1a9cf7ad63a0af9818f",
"ownerName": "Rahul Bhardwaj",
"ownerPhoneNo": "9619820359",
"ownershipShare": "",
"email": "",
"siteVisitContactNo": "9653256964",
"contactPersonName": "Ms. Isha",
"purchaseValueAsPerDocument": "0",
"owners": [
  {
    "name": "Rahul Bhardwaj",
    "phone": "9619820359",
    "ownershipShare": "",
    "email": "",
    "id": "541690"
  },
  {
    "name": "Vijayeta Sharma",
    "phone": "",
    "email": "",
    "ownershipShare": "",
    "id": "709322"
  }
],
"caseReferredBy": "6006d4ce5080a310ac1fdcf2",
"relationWithOwner": "Sales Person",
"fullAddress": "Residential Flat No. F-3904, 39th Floor, Tower - F, Sunflower Runwal Bliss, Crompton Greaves Compound, Kanjurmarg Station Road, Village - Kanjur, Municipality Ward No. 'S', Kanjurmarg (East), Taluka - Mulund, District - Mumbai
```

```
Suburban, PIN - 400 042, State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "10/02/2024",
      "from": {
        "value": "Promoter",
        "label": "Promoter"
      },
      "Promoter": "Evie Real Estate Private Limited",
      "to": {
        "value": "Allottee",
        "label": "Allottee"
      },
      "Allottee": "Rahul Bhardwaj & Vijayeta Sharma",
      "number": {
        "value": "Registration_No",
        "label": "Registration No"
      },
      "Registration_No": "2903/2024"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "585537",
    "path": "cases/65d5d1a9cf7ad63a0af9818f/
document_1708511543781_AGREEMENT_PART_1.pdf",
    "fileName": "document_1708511543781_AGREEMENT_PART_1.pdf"
  },
  {
    "documentType": {
      "value": "60ae1247aa6d152c1801b2ea",
      "label": "Commencement Certificate"
    },
    "inputs": {
      "documentDate": "18/12/2023",
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "CHE / ES / 1699 / S / 337 (NEW) / FCC / 8 /Amend"
    }
  },

```

```
"isHardCopy": false,
"displayStatus": true,
"id": "371668",
"path": "cases/65d5d1a9cf7ad63a0af9818f/document_1708601725710_CC.pdf",
"fileName": "document_1708601725710_CC.pdf"
},
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
    "label": "RERA Certificate"
  },
  "inputs": {
    "documentDate": "02/02/2022",
    "nameOfApprovingAuthority": {
      "value": "Maharashtra_Real_Estate_Regulatory_Authority",
      "label": "Maharashtra Real Estate Regulatory Authority"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "P51800032824"
},
"document_1708601812459_RERA_Certificate.pdf",
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1708601812459_RERA_Certificate.pdf",
"path": "cases/65d5d1a9cf7ad63a0af9818f/
document_1708601812459_RERA_Certificate.pdf",
"id": "759020",
"uploadedBy": "60f91b6f344e052188ffd1fc",
"createdAt": "Thu Feb 22 2024 17:06:52 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "18/12/2023",
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "CHE / ES / 1699 / S / 337 (NEW) / FCC / 8 /Amend"
},
"document_1708601812459_RERA_Certificate.pdf",
"isHardCopy": false,
```

```
"displayStatus": true,
"fileName": "document_1708602474988_4_Commencement_Certificates___NA_Order_for_plotted_development.pdf",
"path": "cases/65d5d1a9cf7ad63a0af9818f/document_1708602474988_4_Commencement_Certificates___NA_Order_for_plotted_development.pdf",
"id": "174228",
"uploadedBy": "60f91b6f344e052188ffd1fc",
"createdAt": "Thu Feb 22 2024 17:17:55 GMT+0530 (India Standard Time)"
},
{
"documentType": {
"value": "60ae1277aa6d152c1801b3cc",
"label": "Approved Building Plan"
},
"inputs": {
"documentDate": "27/03/2023",
"nameOfApprovingAuthority": {
"value": "Municipal_Corporation_of_Greater_Mumbai",
"label": "Municipal Corporation of Greater Mumbai"
},
"remark": "(Downloaded from RERA site)",
"number": {
"value": "No",
"label": "No"
},
"No": "CHE / ES / 1699 / S / 337 (NEW) / 337 / / 16 / Amend"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1708603836965_48_Building_Plan_Approval___NA_Order_for_plotted_development.pdf",
"path": "cases/65d5d1a9cf7ad63a0af9818f/document_1708603836965_48_Building_Plan_Approval___NA_Order_for_plotted_development.pdf",
"id": "982870",
"uploadedBy": "60f91b6f344e052188ffd1fc",
"createdAt": "Thu Feb 22 2024 17:40:37 GMT+0530 (India Standard Time)"
}
],
"isUrgent": "false",
"isExternal": "false",
"proposePurchaserName": "",
"assignmentType": {
"value": "Retail",
"label": "Retail"
},
"scheduleSiteVisitDate": "Invalid date",
```

```
"caseNumber": "007102",
"createdBy": "6006d4ce5080a310ac1fdfc2",
"caseHistory": [
  {
    "id": "410486",
    "title": "Create Case",
    "description": "Create Case",
    "datetime": "Wed Feb 21 2024 16:04:17 GMT+0530 (India Standard Time)"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "selectAreaTypeDocument": "Carpet",
    "squareMeterArea": "107.40",
    "totalAreaDocument": "1156",
    "docBUILTUPPercentage": "10",
    "docFinalBUILTUP": "1271.60",
    "docFinalBUILTUPSquareMeter": "118.14",
    "docSaleablePercentage": "0",
    "docFinalSaleable": "0.00",
    "docFinalSaleableSquareMeter": "0.00",
    "id": "413398"
  }
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "65d7207fcf7ad63a0afb8799",
    "property": "Flat",
    "area": "948",
    "builtUpPercentage": "10",
    "saleablePercentage": "0",
```

```
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "38",
"source": "magic_bricks",
"expectedPrice": "26000000",
"expectedRate": "27426.16",
"builtUpExpectedRate": "24932.87",
"image": "cases/65d5d1a9cf7ad63a0af9818f/
indicator_1708596986396_Image.png",
"squareMeter": "88.07",
"id": "294925"
},
{
  "printlnReport": true,
  "_id": "65d7207fcf7ad63a0afb879a",
  "property": "Flat",
  "area": "906",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "Housing.Com",
  "expectedPrice": "24000000",
  "expectedRate": "26490.07",
  "builtUpExpectedRate": "24081.88",
  "image": "cases/65d5d1a9cf7ad63a0af9818f/
indicator_1708597014174_Image.png",
  "squareMeter": "84.17",
  "id": "911247"
},
{
  "printlnReport": true,
  "_id": "65d7207fcf7ad63a0afb879b",
  "property": "Flat",
  "area": "1249",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "35",
  "source": "Nobroker.com",
  "expectedPrice": "34500000",
  "expectedRate": "27622.10",
  "builtUpExpectedRate": "25111.00",
  "image": "cases/65d5d1a9cf7ad63a0af9818f/
indicator_1708597051837_Image.png",
```

```
"squareMeter": "116.04",
"id": "639264"
},
{
  "printlnReport": true,
  "_id": "65d7207fcf7ad63a0afb879c",
  "property": "Flat",
  "area": "965",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "floor": "50",
  "source": "Index_no.2",
  "expectedPrice": "25528139.00",
  "expectedRate": "26454.03",
  "builtUpExpectedRate": "24049.12",
  "image": "cases/65d5d1a9cf7ad63a0af9818f/
indicator_1708597128359_Image.png",
  "squareMeter": "89.65",
  "id": "907838"
},
{
  "printlnReport": true,
  "_id": "65d7207fcf7ad63a0afb879d",
  "property": "Flat",
  "area": "948",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "25",
  "source": "magic_bricks",
  "expectedPrice": "23800000",
  "expectedRate": "25105.49",
  "builtUpExpectedRate": "22823.17",
  "image": "cases/65d5d1a9cf7ad63a0af9818f/
indicator_1708597227155_Image.png",
  "squareMeter": "88.07",
  "id": "353176"
}
],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```

```
    "_id": "65d71b16cf7ad63a0afb75f9",
    "name": "externallmg_r_1708595980917_1708596134308_image_1.jpg",
    "path": "cases/65d5d1a9cf7ad63a0af9818f/
externallmg_r_1708595980917_1708596134308_image_1.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d71b16cf7ad63a0afb75fa",
    "name": "externallmg_r_1708595979817_1708596134308_image_0.jpg",
    "path": "cases/65d5d1a9cf7ad63a0af9818f/
externallmg_r_1708595979817_1708596134308_image_0.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d71b16cf7ad63a0afb75fb",
    "name": "externallmg_r_1708595985412_1708596134308_image_3.jpg",
    "path": "cases/65d5d1a9cf7ad63a0af9818f/
externallmg_r_1708595985412_1708596134308_image_3.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d71b16cf7ad63a0afb75fc",
    "name": "externallmg_r_1708595983290_1708596134308_image_2.jpg",
    "path": "cases/65d5d1a9cf7ad63a0af9818f/
externallmg_r_1708595983290_1708596134308_image_2.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d71b16cf7ad63a0afb75fd",
    "name": "externallmg_r_1708595987156_1708596134308_image_4.jpg",
    "path": "cases/65d5d1a9cf7ad63a0af9818f/
externallmg_r_1708595987156_1708596134308_image_4.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d71b16cf7ad63a0afb75fe",
```



```
    "name": "externalImg_r_1708595988652_1708596134308_image_5.jpg",
    "path": "cases/65d5d1a9cf7ad63a0af9818f/
externalImg_r_1708595988652_1708596134308_image_5.jpg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65d71b02cf7ad63a0afb75d0",
    "name": "externalImg_r_1708595967447_1708596123599_image_0.png",
    "path": "cases/65d5d1a9cf7ad63a0af9818f/
externalImg_r_1708595967447_1708596123599_image_0.png",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65d71b02cf7ad63a0afb75d1",
    "name": "externalImg_r_1708595967714_1708596123599_image_1.jpg",
    "path": "cases/65d5d1a9cf7ad63a0af9818f/
externalImg_r_1708595967714_1708596123599_image_1.jpg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "igr1.pdf",
    "filename": "1708597398001_igr1.pdf",
    "path": "cases/65d5d1a9cf7ad63a0af9818f/
processingDocuments/1708597398001_igr1.pdf",
    "size": "470682",
    "createdAt": "Thu Feb 22 2024 15:53:19 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "igr2.pdf",
    "filename": "1708597398080_igr2.pdf",
    "path": "cases/65d5d1a9cf7ad63a0af9818f/
processingDocuments/1708597398080_igr2.pdf",
    "size": "476680",
    "createdAt": "Thu Feb 22 2024 15:53:19 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "igr3.pdf",
```

```
    "filename": "1708597398125_igr3.pdf",
    "path": "cases/65d5d1a9cf7ad63a0af9818f/
processingDocuments/1708597398125_igr3.pdf",
    "size": "496974",
    "createdAt": "Thu Feb 22 2024 15:53:19 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "REference report.doc",
    "filename": "1708597398168_REference_report.doc",
    "path": "cases/65d5d1a9cf7ad63a0af9818f/
processingDocuments/1708597398168_REference_report.doc",
    "size": "12250624",
    "createdAt": "Thu Feb 22 2024 15:53:19 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "Summary - rahul.xlsx",
    "filename": "1708597399428_Summary__rahul.xlsx",
    "path": "cases/65d5d1a9cf7ad63a0af9818f/
processingDocuments/1708597399428_Summary__rahul.xlsx",
    "size": "5170826",
    "createdAt": "Thu Feb 22 2024 15:53:19 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "Calculation (2)- Rahul.xlsx",
    "filename": "1708597490166_Calculation_2_Rahul.xlsx",
    "path": "cases/65d5d1a9cf7ad63a0af9818f/
processingDocuments/1708597490166_Calculation_2_Rahul.xlsx",
    "size": "16045",
    "createdAt": "Thu Feb 22 2024 15:54:50 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  }
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-02-21T10:34:17.183Z",
"updatedAt": "2024-02-22T12:21:58.511Z",
"__v": 0,
"addressForMap": "",
"updatedAtBy": "5fc78e26625ecd20ec1f88e9",
"buildingServicesRate": "3000",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement for sale",
```

```
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 1156.00",
"flatRate": "26200",
"landOtherRate": "23200",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
"reportGeneratedDate": "Thu Feb 22 2024 16:00:33 GMT+0530 (India Standard
Time)",
"siteVisitDate": "2024-02-22",
"builtupPercentage": "10",
"carpetTotal": "0",
"extendOfSiteRemark": "RERA Carpet Area in Sq. Ft. = 1,135.00\nUtility Area in sq.
Ft. = 21.00",
"finalBuiltupArea": "0.00",
"finalCarpetArea": "0.00",
"finalSalableArea": "0.00",
"otherCarpetTotal": "0",
"salablePercentage": "10",
"siteMeasurementRemark": "",
"toBeAdded": "",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
}
}
```

Name	Length	Width	Total
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			