

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "63b68184191f7b344b00eceb"
    },
    "type": "CREDITOFFICER",
    "_id": "63d11f66be948726cc141c0b",
    "email": "SmecitycentreNavimumbai@bankofindia.co.in",
    "firstName": "Mr. Ajay ",
    "mobileNo": "91-9004929639",
    "workMobileNo": "9821551918",
    "lastName": "Rathee"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "80.00000",
    "discussWithPerson": "Bijendra ",
    "expectedFees": 0.04,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180a",
  "type": "BANK",
  "name": "Bank of India",
  "displayName": "Bank of India",
  "initial": "BOI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "63b68184191f7b344b00eceb",
  "name": "SME City Centre Belapur",
  "branchCode": "",
  "mobileNo": "2227570151",
  "alternateMobileNo": "",
  "email": "SmecitycentreNavimumbai@bankofindia.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Bank Of India SME City Centre Belapur, Bank Of India Building Ground
Floor , Sector 11, Plot no 11 C B D Belapur, Navi Mumbai - 400614\n"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e2f4b16576061dae469446",
  "zoneName": "Navi Mumbai Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
    "_id": "60b7189d2ffdf65bcd65882b",
    "role": "PICKUPPERSON",
    "firstName": "Ravindra",
    "email": "ravindrakasare186@gmail.com",
    "lastName": "Kasare",
    "mobileNo": "9167204055",
    "shortName": "RBK",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\60b7189d2ffdf65bcd65882b\\
\\profilePhoto_1622701555488_WhatsApp Image 2021-06-03 at 11.46.40 AM.jpeg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "65829f7c65d49d78457ec7be",
    "role": "SITEENGINEER",
    "firstName": "Vaibhav",
    "email": "vaib1234b@gmail.com",
    "lastName": "Bhagat",
    "mobileNo": "8779534609",
    "designation": "Bachlore Of Engireeing",
    "shortName": "Vaibhav",
    "workWithDocumentMaker": "62691c48afd7d55eddecfda3"
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
    "_id": "60eeaeddf3dd69653a581316",
    "role": "MAKER + RATE VERFIER + CHEAKER",
    "firstName": "Shyam",
    "email": "shyam@vastukala.org",
    "lastName": "Kajvilkar",
    "mobileNo": "9765074720",
    "designation": "",
    "shortName": "SK",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Sh Yam_Photo.jpg"
  },
  "maker": null,
  "checker": null,
  "valuers": [
    {
      "valuersRegistrationNumber": [
        {
          "value": "IBBI/RV/07/2018/10366",
          "label": "Registered Valuer"
        }
      ]
    }
  ]
}
```

```
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
```

```
    "PANNo": "AERPC9086P",
    "fatherName": "Baburao"
  }
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.06906688157076",
  "longitude": "72.99821367214736"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.99821367214736,
    19.06906688157076
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "22/02/2024 12:56 pm"
    }
  ]
},
"visitedDate": [],
"marketAnalysisAndRemark": {
  "audioNotes": [],
  "remark": null,
  "rateMin": "10000",
  "lumpsumValue": "1",
  "rateMax": "12000",
  "areaType": {
    "Name": "Carpet",
    "Value": "Carpet",
    "name": "Carpet",
    "value": "Carpet"
  }
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
}
```

```
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Vashi",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "Ground",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": false,
    "name": "District",
    "key": "district",
    "value": "",
    "label": true
  },
  "city": {
    "status": true,
```

```
"name": "City",
"key": "city",
"value": "Vashi",
"label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "80 & 81",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Vashi Plaza Commercial Premises CHSL",
  "label": false
},
"selectArea": {
  "status": true,
  "name": "Sector",
  "key": "selectArea",
  "value": "17",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
}
```

```
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "D",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
```



```
"key": "hissaNo",
"value": "",
"label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "Shop Np 299",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
}
```

```
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "label": "R. C. C. Slab",
    "value": "rcc_Slab"
  },
  "flooring": {
    "label": "Vitrified Tile Flooring",
    "value": "VerifiedTileFlooring"
  },
  "doors": {
```

```
"label": "MS Rolling Shutter",
"value": "MS_Rolling_Shutter"
},
"windows": {
  "label": "Alluminum sliding windows with tinted glass ",
  "value": "Alluminum_sliding_windows_with_tinted_glass_"
},
"fittings": {
  "label": "Open-Conduit plumbing with Casing Capping Electrical wiring ",
  "value": "Open-Conduit_plumbing_with_Casing_Capping_Electrical_wiring_"
},
"finishing": {
  "label": "Normal",
  "value": "Normal"
}
},
"general": {
  "populationClassList": {
    "label": "Middle Class",
    "value": "MiddleClass"
  },
  "populationGroupList": {
    "label": "Urban",
    "value": "Urban"
  },
  "townplanApprovedByList": {
    "label": "CIDCO",
    "value": "CIDCO"
  },
  "asPerActualAgreement": {
    "north": "road",
    "west": "C wing",
    "south": "express way",
    "east": "A wing "
  },
  "asPerDocumentAgreement": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "",
      "west": "",
      "south": "",
```

```
    "east": ""
  },
  "asPerDocument": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
}
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "label": "Ordinary",
    "value": "Ordinary"
  },
  "propertyTypeOfUseList": {
    "label": "Commercial use",
    "value": "Commercial_use"
  },
  "propertyOccupiedByList": {
    "label": "Tenant Occupied",
    "value": "Tenant_Occupied"
  },
  "monthlyRent": ""
},
"siteMeasurement": {
  "partitions": {
    "label": "6\" Thk. Brick Masonery",
    "value": "6\"_Thk._Brick_Masonery"
  },
  "waterTank": {
    "label": "CIDCO",
    "value": "CIDCO"
  },
  "pavementLaid": {
    "label": "Yes",
    "value": "Yes"
  },
  "carParking": {
    "label": "Open Parking",
    "value": "Open_Parking"
  }
}
```

```
},
"constructionWorkStatus": {
  "label": "Completed",
  "value": "Completed"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "1990",
  "fullDate": "1/1/1990"
},
"propertyTypeList": {
  "label": "Residential",
  "value": "Residential"
},
"planningArea": {
  "label": "Residential",
  "value": "Residential"
},
"typeOfStructure": {
  "label": "R.C.C. Framed Structure",
  "value": "R.C.C._Framed_Structure"
},
"qualityOfConstruction": {
  "label": "Normal",
  "value": "Normal"
},
"walls": {
  "label": "Yes",
  "value": "1"
},
"appearanceOfTheBuilding": {
  "label": "Normal",
  "value": "Normal"
},
"maintenanceOfTheBuilding": {
  "label": "Normal",
  "value": "Normal"
},
"visibleDamageInBuilding": {
  "label": "No",
  "value": "0"
},
"groundStilt": {
  "label": "Ground",
  "value": "ground"
}
```

```
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "26",
"ageOfBuilding": "34",
"noOfBasement": "0",
"noOfPodium": "0",
"noOfAmenityFloors": "0",
"noOfFloors": "02",
"flatFloorNo": "",
"noOfLifts": "02",
"noOfLiftsInEachWings": "0",
"noOfDwellingUnitsInBuilding": "0"
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
```

```
"label": "Full Building Rcc",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
"label": "Internal Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
"label": "External Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
"label": "Internal Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
```



```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
```

```
"title": "Wardrobes",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```

```
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
}
```

```
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"invoices": [],
"paymentId": [],
"_id": "65d6df89cf7ad63a0afa7566",
"ownerName": "Charanjit Kaur Saini",
"ownerPhoneNo": "9820069015",
"appAddress": "D. 299 Vashi plaza plot no. 8o/81 sector no. 17 Near Hdfc Bank. soon
panvel Highway Navi mumbai ",
"remark": "bankar Ajay Rathee\n9812551918",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/65d6df89cf7ad63a0afa7566/
document_1708580736211_1708580890298_D299_charanjitcompressed.pdf",
    "fileName":
"document_1708580736211_1708580890298_D299_charanjitcompressed.pdf",
    "id": "396493",
    "uploadedBy": "60b7189d2ffdf65bcd65882b",
    "createdAt": "Thu Feb 22 2024 11:15:45 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "007123",
"createdBy": "60b7189d2ffdf65bcd65882b",
"caseHistory": [
  {
    "id": "201702",
    "title": "Create Lead",
    "description": "Create Lead",
```

```
"datetime": "Thu Feb 22 2024 11:15:45 GMT+0530 (India Standard Time)"
}
],
"owners": [
  {
    "name": "Charanjit Kaur Saini",
    "phone": "9820069015",
    "ownershipShare": "",
    "email": "",
    "id": "299610"
  }
],
"proposePurchasers": [],
"siteInspection": [
  {
    "areaType": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "providedBy": {
      "label": "Owner",
      "value": "Owner"
    },
    "_id": "65db71fadf99cf0e736025c4",
    "area": "170",
    "providedByName": "Charanjit Kaur Saini",
    "providedByContactNo": "9820069015"
  },
  {
    "areaType": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "providedBy": {
      "label": "Owner",
      "value": "Owner"
    },
    "_id": "65db73dddf99cf0e736025d9",
    "area": "150",
    "providedByName": "Charanjit Kaur Saini",
    "providedByContactNo": "9820069015"
  }
],
"composition": [
  {
    "measurementType": {
```

```
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "266701",
  "name": "Unit Area",
  "length": "100.00",
  "length1": "100",
  "length2": "00",
  "width": "150.00",
  "width1": "150",
  "width2": "00",
  "totalArea": "15000.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "15000.00"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-02-22T05:45:45.958Z",
"updatedAt": "2024-02-25T17:09:06.326Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. Shop Np 299, Ground Floor, Wing - D, Vashi Plaza
Commercial Premises CHSL, Plot No. 80 & 81, Sector 17, Village - Vashi, Vashi",
"updatedBy": "65829f7c65d49d78457ec7be",
"addressForMap": "",
"caseReferredBy": "60b7189d2ffdf65bcd65882b",
"contactPersonName": "Charanjit Kaur Saini",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": ""
```

"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9820069015",
"briefDescOfProperty": "Unit Area",
"carpetTotal": "15000",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "0"

}

Name	Length	Width	Total
<hr/>			
Composition :			
<hr/>			
Unit Area	100'00"	150'00"	15000.00
<hr/>			
Other			
Composition :			
<hr/>			