

```
{
  "typeOfReport": {
    "value": "Amalgamated_Flats",
    "label": "Amalgamated Flats"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "6413f770e6a52007fbaadc8"
    },
    "type": "CREDITOFFICER",
    "_id": "6413f770e6a52007fbaadcba",
    "firstName": "Vishakha ",
    "lastName": "Mane",
    "mobileNo": "",
    "workMobileNo": "9833242472",
    "email": "vishakha.mane@cosmosbank.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "6418456a96b58848585f8cb2",
  "name": "Thane",
  "email": "thane@vastukala.com",
  "phone": "1234567890",
  "address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
  "city": "Thane",
  "shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1820",
  "type": "BANK",
  "name": "Cosmos Bank",
  "displayName": "Cosmos Bank",
  "initial": "CB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "6413f770e6a52007fbaadcb8",
  "name": "Ambarnath Branch",
  "branchCode": "",
  "mobileNo": "02512990632\t",
  "alternateMobileNo": "",
  "email": "ambarnath@cosmosbank.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Panvelkar Pride, Shop no 1 to 4, Plot no 63-64, C T S NO 4740, Near
Hutatma Chawk Ambarnath (East)\n"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f919bff3dd69653a5926b8",
  "zoneName": "Mumbai & Aurangabad Zone"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "6410199a140f140ffc59b58c",
  "role": "PICKUPPERSON",
  "firstName": "Prakash ",
  "email": "prakashnvetkoli@gmail.com",
  "lastName": "Vetkoli",
  "mobileNo": "9076237689",
  "shortName": "PV",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/6410199a140f140ffc59b58c/
profilePhoto_1689054480133_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "64e5a649daae6a1c98101989",
  "role": "SITEENGINEER",
  "firstName": "Sameer",
  "email": "sameeryp2010@gmail.com",
  "lastName": "Parab",
  "mobileNo": "8291009567",
  "designation": "Site Engineer",
  "shortName": "Sameer",
  "workWithDocumentMaker": "62ea09ea4e679b264caf07d7"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "64cde526dc9f3034f3fefa49",
  "role": "FRONTDESK",
  "firstName": "Rashmi",
  "email": "rashmijadhav14feb@gmail.com",
  "lastName": "Jadhav",
  "mobileNo": "7738144625",
  "designation": "Back Office Coordination",
  "shortName": "RJ",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627222afafd7d55eddeddd82",
  "role": "FRONTDESK",
  "firstName": "Pratibha",
  "email": "shilvanta_pratibha@yahoo.co.in",
  "lastName": "Shilvantha",
  "mobileNo": "9821518537",
```

```
    "designation": "",
    "shortName": "PS",
    "workWithDocumentMaker": "60f915d3f3dd69653a592199",
    "profilePhoto": "users/627222afafd7d55eddeddd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
  },
  "checker": null,
  "valuers": []
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.176328175497538",
  "longitude": "72.86265704777406"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-02-24",
      "remark": ""
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
```

```
"name": "State",
"key": "state",
"value": "Maharashtra",
"label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": false,
  "name": "Village",
  "key": "village",
  "value": "",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Ground",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Dombivli (West)",
  "label": false
}
```

```
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Kalyan",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Om Trimurti Co.-Op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "M. G. Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
```

```
"key": "street2",
"value": "",
"label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Vishnu Nagar",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": true,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "327",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "166",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
}
```

```
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "1800 & 1802",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "C/3",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
```



```
"value": "",
"label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 421 202",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
}
```

```
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
```

```
"label": "External Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
```

```
"status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
```

```
"finalGuidelineValue": "0",
"selectedBuildUpValue": "0",
"selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  }
}
```

```
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
{others": {
"title": "Others / Car Parking",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
totalValues": {
"title": "Total",
"quantity": "",
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
taskStatus": {
"SITE_INSPECTION": true,
"RATE_VERIFY": false,
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
createCase": "false",
type": "CASE",
leadType": {
"label": "Lead",
"value": "LEAD"
},
siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
finalValuationArea": "0",
empanelmentNo": [],
"isAdvanceInvoice": false,
status": true,
caseStatus": "RATEVERIFICATIONCOMPLETED",
```

```
"invoices": [],
"paymentId": [],
"_id": "65d6f02fcf7ad63a0afacde4",
"ownerName": "Mr. Prasad Ramchandra Kale",
"ownerPhoneNo": "8425896010",
"fullAddress": "Residential Flat No. C/3, Ground Floor, Om Trimurti Co.-Op. Hsg. Soc.
Ltd., Vishnu Nagar, M. G. Road, Taluka - Kalyan, District - Thane, Dombivli (West), PIN
Code - 421 202, State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "20/02/2024",
      "from": {
        "value": "Transferor",
        "label": "Transferor"
      },
      "Transferor": "Mrs. Smita Shrikant Joshi & Mr. Shrikant Manohar Joshi",
      "to": {
        "value": "transferee",
        "label": "transferee"
      },
      "transferee": "Mr. Prasad Ramchandra Kale",
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "2620/2024"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "fileName": "document_1708584991357_Prasad_Kale_cos_A.pdf",
    "path": "cases/65d6f02fcf7ad63a0afacde4/
document_1708584991357_Prasad_Kale_cos_A.pdf",
    "id": "532030",
    "uploadedBy": "6410199a140f140ffc59b58c",
    "createdAt": "Thu Feb 22 2024 12:26:47 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae1277aa6d152c1801b3cc",
      "label": "Approved Building Plan"
    }
  }
]
```



```
},
"inputs": {
  "documentDate": "16/03/1973",
  "nameOfApprovingAuthority": {
    "value": "Dombivali_Municipal_Council",
    "label": "Dombivali Municipal Council"
  },
  "number": {
    "value": "V.P._No._",
    "label": "V.P. No. "
  },
  "V.P._No._": "14230 "
},
"isHardCopy": false,
"displayStatus": true,
"id": "102031",
"path": "cases/65d6f02fcf7ad63a0afacde4/
document_1708585003183_Kale_plan_A.pdf",
"fileName": "document_1708585003183_Kale_plan_A.pdf"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "16/03/1973",
    "nameOfApprovingAuthority": {
      "value": "Dombivali_Municipal_Council",
      "label": "Dombivali Municipal Council"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "14230"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1708939069173_162115.pdf",
  "path": "cases/65d6f02fcf7ad63a0afacde4/document_1708939069173_162115.pdf",
  "id": "598195",
  "uploadedBy": "627222afafd7d55eddeddd82",
  "createdAt": "Mon Feb 26 2024 14:49:18 GMT+0530 (India Standard Time)"
},
{
```

```
"documentType": {
  "value": "60ae1254aa6d152c1801b325",
  "label": "Society NOC Letter "
},
"inputs": {
  "documentDate": "15/02/2024",
  "nameOfApprovingAuthority": {
    "value": "SOCIETY",
    "label": "SOCIETY"
  },
  "remark": "No. RKO / SL – 01 /24 "
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1708939158005_171038.pdf",
"path": "cases/65d6f02fcf7ad63a0afacde4/document_1708939158005_171038.pdf",
"id": "586743",
"uploadedBy": "627222afafd7d55eddeddd82",
"createdAt": "Mon Feb 26 2024 14:49:18 GMT+0530 (India Standard Time)"
}
],
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"caseNumber": "007136",
"createdBy": "6410199a140f140ffc59b58c",
"caseHistory": [
  {
    "id": "605430",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Feb 22 2024 12:26:47 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Prasad Ramchandra Kale",
    "phone": "8425896010",
    "ownershipShare": "",
    "email": "",
    "id": "104650"
  }
],
"proposePurchasers": [],
"siteInspection": [],
```

```
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d96bc9df99cf0e735e56dc",
    "name": "externallmg_1708747721123_1708747877928_image_0.jpeg",
    "path": "cases/65d6f02fcf7ad63a0afacde4/
externallmg_1708747721123_1708747877928_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d96bf7df99cf0e735e5728",
    "name": "externallmg_1708747765036_1708747920828_image_0.jpeg",
    "path": "cases/65d6f02fcf7ad63a0afacde4/
externallmg_1708747765036_1708747920828_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d96bf7df99cf0e735e5729",
    "name": "externallmg_1708747765354_1708747920828_image_1.jpeg",
    "path": "cases/65d6f02fcf7ad63a0afacde4/
externallmg_1708747765354_1708747920828_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d96bf7df99cf0e735e572a",
    "name": "externallmg_1708747765463_1708747920828_image_2.jpeg",
    "path": "cases/65d6f02fcf7ad63a0afacde4/
externallmg_1708747765463_1708747920828_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```

```
    "_id": "65d96bf7df99cf0e735e572b",
    "name": "externalimg_1708747765494_1708747920828_image_3.jpeg",
    "path": "cases/65d6f02fcf7ad63a0afacde4/
externalimg_1708747765494_1708747920828_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d96bf7df99cf0e735e572c",
    "name": "externalimg_1708747766054_1708747920828_image_4.jpeg",
    "path": "cases/65d6f02fcf7ad63a0afacde4/
externalimg_1708747766054_1708747920828_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d96bf7df99cf0e735e572d",
    "name": "externalimg_1708747766063_1708747920828_image_5.jpeg",
    "path": "cases/65d6f02fcf7ad63a0afacde4/
externalimg_1708747766063_1708747920828_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d96bf7df99cf0e735e572e",
    "name": "externalimg_1708747766086_1708747920828_image_6.jpeg",
    "path": "cases/65d6f02fcf7ad63a0afacde4/
externalimg_1708747766086_1708747920828_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d96bf7df99cf0e735e572f",
    "name": "externalimg_1708747766098_1708747920828_image_7.jpeg",
    "path": "cases/65d6f02fcf7ad63a0afacde4/
externalimg_1708747766098_1708747920828_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d96bf7df99cf0e735e5730",
```

```
    "name": "externallmg_1708747766106_1708747920828_image_8.jpeg",
    "path": "cases/65d6f02fcf7ad63a0afacde4/
externallmg_1708747766106_1708747920828_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d96bf7df99cf0e735e5731",
    "name": "externallmg_1708747766117_1708747920828_image_9.jpeg",
    "path": "cases/65d6f02fcf7ad63a0afacde4/
externallmg_1708747766117_1708747920828_image_9.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d96bf7df99cf0e735e5732",
    "name": "externallmg_1708747766466_1708747920828_image_10.jpeg",
    "path": "cases/65d6f02fcf7ad63a0afacde4/
externallmg_1708747766466_1708747920828_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d96bf7df99cf0e735e5733",
    "name": "externallmg_1708747766973_1708747920828_image_11.jpeg",
    "path": "cases/65d6f02fcf7ad63a0afacde4/
externallmg_1708747766973_1708747920828_image_11.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d96bf7df99cf0e735e5734",
    "name": "externallmg_1708747767237_1708747920828_image_12.jpeg",
    "path": "cases/65d6f02fcf7ad63a0afacde4/
externallmg_1708747767237_1708747920828_image_12.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65d96babdf99cf0e735e56c6",
    "name": "externallmg_1708747691217_1708747850005_image_0.jpeg",
```

```
    "path": "cases/65d6f02fcf7ad63a0afacde4/
externallmg_1708747691217_1708747850005_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65d96babdf99cf0e735e56c7",
    "name": "externallmg_1708747691288_1708747850005_image_1.jpeg",
    "path": "cases/65d6f02fcf7ad63a0afacde4/
externallmg_1708747691288_1708747850005_image_1.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "Calculation Sheet NEW COSMOS.xlsx",
    "filename": "1708928637341_Calculation_Sheet_NEW_COSMOS.xlsx",
    "path": "cases/65d6f02fcf7ad63a0afacde4/
processingDocuments/1708928637341_Calculation_Sheet_NEW_COSMOS.xlsx",
    "size": "4162798",
    "createdAt": "Mon Feb 26 2024 11:53:57 GMT+0530 (India Standard Time)",
    "uploadedBy": "64cde526dc9f3034f3fefa49"
  }
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "64cde526dc9f3034f3fefa49",
      "role": "FRONTDESK",
      "firstName": "Rashmi",
      "lastName": "Jadhav",
      "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "65d98c57df99cf0e735ed6a3",
    "note": "Value given for tthe confirmation",
    "taskId": "65d6f071cf7ad63a0afacffa",
    "createdAt": "2024-02-24T06:27:35.475Z"
  }
]
```

```
],
"createdAt": "2024-02-22T06:56:47.726Z",
"updatedAt": "2024-02-26T09:19:18.091Z",
"__v": 0,
"updatedBy": "627222afafd7d55eddedd82",
"addressForMap": "",
"caseReferredBy": "6410199a140f140ffc59b58c",
"contactPersonName": "Mr. Prasad Ramchandra Kale",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "8425896010",
"siteVisitDate": "2024-02-24"
```

}

Name	Length	Width	Total
Composition :			
Other			
Composition :			