

```
{
  "typeOfReport": {
    "value": "Project_Finance",
    "label": "Project Finance"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Project_Valuation",
    "label": "Project Valuation"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b807"
    },
    "type": "CREDITOFFICER",
    "_id": "654b7e1c637db60f88b7010e",
    "firstName": "Amol",
    "lastName": "pawar",
    "mobileNo": "",
    "workMobileNo": "9969810421",
    "email": "1amol.pawar@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "60000"
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b807",
  "branchCode": "000081",
  "type": "BRANCH",
  "name": "SME Vashi Turbhe Branch (Sector 19)",
  "email": "sbi.60347@sbi.co.in",
  "mobileNo": "0000000000",
  "alternateMobileNo": "",
  "address": "Sector No. 19, Vashi Branch, Central Facility Bldg., Phase - II, Market II,
Vashi, Navi Mumbai, State - Maharashtra, Country - India. ",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential cum Commercial",
  "value": "Residential_cum_commercial"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60f91822f3dd69653a5922e3",
  "role": "SITEENGINEER+MAKAR+CHECKER",
  "firstName": "Prayush ",
  "email": "prayush@vastukala.org",
  "lastName": "Parekh ",
  "mobileNo": "9767983840",
  "shortName": "PPP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "65829f7c65d49d78457ec7be",
  "role": "SITEENGINEER",
  "firstName": "Vaibhav",
  "email": "vaib1234b@gmail.com",
  "lastName": "Bhagat",
  "mobileNo": "8779534609",
  "designation": "Bachlore Of Engireeing",
  "shortName": "Vaibhav",
  "workWithDocumentMaker": "62691c48afd7d55eddecfda3"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f91822f3dd69653a5922e3",
  "role": "SITEENGINEER+MAKAR+CHECKER",
  "firstName": "Prayush ",
  "email": "prayush@vastukala.org",
  "lastName": "Parekh ",
  "mobileNo": "9767983840",
  "designation": "",
  "shortName": "PPP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60f91822f3dd69653a5922e3",
  "role": "SITEENGINEER+MAKAR+CHECKER",
  "firstName": "Prayush ",
  "email": "prayush@vastukala.org",
  "lastName": "Parekh ",
  "mobileNo": "9767983840",
```

```
"designation": "",
"shortName": "PPP",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"checker": {
"type": "EMPLOYEE",
"_id": "60f91822f3dd69653a5922e3",
"role": "SITEENGINEER+MAKAR+CHECKER",
"firstName": "Prayush ",
"email": "prayush@vastukala.org",
"lastName": "Parekh ",
"mobileNo": "9767983840",
"designation": "",
"shortName": "PPP",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "IBBI"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
}_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
},
{
"title": {
```

```
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.043441117881997",
  "longitude": "73.07916051425109"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
}
```

```
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": [],
  "remark": null,
  "rateMin": "8000",
  "lumpsumValue": "1",
  "rateMax": "9000",
  "areaType": {
    "Name": "Carpet",
    "Value": "Carpet",
    "name": "Carpet",
    "value": "Carpet"
  }
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Kharghar",
    "label": true
  }
},
```

```
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Basement",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Raigad",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Kharghar, Navi Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Panvel",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
```

```
"value": "38C",
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Elite Vivanta",
  "label": false
},
"selectArea": {
  "status": true,
  "name": "Sector",
  "key": "selectArea",
  "value": "15",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
```



```
"status": true,
"name": "Project Name",
"key": "projectName",
"value": "Elite Vivanta",
"label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
```

```
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
```

```
"name": "Postal Code",
"key": "postalCode",
"value": "410210",
"label": false
},
"suburb": {
"status": false,
"name": "Suburb",
"key": "suburb",
"value": "",
"label": false
}
},
"flatSpecifications": {
"roof": {
"label": "Proposed R.C.C. Slab",
"value": "Proposed_R.C.C._Slab"
},
"flooring": {
"label": "Proposed Italian Marble Flooring",
"value": "Proposed_Italian_Marble_Flooring"
},
"doors": {
"label": "Proposed Teak wood door frame with flush doors",
"value": "Proposed_Teak_wood_door_frame_with_flush_doors"
},
"windows": {
"label": "Proposed Powder coated aluminium sliding windows",
"value": "Proposed_Powder_coated_aluminium_sliding_windows"
},
"fittings": {
"label": "Proposed Concealed plumbing with C.P. fittings. Concealed wiring",
"value": "Proposed_Concealed_plumbing_with_C.P._fittings._Concealed_wiring"
},
"finishing": {
"label": "Proposed Cement Plastering",
"value": "Proposed_Cement_Plastering"
}
},
"general": {
"populationClassList": {
"label": "Middle Class",
"value": "MiddleClass"
},
"populationGroupList": {
"label": "Semi Urban",
```

```
"value": "Semi_Urban"
},
"townplanApprovedByList": {
  "label": "CIDCO",
  "value": "CIDCO"
},
"asPerActualAgreement": {
  "north": "Millennium empire ",
  "west": "crown project",
  "south": "trinity project",
  "east": "open land "
},
"asPerDocumentAgreement": {
  "north": "",
  "west": "",
  "south": "",
  "east": ""
},
"unitBoundaries": {
  "asPerActual": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "asPerDocument": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
}
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "label": "Middle Class",
    "value": "Middle_Class"
  },
  "propertyTypeOfUseList": {
    "label": "Residential Purpose",
    "value": "Residential_Purpose"
  }
}
```

```
},
"propertyOccupiedByList": {
  "label": "Builder Occupied ",
  "value": "Builder_Occupied_"
},
"monthlyRent": ""
},
"siteMeasurement": {
  "partitions": {
    "label": "Building Under Construction",
    "value": "Building_Under_Construction"
  },
  "waterTank": {
    "label": "Proposed Municipal Water Supply",
    "value": "Proposed_Municipal_Water_Supply"
  },
  "pavementLaid": {
    "label": "Building Under Construction",
    "value": "Building_Under_Construction"
  },
  "carParking": {
    "label": "Building Under Construction",
    "value": "Building_Under_Construction"
  },
  "constructionWorkStatus": {
    "label": "Under Construction",
    "value": "InProgress"
  },
  "dateOfConstruction": {
    "date": "",
    "month": "1",
    "year": "2025",
    "fullDate": "1/1/2025"
  },
  "propertyTypeList": {
    "label": "Residential cum Commercial",
    "value": "Residential_cum_commercial"
  },
  "planningArea": {
    "label": "Residential cum Commercial",
    "value": "Residential_cum_commercial"
  },
  "typeOfStructure": {
    "label": "R.C.C. Framed Structure",
    "value": "R.C.C._Framed_Structure"
  },
}
```

```
"qualityOfConstruction": {
  "label": "Building is under construction ",
  "value": "Building_is_under_construction_"
},
"walls": {
  "label": "Building Under Construction",
  "value": "Building_Under_Construction"
},
"appearanceOfTheBuilding": {
  "label": "Building is under construction ",
  "value": "Building_is_under_construction_"
},
"maintenanceOfTheBuilding": {
  "label": "Building is under construction ",
  "value": "Building_is_under_construction_"
},
"visibleDamageInBuilding": {
  "label": "Building Under Construction",
  "value": "Building_Under_Construction"
},
"groundStilt": {
  "label": "Ground",
  "value": "ground"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "",
"estimatedAge": "",
"ageOfBuilding": "",
"noOfBasement": "0",
"noOfPodium": "0",
"noOfAmenityFloors": "0",
"noOfFloors": "0",
"flatFloorNo": "",
"noOfLifts": "0",
"noOfLiftsInEachWings": "0",
"noOfDwellingUnitsInBuilding": "0"
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
```

```
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "InProgress",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```



```
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": []
}
```

```
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
}
```

```
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
```

```
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"invoices": [],
"paymentId": [],
"_id": "65d96964df99cf0e735e4bf8",
"ownerName": "Nathdwara Developers Pvt. Ltd.",
"ownerPhoneNo": "9929977362",
"fullAddress": "Residential Project Finance No. Basement Floor, Elite Vivanta, Elite Vivanta, Plot No. 38C, Sector 15, Village - Kharghar, Taluka - Panvel, District - Raigad, Kharghar, Navi Mumbai, 410210",
"remark": ""
```

```
"documents": [
  {
    "documentType": {
      "value": "60ae129faa6d152c1801b47d",
      "label": "RERA Certificate"
    },
    "inputs": {
      "documentDate": "12/02/2024",
      "nameOfApprovingAuthority": {
        "value": "Maharashtra_Real_Estate_Regulatory_Authority",
        "label": "Maharashtra Real Estate Regulatory Authority"
      },
      "number": {
        "value": "Document_No",
        "label": "Document No"
      },
      "Document_No": "P52000054784"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1708747100808_download.pdf",
    "path": "cases/65d96964df99cf0e735e4bf8/
document_1708747100808_download.pdf",
    "id": "468445",
    "uploadedBy": "60f91822f3dd69653a5922e3",
    "createdAt": "Sat Feb 24 2024 09:28:28 GMT+0530 (India Standard Time)"
  }
],
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"caseNumber": "007213",
"createdBy": "60f91822f3dd69653a5922e3",
"caseHistory": [
  {
    "id": "297839",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Sat Feb 24 2024 09:28:28 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Nathdwara Developers Pvt. Ltd.",
    "phone": "9929977362",
```

```
"ownershipShare": "",
"email": "",
"id": "459292"
},
],
"proposePurchasers": [],
"siteInspection": [
{
"areaType": {
"label": "Carpet",
"value": "Carpet"
},
"providedBy": {
"label": "Owner",
"value": "Owner"
},
"_id": "65db5f8adf99cf0e73602161",
"area": "1335",
"providedByName": "Nathdwara Developers Pvt. Ltd.",
"providedByContactNo": "9929977362"
}
],
"composition": [
{
"measurementType": {
"label": "Square Feet",
"value": "Square_Feet"
},
"id": "103022",
"name": "Unit Area",
"length": "1.00",
"length1": "1",
"length2": "00",
"width": "1.00",
"width1": "1",
"width2": "00",
"totalArea": "1.00",
"images": [],
"extraAreas": [],
"finalArea": "1.00"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
```

```
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65db6028df99cf0e7360218d",
    "name": "externalImg_1708875801704_image.jpeg",
    "path": "cases/65d96964df99cf0e735e4bf8/
externalImg_1708875801704_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65db6028df99cf0e7360218e",
    "name": "externalImg_1708875802813_image.jpeg",
    "path": "cases/65d96964df99cf0e735e4bf8/
externalImg_1708875802813_image.jpeg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-02-24T03:58:28.501Z",
"updatedAt": "2024-02-25T15:44:19.566Z",
"__v": 0,
"updatedBy": "65829f7c65d49d78457ec7be",
"addressForMap": "",
"caseReferredBy": "60f91822f3dd69653a5922e3",
"contactPersonName": "Nathdwara Developers Pvt. Ltd.",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9929977362",
"briefDescOfProperty": "Unit Area",
"carpetTotal": "1",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "0"
}
```

| Name | Length | Width | Total |
|------------------------|---------------|--------------|--------------|
| Composition : | | | |
| Unit Area | 1'00" | 1'00" | 1.00 |
| Other Composition : | | | |