

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b9f4"
    },
    "type": "CREDITOFFICER",
    "_id": "650581d3a8e9b70221e855e5",
    "firstName": "Bhakti",
    "lastName": "Podkar",
    "mobileNo": "",
    "workMobileNo": "8425827511",
    "email": "Bhakti.racpc.sion@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "5000000",
    "discussWithPerson": "Bhakti",
    "expectedFees": 2500,
    "quotedAmount": "2500"
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b9f4",
  "branchCode": "000215",
  "type": "BRANCH",
  "name": "RACPC Sion ",
  "email": "racpc.sion@sbi.co.in",
  "mobileNo": "02225046265",
  "alternateMobileNo": "",
  "address": "B-603 & 604, Kohinoor City, Commercial-1, 6th Floor, Kirol Road, Off
L.B.S. Marg, Kurla (West), Mumbai, Pin Code - 400 070, State - Maharashtra, Country -
India.",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "60b7177d2ffdf65bcd65882a",
  "role": "PICKUPPERSON",
  "firstName": "Saurabh",
  "email": "saurabhvelonde143@gmail.com",
  "lastName": "Velonde",
  "mobileNo": "8691048846",
  "shortName": "SSV",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1686816492317_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "60f9462345132d6a6bddb9d5",
  "role": "SITEENGINEER",
  "firstName": "Dashrath ",
  "email": "dasrat.jaiswar1234@gmail.com",
  "lastName": "Jaiswar",
  "mobileNo": "9987305468",
  "designation": "",
  "shortName": "DFJ",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60092304a16fab0f2af9b0c2",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Nitesh",
  "email": "nitesh.khedekar@vastukala.org",
  "lastName": "Khedekar",
  "mobileNo": "8369040652",
  "designation": "",
  "shortName": "NK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627221f4afd7d55eddeddcb4",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Prajakta",
  "email": "prajakta@vastukala.org",
  "lastName": "Patil",
```

```
"mobileNo": "9769797568",
"designation": "",
"shortName": "P",
"workWithDocumentMaker": "",
"profilePhoto": "users/627221f4afd7d55eddeddcb4/
profilePhoto_1668057197188_WhatsApp_Image_20221110_at_104044_AM.jpeg"
},
"checker": {
  "_id": "60092304a16fab0f2af9b0c2",
  "profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg",
  "firstName": "Nitesh",
  "lastName": "Khedekar",
  "shortName": "NK",
  "email": "nitesh.khedekar@vastukala.org",
  "designation": "",
  "mobileNo": "8369040652",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "type": "EMPLOYEE",
  "workWithDocumentMaker": ""
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  {
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ]
  }
]
```

```
"title": {
  "value": "FIIV",
  "label": "FIIV"
},
"_id": "60af80072ffdf65bcd658652",
"number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.06300827724735",
  "longitude": "72.88072523058798"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.88072523058798,
    19.06300827724735
  ]
}
```

```
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-02-28",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-02-28",
      "remark": "MANUAL_IN_TASK"
    }
  ],
  "schedule": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "2BHK",
  "label": "2 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
```

```
"status": true,
"name": "Village",
"key": "village",
"value": "Kurla",
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "17",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "119",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Suburban District",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Kurla",
```

```
"label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Sayba Opal",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Nehru Nagar",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Mother Dairy Road",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
```



```
"name": "Wing",
"key": "wing",
"value": "A",
"label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "2 Part",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
}
```

```
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "1702",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
```

```
"key": "GUTNo",
"value": "",
"label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 400 024",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Kurla (East), Mumbai",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows",
    "label": "Powder coated Aluminum sliding windows"
  },
  "fittings": {
    "value": "Proposed_Concealed_plumbing_with_C.P._fittings._Concealed_wiring",
    "label": "Proposed Concealed plumbing with C.P. fittings. Concealed wiring"
  },
  "finishing": {
    "value": "Cement_Plastering_+_POP_Finish",
    "label": "Cement Plastering + POP Finish"
  }
}
},
"general": {
```

```
"ownership": {
  "value": "Joint_Ownership",
  "label": "Joint Ownership"
},
"populationClassList": {
  "value": "MiddleClass",
  "label": "Middle Class"
},
"populationGroupList": {
  "value": "Urban",
  "label": "Urban"
},
"townplanApprovedByList": {
  "value": "MCGM",
  "label": "Municipal Corporation of Greater Mumbai (MCGM)"
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "P V Marg",
  "west": "Building No. 120",
  "south": "Nalla & Shree Krupa 89 Building",
  "east": "Building No. 118"
},
"asPerDocumentAgreement": {
  "north": "Details not available",
  "west": "Details not available",
  "south": "Details not available",
  "east": "Details not available"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "asPerDocument": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  }
},
"isDisplay": false,
```

```
    "title": "Boundaries of The Flat"
  },
  "extraDetailOfProperty": "",
  "dateOfIssusApprovePlan": "Copy of Approved Plan were not provided and not
verified",
  "approvePlanVerified": "N.A.",
  "empanelledOfApprovePlan": "N.A.",
  "unauthorizedConstruction": ""
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "depreciatedCostOfConstruction": "",
  "depreciatedBuildingRate": ""
},
"igrRate": {
  "propertyName": "Residential",
  "rate": "82350.00",
  "landRate": "27230",
  "igrImage": "cases/65dc7a38df99cf0e7361c43b/igr_1709122716105_Image.png",
  "squareMeterGuideLineRate": "90585.00",
  "squareFeetGuideLineRate": "8416.00"
},
"igrFinalRate": {
  "floorRatePercentage": "10",
  "depreciationPercentage": "0",
  "rate": "82350.00",
  "squareMeterGuideLineRate": "90585.00",
  "squareFeetGuideLineRate": "8416.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Building_Under_Construction",
    "label": "Building Under Construction"
  },
  "monthlyRent": "29,000/- Expected rental income per month after completion",
```

```
"assessmentNo": "Details not available",
"taxPaidHolderName": "Details not available",
"taxAmount": "Details not available",
"electricityServiceConnectionNo": "Details not available",
"meterCardHolderName": "Details not available",
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per MCGM norms",
"tenantName": "",
"maintenanceOfFlat": "Building Under Construction"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in Developed Area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "Proposed_Municipal_Water_Supply",
    "label": "Proposed Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Stilt + Open Car Parking",
  "constructionWorkStatus": {
    "value": "InProgress",
    "label": "Under Construction"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "",
```

```
"month": "1",
"year": "2024",
"fullDate": "1/1/2024"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C.",
  "label": "R.C.C. Framed"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
"sewerageSystem": {
  "value": "Proposed_Connected_to_Municipal_Sewerage_System_",
  "label": "Proposed Connected to Municipal Sewerage System "
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
```

```
"label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenancelssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "stilt",
  "label": "Stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_site_information",
  "label": "As per site information"
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "0",
"totalLifeBuilding": "60",
"estimatedAge": "0",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "18",
"flatFloorNo": "17",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
  "area": "597.30",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
```



```
"areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/65dc7a38df99cf0e7361c43b/
routeMap_1709148436832_Image.png",
    "routeLat": "19.062636",
    "routeLng": "72.885393",
    "stationName": "Kurla",
    "routeDistance": "750 Mt."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latlng": true,
    "finallatlng": true
  },
  "locationMapImg": [
    {
      "id": "eft98s",
      "name": "eft98s",
      "image": "cases/65dc7a38df99cf0e7361c43b/
routeMap_1709148379574_Image.png"
    }
  ],
  "valuation": {
    "wardrobesRate": "0",
    "totalwardrobesRate": "0",
    "wardrobesQty": "0",
    "showcasesQty": "0",
    "showcasesRate": "0",
    "totalshowcasesRate": "0",
    "kitchenArrangementsQty": "0",
    "kitchenArrangementsRate": "0",
    "totalkitchenArrangementsRate": "0",
    "superfineFinishQty": "0",
```

```
"superfineFinishRate": "0",
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "11403000.00",
"finalValue": "11403000.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValueDocument": null,
"purchaseValueDocument": null,
"bookValue": "0"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Thu Feb 29 2024 14:34:41 GMT+0530 (India Standard Time)",
  "number": "2305231",
  "dayCount": "10",
  "monthCount": "453",
  "generatedBy": "60092304a16fab0f2af9b0c2"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
```

```
"label": "RCC Plinth",
"floorsCompleted": "Complete",
"percentage": "5",
"isHideFloor": false,
"status": true
},
"fullBuildingRcc": {
"label": "Full Building Rcc",
"floorsCompleted": "20",
"percentage": "40",
"isHideFloor": false,
"status": true
},
"internalBrickWork": {
"label": "Internal Brick Work",
"floorsCompleted": "20",
"percentage": "7.00",
"isHideFloor": false,
"status": true
},
"externalBrickWork": {
"label": "External Brick Work",
"floorsCompleted": "20",
"percentage": "7.00",
"isHideFloor": false,
"status": true
},
"internalPlastering": {
"label": "Internal Plastering",
"floorsCompleted": "20",
"percentage": "3.50",
"isHideFloor": false,
"status": true
},
"externalPlastering": {
"label": "External Plastering",
"floorsCompleted": "20",
"percentage": "3.50",
"isHideFloor": false,
"status": true
},
"door": {
"label": "Door",
"floorsCompleted": "20",
"percentage": "2.50",
"isHideFloor": false,
```

```
"status": true
},
"window": {
  "label": "Window",
  "floorsCompleted": "20",
  "percentage": "2.50",
  "isHideFloor": false,
  "status": true
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "20",
  "percentage": "10.00",
  "isHideFloor": false,
  "status": true
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "20",
  "percentage": "1.50",
  "isHideFloor": false,
  "status": true
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "20",
  "percentage": "1.50",
  "isHideFloor": false,
  "status": true
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "20",
  "percentage": "5.00",
  "isHideFloor": false,
  "status": true
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "2",
  "percentage": "2.00",
  "isHideFloor": false,
  "status": true
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "96.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "5026877.00",
  "selectedBuildUpValue": "597.30",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "65df15249a876858ab30f136",
      "name": "externalimg_1709118752784_1709118907780_image_3.jpeg",
      "path": "cases/65dc7a38df99cf0e7361c43b/
externalimg_1709118752784_1709118907780_image_3.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "65df15099a876858ab30f0f5",
      "name": "externalimg_1709118723483_1709118882887_image_2.jpeg",
      "path": "cases/65dc7a38df99cf0e7361c43b/
externalimg_1709118723483_1709118882887_image_2.jpeg",
      "orientation": "portrait"
    }
  ]
},
],
```

```
"externalPhotos": [
  {
    "status": false,
    "_id": "65df15249a876858ab30f137",
    "name": "externallmg_1709118753452_1709118907780_image_4.jpeg",
    "path": "cases/65dc7a38df99cf0e7361c43b/
externallmg_1709118753452_1709118907780_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65df15249a876858ab30f135",
    "name": "externallmg_1709118751797_1709118907780_image_2.jpeg",
    "path": "cases/65dc7a38df99cf0e7361c43b/
externallmg_1709118751797_1709118907780_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65df15099a876858ab30f105",
    "name": "externallmg_1709118728542_1709118882888_image_18.jpeg",
    "path": "cases/65dc7a38df99cf0e7361c43b/
externallmg_1709118728542_1709118882888_image_18.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
    "_id": "65df15099a876858ab30f0f4",
    "name": "Living Room",
    "path": "cases/65dc7a38df99cf0e7361c43b/
externallmg_1709118723246_1709118882887_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65df15099a876858ab30f0f6",
    "name": "Living Room",
    "path": "cases/65dc7a38df99cf0e7361c43b/
externallmg_1709118723746_1709118882887_image_3.jpeg",
    "orientation": "portrait"
  },
  {

```

```
    "status": false,
    "_id": "65df15099a876858ab30f0f7",
    "name": "Living Room",
    "path": "cases/65dc7a38df99cf0e7361c43b/
externallmg_1709118724081_1709118882887_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65df15099a876858ab30f0f9",
    "name": "Living Room",
    "path": "cases/65dc7a38df99cf0e7361c43b/
externallmg_1709118725152_1709118882888_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65df15099a876858ab30f0fb",
    "name": "Living Room",
    "path": "cases/65dc7a38df99cf0e7361c43b/
externallmg_1709118725837_1709118882888_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65df15099a876858ab30f0fd",
    "name": "Living Room",
    "path": "cases/65dc7a38df99cf0e7361c43b/
externallmg_1709118726281_1709118882888_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65df15099a876858ab30f0fc",
    "name": "Living Room",
    "path": "cases/65dc7a38df99cf0e7361c43b/
externallmg_1709118726086_1709118882888_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65df15099a876858ab30f100",
    "name": "Living Room",
    "path": "cases/65dc7a38df99cf0e7361c43b/
externallmg_1709118726676_1709118882888_image_13.jpeg",
    "orientation": "portrait"
  }
```

```
    },
    {
      "status": false,
      "_id": "65df15099a876858ab30f102",
      "name": "Living Room",
      "path": "cases/65dc7a38df99cf0e7361c43b/
externallmg_1709118727406_1709118882888_image_15.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "65df15099a876858ab30f106",
      "name": "Living Room",
      "path": "cases/65dc7a38df99cf0e7361c43b/
externallmg_1709118729093_1709118882888_image_19.jpeg",
      "orientation": "portrait"
    }
  ]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "20390",
    "max": "23572"
  },
  "builtUpRateRange": {
    "min": "18537",
    "max": "21429"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
},
```



```
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
```

```
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
}
```

```
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "543.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3",
  "SME/TCC/221/13"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"invoices": [],
"paymentId": [],
"_id": "65dc7a38df99cf0e7361c43b",
"ownerName": "Mrs. Nasrin Irfan A Khan & Mr. Irfan Mohammed Shamsuddin Khan",
"ownerPhoneNo": "9322405839",
"appAddress": "Flat no. 1702, 17th Floor, Wing - A, Building no. 119, Saiba, Opal,
Nehru Nagar, kurla East",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "22/09/2023",
      "from": {
        "value": "Developers",
        "label": "Developers"
      },
      "Developers": "M/s. Star Rise Developers",
      "to": {
        "value": "purchaser",
        "label": "purchaser"
      },
      "purchaser": "Mrs. Nasrin Irfan A Khan & Mr. Irfan Mohammed Shamsuddin Khan",
      "number": {
        "value": "property_no",
        "label": "property no"
      },
      "property_no": "19162 / 2023"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "150360",
    "path": "cases/65dc7a38df99cf0e7361c43b/
document_1708948005830_1708948164897_Racpc_Sion_Nasrin_Khan.pdf",
```

```
"fileName":
"document_1708948005830_1708948164897_Racpc_Sion_Nasrin_Khan.pdf"
},
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
    "label": "RERA Certificate"
  },
  "inputs": {
    "documentDate": "02/11/2022",
    "nameOfApprovingAuthority": {
      "value": "Maharashtra_Real_Estate_Regulatory_Authority",
      "label": "Maharashtra Real Estate Regulatory Authority"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "P51800047468"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1709149773381_P51800047468.pdf",
  "path": "cases/65dc7a38df99cf0e7361c43b/
document_1709149773381_P51800047468.pdf",
  "id": "972887",
  "uploadedBy": "627221f4afd7d55eddeddcb4",
  "createdAt": "Thu Feb 29 2024 01:19:33 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "21/07/2022",
    "nameOfApprovingAuthority": {
      "value": "Maharashtra_Housing_And_Area_Development_Authority",
      "label": "Maharashtra Housing And Area Development Authority"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "MH / EE / (BP) / GM / MHADA - 22 / 1099 / 2022 / CC / 1 / New"
  },
}
```

```
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1709149845431_cc.pdf",
"path": "cases/65dc7a38df99cf0e7361c43b/document_1709149845431_cc.pdf",
"id": "716440",
"uploadedBy": "627221f4afd7d55eddeddcb4",
"createdAt": "Thu Feb 29 2024 01:20:45 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "007251",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
{
  "id": "449172",
  "title": "Create Lead",
  "description": "Create Lead",
  "datetime": "Mon Feb 26 2024 17:17:04 GMT+0530 (India Standard Time)"
}
],
"owners": [
{
  "name": "Mrs. Nasrin Irfan A Khan & Mr. Irfan Mohammed Shamsuddin Khan",
  "phone": "9322405839",
  "ownershipShare": "",
  "email": "",
  "id": "351585"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "215324",
  "name": "Living Room",
  "length": "8.42",
  "length1": "8",
  "length2": "5",
  "width": "11.33",
  "width1": "11",
  "width2": "4",
  "totalArea": "95.39",
  "images": [],
}
```

```
"extraAreas": [],
"finalArea": "95.39"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Dining",
  "length": "8.58",
  "length1": "8",
  "length2": "7",
  "width": "8.00",
  "width1": "8",
  "width2": "00",
  "totalArea": "68.67",
  "images": [],
  "extraAreas": [],
  "finalArea": "68.67"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Kitchen",
  "length": "6.75",
  "length1": "6",
  "length2": "9",
  "width": "7.83",
  "width1": "7",
  "width2": "10",
  "totalArea": "52.87",
  "images": [],
  "extraAreas": [],
  "finalArea": "52.87"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Passage",
```

```
"length": "8.92",
"length1": "8",
"length2": "11",
"width": "2.92",
"width1": "2",
"width2": "11",
"totalArea": "26.01",
"images": [],
"extraAreas": [],
"finalArea": "26.01"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Toilet",
  "length": "6.42",
  "length1": "6",
  "length2": "5",
  "width": "3.75",
  "width1": "3",
  "width2": "9",
  "totalArea": "24.06",
  "images": [],
  "extraAreas": [],
  "finalArea": "24.06"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Bedroom",
  "length": "8.58",
  "length1": "8",
  "length2": "7",
  "width": "11.08",
  "width1": "11",
  "width2": "1",
  "totalArea": "95.13",
  "images": [],
  "extraAreas": [],
  "finalArea": "95.13"
```

```
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Toilet",
  "length": "3.67",
  "length1": "3",
  "length2": "8",
  "width": "7.50",
  "width1": "7",
  "width2": "6",
  "totalArea": "27.50",
  "images": [],
  "extraAreas": [],
  "finalArea": "27.50"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Bedroom",
  "length": "9.00",
  "length1": "9",
  "length2": "00",
  "width": "12.25",
  "width1": "12",
  "width2": "3",
  "totalArea": "110.25",
  "images": [],
  "extraAreas": [],
  "finalArea": "110.25"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
  },

```



```
"docMeasurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"id": "640965",
"selectAreaTypeDocument": "Carpet",
"totalAreaDocument": "543",
"squareMeterArea": "50.45",
"docFinalBuiltUp": "597.3",
"docFinalBuiltUpSquareMeter": "55.495000000000005",
"docBuiltupPercentage": "10",
"docSaleablePercentage": "0",
"docFinalSaleable": "0",
"docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
{
  "printlnReport": true,
  "_id": "65df24a09a876858ab3129f5",
  "property": "2 BHK Flat For Sale IN Sayba Opal Kurla East, Mumbai",
  "area": "541.00",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "magic_bricks",
  "expectedPrice": "11200000.00",
  "expectedRate": "20702.40",
  "builtUpExpectedRate": "18820.37",
  "image": "cases/65dc7a38df99cf0e7361c43b/
indicator_1709122476428_Image.png",
  "squareMeter": "50.26",
  "id": "207892"
},
{
  "printlnReport": true,
  "_id": "65df24a09a876858ab3129f6",
  "property": "2 BHK Flat For Sale Sayba Opal, Kurla East, Mumbai",
  "area": "564.00",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "magic_bricks",
```

```
"expectedPrice": "11500000.00",
"expectedRate": "20390.07",
"builtUpExpectedRate": "18536.43",
"image": "cases/65dc7a38df99cf0e7361c43b/
indicator_1709122519747_Image.png",
"squareMeter": "52.40",
"id": "299486"
},
{
  "printlnReport": true,
  "_id": "65df24a09a876858ab3129f7",
  "property": "Sayba Opal Kurla Mumbai",
  "area": "462.42",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "square_yards",
  "expectedPrice": "10900000.00",
  "expectedRate": "23571.64",
  "builtUpExpectedRate": "21428.85",
  "image": "cases/65dc7a38df99cf0e7361c43b/
indicator_1709122586014_Image.png",
  "squareMeter": "42.96",
  "id": "233742"
},
{
  "printlnReport": true,
  "_id": "65df24a09a876858ab3129f8",
  "property": "Star Sayba Opal, Nehru Nagar, Kurla",
  "area": "543.00",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "Housing.Com",
  "expectedPrice": "11300000.00",
  "expectedRate": "20810.31",
  "builtUpExpectedRate": "18918.47",
  "image": "cases/65dc7a38df99cf0e7361c43b/
indicator_1709122654639_Image.png",
  "squareMeter": "50.45",
  "id": "673412"
}
],
"externallImages": [
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65df15099a876858ab30f0f3",
  "name": "externallmg_1709118722627_1709118882887_image_0.jpeg",
  "path": "cases/65dc7a38df99cf0e7361c43b/
externallmg_1709118722627_1709118882887_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65df15099a876858ab30f0f4",
  "name": "externallmg_1709118723246_1709118882887_image_1.jpeg",
  "path": "cases/65dc7a38df99cf0e7361c43b/
externallmg_1709118723246_1709118882887_image_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65df15099a876858ab30f0f5",
  "name": "externallmg_1709118723483_1709118882887_image_2.jpeg",
  "path": "cases/65dc7a38df99cf0e7361c43b/
externallmg_1709118723483_1709118882887_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65df15099a876858ab30f0f6",
  "name": "externallmg_1709118723746_1709118882887_image_3.jpeg",
  "path": "cases/65dc7a38df99cf0e7361c43b/
externallmg_1709118723746_1709118882887_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65df15099a876858ab30f0f7",
  "name": "externallmg_1709118724081_1709118882887_image_4.jpeg",
  "path": "cases/65dc7a38df99cf0e7361c43b/
externallmg_1709118724081_1709118882887_image_4.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65df15099a876858ab30f0f8",
    "name": "externallmg_1709118724451_1709118882888_image_5.jpeg",
    "path": "cases/65dc7a38df99cf0e7361c43b/
externallmg_1709118724451_1709118882888_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65df15099a876858ab30f0f9",
    "name": "externallmg_1709118725152_1709118882888_image_6.jpeg",
    "path": "cases/65dc7a38df99cf0e7361c43b/
externallmg_1709118725152_1709118882888_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65df15099a876858ab30f0fa",
    "name": "externallmg_1709118725266_1709118882888_image_7.jpeg",
    "path": "cases/65dc7a38df99cf0e7361c43b/
externallmg_1709118725266_1709118882888_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65df15099a876858ab30f0fb",
    "name": "externallmg_1709118725837_1709118882888_image_8.jpeg",
    "path": "cases/65dc7a38df99cf0e7361c43b/
externallmg_1709118725837_1709118882888_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65df15099a876858ab30f0fc",
    "name": "externallmg_1709118726086_1709118882888_image_9.jpeg",
    "path": "cases/65dc7a38df99cf0e7361c43b/
externallmg_1709118726086_1709118882888_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "65df15099a876858ab30f0fd",
    "name": "externallmg_1709118726281_1709118882888_image_10.jpeg",
    "path": "cases/65dc7a38df99cf0e7361c43b/
externallmg_1709118726281_1709118882888_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65df15099a876858ab30f0fe",
    "name": "externallmg_1709118726377_1709118882888_image_11.jpeg",
    "path": "cases/65dc7a38df99cf0e7361c43b/
externallmg_1709118726377_1709118882888_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65df15099a876858ab30f0ff",
    "name": "externallmg_1709118726546_1709118882888_image_12.jpeg",
    "path": "cases/65dc7a38df99cf0e7361c43b/
externallmg_1709118726546_1709118882888_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65df15099a876858ab30f100",
    "name": "externallmg_1709118726676_1709118882888_image_13.jpeg",
    "path": "cases/65dc7a38df99cf0e7361c43b/
externallmg_1709118726676_1709118882888_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65df15099a876858ab30f101",
    "name": "externallmg_1709118726896_1709118882888_image_14.jpeg",
    "path": "cases/65dc7a38df99cf0e7361c43b/
externallmg_1709118726896_1709118882888_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```

```
    "_id": "65df15099a876858ab30f102",
    "name": "externallmg_1709118727406_1709118882888_image_15.jpeg",
    "path": "cases/65dc7a38df99cf0e7361c43b/
externallmg_1709118727406_1709118882888_image_15.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65df15099a876858ab30f103",
    "name": "externallmg_1709118727632_1709118882888_image_16.jpeg",
    "path": "cases/65dc7a38df99cf0e7361c43b/
externallmg_1709118727632_1709118882888_image_16.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65df15099a876858ab30f104",
    "name": "externallmg_1709118728342_1709118882888_image_17.jpeg",
    "path": "cases/65dc7a38df99cf0e7361c43b/
externallmg_1709118728342_1709118882888_image_17.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65df15099a876858ab30f105",
    "name": "externallmg_1709118728542_1709118882888_image_18.jpeg",
    "path": "cases/65dc7a38df99cf0e7361c43b/
externallmg_1709118728542_1709118882888_image_18.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65df15099a876858ab30f106",
    "name": "externallmg_1709118729093_1709118882888_image_19.jpeg",
    "path": "cases/65dc7a38df99cf0e7361c43b/
externallmg_1709118729093_1709118882888_image_19.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65df15249a876858ab30f133",
```

```
    "name": "externallmg_1709118750071_1709118907780_image_0.jpeg",
    "path": "cases/65dc7a38df99cf0e7361c43b/
externallmg_1709118750071_1709118907780_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65df15249a876858ab30f134",
    "name": "externallmg_1709118750882_1709118907780_image_1.jpeg",
    "path": "cases/65dc7a38df99cf0e7361c43b/
externallmg_1709118750882_1709118907780_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65df15249a876858ab30f135",
    "name": "externallmg_1709118751797_1709118907780_image_2.jpeg",
    "path": "cases/65dc7a38df99cf0e7361c43b/
externallmg_1709118751797_1709118907780_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65df15249a876858ab30f136",
    "name": "externallmg_1709118752784_1709118907780_image_3.jpeg",
    "path": "cases/65dc7a38df99cf0e7361c43b/
externallmg_1709118752784_1709118907780_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65df15249a876858ab30f137",
    "name": "externallmg_1709118753452_1709118907780_image_4.jpeg",
    "path": "cases/65dc7a38df99cf0e7361c43b/
externallmg_1709118753452_1709118907780_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65df14e29a876858ab30f08c",
    "name": "externallmg_1709118687516_1709118845805_image_0.jpeg",
```

```
    "path": "cases/65dc7a38df99cf0e7361c43b/
externalImg_1709118687516_1709118845805_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65df14e29a876858ab30f08d",
    "name": "externalImg_1709118688187_1709118845805_image_1.jpeg",
    "path": "cases/65dc7a38df99cf0e7361c43b/
externalImg_1709118688187_1709118845805_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65df14e29a876858ab30f08e",
    "name": "externalImg_1709118689534_1709118845805_image_2.jpeg",
    "path": "cases/65dc7a38df99cf0e7361c43b/
externalImg_1709118689534_1709118845805_image_2.jpeg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-02-26T11:47:04.735Z",
"updatedAt": "2024-02-29T09:11:41.488Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 1702, 17th Floor, Building No 119, Wing - A, Sayba
Opal, Nehru Nagar, Mother Dairy Road, Village - Kurla, Kurla (East), Mumbai, Taluka -
Kurla, District - Mumbai Suburban District, PIN Code - 400 024, State - Maharashtra,
India",
"updatedBy": "60092304a16fab0f2af9b0c2",
"addressForMap": "",
"caseReferredBy": "60b7177d2ffdf65bcd65882a",
"contactPersonName": "Mr. Sarfraz Khan",
"email": "",
"isExternal": "false",
"isUrgent": "false",
```



```
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Site Engineer",
"siteVisitContactNo": "9004721434",
"buildingServicesRate": "3000",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 543.00",
"flatRate": "21000",
"landOtherRate": "18000",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"finalSaleablePercentage": "0",
"briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + Dining + Passage + 2
Toilet",
"carpetTotal": "499.88",
"otherCarpetTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "549.87",
"finalCarpetArea": "499.88",
"finalSalableArea": "604.85",
"salablePercentage": "10",
```

"toBeAdded": "",  
 "extendOfSiteRemark": "All the above areas are within +/- 10% of the Agreement for Sale Area. The above calculations and detail measurements taken by us prove that the Agreement for Sale are is not exorbitantly inflated. Hence, valuation is based on the Agreement for Sale area",  
 "siteMeasurementRemark": "",  
 "otherCompositionBuiltUpTotal": "0.00",  
 "otherCompositionCarpetTotal": "0.00",  
 "otherCompositionSaleableTotal": "0.00",  
 "reportGeneratedDate": "Thu Feb 29 2024 10:40:56 GMT+0530 (India Standard Time)",  
 "siteVisitDate": "2024-02-28"  
 }

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
Composition :			
Living Room	8'5"	11'4"	95.39
Dining	8'7"	8'00"	68.67
Kitchen	6'9"	7'10"	52.87
Passage	8'11"	2'11"	26.01
Toilet	6'5"	3'9"	24.06
Bedroom	8'7"	11'1"	95.13
Toilet	3'8"	7'6"	27.50
Bedroom	9'00"	12'3"	110.25
Other Composition :			