

Asset Verification Report Prepared for: SFSPL / M/s. Remsons Industries Ltd. (7283/2305187)

Vastu/Thane/02/2024/7283/2305187
27/18-409 APU
Date: 27.02.2024

ASSET VERIFICATION REPORT

1. GENERAL INFORMATION

Agreement Number:	A10124728				
Label Number:	L1731B				
Customer:	M/s. Remsons Industries Ltd.				
Address of Asset Location:	Gat No. 268, 269, 270, Kharabwadi, Remsons Road, Taluka Khed, District Pune – 410501, Maharashtra, India.				
Asset/s financed as per Agreement	Sl.no	Asset Description	Model	Supplier	Quantity
	1	HCV Cable Line	N.A.	Simple Integral Private Limited	1 Set
Name Plate	<input type="checkbox"/> Available <input checked="" type="checkbox"/> Not Available		<input type="checkbox"/> Visible <input checked="" type="checkbox"/> Not Visible		
Serial number (On Asset)	<input type="checkbox"/> Available <input checked="" type="checkbox"/> Not Available		If Available – Refer Photos		
Serial number (in Invoice): (If available)	Not Available				
Type of Foundation for Asset (wherever applicable)	<input checked="" type="checkbox"/> Steel supporting structure		<input type="checkbox"/> Concrete floor <input type="checkbox"/> Other		
Level of Bondage	<input checked="" type="checkbox"/> Asset easy to remove		<input type="checkbox"/> Asset fixed permanently		
Description of the premises:	<input checked="" type="checkbox"/> Manufacturing Facility <input type="checkbox"/> Hospital <input type="checkbox"/> Warehouse <input type="checkbox"/> Office Premises <input type="checkbox"/> Diagnostic <input type="checkbox"/> Others (Please specify): _____				
Asset influencing circumstances (i.e Chemical Zone, Corrosive atmosphere, Highly Polluted location etc.):	<input type="checkbox"/> Yes If yes, please specify:		<input checked="" type="checkbox"/> No		

2 ASSET CONDITION

Optical impression of physical condition of Asset:	<input type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor <input type="checkbox"/> Very Poor				
Was the asset in operation at the time of Inspection	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No If No Please specify reasons				
Age of the Asset at the time of inspection	~ 6 Months				
Asset condition at the time of purchase	<input checked="" type="checkbox"/> New		<input type="checkbox"/> Used		
Any Breakdown in the machine	<input type="checkbox"/> Yes		<input type="checkbox"/> No		<input checked="" type="checkbox"/> Not Known
Photos:	<input checked="" type="checkbox"/> Yes		<input type="checkbox"/> No		



Thane : 101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) - 400 601, (M.S.), INDIA
E-mail : thane@vastukala.org, Tel. : 80978 82976 / 90216 25621

Our Pan India Presence at :

- Mumbai
- Aurangabad
- Pune
- Rajkot
- Thane
- Nanded
- Indore
- Raipur
- Delhi NCR
- Nashik
- Ahmedabad
- Jaipur

Regd. Office : B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Andheri (East), Mumbai - 400 072, (M.S.), INDIA
 TeleFax : +91 22 28371325/24
 mumbai@vastukala.org

3 INFORMATION ABOUT ONSITE VISIT

Date of Onsite Visit:	10/02/2024
Latitude & Longitude	18°45'54.1"N 73°50'08.3"E
Customer Personnel met at site:	Mr. Jaisingh Shelar – 9821080397.
Report created at	Mumbai

For Vastukala Consultants (I) Pvt. Ltd.

Umang Ashwin Patel

Regd. Valuer

Chartered Engineer (India)

Reg. No. IBBI/RV/04/2019/10803

Think.Innovate.Create

Photographs

