

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "6410bda0319ffa48baa5636c"
    },
    "type": "CREDITOFFICER",
    "_id": "6410bda0319ffa48baa5636e",
    "firstName": "Borlar",
    "lastName": "Borlar",
    "mobileNo": "",
    "workMobileNo": "0000000000",
    "email": "kopar@svc.com"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "6418456a96b58848585f8cb2",
  "name": "Thane",
  "email": "thane@vastukala.com",
  "phone": "1234567890",
  "address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
  "city": "Thane",
  "shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d185c",
  "type": "BANK",
  "name": "SVC CO-OPERATIVE BANK LTD",
  "displayName": "SVC BANK",
  "initial": "SVC",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "6410bda0319ffa48baa5636c",
  "name": "Koperkhairane Branch\t",
  "branchCode": "",
  "mobileNo": "02532455407",
  "alternateMobileNo": "",
  "email": "kopar@svc.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "FAM CHSL Shop no 5A to 9A Ground Floor , Plot no 19 & 19 A Sector
kperkhairane Navi Mumbai\n"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60fbaf81d8cfc56a13fa8863",
  "zoneName": "PAN INDIA"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "656aa949cebbe1714411d21b",
  "role": "FRONTDESK",
  "firstName": "Priyanka",
  "email": "thane@vastukala.org",
  "lastName": "Pawar",
  "mobileNo": "8928414480",
  "shortName": "PCP",
  "workWithDocumentMaker": "627222afafd7d55eddeddd82"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "65829f7c65d49d78457ec7be",
  "role": "SITEENGINEER",
  "firstName": "Vaibhav",
  "email": "vaib1234b@gmail.com",
  "lastName": "Bhagat",
  "mobileNo": "8779534609",
  "designation": "Bachlore Of Engireeing",
  "shortName": "Vaibhav",
  "workWithDocumentMaker": "62691c48afd7d55eddecfda3"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "9004437379",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\\
\\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627222afafd7d55eddeddd82",
  "role": "FRONTDESK",
  "firstName": "Pratibha",
  "email": "shilvanta_pratibha@yahoo.co.in",
  "lastName": "Shilvantha",
  "mobileNo": "9821518537",
  "designation": "",
  "shortName": "PS",
```

```
"workWithDocumentMaker": "60f915d3f3dd69653a592199",
"profilePhoto": "users/627222afafd7d55eddedd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      },
      {
        "title": {
          "value": "FIIV",
          "label": "FIIV"
        },
        "_id": "60af80072ffdf65bcd658652",
        "number": "CAT-I-F-1763"
      },
      {
        "title": {
          "value": "Chartered_Engineer",
          "label": "Chartered Engineer"
        },
        "_id": "60af80072ffdf65bcd658653",
        "number": "AM161706-3"
      }
    ]
  }
]
```

```
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.10350539265656",
  "longitude": "73.00992298943022"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": [],
  "remark": null,
  "rateMin": "15000",
  "lumpsumValue": "6000000",
  "rateMax": "20000",
  "areaType": {
    "Name": "Carpet",
    "Value": "Carpet",
```

```
    "name": "Carpet",
    "value": "Carpet"
  }
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Koparkhairane",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "Ground",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
```

```
"status": true,
"name": "District",
"key": "district",
"value": "Thane",
"label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Navi Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Thane",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "24",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Om Sai Owners Association",
  "label": false
},
"selectArea": {
  "status": true,
  "name": "Sector",
  "key": "selectArea",
  "value": "4",
```

```
"label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
```



```
"name": "New/Current Survey No.",
"key": "newSurveyNumber",
"value": "",
"label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "Apartment No. SS - III/934",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
}
```

```
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 400 709",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
```

```
"label": "R. C. C. Slab",
"value": "rcc_Slab"
},
"flooring": {
"label": "Vitrified Tile Flooring",
"value": "VerifiedTileFlooring"
},
"doors": {
"label": "Teak Wood Door Frame With Flush Shutters",
"value": "Teak_Wood_Door_Frame_With_Flush_Shutters"
},
"windows": {
"label": "M.S. Grill Fixed Windows",
"value": "M.S._Grill_Fixed_Windows"
},
"fittings": {
"label": "Concealed plumbing with C.P. fittings. Concealed Electrical wiring",
"value": "Concealed_plumbing_with_C.P._fittings._Concealed_Electrical_wiring"
},
"finishing": {
"label": "Cement Plastering + POP Finish",
"value": "Cement_Plastering_+_POP_Finish"
}
},
"general": {
"populationClassList": {
"label": "Middle Class",
"value": "MiddleClass"
},
"populationGroupList": {
"label": "Urban",
"value": "Urban"
},
"townplanApprovedByList": {
"label": "CIDCO",
"value": "CIDCO"
},
"asPerActualAgreement": {
"north": "row house no - 933",
"west": "row house no - 932",
"south": "open space",
"east": "row house no - 935"
},
"asPerDocumentAgreement": {
"north": "",
"west": "",
```

```
"south": "",
"east": ""
},
"unitBoundaries": {
  "asPerActual": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "asPerDocument": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
}
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "label": "Ordinary",
    "value": "Ordinary"
  },
  "propertyTypeOfUseList": {
    "label": "Residential Purpose",
    "value": "Residential_Purpose"
  },
  "propertyOccupiedByList": {
    "label": "Vacant",
    "value": "Vacant"
  },
  "monthlyRent": ""
},
"siteMeasurement": {
  "partitions": {
    "label": "6\" Thk. Brick Masonery",
    "value": "6\"_Thk._Brick_Masonery"
  },
  "waterTank": {
    "label": "CIDCO",
    "value": "CIDCO"
  }
}
```

```
},
"pavementLaid": {
  "label": "No",
  "value": "No"
},
"carParking": {
  "label": "Open Parking",
  "value": "Open_Parking"
},
"constructionWorkStatus": {
  "label": "Completed",
  "value": "Completed"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2023",
  "fullDate": "1/1/2023"
},
"propertyTypeList": {
  "label": "Residential",
  "value": "Residential"
},
"planningArea": {
  "label": "Residential",
  "value": "Residential"
},
"typeOfStructure": {
  "label": "R.C.C. Framed Structure",
  "value": "R.C.C._Framed_Structure"
},
"qualityOfConstruction": {
  "label": "Good",
  "value": "Good"
},
"walls": {
  "label": "No",
  "value": "0"
},
"appearanceOfTheBuilding": {
  "label": "Good",
  "value": "Good"
},
"maintenanceOfTheBuilding": {
  "label": "Good",
  "value": "Good"
}
```

```
},
"visibleDamageInBuilding": {
  "label": "No",
  "value": "0"
},
"groundStilt": {
  "label": "Ground",
  "value": "ground"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "59",
"ageOfBuilding": "1",
"noOfBasement": "0",
"noOfPodium": "0",
"noOfAmenityFloors": "0",
"noOfFloors": "03",
"flatFloorNo": "",
"noOfLifts": "0",
"noOfLiftsInEachWings": "0",
"noOfDwellingUnitsInBuilding": "01"
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  }
},
```

```
"rccPlinth": {
  "label": "RCC Plinth",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
```



```
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "0",
"selectedBuildUpValue": "0",
"selectedBuildUpMeasurementType": ""
},
"reportImages": {
"frontPageImages": [],
"selfieWithSiteVisitImages": [],
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
"carpetRateRange": {
"min": "0.00",
"max": "0.00"
},
"builtUpRateRange": {
"min": "0.00",
"max": "0.00"
}
},
"detailsOfValuation": {
"presentValueOfFlat": {
```

```
"title": "Present value of the flat (incl. car parking, if provided)",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```

```
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
```

```
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"invoices": [],
"paymentId": [],
"_id": "65ddc454e333566c7d3134ec",
"ownerName": "Mr. Mohammad Irfan Akbal Khan & Mrs. Tabassum Irfan Khan",
"ownerPhoneNo": "9322377789",
"fullAddress": "Residential Flat No. Apartment No. SS - III/934, Ground Floor, Om Sai
Owners Association, Plot No. 24, Sector 4, Village - Koparkhairane, Taluka - Thane,
District - Thane, Navi Mumbai, PIN Code - 400 709",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "16/03/2020",
      "from": {
        "value": "Seller",
        "label": "Seller"
      },
      "Seller": "Smt. Varsha Suresh Patil",
      "to": {
        "value": "purchaser",
```

```
    "label": "purchaser"
  },
  "purchaser": "Mr. Mohammad Irfan Akbal Khan & Mrs. Tabassum Irfan Khan",
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "4757/2020"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1709032520617_189846.pdf",
"path": "cases/65ddc454e333566c7d3134ec/
document_1709032520617_189846.pdf",
"id": "921420",
"uploadedBy": "656aa949cebbe1714411d21b",
"createdAt": "Tue Feb 27 2024 16:45:32 GMT+0530 (India Standard Time)"
}
],
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"caseNumber": "007290",
"createdBy": "656aa949cebbe1714411d21b",
"caseHistory": [
  {
    "id": "586813",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Feb 27 2024 16:45:32 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Mohammad Irfan Akbal Khan & Mrs. Tabassum Irfan Khan",
    "phone": "9322377789",
    "ownershipShare": "",
    "email": "",
    "id": "507081"
  }
],
"proposePurchasers": [],
"siteInspection": [
  {
    "areaType": {
```

```
    "label": "Carpet",
    "value": "Carpet"
  },
  "providedBy": {
    "label": "Owner",
    "value": "Owner"
  },
  "_id": "65e00e0a9a876858ab31c05b",
  "area": "563",
  "providedByName": "Mr. Mohammad Irfan Akbal Khan & Mrs. Tabassum Irfan Khan",
  "providedByContactNo": "9322377789"
}
],
"composition": [
  {
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "110525",
    "name": "Living Room",
    "length": "3610.00",
    "length1": "3610",
    "length2": "00",
    "width": "3550.00",
    "width1": "3550",
    "width2": "00",
    "totalArea": "12815500.00",
    "images": [],
    "extraAreas": [],
    "finalArea": "12815500.00"
  }
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65e00ee09a876858ab31c563",
    "name": "externalImg_1709182673512_image.jpeg",
    "path": "cases/65ddc454e333566c7d3134ec/
externalImg_1709182673512_image.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e00ee09a876858ab31c564",
  "name": "externallmg_1709182674020_image.jpeg",
  "path": "cases/65ddc454e333566c7d3134ec/
externallmg_1709182674020_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e00ee09a876858ab31c565",
  "name": "externallmg_1709182674218_image.jpeg",
  "path": "cases/65ddc454e333566c7d3134ec/
externallmg_1709182674218_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e00ee09a876858ab31c566",
  "name": "externallmg_1709182674706_image.jpeg",
  "path": "cases/65ddc454e333566c7d3134ec/
externallmg_1709182674706_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e00ee09a876858ab31c567",
  "name": "externallmg_1709182675464_image.jpeg",
  "path": "cases/65ddc454e333566c7d3134ec/
externallmg_1709182675464_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e00ee09a876858ab31c568",
  "name": "externallmg_1709182675509_image.jpeg",
  "path": "cases/65ddc454e333566c7d3134ec/
externallmg_1709182675509_image.jpeg",
  "orientation": "portrait"
}
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e00ee09a876858ab31c569",
  "name": "externalimg_1709182676452_image.jpeg",
  "path": "cases/65ddc454e333566c7d3134ec/
externalimg_1709182676452_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e00ee09a876858ab31c56a",
  "name": "externalimg_1709182676460_image.jpeg",
  "path": "cases/65ddc454e333566c7d3134ec/
externalimg_1709182676460_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e00ee09a876858ab31c56b",
  "name": "externalimg_1709182676633_image.jpeg",
  "path": "cases/65ddc454e333566c7d3134ec/
externalimg_1709182676633_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e00ee09a876858ab31c56c",
  "name": "externalimg_1709182676642_image.jpeg",
  "path": "cases/65ddc454e333566c7d3134ec/
externalimg_1709182676642_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e00ee09a876858ab31c56d",
  "name": "externalimg_1709182677359_image.jpeg",
  "path": "cases/65ddc454e333566c7d3134ec/
externalimg_1709182677359_image.jpeg",
  "orientation": "portrait"
},
}
```



```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e00ee09a876858ab31c56e",
  "name": "externallmg_1709182677851_image.jpeg",
  "path": "cases/65ddc454e333566c7d3134ec/
externallmg_1709182677851_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e00ee09a876858ab31c56f",
  "name": "externallmg_1709182678539_image.jpeg",
  "path": "cases/65ddc454e333566c7d3134ec/
externallmg_1709182678539_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e00ee09a876858ab31c570",
  "name": "externallmg_1709182680312_image.jpeg",
  "path": "cases/65ddc454e333566c7d3134ec/
externallmg_1709182680312_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e00ee09a876858ab31c571",
  "name": "externallmg_1709182683953_image.jpeg",
  "path": "cases/65ddc454e333566c7d3134ec/
externallmg_1709182683953_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e00ee09a876858ab31c572",
  "name": "externallmg_1709182684062_image.jpeg",
  "path": "cases/65ddc454e333566c7d3134ec/
externallmg_1709182684062_image.jpeg",
  "orientation": "landscape"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65e00ee09a876858ab31c573",
    "name": "externalimg_1709182684072_image.jpeg",
    "path": "cases/65ddc454e333566c7d3134ec/
externalimg_1709182684072_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65e00ee09a876858ab31c574",
    "name": "externalimg_1709182684077_image.jpeg",
    "path": "cases/65ddc454e333566c7d3134ec/
externalimg_1709182684077_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65e00ee09a876858ab31c575",
    "name": "externalimg_1709182684088_image.jpeg",
    "path": "cases/65ddc454e333566c7d3134ec/
externalimg_1709182684088_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65e00ee09a876858ab31c576",
    "name": "externalimg_1709182684101_image.jpeg",
    "path": "cases/65ddc454e333566c7d3134ec/
externalimg_1709182684101_image.jpeg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-02-27T11:15:32.265Z",
"updatedAt": "2024-02-29T04:58:23.388Z",
"__v": 0,
"updatedBy": "65829f7c65d49d78457ec7be",
"addressForMap": "",
```

```

"caseReferredBy": "64abdb2806d6ec174986d16b",
"contactPersonName": "Mr. Mohammad Irfan Akbal Khan & Mrs. Tabassum Irfan
Khan",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9322377789",
"briefDescOfProperty": "Living Room",
"carpetTotal": "12815500",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "0"
}

```

Name	Length	Width	Total
Composition :			
Living Room	3610'00"	3550'00"	12815500.00
Other Composition :			