

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b9f4"
    },
    "type": "CREDITOFFICER",
    "_id": "64d483a687258203eab0dd0f",
    "firstName": "Rohan ",
    "lastName": "Raut ",
    "mobileNo": "",
    "workMobileNo": "8097138369",
    "email": "Rohan.racpc.sion@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "5000000",
    "discussWithPerson": "Rohan ",
    "expectedFees": 2500,
    "quotedAmount": "2500"
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b9f4",
  "branchCode": "000215",
  "type": "BRANCH",
  "name": "RACPC Sion ",
  "email": "racpc.sion@sbi.co.in",
  "mobileNo": "02225046265",
  "alternateMobileNo": "",
  "address": "B-603 & 604, Kohinoor City, Commercial-1, 6th Floor, Kirol Road, Off
L.B.S. Marg, Kurla (West), Mumbai, Pin Code - 400 070, State - Maharashtra, Country -
India.",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "60b7177d2ffdf65bcd65882a",
  "role": "PICKUPPERSON",
  "firstName": "Saurabh",
  "email": "saurabhvelonde143@gmail.com",
  "lastName": "Velonde",
  "mobileNo": "8691048846",
  "shortName": "SSV",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1686816492317_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "60f9343b45132d6a6bdd96e8",
  "role": "SITEENGINEER",
  "firstName": "Rajesh",
  "email": "rajeshb.ghadi@gmail.com",
  "lastName": "Ghadi",
  "mobileNo": "8652092666",
  "designation": "",
  "shortName": "RHG",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "62fe044a48a26047e6552796",
  "role": "MAKER",
  "firstName": "Pradnya ",
  "email": "pradnya@vastukala.org",
  "lastName": "Rasam",
```

```
"mobileNo": "9529385821",
"designation": "",
"shortName": "PR",
"workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
"profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": {
  "_id": "60f915d3f3dd69653a592199",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg",
  "firstName": "Shobha",
  "lastName": "Kuperkar",
  "shortName": "SH",
  "email": "shobha@vastukala.org",
  "designation": "",
  "mobileNo": "9004134140",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "type": "EMPLOYEE",
  "workWithDocumentMaker": ""
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "AM161706-3",
        "label": "Chartered Engineer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
  }
]
```

```
"title": {
  "value": "FIIV",
  "label": "FIIV"
},
"_id": "60af80072ffdf65bcd658652",
"number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.069029",
  "longitude": "73.104284"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.104284,
    19.069029
  ]
}
```

```
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-02-29",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "Country - India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Kharghar ",
    "label": true
  }
}
```

```
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "13",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "E06",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Raigad ",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Navi Mumbai ",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Panvel",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
```

```
"key": "plotNo",
"value": "1, Sector - 40",
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Mass Housing Scheme (LIG - EWS)",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
}
```



```
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Bageshri Gruhsankul ",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
```

```
"value": "1306",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
```

```
"status": true,
"name": "Postal Code",
"key": "postalCode",
"value": "PIN - 410 208",
"label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Proposed_Powder_coated_aluminium_sliding_windows",
    "label": "Proposed Powder coated aluminium sliding windows"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering_+_POP_Finish",
    "label": "Cement Plastering + POP Finish"
  }
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
}
```

```
"populationClassList": {
  "value": "MiddleClass",
  "label": "Middle Class"
},
"populationGroupList": {
  "value": "Urban",
  "label": "Urban"
},
"townplanApprovedByList": {
  "value": "CIDCO",
  "label": "CIDCO"
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Internal Road ",
  "west": "Building No. E04",
  "south": "Holding Pond ",
  "east": "Open Plot "
},
"asPerDocumentAgreement": {
  "north": "Details not available ",
  "west": "Details not available ",
  "south": "Details not available ",
  "east": "Details not available "
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Details not available ",
    "east": "Details not available ",
    "south": "Details not available ",
    "west": "Details not available "
  },
  "asPerDocument": {
    "north": "Details not available ",
    "east": "Details not available ",
    "south": "Details not available ",
    "west": "Details not available "
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "As Occupancy Certificate is received may be assumed
```

```
that the construction is as per sanctioned plan. ",
  "approvePlanVerified": "N.A",
  "empanelledOfApprovePlan": "N.A",
  "unauthorizedConstruction": ""
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "0",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "buildingServicesDepreciatedRate": "0",
  "depreciatedCostOfConstruction": "11300.00",
  "depreciatedBuildingRate": "2600"
},
"igrRate": {
  "propertyName": "Residential",
  "rate": "55800",
  "landRate": "21100",
  "igrImage": "cases/65decc26e333566c7d31ffac/igr_1709272564400_Image.png",
  "squareMeterGuideLineRate": "55800.00",
  "squareFeetGuideLineRate": "5184.00"
},
"igrFinalRate": {
  "floorRatePercentage": "0",
  "depreciationPercentage": "95",
  "rate": "5023.00",
  "squareFeetGuideLineRate": "5023.00",
  "squareMeterGuideLineRate": "54065.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Tenant_Occupied",
    "label": "Tenant Occupied"
  },
  "monthlyRent": "9,000/- Present rental income per month ",
  "assessmentNo": "Details not available ",
  "taxPaidHolderName": "Details not available ",
  "taxAmount": "Details not available "
```

```
"electricityServiceConnectionNo": "Details not available ",
"meterCardHolderName": "Details not available ",
"undividedAreaOfLandAsPerSaleDeed": "Details not available ",
"floorSpaceIndex": "As per CIDCO norms ",
"tenantName": "Miss. Pooja Khushwe ",
"maintenanceOfFlat": "Good "
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area ",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Open Car Parking Space ",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "2021",
    "fullDate": "1/1/2021"
```

```
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
```

```
"value": "Good",
"label": "Good"
},
"maintenanceIssues": {
"value": "1",
"label": "Yes"
},
"visibleDamageInBuilding": {
"value": "1",
"label": "Yes"
},
"systemOfAirConditioning": {
"value": "1",
"label": "Yes"
},
"provisionOfFirefighting": {
"value": "1",
"label": "Yes"
},
"groundStilt": {
"value": "ground",
"label": "Ground"
},
"yearOfConstructionAsPer": {
"value": "as_per_occupancy_certificate",
"label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "57",
"ageOfBuilding": "3",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "14",
"flatFloorNo": "Basement",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "6"
},
"finalPlinthArea": {
"area": "305.80",
"areaType": "Built Up",
"measurementType": "Sq. Ft.",
"areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
```



```
"routeMapDetail": {
  "routeStation": {
    "value": "Railway_Station",
    "label": "Railway Station"
  },
  "routeMapImg": "cases/65decc26e333566c7d31ffac/
routeMap_1709278686779_Image.png",
  "routeLat": "19.067056",
  "routeLng": "73.086528",
  "stationName": "Taloja Panchanand ",
  "routeDistance": "2.1 Km. "
},
"finalLatLng": {
  "coordinates": [
    null,
    null
  ],
  "type": "Point"
},
"showLocation": {
  "latLng": true,
  "finallatLng": true
},
"locationMapImg": [
  {
    "id": "kv9txd",
    "name": "kv9txd",
    "image": "cases/65decc26e333566c7d31ffac/
routeMap_1709278566873_Image.png"
  }
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
```

```
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "3141400.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "3141400.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
```

```
"label": "Flooring, Tiling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
```

```
"status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "1536033.00",
  "selectedBuildUpValue": "305.80",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "65e185f2e104062801a9ff61",
      "name":
"externallmg_1709278705716_WhatsApp_Image_20240301_at_121436_PM_2.jpeg",
      "path": "cases/65decc26e333566c7d31ffac/
externallmg_1709278705716_WhatsApp_Image_20240301_at_121436_PM_2.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": [
    {
      "status": false,
      "_id": "65e185f2e104062801a9ff58",
      "name": "Living Room",
      "path": "cases/65decc26e333566c7d31ffac/
externallmg_1709278705671_WhatsApp_Image_20240301_at_121435_PM_1.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "65e185f2e104062801a9ff5a",
      "name": "Living Room",
      "path": "cases/65decc26e333566c7d31ffac/
externallmg_1709278705681_WhatsApp_Image_20240301_at_121435_PM_3.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65e185f2e104062801a9ff5b",
    "name": "Living Room",
    "path": "cases/65decc26e333566c7d31ffac/
externallmg_1709278705686_WhatsApp_Image_20240301_at_121435_PM_4.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65e185f2e104062801a9ff62",
    "name": "Living Room",
    "path": "cases/65decc26e333566c7d31ffac/
externallmg_1709278705723_WhatsApp_Image_20240301_at_121436_PM_3.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65e185ffe104062801a9ffa9",
    "name": "Living Room",
    "path": "cases/65decc26e333566c7d31ffac/
externallmg_1709278718827_WhatsApp_Image_20240301_at_121436_PM_6.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65e185f2e104062801a9ff61",
    "name": "Living Room",
    "path": "cases/65decc26e333566c7d31ffac/
externallmg_1709278705716_WhatsApp_Image_20240301_at_121436_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65e185f2e104062801a9ff5d",
    "name": "Living Room",
    "path": "cases/65decc26e333566c7d31ffac/
externallmg_1709278705694_WhatsApp_Image_20240301_at_121435_PM_6.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65e185f2e104062801a9ff5e",
    "name": "Living Room",
```

```
    "path": "cases/65decc26e333566c7d31ffac/
externallmg_1709278705699_WhatsApp_Image_20240301_at_121435_PM_7.jpeg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "11026",
    "max": "11429"
  },
  "builtUpRateRange": {
    "min": "10024",
    "max": "10390"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
```



```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "278.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3",
  "SME/TCC/221/13"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"invoices": [],
"paymentId": [],
"_id": "65decc26e333566c7d31ffac",
```

```
"ownerName": "Mr. Nitin Dilip Gaikwad & Ms. Swapnali Gaikwad",
"ownerPhoneNo": "7506581846",
"appAddress": "Flat no. 1306, 13th Floor, Building no. E-06, Mass Housing Scheme,
Sector - 40, Kharghar, Navi Mumbai ",
"remark": "Value confirm With Shobha madam ",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "29/09/2021",
      "remark": " (9 Pages from documents)",
      "from": {
        "value": "The_Corporation",
        "label": "The Corporation"
      },
      "The_Corporation": "City and Industrial Development Corporation of Maharashtra
(CIDCO)",
      "to": {
        "value": "Purchasers",
        "label": "Purchasers"
      },
      "Purchasers": "Mr. Nitin Dilip Gaikwad & Ms. Swapnali Gaikwad",
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "16754 / 2021"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "373742",
    "path": "cases/65decc26e333566c7d31ffac/
document_1709100054002_1709100215327_Racpc_SionNitin_Gaikwad.pdf",
    "fileName":
"document_1709100054002_1709100215327_Racpc_SionNitin_Gaikwad.pdf"
  },
  {
    "documentType": {
      "value": "60ae1258aa6d152c1801b33b",
      "label": "CIDCO Allotment Letter"
    },
    "inputs": {
      "documentDate": "09/09/2019",
```

```
"nameOfApprovingAuthority": {
  "value": "CIDCO",
  "label": "CIDCO"
},
"to": {
  "value": "Allottee",
  "label": "Allottee"
},
"Allottee": "Mr. Nitin Dilip Gaikwad & Ms. Swapnali Gaikwad"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1709275832530_document_1709100054002_17091002153
27_Racpc_SionNitin_Gaikwad.pdf",
"path": "cases/65decc26e333566c7d31ffac/document_1709275832530_document_
1709100054002_1709100215327_Racpc_SionNitin_Gaikwad.pdf",
"id": "340966",
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Fri Mar 01 2024 12:20:32 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1255aa6d152c1801b329",
    "label": "Possession Receipt"
  },
  "inputs": {
    "documentDate": "29/09/2021",
    "nameOfApprovingAuthority": {
      "value": "CIDCO",
      "label": "CIDCO"
    },
  },
  "remark": " in the name of Mr. Nitin Dilip Gaikwad & Ms. Swapnali Gaikwad"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1709276061114_document_1709100054002_17091002153
27_Racpc_SionNitin_Gaikwad.pdf",
"path": "cases/65decc26e333566c7d31ffac/document_1709276061114_document_
1709100054002_1709100215327_Racpc_SionNitin_Gaikwad.pdf",
"id": "597868",
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Fri Mar 01 2024 12:24:21 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
```

```
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "02/06/2021",
    "nameOfApprovingAuthority": {
      "value": "CIDCO",
      "label": "CIDCO"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "CIDCO / Sr. Arch (BP - IHP) / BP - IHP - 37 / 2021 / 000037"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1709276267610_document_1709100054002_17091002153
27_Racpc_SionNitin_Gaikwad.pdf",
  "path": "cases/65decc26e333566c7d31ffac/document_1709276267610_document_
1709100054002_1709100215327_Racpc_SionNitin_Gaikwad.pdf",
  "id": "300337",
  "uploadedBy": "62fe044a48a26047e6552796",
  "createdAt": "Fri Mar 01 2024 12:27:48 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "007302",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "471427",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Feb 28 2024 11:31:10 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Nitin Dilip Gaikwad & Ms. Swapnali Nitin Gaikwad",
    "phone": "7506581846",
    "ownershipShare": "",
    "email": "",
    "id": "148639"
  }
],
"proposePurchasers": [],
"siteInspection": [],
```

```
"composition": [  
  {  
    "measurementType": {  
      "value": "Square_Feet",  
      "label": "Square Feet"  
    },  
    "id": "625738",  
    "name": "Living Room",  
    "length": "9.67",  
    "length1": "9",  
    "length2": "8",  
    "width": "12.42",  
    "width1": "12",  
    "width2": "5",  
    "totalArea": "120.03",  
    "images": [],  
    "extraAreas": [],  
    "finalArea": "120.03"  
  },  
  {  
    "measurementType": {  
      "value": "Square_Feet",  
      "label": "Square Feet"  
    },  
    "id": "1",  
    "name": "WC",  
    "length": "4.00",  
    "length1": "4",  
    "length2": "00",  
    "width": "4.00",  
    "width1": "4",  
    "width2": "00",  
    "totalArea": "16.00",  
    "images": [],  
    "extraAreas": [],  
    "finalArea": "16.00"  
  },  
  {  
    "measurementType": {  
      "value": "Square_Feet",  
      "label": "Square Feet"  
    },  
    "id": "2",  
    "name": "Bathroom",  
    "length": "3.00",  
    "length1": "3",
```

```
"length2": "00",
"width": "4.00",
"width1": "4",
"width2": "00",
"totalArea": "12.00",
"images": [],
"extraAreas": [],
"finalArea": "12.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Kitchen",
  "length": "6.33",
  "length1": "6",
  "length2": "4",
  "width": "7.00",
  "width1": "7",
  "width2": "00",
  "totalArea": "44.33",
  "images": [],
  "extraAreas": [],
  "finalArea": "44.33"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Bedroom",
  "length": "9.75",
  "length1": "9",
  "length2": "9",
  "width": "9.92",
  "width1": "9",
  "width2": "11",
  "totalArea": "96.69",
  "images": [],
  "extraAreas": [],
  "finalArea": "96.69"
}
],
```

```
"otherComposition": [
  {
    "toBeAdded": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "name": {
      "label": "Cupboard",
      "value": "Cupboard"
    },
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "0",
    "length": "2.00",
    "length1": "2",
    "length2": "00",
    "width": "5.00",
    "width1": "5",
    "width2": "00",
    "totalArea": "10.00",
    "images": [],
    "extraAreas": [],
    "finalArea": "10",
    "percentageBeforeTotal": "10.00",
    "percentage": "100"
  }
],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "label": " Agreement",
      "value": "652d16a0316e1359cebd3c15"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "selectAreaTypeDocument": "Carpet",
    "squareMeterArea": "25.83",
    "totalAreaDocument": "278",
    "docBuiltpPercentage": "10",
    "docFinalBUILTUp": "305.80",
    "docFinalBUILTUpSquareMeter": "28.41",
```

```
"docSaleablePercentage": "",
"docFinalSaleable": "0.00",
"docFinalSaleableSquareMeter": "0.00",
"id": "399884"
}
],
"images": [],
"indicatorArr": [
{
  "printlnReport": true,
  "_id": "65e16e36e104062801a9baa5",
  "property": "Kharghar Sector 40 Mass Housing",
  "area": "280",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "3",
  "source": "https://www.99acres.com/",
  "expectedPrice": "3200000",
  "expectedRate": "11428.57",
  "builtUpExpectedRate": "10389.61",
  "image": "cases/65decc26e333566c7d31ffac/
indicator_1709272390361_Image.png",
  "squareMeter": "26.01",
  "id": "405244"
},
{
  "printlnReport": true,
  "_id": "65e16e36e104062801a9baa6",
  "property": "Kharghar Sector 40 Mass Housing",
  "area": "320",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "5",
  "source": "https://www.99acres.com/",
  "expectedPrice": "3600000",
  "expectedRate": "11250.00",
  "builtUpExpectedRate": "10227.27",
  "image": "cases/65decc26e333566c7d31ffac/
indicator_1709272430670_Image.png",
  "squareMeter": "29.73",
  "id": "986285"
},
}
```



```
{
  "printlnReport": true,
  "_id": "65e16e36e104062801a9baa7",
  "property": "Bhageshree CHSL, Kharghar Sector 40",
  "area": "310",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "Middle",
  "source": "Nobroker.com",
  "expectedPrice": "3500000",
  "expectedRate": "11290.32",
  "builtUpExpectedRate": "10263.93",
  "image": "cases/65decc26e333566c7d31ffac/
indicator_1709272476581_Image.png",
  "squareMeter": "28.80",
  "id": "880861"
},
{
  "printlnReport": true,
  "_id": "65e16e36e104062801a9baa8",
  "property": "Bageshreee CHSL., Kharghar Sector 40",
  "area": "390",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "Middle",
  "source": "Nobroker.com",
  "expectedPrice": "4300000",
  "expectedRate": "11025.64",
  "builtUpExpectedRate": "10023.31",
  "image": "cases/65decc26e333566c7d31ffac/
indicator_1709272534743_Image.png",
  "squareMeter": "36.23",
  "id": "827238"
}
],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65e185f2e104062801a9ff55",
    "name":
"externallmg_1709278705649_WhatsApp_Image_20240301_at_121434_PM_1.jpeg",
```

```
    "path": "cases/65decc26e333566c7d31ffac/
externallmg_1709278705649_WhatsApp_Image_20240301_at_121434_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65e185f2e104062801a9ff56",
    "name":
"externallmg_1709278705654_WhatsApp_Image_20240301_at_121434_PM_2.jpeg",
    "path": "cases/65decc26e333566c7d31ffac/
externallmg_1709278705654_WhatsApp_Image_20240301_at_121434_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65e185f2e104062801a9ff57",
    "name":
"externallmg_1709278705662_WhatsApp_Image_20240301_at_121434_PM.jpeg",
    "path": "cases/65decc26e333566c7d31ffac/
externallmg_1709278705662_WhatsApp_Image_20240301_at_121434_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65e185f2e104062801a9ff58",
    "name":
"externallmg_1709278705671_WhatsApp_Image_20240301_at_121435_PM_1.jpeg",
    "path": "cases/65decc26e333566c7d31ffac/
externallmg_1709278705671_WhatsApp_Image_20240301_at_121435_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65e185f2e104062801a9ff59",
    "name":
"externallmg_1709278705676_WhatsApp_Image_20240301_at_121435_PM_2.jpeg",
    "path": "cases/65decc26e333566c7d31ffac/
externallmg_1709278705676_WhatsApp_Image_20240301_at_121435_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "65e185f2e104062801a9ff5a",
  "name":
"externallmg_1709278705681_WhatsApp_Image_20240301_at_121435_PM_3.jpeg",
  "path": "cases/65decc26e333566c7d31ffac/
externallmg_1709278705681_WhatsApp_Image_20240301_at_121435_PM_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e185f2e104062801a9ff5b",
  "name":
"externallmg_1709278705686_WhatsApp_Image_20240301_at_121435_PM_4.jpeg",
  "path": "cases/65decc26e333566c7d31ffac/
externallmg_1709278705686_WhatsApp_Image_20240301_at_121435_PM_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e185f2e104062801a9ff5c",
  "name":
"externallmg_1709278705690_WhatsApp_Image_20240301_at_121435_PM_5.jpeg",
  "path": "cases/65decc26e333566c7d31ffac/
externallmg_1709278705690_WhatsApp_Image_20240301_at_121435_PM_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e185f2e104062801a9ff5d",
  "name":
"externallmg_1709278705694_WhatsApp_Image_20240301_at_121435_PM_6.jpeg",
  "path": "cases/65decc26e333566c7d31ffac/
externallmg_1709278705694_WhatsApp_Image_20240301_at_121435_PM_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e185f2e104062801a9ff5e",
  "name":
"externallmg_1709278705699_WhatsApp_Image_20240301_at_121435_PM_7.jpeg",
  "path": "cases/65decc26e333566c7d31ffac/
externallmg_1709278705699_WhatsApp_Image_20240301_at_121435_PM_7.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65e185f2e104062801a9ff5f",
    "name":
"externallmg_1709278705707_WhatsApp_Image_20240301_at_121435_PM.jpeg",
    "path": "cases/65decc26e333566c7d31ffac/
externallmg_1709278705707_WhatsApp_Image_20240301_at_121435_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65e185f2e104062801a9ff60",
    "name":
"externallmg_1709278705712_WhatsApp_Image_20240301_at_121436_PM_1.jpeg",
    "path": "cases/65decc26e333566c7d31ffac/
externallmg_1709278705712_WhatsApp_Image_20240301_at_121436_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65e185f2e104062801a9ff61",
    "name":
"externallmg_1709278705716_WhatsApp_Image_20240301_at_121436_PM_2.jpeg",
    "path": "cases/65decc26e333566c7d31ffac/
externallmg_1709278705716_WhatsApp_Image_20240301_at_121436_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65e185f2e104062801a9ff62",
    "name":
"externallmg_1709278705723_WhatsApp_Image_20240301_at_121436_PM_3.jpeg",
    "path": "cases/65decc26e333566c7d31ffac/
externallmg_1709278705723_WhatsApp_Image_20240301_at_121436_PM_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65e185ffe104062801a9ffa7",
```

```
"name":
"externallmg_1709278718807_WhatsApp_Image_20240301_at_121436_PM_4.jpeg",
  "path": "cases/65decc26e333566c7d31ffac/
externallmg_1709278718807_WhatsApp_Image_20240301_at_121436_PM_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e185ffe104062801a9ffa8",
  "name":
"externallmg_1709278718818_WhatsApp_Image_20240301_at_121436_PM_5.jpeg",
  "path": "cases/65decc26e333566c7d31ffac/
externallmg_1709278718818_WhatsApp_Image_20240301_at_121436_PM_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e185ffe104062801a9ffa9",
  "name":
"externallmg_1709278718827_WhatsApp_Image_20240301_at_121436_PM_6.jpeg",
  "path": "cases/65decc26e333566c7d31ffac/
externallmg_1709278718827_WhatsApp_Image_20240301_at_121436_PM_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e185ffe104062801a9ffaa",
  "name":
"externallmg_1709278718834_WhatsApp_Image_20240301_at_121436_PM_7.jpeg",
  "path": "cases/65decc26e333566c7d31ffac/
externallmg_1709278718834_WhatsApp_Image_20240301_at_121436_PM_7.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e185ffe104062801a9ffab",
  "name":
"externallmg_1709278718843_WhatsApp_Image_20240301_at_121436_PM_8.jpeg",
  "path": "cases/65decc26e333566c7d31ffac/
externallmg_1709278718843_WhatsApp_Image_20240301_at_121436_PM_8.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e185ffe104062801a9ffac",
  "name":
"externalImg_1709278718848_WhatsApp_Image_20240301_at_121436_PM.jpeg",
  "path": "cases/65decc26e333566c7d31ffac/
externalImg_1709278718848_WhatsApp_Image_20240301_at_121436_PM.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-02-28T06:01:10.506Z",
"updatedAt": "2024-03-01T07:58:23.777Z",
"__v": 0,
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"fullAddress": "Residential Flat No. 1306, 13th Floor, Building No E06, Mass Housing
Scheme (LIG - EWS), Bageshri Gruhsankul , Plot No. 1, Sector - 40, Village -
Kharghar , Taluka - Panvel, District - Raigad , Navi Mumbai , PIN - 410 208, State -
Maharashtra, Country - India",
"updatedBy": "60f915d3f3dd69653a592199",
"addressForMap": "",
"caseReferredBy": "",
"contactPersonName": "Miss. Pooja Khushwe ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Tenant ",
"siteVisitContactNo": "7506581846",
"buildingServicesRate": "2600.00",
"finalAreaType": "Carpet Area",
"finalAsPerArea": " Agreement",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 278.00",
```

```
"flatRate": "11300",
"landOtherRate": "8700",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
"builtupPercentage": "10",
"carpetTotal": "289.05",
"extendOfSiteRemark": "",
"finalBuiltupArea": "328.96",
"finalCarpetArea": "299.05",
"finalSalableArea": "361.85",
"otherCarpetTotal": "10.00",
"salablePercentage": "10",
"siteMeasurementRemark": "Carpet Area in Sq. Ft. = 289.00\nCupboard Area in Sq.
Ft. = 10.00\n\n",
"toBeAdded": "",
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + WC + Bathroom",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "10.00",
"otherCompositionSaleableTotal": "0.00",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
},
"leaseDetails": {
  "lessorName": "",
  "lesseeName": "",
  "leasePremium": "",
  "leaseRent": "",
  "leasePeriod": 0,
  "leaseFrom": "",
  "leaseTo": "",
  "remainingLeasePeriod": 0,
  "leaseDate": ""
}
},
"reportGeneratedDate": "Fri Mar 01 2024 12:15:57 GMT+0530 (India Standard Time)",
"siteVisitDate": "2024-02-29"
}
```

Name	Length	Width	Total
Composition :			
Living Room	9'8"	12'5"	120.03
WC	4'00"	4'00"	16.00
Bathroom	3'00"	4'00"	12.00
Kitchen	6'4"	7'00"	44.33
Bedroom	9'9"	9'11"	96.69
Other Composition :			
Cupboard	2'00"	5'00"	10.00