

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856bb63"
    },
    "type": "CREDITOFFICER",
    "_id": "64bb68afa87c525d5c04ab8b",
    "firstName": "Sayali",
    "lastName": "Bangar",
    "mobileNo": "",
    "workMobileNo": "8097275708",
    "email": "cord.racpckalyan@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "6418456a96b58848585f8cb2",
  "name": "Thane",
  "email": "thane@vastukala.com",
  "phone": "1234567890",
  "address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
  "city": "Thane",
  "shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856bb63",
  "branchCode": "000355",
  "type": "BRANCH",
  "name": "RACPC Kalyan",
  "email": "cord.racpckalyan@sbi.co.in",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "address": "Ground Floor, 1 st Floor, Millenium Heights, Opp. Patedar Bhawan
Marriage Hall, Shahad Mohone Road, Shahad, Kalyan (West) - 421 103 \n\n",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "6410199a140f140ffc59b58c",
  "role": "PICKUPPERSON",
  "firstName": "Prakash ",
  "email": "prakashnvetkoli@gmail.com",
  "lastName": "Vetkoli",
  "mobileNo": "9076237689",
  "shortName": "PV",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/6410199a140f140ffc59b58c/
profilePhoto_1689054480133_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "64e5a649daae6a1c98101989",
  "role": "SITEENGINEER",
  "firstName": "Sameer",
  "email": "sameeryp2010@gmail.com",
  "lastName": "Parab",
  "mobileNo": "8291009567",
  "designation": "Site Engineer",
  "shortName": "Sameer",
  "workWithDocumentMaker": "62ea09ea4e679b264caf07d7"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": "",
  "shortName": "SK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Shym_Photo.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627222afafd7d55eddeddd82",
  "role": "FRONTDESK",
  "firstName": "Pratibha",
  "email": "shilvanta_pratibha@yahoo.co.in",
  "lastName": "Shilvantha",
```

```
"mobileNo": "9821518537",
"designation": "",
"shortName": "PS",
"workWithDocumentMaker": "60f915d3f3dd69653a592199",
"profilePhoto": "users/627222afafd7d55eddeddd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": "",
  "shortName": "SK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\
profilePhoto_1626255068979_Sh Yam_Photo.jpg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  {
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ]
  }
]
```

```
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.24998301447386",
  "longitude": "73.10516488864526"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
}
```

```
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-03-04",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-03-04",
      "remark": "MANUAL_IN_TASK"
    }
  ],
  "schedule": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
```

```
"status": true,
"name": "Village",
"key": "village",
"value": "Kon",
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "7",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Bhiwandi",
```

```
"label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Namo Maxima",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Water Supply Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Near Chhatrapati Shivaji Maharaj Kridangan",
  "label": false
},
"wing": {
  "status": false,
```



```
"name": "Wing",
"key": "wing",
"value": "",
"label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "188/1",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
}
```

```
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "705",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
```

```
"key": "GUTNo",
"value": "",
"label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 421 311",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "Proposed_RCC_SLab",
    "label": "Proposed RCC SLab"
  },
  "flooring": {
    "value": "Proposed_Vitrified_tiles_flooring",
    "label": "Proposed Vitrified tiles flooring"
  },
  "doors": {
    "value": "Proposed_Teak_wood_door_frame_with_flush_doors",
    "label": "Proposed Teak wood door frame with flush doors"
  },
  "windows": {
    "value": "Proposed_Powder_coated_aluminium_sliding_windows",
    "label": "Proposed Powder coated aluminium sliding windows"
  },
  "fittings": {
    "value": "Concealed_plumbing_with_C.P._fittings._Concealed_Electrical_wiring",
    "label": "Concealed plumbing with C.P. fittings. Concealed Electrical wiring"
  },
  "finishing": {
    "value": "Proposed_Cement_Plastering",
    "label": "Proposed Cement Plastering"
  }
}
},
"general": {
```

```
"ownership": {
  "value": "Sole_Ownership",
  "label": "Sole Ownership"
},
"populationClassList": {
  "value": "MiddleClass",
  "label": "Middle Class"
},
"populationGroupList": {
  "value": "Urban",
  "label": "Urban"
},
"townplanApprovedByList": {
  "value": "Mumbai_Metropolitan_Region_Development_Authority",
  "label": "Mumbai Metropolitan Region Development Authority"
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Internal Road",
  "west": "Timber Mart",
  "south": "Koli Darbar Dhaba",
  "east": "Water Supply Road"
},
"asPerDocumentAgreement": {
  "north": "Survey No. 278/23",
  "west": "Survey No. 278",
  "south": "Survey No. 188/2",
  "east": "12 Meter Road"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Detail not available",
    "east": "Detail not available",
    "south": "Detail not available",
    "west": "Detail not available"
  },
  "asPerDocument": {
    "north": "Detail not available",
    "east": "Detail not available",
    "south": "Detail not available",
    "west": "Detail not available"
  },
  "isDisplay": false,
```

```
"title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "Copy of Approved Building Plan No. SROT / BSNA /
2501 / BP / Kon-114 / CC/1241/2023 Dated 11.09.2023 issued by Mumbai Metropolitan
Region Development Authority.",
"approvePlanVerified": "Yes",
"empanelledOfApprovePlan": "No",
"unauthorizedConstruction": ""
},
"compositeRate": {
"remark": "",
"depreciationPercentage": "",
"depreciationRatioOfBuilding": "",
"salvageValue": "",
"depreciatedCostOfConstruction": "",
"depreciatedBuildingRate": ""
},
"igrRate": {
"propertyName": "Residential Flat",
"rate": "28400",
"landRate": "3540",
"igrImage": "cases/65e2e838f9222577acb6d792/igr_1709715633491_Image.png",
"squareMeterGuideLineRate": "29820.00",
"squareFeetGuideLineRate": "2770.00"
},
"igrFinalRate": {
"floorRatePercentage": "5",
"depreciationPercentage": "0",
"rate": "28400.00",
"squareMeterGuideLineRate": "29820.00",
"squareFeetGuideLineRate": "2770.00"
},
"outgoingDetail": {
"areaStatusList": {
"value": "Medium",
"label": "Medium"
},
"propertyTypeOfUseList": {
"value": "Residential_Purpose",
"label": "Residential Purpose"
},
"propertyOccupiedByList": {
"value": "Building_Under_Construction",
"label": "Building Under Construction"
},
}
```

```
"monthlyRent": "N.A.",
"assessmentNo": "Details not available",
"taxPaidHolderName": "Details not available",
"taxAmount": "Details not available",
"electricityServiceConnectionNo": "Details not available",
"meterCardHolderName": "Details not available",
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per MMRDA norms",
"tenantName": "",
"maintenanceOfFlat": "Building is under construction"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "Proposed_R.C.C._Slab",
    "label": "Proposed R.C.C. Slab"
  },
  "partitions": {
    "value": "Proposed_6\"_Thk._Brick_Masonry",
    "label": "Proposed 6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "Proposed_Municipal_Water_Supply",
    "label": "Proposed Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Proposed,_Yes",
    "label": "Proposed, Yes"
  },
  "carParking": "Stilt Parking",
  "constructionWorkStatus": {
    "value": "InProgress",
    "label": "Under Construction"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
```

```
"date": "",
"month": "1",
"year": "2026",
"fullDate": "1/1/2026"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "Proposed_RCC_Slab",
  "label": "Proposed RCC Slab"
},
"typeOfFoundation": {
  "value": "Proposed_R.C.C._Foundation",
  "label": "Proposed R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"materialUsedList": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"buildingSpecification": {
  "value": "Proposed_Standard",
  "label": "Proposed Standard"
},
"structuralSafety": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "Proposed_Connected_to_Municipal_Sewerage_System_",
  "label": "Proposed Connected to Municipal Sewerage System "
},
"walls": {
  "value": "Proposed,_Yes",
  "label": "Proposed, Yes"
},
"appearanceOfTheBuilding": {
```

```
"value": "UnderConstruction",
"label": "Building Under Construction"
},
"maintenanceOfTheBuilding": {
"value": "UnderConstruction",
"label": "Building Under Construction"
},
"maintenanceIssues": {
"value": "Building_Under_Construction",
"label": "Building Under Construction"
},
"visibleDamageInBuilding": {
"value": "Building_Under_Construction",
"label": "Building Under Construction"
},
"systemOfAirConditioning": {
"value": "Building_Under_Construction",
"label": "Building Under Construction"
},
"provisionOfFirefighting": {
"value": "Building_Under_Construction",
"label": "Building Under Construction"
},
"groundStilt": {
"value": "Part_Ground_and_Part_Stilt",
"label": "Part Ground + Part Stilt"
},
"yearOfConstructionAsPer": {
"value": "as_per_site_information",
"label": "As per site information"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "0",
"ageOfBuilding": "0",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "7",
"flatFloorNo": "7",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "7"
},
"finalPlinthArea": {
"area": "532.40",
"areaType": "Built Up",
```



```
"measurementType": "Sq. Ft.",
"areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/65e2e838f9222577acb6d792/
routeMap_1709726405621_Image.png",
    "routeLat": "19.251083",
    "routeLng": "73.104993",
    "stationName": "Kalyan",
    "routeDistance": "4.2 KM"
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "pgwndl",
      "name": "pgwndl",
      "image": "cases/65e2e838f9222577acb6d792/
routeMap_1709725038119_Image.png"
    }
  ]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
```

```
"superfineFinishQty": "0",
"superfineFinishRate": "0",
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "4017200.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "4017200.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
}
```

```
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
```

```
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "10.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "1474748.00",
"selectedBuildUpValue": "532.40",
"selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
"frontPageImages": [
{
"status": false,
"_id": "65e59feaf9222577acb8e1db",
"name": "externallmg_1709547496556_1709547660478_image_3.jpeg",
"path": "cases/65e2e838f9222577acb6d792/
externallmg_1709547496556_1709547660478_image_3.jpeg",
"orientation": "landscape"
}
],
"selfieWithSiteVisitImages": [],
"externalPhotos": [
{
"status": false,
"_id": "65e59feaf9222577acb8e1d8",
"name": "externallmg_1709547495307_1709547660478_image_0.jpeg",
"path": "cases/65e2e838f9222577acb6d792/
externallmg_1709547495307_1709547660478_image_0.jpeg",
"orientation": "landscape"
},
{
"status": false,
"_id": "65e59feaf9222577acb8e1da",
"name": "externallmg_1709547496208_1709547660478_image_2.jpeg",
"path": "cases/65e2e838f9222577acb6d792/
externallmg_1709547496208_1709547660478_image_2.jpeg",
```

```
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "65e59feaf9222577acb8e1db",
    "name": "externallmg_1709547496556_1709547660478_image_3.jpeg",
    "path": "cases/65e2e838f9222577acb6d792/
externallmg_1709547496556_1709547660478_image_3.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "65e59feaf9222577acb8e1de",
    "name": "externallmg_1709547497213_1709547660478_image_6.jpeg",
    "path": "cases/65e2e838f9222577acb6d792/
externallmg_1709547497213_1709547660478_image_6.jpeg",
    "orientation": "landscape"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "8000",
    "max": "9057"
  },
  "builtUpRateRange": {
    "min": "7273",
    "max": "8234"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
```



```
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "484.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3",
  "SME/TCC/221/13"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"invoices": [],
"paymentIds": [],
"_id": "65e2e838f9222577acb6d792",
"ownerName": "Mr. Deepesh Ganesh Shetty",
"ownerPhoneNo": "9821246962",
"fullAddress": "Residential Flat No. 705, 7th Floor, Namo Maxima, Near Chhatrapati
Shivaji Maharaj Kridangan, Water Supply Road, Village - Kon, Taluka - Bhiwandi,
District - Thane, PIN Code - 421 311, State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "01/02/2024",
      "from": {
        "value": "Promoter",
        "label": "Promoter"
      },
      "Promoter": "M/s. Jain Realty",
      "to": {
        "value": "The_Allottees",
        "label": "The Allottees"
      },
      "The_Allottees": "Mr. Deepesh Ganesh Shetty",
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "1021/2024"
```

```
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "528683",
    "path": "cases/65e2e838f9222577acb6d792/
document_1709369364051_AGREEMENT_0001.pdf",
    "fileName": "document_1709369364051_AGREEMENT_0001.pdf"
  },
  {
    "documentType": {
      "value": "60ae129faa6d152c1801b47d",
      "label": "RERA Certificate"
    },
    "inputs": {
      "documentDate": "27/10/2023",
      "nameOfApprovingAuthority": {
        "value": "Maharashtra_Real_Estate_Regulatory_Authority",
        "label": "Maharashtra Real Estate Regulatory Authority"
      },
      "number": {
        "value": "No",
        "label": "No"
      }
    },
    "No": "P51700053313"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "566184",
  "path": "cases/65e2e838f9222577acb6d792/
document_1709369383427_RERA_0001.pdf",
  "fileName": "document_1709369383427_RERA_0001.pdf"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "11/09/2023",
    "nameOfApprovingAuthority": {
      "value": "Mumbai_Metropolitan_Region_Development_Authority",
      "label": "Mumbai Metropolitan Region Development Authority"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  }
}
```

```
    },
    "No": "SROT / BSNA / 2501 / BP / Kon-114 / CC/1241/2023"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1709723336901_1_Commencement_Certificates__NA_Order_for_plotted_development__20240306T163825991.pdf",
  "path": "cases/65e2e838f9222577acb6d792/document_1709723336901_1_Commencement_Certificates__NA_Order_for_plotted_development__20240306T163825991.pdf",
  "id": "332422",
  "uploadedBy": "627222afafd7d55eddeddd82",
  "createdAt": "Wed Mar 06 2024 16:38:57 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1277aa6d152c1801b3cc",
    "label": "Approved Building Plan"
  },
  "inputs": {
    "documentDate": "11/09/2023",
    "nameOfApprovingAuthority": {
      "value": "Mumbai_Metropolitan_Region_Development_Authority",
      "label": "Mumbai Metropolitan Region Development Authority"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "SROT / BSNA / 2501 / BP / Kon-114 / CC/1241/2023"
},
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1709723557507_1_Copy_of_Layout_Approval_in_case_of_Layout__20240306T164200948.pdf",
  "path": "cases/65e2e838f9222577acb6d792/document_1709723557507_1_Copy_of_Layout_Approval_in_case_of_Layout__20240306T164200948.pdf",
  "id": "488241",
  "uploadedBy": "627222afafd7d55eddeddd82",
  "createdAt": "Wed Mar 06 2024 16:42:37 GMT+0530 (India Standard Time)"
}
],
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
}
```

```
"caseNumber": "007383",
"createdBy": "6410199a140f140ffc59b58c",
"caseHistory": [
  {
    "id": "309554",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Sat Mar 02 2024 14:20:00 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Deepesh Ganesh Shetty",
    "phone": "9821246962",
    "ownershipShare": "",
    "email": "",
    "id": "901286"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "827441",
    "name": "Living Room",
    "length": "0.00",
    "length1": "0",
    "length2": "00",
    "width": "0.00",
    "width1": "0",
    "width2": "00",
    "totalArea": "0.00",
    "images": [],
    "extraAreas": [],
    "finalArea": "0.00"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "1",
```

```
"name": "Bedroom",
"length": "0.00",
"length1": "0",
"length2": "00",
"width": "0.00",
"width1": "0",
"width2": "00",
"totalArea": "0.00",
"images": [],
"extraAreas": [],
"finalArea": "0.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Kitchen",
  "length": "0.00",
  "length1": "0",
  "length2": "00",
  "width": "0.00",
  "width1": "0",
  "width2": "00",
  "totalArea": "0.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "0.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Toilet",
  "length": "0.00",
  "length1": "0",
  "length2": "00",
  "width": "0.00",
  "width1": "0",
  "width2": "00",
  "totalArea": "0.00",
  "images": [],
  "extraAreas": [],
```

```
"finalArea": "0.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Toilet",
  "length": "0.00",
  "length1": "0",
  "length2": "00",
  "width": "0.00",
  "width1": "0",
  "width2": "00",
  "totalArea": "0.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "0.00"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "selectAreaTypeDocument": "Carpet",
    "squareMeterArea": "44.97",
    "totalAreaDocument": "484",
    "docBuiltpupPercentage": "10",
    "docFinalBuiltpup": "532.40",
    "docFinalBuiltpupSquareMeter": "49.46",
    "docSaleablePercentage": "",
    "docFinalSaleable": "0.00",
    "docFinalSaleableSquareMeter": "0.00",
    "id": "863988"
  }
],
"images": [],
```

```
"indicatorArr": [  
  {  
    "printlnReport": true,  
    "_id": "65e830b6f9222577acbca69a",  
    "property": "Residential Flat",  
    "area": "341",  
    "builtUpPercentage": "10",  
    "saleablePercentage": "0",  
    "rateType": "sale_Instance",  
    "areaType": "Carpet",  
    "source": "Index_no.2",  
    "expectedPrice": "2863889",  
    "expectedRate": "8398.50",  
    "builtUpExpectedRate": "7635.00",  
    "image": "cases/65e2e838f9222577acb6d792/  
indicator_1709715436053_Image.jpeg",  
    "squareMeter": "31.68",  
    "id": "260648"  
  },  
  {  
    "printlnReport": true,  
    "_id": "65e830b6f9222577acbca69b",  
    "property": "Residential Flat",  
    "area": "341",  
    "builtUpPercentage": "10",  
    "saleablePercentage": "0",  
    "rateType": "sale_Instance",  
    "areaType": "Carpet",  
    "source": "Index_no.2",  
    "expectedPrice": "2863889",  
    "expectedRate": "8398.50",  
    "builtUpExpectedRate": "7635.00",  
    "image": "cases/65e2e838f9222577acb6d792/  
indicator_1709715476894_Image.jpeg",  
    "squareMeter": "31.68",  
    "id": "511488"  
  },  
  {  
    "printlnReport": true,  
    "_id": "65e830b6f9222577acbca69c",  
    "property": "Residential Flat",  
    "area": "384",  
    "builtUpPercentage": "10",  
    "saleablePercentage": "0",  
    "rateType": "price_Indicator",  
    "areaType": "Carpet",
```

```
"source": "Index_no.2",
"expectedPrice": "3478000",
"expectedRate": "9057.29",
"builtUpExpectedRate": "8233.90",
"image": "cases/65e2e838f9222577acb6d792/
indicator_1709715508209_Image.png",
"squareMeter": "35.67",
"id": "576805"
},
{
"printlnReport": true,
"_id": "65e830b6f9222577acbca69d",
"property": "Residential Flat",
"area": "450",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"source": "Nobroker.com",
"expectedPrice": "3600000",
"expectedRate": "8000.00",
"builtUpExpectedRate": "7272.73",
"image": "cases/65e2e838f9222577acb6d792/
indicator_1709715526479_Image.png",
"squareMeter": "41.81",
"id": "192305"
}
],
"externalImages": [
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "65e59feaf9222577acb8e1d8",
"name": "externalImg_1709547495307_1709547660478_image_0.jpeg",
"path": "cases/65e2e838f9222577acb6d792/
externalImg_1709547495307_1709547660478_image_0.jpeg",
"orientation": "landscape"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "65e59feaf9222577acb8e1d9",
"name": "externalImg_1709547495949_1709547660478_image_1.jpeg",
"path": "cases/65e2e838f9222577acb6d792/
externalImg_1709547495949_1709547660478_image_1.jpeg",
"orientation": "landscape"
}
```



```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e59feaf9222577acb8e1da",
  "name": "externallmg_1709547496208_1709547660478_image_2.jpeg",
  "path": "cases/65e2e838f9222577acb6d792/
externallmg_1709547496208_1709547660478_image_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e59feaf9222577acb8e1db",
  "name": "externallmg_1709547496556_1709547660478_image_3.jpeg",
  "path": "cases/65e2e838f9222577acb6d792/
externallmg_1709547496556_1709547660478_image_3.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e59feaf9222577acb8e1dc",
  "name": "externallmg_1709547496852_1709547660478_image_4.jpeg",
  "path": "cases/65e2e838f9222577acb6d792/
externallmg_1709547496852_1709547660478_image_4.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e59feaf9222577acb8e1dd",
  "name": "externallmg_1709547497107_1709547660478_image_5.jpeg",
  "path": "cases/65e2e838f9222577acb6d792/
externallmg_1709547497107_1709547660478_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e59feaf9222577acb8e1de",
  "name": "externallmg_1709547497213_1709547660478_image_6.jpeg",
  "path": "cases/65e2e838f9222577acb6d792/
externallmg_1709547497213_1709547660478_image_6.jpeg",
  "orientation": "landscape"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e59feaf9222577acb8e1df",
  "name": "externalImg_1709547497368_1709547660478_image_7.jpeg",
  "path": "cases/65e2e838f9222577acb6d792/
externalImg_1709547497368_1709547660478_image_7.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "65e59fa8f9222577acb8df42",
  "name": "externalImg_1709547431748_1709547598838_image_0.jpeg",
  "path": "cases/65e2e838f9222577acb6d792/
externalImg_1709547431748_1709547598838_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "65e59fa8f9222577acb8df43",
  "name": "externalImg_1709547432146_1709547598838_image_1.jpeg",
  "path": "cases/65e2e838f9222577acb6d792/
externalImg_1709547432146_1709547598838_image_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "65e59fb8f9222577acb8dfef",
  "name": "externalImg_1709547446989_1709547612858_image_0.jpeg",
  "path": "cases/65e2e838f9222577acb6d792/
externalImg_1709547446989_1709547612858_image_0.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "AGR_PLAN.pdf",
    "filename": "1709715661323_AGR_PLAN.pdf",
    "path": "cases/65e2e838f9222577acb6d792/
processingDocuments/1709715661323_AGR_PLAN.pdf",
    "size": "32804",
    "createdAt": "Wed Mar 06 2024 14:31:01 GMT+0530 (India Standard Time)",
```

```
"uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "AGR.pdf",
  "filename": "1709715661327_AGR.pdf",
  "path": "cases/65e2e838f9222577acb6d792/processingDocuments/1709715661327_AGR.pdf",
  "size": "1485758",
  "createdAt": "Wed Mar 06 2024 14:31:01 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "Deepesh Ganesh Shetty - Jain Realty - 5th Jan 2024-...pdf",
  "filename":
"1709715661362_Deepesh_Ganesh_Shetty__Jain_Realty__5th_Jan_2024.pdf",
  "path": "cases/65e2e838f9222577acb6d792/processingDocuments/1709715661362_Deepesh_Ganesh_Shetty__Jain_Realty__5th_Jan_2024.pdf",
  "size": "809153",
  "createdAt": "Wed Mar 06 2024 14:31:01 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "externallmg_1709547431748_1709547598838_image_0.jpeg",
  "filename":
"1709715661374_externallmg_1709547431748_1709547598838_image_0.jpeg",
  "path": "cases/65e2e838f9222577acb6d792/processingDocuments/1709715661374_externallmg_1709547431748_1709547598838_image_0.jpeg",
  "size": "627564",
  "createdAt": "Wed Mar 06 2024 14:31:01 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "externallmg_1709547432146_1709547598838_image_1.jpeg",
  "filename":
"1709715661421_externallmg_1709547432146_1709547598838_image_1.jpeg",
  "path": "cases/65e2e838f9222577acb6d792/processingDocuments/1709715661421_externallmg_1709547432146_1709547598838_image_1.jpeg",
  "size": "234476",
  "createdAt": "Wed Mar 06 2024 14:31:01 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "externallmg_1709547446989_1709547612858_image_0.jpeg",
  "filename":
"1709715661476_externallmg_1709547446989_1709547612858_image_0.jpeg",
  "path": "cases/65e2e838f9222577acb6d792/processingDocuments/1709715661476
```

```
_externallmg_1709547446989_1709547612858_image_0.jpeg",
  "size": "859483",
  "createdAt": "Wed Mar 06 2024 14:31:01 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "IGR-01.pdf",
  "filename": "1709715661534_IGR01.pdf",
  "path": "cases/65e2e838f9222577acb6d792/
processingDocuments/1709715661534_IGR01.pdf",
  "size": "148329",
  "createdAt": "Wed Mar 06 2024 14:31:01 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "IGR-02.pdf",
  "filename": "1709715661539_IGR02.pdf",
  "path": "cases/65e2e838f9222577acb6d792/
processingDocuments/1709715661539_IGR02.pdf",
  "size": "150110",
  "createdAt": "Wed Mar 06 2024 14:31:01 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "IGR-03.pdf",
  "filename": "1709715661544_IGR03.pdf",
  "path": "cases/65e2e838f9222577acb6d792/
processingDocuments/1709715661544_IGR03.pdf",
  "size": "153147",
  "createdAt": "Wed Mar 06 2024 14:31:01 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "IGR-04.pdf",
  "filename": "1709715661548_IGR04.pdf",
  "path": "cases/65e2e838f9222577acb6d792/
processingDocuments/1709715661548_IGR04.pdf",
  "size": "156322",
  "createdAt": "Wed Mar 06 2024 14:31:01 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "RERA.pdf",
  "filename": "1709715667551_RERA.pdf",
  "path": "cases/65e2e838f9222577acb6d792/
processingDocuments/1709715667551_RERA.pdf",
```

```
"size": "43682",
"createdAt": "Wed Mar 06 2024 14:31:07 GMT+0530 (India Standard Time)",
"uploadedBy": "60eeaeddf3dd69653a581316"
},
{
"originalname": "Summary New=DEEPESH.xlsx",
"filename": "1709715667552_Summary_NewDEEPESH.xlsx",
"path": "cases/65e2e838f9222577acb6d792/
processingDocuments/1709715667552_Summary_NewDEEPESH.xlsx",
"size": "3744764",
"createdAt": "Wed Mar 06 2024 14:31:07 GMT+0530 (India Standard Time)",
"uploadedBy": "60eeaeddf3dd69653a581316"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
{
"createdBy": {
"_id": "60eeaeddf3dd69653a581316",
"role": "MAKER + RATE VERIFIER + CHEAKER",
"firstName": "Shyam",
"lastName": "Kajvilkar",
"profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Sh Yam_Photo.jpg"
},
"workType": "RATE_VERIFY",
"display": true,
"status": true,
"_id": "65e6e631f9222577acbaade4",
"note": "Pending for value confirmation",
"taskId": "65e2e85df9222577acb6d87c",
"createdAt": "2024-03-05T09:30:25.667Z"
}
],
"createdAt": "2024-03-02T08:50:00.913Z",
"updatedAt": "2024-03-06T12:03:02.702Z",
"__v": 0,
"updatedBy": "60eeaeddf3dd69653a581316",
"addressForMap": "",
"caseReferredBy": "6410199a140f140ffc59b58c",
"contactPersonName": "Mr. Prince Upadhyay",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": ""
```

```
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Sales Person",
"siteVisitContactNo": "7021486596",
"buildingServicesRate": "2500",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 484.00",
"flatRate": "8300",
"landOtherRate": "5800",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  },
  "roadFacing": false,
  "mall": false
},
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + 2 Toilet",
"carpetTotal": "0.00",
"otherCarpetTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "0.00",
"finalCarpetArea": "0.00",
"finalSalableArea": "0.00",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "Carpet Area in Sq. Ft. = 383.00\nFoyer Area in Sq. Ft. = 34.00\nO.P. Area in Sq. Ft. = 67.00",
"siteMeasurementRemark": "",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
```

```
"leaseTo": "",
"remainingLeasePeriod": 0,
"leaseDate": ""
},
"reportGeneratedDate": "Wed Mar 06 2024 16:12:13 GMT+0530 (India Standard
Time)",
"siteVisitDate": "2024-03-04"
}
```

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
Composition :			
Living Room	0'00"	0'00"	0.00
Bedroom	0'00"	0'00"	0.00
Kitchen	0'00"	0'00"	0.00
Toilet	0'00"	0'00"	0.00
Toilet	0'00"	0'00"	0.00
Other Composition :			