

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": true,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b80a"
    },
    "type": "CREDITOFFICER",
    "_id": "63d11f65be948726cc1419a7",
    "email": "kaushik.datta@sbi.co.in",
    "firstName": "KAUSHUIK",
    "mobileNo": "",
    "workMobileNo": "9757023640",
    "lastName": " DATTA"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "8500000",
    "discussWithPerson": "KAUSHUIK",
    "expectedFees": 4250,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b80a",
  "branchCode": "000088",
  "type": "BRANCH",
  "name": "RACPC- Chinchpokli ",
  "email": "sbi.17889@sbi.co.in",
  "mobileNo": "022-23707514",
  "alternateMobileNo": "",
  "address": "Retail Assets Centralised Processing Centre, Mumbai South Voltas
House, 'A', 1st Floor, Dr. Ambedkar Road, Chinchpokli (East), Mumbai - 400 033, State
- Maharashtra, Country - India.\r\n",
  "ledgerName": "STATE BANK OF INDIA - CHINCHPOKALI",
  "fax": "022-23707512 / 13",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "62727444afd7d55eddee092c",
  "role": "PICKUPPERSON",
  "firstName": "Shantilal",
  "email": "shantilal@vastukala.org",
  "lastName": "Patel",
  "mobileNo": "9969039853",
  "shortName": "SHP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62727444afd7d55eddee092c/
profilePhoto_1668057663775_WhatsApp_Image_20221110_at_104853_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "642bad2b91d7c62df117fef2",
  "role": "SITEENGINEER",
  "firstName": "Abhiraj",
  "email": "abhishekharijan@gmail.com",
  "lastName": "Bhagat",
  "mobileNo": "8369839430",
  "designation": "",
  "shortName": "AH",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60f91b6f344e052188ffd1fc",
  "role": "MAKER",
  "firstName": "Jayaraja",
  "email": "jayaraja@vastukala.org",
  "lastName": "Acharya",
```

```
"mobileNo": "9867664219",
"designation": "",
"shortName": "JA",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91b6f344e052188ffd1fc/
profilePhoto_1678780588416_Profile_Photo.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  "type": "EMPLOYEE",
  "_id": "5ffe92d27737ca4d986b6453",
  "role": "VALUER",
  "firstName": "Manoj",
  "email": "manoj@vastukala.org",
  "lastName": "Chalikwar",
  "mobileNo": "9819597579",
  "designation": "Registered Valuer",
  "registrationNo": [
    {
      "title": {
        "label": "IBBI"
      },
      "_id": "60af80072ffdf65bcd658651",
      "number": "IBBI/RV/07/2018/10366"
    }
  ],
  {
```

```
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "18.51295710443916",
  "longitude": "73.94531432980217"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.94531432980217,
    18.51295710443916
  ]
}
```

```
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "4/03/2024 01:39 pm"
    },
    {
      "dateTime": "4/03/2024 12:00 am"
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-03-05",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "3BHK",
  "label": "3 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  }
}
```

```
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Hadapsar",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "2",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "B3",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Pune",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
```

```
"key": "taluka",
"value": "Haveli",
"label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Leisure Town Phase I",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Near Amnora Town Fire Station",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Sadesataranali",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
```



```
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "202/A, 202/B/1/1 to 7, 202/B/2, 202/B/3, 202/B/4",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
```

```
"value": "",
"label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "B3/203",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
```

```
"status": false,
"name": "Gut No.",
"key": "GUTNo",
"value": "",
"label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 411 028",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "R.C.C._slab",
    "label": "R.C.C. slab"
  },
  "flooring": {
    "value": "Vitrified_tiles_flooring",
    "label": "Vitrified tiles flooring"
  },
  "doors": {
    "value": "Teak_wood_door_frame_with_flush_shutters",
    "label": "Teak wood door frame with flush shutters"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows",
    "label": "Powder coated Aluminum sliding windows"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering_+_POP_Finish",
    "label": "Cement Plastering + POP Finish"
  }
}
```

```
}
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "Pune_Municipal_Corporation",
    "label": "Pune Municipal Corporation"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Open Land",
    "west": "Open Plot / Road",
    "south": "Open Land",
    "east": "Internal Road"
  },
  "asPerDocumentAgreement": {
    "north": "Information not available",
    "west": "Information not available",
    "south": "Information not available",
    "east": "Information not available"
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "",
      "west": "",
      "south": "",
      "east": ""
    },
    "asPerDocument": {
      "north": "",
      "west": "",
      "south": "",
```

```
    "east": ""
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "+ Dry Balcony Area + Balcony Aera + Attached Terrace Area",
"dateOfIssusApprovePlan": "As Occupancy Certificate is received it may be assumed that the construction is as per Sanctioned Plan.",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "No",
"unauthorizedConstruction": ""
},
"compositeRate": {
  "remark": "As per Site Inspection, Actual Carpet area 815.48 Sq. Ft. (Including Enclosed Balcony + Dry Balcony + Attached Terrace Area) is more than Carpet area 739.00 Sq. Ft. mentioned in the Memorandum of Understanding provided to us. We have considered area mentioned in the Memorandum of Understanding / Index II.",
  "depreciationPercentage": "",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "depreciatedCostOfConstruction": "",
  "depreciatedBuildingRate": ""
},
"igrRate": {
  "propertyName": "Residential",
  "rate": "63550",
  "landRate": "17040",
  "igrImage": "cases/65e35154f9222577acb79c43/igr_1709798762602_Image.png",
  "squareMeterGuideLineRate": "57195.00",
  "squareFeetGuideLineRate": "5314.00"
},
"igrFinalRate": {
  "floorRatePercentage": "90",
  "depreciationPercentage": "0",
  "rate": "63550.00",
  "squareMeterGuideLineRate": "57195.00",
  "squareFeetGuideLineRate": "5314.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  }
},
"propertyTypeOfUseList": {
  "value": "Residential_Purpose",
```

```
"label": "Residential Purpose"
},
"propertyOccupiedByList": {
  "value": "Vacant",
  "label": "Vacant"
},
"monthlyRent": "19,000/- Expected rental income per month",
"assessmentNo": "Property ID : O/K/81/04524364, Bill No. 85272, dated 09.02.2024",
"taxPaidHolderName": "Bill in the name of Rhythm Anjankumar Kothari & Mrs.
Kanan Rhythm Kothari",
"taxAmount": "14059/-",
"electricityServiceConnectionNo": "Information not available",
"meterCardHolderName": "Information not available",
"undividedAreaOfLandAsPerSaleDeed": "Information not available",
"floorSpaceIndex": "As per PMC norms",
"tenantName": "",
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  }
},
"anyFavouringForExtraPotentialValue": "Located in developed area",
"negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "R.C.C._slab",
    "label": "R.C.C. slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  }
},
"waterTank": {
  "value": "MunicipalWaterSupply",
  "label": "Municipal Water Supply"
},
"pavementLaid": {
  "value": "Yes",
  "label": "Yes"
},
"carParking": "Covered Car Parking Space",
"constructionWorkStatus": {
  "value": "Completed",
```

```
"label": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2021",
  "fullDate": "1/1/2021"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Designed_as_per_I.S._codes",
  "label": "Designed as per I.S. codes"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
```

```
"label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenancelssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "0",
  "label": "No"
},
"provisionOfFirefighting": {
  "value": "0",
  "label": "No"
},
"groundStilt": {
  "value": "stilt",
  "label": "Stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "57",
"ageOfBuilding": "3",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "11",
```



```
"flatFloorNo": "2",
"noOfLifts": "3",
"noOfDwellingUnitsInBuilding": "8"
},
"finalPlinthArea": {
  "area": "812.90",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/65e35154f9222577acb79c43/
routeMap_1709816442572_Image.png",
    "routeLat": "18.513757",
    "routeLng": "73.945613",
    "stationName": "Pune",
    "routeDistance": "3.9 km"
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "jwd8z7",
      "name": "jwd8z7",
      "image": "cases/65e35154f9222577acb79c43/
routeMap_1709816143754_Image.png"
    }
  ]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
```

```
"wardrobesQty": "0",
"showcasesQty": "0",
"showcasesRate": "0",
"totalshowcasesRate": "0",
"kitchenArrangementsQty": "0",
"kitchenArrangementsRate": "0",
"totalkitchenArrangementsRate": "0",
"superfineFinishQty": "0",
"superfineFinishRate": "0",
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "7463900.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "7463900.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  }
},
```

```
"rccPlinth": {
  "label": "RCC Plinth",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
```

```
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "4623775.00",
"selectedBuildUpValue": "812.90",
"selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
"frontPageImages": [
{
"status": false,
"_id": "65e95d37f9222577acbe1c78",
"name":
"externalImg_1709792566973_WhatsApp_Image_20240307_at_114152.jpeg",
"path": "cases/65e35154f9222577acb79c43/
externalImg_1709792566973_WhatsApp_Image_20240307_at_114152.jpeg",
"orientation": "landscape"
}
],
"selfieWithSiteVisitImages": [
{
"status": false,
"_id": "65e95d37f9222577acbe1c7f",
"name":
"externalImg_1709792567011_WhatsApp_Image_20240307_at_114155.jpeg",
"path": "cases/65e35154f9222577acb79c43/
externalImg_1709792567011_WhatsApp_Image_20240307_at_114155.jpeg",
```

```
    "orientation": "landscape"
  }
],
"externalPhotos": [
  {
    "status": false,
    "_id": "65e95d37f9222577acbe1c79",
    "name":
"externallmg_1709792566980_WhatsApp_Image_20240307_at_114153_1.jpeg",
    "path": "cases/65e35154f9222577acb79c43/
externallmg_1709792566980_WhatsApp_Image_20240307_at_114153_1.jpeg",
    "orientation": "landscape"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
    "_id": "65e95d22f9222577acbe1baa",
    "name": "Living Room",
    "path": "cases/65e35154f9222577acb79c43/
externallmg_1709792546243_WhatsApp_Image_20240307_at_114145_1.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "65e95d22f9222577acbe1ba8",
    "name": "Living Room",
    "path": "cases/65e35154f9222577acb79c43/
externallmg_1709792546222_WhatsApp_Image_20240307_at_114144_2.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "65e95d22f9222577acbe1bab",
    "name": "Living Room",
    "path": "cases/65e35154f9222577acb79c43/
externallmg_1709792546249_WhatsApp_Image_20240307_at_114145.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "65e95d22f9222577acbe1baf",
    "name": "Living Room",
    "path": "cases/65e35154f9222577acb79c43/
externallmg_1709792546262_WhatsApp_Image_20240307_at_114147_2.jpeg",
```

```
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "65e95d37f9222577acbe1c80",
    "name": "Living Room",
    "path": "cases/65e35154f9222577acb79c43/
externallmg_1709792567018_WhatsApp_Image_20240307_at_114136.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "65e95d37f9222577acbe1c81",
    "name": "Living Room",
    "path": "cases/65e35154f9222577acb79c43/
externallmg_1709792567020_WhatsApp_Image_20240307_at_114137_1.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "65e95d37f9222577acbe1c84",
    "name": "Living Room",
    "path": "cases/65e35154f9222577acb79c43/
externallmg_1709792567030_WhatsApp_Image_20240307_at_114138.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "65e95d37f9222577acbe1c89",
    "name": "Living Room",
    "path": "cases/65e35154f9222577acb79c43/
externallmg_1709792567047_WhatsApp_Image_20240307_at_114143.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "65e95d37f9222577acbe1c88",
    "name": "Living Room",
    "path": "cases/65e35154f9222577acb79c43/
externallmg_1709792567044_WhatsApp_Image_20240307_at_114143_1.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "65e95d22f9222577acbe1bb5",
    "name": "Living Room",
```

```
    "path": "cases/65e35154f9222577acb79c43/
externallmg_1709792546291_WhatsApp_Image_20240307_at_114151.jpeg",
    "orientation": "landscape"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "10108",
    "max": "10959"
  },
  "builtUpRateRange": {
    "min": "9189",
    "max": "9963"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```



```
"status": true,
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "739.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3",
  "SME/TCC/221/13"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"invoices": [],
"paymentIds": [],
"_id": "65e35154f9222577acb79c43",
```

```
"ownerName": "Mr. Rhythm Anjankumar Kothari",
"ownerPhoneNo": "9850387794",
"appAddress": "Rhythm Anjana Kumar Kothari\n202 flat no B/3\nLeisure Town
\nsadesatranli \nHadapsar\nPune 411026",
"remark": "Loan 50 Lakhs ",
"documents": [
  {
    "documentType": {
      "value": "60ae124aaa6d152c1801b2f9",
      "label": "Memorandum of Understanding"
    },
    "inputs": {
      "documentDate": "23/02/2024",
      "remark": "(Noted And registered at Serial Number 536/2024 dated 23.02.2024)",
      "from": {
        "value": "Seller",
        "label": "Seller"
      },
      "Seller": "Mr. Rhythm Anjankumar Kothari & Mrs. Kanan Rhythm Kothari",
      "to": {
        "value": "Purchaser",
        "label": "Purchaser"
      },
      "Purchaser": "Ms. Vidya Gourishankar Upadhye"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "727530",
    "path": "cases/65e35154f9222577acb79c43/
document_1709798497739_SKMBT_C36024022305230_1.pdf",
    "fileName": "document_1709798497739_SKMBT_C36024022305230_1.pdf"
  },
  {
    "documentType": {
      "value": "60ae124baa6d152c1801b2fd",
      "label": "Occupancy Certificate"
    },
    "inputs": {
      "documentDate": "17/03/2021",
      "nameOfApprovingAuthority": {
        "value": "Pune_Municipal_Corporation",
        "label": "Pune Municipal Corporation"
      },
      "remark": "(Downloaded from RERA)",
      "number": {
        "value": "No",
```

```
    "label": "No"
  },
  "No": "OCC/09085/20"
},
"isHardCopy": false,
"displayStatus": true,
"id": "682405",
"path": "cases/65e35154f9222577acb79c43/document_1709873025622_2_Occupa
ncy_Certificate__Completion_Certificate__Architects_certificate_of_completion_for_plotted_development.pdf",
"fileName": "document_1709873025622_2_Occupancy_Certificate__Completion_C
ertificate__Architects_certificate_of_completion_for_plotted_development.pdf"
},
{
  "documentType": {
    "value": "65ea9becf9222577acbf285",
    "label": "NA Order Cum Commencement Certificate"
  },
  "inputs": {
    "documentDate": "15/11/2014",
    "nameOfApprovingAuthority": {
      "value": "Collector's Office, Pune (Revenue Branch)",
      "label": "Collector's Office, Pune (Revenue Branch)"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "PMH / NA / SR / 818 / 14"
},
"isHardCopy": false,
"displayStatus": true,
"id": "732279",
"path": "cases/65e35154f9222577acb79c43/document_1709873644776_1_Comme
ncement_Certificates__NA_Order_for_plotted_development.pdf",
"fileName": "document_1709873644776_1_Commencement_Certificates__NA_Or
der_for_plotted_development.pdf"
},
{
  "documentType": {
    "value": "60ae1246aa6d152c1801b2e4",
    "label": "Index- II"
  },
  "inputs": {
    "documentDate": "25/06/2020",
    "from": {
```

```
    "value": "Promoter",
    "label": "Promoter"
  },
  "Promoter": "M/s. Sai Proviso Homes (Erstshile Wellwisher Homes)",
  "to": {
    "value": "Purchasers",
    "label": "Purchasers"
  },
  "Purchasers": "Rhythm Anjankumar Kothari & Kanan Ghythm Kothari",
  "number": {
    "value": "Registration_No",
    "label": "Registration No"
  },
  "Registration_No": "3690/2020"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1709875877928_Index_II.pdf",
"path": "cases/65e35154f9222577acb79c43/
document_1709875877928_Index_II.pdf",
"id": "158153",
"uploadedBy": "60f91b6f344e052188ffd1fc",
"createdAt": "Fri Mar 08 2024 11:01:18 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae126aaa6d152c1801b38b",
    "label": "Property Tax Bill"
  },
  "inputs": {
    "documentDate": "09/02/2024",
    "nameOfApprovingAuthority": {
      "value": "Pune_Municipal_Corporation",
      "label": "Pune Municipal Corporation"
    },
    "to": {
      "value": "Seller",
      "label": "Seller"
    },
    "Seller": "Rhythm Anjankumar Kothari & Mrs. Kanan Rhythm Kothari",
    "number": {
      "value": "Property_No",
      "label": "Property No"
    },
    "Property_No": "O/K/81/04524364"
  },
}
```

```
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1709876789852_Tax_Bioll.pdf",
"path": "cases/65e35154f9222577acb79c43/
document_1709876789852_Tax_Bioll.pdf",
"id": "373019",
"uploadedBy": "60f91b6f344e052188ffd1fc",
"createdAt": "Fri Mar 08 2024 11:16:29 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
    "label": "RERA Certificate"
  },
  "inputs": {
    "documentDate": "09/09/2021",
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "P52100002395"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1709883513815_P52100002395.pdf",
  "path": "cases/65e35154f9222577acb79c43/
document_1709883513815_P52100002395.pdf",
  "id": "243725",
  "uploadedBy": "60f915d3f3dd69653a592199",
  "createdAt": "Fri Mar 08 2024 13:08:33 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "007405",
"createdBy": "62727444afd7d55eddee092c",
"caseHistory": [
  {
    "id": "766338",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Sat Mar 02 2024 21:48:28 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Rhythm Anjankumar Kothari",
    "phone": "9850387794",
```

```
"ownershipShare": "",
"email": "",
"id": "174927"
},
{
  "name": "Mrs. Kanan Rhythm Kothari",
  "phone": "",
  "email": "",
  "ownershipShare": "",
  "id": "217586"
}
],
"proposePurchasers": [
  {
    "name": "Ms. Vidya Gourishankar Upadhye",
    "phone": "",
    "email": "",
    "ownershipShare": ""
  }
],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "986199",
    "name": "Passage",
    "length": "4.33",
    "length1": "4",
    "length2": "4",
    "width": "3.75",
    "width1": "3",
    "width2": "9",
    "totalArea": "16.25",
    "images": [],
    "extraAreas": [],
    "finalArea": "16.25"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "1",
```

```
"name": "Living Room",
"length": "16.42",
"length1": "16",
"length2": "5",
"width": "10.33",
"width1": "10",
"width2": "4",
"totalArea": "169.64",
"images": [],
"extraAreas": [],
"finalArea": "169.64"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "8",
  "name": "Kitchen",
  "length": "7.92",
  "length1": "7",
  "length2": "11",
  "width": "7.92",
  "width1": "7",
  "width2": "11",
  "totalArea": "62.67",
  "images": [],
  "finalArea": "62.67",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Passage",
  "length": "8.83",
  "length1": "8",
  "length2": "10",
  "width": "3.42",
  "width1": "3",
  "width2": "5",
  "totalArea": "30.18",
  "images": [],
  "extraAreas": [],
```



```
"finalArea": "30.18"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Bedroom",
  "length": "6.83",
  "length1": "6",
  "length2": "10",
  "width": "3.92",
  "width1": "3",
  "width2": "11",
  "totalArea": "26.76",
  "images": [],
  "extraAreas": [],
  "finalArea": "26.76"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Bedroom",
  "length": "10.83",
  "length1": "10",
  "length2": "10",
  "width": "9.08",
  "width1": "9",
  "width2": "1",
  "totalArea": "98.40",
  "images": [],
  "extraAreas": [],
  "finalArea": "98.40"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Bedroom",
  "length": "10.92",
```

```
"length1": "10",
"length2": "11",
"width": "10.42",
"width1": "10",
"width2": "5",
"totalArea": "113.71",
"images": [],
"extraAreas": [],
"finalArea": "113.71"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Toilet",
  "length": "7.92",
  "length1": "7",
  "length2": "11",
  "width": "4.75",
  "width1": "4",
  "width2": "9",
  "totalArea": "37.60",
  "images": [],
  "extraAreas": [],
  "finalArea": "37.60"
}
],
"otherComposition": [
  {
    "toBeAdded": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "name": {
      "label": "Dry Balcony Area",
      "value": "Dry_Balcony_Area"
    },
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "0",
    "length": "7.83",
    "length1": "7",
```

```
"length2": "10",
"width": "3.25",
"width1": "3",
"width2": "3",
"totalArea": "25.46",
"images": [],
"extraAreas": [],
"finalArea": "25.46",
"percentageBeforeTotal": "25.46",
"percentage": "100"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Balcony Area",
    "value": "Balcony_Area"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "length": "1.83",
  "length1": "1",
  "length2": "10",
  "width": "4.33",
  "width1": "4",
  "width2": "4",
  "totalArea": "7.94",
  "images": [],
  "extraAreas": [],
  "finalArea": "7.94",
  "percentageBeforeTotal": "7.94",
  "percentage": "100"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Terrace Area",
    "value": "Terrace_Area"
  }
}
```

```
    },
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "2",
    "length": "24.75",
    "length1": "24",
    "length2": "9",
    "width": "9.17",
    "width1": "9",
    "width2": "2",
    "totalArea": "226.87",
    "images": [],
    "extraAreas": [],
    "finalArea": "226.87",
    "percentageBeforeTotal": "226.87",
    "percentage": "100"
  }
],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60ae124aaa6d152c1801b2f9",
      "label": "Memorandum of Understanding"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "selectAreaTypeDocument": "Carpet",
    "squareMeterArea": "68.66",
    "totalAreaDocument": "739",
    "docBultupPercentage": "10",
    "docFinalBultUp": "812.90",
    "docFinalBultUpSquareMeter": "75.52",
    "docSaleablePercentage": "",
    "docFinalSaleable": "0.00",
    "docFinalSaleableSquareMeter": "0.00",
    "id": "767381"
  }
],
"images": [],
"indicatorArr": [
  {
```

```
"printlnReport": true,
  "_id": "65e975c7f9222577acbe601b",
  "property": "Sai Proviso Leisure Town, Pune",
  "area": "742",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "8",
  "source": "magic_bricks",
  "expectedPrice": "7500000",
  "expectedRate": "10107.82",
  "builtUpExpectedRate": "9188.92",
  "image": "cases/65e35154f9222577acb79c43/
indicator_1709798597781_Image.png",
  "squareMeter": "68.93",
  "id": "583432"
},
{
  "printlnReport": true,
  "_id": "65e975c7f9222577acbe601c",
  "property": "Sai Proviso Leisure Town, Pune",
  "area": "800",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "3",
  "source": "https://www.99acres.com/",
  "expectedPrice": "8600000",
  "expectedRate": "10750.00",
  "builtUpExpectedRate": "9772.73",
  "image": "cases/65e35154f9222577acb79c43/
indicator_1709798632625_Image.png",
  "squareMeter": "74.32",
  "id": "474922"
},
{
  "printlnReport": true,
  "_id": "65e975c7f9222577acbe601d",
  "property": "Sai Proviso Leisure Town, Pune",
  "area": "736",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
```

```
"floor": "6",
"source": "Index_no.2",
"expectedPrice": "7453700",
"expectedRate": "10127.31",
"builtUpExpectedRate": "9206.65",
"image": "cases/65e35154f9222577acb79c43/
indicator_1709798727917_Image.png",
"squareMeter": "68.38",
"id": "106090"
},
{
  "printlnReport": true,
  "_id": "65e975c7f9222577acbe601e",
  "property": "Sai Proviso Leisure Town, Pune",
  "area": "730",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "4",
  "source": "magic_bricks",
  "expectedPrice": "8000000",
  "expectedRate": "10958.90",
  "builtUpExpectedRate": "9962.64",
  "image": "cases/65e35154f9222577acb79c43/
indicator_1709798799194_Image.png",
  "squareMeter": "67.82",
  "id": "272120"
}
],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65e95d22f9222577acbe1ba7",
    "name":
"externallmg_1709792546216_WhatsApp_Image_20240307_at_114144_1.jpeg",
    "path": "cases/65e35154f9222577acb79c43/
externallmg_1709792546216_WhatsApp_Image_20240307_at_114144_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65e95d22f9222577acbe1ba8",
    "name":
"externallmg_1709792546222_WhatsApp_Image_20240307_at_114144_2.jpeg",
```

```
    "path": "cases/65e35154f9222577acb79c43/
externallmg_1709792546222_WhatsApp_Image_20240307_at_114144_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65e95d22f9222577acbe1ba9",
    "name":
"externallmg_1709792546233_WhatsApp_Image_20240307_at_114144.jpeg",
    "path": "cases/65e35154f9222577acb79c43/
externallmg_1709792546233_WhatsApp_Image_20240307_at_114144.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65e95d22f9222577acbe1baa",
    "name":
"externallmg_1709792546243_WhatsApp_Image_20240307_at_114145_1.jpeg",
    "path": "cases/65e35154f9222577acb79c43/
externallmg_1709792546243_WhatsApp_Image_20240307_at_114145_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65e95d22f9222577acbe1bab",
    "name":
"externallmg_1709792546249_WhatsApp_Image_20240307_at_114145.jpeg",
    "path": "cases/65e35154f9222577acb79c43/
externallmg_1709792546249_WhatsApp_Image_20240307_at_114145.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65e95d22f9222577acbe1bac",
    "name":
"externallmg_1709792546253_WhatsApp_Image_20240307_at_114146_1.jpeg",
    "path": "cases/65e35154f9222577acb79c43/
externallmg_1709792546253_WhatsApp_Image_20240307_at_114146_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "65e95d22f9222577acbe1bad",
  "name":
"externallmg_1709792546257_WhatsApp_Image_20240307_at_114146.jpeg",
  "path": "cases/65e35154f9222577acb79c43/
externallmg_1709792546257_WhatsApp_Image_20240307_at_114146.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e95d22f9222577acbe1bae",
  "name":
"externallmg_1709792546261_WhatsApp_Image_20240307_at_114147_1.jpeg",
  "path": "cases/65e35154f9222577acb79c43/
externallmg_1709792546261_WhatsApp_Image_20240307_at_114147_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e95d22f9222577acbe1baf",
  "name":
"externallmg_1709792546262_WhatsApp_Image_20240307_at_114147_2.jpeg",
  "path": "cases/65e35154f9222577acb79c43/
externallmg_1709792546262_WhatsApp_Image_20240307_at_114147_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e95d22f9222577acbe1bb0",
  "name":
"externallmg_1709792546265_WhatsApp_Image_20240307_at_114147.jpeg",
  "path": "cases/65e35154f9222577acb79c43/
externallmg_1709792546265_WhatsApp_Image_20240307_at_114147.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e95d22f9222577acbe1bb1",
  "name":
"externallmg_1709792546270_WhatsApp_Image_20240307_at_114148.jpeg",
  "path": "cases/65e35154f9222577acb79c43/
externallmg_1709792546270_WhatsApp_Image_20240307_at_114148.jpeg",
```



```
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65e95d22f9222577acbe1bb2",
    "name":
"externallmg_1709792546277_WhatsApp_Image_20240307_at_114149.jpeg",
    "path": "cases/65e35154f9222577acb79c43/
externallmg_1709792546277_WhatsApp_Image_20240307_at_114149.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65e95d22f9222577acbe1bb3",
    "name":
"externallmg_1709792546281_WhatsApp_Image_20240307_at_114151_1.jpeg",
    "path": "cases/65e35154f9222577acb79c43/
externallmg_1709792546281_WhatsApp_Image_20240307_at_114151_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65e95d22f9222577acbe1bb4",
    "name":
"externallmg_1709792546286_WhatsApp_Image_20240307_at_114151_2.jpeg",
    "path": "cases/65e35154f9222577acb79c43/
externallmg_1709792546286_WhatsApp_Image_20240307_at_114151_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65e95d22f9222577acbe1bb5",
    "name":
"externallmg_1709792546291_WhatsApp_Image_20240307_at_114151.jpeg",
    "path": "cases/65e35154f9222577acb79c43/
externallmg_1709792546291_WhatsApp_Image_20240307_at_114151.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65e95d37f9222577acbe1c77",
```

```
"name":
"externalimg_1709792566962_WhatsApp_Image_20240307_at_114152_1.jpeg",
  "path": "cases/65e35154f9222577acb79c43/
externalimg_1709792566962_WhatsApp_Image_20240307_at_114152_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e95d37f9222577acbe1c78",
  "name":
"externalimg_1709792566973_WhatsApp_Image_20240307_at_114152.jpeg",
  "path": "cases/65e35154f9222577acb79c43/
externalimg_1709792566973_WhatsApp_Image_20240307_at_114152.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e95d37f9222577acbe1c79",
  "name":
"externalimg_1709792566980_WhatsApp_Image_20240307_at_114153_1.jpeg",
  "path": "cases/65e35154f9222577acb79c43/
externalimg_1709792566980_WhatsApp_Image_20240307_at_114153_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e95d37f9222577acbe1c7a",
  "name":
"externalimg_1709792566986_WhatsApp_Image_20240307_at_114153_2.jpeg",
  "path": "cases/65e35154f9222577acb79c43/
externalimg_1709792566986_WhatsApp_Image_20240307_at_114153_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e95d37f9222577acbe1c7b",
  "name":
"externalimg_1709792566991_WhatsApp_Image_20240307_at_114153.jpeg",
  "path": "cases/65e35154f9222577acb79c43/
externalimg_1709792566991_WhatsApp_Image_20240307_at_114153.jpeg",
  "orientation": "landscape"
},
},
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e95d37f9222577acbe1c7c",
  "name":
"externallmg_1709792566998_WhatsApp_Image_20240307_at_114154_1.jpeg",
  "path": "cases/65e35154f9222577acb79c43/
externallmg_1709792566998_WhatsApp_Image_20240307_at_114154_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e95d37f9222577acbe1c7d",
  "name":
"externallmg_1709792567001_WhatsApp_Image_20240307_at_114154.jpeg",
  "path": "cases/65e35154f9222577acb79c43/
externallmg_1709792567001_WhatsApp_Image_20240307_at_114154.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e95d37f9222577acbe1c7e",
  "name":
"externallmg_1709792567005_WhatsApp_Image_20240307_at_114155_1.jpeg",
  "path": "cases/65e35154f9222577acb79c43/
externallmg_1709792567005_WhatsApp_Image_20240307_at_114155_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e95d37f9222577acbe1c7f",
  "name":
"externallmg_1709792567011_WhatsApp_Image_20240307_at_114155.jpeg",
  "path": "cases/65e35154f9222577acb79c43/
externallmg_1709792567011_WhatsApp_Image_20240307_at_114155.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e95d37f9222577acbe1c80",
  "name":
"externallmg_1709792567018_WhatsApp_Image_20240307_at_114136.jpeg",
```

```
    "path": "cases/65e35154f9222577acb79c43/
externallmg_1709792567018_WhatsApp_Image_20240307_at_114136.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65e95d37f9222577acbe1c81",
    "name":
"externallmg_1709792567020_WhatsApp_Image_20240307_at_114137_1.jpeg",
    "path": "cases/65e35154f9222577acb79c43/
externallmg_1709792567020_WhatsApp_Image_20240307_at_114137_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65e95d37f9222577acbe1c82",
    "name":
"externallmg_1709792567024_WhatsApp_Image_20240307_at_114137.jpeg",
    "path": "cases/65e35154f9222577acb79c43/
externallmg_1709792567024_WhatsApp_Image_20240307_at_114137.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65e95d37f9222577acbe1c83",
    "name":
"externallmg_1709792567026_WhatsApp_Image_20240307_at_114138_1.jpeg",
    "path": "cases/65e35154f9222577acb79c43/
externallmg_1709792567026_WhatsApp_Image_20240307_at_114138_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65e95d37f9222577acbe1c84",
    "name":
"externallmg_1709792567030_WhatsApp_Image_20240307_at_114138.jpeg",
    "path": "cases/65e35154f9222577acb79c43/
externallmg_1709792567030_WhatsApp_Image_20240307_at_114138.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "65e95d37f9222577acbe1c85",
  "name":
"externallmg_1709792567031_WhatsApp_Image_20240307_at_114141.jpeg",
  "path": "cases/65e35154f9222577acb79c43/
externallmg_1709792567031_WhatsApp_Image_20240307_at_114141.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e95d37f9222577acbe1c86",
  "name":
"externallmg_1709792567037_WhatsApp_Image_20240307_at_114142_1.jpeg",
  "path": "cases/65e35154f9222577acb79c43/
externallmg_1709792567037_WhatsApp_Image_20240307_at_114142_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e95d37f9222577acbe1c87",
  "name":
"externallmg_1709792567040_WhatsApp_Image_20240307_at_114142.jpeg",
  "path": "cases/65e35154f9222577acb79c43/
externallmg_1709792567040_WhatsApp_Image_20240307_at_114142.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e95d37f9222577acbe1c88",
  "name":
"externallmg_1709792567044_WhatsApp_Image_20240307_at_114143_1.jpeg",
  "path": "cases/65e35154f9222577acb79c43/
externallmg_1709792567044_WhatsApp_Image_20240307_at_114143_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e95d37f9222577acbe1c89",
  "name":
"externallmg_1709792567047_WhatsApp_Image_20240307_at_114143.jpeg",
  "path": "cases/65e35154f9222577acb79c43/
externallmg_1709792567047_WhatsApp_Image_20240307_at_114143.jpeg",
```

```
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "Calculation.xlsx",
    "filename": "1709798867895_Calculation.xlsx",
    "path": "cases/65e35154f9222577acb79c43/processingDocuments/1709798867895_Calculation.xlsx",
    "size": "2134504",
    "createdAt": "Thu Mar 07 2024 13:37:48 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f915d3f3dd69653a592199"
  },
  {
    "originalname": "1 Commencement Certificates _ NA Order for plotted development.pdf",
    "filename": "1709876947791_1_Commencement_Certificates__NA_Order_for_plotted_development.pdf",
    "path": "cases/65e35154f9222577acb79c43/processingDocuments/1709876947791_1_Commencement_Certificates__NA_Order_for_plotted_development.pdf",
    "size": "826048",
    "createdAt": "Fri Mar 08 2024 11:19:08 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
  {
    "originalname": "1 Declaration about Commencement Certificate.pdf",
    "filename": "1709876947808_1_Declaration_about_Commencement_Certificate.pdf",
    "path": "cases/65e35154f9222577acb79c43/processingDocuments/1709876947808_1_Declaration_about_Commencement_Certificate.pdf",
    "size": "332827",
    "createdAt": "Fri Mar 08 2024 11:19:08 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
  {
    "originalname": "2 Occupancy Certificate_ Completion Certificate_ Architect's certificate of completion for plotted development.pdf",
    "filename": "1709876947816_2_Occupancy_Certificate__Completion_Certificate__Architects_certificate_of_completion_for_plotted_development.pdf",
    "path": "cases/65e35154f9222577acb79c43/processingDocuments/1709876947816_2_Occupancy_Certificate__Completion_Certificate__Architects_certificate_of_completion_for_plotted_development.pdf",
    "size": "284325",
    "createdAt": "Fri Mar 08 2024 11:19:08 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  }
]
```

```
    },
    {
      "originalname": "Documents.pdf",
      "filename": "1709876947822_Documents.pdf",
      "path": "cases/65e35154f9222577acb79c43/processingDocuments/1709876947822_Documents.pdf",
      "size": "5620923",
      "createdAt": "Fri Mar 08 2024 11:19:08 GMT+0530 (India Standard Time)",
      "uploadedBy": "60f91b6f344e052188ffd1fc"
    },
    {
      "originalname": "Draft Agreement.pdf",
      "filename": "1709876947912_Draft_Agreement.pdf",
      "path": "cases/65e35154f9222577acb79c43/processingDocuments/1709876947912_Draft_Agreement.pdf",
      "size": "9028723",
      "createdAt": "Fri Mar 08 2024 11:19:08 GMT+0530 (India Standard Time)",
      "uploadedBy": "60f91b6f344e052188ffd1fc"
    },
    {
      "originalname": "Index II.pdf",
      "filename": "1709876948097_Index_II.pdf",
      "path": "cases/65e35154f9222577acb79c43/processingDocuments/1709876948097_Index_II.pdf",
      "size": "328770",
      "createdAt": "Fri Mar 08 2024 11:19:08 GMT+0530 (India Standard Time)",
      "uploadedBy": "60f91b6f344e052188ffd1fc"
    },
    {
      "originalname": "MOU.pdf",
      "filename": "1709876948104_MOU.pdf",
      "path": "cases/65e35154f9222577acb79c43/processingDocuments/1709876948104_MOU.pdf",
      "size": "7306312",
      "createdAt": "Fri Mar 08 2024 11:19:08 GMT+0530 (India Standard Time)",
      "uploadedBy": "60f91b6f344e052188ffd1fc"
    },
    {
      "originalname": "MR.RHYTHM ANJANKUMAR KOTHARI KANAN RHYTHM KOTHARI.xlsx",
      "filename": "1709876948193_MRRHYTHM_ANJANKUMAR_KOTHARI_KANAN_RHYTHM_KOTHARI.xlsx",
      "path": "cases/65e35154f9222577acb79c43/processingDocuments/1709876948193_MRRHYTHM_ANJANKUMAR_KOTHARI_KANAN_RHYTHM_KOTHARI.xlsx",
      "size": "26564",
      "createdAt": "Fri Mar 08 2024 11:19:08 GMT+0530 (India Standard Time)",
```

```
"uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
  "originalname": "Tax Bioll.pdf",
  "filename": "1709876948194_Tax_Bioll.pdf",
  "path": "cases/65e35154f9222577acb79c43/
processingDocuments/1709876948194_Tax_Bioll.pdf",
  "size": "423774",
  "createdAt": "Fri Mar 08 2024 11:19:08 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "60f915d3f3dd69653a592199",
      "role": "MAKER + RATE VERIFIER + CHEAKER",
      "firstName": "Shobha",
      "lastName": "Kuperkar",
      "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "65e7fa2cf9222577acbbf665",
    "note": "Rate verification done, visit pending",
    "taskId": "65e58112f9222577acb8856b",
    "createdAt": "2024-03-06T05:07:56.895Z"
  }
],
"createdAt": "2024-03-02T16:18:28.694Z",
"updatedAt": "2024-03-08T07:38:59.107Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. B3/203, 2nd Floor, Building No B3, Leisure Town
Phase I, Near Amnora Town Fire Station, Sadesataranali, Village - Hadapsar, Taluka -
Haveli, District - Pune, PIN - 411 028, State - Maharashtra, India",
"updatedBy": "60f915d3f3dd69653a592199",
"addressForMap": "",
"caseReferredBy": ""
```



```
"contactPersonName": "Mr. Rahul ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "Ms. Vidya Gourishankar Upadhye",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Representative of Purchaser",
"siteVisitContactNo": "9850387794",
"buildingServicesRate": "2600.00",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Memorandum of Understanding",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 739.00",
"flatRate": "10100",
"landOtherRate": "7500",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
"briefDescOfProperty": "3 Bedroom + Living Room + Kitchen + 2 Passage + Toilet",
"carpetTotal": "555.21",
"otherCarpetTotal": "260.27",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "260.27",
"otherCompositionSaleableTotal": "0.00",
"builtupPercentage": "10",
"extendOfSiteRemark": "Carpet Area in Sq. Ft. = 540.00\nEnclosed Balcony Area in
Sq. Ft. = 70.00\nDry Balcony Area in Sq. Ft. = 29\nTerrace Area in Sq. Ft. = 100.00\n",
"finalBuiltupArea": "897.03",
"finalCarpetArea": "815.48",
"finalSalableArea": "897.03",
"salablePercentage": "0",
"siteMeasurementRemark": "Carpet Area in Sq. Ft. = 555.21\nDry Balcony Area in Sq.
Ft. = 25.46\nBalcony Aera in Sq. Ft. = 7.94\nAttached Terrace Area in Sq. Ft. = 226.87
\n<br />",
"toBeAdded": "",
"finalSaleablePercentage": "0",
"reportGeneratedDate": "Fri Mar 08 2024 10:37:18 GMT+0530 (India Standard Time)",
"siteVisitDate": "2024-03-05",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
```

```

    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
}

```

Name	Length	Width	Total
Composition :			
Passage	4'4"	3'9"	16.25
Living Room	16'5"	10'4"	169.64
Kitchen	7'11"	7'11"	62.67
Passage	8'10"	3'5"	30.18
Bedroom	6'10"	3'11"	26.76
Bedroom	10'10"	9'1"	98.40
Bedroom	10'11"	10'5"	113.71
Toilet	7'11"	4'9"	37.60
Other Composition :			
Dry Balcony Area	7'10"	3'3"	25.46
Balcony Area	1'10"	4'4"	7.94
Terrace Area	24'9"	9'2"	226.87