

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Bank_Loan",
    "label": "Bank Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b951"
    },
    "type": "CREDITOFFICER",
    "_id": "635f732fe363ef22db2f1c80",
    "firstName": "Ravindra Sir",
    "lastName": "sir",
    "mobileNo": "",
    "email": "1sbi.14677@sbi.co.in",
    "workMobileNo": "7738642220"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b951",
  "branchCode": "000167",
  "type": "BRANCH",
  "name": "RACPC Belapur ",
  "email": "sbi.14677@sbi.co.in",
  "mobileNo": "022-27524090",
  "alternateMobileNo": "",
  "address": "Estate Department Corporate Centre, 4th Floor, CIDCO Tower No. 4,
Railway Station Building, C.B.D. Belapur, Navi Mumbai - 400 614, State - Maharashtra,
Country - India.",
  "ledgerName": "STATE BANK OF INDIA - CBD Estate Department",
  "fax": "022 2757 7002",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "60b7189d2ffdf65bcd65882b",
  "role": "PICKUPPERSON",
  "firstName": "Ravindra",
  "email": "ravindrakasare186@gmail.com",
  "lastName": "Kasare",
  "mobileNo": "9167204055",
  "shortName": "RBK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60b7189d2ffdf65bcd65882b\\
\\profilePhoto_1622701555488_WhatsApp Image 2021-06-03 at 11.46.40 AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "627362b3afd7d55eddee1ee7",
  "role": "SITEENGINEER",
  "firstName": "Vicky ",
  "email": "vicky@vastukala.org",
  "lastName": "Baar",
  "mobileNo": "9004386288",
  "designation": "",
  "shortName": "VB",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60f91b6f344e052188ffd1fc",
  "role": "MAKER",
  "firstName": "Jayaraja",
  "email": "jayaraja@vastukala.org",
  "lastName": "Acharya",
```

```
"mobileNo": "9867664219",
"designation": "",
"shortName": "JA",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91b6f344e052188ffd1fc/
profilePhoto_1678780588416_Profile_Photo.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  {
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ]
  }
]
```

```
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.00765158903981",
  "longitude": "73.10662260296323"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
}
```

```
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "5/03/2024 09:16 am"
    },
    {
      "dateTime": "5/03/2024 12:00 am"
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-03-05",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "3BHK",
  "label": "3 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  }
}
```

```
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "New Panvel (West)",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "8",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Raigad",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
```

```
"key": "taluka",
"value": "Panvel",
"label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "9",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Millennium Flora",
  "label": false
},
"selectArea": {
  "status": true,
  "name": "Sector",
  "key": "selectArea",
  "value": "17",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Khanda Colony",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
}
```



```
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
```

```
"value": "",
"label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "805",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
```

```
"status": false,
"name": "Gut No.",
"key": "GUTNo",
"value": "",
"label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 410 206",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Navi Mumbai",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "Proposed_R.C.C._Slab",
    "label": "Proposed R.C.C. Slab"
  },
  "flooring": {
    "value": "Proposed_Vitrified_tiles_flooring",
    "label": "Proposed Vitrified tiles flooring"
  },
  "doors": {
    "value": "Proposed_Teak_wood_door_frame_with_flush_doors",
    "label": "Proposed Teak wood door frame with flush doors"
  },
  "windows": {
    "value": "Proposed_Powder_coated_aluminium_sliding_windows",
    "label": "Proposed Powder coated aluminium sliding windows"
  },
  "fittings": {
    "value": "Proposed_Concealed_plumbing_with_C.P._fittings._Proposed_Electrical_wiring_with_Concealed.",
    "label": "Proposed Concealed plumbing with C.P. fittings. Proposed Electrical wiring with Concealed."
  },
  "finishing": {
    "value": "Proposed_Cement_Plastering",
```

```
    "label": "Proposed Cement Plastering"
  }
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "Panvel_Municipal_Corporation",
    "label": "Panvel Municipal Corporation"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Under Construction Building",
    "west": "Road",
    "south": "Open Plot",
    "east": "Trifed Tower"
  },
  "asPerDocumentAgreement": {
    "north": "Plot No. 08",
    "west": "30 Mtrs. Wide Road",
    "south": "Plot No. 10",
    "east": "Plot No. 03, Trifed and Plot No. 2A"
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "",
      "west": "",
      "south": "",
      "east": ""
    },
    "asPerDocument": {
      "north": "",
      "west": "",
```

```
    "south": "",
    "east": ""
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "+ Balcony Area + Dry Balcony Area",
"dateOfIssusApprovePlan": "Copy of Approved Building Plan No. PMC / NRV /
16092, Outward No. 128 / 2022 Dated 14.01.2022 issued by Panvel Municipal
Corporation",
"approvePlanVerified": "Yes",
"empanelledOfApprovePlan": "No",
"unauthorizedConstruction": ""
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "0",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "buildingServicesDepreciatedRate": "0",
  "depreciatedCostOfConstruction": "17500.00",
  "depreciatedBuildingRate": "2700"
},
"igrRate": {
  "propertyName": "Residential",
  "rate": "97700",
  "landRate": "36100",
  "igrImage": "cases/65e695d3f9222577acb9812f/igr_1709632322164_Image.png",
  "squareMeterGuideLineRate": "102585.00",
  "squareFeetGuideLineRate": "9530.00"
},
"igrFinalRate": {
  "floorRatePercentage": "5",
  "depreciationPercentage": "0",
  "rate": "97700.00",
  "squareMeterGuideLineRate": "102585.00",
  "squareFeetGuideLineRate": "9530.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  }
}
```

```
},
"propertyOccupiedByList": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"monthlyRent": "40,000/- Expected rental income per month",
"assessmentNo": "Information not available",
"taxPaidHolderName": "Information not available",
"taxAmount": "Information not available",
"electricityServiceConnectionNo": "Information not available",
"meterCardHolderName": "Information not available",
"undividedAreaOfLandAsPerSaleDeed": "Information not available",
"floorSpaceIndex": "As per PMC norms",
"tenantName": "",
"maintenanceOfFlat": "Building Under Construction"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "Proposed_R.C.C._Slab",
    "label": "Proposed R.C.C. Slab"
  },
  "partitions": {
    "value": "Proposed_6\"_Thk._Brick_Masonry",
    "label": "Proposed 6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "Proposed_Municipal_Water_Supply",
    "label": "Proposed Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Proposed,_Yes",
    "label": "Proposed, Yes"
  },
  "carParking": "01 Front / Back Car Parking Space (As per Index II)",
  "constructionWorkStatus": {
    "value": "InProgress",
    "label": "Under Construction"
  }
},
```

```
"asthetikLook": {
  "value": "Proposed_Plain_Looking",
  "label": "Proposed Plain Looking"
},
"dateOfConstruction": {
  "date": "",
  "month": "1",
  "year": "2026",
  "fullDate": "1/1/2026"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "Proposed_R.C.C_Framed_Structure",
  "label": "Proposed R.C.C Framed Structure"
},
"typeOfFoundation": {
  "value": "Proposed_R.C.C_Foundation",
  "label": "Proposed R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"materialUsedList": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"buildingSpecification": {
  "value": "Proposed_Standard",
  "label": "Proposed Standard"
},
"structuralSafety": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "Proposed_Connected_to_Municipal_Sewerage_System_",
  "label": "Proposed Connected to Municipal Sewerage System "
},
```

```
"walls": {
  "value": "Proposed,_Yes",
  "label": "Proposed, Yes"
},
"appearanceOfTheBuilding": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"maintenanceOfTheBuilding": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"maintenanceIssues": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"visibleDamageInBuilding": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"systemOfAirConditioning": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"provisionOfFirefighting": {
  "value": "Proposed,_Yes",
  "label": "Proposed, Yes"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "As_per_RERA_Certificate",
  "label": "As per RERA Certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "0",
"ageOfBuilding": "0",
"noOfBasement": "",
"noOfPodium": "2",
"noOfAmenityFloors": "1",
"noOfFloors": "11",
"flatFloorNo": "8",
"noOfLifts": "3",
```



```
"noOfDwellingUnitsInBuilding": "12"
},
"finalPlinthArea": {
  "area": "965.80",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/65e695d3f9222577acb9812f/
routeMap_1709700625898_Image.png",
    "routeLat": "19.007722",
    "routeLng": "73.106472",
    "stationName": "Khandeshwar",
    "routeDistance": "1.8 km"
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finalLatLng": true
  },
  "locationMapImg": [
    {
      "id": "51s4us",
      "name": "51s4us",
      "image": "cases/65e695d3f9222577acb9812f/
routeMap_1709700508945_Image.png"
    }
  ]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
```

```
"showcasesRate": "0",
"totalshowcasesRate": "0",
"kitchenArrangementsQty": "0",
"kitchenArrangementsRate": "0",
"totalkitchenArrangementsRate": "0",
"superfineFinishQty": "0",
"superfineFinishRate": "0",
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "1",
"othersRate": "700000",
"totalothersRate": "700000",
"finaltotal": "16065000.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "15365000.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
```

```
"floorsCompleted": "Complete",
"percentage": "5",
"isHideFloor": false,
"status": true
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "16",
  "percentage": "40",
  "isHideFloor": false,
  "status": true
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "16",
  "percentage": "7.00",
  "isHideFloor": false,
  "status": true
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "16",
  "percentage": "7.00",
  "isHideFloor": false,
  "status": true
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "16",
  "percentage": "3.50",
  "isHideFloor": false,
  "status": true
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
}
```

```
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "67.50",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "9204074.00",
  "selectedBuildUpValue": "965.80",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "65e7efeff9222577acbbcc12",
      "name": "externallmg_1709699054687_IMG_20240306_394.jpg",
      "path": "cases/65e695d3f9222577acb9812f/
externallmg_1709699054687_IMG_20240306_394.jpg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "65e7efeff9222577acbbcc14",
      "name": "externallmg_1709699054698_IMG_20240306_1743.jpg",
      "path": "cases/65e695d3f9222577acb9812f/
externallmg_1709699054698_IMG_20240306_1743.jpg",
      "orientation": "landscape"
    }
  ],
  "externalPhotos": [
```

```
{
  "status": false,
  "_id": "65e7eff9222577acbbcc13",
  "name": "externallmg_1709699054692_IMG_20240306_0556.jpg",
  "path": "cases/65e695d3f9222577acb9812f/
externallmg_1709699054692_IMG_20240306_0556.jpg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "65e7eff9222577acbbcc76",
  "name": "externallmg_1709699070509_IMG_20240306_56796.jpg",
  "path": "cases/65e695d3f9222577acb9812f/
externallmg_1709699070509_IMG_20240306_56796.jpg",
  "orientation": "portrait"
}
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
    "_id": "65e7eff9222577acbbcc17",
    "name": "Living Room",
    "path": "cases/65e695d3f9222577acb9812f/
externallmg_1709699054709_IMG_20240306_5931.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65e7eff9222577acbbcc65",
    "name": "Living Room",
    "path": "cases/65e695d3f9222577acb9812f/
externallmg_1709699070465_IMG_20240306_3396.jpg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "65e7eff9222577acbbcc67",
    "name": "Living Room",
    "path": "cases/65e695d3f9222577acb9812f/
externallmg_1709699070472_IMG_20240306_4510.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
```

```
    "_id": "65e7effef9222577acbbcc69",
    "name": "Living Room",
    "path": "cases/65e695d3f9222577acb9812f/
externallmg_1709699070478_IMG_20240306_5199.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65e7effef9222577acbbcc6e",
    "name": "Living Room",
    "path": "cases/65e695d3f9222577acb9812f/
externallmg_1709699070492_IMG_20240306_8169.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65e7effef9222577acbbcc6f",
    "name": "Living Room",
    "path": "cases/65e695d3f9222577acb9812f/
externallmg_1709699070493_IMG_20240306_8534.jpg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "65e7effef9222577acbbcc70",
    "name": "Living Room",
    "path": "cases/65e695d3f9222577acb9812f/
externallmg_1709699070497_IMG_20240306_8940.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65e7effef9222577acbbcc71",
    "name": "Living Room",
    "path": "cases/65e695d3f9222577acb9812f/
externallmg_1709699070498_IMG_20240306_9352.jpg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "65e7effef9222577acbbcc73",
    "name": "Living Room",
    "path": "cases/65e695d3f9222577acb9812f/
externallmg_1709699070501_IMG_20240306_10248.jpg",
    "orientation": "portrait"
  },
}
```

```
{
  "status": false,
  "_id": "65e7eff9222577acbbcc6c",
  "name": "Living Room",
  "path": "cases/65e695d3f9222577acb9812f/
externallmg_1709699070486_IMG_20240306_7242.jpg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "65e7efeff9222577acbbcc15",
  "name": "Living Room",
  "path": "cases/65e695d3f9222577acb9812f/
externallmg_1709699054701_IMG_20240306_5549.jpg",
  "orientation": "portrait"
}
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "16970",
    "max": "17742"
  },
  "builtUpRateRange": {
    "min": "15428",
    "max": "16130"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
```



```
"title": "Showcases",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```

```
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "true",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
```

```
"isSiteMeasurementAllowed": true,
"finalValuationArea": "878.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3",
  "SME/TCC/221/13"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"invoices": [],
"paymentIds": [],
"_id": "65e695d3f9222577acb9812f",
"ownerName": "Mr. Narendra Raghunath Gaikwad",
"ownerPhoneNo": "9136366120",
"ownershipShare": "",
"email": "",
"siteVisitContactNo": "8591889050",
"contactPersonName": "Mr. Darshak",
"purchaseValueAsPerDocument": "0",
"owners": [
  {
    "name": "Mr. Narendra Raghunath Gaikwad",
    "phone": "9136366120",
    "ownershipShare": "",
    "email": "",
    "id": "306871"
  },
  {
    "name": "Dr. Mrs. Madhura Narendra Gaikwad",
    "phone": "",
    "email": "",
    "ownershipShare": "",
    "id": "684514"
  },
  {
    "name": "Smt. Sulakashana Raghunath Gaikwad",
    "phone": "",
    "email": "",
    "ownershipShare": "",
    "id": "686308"
  }
],
"caseReferredBy": "60b7189d2ffdf65bcd65882b",
"relationWithOwner": "Sales Person",
"fullAddress": "Residential Flat No. 805, 8th Floor, Millennium Flora, Plot No. 9, Sector
17, Khanda Colony, Village - New Panvel (West), Navi Mumbai, Taluka - Panvel, District
```

```
- Raigad, PIN - 410 206, State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "12/02/2024",
      "from": {
        "value": "Promoter",
        "label": "Promoter"
      },
      "Promoter": "M/s. Millennium Infra",
      "to": {
        "value": "Allottee",
        "label": "Allottee"
      },
      "Allottee": "Mr. Narendra Raghunath Gaikwad, Dr. Mrs. Madhura Narendra
Gaikwad & Smt. Sulakashana Raghunath Gaikwad",
      "number": {
        "value": "Registration_No",
        "label": "Registration No"
      },
      "Registration_No": "2803/2024"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "542079",
    "path": "cases/65e695d3f9222577acb9812f/
document_1709610448086_CamScanner_03042024_1317_1.pdf",
    "fileName": "document_1709610448086_CamScanner_03042024_1317_1.pdf"
  },
  {
    "documentType": {
      "value": "60ae1247aa6d152c1801b2ea",
      "label": "Commencement Certificate"
    },
    "inputs": {
      "documentDate": "14/01/2022",
      "nameOfApprovingAuthority": {
        "value": "Panvel_Municipal_Corporation",
        "label": "Panvel Muncipal Corporation"
      },
      "number": {
```

```
    "value": "No",
    "label": "No"
  },
  "No": "PMC / TP / N.Panvel / 17 / 09 / 21-22 / 16092 / 128 / 2022"
},
"isHardCopy": false,
"displayStatus": true,
"id": "356584",
"path": "cases/65e695d3f9222577acb9812f/document_1709639080692_1_Commencement_Certificates___NA_Order_for_plotted_development.pdf",
"fileName": "document_1709639080692_1_Commencement_Certificates___NA_Order_for_plotted_development.pdf"
},
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
    "label": "RERA Certificate"
  },
  "inputs": {
    "documentDate": "16/02/2022",
    "nameOfApprovingAuthority": {
      "value": "Maharashtra_Real_Estate_Regulatory_Authority",
      "label": "Maharashtra Real Estate Regulatory Authority"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "P52000033391"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1709639135003_P52000033391.pdf",
"path": "cases/65e695d3f9222577acb9812f/document_1709639135003_P52000033391.pdf",
"id": "221018",
"uploadedBy": "60f91b6f344e052188ffd1fc",
"createdAt": "Tue Mar 05 2024 17:15:35 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1277aa6d152c1801b3cc",
    "label": "Approved Building Plan"
  },
  "inputs": {
    "documentDate": "14/01/2022",
```

```
"nameOfApprovingAuthority": {
  "value": "Panvel_Municipal_Corporation",
  "label": "Panvel Municipal Corporation"
},
"remark": "(Downloaded from RERA)",
"number": {
  "value": "No",
  "label": "No"
},
"No": "PMC / NRV / 16092, Outward No. 128 / 2022"
},
"isHardCopy": false,
"displayStatus": true,
"id": "692628",
"path": "cases/65e695d3f9222577acb9812f/document_1709639534603_3_Building
_Plan_Approval___NA_Order_for_plotted_development.pdf",
"fileName": "document_1709639534603_3_Building_Plan_Approval___NA_Order_f
or_plotted_development.pdf"
}
],
"isUrgent": "false",
"isExternal": "false",
"proposePurchaserName": "",
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"scheduleSiteVisitDate": "Invalid date",
"caseNumber": "007433",
"createdBy": "6006d4ce5080a310ac1fdcf2",
"caseHistory": [
  {
    "id": "506908",
    "title": "Create Case",
    "description": "Create Case",
    "datetime": "Tue Mar 05 2024 09:17:31 GMT+0530 (India Standard Time)"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    }
  },

```

```
"id": "206992",
"name": "Living Room",
"length": "3.50",
"length1": "3",
"length2": "6",
"width": "4.17",
"width1": "4",
"width2": "2",
"totalArea": "14.58",
"images": [],
"extraAreas": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "_id": "65e7f86df9222577acbbf100",
    "name": "Living Room",
    "extraAreaType": "Add",
    "length": "16.67",
    "length1": "16",
    "length2": "8",
    "width": "9.67",
    "width1": "9",
    "width2": "8",
    "totalArea": "161.11"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "_id": "65e7f8b3f9222577acbbf200",
    "name": "Living Room",
    "extraAreaType": "Add",
    "length": "13.17",
    "length1": "13",
    "length2": "2",
    "width": "8.25",
    "width1": "8",
    "width2": "3",
    "totalArea": "108.62"
  }
],
"finalArea": "284.31000000000006"
},
```

```
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "9",
  "name": "Passage",
  "length": "",
  "length1": "3",
  "length2": "11",
  "width": "",
  "width1": "2",
  "width2": "2",
  "totalArea": "8.49",
  "images": [],
  "finalArea": "8.49",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Toilet",
  "length": "3.83",
  "length1": "3",
  "length2": "10",
  "width": "6.67",
  "width1": "6",
  "width2": "8",
  "totalArea": "25.56",
  "images": [],
  "extraAreas": [],
  "finalArea": "25.56"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Toilet",
  "length": "3.83",
  "length1": "3",
  "length2": "10",
```



```
"width": "7.00",
"width1": "7",
"width2": "00",
"totalArea": "26.83",
"images": [],
"extraAreas": [],
"finalArea": "26.83"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Toilet",
  "length": "3.83",
  "length1": "3",
  "length2": "10",
  "width": "7.33",
  "width1": "7",
  "width2": "4",
  "totalArea": "28.11",
  "images": [],
  "extraAreas": [],
  "finalArea": "28.11"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Kitchen",
  "length": "11.67",
  "length1": "11",
  "length2": "8",
  "width": "7.25",
  "width1": "7",
  "width2": "3",
  "totalArea": "84.58",
  "images": [],
  "extraAreas": [],
  "finalArea": "84.58"
},
{
  "measurementType": {
```

```
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Bedroom",
  "length": "11.92",
  "length1": "11",
  "length2": "11",
  "width": "8.75",
  "width1": "8",
  "width2": "9",
  "totalArea": "104.27",
  "images": [],
  "extraAreas": [],
  "finalArea": "104.27"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Bedroom",
  "length": "11.92",
  "length1": "11",
  "length2": "11",
  "width": "10.00",
  "width1": "10",
  "width2": "00",
  "totalArea": "119.17",
  "images": [],
  "extraAreas": [],
  "finalArea": "119.17"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "8",
  "name": "Bedroom",
  "length": "10.92",
  "length1": "10",
  "length2": "11",
  "width": "9.67",
  "width1": "9",
```

```
"width2": "8",
"totalArea": "105.53",
"images": [],
"extraAreas": [],
"finalArea": "105.53"
}
],
"otherComposition": [
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Balcony Area",
    "value": "Balcony_Area"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "0",
  "length": "9.83",
  "length1": "9",
  "length2": "10",
  "width": "3.08",
  "width1": "3",
  "width2": "1",
  "totalArea": "30.32",
  "images": [],
  "extraAreas": [],
  "finalArea": "30.32",
  "percentageBeforeTotal": "30.32",
  "percentage": "100"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Balcony Area",
    "value": "Balcony_Area"
  },
  "measurementType": {
    "value": "Square_Feet",
```

```
    "label": "Square Feet"
  },
  "id": "1",
  "length": "19.00",
  "length1": "19",
  "length2": "00",
  "width": "2.00",
  "width1": "2",
  "width2": "00",
  "totalArea": "38.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "38",
  "percentageBeforeTotal": "38.00",
  "percentage": "100"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Balcony Area",
    "value": "Balcony_Area"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "length": "7.33",
  "length1": "7",
  "length2": "4",
  "width": "2.00",
  "width1": "2",
  "width2": "00",
  "totalArea": "14.67",
  "images": [],
  "extraAreas": [],
  "finalArea": "14.67",
  "percentageBeforeTotal": "14.67",
  "percentage": "100"
},
{
  "toBeAdded": {
    "label": "Carpet",
```

```
"value": "Carpet"
},
"name": {
  "label": "Balcony Area",
  "value": "Balcony_Area"
},
"measurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"length": "9.75",
"length1": "9",
"length2": "9",
"width": "2.00",
"width1": "2",
"width2": "00",
"totalArea": "19.50",
"images": [],
"extraAreas": [],
"finalArea": "19.5",
"percentageBeforeTotal": "19.50",
"percentage": "100"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Dry Balcony Area",
    "value": "Dry_Balcony_Area"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "length": "3.58",
  "length1": "3",
  "length2": "7",
  "width": "2.58",
  "width1": "2",
  "width2": "7",
  "totalArea": "9.26",
  "images": [],
```

```
"extraAreas": [],
"finalArea": "9.26",
"percentageBeforeTotal": "9.26",
"percentage": "100"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Dry Balcony Area",
    "value": "Dry_Balcony_Area"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "length": "2.83",
  "length1": "2",
  "length2": "10",
  "width": "7.33",
  "width1": "7",
  "width2": "4",
  "totalArea": "20.78",
  "images": [],
  "extraAreas": [],
  "finalArea": "20.78",
  "percentageBeforeTotal": "20.78",
  "percentage": "100"
}
],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "491963",
    "selectAreaTypeDocument": "Carpet",
```

```
"totalAreaDocument": "878",
"squareMeterArea": "81.57",
"docFinalBuiltUp": "965.8",
"docFinalBuiltUpSquareMeter": "89.72699999999999",
"docBuiltupPercentage": "10",
"docSaleablePercentage": "0",
"docFinalSaleable": "0",
"docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
{
  "printlnReport": true,
  "_id": "65e6eb46f9222577acb1ee",
  "property": "Millennium Flora, Panvel",
  "area": "878",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "Middle",
  "source": "Housing.Com",
  "expectedPrice": "14900000",
  "expectedRate": "16970.39",
  "builtUpExpectedRate": "15427.62",
  "image": "cases/65e695d3f9222577acb9812f/
indicator_1709631667112_Image.png",
  "squareMeter": "81.57",
  "id": "948183"
},
{
  "printlnReport": true,
  "_id": "65e6eb46f9222577acb1ef",
  "property": "Millennium Flora, Panvel",
  "area": "620",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "5",
  "source": "magic_bricks",
  "expectedPrice": "11000000",
  "expectedRate": "17741.94",
  "builtUpExpectedRate": "16129.03",
  "image": "cases/65e695d3f9222577acb9812f/
indicator_1709631703717_Image.png",
```

```
"squareMeter": "57.60",
"id": "775613"
},
{
  "printlnReport": true,
  "_id": "65e6eb46f9222577acb1f0",
  "property": "Millennium Flora, Panvel",
  "area": "768",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "Middle",
  "source": "Commonfloor.com",
  "expectedPrice": "13600000",
  "expectedRate": "17708.33",
  "builtUpExpectedRate": "16098.48",
  "image": "cases/65e695d3f9222577acb9812f/
indicator_1709631739319_Image.png",
  "squareMeter": "71.35",
  "id": "222093"
},
{
  "printlnReport": true,
  "_id": "65e6eb46f9222577acb1f1",
  "property": "Millennium Flora, Panvel",
  "area": "840",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "5",
  "source": "magic_bricks",
  "expectedPrice": "14500000",
  "expectedRate": "17261.90",
  "builtUpExpectedRate": "15692.64",
  "image": "cases/65e695d3f9222577acb9812f/
indicator_1709631778813_Image.png",
  "squareMeter": "78.04",
  "id": "120741"
}
],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```



```
    "_id": "65e7efeff9222577acbbcc11",
    "name": "externallmg_1709699054683_IMG_20240306_40.jpg",
    "path": "cases/65e695d3f9222577acb9812f/
externallmg_1709699054683_IMG_20240306_40.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65e7efeff9222577acbbcc12",
    "name": "externallmg_1709699054687_IMG_20240306_394.jpg",
    "path": "cases/65e695d3f9222577acb9812f/
externallmg_1709699054687_IMG_20240306_394.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65e7efeff9222577acbbcc13",
    "name": "externallmg_1709699054692_IMG_20240306_0556.jpg",
    "path": "cases/65e695d3f9222577acb9812f/
externallmg_1709699054692_IMG_20240306_0556.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65e7efeff9222577acbbcc14",
    "name": "externallmg_1709699054698_IMG_20240306_1743.jpg",
    "path": "cases/65e695d3f9222577acb9812f/
externallmg_1709699054698_IMG_20240306_1743.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65e7efeff9222577acbbcc15",
    "name": "externallmg_1709699054701_IMG_20240306_5549.jpg",
    "path": "cases/65e695d3f9222577acb9812f/
externallmg_1709699054701_IMG_20240306_5549.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65e7efeff9222577acbbcc16",
```

```
    "name": "externallmg_1709699054703_IMG_20240306_5638.jpg",
    "path": "cases/65e695d3f9222577acb9812f/
externallmg_1709699054703_IMG_20240306_5638.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65e7efeff9222577acbbcc17",
    "name": "externallmg_1709699054709_IMG_20240306_5931.jpg",
    "path": "cases/65e695d3f9222577acb9812f/
externallmg_1709699054709_IMG_20240306_5931.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65e7efeff9222577acbbcc18",
    "name": "externallmg_1709699054711_IMG_20240306_11978.jpg",
    "path": "cases/65e695d3f9222577acb9812f/
externallmg_1709699054711_IMG_20240306_11978.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65e7efeff9222577acbbcc19",
    "name": "externallmg_1709699054714_IMG_20240306_092833.jpg",
    "path": "cases/65e695d3f9222577acb9812f/
externallmg_1709699054714_IMG_20240306_092833.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65e7efeff9222577acbbcc1a",
    "name": "externallmg_1709699054731_IMG_20240306_092849.jpg",
    "path": "cases/65e695d3f9222577acb9812f/
externallmg_1709699054731_IMG_20240306_092849.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65e7efeff9222577acbbcc1b",
    "name": "externallmg_1709699054874_Screenshot_2024030514521863_3d9111e2
```

```
d3171bf4882369f490c087b4.jpg",
  "path": "cases/65e695d3f9222577acb9812f/externallmg_1709699054874_Screensh
ot_2024030514521863_3d9111e2d3171bf4882369f490c087b4.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e7efeff9222577acbbcc1c",
  "name": "externallmg_1709699054897_IMG_20240306_196.jpg",
  "path": "cases/65e695d3f9222577acb9812f/
externallmg_1709699054897_IMG_20240306_196.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e7efeff9222577acbbcc1d",
  "name": "externallmg_1709699054901_IMG_20240306_2136.jpg",
  "path": "cases/65e695d3f9222577acb9812f/
externallmg_1709699054901_IMG_20240306_2136.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e7efeff9222577acbbcc1e",
  "name": "externallmg_r_1709699054744_IMG20240305144645.jpg",
  "path": "cases/65e695d3f9222577acb9812f/
externallmg_r_1709699054744_IMG20240305144645.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e7efeff9222577acbbcc1f",
  "name": "externallmg_r_1709699054824_IMG20240306092738.jpg",
  "path": "cases/65e695d3f9222577acb9812f/
externallmg_r_1709699054824_IMG20240306092738.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e7efeff9222577acbbcc20",
  "name": "externallmg_r_1709699054773_IMG20240305144648.jpg",
```

```
    "path": "cases/65e695d3f9222577acb9812f/
externallmg_r_1709699054773_IMG20240305144648.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65e7effef9222577acbbcc64",
    "name": "externallmg_1709699070461_IMG_20240306_2515.jpg",
    "path": "cases/65e695d3f9222577acb9812f/
externallmg_1709699070461_IMG_20240306_2515.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65e7effef9222577acbbcc65",
    "name": "externallmg_1709699070465_IMG_20240306_3396.jpg",
    "path": "cases/65e695d3f9222577acb9812f/
externallmg_1709699070465_IMG_20240306_3396.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65e7effef9222577acbbcc66",
    "name": "externallmg_1709699070469_IMG_20240306_3698.jpg",
    "path": "cases/65e695d3f9222577acb9812f/
externallmg_1709699070469_IMG_20240306_3698.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65e7effef9222577acbbcc67",
    "name": "externallmg_1709699070472_IMG_20240306_4510.jpg",
    "path": "cases/65e695d3f9222577acb9812f/
externallmg_1709699070472_IMG_20240306_4510.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65e7effef9222577acbbcc68",
    "name": "externallmg_1709699070477_IMG_20240306_4778.jpg",
    "path": "cases/65e695d3f9222577acb9812f/
externallmg_1709699070477_IMG_20240306_4778.jpg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e7effef9222577acbbcc69",
  "name": "externallmg_1709699070478_IMG_20240306_5199.jpg",
  "path": "cases/65e695d3f9222577acb9812f/
externallmg_1709699070478_IMG_20240306_5199.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e7effef9222577acbbcc6a",
  "name": "externallmg_1709699070482_IMG_20240306_6333.jpg",
  "path": "cases/65e695d3f9222577acb9812f/
externallmg_1709699070482_IMG_20240306_6333.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e7effef9222577acbbcc6b",
  "name": "externallmg_1709699070484_IMG_20240306_6801.jpg",
  "path": "cases/65e695d3f9222577acb9812f/
externallmg_1709699070484_IMG_20240306_6801.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e7effef9222577acbbcc6c",
  "name": "externallmg_1709699070486_IMG_20240306_7242.jpg",
  "path": "cases/65e695d3f9222577acb9812f/
externallmg_1709699070486_IMG_20240306_7242.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e7effef9222577acbbcc6d",
  "name": "externallmg_1709699070489_IMG_20240306_7654.jpg",
  "path": "cases/65e695d3f9222577acb9812f/
externallmg_1709699070489_IMG_20240306_7654.jpg",
  "orientation": "landscape"
}
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e7effef9222577acbbcc6e",
  "name": "externallmg_1709699070492_IMG_20240306_8169.jpg",
  "path": "cases/65e695d3f9222577acb9812f/
externallmg_1709699070492_IMG_20240306_8169.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e7effef9222577acbbcc6f",
  "name": "externallmg_1709699070493_IMG_20240306_8534.jpg",
  "path": "cases/65e695d3f9222577acb9812f/
externallmg_1709699070493_IMG_20240306_8534.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e7effef9222577acbbcc70",
  "name": "externallmg_1709699070497_IMG_20240306_8940.jpg",
  "path": "cases/65e695d3f9222577acb9812f/
externallmg_1709699070497_IMG_20240306_8940.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e7effef9222577acbbcc71",
  "name": "externallmg_1709699070498_IMG_20240306_9352.jpg",
  "path": "cases/65e695d3f9222577acb9812f/
externallmg_1709699070498_IMG_20240306_9352.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e7effef9222577acbbcc72",
  "name": "externallmg_1709699070501_IMG_20240306_9703.jpg",
  "path": "cases/65e695d3f9222577acb9812f/
externallmg_1709699070501_IMG_20240306_9703.jpg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e7effef9222577acbbcc73",
  "name": "externallmg_1709699070501_IMG_20240306_10248.jpg",
  "path": "cases/65e695d3f9222577acb9812f/
externallmg_1709699070501_IMG_20240306_10248.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e7effef9222577acbbcc74",
  "name": "externallmg_1709699070503_IMG_20240306_10690.jpg",
  "path": "cases/65e695d3f9222577acb9812f/
externallmg_1709699070503_IMG_20240306_10690.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e7effef9222577acbbcc75",
  "name": "externallmg_1709699070506_IMG_20240306_11305.jpg",
  "path": "cases/65e695d3f9222577acb9812f/
externallmg_1709699070506_IMG_20240306_11305.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e7effef9222577acbbcc76",
  "name": "externallmg_1709699070509_IMG_20240306_56796.jpg",
  "path": "cases/65e695d3f9222577acb9812f/
externallmg_1709699070509_IMG_20240306_56796.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e7effef9222577acbbcc77",
  "name": "externallmg_1709699070516_IMG_20240306_59739.jpg",
  "path": "cases/65e695d3f9222577acb9812f/
externallmg_1709699070516_IMG_20240306_59739.jpg",
  "orientation": "portrait"
}
],
```

```
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "Calculation.xlsx",
    "filename": "1709632338816_Calculation.xlsx",
    "path": "cases/65e695d3f9222577acb9812f/
processingDocuments/1709632338816_Calculation.xlsx",
    "size": "1611547",
    "createdAt": "Tue Mar 05 2024 15:22:20 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f915d3f3dd69653a592199"
  },
  {
    "originalname": "Approved Plan.pdf",
    "filename": "1709703317834_Approved_Plan.pdf",
    "path": "cases/65e695d3f9222577acb9812f/
processingDocuments/1709703317834_Approved_Plan.pdf",
    "size": "775882",
    "createdAt": "Wed Mar 06 2024 11:05:18 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
  {
    "originalname": "CC.pdf",
    "filename": "1709703317880_CC.pdf",
    "path": "cases/65e695d3f9222577acb9812f/
processingDocuments/1709703317880_CC.pdf",
    "size": "850828",
    "createdAt": "Wed Mar 06 2024 11:05:18 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
  {
    "originalname": "Google Location.jpg",
    "filename": "1709703317913_Google_Location.jpg",
    "path": "cases/65e695d3f9222577acb9812f/
processingDocuments/1709703317913_Google_Location.jpg",
    "size": "1185795",
    "createdAt": "Wed Mar 06 2024 11:05:18 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
  {
    "originalname": "Location.jpg",
    "filename": "1709703318008_Location.jpg",
    "path": "cases/65e695d3f9222577acb9812f/
processingDocuments/1709703318008_Location.jpg",
    "size": "860813",
    "createdAt": "Wed Mar 06 2024 11:05:18 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  }
]
```



```
    },
    {
      "originalname": "Sale Deed - 2024.pdf",
      "filename": "1709703318058_Sale_Deed__2024.pdf",
      "path": "cases/65e695d3f9222577acb9812f/
processingDocuments/1709703318058_Sale_Deed__2024.pdf",
      "size": "4419391",
      "createdAt": "Wed Mar 06 2024 11:05:18 GMT+0530 (India Standard Time)",
      "uploadedBy": "60f91b6f344e052188ffd1fc"
    },
    {
      "originalname": "Sale Plan 1.jpg",
      "filename": "1709703318123_Sale_Plan_1.jpg",
      "path": "cases/65e695d3f9222577acb9812f/
processingDocuments/1709703318123_Sale_Plan_1.jpg",
      "size": "961731",
      "createdAt": "Wed Mar 06 2024 11:05:18 GMT+0530 (India Standard Time)",
      "uploadedBy": "60f91b6f344e052188ffd1fc"
    },
    {
      "originalname": "Sale Plan.jpg",
      "filename": "1709703318191_Sale_Plan.jpg",
      "path": "cases/65e695d3f9222577acb9812f/
processingDocuments/1709703318191_Sale_Plan.jpg",
      "size": "1551544",
      "createdAt": "Wed Mar 06 2024 11:05:18 GMT+0530 (India Standard Time)",
      "uploadedBy": "60f91b6f344e052188ffd1fc"
    },
    {
      "originalname": "Site Detail.jpg",
      "filename": "1709703318270_Site_Detail.jpg",
      "path": "cases/65e695d3f9222577acb9812f/
processingDocuments/1709703318270_Site_Detail.jpg",
      "size": "1141845",
      "createdAt": "Wed Mar 06 2024 11:05:18 GMT+0530 (India Standard Time)",
      "uploadedBy": "60f91b6f344e052188ffd1fc"
    },
    {
      "originalname": "Sketch.jpg",
      "filename": "1709703318336_Sketch.jpg",
      "path": "cases/65e695d3f9222577acb9812f/
processingDocuments/1709703318336_Sketch.jpg",
      "size": "1093314",
      "createdAt": "Wed Mar 06 2024 11:05:18 GMT+0530 (India Standard Time)",
      "uploadedBy": "60f91b6f344e052188ffd1fc"
    }
  }
```

```
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-03-05T03:47:31.908Z",
"updatedAt": "2024-03-06T06:54:57.313Z",
"__v": 0,
"addressForMap": "",
"updatedBy": "60f915d3f3dd69653a592199",
"buildingServicesRate": "2700.00",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 878.00",
"flatRate": "17500",
"landOtherRate": "14800",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
"builtupPercentage": "10",
"carpetTotal": "786.85",
"extendOfSiteRemark": "Carpet Area in Sq. Ft. = 839.00\nBalcony Area in Sq. Ft. = 39.00\n",
"finalBuiltupArea": "1011.32",
"finalCarpetArea": "919.38",
"finalSalableArea": "1011.32",
"otherCarpetTotal": "132.53",
"salablePercentage": "0",
"siteMeasurementRemark": "Carpet Area in Sq. Ft. = 786.85\nBalcony Area in Sq. Ft = 102.49\nDry Balcony Area in Sq. Ft. = 30.04\n<br />\n",
"toBeAdded": "",
"finalSaleablePercentage": "0",
"briefDescOfProperty": "3 Bedroom + Living Room + Kitchen + Passage + 3 Toilet",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "132.53",
"otherCompositionSaleableTotal": "0.00",
"reportGeneratedDate": "Wed Mar 06 2024 10:13:49 GMT+0530 (India Standard Time)",
"siteVisitDate": "2024-03-05",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
```

```

    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
}

```

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
<b>Composition :</b>			
Living Room	3'6"	4'2"	14.58
Passage	3'11"	2'2"	8.49
Toilet	3'10"	6'8"	25.56
Toilet	3'10"	7'00"	26.83
Toilet	3'10"	7'4"	28.11
Kitchen	11'8"	7'3"	84.58
Bedroom	11'11"	8'9"	104.27
Bedroom	11'11"	10'00"	119.17
Bedroom	10'11"	9'8"	105.53
<b>Other Composition :</b>			
Balcony Area	9'10"	3'1"	30.32
Balcony Area	19'00"	2'00"	38.00
Balcony Area	7'4"	2'00"	14.67
Balcony Area	9'9"	2'00"	19.50
Dry Balcony Area	3'7"	2'7"	9.26

Dry Balcony Area

2'10"

7'4"

20.78

---