

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b9f4"
    },
    "type": "CREDITOFFICER",
    "_id": "650581d3a8e9b70221e855e5",
    "firstName": "Bhakti",
    "lastName": "Podkar",
    "mobileNo": "",
    "workMobileNo": "8425827511",
    "email": "Bhakti.racpc.sion@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "5000000",
    "discussWithPerson": "Bhakti",
    "expectedFees": 2500,
    "quotedAmount": "2500"
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b9f4",
  "branchCode": "000215",
  "type": "BRANCH",
  "name": "RACPC Sion ",
  "email": "racpc.sion@sbi.co.in",
  "mobileNo": "02225046265",
  "alternateMobileNo": "",
  "address": "B-603 & 604, Kohinoor City, Commercial-1, 6th Floor, Kirol Road, Off
L.B.S. Marg, Kurla (West), Mumbai, Pin Code - 400 070, State - Maharashtra, Country -
India.",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "60b7177d2ffdf65bcd65882a",
  "role": "PICKUPPERSON",
  "firstName": "Saurabh",
  "email": "saurabhvelonde143@gmail.com",
  "lastName": "Velonde",
  "mobileNo": "8691048846",
  "shortName": "SSV",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1686816492317_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "60f9343b45132d6a6bdd96e8",
  "role": "SITEENGINEER",
  "firstName": "Rajesh",
  "email": "rajeshb.ghadi@gmail.com",
  "lastName": "Ghadi",
  "mobileNo": "8652092666",
  "designation": "",
  "shortName": "RHG",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "64dc7184ccaf1e7b7f637f47",
  "role": "FRONTDESK",
  "firstName": "Binumon",
  "email": "binu@vastukala.org",
  "lastName": "Moozhickal",
  "mobileNo": "9930252906",
  "designation": "Back Office Team Leader",
  "shortName": "BS",
  "workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
  "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
},
"maker": null,
"checker": null,
"valuers": []
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
```

```
},
"location": {
  "latitude": "19.021772677568183",
  "longitude": "73.09232065949993"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.09232065949993,
    19.021772677568183
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-03-11",
      "remark": ""
    }
  ],
  "schedule": []
},
"marketAnalysisAndRemark": {
  "audioNotes": [],
  "remark": "na",
  "rateMin": "7000.00",
  "lumpsumValue": "3300000.00",
  "rateMax": "7500.00",
  "areaType": {
    "Name": "Carpet",
    "Value": "Carpet",
    "name": "Carpet",
    "value": "Carpet"
  }
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
  }
}
```

```
"value": "Maharashtra",
"label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Kamothe",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "3",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Navi Mumbai",
  "label": false
},
"tahasilNo": {
```

```
"status": false,
"name": "Tahasil",
"key": "tahasilNo",
"value": "",
"label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "3",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Gangadhar Complex CHSL",
  "label": false
},
"selectArea": {
  "status": true,
  "name": "Sector",
  "key": "selectArea",
  "value": "7",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
```

```
"label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "B",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
```

```
"name": "CTS No.",
"key": "CTSNo",
"value": "",
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "304",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
}
```



```
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "label": "R. C. C. Slab",
    "value": "rcc_Slab"
  },
  "flooring": {
    "label": "Vitrified Tile Flooring",
    "value": "VerifiedTileFlooring"
  },
  "doors": {
    "label": "Teak Wood door frame, Flush doors shutters",
    "value": "Teak_Wood_door_frame,_Flush_doors_shutters"
  },
  "windows": {
    "label": "Alluminum sliding windows with M. S. Grills",
    "value": "Alluminum_sliding_windows_with_M._S._Grills"
  }
}
```

```
    },
    "fittings": {
      "label": "Concealed plumbing with C.P. fittings. Casting Capping Electrical wiring",
      "value":
"Concealed_plumbing_with_C.P._fittings._Casting_Capping_Electrical_wiring"
    },
    "finishing": {
      "label": "Cement Plastering",
      "value": "Cement_Plastering"
    }
  },
  "general": {
    "populationClassList": {
      "label": "Middle Class",
      "value": "MiddleClass"
    },
    "populationGroupList": {
      "label": "Urban",
      "value": "Urban"
    },
    "townplanApprovedByList": {
      "label": "Panvel Municipal Corporation",
      "value": "Panvel_Municipal_Corporation"
    },
    "asPerActualAgreement": {
      "north": "C WING",
      "west": "SHIHGAD",
      "south": "ROAD",
      "east": "ROAD"
    },
    "asPerDocumentAgreement": {
      "north": "",
      "west": "",
      "south": "",
      "east": ""
    },
    "unitBoundaries": {
      "asPerActual": {
        "north": "C wing",
        "west": "303",
        "south": "Road",
        "east": "staircase"
      },
      "asPerDocument": {
        "north": "",
        "west": "",
```

```
    "south": "",
    "east": ""
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
}
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "label": "Middle Class",
    "value": "Middle_Class"
  },
  "propertyTypeOfUseList": {
    "label": "Residential Purpose",
    "value": "Residential_Purpose"
  },
  "propertyOccupiedByList": {
    "label": "Tenant Occupied",
    "value": "Tenant_Occupied"
  },
  "monthlyRent": ""
},
"siteMeasurement": {
  "partitions": {
    "label": "6\" Thk. Brick Masonery",
    "value": "6\"_Thk._Brick_Masonery"
  },
  "waterTank": {
    "label": "Municipal Water Supply",
    "value": "MunicipalWaterSupply"
  },
  "pavementLaid": {
    "label": "Yes",
    "value": "Yes"
  },
  "carParking": {
    "label": "Open Car Parking Space",
    "value": "Open_Car_Parking_Space"
  },
  "constructionWorkStatus": {
    "label": "Completed",
    "value": "Completed"
  },
}
```

```
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2008",
  "fullDate": "1/1/2008"
},
"propertyTypeList": {
  "label": "Residential",
  "value": "Residential"
},
"planningArea": {
  "label": "Residential",
  "value": "Residential"
},
"typeOfStructure": {
  "label": "R.C.C. Framed",
  "value": "R.C.C."
},
"qualityOfConstruction": {
  "label": "Good",
  "value": "Good"
},
"walls": {
  "label": "Yes",
  "value": "1"
},
"appearanceOfTheBuilding": {
  "label": "Good",
  "value": "Good"
},
"maintenanceOfTheBuilding": {
  "label": "Good",
  "value": "Good"
},
"visibleDamageInBuilding": {
  "label": "No",
  "value": "0"
},
"groundStilt": {
  "label": "Part Ground + Part Stilt",
  "value": "Part_Ground_and_Part_Stilt"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "44",
"ageOfBuilding": "16",
```

```
"noOfBasement": "0",
"noOfPodium": "0",
"noOfAmenityFloors": "0",
"noOfFloors": "04",
"flatFloorNo": "",
"noOfLifts": "0",
"noOfLiftsInEachWings": "0",
"noOfDwellingUnitsInBuilding": "04"
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
}
```

```
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
  }
}
```



```
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
```

```
"value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
"invoices": [],
"paymentIds": [],
"_id": "65e86c4bf9222577acbda30b",
"ownerName": "Sunita Nilesh Ithape",
"ownerPhoneNo": "9224773885",
"appAddress": "Flat no. 304, 3rd Floor, Wing - B, Gangadhar Complex CHS, Plot no.
03, sector no. 07, Kamothe, Panvel",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": " Agreement",
      "value": "652d16a0316e1359cebd3c15"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/65e86c4bf9222577acbda30b/
document_1709730880427_1709731049025_CamScanner_03062024_170518.pdf",
    "fileName":
"document_1709730880427_1709731049025_CamScanner_03062024_170518.pdf",
    "id": "134411",
    "uploadedBy": "60b7177d2ffdf65bcd65882a",
    "createdAt": "Wed Mar 06 2024 18:44:51 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "007527",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "561339",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Mar 06 2024 18:44:51 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
```

```
"name": "Sunita Nilesh Ithape",
"phone": "9224773885",
"ownershipShare": "",
"email": "",
"id": "407717"
}
],
"proposePurchasers": [],
"siteInspection": [
{
"areaType": {
"label": "Carpet",
"value": "Carpet"
},
"providedBy": {
"label": "Owner",
"value": "Owner"
},
}_id": "65ee72e3857bdc098a985385",
"area": "0",
"providedByName": "Sunita Nilesh Ithape",
"providedByContactNo": "9224773885"
},
{
"areaType": {
"label": "Carpet",
"value": "Carpet"
},
"providedBy": {
"label": "Owner",
"value": "Owner"
},
}_id": "65ee72e3857bdc098a985386",
"area": "245",
"providedByName": "Sunita Nilesh Ithape",
"providedByContactNo": "9224773885"
},
{
"areaType": {
"label": "Carpet",
"value": "Carpet"
},
"providedBy": {
"label": "Owner",
"value": "Owner"
},
}
```

```
    "_id": "65ee72e3857bdc098a985387",
    "area": "245",
    "providedByName": "Sunita Nilesh Ithape",
    "providedByContactNo": "9224773885"
  }
],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65ee71ce857bdc098a9852a2",
    "name": "externallmg_1710125515799_1710125687886_image_0.jpeg",
    "path": "cases/65e86c4bf9222577acbda30b/
externallmg_1710125515799_1710125687886_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65ee71ce857bdc098a9852a3",
    "name": "externallmg_1710125516964_1710125687886_image_1.jpeg",
    "path": "cases/65e86c4bf9222577acbda30b/
externallmg_1710125516964_1710125687886_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65ee71ce857bdc098a9852a4",
    "name": "externallmg_1710125517389_1710125687886_image_2.jpeg",
    "path": "cases/65e86c4bf9222577acbda30b/
externallmg_1710125517389_1710125687886_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65ee71a2857bdc098a98526d",
    "name": "externallmg_1710125471658_1710125643764_image_0.jpeg",
    "path": "cases/65e86c4bf9222577acbda30b/
externallmg_1710125471658_1710125643764_image_0.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "65ee71a2857bdc098a98526e",
  "name": "externallmg_1710125473245_1710125643764_image_1.jpeg",
  "path": "cases/65e86c4bf9222577acbda30b/
externallmg_1710125473245_1710125643764_image_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "65ee71a2857bdc098a98526f",
  "name": "externallmg_1710125474566_1710125643764_image_2.jpeg",
  "path": "cases/65e86c4bf9222577acbda30b/
externallmg_1710125474566_1710125643764_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "65ee71ba857bdc098a985286",
  "name": "externallmg_1710125495509_1710125667978_image_0.jpeg",
  "path": "cases/65e86c4bf9222577acbda30b/
externallmg_1710125495509_1710125667978_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "65ee71ba857bdc098a985287",
  "name": "externallmg_1710125496669_1710125667978_image_1.jpeg",
  "path": "cases/65e86c4bf9222577acbda30b/
externallmg_1710125496669_1710125667978_image_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "65ee71ba857bdc098a985288",
  "name": "externallmg_1710125497109_1710125667978_image_2.jpeg",
  "path": "cases/65e86c4bf9222577acbda30b/
externallmg_1710125497109_1710125667978_image_2.jpeg",
  "orientation": "portrait"
}
```

```

    }
  ],
  "externalDocuments": [],
  "processingDocuments": [],
  "leadRemarks": [],
  "audioRemarks": [],
  "remarks": [],
  "createdAt": "2024-03-06T13:14:52.011Z",
  "updatedAt": "2024-03-11T03:00:05.152Z",
  "__v": 0,
  "assignmentType": {
    "value": "Retail",
    "label": "Retail"
  },
  },
  "fullAddress": "Residential Flat No. 304, 3rd Floor, Wing - B, Gangadhar Complex
CHSL, Plot No. 3, Sector 7, Village - Kamothe, Navi Mumbai",
  "updatedBy": "60f9343b45132d6a6bdd96e8",
  "addressForMap": "",
  "caseReferredBy": "",
  "contactPersonName": "Sunita Nilesh Ithape",
  "email": "",
  "isExternal": "false",
  "isUrgent": "false",
  "ownershipShare": "",
  "proposePurchaserName": "",
  "purchaseValueAsPerDocument": "",
  "relationWithOwner": "self",
  "siteVisitContactNo": "9224773885"
}

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			