

```
{
  "typeOfReport": {
    "label": "Bungalow",
    "value": "Bungalow"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "652e3ee4316e1359cebed68e"
    },
    "type": "CREDITOFFICER",
    "_id": "652e3ee4316e1359cebed690",
    "firstName": "Siddharth",
    "lastName": "Jha",
    "mobileNo": "",
    "workMobileNo": "8657798653",
    "email": "brmgr1756@mahabank.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "70146500",
    "discussWithPerson": "Siddharth",
    "expectedFees": 35073.25,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180e",
  "type": "BANK",
  "name": "Bank Of Maharashtra",
  "displayName": "Bank Of Maharashtra",
  "initial": "BOM",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "652e3ee4316e1359cebed68e",
  "name": "Andheri East Seepz Branch",
  "branchCode": "1756",
  "mobileNo": "0000000000",
  "alternateMobileNo": "",
  "email": "brmgr1756@mahabank.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Shop No 4 & 5, Options PrimoBuilding , Plot no 21, MIDC Andheri East
Mumbai 400093"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "63abe77f4e30460e90087d32",
  "zoneName": "Mumbai City Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
  "_id": "60af6ae22ffdf65bcd65861d",
  "role": "PICKUPPERSON",
  "firstName": "Sunil",
  "email": "misalsunil87@gmail.com",
  "lastName": "Misal",
  "mobileNo": "8422982721",
  "shortName": "SM",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60af6ae22ffdf65bcd65861d\\
\\profilePhoto_1622701583996_WhatsApp Image 2021-06-03 at 11.43.11 AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62691c48afd7d55eddecfda3",
  "role": "SITEENGINEER+MAKAR",
  "firstName": "Bhavika",
  "email": "bhavikachavan0102@gmail.com",
  "lastName": "chavan",
  "mobileNo": "8390804382",
  "designation": "Site Engineer",
  "shortName": "BH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62691c48afd7d55eddecfda3/
profilePhoto_1668055228258_bhavika.jpeg"
},
"rateVerifier": null,
"maker": null,
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  "type": "EMPLOYEE",
  "_id": "5ffe92d27737ca4d986b6453",
  "role": "VALUER",
  "firstName": "Manoj",
  "email": "manoj@vastukala.org",
  "lastName": "Chalikwar",
  "mobileNo": "9819597579",
  "designation": "Registered Valuer",
  "registrationNo": [
    {
```

```
"title": {
  "label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
},
{
  "title": {
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.157515722732608",
```

```
"longitude": "72.84423313235818"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.84423313235818,
    19.157515722732608
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "7/03/2024 02:58 pm"
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": false,
    "name": "Village",
    "key": "village",
    "value": "",

```

```
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Ground",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
```

```
"name": "Plot No.",
"key": "plotNo",
"value": "",
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Goregaon Yashwant Nagar CHSL",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Yashwant Nagar",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
}
```

```
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
```



```
"key": "selectNo",
"value": "Bunglow No 19/75",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
}
```

```
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Goregaon West",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
```

```
"rccFootingFoundation": {
  "label": "RCC Footing/Foundation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"rccPlinth": {
  "label": "RCC Plinth",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
```

```
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "0",
"selectedBuildUpValue": "0",
"selectedBuildUpMeasurementType": ""
},
"reportImages": {
"frontPageImages": [],
"selfieWithSiteVisitImages": [],
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
"carpetRateRange": {
"min": "0.00",
"max": "0.00"
}
},
```

```
"builtUpRateRange": {
  "min": "0.00",
  "max": "0.00"
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
}
```

```
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
```

```
    "isEditable": false
  }
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"invoices": [],
"paymentIds": [],
"_id": "65e9763ff9222577acbe60cf",
"ownerName": "Sharda Mukund Tated ",
"ownerPhoneNo": "8657798653",
"appAddress": "Bungalow Tenement no 19 75 Goregoan Yeshwant Nagar CHS Ltd
Goregoan East 400062",
"remark": "Bank Manegar sir Visit la yenar ahe 2:00 to 2:30 la today ",
"documents": [
  {
    "documentType": {
      "label": "Deed Of Declaration",
      "value": "60ae1246aa6d152c1801b2e7"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/65e9763ff9222577acbe60cf/document_1709798712487_170979887
```



```
9900_Deed_of_Declaration_BOM_Sharda_Tated_Bungalow.pdf",
  "fileName": "document_1709798712487_1709798879900_Deed_of_Declaration_B
OM_Sharda_Tated_Bungalow.pdf",
  "id": "799360",
  "uploadedBy": "60af6ae22ffdf65bcd65861d",
  "createdAt": "Thu Mar 07 2024 13:39:35 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "label": "Previous Valuation Report",
    "value": "60ae1248aa6d152c1801b2ee"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/65e9763ff9222577acbe60cf/
document_1709798818062_1709798986479_Sharda_Tated_Valuation_report_1.pdf",
  "fileName":
"document_1709798818062_1709798986479_Sharda_Tated_Valuation_report_1.pdf",
  "id": "857024",
  "uploadedBy": "60af6ae22ffdf65bcd65861d",
  "createdAt": "Thu Mar 07 2024 13:39:35 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "007532",
"createdBy": "60af6ae22ffdf65bcd65861d",
"caseHistory": [
  {
    "id": "774349",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Mar 07 2024 13:39:35 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Sharda Mukund Tated ",
    "phone": "8657798653",
    "ownershipShare": "",
    "email": "",
    "id": "979359"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
```

```
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65eaed80f9222577acc13996",
    "name": "externalImg_1709895025421_1709895193516_image_0.jpeg",
    "path": "cases/65e9763ff9222577acbe60cf/
externalImg_1709895025421_1709895193516_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65eaed80f9222577acc13997",
    "name": "externalImg_1709895034187_1709895193520_image_1.jpeg",
    "path": "cases/65e9763ff9222577acbe60cf/
externalImg_1709895034187_1709895193520_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65eaed80f9222577acc13998",
    "name": "externalImg_1709895034459_1709895193520_image_2.jpeg",
    "path": "cases/65e9763ff9222577acbe60cf/
externalImg_1709895034459_1709895193520_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65eaed80f9222577acc13999",
    "name": "externalImg_1709895034872_1709895193520_image_3.jpeg",
    "path": "cases/65e9763ff9222577acbe60cf/
externalImg_1709895034872_1709895193520_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65eaed80f9222577acc1399a",
    "name": "externalImg_1709895034898_1709895193520_image_4.jpeg",
```

```
    "path": "cases/65e9763ff9222577acbe60cf/
externallmg_1709895034898_1709895193520_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65eaed80f9222577acc1399b",
    "name": "externallmg_1709895035161_1709895193521_image_5.jpeg",
    "path": "cases/65e9763ff9222577acbe60cf/
externallmg_1709895035161_1709895193521_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65eaed80f9222577acc1399c",
    "name": "externallmg_1709895035700_1709895193521_image_6.jpeg",
    "path": "cases/65e9763ff9222577acbe60cf/
externallmg_1709895035700_1709895193521_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65eaed80f9222577acc1399d",
    "name": "externallmg_1709895035859_1709895193521_image_7.jpeg",
    "path": "cases/65e9763ff9222577acbe60cf/
externallmg_1709895035859_1709895193521_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65eaed80f9222577acc1399e",
    "name": "externallmg_1709895036438_1709895193521_image_8.jpeg",
    "path": "cases/65e9763ff9222577acbe60cf/
externallmg_1709895036438_1709895193521_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65eaed80f9222577acc1399f",
    "name": "externallmg_1709895036669_1709895193521_image_9.jpeg",
    "path": "cases/65e9763ff9222577acbe60cf/
externallmg_1709895036669_1709895193521_image_9.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65eaed80f9222577acc139a0",
  "name": "externallmg_1709895037038_1709895193521_image_10.jpeg",
  "path": "cases/65e9763ff9222577acbe60cf/
externallmg_1709895037038_1709895193521_image_10.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65eaed80f9222577acc139a1",
  "name": "externallmg_1709895037168_1709895193521_image_11.jpeg",
  "path": "cases/65e9763ff9222577acbe60cf/
externallmg_1709895037168_1709895193521_image_11.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65eaed80f9222577acc139a2",
  "name": "externallmg_1709895037715_1709895193521_image_12.jpeg",
  "path": "cases/65e9763ff9222577acbe60cf/
externallmg_1709895037715_1709895193521_image_12.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65eaed80f9222577acc139a3",
  "name": "externallmg_1709895037862_1709895193521_image_13.jpeg",
  "path": "cases/65e9763ff9222577acbe60cf/
externallmg_1709895037862_1709895193521_image_13.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65eaed80f9222577acc139a4",
  "name": "externallmg_1709895038104_1709895193521_image_14.jpeg",
  "path": "cases/65e9763ff9222577acbe60cf/
externallmg_1709895038104_1709895193521_image_14.jpeg",
  "orientation": "portrait"
}
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65eaed80f9222577acc139a5",
  "name": "externallmg_1709895038312_1709895193521_image_15.jpeg",
  "path": "cases/65e9763ff9222577acbe60cf/
externallmg_1709895038312_1709895193521_image_15.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65eaed80f9222577acc139a6",
  "name": "externallmg_1709895038998_1709895193521_image_16.jpeg",
  "path": "cases/65e9763ff9222577acbe60cf/
externallmg_1709895038998_1709895193521_image_16.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65eaed80f9222577acc139a7",
  "name": "externallmg_1709895039281_1709895193521_image_17.jpeg",
  "path": "cases/65e9763ff9222577acbe60cf/
externallmg_1709895039281_1709895193521_image_17.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65eaed80f9222577acc139a8",
  "name": "externallmg_1709895039682_1709895193521_image_18.jpeg",
  "path": "cases/65e9763ff9222577acbe60cf/
externallmg_1709895039682_1709895193521_image_18.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65eaed80f9222577acc139a9",
  "name": "externallmg_1709895040176_1709895193521_image_19.jpeg",
  "path": "cases/65e9763ff9222577acbe60cf/
externallmg_1709895040176_1709895193521_image_19.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "65eaed63f9222577acc13889",
  "name": "externallmg_1709894998718_1709895127309_image_0.jpeg",
  "path": "cases/65e9763ff9222577acbe60cf/
externallmg_1709894998718_1709895127309_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "65eaed63f9222577acc1388a",
  "name": "externallmg_1709894999796_1709895127312_image_1.jpeg",
  "path": "cases/65e9763ff9222577acbe60cf/
externallmg_1709894999796_1709895127312_image_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "65eaed63f9222577acc1388b",
  "name": "externallmg_1709895000339_1709895127312_image_2.jpeg",
  "path": "cases/65e9763ff9222577acbe60cf/
externallmg_1709895000339_1709895127312_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "65eaed63f9222577acc1388c",
  "name": "externallmg_1709895000637_1709895127312_image_3.jpeg",
  "path": "cases/65e9763ff9222577acbe60cf/
externallmg_1709895000637_1709895127312_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "65eaed63f9222577acc1388d",
  "name": "externallmg_1709895001764_1709895127312_image_4.jpeg",
  "path": "cases/65e9763ff9222577acbe60cf/
externallmg_1709895001764_1709895127312_image_4.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65eaed63f9222577acc1388e",
    "name": "externallmg_1709895002418_1709895127312_image_5.jpeg",
    "path": "cases/65e9763ff9222577acbe60cf/
externallmg_1709895002418_1709895127312_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65eaed63f9222577acc1388f",
    "name": "externallmg_1709895003182_1709895127312_image_6.jpeg",
    "path": "cases/65e9763ff9222577acbe60cf/
externallmg_1709895003182_1709895127312_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65eaed63f9222577acc13890",
    "name": "externallmg_1709895003962_1709895127312_image_7.jpeg",
    "path": "cases/65e9763ff9222577acbe60cf/
externallmg_1709895003962_1709895127312_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65eaed63f9222577acc13891",
    "name": "externallmg_1709895004034_1709895127312_image_8.jpeg",
    "path": "cases/65e9763ff9222577acbe60cf/
externallmg_1709895004034_1709895127312_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65eaed63f9222577acc13892",
    "name": "externallmg_1709895004209_1709895127312_image_9.jpeg",
    "path": "cases/65e9763ff9222577acbe60cf/
externallmg_1709895004209_1709895127312_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
```

```
"status": false,
  "_id": "65eaed63f9222577acc13893",
  "name": "externalimg_1709895004453_1709895127312_image_10.jpeg",
  "path": "cases/65e9763ff9222577acbe60cf/
externalimg_1709895004453_1709895127312_image_10.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "65eaed63f9222577acc13894",
  "name": "externalimg_1709895004652_1709895127312_image_11.jpeg",
  "path": "cases/65e9763ff9222577acbe60cf/
externalimg_1709895004652_1709895127312_image_11.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "65eaed63f9222577acc13895",
  "name": "externalimg_1709895005302_1709895127312_image_12.jpeg",
  "path": "cases/65e9763ff9222577acbe60cf/
externalimg_1709895005302_1709895127312_image_12.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "65eaed63f9222577acc13896",
  "name": "externalimg_1709895006205_1709895127312_image_13.jpeg",
  "path": "cases/65e9763ff9222577acbe60cf/
externalimg_1709895006205_1709895127312_image_13.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "65eaed63f9222577acc13897",
  "name": "externalimg_1709895006342_1709895127312_image_14.jpeg",
  "path": "cases/65e9763ff9222577acbe60cf/
externalimg_1709895006342_1709895127312_image_14.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
```



```
    "_id": "65eaed63f9222577acc13898",
    "name": "externallmg_1709895006705_1709895127312_image_15.jpeg",
    "path": "cases/65e9763ff9222577acbe60cf/
externallmg_1709895006705_1709895127312_image_15.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65eaed63f9222577acc13899",
    "name": "externallmg_1709895007231_1709895127312_image_16.jpeg",
    "path": "cases/65e9763ff9222577acbe60cf/
externallmg_1709895007231_1709895127312_image_16.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65eaed63f9222577acc1389a",
    "name": "externallmg_1709895007717_1709895127313_image_17.jpeg",
    "path": "cases/65e9763ff9222577acbe60cf/
externallmg_1709895007717_1709895127313_image_17.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65eaed63f9222577acc1389b",
    "name": "externallmg_1709895007977_1709895127313_image_18.jpeg",
    "path": "cases/65e9763ff9222577acbe60cf/
externallmg_1709895007977_1709895127313_image_18.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65eaed63f9222577acc1389c",
    "name": "externallmg_1709895008520_1709895127313_image_19.jpeg",
    "path": "cases/65e9763ff9222577acbe60cf/
externallmg_1709895008520_1709895127313_image_19.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65eaeda0f9222577acc13abf",
```

```
    "name": "externallmg_1709895066960_1709895229815_image_0.jpeg",
    "path": "cases/65e9763ff9222577acbe60cf/
externallmg_1709895066960_1709895229815_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65eaeda0f9222577acc13ac0",
    "name": "externallmg_1709895067215_1709895229817_image_1.jpeg",
    "path": "cases/65e9763ff9222577acbe60cf/
externallmg_1709895067215_1709895229817_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65eaeda0f9222577acc13ac1",
    "name": "externallmg_1709895067668_1709895229818_image_2.jpeg",
    "path": "cases/65e9763ff9222577acbe60cf/
externallmg_1709895067668_1709895229818_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65eaeda0f9222577acc13ac2",
    "name": "externallmg_1709895068204_1709895229818_image_3.jpeg",
    "path": "cases/65e9763ff9222577acbe60cf/
externallmg_1709895068204_1709895229818_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65eaeda0f9222577acc13ac3",
    "name": "externallmg_1709895068871_1709895229818_image_4.jpeg",
    "path": "cases/65e9763ff9222577acbe60cf/
externallmg_1709895068871_1709895229818_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65eaeda0f9222577acc13ac4",
    "name": "externallmg_1709895069270_1709895229818_image_5.jpeg",
```

```
    "path": "cases/65e9763ff9222577acbe60cf/
externalImg_1709895069270_1709895229818_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65eaeda0f9222577acc13ac5",
    "name": "externalImg_1709895069730_1709895229818_image_6.jpeg",
    "path": "cases/65e9763ff9222577acbe60cf/
externalImg_1709895069730_1709895229818_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65eaeda0f9222577acc13ac6",
    "name": "externalImg_1709895071373_1709895229818_image_7.jpeg",
    "path": "cases/65e9763ff9222577acbe60cf/
externalImg_1709895071373_1709895229818_image_7.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-03-07T08:09:35.267Z",
"updatedAt": "2024-03-08T10:51:12.457Z",
"__v": 0,
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"fullAddress": "Residential Bungalow No. Bunglow No 19/75, Ground Floor, Goregaon
Yashwant Nagar CHSL, Yashwant Nagar, Goregaon West, Mumbai",
"updatedBy": "62691c48afd7d55eddecfda3",
"addressForMap": "",
"caseReferredBy": "60af6ae22ffdf65bcd65861d",
"contactPersonName": "Sharda Mukund Tated ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": ""
```

"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "8657798653"

}

Name	Length	Width	Total
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			