

```
{
  "typeOfReport": {
    "value": "Unit",
    "label": "Unit"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": "",
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "6418456a96b58848585f8cb2",
    "name": "Thane",
    "email": "thane@vastukala.com",
    "phone": "1234567890",
    "address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
    "city": "Thane",
    "shortName": "VCIPL/Thane"
  },
  "client": {
```

```
"_id": "65d6d6a9cf7ad63a0afa52a7",
"type": "PRIVATE_CLIENT",
"name": "Maharashtra State Corporation Cotton Grains Marketing Federation
Limited",
"displayName": "Maharashtra State Corporation Cotton Grains Marketing Federation
Limited",
"initial": "M"
},
"branch": "",
"assetsClass": {
"value": "Land_&_Building_/_Immovable_Property",
"label": "Land & Building / Immovable Property"
},
"propertyType": {
"label": "Commercial",
"value": "Commercial"
},
"zone": "",
"staff": {
"pickupPerson": {
"type": "EMPLOYEE",
"_id": "656aa949cebbe1714411d21b",
"role": "FRONTDESK",
"firstName": "Priyanka",
"email": "thane@vastukala.org",
"lastName": "Pawar",
"mobileNo": "8928414480",
"shortName": "PCP",
"workWithDocumentMaker": "627222afafd7d55eddeddd82"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "62720e52afd7d55eddedc887",
"role": "PICKUPPERSON",
"firstName": "Harshad",
"email": "harshad@vastukala.org",
"lastName": "Panchal",
"mobileNo": "9029575553",
"designation": "",
"shortName": "HP",
"workWithDocumentMaker": ""
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "62720b21afd7d55eddedc545",
"role": "MAKER+CHECKER",
```

```
"firstName": "Avinash",
"email": "avinash.pandey@vastukala.org",
"lastName": "Pandey",
"mobileNo": "9021605621",
"designation": "",
"shortName": "AV",
"workWithDocumentMaker": ""
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "62720b21afd7d55eddedc545",
  "role": "MAKER+CHECKER",
  "firstName": "Avinash",
  "email": "avinash.pandey@vastukala.org",
  "lastName": "Pandey",
  "mobileNo": "9021605621",
  "designation": "",
  "shortName": "AV",
  "workWithDocumentMaker": ""
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "62720b21afd7d55eddedc545",
  "role": "MAKER+CHECKER",
  "firstName": "Avinash",
  "email": "avinash.pandey@vastukala.org",
  "lastName": "Pandey",
  "mobileNo": "9021605621",
  "designation": "",
  "shortName": "AV",
  "workWithDocumentMaker": ""
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  {
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
  }
]
```

```
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "PRIVATE_CLIENT",
```

```
"label": "Private Clients"
},
"location": {
  "latitude": "18.9874330636814",
  "longitude": "72.8443052781133"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": false,
    "name": "Village",
    "key": "village",
    "value": "",

```

```
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "2",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Cotton Green (East)",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
```

```
"name": "Plot No.",
"key": "plotNo",
"value": "",
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Cotton Exchange of India",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Cotton Green Railway Station",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Zakaria Bunder Road",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
}
```

```
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
```



```
"key": "selectNo",
"value": "Unit No. B-116",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
}
```

```
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 400 033",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
```

```
"rccFootingFoundation": {
  "label": "RCC Footing/Foundation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"rccPlinth": {
  "label": "RCC Plinth",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
```

```
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "0",
"selectedBuildUpValue": "0",
"selectedBuildUpMeasurementType": ""
},
"reportImages": {
"frontPageImages": [],
"selfieWithSiteVisitImages": [],
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
"carpetRateRange": {
"min": "0.00",
"max": "0.00"
}
},
```

```
"builtUpRateRange": {
  "min": "0.00",
  "max": "0.00"
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
}
```

```
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
```

```
"isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"invoices": [],
"paymentIds": [],
"_id": "65ec0f6ef9222577acc27dc5",
"ownerName": "Maharashtra State Corporation Cotton Grains Marketing Federation Limited",
"ownerPhoneNo": "0000000000",
"fullAddress": "Residential Unit No. Unit No. B-116, 2nd Floor, Cotton Exchange of India, Zakaria Bunder Road, Cotton Green Railway Station, District - Mumbai, Cotton Green (East), PIN Code - 400 033",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae1248aa6d152c1801b2ee",
      "label": "Previous Valuation Report"
    }
  },
  "isHardCopy": false,
```



```
    "displayStatus": false,
    "fileName":
"document_1709969256572_Final__Cotton_Exchange_off_India__116.pdf",
    "path": "cases/65ec0f6ef9222577acc27dc5/
document_1709969256572_Final__Cotton_Exchange_off_India__116.pdf",
    "id": "723972",
    "uploadedBy": "656aa949cebbe1714411d21b",
    "createdAt": "Sat Mar 09 2024 12:57:41 GMT+0530 (India Standard Time)"
  }
],
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"caseNumber": "007571",
"createdBy": "656aa949cebbe1714411d21b",
"caseHistory": [
  {
    "id": "371515",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Sat Mar 09 2024 12:57:42 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Maharashtra State Corporation Cotton Grains Marketing Federation
Limited",
    "phone": "0000000000",
    "ownershipShare": "",
    "email": "",
    "id": "473640"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,

```

```
    "_id": "65ee9028857bdc098a988608",
    "name": "externalimg_1710133287835_9b50aca739fe47fcbe266dc7a9ea2ccc.jpg",
    "path": "cases/65ec0f6ef9222577acc27dc5/
externalimg_1710133287835_9b50aca739fe47fcbe266dc7a9ea2ccc.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65ee9028857bdc098a988609",
    "name":
"externalimg_1710133287843_WhatsApp_Image_20240202_at_55229_PM.jpeg",
    "path": "cases/65ec0f6ef9222577acc27dc5/
externalimg_1710133287843_WhatsApp_Image_20240202_at_55229_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65ee9028857bdc098a98860a",
    "name":
"externalimg_1710133287873_WhatsApp_Image_20240202_at_55230_PM_1.jpeg",
    "path": "cases/65ec0f6ef9222577acc27dc5/
externalimg_1710133287873_WhatsApp_Image_20240202_at_55230_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65ee9028857bdc098a98860b",
    "name":
"externalimg_1710133287903_WhatsApp_Image_20240202_at_55230_PM.jpeg",
    "path": "cases/65ec0f6ef9222577acc27dc5/
externalimg_1710133287903_WhatsApp_Image_20240202_at_55230_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65ee9028857bdc098a98860c",
    "name":
"externalimg_1710133287929_WhatsApp_Image_20240202_at_55726_PM.jpeg",
    "path": "cases/65ec0f6ef9222577acc27dc5/
externalimg_1710133287929_WhatsApp_Image_20240202_at_55726_PM.jpeg",
    "orientation": "portrait"
  },
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65ee9028857bdc098a98860d",
  "name":
"externallmg_1710133287949_WhatsApp_Image_20240202_at_55727_PM_1.jpeg",
  "path": "cases/65ec0f6ef9222577acc27dc5/
externallmg_1710133287949_WhatsApp_Image_20240202_at_55727_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65ee9028857bdc098a98860e",
  "name":
"externallmg_1710133287965_WhatsApp_Image_20240202_at_55727_PM.jpeg",
  "path": "cases/65ec0f6ef9222577acc27dc5/
externallmg_1710133287965_WhatsApp_Image_20240202_at_55727_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65ee9028857bdc098a98860f",
  "name":
"externallmg_1710133287983_WhatsApp_Image_20240202_at_55728_PM_1.jpeg",
  "path": "cases/65ec0f6ef9222577acc27dc5/
externallmg_1710133287983_WhatsApp_Image_20240202_at_55728_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65ee9028857bdc098a988610",
  "name":
"externallmg_1710133287999_WhatsApp_Image_20240202_at_55728_PM_2.jpeg",
  "path": "cases/65ec0f6ef9222577acc27dc5/
externallmg_1710133287999_WhatsApp_Image_20240202_at_55728_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65ee9028857bdc098a988611",
  "name":
"externallmg_1710133288017_WhatsApp_Image_20240202_at_55728_PM.jpeg",
```

```

    "path": "cases/65ec0f6ef9222577acc27dc5/
externallmg_1710133288017_WhatsApp_Image_20240202_at_55728_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65ee9028857bdc098a988612",
    "name":
"externallmg_1710133288033_WhatsApp_Image_20240202_at_55729_PM.jpeg",
    "path": "cases/65ec0f6ef9222577acc27dc5/
externallmg_1710133288033_WhatsApp_Image_20240202_at_55729_PM.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-03-09T07:27:42.073Z",
"updatedAt": "2024-03-11T05:01:28.128Z",
"__v": 0,
"updatedBy": "656aa949cebbe1714411d21b",
"addressForMap": "",
"caseReferredBy": "62720b21afd7d55eddedc545",
"contactPersonName": "Maharashtra State Corporation Cotton Grains Marketing
Federation Limited",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "0000000000"
}

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			