

```
{
  "typeOfReport": {
    "label": "Unit",
    "value": "Unit"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b99c"
    },
    "type": "CREDITOFFICER",
    "_id": "65000e71a8e9b70221dfa1f3",
    "firstName": "Lalita ",
    "lastName": "Madam",
    "mobileNo": "",
    "workMobileNo": "9820287285",
    "email": "Lalita@cosmosbank.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "6545685",
    "discussWithPerson": "Lalita ",
    "expectedFees": 3272.8425,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1820",
  "type": "BANK",
  "name": "Cosmos Bank",
  "displayName": "Cosmos Bank",
  "initial": "CB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b99c",
  "branchCode": "000011",
  "type": "BRANCH",
  "name": "Dadar Branch ",
  "email": "dadar@cosmosbank.in",
  "mobileNo": "02224476018",
  "alternateMobileNo": "8369167372",
  "address": "Horizon Bldg.,1st Floor, Ranade Road & Gokhale Road, Dadar (West),
Mumbai - 400 028, State - Maharashtra, Country - India.",
  "ledgerName": "COSMOS BANK - DADAR",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f919bff3dd69653a5926b8",
  "zoneName": "Mumbai & Aurangabad Zone"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "62723addafd7d55eddeddfe4",
  "role": "PICKUPPERSON",
  "firstName": "Ramkrishna ",
  "email": "rampatakar1991@gmail.com",
  "lastName": "Patkar",
  "mobileNo": "7045746060",
  "shortName": "RP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62723addafd7d55eddeddfe4/
profilePhoto_1668056044525_WhatsApp_Image_20221110_at_102139_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62ea09ea4e679b264caf07d7",
  "role": "SITEENGINEER",
  "firstName": "Suraj",
  "email": "suraj@vastukala.org",
  "lastName": "Zore",
  "mobileNo": "8652448654",
  "designation": "",
  "shortName": "SZ",
  "workWithDocumentMaker": "60092304a16fab0f2af9b0c2",
  "profilePhoto": "users/62ea09ea4e679b264caf07d7/
profilePhoto_1685629394240_image.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": "",
  "shortName": "SK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\
profilePhoto_1626255068979_Shym_Photo.jpg"
},
"maker": null,
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
```

```
    "value": "IBBI/RV/07/2018/10366",
    "label": "Registered Valuer"
  }
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
```

```
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
    "PANNo": "AERPC9086P",
    "fatherName": "Baburao"
  }
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.29686236260167",
  "longitude": "73.04233801381082"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.04233801381082,
    19.29686236260167
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "13/03/2024 06:10 pm"
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
```

```
"label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Val",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Ground",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Bhiwandi",
  "label": false
},
"tahsilNo": {
  "status": false,
```

```
"name": "Tahasil",
"key": "tahasilNo",
"value": "",
"label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Krishna Complex",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
}
```

```
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
```



```
"key": "CTSNo",
"value": "",
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "1,2,3,4,5,6",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
```

```
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Bhiwandi",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
}
```

```
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
```

```
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "0",
"selectedBuildUpValue": "0",
"selectedBuildUpMeasurementType": ""
```

```
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
}
```

```
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"invoices": [],
"paymentIds": [],
"_id": "65f193f5857bdc098a9d8b21",
```



```
"ownerName": "Rajesh Nanalal Shah ",
"ownerPhoneNo": "7506445515",
"appAddress": "Bhiwandi location \nkrishna complex - Bldg no - 0, Godown no - 1 to 6",
"remark": "urgent basis\ncontact - Bharat ",
"documents": [
  {
    "documentType": {
      "label": "Any Other Document",
      "value": "60ae124aaa6d152c1801b2f7"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/65f193f5857bdc098a9d8b21/
document_1710330831639_1710331004645_O__123456_URO.pdf",
    "fileName": "document_1710330831639_1710331004645_O__123456_URO.pdf",
    "id": "981759",
    "uploadedBy": "62723addafd7d55eddeddfe4",
    "createdAt": "Wed Mar 13 2024 17:24:29 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "007658",
"createdBy": "62723addafd7d55eddeddfe4",
"caseHistory": [
  {
    "id": "269436",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Mar 13 2024 17:24:29 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Rajesh Nanalal Shah ",
    "phone": "7506445515",
    "ownershipShare": "",
    "email": "",
    "id": "902067"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
```

```
"indicatorArr": [],
"externalImages": [
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65f2e721857bdc098a9f92ef",
    "name": "externalimg_r_1710417693759_1710417870056_image_1.png",
    "path": "cases/65f193f5857bdc098a9d8b21/
externalimg_r_1710417693759_1710417870056_image_1.png",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65f2e721857bdc098a9f92f0",
    "name": "externalimg_r_1710417692991_1710417870056_image_0.jpg",
    "path": "cases/65f193f5857bdc098a9d8b21/
externalimg_r_1710417692991_1710417870056_image_0.jpg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65f2e721857bdc098a9f92f1",
    "name": "externalimg_r_1710417694563_1710417870056_image_2.jpg",
    "path": "cases/65f193f5857bdc098a9d8b21/
externalimg_r_1710417694563_1710417870056_image_2.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f2e775857bdc098a9f94e2",
    "name": "externalimg_r_1710417750284_1710417895660_image_1.jpg",
    "path": "cases/65f193f5857bdc098a9d8b21/
externalimg_r_1710417750284_1710417895660_image_1.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f2e775857bdc098a9f94e3",
    "name": "externalimg_r_1710417748440_1710417895660_image_0.jpg",
    "path": "cases/65f193f5857bdc098a9d8b21/
externalimg_r_1710417748440_1710417895660_image_0.jpg",
    "orientation": "portrait"
  }
]
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "65f2e775857bdc098a9f94e4",
      "name": "externallmg_r_1710417754607_1710417895660_image_3.jpg",
      "path": "cases/65f193f5857bdc098a9d8b21/
externallmg_r_1710417754607_1710417895660_image_3.jpg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "65f2e775857bdc098a9f94e5",
      "name": "externallmg_r_1710417752493_1710417895660_image_2.jpg",
      "path": "cases/65f193f5857bdc098a9d8b21/
externallmg_r_1710417752493_1710417895660_image_2.jpg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "65f2e775857bdc098a9f94e6",
      "name": "externallmg_r_1710417756801_1710417895660_image_4.jpg",
      "path": "cases/65f193f5857bdc098a9d8b21/
externallmg_r_1710417756801_1710417895660_image_4.jpg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "65f2e775857bdc098a9f94e7",
      "name": "externallmg_r_1710417757975_1710417895660_image_5.jpg",
      "path": "cases/65f193f5857bdc098a9d8b21/
externallmg_r_1710417757975_1710417895660_image_5.jpg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "65f2e775857bdc098a9f94e8",
      "name": "externallmg_r_1710417760917_1710417895660_image_7.jpg",
      "path": "cases/65f193f5857bdc098a9d8b21/
externallmg_r_1710417760917_1710417895660_image_7.jpg",
      "orientation": "portrait"
    },
  },
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65f2e775857bdc098a9f94e9",
  "name": "externallmg_r_1710417759405_1710417895660_image_6.jpg",
  "path": "cases/65f193f5857bdc098a9d8b21/
externallmg_r_1710417759405_1710417895660_image_6.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65f2e775857bdc098a9f94ea",
  "name": "externallmg_r_1710417762279_1710417895660_image_8.jpg",
  "path": "cases/65f193f5857bdc098a9d8b21/
externallmg_r_1710417762279_1710417895660_image_8.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65f2e775857bdc098a9f94eb",
  "name": "externallmg_r_1710417764812_1710417895660_image_10.jpg",
  "path": "cases/65f193f5857bdc098a9d8b21/
externallmg_r_1710417764812_1710417895660_image_10.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65f2e775857bdc098a9f94ec",
  "name": "externallmg_r_1710417766739_1710417895660_image_11.jpg",
  "path": "cases/65f193f5857bdc098a9d8b21/
externallmg_r_1710417766739_1710417895660_image_11.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65f2e775857bdc098a9f94ed",
  "name": "externallmg_r_1710417763390_1710417895660_image_9.jpg",
  "path": "cases/65f193f5857bdc098a9d8b21/
externallmg_r_1710417763390_1710417895660_image_9.jpg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f2e775857bdc098a9f94ee",
    "name": "externallmg_r_1710417767947_1710417895660_image_12.jpg",
    "path": "cases/65f193f5857bdc098a9d8b21/
externallmg_r_1710417767947_1710417895660_image_12.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f2e775857bdc098a9f94ef",
    "name": "externallmg_r_1710417770225_1710417895660_image_14.jpg",
    "path": "cases/65f193f5857bdc098a9d8b21/
externallmg_r_1710417770225_1710417895660_image_14.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f2e775857bdc098a9f94f0",
    "name": "externallmg_r_1710417768907_1710417895660_image_13.jpg",
    "path": "cases/65f193f5857bdc098a9d8b21/
externallmg_r_1710417768907_1710417895660_image_13.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f2e775857bdc098a9f94f1",
    "name": "externallmg_r_1710417771368_1710417895660_image_15.jpg",
    "path": "cases/65f193f5857bdc098a9d8b21/
externallmg_r_1710417771368_1710417895660_image_15.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f2e775857bdc098a9f94f2",
    "name": "externallmg_r_1710417772791_1710417895660_image_16.jpg",
    "path": "cases/65f193f5857bdc098a9d8b21/
externallmg_r_1710417772791_1710417895660_image_16.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "65f2e775857bdc098a9f94f3",
  "name": "externallmg_r_1710417775395_1710417895660_image_18.jpg",
  "path": "cases/65f193f5857bdc098a9d8b21/
externallmg_r_1710417775395_1710417895660_image_18.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65f2e775857bdc098a9f94f4",
  "name": "externallmg_r_1710417774051_1710417895660_image_17.jpg",
  "path": "cases/65f193f5857bdc098a9d8b21/
externallmg_r_1710417774051_1710417895660_image_17.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65f2e775857bdc098a9f94f5",
  "name": "externallmg_r_1710417777058_1710417895660_image_19.jpg",
  "path": "cases/65f193f5857bdc098a9d8b21/
externallmg_r_1710417777058_1710417895660_image_19.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65f2e7ef857bdc098a9f9693",
  "name": "externallmg_r_1710417877324_1710417979196_image_0.jpg",
  "path": "cases/65f193f5857bdc098a9d8b21/
externallmg_r_1710417877324_1710417979196_image_0.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65f2e7ef857bdc098a9f9694",
  "name": "externallmg_r_1710417879253_1710417979196_image_1.jpg",
  "path": "cases/65f193f5857bdc098a9d8b21/
externallmg_r_1710417879253_1710417979196_image_1.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "65f2e7ef857bdc098a9f9695",
    "name": "externallmg_r_1710417882155_1710417979196_image_3.jpg",
    "path": "cases/65f193f5857bdc098a9d8b21/
externallmg_r_1710417882155_1710417979196_image_3.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f2e7ef857bdc098a9f9696",
    "name": "externallmg_r_1710417880544_1710417979196_image_2.jpg",
    "path": "cases/65f193f5857bdc098a9d8b21/
externallmg_r_1710417880544_1710417979196_image_2.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f2e7ef857bdc098a9f9697",
    "name": "externallmg_r_1710417883902_1710417979196_image_4.jpg",
    "path": "cases/65f193f5857bdc098a9d8b21/
externallmg_r_1710417883902_1710417979196_image_4.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f2e7ef857bdc098a9f9698",
    "name": "externallmg_r_1710417885518_1710417979196_image_5.jpg",
    "path": "cases/65f193f5857bdc098a9d8b21/
externallmg_r_1710417885518_1710417979196_image_5.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f2e7ef857bdc098a9f9699",
    "name": "externallmg_r_1710417887128_1710417979196_image_6.jpg",
    "path": "cases/65f193f5857bdc098a9d8b21/
externallmg_r_1710417887128_1710417979196_image_6.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f2e7ef857bdc098a9f969a",
```

```
    "name": "externallmg_r_1710417888623_1710417979196_image_7.jpg",
    "path": "cases/65f193f5857bdc098a9d8b21/
externallmg_r_1710417888623_1710417979196_image_7.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f2e7ef857bdc098a9f969b",
    "name": "externallmg_r_1710417895821_1710417979196_image_10.jpg",
    "path": "cases/65f193f5857bdc098a9d8b21/
externallmg_r_1710417895821_1710417979196_image_10.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f2e7ef857bdc098a9f969c",
    "name": "externallmg_r_1710417895062_1710417979196_image_9.jpg",
    "path": "cases/65f193f5857bdc098a9d8b21/
externallmg_r_1710417895062_1710417979196_image_9.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f2e7ef857bdc098a9f969d",
    "name": "externallmg_r_1710417891193_1710417979196_image_8.jpg",
    "path": "cases/65f193f5857bdc098a9d8b21/
externallmg_r_1710417891193_1710417979196_image_8.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f2e7ef857bdc098a9f969e",
    "name": "externallmg_r_1710417896685_1710417979196_image_11.jpg",
    "path": "cases/65f193f5857bdc098a9d8b21/
externallmg_r_1710417896685_1710417979196_image_11.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f2e7ef857bdc098a9f969f",
    "name": "externallmg_r_1710417898236_1710417979196_image_12.jpg",
```



```
    "path": "cases/65f193f5857bdc098a9d8b21/
externallmg_r_1710417898236_1710417979196_image_12.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f2e7ef857bdc098a9f96a0",
    "name": "externallmg_r_1710417899049_1710417979196_image_13.jpg",
    "path": "cases/65f193f5857bdc098a9d8b21/
externallmg_r_1710417899049_1710417979196_image_13.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f2e7ef857bdc098a9f96a1",
    "name": "externallmg_r_1710417900153_1710417979196_image_14.jpg",
    "path": "cases/65f193f5857bdc098a9d8b21/
externallmg_r_1710417900153_1710417979196_image_14.jpg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-03-13T11:54:29.722Z",
"updatedAt": "2024-03-14T12:05:03.343Z",
"__v": 0,
"uniqueNo": "",
"updatedBy": "62ea09ea4e679b264caf07d7",
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Unit No. 1,2,3,4,5,6, Ground Floor, Krishna Complex,
Village - Val, Bhiwandi, Bhiwandi",
"addressForMap": "",
"caseReferredBy": "62723addafd7d55eddeddfe4",
"contactPersonName": "Rajesh Nanalal Shah ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": ""
```

"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "7506445515"

}

Name	Length	Width	Total
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			