

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "63638ca6e363ef22db2fb2c9"
    },
    "type": "CREDITOFFICER",
    "_id": "63d11f65be948726cc1419f5",
    "email": "bhiwandi.navimumbai@bankofindia.co.in",
    "firstName": "Mr. Snehal",
    "mobileNo": "91-7977133309",
    "workMobileNo": "7977133309",
    "lastName": "Snehal"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "6418456a96b58848585f8cb2",
  "name": "Thane",
  "email": "thane@vastukala.com",
  "phone": "1234567890",
  "address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
  "city": "Thane",
  "shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180a",
  "type": "BANK",
  "name": "Bank of India",
  "displayName": "Bank of India",
  "initial": "BOI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "63638ca6e363ef22db2fb2c9",
  "name": "Bhiwandi",
  "branchCode": "0075",
  "mobileNo": "2522225009",
  "alternateMobileNo": "",
  "email": "bhiwandi.navimumbai@bankofindia.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "255, Sonar Kasar Ali, Bhiwandi, Maharashtra Mumbai 421302\n"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e2f4b16576061dae469446",
  "zoneName": "Navi Mumbai Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
"_id": "64abdb2806d6ec174986d16b",
"role": "PICKUPPERSON",
"firstName": "Sahadu",
"email": "thoratsahadu8679@gmail.com",
"lastName": "Thorat",
"mobileNo": "9422389642",
"shortName": "ST",
"workWithDocumentMaker": ""
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62ea09ea4e679b264caf07d7",
  "role": "SITEENGINEER",
  "firstName": "Suraj",
  "email": "suraj@vastukala.org",
  "lastName": "Zore",
  "mobileNo": "8652448654",
  "designation": "",
  "shortName": "SZ",
  "workWithDocumentMaker": "60092304a16fab0f2af9b0c2",
  "profilePhoto": "users/62ea09ea4e679b264caf07d7/
profilePhoto_1685629394240_image.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": "",
  "shortName": "SK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Shyan_Photo.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627222afafd7d55eddeddd82",
  "role": "FRONTDESK",
  "firstName": "Pratibha",
  "email": "shilvanta_pratibha@yahoo.co.in",
  "lastName": "Shilvantha",
  "mobileNo": "9821518537",
  "designation": "",
```

```
"shortName": "PS",
"workWithDocumentMaker": "60f915d3f3dd69653a592199",
"profilePhoto": "users/627222afafd7d55eddeddd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
"checker": null,
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
},
{
"title": {
"value": "FIIV",
"label": "FIIV"
},
"_id": "60af80072ffdf65bcd658652",
"number": "CAT-I-F-1763"
},
{
"title": {
"value": "Chartered_Engineer",
"label": "Chartered Engineer"
},
"_id": "60af80072ffdf65bcd658653",
"number": "AM161706-3"
},
}
```

```
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
},
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.27763768868079",
  "longitude": "73.04861891240668"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "14/03/2024 01:12 pm"
    }
  ]
},
"visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
```

```
"finalAreaType": "Built_Up",
"finalMeasurementType": "Sq. Ft.",
"underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Kamatghar",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "4",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": true,
    "name": "District",
    "key": "district",
    "value": "Thane",
    "label": true
  }
}
```

```
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Bhiwandi",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Ashtavinayak Heights CHSL",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
```

```
"key": "street1",
"value": "",
"label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "A",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": true,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "1530/0",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "135",
  "label": true
},
```



```
"hissaNo": {
  "status": true,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "1",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "402",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
```

```
"value": "",
"label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "421 302",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
```

```
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
```

```
"label": "Internal Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
"label": "External Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
"label": "Internal Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
"label": "Flooring, Tiling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
}
```

```
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
```

```
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
}
```



```
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"invoices": [],
"paymentIds": [],
"_id": "65f28ecc857bdc098a9e3e6d",
"ownerName": "Govind Kishanlal Parik",
"ownerPhoneNo": "8668860154",
"fullAddress": "Residential Flat No. 402, 4th Floor, Wing - A, Ashtavinayak Heights
CHSL, Village - Kamatghar, Taluka - Bhiwandi, District - Thane, 421 302",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae124eaa6d152c1801b30b",
      "label": "Other"
    },
    "inputs": {
      "nameOfApprovingAuthority": {
        "value": "Bhiwandi_Nizampur_Municipal_Council",
        "label": "Bhiwandi Nizampur Municipal Council"
      }
    },
    "isHardCopy": false,
    "displayStatus": true,
    "fileName": "document_1710394679909_Govind.pdf",
    "path": "cases/65f28ecc857bdc098a9e3e6d/
document_1710394679909_Govind.pdf",
    "id": "585978",
    "uploadedBy": "64abdb2806d6ec174986d16b",
    "createdAt": "Thu Mar 14 2024 11:14:44 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae124eaa6d152c1801b30b",
      "label": "Other"
    },
    "inputs": {
      "documentDate": "10/02/2024",
      "nameOfApprovingAuthority": {
        "value": "Bhiwandi_Nizampur_Municipal_Council",
        "label": "Bhiwandi Nizampur Municipal Council"
      }
    }
  }
]
```

```
    }
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1710394978114_Govind_3.pdf",
  "path": "cases/65f28ecc857bdc098a9e3e6d/
document_1710394978114_Govind_3.pdf",
  "id": "962499",
  "uploadedBy": "64abdb2806d6ec174986d16b",
  "createdAt": "Thu Mar 14 2024 11:14:44 GMT+0530 (India Standard Time)"
}
],
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"caseNumber": "007670",
"createdBy": "64abdb2806d6ec174986d16b",
"caseHistory": [
  {
    "id": "740369",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Mar 14 2024 11:14:44 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Govind Kishanlal Parik",
    "phone": "8668860154",
    "ownershipShare": "",
    "email": "",
    "id": "209707"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "MEASUREMENT_IMAGE",
```

```
"status": false,
  "_id": "65f2d753857bdc098a9f4881",
  "name": "externallmg_r_1710413647860_1710413821371_image_0.png",
  "path": "cases/65f28ecc857bdc098a9e3e6d/
externallmg_r_1710413647860_1710413821371_image_0.png",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "65f2d753857bdc098a9f4882",
  "name": "externallmg_r_1710413648039_1710413821371_image_1.jpg",
  "path": "cases/65f28ecc857bdc098a9e3e6d/
externallmg_r_1710413648039_1710413821371_image_1.jpg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "65f2d753857bdc098a9f4883",
  "name": "externallmg_r_1710413649502_1710413821371_image_2.jpg",
  "path": "cases/65f28ecc857bdc098a9e3e6d/
externallmg_r_1710413649502_1710413821371_image_2.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65f2d79d857bdc098a9f49ce",
  "name": "externallmg_r_1710413692839_1710413861839_image_0.jpg",
  "path": "cases/65f28ecc857bdc098a9e3e6d/
externallmg_r_1710413692839_1710413861839_image_0.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65f2d79d857bdc098a9f49cf",
  "name": "externallmg_r_1710413694024_1710413861839_image_1.jpg",
  "path": "cases/65f28ecc857bdc098a9e3e6d/
externallmg_r_1710413694024_1710413861839_image_1.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "65f2d79d857bdc098a9f49d0",
    "name": "externallmg_r_1710413697084_1710413861839_image_3.jpg",
    "path": "cases/65f28ecc857bdc098a9e3e6d/
externallmg_r_1710413697084_1710413861839_image_3.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f2d79d857bdc098a9f49d1",
    "name": "externallmg_r_1710413695171_1710413861839_image_2.jpg",
    "path": "cases/65f28ecc857bdc098a9e3e6d/
externallmg_r_1710413695171_1710413861839_image_2.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f2d79d857bdc098a9f49d2",
    "name": "externallmg_r_1710413703371_1710413861839_image_7.jpg",
    "path": "cases/65f28ecc857bdc098a9e3e6d/
externallmg_r_1710413703371_1710413861839_image_7.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f2d79d857bdc098a9f49d3",
    "name": "externallmg_r_1710413698556_1710413861839_image_4.jpg",
    "path": "cases/65f28ecc857bdc098a9e3e6d/
externallmg_r_1710413698556_1710413861839_image_4.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f2d79d857bdc098a9f49d4",
    "name": "externallmg_r_1710413702194_1710413861839_image_6.jpg",
    "path": "cases/65f28ecc857bdc098a9e3e6d/
externallmg_r_1710413702194_1710413861839_image_6.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f2d79d857bdc098a9f49d5",
```

```
    "name": "externallmg_r_1710413700471_1710413861839_image_5.jpg",
    "path": "cases/65f28ecc857bdc098a9e3e6d/
externallmg_r_1710413700471_1710413861839_image_5.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f2d79d857bdc098a9f49d6",
    "name": "externallmg_r_1710413709787_1710413861839_image_11.jpg",
    "path": "cases/65f28ecc857bdc098a9e3e6d/
externallmg_r_1710413709787_1710413861839_image_11.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f2d79d857bdc098a9f49d7",
    "name": "externallmg_r_1710413704637_1710413861839_image_8.jpg",
    "path": "cases/65f28ecc857bdc098a9e3e6d/
externallmg_r_1710413704637_1710413861839_image_8.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f2d79d857bdc098a9f49d8",
    "name": "externallmg_r_1710413707833_1710413861839_image_10.jpg",
    "path": "cases/65f28ecc857bdc098a9e3e6d/
externallmg_r_1710413707833_1710413861839_image_10.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f2d79d857bdc098a9f49d9",
    "name": "externallmg_r_1710413706124_1710413861839_image_9.jpg",
    "path": "cases/65f28ecc857bdc098a9e3e6d/
externallmg_r_1710413706124_1710413861839_image_9.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f2d79d857bdc098a9f49da",
    "name": "externallmg_r_1710413710928_1710413861839_image_12.jpg",
```

```
    "path": "cases/65f28ecc857bdc098a9e3e6d/
externallmg_r_1710413710928_1710413861839_image_12.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f2d79d857bdc098a9f49db",
    "name": "externallmg_r_1710413716075_1710413861839_image_15.jpg",
    "path": "cases/65f28ecc857bdc098a9e3e6d/
externallmg_r_1710413716075_1710413861839_image_15.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f2d79d857bdc098a9f49dc",
    "name": "externallmg_r_1710413712417_1710413861839_image_13.jpg",
    "path": "cases/65f28ecc857bdc098a9e3e6d/
externallmg_r_1710413712417_1710413861839_image_13.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f2d79d857bdc098a9f49dd",
    "name": "externallmg_r_1710413713866_1710413861839_image_14.jpg",
    "path": "cases/65f28ecc857bdc098a9e3e6d/
externallmg_r_1710413713866_1710413861839_image_14.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f2d79d857bdc098a9f49de",
    "name": "externallmg_r_1710413719568_1710413861839_image_17.jpg",
    "path": "cases/65f28ecc857bdc098a9e3e6d/
externallmg_r_1710413719568_1710413861839_image_17.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f2d79d857bdc098a9f49df",
    "name": "externallmg_r_1710413717749_1710413861839_image_16.jpg",
    "path": "cases/65f28ecc857bdc098a9e3e6d/
externallmg_r_1710413717749_1710413861839_image_16.jpg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65f2d79d857bdc098a9f49e0",
  "name": "externallmg_r_1710413721118_1710413861839_image_18.jpg",
  "path": "cases/65f28ecc857bdc098a9e3e6d/
externallmg_r_1710413721118_1710413861839_image_18.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65f2d7b3857bdc098a9f4a52",
  "name": "externallmg_r_1710413740934_1710413915407_image_1.jpg",
  "path": "cases/65f28ecc857bdc098a9e3e6d/
externallmg_r_1710413740934_1710413915407_image_1.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65f2d7b3857bdc098a9f4a53",
  "name": "externallmg_r_1710413742112_1710413915407_image_2.jpg",
  "path": "cases/65f28ecc857bdc098a9e3e6d/
externallmg_r_1710413742112_1710413915407_image_2.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65f2d7b3857bdc098a9f4a54",
  "name": "externallmg_r_1710413743409_1710413915407_image_3.jpg",
  "path": "cases/65f28ecc857bdc098a9e3e6d/
externallmg_r_1710413743409_1710413915407_image_3.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65f2d7b3857bdc098a9f4a55",
  "name": "externallmg_r_1710413739497_1710413915407_image_0.jpg",
  "path": "cases/65f28ecc857bdc098a9e3e6d/
externallmg_r_1710413739497_1710413915407_image_0.jpg",
  "orientation": "portrait"
}
```

```

    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "65f2d7b3857bdc098a9f4a56",
      "name": "externalImg_r_1710413744840_1710413915407_image_4.jpg",
      "path": "cases/65f28ecc857bdc098a9e3e6d/
externalImg_r_1710413744840_1710413915407_image_4.jpg",
      "orientation": "landscape"
    }
  ],
  "externalDocuments": [],
  "processingDocuments": [],
  "leadRemarks": [],
  "audioRemarks": [],
  "remarks": [],
  "createdAt": "2024-03-14T05:44:44.382Z",
  "updatedAt": "2024-03-14T10:55:47.369Z",
  "__v": 0,
  "updatedBy": "62ea09ea4e679b264caf07d7",
  "addressForMap": "",
  "caseReferredBy": "64abdb2806d6ec174986d16b",
  "contactPersonName": "Govind Kishanlal Parik",
  "email": "",
  "isExternal": "false",
  "isUrgent": "false",
  "ownershipShare": "",
  "proposePurchaserName": "",
  "purchaseValueAsPerDocument": "",
  "relationWithOwner": "self",
  "siteVisitContactNo": "8668860154"
}

```

Name	Length	Width	Total
Composition :			
Other Composition :			