

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b951"
    },
    "type": "CREDITOFFICER",
    "_id": "659e42a602c44c777bae2d2f",
    "firstName": "Surendra",
    "lastName": "Kamble",
    "mobileNo": "",
    "workMobileNo": "8689869332",
    "email": "2sbi.14677@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "45000000",
    "discussWithPerson": "Surendra",
    "expectedFees": 22500,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b951",
  "branchCode": "000167",
  "type": "BRANCH",
  "name": "RACPC Belapur ",
  "email": "sbi.14677@sbi.co.in",
  "mobileNo": "022-27524090",
  "alternateMobileNo": "",
  "address": "Estate Department Corporate Centre, 4th Floor, CIDCO Tower No. 4,
Railway Station Building, C.B.D. Belapur, Navi Mumbai - 400 614, State - Maharashtra,
Country - India.",
  "ledgerName": "STATE BANK OF INDIA - CBD Estate Department",
  "fax": "022 2757 7002",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "60b7189d2ffdf65bcd65882b",
  "role": "PICKUPPERSON",
  "firstName": "Ravindra",
  "email": "ravindrakasare186@gmail.com",
  "lastName": "Kasare",
  "mobileNo": "9167204055",
  "shortName": "RBK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60b7189d2ffdf65bcd65882b\\
\\profilePhoto_1622701555488_WhatsApp Image 2021-06-03 at 11.46.40 AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "63fc4680ce84bf289ba9c7fc",
  "role": "SITEENGINEER",
  "firstName": "Nikhil ",
  "email": "valtechnical2022@gmail.com",
  "lastName": "Sonawane",
  "mobileNo": "9819470709",
  "designation": "",
  "shortName": "NS",
  "workWithDocumentMaker": "6006d4ce5080a310ac1fdcf2",
  "profilePhoto": "users/63fc4680ce84bf289ba9c7fc/
profilePhoto_1681380664371_WhatsApp_Image_20230413_at_33801_PM.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": "",
  "shortName": "SK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Shymam_Photo.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shyam",
```

```
"email": "shyam@vastukala.org",
"lastName": "Kajvilkar",
"mobileNo": "9765074720",
"designation": "",
"shortName": "SK",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Shyam_Photo.jpg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "9004437379",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ]
  }
]
```

```
    },
    {
      "title": {
        "value": "FIIV",
        "label": "FIIV"
      },
      "_id": "60af80072ffdf65bcd658652",
      "number": "CAT-I-F-1763"
    },
    {
      "title": {
        "value": "Chartered_Engineer",
        "label": "Chartered Engineer"
      },
      "_id": "60af80072ffdf65bcd658653",
      "number": "AM161706-3"
    },
    {
      "title": {
        "value": "Registered_Valuer",
        "label": "Registered Valuer"
      },
      "_id": "60af80072ffdf65bcd658654",
      "number": "IBBI/RV/07/2018/10366"
    }
  ],
  "shortName": "MBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
  "PANNo": "AERPC9086P",
  "fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.155370663619458",
  "longitude": "73.06381197671048"
},
"geo": {
  "type": "Point",
  "coordinates": [
```

```
73.06381197671048,
19.155370663619458
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-03-19",
      "remark": "ssl surendra "
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-03-18",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "2BHK",
  "label": "2 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  }
}
```

```
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Khidkali",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "11",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "A1",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Thane",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
```

```
"key": "taluka",
"value": "Thane",
"label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Sai Srushti Annex",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
}
```



```
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "155, Hissa No. 11",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
```

```
"value": "",
"label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "1105",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
```

```
"status": false,
"name": "Gut No.",
"key": "GUTNo",
"value": "",
"label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "421204",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Diva (East)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "Vitrified_tiles_flooring",
    "label": "Vitrified tiles flooring"
  },
  "doors": {
    "value": "Teak_Wood_door_frame,_Flush_doors_shutters",
    "label": "Teak Wood door frame, Flush doors shutters"
  },
  "windows": {
    "value": "Aluminium_Sliding_Window_",
    "label": "Aluminium Sliding Window "
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering",
    "label": "Cement Plastering"
  }
}
```

```
}
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "Thane_Municipal_Corporation",
    "label": "Thane Municipal Corporation"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Open Plot",
    "west": "Cosmos Mehula Building",
    "south": "Shiv Siddhi Complex",
    "east": "Internal Road"
  },
  "asPerDocumentAgreement": {
    "north": "Details not available",
    "west": "Details not available",
    "south": "Details not available",
    "east": "Details not available"
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "Details not available",
      "east": "Details not available",
      "south": "Details not available",
      "west": "Details not available"
    },
    "asPerDocument": {
      "north": "Details not available",
      "east": "Details not available",
      "south": "Details not available",
    }
  }
}
```

```
    "west": "Details not available"
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "Copy of Approved Building Plan No. V. P. No. S11 /
0146 / 17 TMC / TDD / 2648 / 18 Dated 26.05.2018 issue by Thane Municipal
Corporaiton.",
"approvePlanVerified": "Yes",
"empanelledOfApprovePlan": "No",
"unauthorizedConstruction": ""
},
"compositeRate": {
  "remark": "As per Site Inspection, Actual Carpet Area 624.00 Sq. Ft. (Including Dry
Balcony & Flowerbed Area) is more than Carpet Area 560.00 Sq. Ft. mentioned in
Agreement for Sale. For the purpose of valuation, we have considered the area as per
agreement for sale.",
  "depreciationPercentage": "",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "depreciatedCostOfConstruction": "",
  "depreciatedBuildingRate": ""
},
"igrRate": {
  "propertyName": "Residential Flat",
  "rate": "59600",
  "landRate": "11900",
  "igrImage": "cases/65f43636857bdc098aa1fbd8/igr_1711535139339_Image.png",
  "squareMeterGuideLineRate": "65560.00",
  "squareFeetGuideLineRate": "6091.00"
},
"igrFinalRate": {
  "floorRatePercentage": "10",
  "depreciationPercentage": "95",
  "rate": "5841.00",
  "squareMeterGuideLineRate": "62877.00",
  "squareFeetGuideLineRate": "5841.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
```

```
"label": "Residential Purpose"
},
"propertyOccupiedByList": {
  "value": "Owner_Occupied",
  "label": "Owner Occupied"
},
"monthlyRent": "N.A.",
"assessmentNo": "Details not available",
"taxPaidHolderName": "Details not available",
"taxAmount": "Details not available",
"electricityServiceConnectionNo": "Details not available",
"meterCardHolderName": "Details not available",
"undividedAreaOfLandAsPerSaleDeed": "N.A.",
"floorSpaceIndex": "As per TMC norms",
"tenantName": "",
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "N.A."
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Stilt Car Parking Space",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  }
}
```

```
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2020",
  "fullDate": "1/1/2020"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C.",
  "label": "R.C.C. Framed"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
```

```
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "1",
  "label": "Yes"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "stilt",
  "label": "Stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "56",
"ageOfBuilding": "4",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "18",
"flatFloorNo": "11",
```



```
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "5"
},
"finalPlinthArea": {
  "area": "616.00",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/65f43636857bdc098aa1fbd8/
routeMap_1711535372434_Image.png",
    "routeLat": "19.155062",
    "routeLng": "73.063606",
    "stationName": "Diva",
    "routeDistance": "7.9 Km. "
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "3vbov8",
      "name": "3vbov8",
      "image": "cases/65f43636857bdc098aa1fbd8/
routeMap_1711535309836_Image.png"
    }
  ]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
```

```
"showcasesQty": "0",
"showcasesRate": "0",
"totalshowcasesRate": "0",
"kitchenArrangementsQty": "0",
"kitchenArrangementsRate": "0",
"totalkitchenArrangementsRate": "0",
"superfineFinishQty": "0",
"superfineFinishRate": "0",
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "5880000.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "5880000.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Wed Mar 27 2024 16:19:19 GMT+0530 (India Standard Time)",
  "number": "2305761",
  "dayCount": "12",
  "monthCount": "509",
  "generatedBy": "5fc78e26625ecd20ec1f88e9"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": ""
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"rccPlinth": {
  "label": "RCC Plinth",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "3598056.00",
  "selectedBuildUpValue": "616.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "65f88cf249003e142a8d7732",
      "name": "externalimg_r_1710787817667_1710787998890_image_0.jpg",
      "path": "cases/65f43636857bdc098aa1fbd8/
externalimg_r_1710787817667_1710787998890_image_0.jpg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [
    {
      "status": false,
      "_id": "65f88cf249003e142a8d7732",
```

```
    "name": "externallmg_r_1710787817667_1710787998890_image_0.jpg",
    "path": "cases/65f43636857bdc098aa1fbd8/
externallmg_r_1710787817667_1710787998890_image_0.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65f88cf249003e142a8d7733",
    "name": "externallmg_r_1710787819516_1710787998890_image_1.jpg",
    "path": "cases/65f43636857bdc098aa1fbd8/
externallmg_r_1710787819516_1710787998890_image_1.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65f88cdc49003e142a8d76f9",
    "name": "externallmg_r_1710787797008_1710787935495_image_18.jpg",
    "path": "cases/65f43636857bdc098aa1fbd8/
externallmg_r_1710787797008_1710787935495_image_18.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65f88cdc49003e142a8d76f7",
    "name": "externallmg_r_1710787794266_1710787935495_image_17.jpg",
    "path": "cases/65f43636857bdc098aa1fbd8/
externallmg_r_1710787794266_1710787935495_image_17.jpg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "65f88cdc49003e142a8d76f4",
    "name": "externallmg_r_1710787789676_1710787935495_image_15.jpg",
    "path": "cases/65f43636857bdc098aa1fbd8/
externallmg_r_1710787789676_1710787935495_image_15.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65f88cdc49003e142a8d76f5",
    "name": "externallmg_r_1710787787377_1710787935495_image_14.jpg",
    "path": "cases/65f43636857bdc098aa1fbd8/
externallmg_r_1710787787377_1710787935495_image_14.jpg",
    "orientation": "portrait"
  },
  {
```

```
    "status": false,
    "_id": "65f88cdc49003e142a8d76f0",
    "name": "externallmg_r_1710787779380_1710787935495_image_10.jpg",
    "path": "cases/65f43636857bdc098aa1fbd8/
externallmg_r_1710787779380_1710787935495_image_10.jpg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
    "_id": "65f88cdc49003e142a8d76f2",
    "name": "Living Room",
    "path": "cases/65f43636857bdc098aa1fbd8/
externallmg_r_1710787783686_1710787935495_image_12.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65f88cdc49003e142a8d76ef",
    "name": "Living Room",
    "path": "cases/65f43636857bdc098aa1fbd8/
externallmg_r_1710787777200_1710787935495_image_9.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65f88cdc49003e142a8d76ec",
    "name": "Living Room",
    "path": "cases/65f43636857bdc098aa1fbd8/
externallmg_r_1710787771072_1710787935495_image_6.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65f88cdc49003e142a8d76ea",
    "name": "Living Room",
    "path": "cases/65f43636857bdc098aa1fbd8/
externallmg_r_1710787767030_1710787935495_image_4.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65f88cdc49003e142a8d76e7",
```

```
    "name": "Living Room",
    "path": "cases/65f43636857bdc098aa1fbd8/
externallmg_r_1710787765171_1710787935495_image_3.jpg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
```



```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "560.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"invoices": [],
"paymentIds": [],
"_id": "65f43636857bdc098aa1fbd8",
```

```
"ownerName": "Mr. Sandip R. Halkunde & Mrs. Indubai R. Halkunde",
"ownerPhoneNo": "7021059124",
"appAddress": "flat no 1105 11 th floor Bldg no A1 sai srishti village khldkali thane ",
"remark": "ssl surendra ",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "15/02/2019",
      "from": {
        "value": "Promoter",
        "label": "Promoter"
      },
      "Promoter": "M/s. Sai Shrushti Enterprises",
      "to": {
        "value": "Purchaser",
        "label": "Purchaser"
      },
      "Purchaser": "Mr. Sandip R. Halkunde & Mrs. Indubai R. Halkunde",
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "2608/2019"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "fileName": "document_1711534118492_Document_Sandeep_.pdf",
    "path": "cases/65f43636857bdc098aa1fbd8/
document_1711534118492_Document_Sandeep_.pdf",
    "id": "604062",
    "uploadedBy": "60eeaeddf3dd69653a581316",
    "createdAt": "Wed Mar 27 2024 15:38:38 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae129faa6d152c1801b47d",
      "label": "RERA Certificate"
    },
    "inputs": {
      "documentDate": "08/03/2024",
      "nameOfApprovingAuthority": {
        "value": "Maharashtra_Real_Estate_Regulatory_Authority",
```

```
    "label": "Maharashtra Real Estate Regulatory Authority"
  },
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "P51700015209"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1711534181525_RERA.pdf",
"path": "cases/65f43636857bdc098aa1fbd8/document_1711534181525_RERA.pdf",
"id": "529510",
"uploadedBy": "60eeaeddf3dd69653a581316",
"createdAt": "Wed Mar 27 2024 15:39:41 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "09/10/2020",
    "nameOfApprovingAuthority": {
      "value": "Thane_Municipal_Corporation",
      "label": "Thane Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "V.P. No. S11 / 0146 / 17 / OCC / 0856 / 20"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1711534211514_OC.pdf",
  "path": "cases/65f43636857bdc098aa1fbd8/document_1711534211514_OC.pdf",
  "id": "111665",
  "uploadedBy": "60eeaeddf3dd69653a581316",
  "createdAt": "Wed Mar 27 2024 15:40:11 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
}
```

```
"inputs": {
  "documentDate": "24/05/2018",
  "nameOfApprovingAuthority": {
    "value": "Thane_Municipal_Corporation",
    "label": "Thane Municipal Corporation"
  },
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "V. P. No. S11 / 0146 / 17 TMC / TDD / 2648 / 18"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1711534233255_CC.pdf",
"path": "cases/65f43636857bdc098aa1fbd8/document_1711534233255_CC.pdf",
"id": "539637",
"uploadedBy": "60eeaeddf3dd69653a581316",
"createdAt": "Wed Mar 27 2024 15:40:33 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1277aa6d152c1801b3cc",
    "label": "Approved Building Plan"
  },
  "inputs": {
    "documentDate": "26/05/2018",
    "nameOfApprovingAuthority": {
      "value": "Thane_Municipal_Corporation",
      "label": "Thane Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "V. P. No. S11 / 0146 / 17 TMC / TDD / 2648 / 18"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1711534294848_PLAN.pdf",
  "path": "cases/65f43636857bdc098aa1fbd8/document_1711534294848_PLAN.pdf",
  "id": "606137",
  "uploadedBy": "60eeaeddf3dd69653a581316",
  "createdAt": "Wed Mar 27 2024 15:41:34 GMT+0530 (India Standard Time)"
}
],
```

```
"caseNumber": "007724",
"createdBy": "60b7189d2ffdf65bcd65882b",
"caseHistory": [
  {
    "id": "102033",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Mar 15 2024 17:21:18 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Sandip R. Halkunde & Mrs. Indubai R. Halkunde",
    "phone": "7021059124",
    "ownershipShare": "",
    "email": "",
    "id": "408721"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "598232",
    "name": "Bedroom",
    "length": "10.00",
    "length1": "10",
    "length2": "00",
    "width": "9.50",
    "width1": "9",
    "width2": "6",
    "totalArea": "95.00",
    "images": [],
    "extraAreas": [],
    "finalArea": "95.00"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "1",
```

```
"name": "Cupboard",
"length": "7.00",
"length1": "7",
"length2": "00",
"width": "2.00",
"width1": "2",
"width2": "00",
"totalArea": "14.00",
"images": [],
"extraAreas": [],
"finalArea": "14.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Toilet",
  "length": "",
  "length1": "4",
  "length2": "0",
  "width": "",
  "width1": "6",
  "width2": "9",
  "totalArea": "27.00",
  "images": [],
  "finalArea": "27.00",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Passage",
  "length": "",
  "length1": "5",
  "length2": "6",
  "width": "",
  "width1": "3",
  "width2": "0",
  "totalArea": "16.50",
  "images": [],
  "finalArea": "16.50",
```

```
"extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Toilet",
  "length": "7.00",
  "length1": "7",
  "length2": "00",
  "width": "4.00",
  "width1": "4",
  "width2": "00",
  "totalArea": "28.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "28.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Living Room",
  "length": "14.67",
  "length1": "14",
  "length2": "8",
  "width": "11.00",
  "width1": "11",
  "width2": "00",
  "totalArea": "161.33",
  "images": [],
  "extraAreas": [],
  "finalArea": "161.33"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Dining",
  "length": "9.58",
```



```
"length1": "9",
"length2": "7",
"width": "3.58",
"width1": "3",
"width2": "7",
"totalArea": "34.34",
"images": [],
"extraAreas": [],
"finalArea": "34.34"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Bedroom",
  "length": "9.17",
  "length1": "9",
  "length2": "2",
  "width": "9.08",
  "width1": "9",
  "width2": "1",
  "totalArea": "83.26",
  "images": [],
  "extraAreas": [],
  "finalArea": "83.26"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "8",
  "name": "Cupboard",
  "length": "4.00",
  "length1": "4",
  "length2": "00",
  "width": "2.00",
  "width1": "2",
  "width2": "00",
  "totalArea": "8.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "8.00"
},
}
```

```
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "9",
  "name": "Kitchen",
  "length": "8.42",
  "length1": "8",
  "length2": "5",
  "width": "7.83",
  "width1": "7",
  "width2": "10",
  "totalArea": "65.93",
  "images": [],
  "extraAreas": [],
  "finalArea": "65.93"
}
],
"otherComposition": [
  {
    "toBeAdded": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "name": {
      "label": "Flowerbed",
      "value": "Flowerbed"
    },
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "0",
    "length": "2.00",
    "length1": "2",
    "length2": "00",
    "width": "10.00",
    "width1": "10",
    "width2": "00",
    "totalArea": "20.00",
    "images": [],
    "extraAreas": [],
    "finalArea": "20",
    "percentageBeforeTotal": "20.00",
    "percentage": "100"
  }
]
```

```
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Flowered Area",
    "value": "Flowered_Area"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "length": "9.50",
  "length1": "9",
  "length2": "6",
  "width": "2.00",
  "width1": "2",
  "width2": "00",
  "totalArea": "19.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "19",
  "percentageBeforeTotal": "19.00",
  "percentage": "100"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Flowered Area",
    "value": "Flowered_Area"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "length": "7.83",
  "length1": "7",
  "length2": "10",
  "width": "2.00",
```

```
"width1": "2",
"width2": "00",
"totalArea": "15.67",
"images": [],
"extraAreas": [],
"finalArea": "15.67",
"percentageBeforeTotal": "15.67",
"percentage": "100"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Dry Balcony",
    "value": "Dry_Balcony"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "length": "12.00",
  "length1": "12",
  "length2": "00",
  "width": "3.00",
  "width1": "3",
  "width2": "00",
  "totalArea": "36.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "36",
  "percentageBeforeTotal": "36.00",
  "percentage": "100"
}
],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
```

```
    "label": "Square Feet"
  },
  "id": "733527",
  "selectAreaTypeDocument": "Carpet",
  "totalAreaDocument": "560",
  "squareMeterArea": "52.03",
  "docFinalBuiltUp": "616",
  "docFinalBuiltUpSquareMeter": "57.233000000000004",
  "docBuiltupPercentage": "10",
  "docSaleablePercentage": "0",
  "docFinalSaleable": "0",
  "docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": false,
    "_id": "6603f3bd5ca1625e50631003",
    "property": "Residential Flat",
    "area": "635",
    "builtUpPercentage": "10",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "source": "Housing.Com",
    "expectedPrice": "6900000",
    "expectedRate": "10866.14",
    "builtUpExpectedRate": "9878.31",
    "image": "cases/65f43636857bdc098aa1fbd8/
indicator_1711534985203_Image.png",
    "squareMeter": "58.99",
    "id": "459706"
  },
  {
    "printlnReport": false,
    "_id": "6603f3bd5ca1625e50631004",
    "property": "Residential Flat",
    "area": "695",
    "builtUpPercentage": "10",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "source": "Housing.Com",
    "expectedPrice": "6650000",
    "expectedRate": "9568.35",
```

```
"builtUpExpectedRate": "8698.50",
"image": "cases/65f43636857bdc098aa1fbd8/
indicator_1711535014932_Image.png",
"squareMeter": "64.57",
"id": "569812"
},
{
  "printlnReport": false,
  "_id": "6603f3bd5ca1625e50631005",
  "property": "Residential Flat",
  "area": "603",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "Nobroker.com",
  "expectedPrice": "7000000",
  "expectedRate": "11608.62",
  "builtUpExpectedRate": "10553.29",
  "image": "cases/65f43636857bdc098aa1fbd8/
indicator_1711535036979_Image.png",
  "squareMeter": "56.02",
  "id": "809626"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f88cdc49003e142a8d76e6",
    "name": "externalImg_r_1710787759680_1710787935495_image_0.png",
    "path": "cases/65f43636857bdc098aa1fbd8/
externalImg_r_1710787759680_1710787935495_image_0.png",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f88cdc49003e142a8d76e7",
    "name": "externalImg_r_1710787765171_1710787935495_image_3.jpg",
    "path": "cases/65f43636857bdc098aa1fbd8/
externalImg_r_1710787765171_1710787935495_image_3.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "65f88cdc49003e142a8d76e8",
    "name": "externallmg_r_1710787762652_1710787935495_image_2.jpg",
    "path": "cases/65f43636857bdc098aa1fbd8/
externallmg_r_1710787762652_1710787935495_image_2.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f88cdc49003e142a8d76e9",
    "name": "externallmg_r_1710787760559_1710787935495_image_1.jpg",
    "path": "cases/65f43636857bdc098aa1fbd8/
externallmg_r_1710787760559_1710787935495_image_1.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f88cdc49003e142a8d76ea",
    "name": "externallmg_r_1710787767030_1710787935495_image_4.jpg",
    "path": "cases/65f43636857bdc098aa1fbd8/
externallmg_r_1710787767030_1710787935495_image_4.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f88cdc49003e142a8d76eb",
    "name": "externallmg_r_1710787769097_1710787935495_image_5.jpg",
    "path": "cases/65f43636857bdc098aa1fbd8/
externallmg_r_1710787769097_1710787935495_image_5.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f88cdc49003e142a8d76ec",
    "name": "externallmg_r_1710787771072_1710787935495_image_6.jpg",
    "path": "cases/65f43636857bdc098aa1fbd8/
externallmg_r_1710787771072_1710787935495_image_6.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```

```
    "_id": "65f88cdc49003e142a8d76ed",
    "name": "externallmg_r_1710787775365_1710787935495_image_8.jpg",
    "path": "cases/65f43636857bdc098aa1fbd8/
externallmg_r_1710787775365_1710787935495_image_8.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f88cdc49003e142a8d76ee",
    "name": "externallmg_r_1710787772966_1710787935495_image_7.jpg",
    "path": "cases/65f43636857bdc098aa1fbd8/
externallmg_r_1710787772966_1710787935495_image_7.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f88cdc49003e142a8d76ef",
    "name": "externallmg_r_1710787777200_1710787935495_image_9.jpg",
    "path": "cases/65f43636857bdc098aa1fbd8/
externallmg_r_1710787777200_1710787935495_image_9.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f88cdc49003e142a8d76f0",
    "name": "externallmg_r_1710787779380_1710787935495_image_10.jpg",
    "path": "cases/65f43636857bdc098aa1fbd8/
externallmg_r_1710787779380_1710787935495_image_10.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f88cdc49003e142a8d76f1",
    "name": "externallmg_r_1710787781543_1710787935495_image_11.jpg",
    "path": "cases/65f43636857bdc098aa1fbd8/
externallmg_r_1710787781543_1710787935495_image_11.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f88cdc49003e142a8d76f2",
```



```
    "name": "externallmg_r_1710787783686_1710787935495_image_12.jpg",
    "path": "cases/65f43636857bdc098aa1fbd8/
externallmg_r_1710787783686_1710787935495_image_12.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f88cdc49003e142a8d76f3",
    "name": "externallmg_r_1710787785759_1710787935495_image_13.jpg",
    "path": "cases/65f43636857bdc098aa1fbd8/
externallmg_r_1710787785759_1710787935495_image_13.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f88cdc49003e142a8d76f4",
    "name": "externallmg_r_1710787789676_1710787935495_image_15.jpg",
    "path": "cases/65f43636857bdc098aa1fbd8/
externallmg_r_1710787789676_1710787935495_image_15.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f88cdc49003e142a8d76f5",
    "name": "externallmg_r_1710787787377_1710787935495_image_14.jpg",
    "path": "cases/65f43636857bdc098aa1fbd8/
externallmg_r_1710787787377_1710787935495_image_14.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f88cdc49003e142a8d76f6",
    "name": "externallmg_r_1710787791733_1710787935495_image_16.jpg",
    "path": "cases/65f43636857bdc098aa1fbd8/
externallmg_r_1710787791733_1710787935495_image_16.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f88cdc49003e142a8d76f7",
    "name": "externallmg_r_1710787794266_1710787935495_image_17.jpg",
```

```
    "path": "cases/65f43636857bdc098aa1fbd8/
externallmg_r_1710787794266_1710787935495_image_17.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f88cdc49003e142a8d76f8",
    "name": "externallmg_r_1710787799458_1710787935495_image_19.jpg",
    "path": "cases/65f43636857bdc098aa1fbd8/
externallmg_r_1710787799458_1710787935495_image_19.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f88cdc49003e142a8d76f9",
    "name": "externallmg_r_1710787797008_1710787935495_image_18.jpg",
    "path": "cases/65f43636857bdc098aa1fbd8/
externallmg_r_1710787797008_1710787935495_image_18.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f88cf249003e142a8d7732",
    "name": "externallmg_r_1710787817667_1710787998890_image_0.jpg",
    "path": "cases/65f43636857bdc098aa1fbd8/
externallmg_r_1710787817667_1710787998890_image_0.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f88cf249003e142a8d7733",
    "name": "externallmg_r_1710787819516_1710787998890_image_1.jpg",
    "path": "cases/65f43636857bdc098aa1fbd8/
externallmg_r_1710787819516_1710787998890_image_1.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f88cf249003e142a8d7734",
    "name": "externallmg_r_1710787822087_1710787998890_image_2.jpg",
    "path": "cases/65f43636857bdc098aa1fbd8/
externallmg_r_1710787822087_1710787998890_image_2.jpg",
```

```
"orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "65f88c8649003e142a8d76aa",
  "name": "externallmg_r_1710787715444_1710787897332_image_0.jpg",
  "path": "cases/65f43636857bdc098aa1fbd8/
externallmg_r_1710787715444_1710787897332_image_0.jpg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "CC.pdf",
    "filename": "1711535507463_CC.pdf",
    "path": "cases/65f43636857bdc098aa1fbd8/
processingDocuments/1711535507463_CC.pdf",
    "size": "349171",
    "createdAt": "Wed Mar 27 2024 16:01:48 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "Document_Sandeep .pdf",
    "filename": "1711535507472_Document_Sandeep_.pdf",
    "path": "cases/65f43636857bdc098aa1fbd8/
processingDocuments/1711535507472_Document_Sandeep_.pdf",
    "size": "3258631",
    "createdAt": "Wed Mar 27 2024 16:01:48 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "externallmg_r_1710787715444_1710787897332_image_0.jpg",
    "filename":
"1711535507531_externallmg_r_1710787715444_1710787897332_image_0.jpg",
    "path": "cases/65f43636857bdc098aa1fbd8/processingDocuments/1711535507531
_externallmg_r_1710787715444_1710787897332_image_0.jpg",
    "size": "2183675",
    "createdAt": "Wed Mar 27 2024 16:01:48 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "externallmg_r_1710787759680_1710787935495_image_0.png",
    "filename":
"1711535507567_externallmg_r_1710787759680_1710787935495_image_0.png",
```

```
    "path": "cases/65f43636857bdc098aa1fbd8/processingDocuments/1711535507567_externallmg_r_1710787759680_1710787935495_image_0.png",
    "size": "3257115",
    "createdAt": "Wed Mar 27 2024 16:01:48 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "externallmg_r_1710787760559_1710787935495_image_1.jpg",
    "filename":
"1711535507608_externallmg_r_1710787760559_1710787935495_image_1.jpg",
    "path": "cases/65f43636857bdc098aa1fbd8/processingDocuments/1711535507608_externallmg_r_1710787760559_1710787935495_image_1.jpg",
    "size": "2183675",
    "createdAt": "Wed Mar 27 2024 16:01:48 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "OC.pdf",
    "filename": "1711535507662_OC.pdf",
    "path": "cases/65f43636857bdc098aa1fbd8/processingDocuments/1711535507662_OC.pdf",
    "size": "518518",
    "createdAt": "Wed Mar 27 2024 16:01:48 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "PLAN.pdf",
    "filename": "1711535507672_PLAN.pdf",
    "path": "cases/65f43636857bdc098aa1fbd8/processingDocuments/1711535507672_PLAN.pdf",
    "size": "647079",
    "createdAt": "Wed Mar 27 2024 16:01:48 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "RERA.pdf",
    "filename": "1711535507687_RERA.pdf",
    "path": "cases/65f43636857bdc098aa1fbd8/processingDocuments/1711535507687_RERA.pdf",
    "size": "261035",
    "createdAt": "Wed Mar 27 2024 16:01:48 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "Sandeep Halkunde Final.doc.pdf",
    "filename": "1711535507716_Sandeep_Halkunde_Finaldoc.pdf",
```

```
"path": "cases/65f43636857bdc098aa1fbd8/
processingDocuments/1711535507716_Sandeep_Halkunde_Finaldoc.pdf",
"size": "20342936",
"createdAt": "Wed Mar 27 2024 16:01:48 GMT+0530 (India Standard Time)",
"uploadedBy": "60eeaeddf3dd69653a581316"
},
{
"originalname": "Summary New=SANDIP.xlsx",
"filename": "1711535508125_Summary_NewSANDIP.xlsx",
"path": "cases/65f43636857bdc098aa1fbd8/
processingDocuments/1711535508125_Summary_NewSANDIP.xlsx",
"size": "2008573",
"createdAt": "Wed Mar 27 2024 16:01:48 GMT+0530 (India Standard Time)",
"uploadedBy": "60eeaeddf3dd69653a581316"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
{
"createdBy": {
"_id": "60eeaeddf3dd69653a581316",
"role": "MAKER + RATE VERIFIER + CHEAKER",
"firstName": "Shyam",
"lastName": "Kajvilkar",
"profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Shyam_Photo.jpg"
},
"workType": "RATE_VERIFY",
"display": true,
"status": true,
"_id": "65f93d0049003e142a8e6eb3",
"note": "Pending for value confirmation",
"taskId": "65f437ec857bdc098aa20718",
"createdAt": "2024-03-19T07:21:36.945Z"
}
],
"createdAt": "2024-03-15T11:51:18.749Z",
"updatedAt": "2024-03-27T10:54:29.355Z",
"__v": 0,
"assignmentType": {
"value": "Retail",
"label": "Retail"
},
"fullAddress": "Residential Flat No. 1105, 11th Floor, Building No A1, Sai Srushti
Annex, Village - Khidkali, Diva (East), Taluka - Thane, Thane, 421204, State -
```

Maharashtra, India",  
"updatedBy": "5fc78e26625ecd20ec1f88e9",  
"addressForMap": "",  
"caseReferredBy": "60b7189d2ffdf65bcd65882b",  
"contactPersonName": "Smt. Indubai Halkunde",  
"email": "",  
"isExternal": "false",  
"isUrgent": "false",  
"ownershipShare": "",  
"proposePurchaserName": "",  
"purchaseValueAsPerDocument": "",  
"relationWithOwner": "Self",  
"siteVisitContactNo": "7021059124",  
"reason": "Reopen",  
"briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + 2 Cupboard + 2 Toilet  
+ Passage + Dining",  
"carpetTotal": "533.36",  
"finalMeasurementType": "Sq. Ft.",  
"otherCarpetTotal": "90.67",  
"otherCompositionBuiltUpTotal": "0.00",  
"otherCompositionCarpetTotal": "90.67",  
"otherCompositionSaleableTotal": "0.00",  
"builtupPercentage": "10",  
"finalBuiltupArea": "686.43",  
"finalCarpetArea": "624.03",  
"finalSalableArea": "755.08",  
"salablePercentage": "10",  
"toBeAdded": "",  
"extendOfSiteRemark": "Carpet Area in Sq. Ft. = 483.00\nFlowerbed & Dry Balcony  
Area in Sq. Ft. = 77.00\n\n",  
"siteMeasurementRemark": "Carpet Area in Sq. Ft. = 533.00\nFlowerbed & Dry  
Balcony Area in Sq. Ft. = 91.00\n\n",  
"finalAreaType": "Carpet Area",  
"finalAsPerArea": "Agreement for sale",  
"finalBuiltUpPercentage": "10",  
"finalCarpetConvertToBuiltUpPer": "10",  
"finalSaleablePercentage": "0",  
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 560.00",  
"buildingServicesRate": "2500",  
"flatRate": "10500",  
"landOtherRate": "8000",  
"landDetails": {  
"holdType": {  
"label": "Free Hold",  
"value": "Free\_Hold"  
},  
},

```

"leaseDetails": {
  "lessorName": "",
  "lesseeName": "",
  "leasePremium": "",
  "leaseRent": "",
  "leasePeriod": 0,
  "leaseFrom": "",
  "leaseTo": "",
  "remainingLeasePeriod": 0,
  "leaseDate": ""
}
},
"reportGeneratedDate": "Wed Mar 27 2024 15:18:50 GMT+0530 (India Standard
Time)",
"siteVisitDate": "2024-03-18"
}

```

Name	Length	Width	Total
Composition :			
Bedroom	10'00"	9'6"	95.00
Cupboard	7'00"	2'00"	14.00
Toilet	4'0"	6'9"	27.00
Passage	5'6"	3'0"	16.50
Toilet	7'00"	4'00"	28.00
Living Room	14'8"	11'00"	161.33
Dining	9'7"	3'7"	34.34
Bedroom	9'2"	9'1"	83.26
Cupboard	4'00"	2'00"	8.00
Kitchen	8'5"	7'10"	65.93
Other Composition :			
Flowerbed	2'00"	10'00"	20.00
Flowered Area	9'6"	2'00"	19.00
Flowered Area	7'10"	2'00"	15.67

Dry Balcony

12'00"

3'00"

36.00

---