

```
{
  "typeOfReport": {
    "label": "APF",
    "value": "APF"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "63b26652191f7b344b008cac"
    },
    "type": "CREDITOFFICER",
    "_id": "63d11f66be948726cc141b93",
    "email": "sbi.04380@sbi.co.in",
    "firstName": "BHAUSAHEB ",
    "mobileNo": "",
    "workMobileNo": "9167778443",
    "lastName": "PATIL"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "6484648",
    "discussWithPerson": "BHAUSAHEB ",
    "expectedFees": 3242.324,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "63b26652191f7b344b008cac",
  "name": "HLST BKC",
  "branchCode": "",
  "mobileNo": "022-26445021",
  "alternateMobileNo": "",
  "email": "sbi.04380@sbi.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "HLST Synergy Building, 1st floor, C – 6, G Block\nBandra Kurla
Complex, Bandra (East),\nMumbai – 400 051."
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
  "_id": "62723addafd7d55eddeddfe4",
  "role": "PICKUPPERSON",
  "firstName": "Ramkrishna ",
  "email": "rampatakar1991@gmail.com",
  "lastName": "Patkar",
  "mobileNo": "7045746060",
  "shortName": "RP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62723addafd7d55eddeddfe4/
profilePhoto_1668056044525_WhatsApp_Image_20221110_at_102139_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "65829f7c65d49d78457ec7be",
  "role": "SITEENGINEER",
  "firstName": "Vaibhav",
  "email": "vaib1234b@gmail.com",
  "lastName": "Bhagat",
  "mobileNo": "8779534609",
  "designation": "Bachlore Of Engireeing",
  "shortName": "Vaibhav",
  "workWithDocumentMaker": "62691c48afd7d55eddecfda3"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f9147bf3dd69653a591e8c",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Vinita",
  "email": "vinita.surve@vastukala.org",
  "lastName": "Surve",
  "mobileNo": "9820652818",
  "designation": "",
  "shortName": "V",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f9147bf3dd69653a591e8c/
profilePhoto_1668058171670_WhatsApp_Image_20221110_at_105714_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60f9147bf3dd69653a591e8c",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Vinita",
  "email": "vinita.surve@vastukala.org",
  "lastName": "Surve",
  "mobileNo": "9820652818",
  "designation": "",
```

```
"shortName": "V",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f9147bf3dd69653a591e8c/
profilePhoto_1668058171670_WhatsApp_Image_20221110_at_105714_AM.jpeg"
},
"checker": {
"type": "EMPLOYEE",
"_id": "60f9147bf3dd69653a591e8c",
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Vinita",
"email": "vinita.surve@vastukala.org",
"lastName": "Surve",
"mobileNo": "9820652818",
"designation": "",
"shortName": "V",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f9147bf3dd69653a591e8c/
profilePhoto_1668058171670_WhatsApp_Image_20221110_at_105714_AM.jpeg"
},
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
}
],
{
"title": {
"value": "FIIV",
```

```
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "18.97082675682679",
  "longitude": "73.07986410429804"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.07986410429804,
    18.97082675682679
  ]
}
},
```

```
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "18/03/2024 08:47 am"
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": [],
  "remark": null,
  "rateMin": "1",
  "lumpsumValue": "1",
  "rateMax": "1",
  "areaType": {
    "Name": "Saleable",
    "Value": "Saleable",
    "name": "Saleable",
    "value": "Saleable"
  }
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
```

```
"value": "Dapoli",
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Basement",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
```

```
"status": true,
"name": "Plot No.",
"key": "plotNo",
"value": "37 & 68",
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Matrix Landmark ",
  "label": false
},
"selectArea": {
  "status": true,
  "name": "Sector",
  "key": "selectArea",
  "value": "8",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Pushpak Nagar",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
```



```
"label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
```

```
"name": "Flat / Unit / Office / Gala No.",
"key": "selectNo",
"value": "",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
}
```

```
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "label": "Proposed RCC SLab",
    "value": "Proposed_RCC_SLab"
  },
  "flooring": {
    "label": "Proposed Italian Marble Flooring",
    "value": "Proposed_Italian_Marble_Flooring"
  },
  "doors": {
    "label": "Proposed Teak wood door frame with flush doors",
    "value": "Proposed_Teak_wood_door_frame_with_flush_doors"
  },
  "windows": {
    "label": "Proposed Powder coated aluminium sliding windows",
    "value": "Proposed_Powder_coated_aluminium_sliding_windows"
  },
  "fittings": {
    "label": "Proposed Concealed plumbing with C.P. fittings. Concealed wiring",
    "value": "Proposed_Concealed_plumbing_with_C.P._fittings._Concealed_wiring"
  },
  "finishing": {
    "label": "Proposed Cement Plastering",
    "value": "Proposed_Cement_Plastering"
  }
},
"general": {
  "populationClassList": {
    "label": "Middle Class",
    "value": "MiddleClass"
  }
}
```

```
},
"populationGroupList": {
  "label": "Rural",
  "value": "Rural"
},
"townplanApprovedByList": {
  "label": "CIDCO",
  "value": "CIDCO"
},
"asPerActualAgreement": {
  "north": "under construction project",
  "west": "open plot",
  "south": "road",
  "east": "delta greens project"
},
"asPerDocumentAgreement": {
  "north": "",
  "west": "",
  "south": "",
  "east": ""
},
"unitBoundaries": {
  "asPerActual": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "asPerDocument": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
}
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "label": "Middle Class",
    "value": "Middle_Class"
  },
}
```

```
"propertyTypeOfUseList": {
  "label": "Residential Purpose",
  "value": "Residential_Purpose"
},
"propertyOccupiedByList": {
  "label": "Building Under Construction",
  "value": "Building_Under_Construction"
},
"monthlyRent": ""
},
"siteMeasurement": {
  "partitions": {
    "label": "Building Under Construction",
    "value": "Building_Under_Construction"
  },
  "waterTank": {
    "label": "Proposed Municipal Water Supply",
    "value": "Proposed_Municipal_Water_Supply"
  },
  "pavementLaid": {
    "label": "Building Under Construction",
    "value": "Building_Under_Construction"
  },
  "carParking": {
    "label": "Building Under Construction",
    "value": "Building_Under_Construction"
  },
  "constructionWorkStatus": {
    "label": "Under Construction",
    "value": "InProgress"
  },
  "dateOfConstruction": {
    "date": "",
    "month": "1",
    "year": "2028",
    "fullDate": "1/1/2028"
  },
  "propertyTypeList": {
    "label": "Residential",
    "value": "Residential"
  },
  "planningArea": {
    "label": "Residential",
    "value": "Residential"
  },
  "typeOfStructure": {
```

```
"label": "Proposed R.C.C Framed Structure",
"value": "Proposed_R.C.C_Framed_Structure"
},
"qualityOfConstruction": {
"label": "Building is under construction ",
"value": "Building_is_under_construction_"
},
"walls": {
"label": "Building Under Construction",
"value": "Building_Under_Construction"
},
"appearanceOfTheBuilding": {
"label": "Building is under construction ",
"value": "Building_is_under_construction_"
},
"maintenanceOfTheBuilding": {
"label": "Building Under Construction",
"value": "UnderConstruction"
},
"visibleDamageInBuilding": {
"label": "Building Under Construction",
"value": "Building_Under_Construction"
},
"groundStilt": {
"label": "Lower Ground + Ground",
"value": "Lower_Ground+_Ground"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "",
"estimatedAge": "",
"ageOfBuilding": "",
"noOfBasement": "0",
"noOfPodium": "0",
"noOfAmenityFloors": "0",
"noOfFloors": "012",
"flatFloorNo": "",
"noOfLifts": "03",
"noOfLiftsInEachWings": "0",
"noOfDwellingUnitsInBuilding": "010"
},
"finalPlinthArea": {
"area": "0.00"
},
"routeMap": {
"finalLatLng": {
"coordinates": []
}
```

```
    },
    "locationMapImg": [],
  },
  "outward": {
    "status": false,
    "remark": "SYSTEM_GENERATED"
  },
  "rateVerify": {
    "status": false
  },
  "underConstruction": {
    "rccFootingFoundation": {
      "label": "RCC Footing/Foundation",
      "floorsCompleted": "InProgress",
      "percentage": "0.00",
      "isHideFloor": false,
      "status": true
    },
    "rccPlinth": {
      "label": "RCC Plinth",
      "floorsCompleted": "",
      "percentage": "0.00",
      "isHideFloor": false,
      "status": false
    },
    "fullBuildingRcc": {
      "label": "Full Building Rcc",
      "floorsCompleted": "",
      "percentage": "0.00",
      "isHideFloor": false,
      "status": false
    },
    "internalBrickWork": {
      "label": "Internal Brick Work",
      "floorsCompleted": "",
      "percentage": "0.00",
      "isHideFloor": false,
      "status": false
    },
    "externalBrickWork": {
      "label": "External Brick Work",
      "floorsCompleted": "",
      "percentage": "0.00",
      "isHideFloor": false,
      "status": false
    }
  },
}
```

```
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
```



```
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
```

```
"selfieWithSiteVisitImages": [],
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"invoices": [],
"paymentIds": [],
"_id": "65f5d197857bdc098aa492ad",
"ownerName": "Matrix Landmark ",
"ownerPhoneNo": "7977482090",
"appAddress": "Pushpak Nagar, Dapoli, Panvel ",
```

```
"remark": "contact - Sanket Bhosale \n vastukala + Vankar ",
"documents": [
  {
    "documentType": {
      "label": "Any Other Document",
      "value": "60ae124aaa6d152c1801b2f7"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/65f5d197857bdc098aa492ad/
document_1710608748815_1710608924873_Matrix_Landmark.pdf",
    "fileName": "document_1710608748815_1710608924873_Matrix_Landmark.pdf",
    "id": "819688",
    "uploadedBy": "62723addafd7d55eddeddfe4",
    "createdAt": "Sat Mar 16 2024 22:36:31 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "007756",
"createdBy": "62723addafd7d55eddeddfe4",
"caseHistory": [
  {
    "id": "877605",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Sat Mar 16 2024 22:36:31 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Matrix Landmark ",
    "phone": "7977482090",
    "ownershipShare": "",
    "email": "",
    "id": "838686"
  }
],
"proposePurchasers": [],
"siteInspection": [
  {
    "areaType": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "providedBy": {
      "label": "Owner",
      "value": "Owner"
    }
  }
]
```

```
    },
    "_id": "65fb01a65ca1625e50590364",
    "area": "3189",
    "providedByName": "Matrix Landmark ",
    "providedByContactNo": "7977482090"
  }
],
"composition": [
  {
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "282915",
    "name": "Living Room",
    "length": "1.00",
    "length1": "1",
    "length2": "00",
    "width": "1.00",
    "width1": "1",
    "width2": "00",
    "totalArea": "1.00",
    "images": [],
    "extraAreas": [],
    "finalArea": "1.00"
  }
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fb02e95ca1625e505903b5",
    "name": "externalImg_1710948940198_image.jpeg",
    "path": "cases/65f5d197857bdc098aa492ad/
externalImg_1710948940198_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fb02e95ca1625e505903b6",
```

```
    "name": "externalImg_1710948946096_image.jpeg",
    "path": "cases/65f5d197857bdc098aa492ad/
externalImg_1710948946096_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fb02e95ca1625e505903b7",
    "name": "externalImg_1710948947484_image.jpeg",
    "path": "cases/65f5d197857bdc098aa492ad/
externalImg_1710948947484_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fb02e95ca1625e505903b8",
    "name": "externalImg_1710948954049_image.jpeg",
    "path": "cases/65f5d197857bdc098aa492ad/
externalImg_1710948954049_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fb02e95ca1625e505903b9",
    "name": "externalImg_1710948954504_image.jpeg",
    "path": "cases/65f5d197857bdc098aa492ad/
externalImg_1710948954504_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fb02e95ca1625e505903ba",
    "name": "externalImg_1710948959412_image.jpeg",
    "path": "cases/65f5d197857bdc098aa492ad/
externalImg_1710948959412_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fb02e95ca1625e505903bb",
    "name": "externalImg_1710948964284_image.jpeg",
```

```
    "path": "cases/65f5d197857bdc098aa492ad/
externallmg_1710948964284_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fb02e95ca1625e505903bc",
    "name": "externallmg_1710948970949_image.jpeg",
    "path": "cases/65f5d197857bdc098aa492ad/
externallmg_1710948970949_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fb02e95ca1625e505903bd",
    "name": "externallmg_1710948976604_image.jpeg",
    "path": "cases/65f5d197857bdc098aa492ad/
externallmg_1710948976604_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fb02e95ca1625e505903be",
    "name": "externallmg_1710948981314_image.jpeg",
    "path": "cases/65f5d197857bdc098aa492ad/
externallmg_1710948981314_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fb02e95ca1625e505903bf",
    "name": "externallmg_1710948986354_image.jpeg",
    "path": "cases/65f5d197857bdc098aa492ad/
externallmg_1710948986354_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fb02e95ca1625e505903c0",
    "name": "externallmg_1710948990865_image.jpeg",
    "path": "cases/65f5d197857bdc098aa492ad/
externallmg_1710948990865_image.jpeg",
```



```
"orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65fb02e95ca1625e505903c1",
  "name": "externallmg_1710948998544_image.jpeg",
  "path": "cases/65f5d197857bdc098aa492ad/
externallmg_1710948998544_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65fb02e95ca1625e505903c2",
  "name": "externallmg_1710949006424_image.jpeg",
  "path": "cases/65f5d197857bdc098aa492ad/
externallmg_1710949006424_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65fb02e95ca1625e505903c3",
  "name": "externallmg_1710949016268_image.jpeg",
  "path": "cases/65f5d197857bdc098aa492ad/
externallmg_1710949016268_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65fb02e95ca1625e505903c4",
  "name": "externallmg_1710949034573_image.jpeg",
  "path": "cases/65f5d197857bdc098aa492ad/
externallmg_1710949034573_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65fb02e95ca1625e505903c5",
  "name": "externallmg_1710949053768_image.jpeg",
  "path": "cases/65f5d197857bdc098aa492ad/
externallmg_1710949053768_image.jpeg",
  "orientation": "landscape"
}
```

```

    }
  ],
  "externalDocuments": [],
  "processingDocuments": [],
  "leadRemarks": [],
  "audioRemarks": [],
  "remarks": [],
  "createdAt": "2024-03-16T17:06:31.286Z",
  "updatedAt": "2024-03-20T15:39:28.555Z",
  "__v": 0,
  "assignmentType": {
    "value": "Commercial",
    "label": "Commercial"
  },
  },
  "fullAddress": "Residential APF No. Basement Floor, Matrix Landmark , Plot No. 37 &
68, Sector 8, Pushpak Nagar, Village - Dapoli",
  "updatedBy": "65829f7c65d49d78457ec7be",
  "addressForMap": "",
  "caseReferredBy": "62723addafd7d55eddeddfe4",
  "contactPersonName": "Matrix Landmark ",
  "email": "",
  "isExternal": "false",
  "isUrgent": "false",
  "ownershipShare": "",
  "proposePurchaserName": "",
  "purchaseValueAsPerDocument": "",
  "relationWithOwner": "self",
  "siteVisitContactNo": "7977482090",
  "briefDescOfProperty": "Living Room",
  "carpetTotal": "1",
  "finalMeasurementType": "Sq. Ft.",
  "otherCarpetTotal": "0"
}

```

Name	Length	Width	Total
Composition :			
Living Room	1'00"	1'00"	1.00
Other Composition :			