

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "63b666c8191f7b344b00e421"
    },
    "type": "CREDITOFFICER",
    "_id": "65d6e741cf7ad63a0afaa5e0",
    "firstName": "Nagesh",
    "lastName": "Sir",
    "mobileNo": "8087211158",
    "workMobileNo": "9820927890",
    "email": "1rbc.cbdbelapur@bankofindia.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "20000000",
    "discussWithPerson": "Nagesh",
    "expectedFees": 10000,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180a",
  "type": "BANK",
  "name": "Bank of India",
  "displayName": "Bank of India",
  "initial": "BOI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "63b666c8191f7b344b00e421",
  "name": "RBC Belapur",
  "branchCode": "",
  "mobileNo": "2227570151",
  "alternateMobileNo": "",
  "email": "rbc.cbdbelapur@bankofindia.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Bank Of India RBC Cbd Belapur, Bank Of India Building Ground Floor ,
Sector 11, Plot no 11 C B D Belapur, Navi Mumbai - 400614\n"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e2f4b16576061dae469446",
  "zoneName": "Navi Mumbai Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
    "_id": "60b7189d2ffdf65bcd65882b",
    "role": "PICKUPPERSON",
    "firstName": "Ravindra",
    "email": "ravindrakasare186@gmail.com",
    "lastName": "Kasare",
    "mobileNo": "9167204055",
    "shortName": "RBK",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\60b7189d2ffdf65bcd65882b\\
\\profilePhoto_1622701555488_WhatsApp Image 2021-06-03 at 11.46.40 AM.jpeg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "62691c48afd7d55eddecfda3",
    "role": "SITEENGINEER+MAKAR",
    "firstName": "Bhavika",
    "email": "bhavikachavan0102@gmail.com",
    "lastName": "chavan",
    "mobileNo": "8390804382",
    "designation": "Site Engineer",
    "shortName": "BH",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/62691c48afd7d55eddecfda3/
profilePhoto_1668055228258_bhavika.jpeg"
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
    "_id": "60eeaeddf3dd69653a581316",
    "role": "MAKER + RATE VERFIER + CHEAKER",
    "firstName": "Shyam",
    "email": "shyam@vastukala.org",
    "lastName": "Kajvilkar",
    "mobileNo": "9765074720",
    "designation": "",
    "shortName": "SK",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Shym_Photo.jpg"
  },
  "maker": {
    "type": "EMPLOYEE",
    "_id": "60eeaeddf3dd69653a581316",
    "role": "MAKER + RATE VERFIER + CHEAKER",
    "firstName": "Shyam",
    "email": "shyam@vastukala.org",
    "lastName": "Kajvilkar",
```

```
"mobileNo": "9765074720",
"designation": "",
"shortName": "SK",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Shymam_Photo.jpg"
},
"checker": null,
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
},
{
"title": {
"value": "FIIV",
"label": "FIIV"
},
"_id": "60af80072ffdf65bcd658652",
"number": "CAT-I-F-1763"
},
{
"title": {
"value": "Chartered_Engineer",
"label": "Chartered Engineer"
},
"_id": "60af80072ffdf65bcd658653",
```

```
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.00538929162674",
  "longitude": "72.82853225871969"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.82853225871969,
    19.00538929162674
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "19/03/2024 09:31 am"
    }
  ]
},
"visitedDate": [],
"marketAnalysisAndRemark": {
  "audioNotes": []
}
```

```
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Worli",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "65",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": false,
    "name": "District",
    "key": "district",
```

```
"value": "",
"label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Trump Tower Mumbai",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
```

```
"status": true,
"name": "Street 1",
"key": "street1",
"value": "Near SImandhar Jain Temple",
"label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Pandurang Budhakar Marg",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
```



```
"label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "6501",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
```

```
"name": "Mouza",
"key": "mouza",
"value": "",
"label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
}
},
```

```
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
}
```

```
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
  }
}
```

```
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
```



```
"value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"invoices": [],
"paymentIds": [],
"_id": "65f90bcd49003e142a8d89b6",
"ownerName": "Avantika Agarwal",
"ownerPhoneNo": "9820927890",
"appAddress": "flat no.. B6501 65 th floor Trump Tower Near shalimar Jain Temple
Worli ",
"remark": "bankar Nagesh sir ",
"documents": [
{
  "documentType": {
    "label": "Agreement For Sale",
    "value": "60ae1254aa6d152c1801b326"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/65f90bcd49003e142a8d89b6/
document_1710820292196_1710820471822_6501_agreement.pdf",
  "fileName": "document_1710820292196_1710820471822_6501_agreement.pdf",
  "id": "956375",
  "uploadedBy": "60b7189d2ffdf65bcd65882b",
  "createdAt": "Tue Mar 19 2024 09:21:41 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "007801",
"createdBy": "60b7189d2ffdf65bcd65882b",
"caseHistory": [
{
  "id": "290836",
  "title": "Create Lead",
  "description": "Create Lead",
  "datetime": "Tue Mar 19 2024 09:21:41 GMT+0530 (India Standard Time)"
}
],
"owners": [
{
  "name": "Avantika Agarwal",
```

```
"phone": "9820927890",
"ownershipShare": "",
"email": "",
"id": "948955"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
{
"type": "MEASUREMENT_IMAGE",
"status": false,
"_id": "65f9417749003e142a8e80e6",
"name": "externalImg_1710833431259_1710833550677_image_0.jpeg",
"path": "cases/65f90bcd49003e142a8d89b6/
externalImg_1710833431259_1710833550677_image_0.jpeg",
"orientation": "landscape"
},
{
"type": "MEASUREMENT_IMAGE",
"status": false,
"_id": "65f9417749003e142a8e80e7",
"name": "externalImg_1710833439122_1710833550681_image_1.jpeg",
"path": "cases/65f90bcd49003e142a8d89b6/
externalImg_1710833439122_1710833550681_image_1.jpeg",
"orientation": "portrait"
},
{
"type": "MEASUREMENT_IMAGE",
"status": false,
"_id": "65f9417749003e142a8e80e8",
"name": "externalImg_1710833444335_1710833550681_image_2.jpeg",
"path": "cases/65f90bcd49003e142a8d89b6/
externalImg_1710833444335_1710833550681_image_2.jpeg",
"orientation": "portrait"
},
{
"type": "MEASUREMENT_IMAGE",
"status": false,
"_id": "65f9417749003e142a8e80e9",
```

```
    "name": "externallmg_1710833448626_1710833550681_image_3.jpeg",
    "path": "cases/65f90bcd49003e142a8d89b6/
externallmg_1710833448626_1710833550681_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65f9417749003e142a8e80ea",
    "name": "externallmg_1710833451696_1710833550681_image_4.jpeg",
    "path": "cases/65f90bcd49003e142a8d89b6/
externallmg_1710833451696_1710833550681_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65f9417749003e142a8e80eb",
    "name": "externallmg_1710833456376_1710833550681_image_5.jpeg",
    "path": "cases/65f90bcd49003e142a8d89b6/
externallmg_1710833456376_1710833550681_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65f9417749003e142a8e80ec",
    "name": "externallmg_1710833481690_1710833550681_image_6.jpeg",
    "path": "cases/65f90bcd49003e142a8d89b6/
externallmg_1710833481690_1710833550681_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65f9417749003e142a8e80ed",
    "name": "externallmg_1710833560172_1710833550681_image_7.jpeg",
    "path": "cases/65f90bcd49003e142a8d89b6/
externallmg_1710833560172_1710833550681_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65f9417749003e142a8e80ee",
    "name": "externallmg_1710833585493_1710833550681_image_8.jpeg",
```

```
    "path": "cases/65f90bcd49003e142a8d89b6/
externallmg_1710833585493_1710833550681_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65f9417749003e142a8e80ef",
    "name": "externallmg_1710833586853_1710833550681_image_9.jpeg",
    "path": "cases/65f90bcd49003e142a8d89b6/
externallmg_1710833586853_1710833550681_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65f9417749003e142a8e80f0",
    "name": "externallmg_1710833643603_1710833550681_image_10.jpeg",
    "path": "cases/65f90bcd49003e142a8d89b6/
externallmg_1710833643603_1710833550681_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65f9417749003e142a8e80f1",
    "name": "externallmg_1710833686372_1710833550681_image_11.jpeg",
    "path": "cases/65f90bcd49003e142a8d89b6/
externallmg_1710833686372_1710833550681_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65f9417749003e142a8e80f2",
    "name": "externallmg_1710833722117_1710833550681_image_12.jpeg",
    "path": "cases/65f90bcd49003e142a8d89b6/
externallmg_1710833722117_1710833550681_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65f9417749003e142a8e80f3",
    "name": "externallmg_1710833740992_1710833550681_image_13.jpeg",
    "path": "cases/65f90bcd49003e142a8d89b6/
externallmg_1710833740992_1710833550681_image_13.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "65f9417749003e142a8e80f4",
  "name": "externallmg_1710833768604_1710833550681_image_14.jpeg",
  "path": "cases/65f90bcd49003e142a8d89b6/
externallmg_1710833768604_1710833550681_image_14.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "65f9417749003e142a8e80f5",
  "name": "externallmg_1710833797002_1710833550681_image_15.jpeg",
  "path": "cases/65f90bcd49003e142a8d89b6/
externallmg_1710833797002_1710833550681_image_15.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "65f9417749003e142a8e80f6",
  "name": "externallmg_1710833829160_1710833550681_image_16.jpeg",
  "path": "cases/65f90bcd49003e142a8d89b6/
externallmg_1710833829160_1710833550681_image_16.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "65f9417749003e142a8e80f7",
  "name": "externallmg_1710833865068_1710833550681_image_17.jpeg",
  "path": "cases/65f90bcd49003e142a8d89b6/
externallmg_1710833865068_1710833550681_image_17.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "65f9417749003e142a8e80f8",
  "name": "externallmg_1710833893107_1710833550681_image_18.jpeg",
  "path": "cases/65f90bcd49003e142a8d89b6/
externallmg_1710833893107_1710833550681_image_18.jpeg",
  "orientation": "portrait"
}
```

```
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "65f9417749003e142a8e80f9",
      "name": "externallmg_1710833965643_1710833550681_image_19.jpeg",
      "path": "cases/65f90bcd49003e142a8d89b6/
externallmg_1710833965643_1710833550681_image_19.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "65f941a249003e142a8e81da",
      "name": "externallmg_1710833475361_1710833635497_image_0.jpeg",
      "path": "cases/65f90bcd49003e142a8d89b6/
externallmg_1710833475361_1710833635497_image_0.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "65f941a249003e142a8e81db",
      "name": "externallmg_1710833509210_1710833635498_image_1.jpeg",
      "path": "cases/65f90bcd49003e142a8d89b6/
externallmg_1710833509210_1710833635498_image_1.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "65f941a249003e142a8e81dc",
      "name": "externallmg_1710833592633_1710833635498_image_2.jpeg",
      "path": "cases/65f90bcd49003e142a8d89b6/
externallmg_1710833592633_1710833635498_image_2.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "65f941a249003e142a8e81dd",
      "name": "externallmg_1710833627495_1710833635498_image_3.jpeg",
      "path": "cases/65f90bcd49003e142a8d89b6/
externallmg_1710833627495_1710833635498_image_3.jpeg",
      "orientation": "portrait"
    },
  },
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65f941a249003e142a8e81de",
  "name": "externallmg_1710833652728_1710833635498_image_4.jpeg",
  "path": "cases/65f90bcd49003e142a8d89b6/
externallmg_1710833652728_1710833635498_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65f941a249003e142a8e81df",
  "name": "externallmg_1710833666938_1710833635498_image_5.jpeg",
  "path": "cases/65f90bcd49003e142a8d89b6/
externallmg_1710833666938_1710833635498_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65f941a249003e142a8e81e0",
  "name": "externallmg_1710833678158_1710833635498_image_6.jpeg",
  "path": "cases/65f90bcd49003e142a8d89b6/
externallmg_1710833678158_1710833635498_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65f941a249003e142a8e81e1",
  "name": "externallmg_1710833714283_1710833635498_image_7.jpeg",
  "path": "cases/65f90bcd49003e142a8d89b6/
externallmg_1710833714283_1710833635498_image_7.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65f941a249003e142a8e81e2",
  "name": "externallmg_1710833729542_1710833635498_image_8.jpeg",
  "path": "cases/65f90bcd49003e142a8d89b6/
externallmg_1710833729542_1710833635498_image_8.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f941a249003e142a8e81e3",
    "name": "externallmg_1710833749367_1710833635498_image_9.jpeg",
    "path": "cases/65f90bcd49003e142a8d89b6/
externallmg_1710833749367_1710833635498_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f941a249003e142a8e81e4",
    "name": "externallmg_1710833778823_1710833635498_image_10.jpeg",
    "path": "cases/65f90bcd49003e142a8d89b6/
externallmg_1710833778823_1710833635498_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f941a249003e142a8e81e5",
    "name": "externallmg_1710833794846_1710833635498_image_11.jpeg",
    "path": "cases/65f90bcd49003e142a8d89b6/
externallmg_1710833794846_1710833635498_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f941a249003e142a8e81e6",
    "name": "externallmg_1710833812705_1710833635498_image_12.jpeg",
    "path": "cases/65f90bcd49003e142a8d89b6/
externallmg_1710833812705_1710833635498_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f941a249003e142a8e81e7",
    "name": "externallmg_1710833828120_1710833635498_image_13.jpeg",
    "path": "cases/65f90bcd49003e142a8d89b6/
externallmg_1710833828120_1710833635498_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```



```
    "status": false,
    "_id": "65f941a249003e142a8e81e8",
    "name": "externallmg_1710833898525_1710833635498_image_14.jpeg",
    "path": "cases/65f90bcd49003e142a8d89b6/
externallmg_1710833898525_1710833635498_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f941a249003e142a8e81e9",
    "name": "externallmg_1710833978664_1710833635498_image_15.jpeg",
    "path": "cases/65f90bcd49003e142a8d89b6/
externallmg_1710833978664_1710833635498_image_15.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f941a249003e142a8e81ea",
    "name": "externallmg_1710834005594_1710833635498_image_16.jpeg",
    "path": "cases/65f90bcd49003e142a8d89b6/
externallmg_1710834005594_1710833635498_image_16.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f941a249003e142a8e81eb",
    "name": "externallmg_1710834024169_1710833635498_image_17.jpeg",
    "path": "cases/65f90bcd49003e142a8d89b6/
externallmg_1710834024169_1710833635498_image_17.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f941a249003e142a8e81ec",
    "name": "externallmg_1710834035838_1710833635498_image_18.jpeg",
    "path": "cases/65f90bcd49003e142a8d89b6/
externallmg_1710834035838_1710833635498_image_18.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```

```
    "_id": "65f941a249003e142a8e81ed",
    "name": "externalimg_1710834058174_1710833635498_image_19.jpeg",
    "path": "cases/65f90bcd49003e142a8d89b6/
externalimg_1710834058174_1710833635498_image_19.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "AGR.pdf",
    "filename": "1710831285877_AGR.pdf",
    "path": "cases/65f90bcd49003e142a8d89b6/
processingDocuments/1710831285877_AGR.pdf",
    "size": "7807985",
    "createdAt": "Tue Mar 19 2024 12:24:46 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  }
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-03-19T03:51:41.616Z",
"updatedAt": "2024-03-19T07:41:22.036Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 6501, 65th Floor, Trump Tower Mumbai, Near
SImandhar Jain Temple, Pandurang Budhakar Marg, Village - Worli, Mumbai",
"updatedBy": "62691c48afd7d55eddecfda3",
"addressForMap": "",
"caseReferredBy": "60b7189d2ffdf65bcd65882b",
"contactPersonName": "Avantika Agarwal",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9820927890"
}
```

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			