

```
{
  "typeOfReport": {
    "value": "Project_Finance",
    "label": "Project Finance"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Market_Value",
    "label": "Market Value"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": "",
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "500000"
  },
  "organization": {
    "_id": "643a5702108b68389ed72f71",
    "name": "Mumbai",
    "shortName": "VCIPL/Mumbai",
    "email": "vastukalamumbai@vastukala.com",
    "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
    "city": "Mumbai"
  },
  "client": {
    "_id": "65faa31c5ca1625e5057a7bd",
```

```
"type": "PRIVATE_CLIENT",
"name": "M/s. Shreepati Investments",
"displayName": "M/s. Shreepati Investments",
"initial": "M"
},
"branch": "",
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": "",
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60f91822f3dd69653a5922e3",
    "role": "SITEENGINEER+MAKAR+CHECKER",
    "firstName": "Prayush ",
    "email": "prayush@vastukala.org",
    "lastName": "Parekh ",
    "mobileNo": "9767983840",
    "shortName": "PPP",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "60f91822f3dd69653a5922e3",
    "role": "SITEENGINEER+MAKAR+CHECKER",
    "firstName": "Prayush ",
    "email": "prayush@vastukala.org",
    "lastName": "Parekh ",
    "mobileNo": "9767983840",
    "designation": "",
    "shortName": "PPP",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
    "_id": "60f91822f3dd69653a5922e3",
```

```
"role": "SITEENGINEER+MAKAR+CHECKER",
"firstName": "Prayush ",
"email": "prayush@vastukala.org",
"lastName": "Parekh ",
"mobileNo": "9767983840",
"designation": "",
"shortName": "PPP",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "60f91822f3dd69653a5922e3",
"role": "SITEENGINEER+MAKAR+CHECKER",
"firstName": "Prayush ",
"email": "prayush@vastukala.org",
"lastName": "Parekh ",
"mobileNo": "9767983840",
"designation": "",
"shortName": "PPP",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"checker": {
"type": "EMPLOYEE",
"_id": "60f91822f3dd69653a5922e3",
"role": "SITEENGINEER+MAKAR+CHECKER",
"firstName": "Prayush ",
"email": "prayush@vastukala.org",
"lastName": "Parekh ",
"mobileNo": "9767983840",
"designation": "",
"shortName": "PPP",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "IBBI"
}
}
]
```

```
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
```

```
    "PANNo": "AERPC9086P",
    "fatherName": "Baburao"
  }
]
},
"clientType": {
  "value": "PRIVATE_CLIENT",
  "label": "Private Clients"
},
"location": {
  "latitude": "19.003384955622174",
  "longitude": "72.83828219065678"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
```

```
"label": false
},
"village": {
  "status": false,
  "name": "Village",
  "key": "village",
  "value": "",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Basement",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Parel (East), Mumbai ",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
```

```
"name": "Taluka",
"key": "taluka",
"value": "",
"label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Shreepati Garden",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Dr. Babasaheb Ambedkar Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Krishna Nagar",
  "label": false
}
```

```
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "98, 99, 97, 1/97, 2/97, 3/97, 1A/97, 198/74, 222/74 & 204/74",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
```



```
"key": "blockNo",
"value": "",
"label": true
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
  "label": false
},
"municipalityWardNo": {
  "status": true,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "Parel Sewri Division",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
}
```

```
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "400012",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
```

```
"status": false,
"remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
```

```
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "0",
"selectedBuildUpValue": "0",
"selectedBuildUpMeasurementType": ""
},
"reportImages": {
"frontPageImages": [],
"selfieWithSiteVisitImages": [],
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
```

```
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
```

```
"title": "Superfine finish",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```

```
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"invoices": [],
"paymentIds": [],
"_id": "65faa31c5ca1625e5057a7c2",
"ownerName": "M/s. Shreepati Investments",
"ownerPhoneNo": "9833922579",
"fullAddress": "Residential Project Finance No. Basement Floor, Shreepati Garden,
Krishna Nagar, CTS No. 98, 99, 97, 1/97, 2/97, 3/97, 1A/97, 198/74, 222/74 & 204/74,
Dr. Babasaheb Ambedkar Road, Municipality Ward No. Parel Sewri Division, Parel
(East), Mumbai , 400012",
"remark": "",
```



```
"documents": [
  {
    "documentType": {
      "value": "60ae126eaa6d152c1801b3a2",
      "label": "Area Certificate"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1710924564582_Adobe_Scan_19_Mar_2024.pdf",
    "path": "cases/65faa31c5ca1625e5057a7c2/
document_1710924564582_Adobe_Scan_19_Mar_2024.pdf",
    "id": "590631",
    "uploadedBy": "60f91822f3dd69653a5922e3",
    "createdAt": "Wed Mar 20 2024 14:19:32 GMT+0530 (India Standard Time)"
  }
],
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"caseNumber": "007839",
"createdBy": "60f91822f3dd69653a5922e3",
"caseHistory": [
  {
    "id": "431883",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Mar 20 2024 14:19:32 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "M/s. Shreepati Investments",
    "phone": "9833922579",
    "ownershipShare": "",
    "email": "",
    "id": "272649"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
```

```
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65faa9825ca1625e5057c605",
    "name": "externalimg_r_1710926204026_IMG_20240316_154117.jpg",
    "path": "cases/65faa31c5ca1625e5057a7c2/
externalimg_r_1710926204026_IMG_20240316_154117.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65faa9825ca1625e5057c606",
    "name": "externalimg_r_1710926202783_IMG_20240316_154111.jpg",
    "path": "cases/65faa31c5ca1625e5057a7c2/
externalimg_r_1710926202783_IMG_20240316_154111.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65faa9825ca1625e5057c607",
    "name": "externalimg_r_1710926203224_IMG_20240316_154112.jpg",
    "path": "cases/65faa31c5ca1625e5057a7c2/
externalimg_r_1710926203224_IMG_20240316_154112.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65faa9825ca1625e5057c608",
    "name": "externalimg_r_1710926203655_IMG_20240316_154115.jpg",
    "path": "cases/65faa31c5ca1625e5057a7c2/
externalimg_r_1710926203655_IMG_20240316_154115.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65faa9825ca1625e5057c609",
    "name": "externalimg_r_1710926205708_IMG_20240316_154239.jpg",
    "path": "cases/65faa31c5ca1625e5057a7c2/
externalimg_r_1710926205708_IMG_20240316_154239.jpg",
    "orientation": "landscape"
  }
]
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65faa9825ca1625e5057c60a",
  "name": "externallmg_r_1710926205320_IMG_20240316_154237.jpg",
  "path": "cases/65faa31c5ca1625e5057a7c2/
externallmg_r_1710926205320_IMG_20240316_154237.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65faa9825ca1625e5057c60b",
  "name": "externallmg_r_1710926204421_IMG_20240316_154121.jpg",
  "path": "cases/65faa31c5ca1625e5057a7c2/
externallmg_r_1710926204421_IMG_20240316_154121.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65faa9825ca1625e5057c60c",
  "name": "externallmg_r_1710926204904_IMG_20240316_154220.jpg",
  "path": "cases/65faa31c5ca1625e5057a7c2/
externallmg_r_1710926204904_IMG_20240316_154220.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65faa9825ca1625e5057c60d",
  "name": "externallmg_r_1710926207484_IMG_20240316_154307.jpg",
  "path": "cases/65faa31c5ca1625e5057a7c2/
externallmg_r_1710926207484_IMG_20240316_154307.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65faa9825ca1625e5057c60e",
  "name": "externallmg_r_1710926207091_IMG_20240316_154306.jpg",
  "path": "cases/65faa31c5ca1625e5057a7c2/
externallmg_r_1710926207091_IMG_20240316_154306.jpg",
  "orientation": "landscape"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65faa9825ca1625e5057c60f",
  "name": "externallmg_r_1710926206112_IMG_20240316_154243.jpg",
  "path": "cases/65faa31c5ca1625e5057a7c2/
externallmg_r_1710926206112_IMG_20240316_154243.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65faa9825ca1625e5057c610",
  "name": "externallmg_r_1710926206636_IMG_20240316_154247.jpg",
  "path": "cases/65faa31c5ca1625e5057a7c2/
externallmg_r_1710926206636_IMG_20240316_154247.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65faa9825ca1625e5057c611",
  "name": "externallmg_r_1710926207866_IMG_20240316_154318.jpg",
  "path": "cases/65faa31c5ca1625e5057a7c2/
externallmg_r_1710926207866_IMG_20240316_154318.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65faa9975ca1625e5057c659",
  "name": "externallmg_r_1710926224063_IMG_20240316_154428.jpg",
  "path": "cases/65faa31c5ca1625e5057a7c2/
externallmg_r_1710926224063_IMG_20240316_154428.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65faa9975ca1625e5057c65a",
  "name": "externallmg_r_1710926224424_IMG_20240316_154429.jpg",
  "path": "cases/65faa31c5ca1625e5057a7c2/
externallmg_r_1710926224424_IMG_20240316_154429.jpg",
  "orientation": "landscape"
},
{
```

```
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "65faa9975ca1625e5057c65b",
"name": "externallmg_r_1710926223659_IMG_20240316_154332.jpg",
"path": "cases/65faa31c5ca1625e5057a7c2/
externallmg_r_1710926223659_IMG_20240316_154332.jpg",
"orientation": "landscape"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "65faa9975ca1625e5057c65c",
"name": "externallmg_r_1710926223266_IMG_20240316_154319.jpg",
"path": "cases/65faa31c5ca1625e5057a7c2/
externallmg_r_1710926223266_IMG_20240316_154319.jpg",
"orientation": "landscape"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "65faa9975ca1625e5057c65d",
"name": "externallmg_r_1710926224792_IMG_20240316_154430.jpg",
"path": "cases/65faa31c5ca1625e5057a7c2/
externallmg_r_1710926224792_IMG_20240316_154430.jpg",
"orientation": "landscape"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "65faa9975ca1625e5057c65e",
"name": "externallmg_r_1710926225214_IMG_20240316_154433.jpg",
"path": "cases/65faa31c5ca1625e5057a7c2/
externallmg_r_1710926225214_IMG_20240316_154433.jpg",
"orientation": "landscape"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "65faa9975ca1625e5057c65f",
"name": "externallmg_r_1710926225680_IMG_20240316_154441.jpg",
"path": "cases/65faa31c5ca1625e5057a7c2/
externallmg_r_1710926225680_IMG_20240316_154441.jpg",
"orientation": "landscape"
},
{
"type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "65faa9975ca1625e5057c660",
    "name": "externallmg_r_1710926226147_IMG_20240316_154849.jpg",
    "path": "cases/65faa31c5ca1625e5057a7c2/
externallmg_r_1710926226147_IMG_20240316_154849.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65faa9975ca1625e5057c661",
    "name": "externallmg_r_1710926227381_IMG_20240316_154853.jpg",
    "path": "cases/65faa31c5ca1625e5057a7c2/
externallmg_r_1710926227381_IMG_20240316_154853.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65faa9975ca1625e5057c662",
    "name": "externallmg_r_1710926227890_IMG_20240316_154901.jpg",
    "path": "cases/65faa31c5ca1625e5057a7c2/
externallmg_r_1710926227890_IMG_20240316_154901.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65faa9975ca1625e5057c663",
    "name": "externallmg_r_1710926226666_IMG_20240316_154851.jpg",
    "path": "cases/65faa31c5ca1625e5057a7c2/
externallmg_r_1710926226666_IMG_20240316_154851.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65faa9975ca1625e5057c664",
    "name": "externallmg_r_1710926228349_IMG_20240316_154908.jpg",
    "path": "cases/65faa31c5ca1625e5057a7c2/
externallmg_r_1710926228349_IMG_20240316_154908.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```

```
    "_id": "65faa9975ca1625e5057c665",
    "name": "externallmg_r_1710926228921_IMG_20240316_154909.jpg",
    "path": "cases/65faa31c5ca1625e5057a7c2/
externallmg_r_1710926228921_IMG_20240316_154909.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65faa9aa5ca1625e5057c6cb",
    "name": "externallmg_r_1710926242330_IMG_20240316_155011.jpg",
    "path": "cases/65faa31c5ca1625e5057a7c2/
externallmg_r_1710926242330_IMG_20240316_155011.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65faa9aa5ca1625e5057c6cc",
    "name": "externallmg_r_1710926240478_IMG_20240316_154925.jpg",
    "path": "cases/65faa31c5ca1625e5057a7c2/
externallmg_r_1710926240478_IMG_20240316_154925.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65faa9aa5ca1625e5057c6cd",
    "name": "externallmg_r_1710926245637_IMG_20240316_155012.jpg",
    "path": "cases/65faa31c5ca1625e5057a7c2/
externallmg_r_1710926245637_IMG_20240316_155012.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65faa9aa5ca1625e5057c6ce",
    "name": "externallmg_r_1710926239979_IMG_20240316_154924.jpg",
    "path": "cases/65faa31c5ca1625e5057a7c2/
externallmg_r_1710926239979_IMG_20240316_154924.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65faa9aa5ca1625e5057c6cf",
```

```
    "name": "externallmg_r_1710926245883_IMG_20240316_155027.jpg",
    "path": "cases/65faa31c5ca1625e5057a7c2/
externallmg_r_1710926245883_IMG_20240316_155027.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65faa9aa5ca1625e5057c6d0",
    "name": "externallmg_r_1710926246230_IMG_20240316_155028.jpg",
    "path": "cases/65faa31c5ca1625e5057a7c2/
externallmg_r_1710926246230_IMG_20240316_155028.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65faa9aa5ca1625e5057c6d1",
    "name": "externallmg_r_1710926246585_IMG_20240316_155042.jpg",
    "path": "cases/65faa31c5ca1625e5057a7c2/
externallmg_r_1710926246585_IMG_20240316_155042.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65faa9aa5ca1625e5057c6d2",
    "name": "externallmg_r_1710926246992_IMG_20240316_155136.jpg",
    "path": "cases/65faa31c5ca1625e5057a7c2/
externallmg_r_1710926246992_IMG_20240316_155136.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65faa9aa5ca1625e5057c6d3",
    "name": "externallmg_r_1710926248458_IMG_20240316_155150.jpg",
    "path": "cases/65faa31c5ca1625e5057a7c2/
externallmg_r_1710926248458_IMG_20240316_155150.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65faa9aa5ca1625e5057c6d4",
    "name": "externallmg_r_1710926247472_IMG_20240316_155139.jpg",
```



```

    "path": "cases/65faa31c5ca1625e5057a7c2/
externallmg_r_1710926247472_IMG_20240316_155139.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65faa9aa5ca1625e5057c6d5",
    "name": "externallmg_r_1710926247970_IMG_20240316_155148.jpg",
    "path": "cases/65faa31c5ca1625e5057a7c2/
externallmg_r_1710926247970_IMG_20240316_155148.jpg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-03-20T08:49:32.504Z",
"updatedAt": "2024-03-20T09:17:30.444Z",
"__v": 0,
"updatedBy": "60f91822f3dd69653a5922e3",
"addressForMap": "",
"caseReferredBy": "5ffe92d27737ca4d986b6453",
"contactPersonName": "CA Leena Agarwal",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "CA",
"siteVisitContactNo": "9833922579"
}

```

Name	Length	Width	Total
Composition :			
Other Composition :			