

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "65faae535ca1625e5057df79"
    },
    "type": "CREDITOFFICER",
    "_id": "65faae535ca1625e5057df7b",
    "firstName": "Abhishek",
    "lastName": "Kumar",
    "mobileNo": "",
    "workMobileNo": "9372195994",
    "email": "brmgr2403@mahabank.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "6418456a96b58848585f8cb2",
  "name": "Thane",
  "email": "thane@vastukala.com",
  "phone": "1234567890",
  "address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
  "city": "Thane",
  "shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180e",
  "type": "BANK",
  "name": "Bank Of Maharashtra",
  "displayName": "Bank Of Maharashtra",
  "initial": "BOM",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "65faae535ca1625e5057df79",
  "name": "Housing Finance Branch Thane",
  "branchCode": "2403",
  "mobileNo": "0000000000",
  "alternateMobileNo": "",
  "email": "brmgr2403@mahabank.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": " Plot No B 37, Mahabank Building, 2nd Floor Wagle Industrial Estate,
Thane, Maharashtra 400604"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f90ffff3dd69653a591ae9",
  "zoneName": "THANE ZONE"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "627222afafd7d55eddeddd82",
  "role": "FRONTDESK",
  "firstName": "Pratibha",
  "email": "shilvanta_pratibha@yahoo.co.in",
  "lastName": "Shilvantha",
  "mobileNo": "9821518537",
  "shortName": "PS",
  "workWithDocumentMaker": "60f915d3f3dd69653a592199",
  "profilePhoto": "users/627222afafd7d55eddeddd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "65829f7c65d49d78457ec7be",
  "role": "SITEENGINEER",
  "firstName": "Vaibhav",
  "email": "vaib1234b@gmail.com",
  "lastName": "Bhagat",
  "mobileNo": "8779534609",
  "designation": "Bachlore Of Engireeing",
  "shortName": "Vaibhav",
  "workWithDocumentMaker": "62691c48afd7d55eddecfda3"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": "",
  "shortName": "SK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Shyma_Photo.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627222afafd7d55eddeddd82",
  "role": "FRONTDESK",
  "firstName": "Pratibha",
  "email": "shilvanta_pratibha@yahoo.co.in",
  "lastName": "Shilvantha",
  "mobileNo": "9821518537",
```

```
"designation": "",
"shortName": "PS",
"workWithDocumentMaker": "60f915d3f3dd69653a592199",
"profilePhoto": "users/627222afafd7d55eddeddd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
"checker": {
"type": "EMPLOYEE",
"_id": "60eeaeddf3dd69653a581316",
"role": "MAKER + RATE VERIFIER + CHEAKER",
"firstName": "Shyam",
"email": "shyam@vastukala.org",
"lastName": "Kajvilkar",
"mobileNo": "9765074720",
"designation": "",
"shortName": "SK",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Shyma_Photo.jpg"
},
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
},
{
"title": {
```

```
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.183909014716935",
  "longitude": "72.992059541593"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
}
```

```
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-03-20T17:39:06.677Z",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-03-19",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-03-19",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": [],
  "remark": null,
  "rateMin": "15000",
  "lumpsumValue": "1",
  "rateMax": "16000",
  "areaType": {
    "Name": "Carpet",
    "Value": "Carpet",
    "name": "Carpet",
    "value": "Carpet"
  }
},
"compositionFlatType": {
  "value": "2BHK",
  "label": "2 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
```

```
"status": true,
"name": "State",
"key": "state",
"value": "Maharashtra",
"label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Dighe",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "12",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Navi Mumbai",
```

```
"label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Thane",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Green World",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Thane Belapur Road",
  "label": false
},
"street2": {
  "status": false,
```



```
"name": "Street 2",
"key": "street2",
"value": "",
"label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Near Dighagaon Railway Station",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "I",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "242 / 1 to 7",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
}
```

```
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "1204",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
```

```
"key": "SRO",
"value": "",
"label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 400 708",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_door_with_safety_door",
    "label": "Teak Wood Door frame with Solid door with safety door"
  },
}
```

```
"windows": {
  "value": "Proposed_Powder_coated_aluminium_sliding_windows",
  "label": "Proposed Powder coated aluminium sliding windows"
},
"fittings": {
  "label": "Concealed plumbing with C.P. fittings. Concealed Electrical wiring",
  "value": "Concealed_plumbing_with_C.P._fittings._Concealed_Electrical_wiring"
},
"finishing": {
  "value": "Cement_Plastering_with_POP_false_Celling",
  "label": "Cement Plastering with POP false Ceiling"
}
},
"general": {
  "ownership": {
    "value": "sole_ownership",
    "label": "sole ownership"
  },
  "populationClassList": {
    "label": "Middle Class",
    "value": "MiddleClass"
  },
  "populationGroupList": {
    "label": "Urban",
    "value": "Urban"
  },
  "townplanApprovedByList": {
    "value": "NMMC",
    "label": "Navi Mumbai Municipal Corporation"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "A - Wing, Neelkanth Park",
    "west": "Shankar Mandir Road",
    "south": "TMC STP Plant Vitawa",
    "east": "H-Wing, Green World"
  },
  "asPerDocumentAgreement": {
    "north": "MIDC Land",
    "west": "MIDC Land",
    "south": "Nodal Road and MRTP Railway Line",
    "east": "Thane Belapur Road"
  },
}
```

```
"unitBoundaries": {
  "asPerActual": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "asPerDocument": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "As Occupancy Certificate is received may be assumed
that the construction is as per sanctioned plan. ",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "N.A.",
"unauthorizedConstruction": ""
},
"compositeRate": {
  "remark": "As per site inspection, Total Carpet Area 652.00 Sq. Ft. (Including Balcony
& Dry Area) is more than Carpet Area 527.00 Sq. Ft. mentioned in the agreement
provided to us. For the purpose of valuation, we have considered the area as per
agreement.",
  "depreciationPercentage": "7.5",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "23512.5",
  "depreciatedBuildingRate": "2312.5"
},
"igrRate": {
  "propertyName": "Residential Flat",
  "rate": "67800",
  "landRate": "19700",
  "igrImage": "cases/65fabe265ca1625e5058276e/igr_1711192464427_Image.png",
  "squareMeterGuideLineRate": "74580.00",
  "squareFeetGuideLineRate": "6929.00"
},
"igrFinalRate": {
  "floorRatePercentage": "10",
  "depreciationPercentage": "95",
  "rate": "6674.00",
```

```
"squareFeetGuideLineRate": "6674.00",
"squareMeterGuideLineRate": "71836.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "label": "Middle Class",
    "value": "Middle_Class"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "label": "Owner Occupied",
    "value": "Owner_Occupied"
  },
  "monthlyRent": "N.A.",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
  "meterCardHolderName": "Details not available",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available",
  "floorSpaceIndex": "As per NMMC norms",
  "tenantName": "",
  "maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "label": "6\" Thk. Brick Masonery",
    "value": "6\"_Thk._Brick_Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
```

```
"label": "Municipal Water Supply"
},
"pavementLaid": {
  "value": "Yes",
  "label": "Yes"
},
"carParking": "Covered Parking",
"constructionWorkStatus": {
  "label": "Completed",
  "value": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2019",
  "fullDate": "1/1/2019"
},
"planningArea": {
  "label": "Residential",
  "value": "Residential"
},
"typeOfStructure": {
  "label": "R.C.C. Framed Structure",
  "value": "R.C.C._Framed_Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
```

```
"value": "Good",
"label": "Good"
},
"protAgainstNatDis": {
"value": "Information_not_available",
"label": "Information not available"
},
"sewerageSystem": {
"value": "MunicipalSewerageSystem",
"label": "Connected to Municipal Sewerage System"
},
"walls": {
"value": "1",
"label": "Yes"
},
"appearanceOfTheBuilding": {
"value": "Good",
"label": "Good"
},
"maintenanceOfTheBuilding": {
"label": "Good",
"value": "Good"
},
"maintenancelssues": {
"value": "0",
"label": "No"
},
"visibleDamageInBuilding": {
"value": "0",
"label": "No"
},
"systemOfAirConditioning": {
"value": "Information_not_available",
"label": "Information not available"
},
"provisionOfFirefighting": {
"value": "Information_not_available",
"label": "Information not available"
},
"groundStilt": {
"value": "ground",
"label": "Ground"
},
"yearOfConstructionAsPer": {
"value": "As_Per_Part_Occupancy_Certificate",
"label": "As Per Part Occupancy Certificate"
}
```



```
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "55",
"ageOfBuilding": "5",
"noOfBasement": "0",
"noOfPodium": "0",
"noOfAmenityFloors": "0",
"noOfFloors": "21",
"flatFloorNo": "12",
"noOfLifts": "3",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
  "area": "632.40",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 20%"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/65fabe265ca1625e5058276e/
routeMap_1711452738840_Image.png",
    "routeLat": "19.183912",
    "routeLng": "72.992031",
    "stationName": "Digha",
    "routeDistance": "1.3 Km"
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "2okv3",
```

```
    "name": "2okv3",
    "image": "cases/65fabe265ca1625e5058276e/
routeMap_1711452603066_Image.png"
  }
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "12391351.00",
  "distressValuePercentage": "80",
  "realizableValuePercentage": "90",
  "bookValue": "0",
  "finalValue": "12391351.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Wed Mar 27 2024 11:31:28 GMT+0530 (India Standard Time)",
  "number": "2305750",
  "dayCount": "1",
```

```
"monthCount": "498",
"generatedBy": "60eeaeddf3dd69653a581316"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
```

```
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "4220638.00",
"selectedBuildUpValue": "632.40",
"selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
"frontPageImages": [
{
"status": false,
"_id": "6602b77f5ca1625e50614710",
"name":
"externalimg_1711454079099_WhatsApp_Image_20240326_at_52557_PM_2.jpeg",
```

```
    "path": "cases/65fabe265ca1625e5058276e/
externallmg_1711454079099_WhatsApp_Image_20240326_at_52557_PM_2.jpeg",
    "orientation": "portrait"
  }
],
"selfieWithSiteVisitImages": [],
"externalPhotos": [
  {
    "status": false,
    "_id": "65fb1e0f5ca1625e50590bda",
    "name": "externallmg_1710956000896_image.jpeg",
    "path": "cases/65fabe265ca1625e5058276e/
externallmg_1710956000896_image.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "65fb1e0f5ca1625e50590bdb",
    "name": "externallmg_1710956002496_image.jpeg",
    "path": "cases/65fabe265ca1625e5058276e/
externallmg_1710956002496_image.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "65fb1e0f5ca1625e50590bdc",
    "name": "externallmg_1710956003906_image.jpeg",
    "path": "cases/65fabe265ca1625e5058276e/
externallmg_1710956003906_image.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "65fb1e0f5ca1625e50590bd7",
    "name": "externallmg_1710955996307_image.jpeg",
    "path": "cases/65fabe265ca1625e5058276e/
externallmg_1710955996307_image.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65fb1e0f5ca1625e50590bd5",
    "name": "externallmg_1710955993286_image.jpeg",
    "path": "cases/65fabe265ca1625e5058276e/
externallmg_1710955993286_image.jpeg",
    "orientation": "portrait"
  }
]
```

```
    },
    {
      "status": false,
      "_id": "65fb1e0f5ca1625e50590bd9",
      "name": "externallmg_1710955998646_image.jpeg",
      "path": "cases/65fabe265ca1625e5058276e/
externallmg_1710955998646_image.jpeg",
      "orientation": "landscape"
    },
    {
      "status": false,
      "_id": "65fb1e0f5ca1625e50590bd3",
      "name": "externallmg_1710955990661_image.jpeg",
      "path": "cases/65fabe265ca1625e5058276e/
externallmg_1710955990661_image.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "65fb1e0f5ca1625e50590bd0",
      "name": "externallmg_1710955987751_image.jpeg",
      "path": "cases/65fabe265ca1625e5058276e/
externallmg_1710955987751_image.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "65fb1e0f5ca1625e50590bce",
      "name": "externallmg_1710955986522_image.jpeg",
      "path": "cases/65fabe265ca1625e5058276e/
externallmg_1710955986522_image.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "65fb1e0f5ca1625e50590bcd",
      "name": "externallmg_1710955983627_image.jpeg",
      "path": "cases/65fabe265ca1625e5058276e/
externallmg_1710955983627_image.jpeg",
      "orientation": "landscape"
    },
    {
      "status": false,
      "_id": "65fb1e0f5ca1625e50590bcf",
      "name": "externallmg_1710955987400_image.jpeg",
      "path": "cases/65fabe265ca1625e5058276e/
externallmg_1710955987400_image.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6602b77f5ca1625e50614710",
    "name":
"externallmg_1711454079099_WhatsApp_Image_20240326_at_52557_PM_2.jpeg",
    "path": "cases/65fabe265ca1625e5058276e/
externallmg_1711454079099_WhatsApp_Image_20240326_at_52557_PM_2.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
    "_id": "6603b3365ca1625e5061ec3f",
    "name": "Living Room",
    "path": "cases/65fabe265ca1625e5058276e/
externallmg_1711518518014_WhatsApp_Image_20240327_at_105823_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6603b3365ca1625e5061ec40",
    "name": "Living Room",
    "path": "cases/65fabe265ca1625e5058276e/
externallmg_1711518518019_WhatsApp_Image_20240327_at_105823_1.jpeg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "22198",
    "max": "25333"
  },
  "builtUpRateRange": {
    "min": "18499",
    "max": "21112"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
```



```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
```

```
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
```

```
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "527.00",
"empanelmentNo": [
  "AX33 /CREMON/Valuer/Empanelment/Sr No.55/2019-20"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REPORTGENERATED",
"invoices": [],
"paymentIds": [],
"_id": "65fabe265ca1625e5058276e",
"ownerName": "Miss. Sushama Sadashiv Borate",
"ownerPhoneNo": "0000000000",
"fullAddress": "Residential Flat No. 1204, 12th Floor, Wing - I, Green World, Near
Dighagaon Railway Station, Thane Belapur Road, Village - Dighe, Taluka - Thane,
District - Thane, Navi Mumbai, PIN Code - 400 708, State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae126eaa6d152c1801b39f",
      "label": "Agreement"
    }
  },
  "inputs": {
    "documentDate": "28/08/2012",
    "from": {
      "value": "Promoter",
      "label": "Promoter"
    }
  },
  "Promoter": "M/s. Mount Mary Builders",
  "to": {
```

```
    "value": "purchaser",
    "label": "purchaser"
  },
  "purchaser": "Miss. Sushama Sadashiv Borate"
},
"isHardCopy": false,
"displayStatus": true,
"id": "998838",
"path": "cases/65fabe265ca1625e5058276e/
document_1710931472386_Sushama_Borate_1204_i_Green_World.pdf",
"fileName":
"document_1710931472386_Sushama_Borate_1204_i_Green_World.pdf"
},
{
  "documentType": {
    "value": "60ae1250aa6d152c1801b316",
    "label": "Part Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "27/02/2019",
    "nameOfApprovingAuthority": {
      "value": "Navi_Mumbai_Municipal_Corporation.",
      "label": "Navi Mumbai Municipal Corporation."
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "NRV / BP / 20181BONMMC54296 / 723 / 2019 "
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1711451719165_1711192488062_OC.pdf",
  "path": "cases/65fabe265ca1625e5058276e/
document_1711451719165_1711192488062_OC.pdf",
  "id": "443987",
  "uploadedBy": "627222afafd7d55eddedd82",
  "createdAt": "Tue Mar 26 2024 16:45:19 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "23/04/2010",
```

```
"nameOfApprovingAuthority": {
  "value": "Navi_Mumbai_Municipal_Corporation.",
  "label": "Navi Mumbai Municipal Corporation."
},
"number": {
  "value": "No",
  "label": "No"
},
"No": "NMMC / TPD / BP / CASE No. A - 10620 / 1525 / 2010"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1711451936371_324891.pdf",
"path": "cases/65fabe265ca1625e5058276e/
document_1711451936371_324891.pdf",
"id": "276925",
"uploadedBy": "627222afafd7d55eddeddd82",
"createdAt": "Tue Mar 26 2024 16:48:56 GMT+0530 (India Standard Time)"
}
],
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"caseNumber": "007850",
"createdBy": "627222afafd7d55eddeddd82",
"caseHistory": [
  {
    "id": "224888",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Mar 20 2024 16:14:54 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Miss. Sushama Sadashiv Borate",
    "phone": "0000000000",
    "ownershipShare": "",
    "email": "",
    "id": "328952"
  }
],
"proposePurchasers": [],
"siteInspection": [
  {
```

```
"areaType": {
  "label": "Carpet",
  "value": "Carpet"
},
"providedBy": {
  "label": "Owner",
  "value": "Owner"
},
"_id": "65fb1b045ca1625e50590b72",
"area": "651",
"providedByName": "Miss. Sushama Sadashiv Borate",
"providedByContactNo": "0000000000"
},
],
"composition": [
  {
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "1",
    "name": "Living Room",
    "length": "12.00",
    "length1": "12",
    "length2": "00",
    "width": "15.00",
    "width1": "15",
    "width2": "00",
    "totalArea": "180.00",
    "images": [],
    "extraAreas": [],
    "finalArea": "180.00"
  },
  {
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "1",
    "name": "Bedroom",
    "length": "12.00",
    "length1": "12",
    "length2": "00",
    "width": "7.00",
    "width1": "7",
    "width2": "00",
```

```
"totalArea": "84.00",
"images": [],
"extraAreas": [],
"finalArea": "84.00"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "2",
  "name": "Bedroom",
  "length": "14.00",
  "length1": "14",
  "length2": "00",
  "width": "9.00",
  "width1": "9",
  "width2": "00",
  "totalArea": "126.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "126.00"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "3",
  "name": "Kitchen",
  "length": "13.00",
  "length1": "13",
  "length2": "00",
  "width": "5.00",
  "width1": "5",
  "width2": "00",
  "totalArea": "65.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "65.00"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
}
```

```
"id": "11",
"name": "Toilet",
"length": "4.00",
"length1": "4",
"length2": "0",
"width": "7.00",
"width1": "7",
"width2": "0",
"totalArea": "28.00",
"images": [],
"finalArea": "28.00",
"extraAreas": []
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "5",
  "name": "Toilet",
  "length": "4.00",
  "length1": "4",
  "length2": "00",
  "width": "7.00",
  "width1": "7",
  "width2": "00",
  "totalArea": "28.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "28.00"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "11",
  "name": "Passage",
  "length": "4.00",
  "length1": "4",
  "length2": "0",
  "width": "4.00",
  "width1": "4",
  "width2": "0",
  "totalArea": "16.00",
  "images": [],
```



```
"finalArea": "16.00",
"extraAreas": []
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "11",
  "name": "Balcony",
  "length": "",
  "length1": "3",
  "length2": "0",
  "width": "",
  "width1": "9",
  "width2": "0",
  "totalArea": "27.00",
  "images": [],
  "finalArea": "27.00",
  "extraAreas": []
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "11",
  "name": "Balcony",
  "length": "",
  "length1": "4",
  "length2": "0",
  "width": "",
  "width1": "4",
  "width2": "0",
  "totalArea": "16.00",
  "images": [],
  "finalArea": "16.00",
  "extraAreas": []
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "9",
  "name": "Balcony",
```

```
"length": "5.00",
"length1": "5",
"length2": "00",
"width": "5.00",
"width1": "5",
"width2": "00",
"totalArea": "25.00",
"images": [],
"extraAreas": [],
"finalArea": "25.00"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "11",
  "name": "Balcony",
  "length": "",
  "length1": "5",
  "length2": "0",
  "width": "",
  "width1": "6",
  "width2": "0",
  "totalArea": "30.00",
  "images": [],
  "finalArea": "30.00",
  "extraAreas": []
}
],
"otherComposition": [
  {
    "toBeAdded": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "name": {
      "label": "Dry Balcony",
      "value": "Dry_Balcony"
    },
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "0",
    "length": "3.00",
```

```
"length1": "3",
"length2": "00",
"width": "9.00",
"width1": "9",
"width2": "00",
"totalArea": "27.00",
"images": [],
"extraAreas": [],
"finalArea": "27",
"percentageBeforeTotal": "27.00",
"percentage": "100"
}
],
"externalReport": [],
"documentPerArea": [
{
  "typeOfDocument": {
    "value": "60ae126eaa6d152c1801b39f",
    "label": "Agreement"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "811600",
  "selectAreaTypeDocument": "Carpet",
  "totalAreaDocument": "527",
  "squareMeterArea": "48.96",
  "docFinalBuiltUp": "632.4",
  "docFinalBuiltUpSquareMeter": "58.752",
  "docBuiltupPercentage": "20",
  "docSaleablePercentage": "0",
  "docFinalSaleable": "0",
  "docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
{
  "printlnReport": true,
  "_id": "65feb9985ca1625e505ec0da",
  "property": "Residential Flat",
  "area": "952",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
```

```
"areaType": "Carpet",
"source": "https://www.99acres.com/",
"expectedPrice": "22000000",
"expectedRate": "23109.24",
"builtUpExpectedRate": "19257.70",
"image": "cases/65fabe265ca1625e5058276e/
indicator_1711192230566_Image.png",
"squareMeter": "88.44",
"id": "508903"
},
{
  "printlnReport": true,
  "_id": "65feb9985ca1625e505ec0db",
  "property": "Residential Flat",
  "area": "1050",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "magic_bricks",
  "expectedPrice": "24700000",
  "expectedRate": "23523.81",
  "builtUpExpectedRate": "19603.17",
  "image": "cases/65fabe265ca1625e5058276e/
indicator_1711192254253_Image.png",
  "squareMeter": "97.55",
  "id": "971262"
},
{
  "printlnReport": true,
  "_id": "65feb9985ca1625e505ec0dc",
  "property": "Residential Flat",
  "area": "750",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "magic_bricks",
  "expectedPrice": "19000000",
  "expectedRate": "25333.33",
  "builtUpExpectedRate": "21111.11",
  "image": "cases/65fabe265ca1625e5058276e/
indicator_1711192280097_Image.png",
  "squareMeter": "69.68",
  "id": "344476"
},
```

```
{
  "printlnReport": true,
  "_id": "65feb9985ca1625e505ec0dd",
  "property": "Residential Flat",
  "area": "687",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "source": "Index_no.2",
  "expectedPrice": "15250000",
  "expectedRate": "22197.96",
  "builtUpExpectedRate": "18498.30",
  "image": "cases/65fabe265ca1625e5058276e/
indicator_1711192359978_Image.png",
  "squareMeter": "63.82",
  "id": "589624"
},
{
  "printlnReport": true,
  "_id": "65feb9985ca1625e505ec0de",
  "property": "Residential Flat",
  "area": "913",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "source": "Index_no.2",
  "expectedPrice": "20400000",
  "expectedRate": "22343.92",
  "builtUpExpectedRate": "18619.93",
  "image": "cases/65fabe265ca1625e5058276e/
indicator_1711192386858_Image.png",
  "squareMeter": "84.82",
  "id": "307115"
},
{
  "printlnReport": true,
  "_id": "65feb9985ca1625e505ec0df",
  "property": "Residential Flat",
  "area": "526",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "source": "Index_no.2",
```



```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65fb1e0f5ca1625e50590bcd",
  "name": "externallmg_1710955983627_image.jpeg",
  "path": "cases/65fabe265ca1625e5058276e/
externallmg_1710955983627_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65fb1e0f5ca1625e50590bce",
  "name": "externallmg_1710955986522_image.jpeg",
  "path": "cases/65fabe265ca1625e5058276e/
externallmg_1710955986522_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65fb1e0f5ca1625e50590bcf",
  "name": "externallmg_1710955987400_image.jpeg",
  "path": "cases/65fabe265ca1625e5058276e/
externallmg_1710955987400_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65fb1e0f5ca1625e50590bd0",
  "name": "externallmg_1710955987751_image.jpeg",
  "path": "cases/65fabe265ca1625e5058276e/
externallmg_1710955987751_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65fb1e0f5ca1625e50590bd1",
  "name": "externallmg_1710955988581_image.jpeg",
  "path": "cases/65fabe265ca1625e5058276e/
externallmg_1710955988581_image.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fb1e0f5ca1625e50590bd2",
    "name": "externallmg_1710955989481_image.jpeg",
    "path": "cases/65fabe265ca1625e5058276e/
externallmg_1710955989481_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fb1e0f5ca1625e50590bd3",
    "name": "externallmg_1710955990661_image.jpeg",
    "path": "cases/65fabe265ca1625e5058276e/
externallmg_1710955990661_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fb1e0f5ca1625e50590bd4",
    "name": "externallmg_1710955992402_image.jpeg",
    "path": "cases/65fabe265ca1625e5058276e/
externallmg_1710955992402_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fb1e0f5ca1625e50590bd5",
    "name": "externallmg_1710955993286_image.jpeg",
    "path": "cases/65fabe265ca1625e5058276e/
externallmg_1710955993286_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fb1e0f5ca1625e50590bd6",
    "name": "externallmg_1710955995363_image.jpeg",
    "path": "cases/65fabe265ca1625e5058276e/
externallmg_1710955995363_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```



```
    "status": false,
    "_id": "65fb1e0f5ca1625e50590bd7",
    "name": "externallmg_1710955996307_image.jpeg",
    "path": "cases/65fabe265ca1625e5058276e/
externallmg_1710955996307_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fb1e0f5ca1625e50590bd8",
    "name": "externallmg_1710955997971_image.jpeg",
    "path": "cases/65fabe265ca1625e5058276e/
externallmg_1710955997971_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fb1e0f5ca1625e50590bd9",
    "name": "externallmg_1710955998646_image.jpeg",
    "path": "cases/65fabe265ca1625e5058276e/
externallmg_1710955998646_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fb1e0f5ca1625e50590bda",
    "name": "externallmg_1710956000896_image.jpeg",
    "path": "cases/65fabe265ca1625e5058276e/
externallmg_1710956000896_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fb1e0f5ca1625e50590bdb",
    "name": "externallmg_1710956002496_image.jpeg",
    "path": "cases/65fabe265ca1625e5058276e/
externallmg_1710956002496_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```

```
    "_id": "65fb1e0f5ca1625e50590bdc",
    "name": "externalimg_1710956003906_image.jpeg",
    "path": "cases/65fabe265ca1625e5058276e/
externalimg_1710956003906_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6602b77f5ca1625e50614710",
    "name":
"externalimg_1711454079099_WhatsApp_Image_20240326_at_52557_PM_2.jpeg",
    "path": "cases/65fabe265ca1625e5058276e/
externalimg_1711454079099_WhatsApp_Image_20240326_at_52557_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6602b77f5ca1625e50614711",
    "name":
"externalimg_1711454079111_WhatsApp_Image_20240326_at_52558_PM.jpeg",
    "path": "cases/65fabe265ca1625e5058276e/
externalimg_1711454079111_WhatsApp_Image_20240326_at_52558_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6603b3365ca1625e5061ec3f",
    "name":
"externalimg_1711518518014_WhatsApp_Image_20240327_at_105823_2.jpeg",
    "path": "cases/65fabe265ca1625e5058276e/
externalimg_1711518518014_WhatsApp_Image_20240327_at_105823_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6603b3365ca1625e5061ec40",
    "name":
"externalimg_1711518518019_WhatsApp_Image_20240327_at_105823_1.jpeg",
    "path": "cases/65fabe265ca1625e5058276e/
externalimg_1711518518019_WhatsApp_Image_20240327_at_105823_1.jpeg",
    "orientation": "portrait"
  },
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6603b3365ca1625e5061ec41",
  "name":
"externallmg_1711518518023_WhatsApp_Image_20240327_at_105823.jpeg",
  "path": "cases/65fabe265ca1625e5058276e/
externallmg_1711518518023_WhatsApp_Image_20240327_at_105823.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
{
  "originalname": "AGR-1.pdf",
  "filename": "1711192486824_AGR1.pdf",
  "path": "cases/65fabe265ca1625e5058276e/
processingDocuments/1711192486824_AGR1.pdf",
  "size": "15331420",
  "createdAt": "Sat Mar 23 2024 16:44:48 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "CC-2010.pdf",
  "filename": "1711192487488_CC2010.pdf",
  "path": "cases/65fabe265ca1625e5058276e/
processingDocuments/1711192487488_CC2010.pdf",
  "size": "13970754",
  "createdAt": "Sat Mar 23 2024 16:44:48 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "IGR-01.pdf",
  "filename": "1711192488040_IGR01.pdf",
  "path": "cases/65fabe265ca1625e5058276e/
processingDocuments/1711192488040_IGR01.pdf",
  "size": "150617",
  "createdAt": "Sat Mar 23 2024 16:44:48 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "IGR-02.pdf",
  "filename": "1711192488047_IGR02.pdf",
  "path": "cases/65fabe265ca1625e5058276e/
processingDocuments/1711192488047_IGR02.pdf",
  "size": "148114",
```

```
"createdAt": "Sat Mar 23 2024 16:44:48 GMT+0530 (India Standard Time)",
"uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "IGR-03.pdf",
  "filename": "1711192488052_IGR03.pdf",
  "path": "cases/65fabe265ca1625e5058276e/
processingDocuments/1711192488052_IGR03.pdf",
  "size": "143607",
  "createdAt": "Sat Mar 23 2024 16:44:48 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "IGR-04.pdf",
  "filename": "1711192488057_IGR04.pdf",
  "path": "cases/65fabe265ca1625e5058276e/
processingDocuments/1711192488057_IGR04.pdf",
  "size": "154106",
  "createdAt": "Sat Mar 23 2024 16:44:48 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "OC.pdf",
  "filename": "1711192488062_OC.pdf",
  "path": "cases/65fabe265ca1625e5058276e/
processingDocuments/1711192488062_OC.pdf",
  "size": "818903",
  "createdAt": "Sat Mar 23 2024 16:44:48 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "Summary New=Sushma.xlsx",
  "filename": "1711192488077_Summary_NewSushma.xlsx",
  "path": "cases/65fabe265ca1625e5058276e/
processingDocuments/1711192488077_Summary_NewSushma.xlsx",
  "size": "3045469",
  "createdAt": "Sat Mar 23 2024 16:44:48 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "60eeaeddf3dd69653a581316",
```

```
    "role": "MAKER + RATE VERFIER + CHEAKER",
    "firstName": "Shyam",
    "lastName": "Kajvilkar",
    "profilePhoto": "users\\60eeaeddf3dd69653a581316\
\\profilePhoto_1626255068979_Sh Yam_Photo.jpg"
  },
  "workType": "RATE_VERIFY",
  "display": true,
  "status": true,
  "_id": "65fac8d25ca1625e50586293",
  "note": "Given Approx Rs. 1,23,84,000/-",
  "taskId": "65fabe385ca1625e50582859",
  "createdAt": "2024-03-20T11:30:26.190Z"
}
],
"createdAt": "2024-03-20T10:44:54.667Z",
"updatedAt": "2024-03-27T06:11:21.173Z",
"__v": 0,
"updatedBy": "60eeaeddf3dd69653a581316",
"addressForMap": "",
"caseReferredBy": "62720e52afd7d55eddedc887",
"contactPersonName": "Mr. Windson Kadam",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Owner's Husband",
"siteVisitContactNo": "9167980999",
"briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + 2 Toilet + Passage + 4
Balcony",
"carpetTotal": "625",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "27.00",
"siteVisitDate": "2024-03-19",
"buildingServicesRate": "2500",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Other",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 527.00",
"flatRate": "23700",
"landOtherRate": "21200",
"shopDetails": {
  "typeOfShops": {
```

```

    "label": "Independent Building",
    "value": "Independent_Building"
  },
  "roadFacing": false,
  "mall": false
},
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "27.00",
"otherCompositionSaleableTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "717.20",
"finalCarpetArea": "652.00",
"finalSalableArea": "788.92",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "\nCarpet Area in Sq. Ft. = 527.00\nBalcony Area in Sq.
Ft. = 98.00\nDry Balcony Area in Sq. Ft. = 27.00\n\n",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
}
},
"reportGeneratedDate": "Wed Mar 27 2024 15:59:31 GMT+0530 (India Standard
Time)"
}

```

| Name          | Length | Width  | Total  |
|---------------|--------|--------|--------|
| Composition : |        |        |        |
| Living Room   | 12'00" | 15'00" | 180.00 |
| Bedroom       | 12'00" | 7'00"  | 84.00  |

|                        |        |       |        |
|------------------------|--------|-------|--------|
| Bedroom                | 14'00" | 9'00" | 126.00 |
| Kitchen                | 13'00" | 5'00" | 65.00  |
| Toilet                 | 4'0"   | 7'0"  | 28.00  |
| Toilet                 | 4'00"  | 7'00" | 28.00  |
| Passage                | 4'0"   | 4'0"  | 16.00  |
| Balcony                | 3'0"   | 9'0"  | 27.00  |
| Balcony                | 4'0"   | 4'0"  | 16.00  |
| Balcony                | 5'00"  | 5'00" | 25.00  |
| Balcony                | 5'0"   | 6'0"  | 30.00  |
| Other<br>Composition : |        |       |        |
| Dry Balcony            | 3'00"  | 9'00" | 27.00  |