

```
{
  "typeOfReport": {
    "value": "Project_Finance",
    "label": "Project Finance"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Project_Valuation",
    "label": "Project Valuation"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7cc"
    },
    "type": "CREDITOFFICER",
    "_id": "64338d21d267175d008119f1",
    "firstName": "Manish",
    "lastName": "Jha",
    "mobileNo": "",
    "workMobileNo": "9049983319",
    "email": "manish.jha9@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "40000"
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7cc",
  "branchCode": "13340",
  "type": "BRANCH",
  "name": "SME Chembur Branch",
  "email": "sbi.13340@sbi.co.in",
  "mobileNo": "02225273906",
  "alternateMobileNo": "02225273907",
  "address": "Unit No. 11, (BLDG NO. 11), Ground Floor, Corporate Park, Sion-
Trombay Road, Chembur, Mumbai – 400 071, State – Maharashtra, Country – India.",
  "ledgerName": "",
  "fax": "02225274524",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60f91822f3dd69653a5922e3",
  "role": "SITEENGINEER+MAKAR+CHECKER",
  "firstName": "Prayush ",
  "email": "prayush@vastukala.org",
  "lastName": "Parekh ",
  "mobileNo": "9767983840",
  "shortName": "PPP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "60f91822f3dd69653a5922e3",
  "role": "SITEENGINEER+MAKAR+CHECKER",
  "firstName": "Prayush ",
  "email": "prayush@vastukala.org",
  "lastName": "Parekh ",
  "mobileNo": "9767983840",
  "designation": "",
  "shortName": "PPP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f91822f3dd69653a5922e3",
  "role": "SITEENGINEER+MAKAR+CHECKER",
  "firstName": "Prayush ",
  "email": "prayush@vastukala.org",
  "lastName": "Parekh ",
  "mobileNo": "9767983840",
  "designation": "",
  "shortName": "PPP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "65dee3f79a876858ab30487f",
  "role": "SITEENGINEER",
  "firstName": "Saiprasad",
  "email": "saiprasadpatil1010@gmail.com",
```

```
"lastName": "Patil",
"mobileNo": "8830049996",
"designation": "Valuation Engineer",
"shortName": "SSP",
"workWithDocumentMaker": "60f91822f3dd69653a5922e3",
"profilePhoto": "users/65dee3f79a876858ab30487f/
profilePhoto_1709108668945_image.jpeg"
},
"checker": {
"type": "EMPLOYEE",
"_id": "60f91822f3dd69653a5922e3",
"role": "SITEENGINEER+MAKAR+CHECKER",
"firstName": "Prayush ",
"email": "prayush@vastukala.org",
"lastName": "Parekh ",
"mobileNo": "9767983840",
"designation": "",
"shortName": "PPP",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "IBBI"
},
{
"value": "CAT-I-F-1763",
"label": "FIIV"
},
{
"value": "AM161706-3",
"label": "Chartered Engineer"
}
]
},
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
```

```
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
```

```
"location": {
  "latitude": "19.204309790758632",
  "longitude": "72.98039114445146"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": false,
    "name": "Village",
    "key": "village",
    "value": "",
    "label": true
  }
},
```

```
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "7",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Thane",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Thane",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
```

```
"value": "",
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Srinathji Vishwashree",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
```



```
"status": true,
"name": "Project Name",
"key": "projectName",
"value": "Srinathji Vishwashree",
"label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": true,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "8",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "13/A/1",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
```

```
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
```

```
"name": "Postal Code",
"key": "postalCode",
"value": "400601",
"label": false
},
"suburb": {
"status": false,
"name": "Suburb",
"key": "suburb",
"value": "",
"label": false
}
},
"general": {
"unitBoundaries": {
"isDisplay": false
}
},
"landAndBuildingDetails": {
"actualBuildingBoundaries": [],
"documentsBuildingBoundaries": []
},
"igrFinalRate": {
"floorRatePercentage": "0.00"
},
"outgoingDetail": {
"monthlyRent": ""
},
"siteMeasurement": {
"isSiteVisitAllowed": true
},
"finalPlinthArea": {
"area": "0.00"
},
"routeMap": {
"finalLatLng": {
"coordinates": []
}
},
"locationMapImg": []
},
"outward": {
"status": false,
"remark": "SYSTEM_GENERATED"
},
"rateVerify": {
"status": false
}
```

```
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalPlastering": {
    "label": "External Plastering",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
```

```
"max": "0.00"
},
"builtUpRateRange": {
  "min": "0.00",
  "max": "0.00"
},
"saleableRateRange": {
  "min": "0.00",
  "max": "0.00"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
```



```
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": true,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"invoices": [],
"paymentIds": [],
"_id": "660287ef5ca1625e50606ccb",
"ownerName": "Srinathji Constructions",
"ownerPhoneNo": "9819874899",
"fullAddress": "Residential Project Finance No. 7th Floor, Srinathji Vishwashree,
Srinathji Vishwashree, Hissa No. 8, CTS No. 13/A/1, Taluka - Thane, District - Thane,
Thane, 400601",
"remark": "",
"documents": [
  {
```

```
"documentType": {
  "value": "60ae129faa6d152c1801b47d",
  "label": "RERA Certificate"
},
"inputs": {
  "documentDate": "07/07/2023",
  "nameOfApprovingAuthority": {
    "value": "Maharashtra_Real_Estate_Regulatory_Authority",
    "label": "Maharashtra Real Estate Regulatory Authority"
  },
  "number": {
    "value": "Document_No",
    "label": "Document No"
  },
  "Document_No": "P51700051822"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1714817859054_RERA_Certificate.pdf",
"path": "cases/660287ef5ca1625e50606ccb/
document_1714817859054_RERA_Certificate.pdf",
"id": "939663",
"uploadedBy": "60f91822f3dd69653a5922e3",
"createdAt": "Sat May 04 2024 15:47:40 GMT+0530 (India Standard Time)"
}
],
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"gstNo": "27AAOPJ7283J2Z1",
"caseNumber": "007963",
"createdBy": "60f91822f3dd69653a5922e3",
"caseHistory": [
  {
    "id": "332206",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Mar 26 2024 14:01:43 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Srinathji Constructions",
    "phone": "9819874899",
    "ownershipShare": ""
  }
]
```

```
    "email": "",
    "id": "397916"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66360b8aa98105612e6e7b43",
    "name": "externalImg_1714817929835_IMG20240423WA0026.jpg",
    "path": "cases/660287ef5ca1625e50606ccb/
externalImg_1714817929835_IMG20240423WA0026.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66360b8aa98105612e6e7b44",
    "name": "externalImg_1714817929844_IMG20240423WA0027.jpg",
    "path": "cases/660287ef5ca1625e50606ccb/
externalImg_1714817929844_IMG20240423WA0027.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66360b8aa98105612e6e7b45",
    "name": "externalImg_1714817929855_IMG20240423WA0029.jpg",
    "path": "cases/660287ef5ca1625e50606ccb/
externalImg_1714817929855_IMG20240423WA0029.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66360b8aa98105612e6e7b46",
    "name": "externalImg_1714817929866_IMG20240423WA0030.jpg",
    "path": "cases/660287ef5ca1625e50606ccb/
externalImg_1714817929866_IMG20240423WA0030.jpg",
```

```
"orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66360b8aa98105612e6e7b47",
  "name": "externallmg_1714817929872_IMG20240423WA0031.jpg",
  "path": "cases/660287ef5ca1625e50606ccb/
externallmg_1714817929872_IMG20240423WA0031.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66360b8aa98105612e6e7b48",
  "name": "externallmg_1714817929883_IMG20240423WA0032.jpg",
  "path": "cases/660287ef5ca1625e50606ccb/
externallmg_1714817929883_IMG20240423WA0032.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66360b8aa98105612e6e7b49",
  "name": "externallmg_1714817929894_IMG20240423WA0033.jpg",
  "path": "cases/660287ef5ca1625e50606ccb/
externallmg_1714817929894_IMG20240423WA0033.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66360b8aa98105612e6e7b4a",
  "name": "externallmg_1714817929902_IMG20240423WA0034.jpg",
  "path": "cases/660287ef5ca1625e50606ccb/
externallmg_1714817929902_IMG20240423WA0034.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66360b8aa98105612e6e7b4b",
  "name": "externallmg_1714817929910_IMG20240423WA0035.jpg",
  "path": "cases/660287ef5ca1625e50606ccb/
externallmg_1714817929910_IMG20240423WA0035.jpg",
  "orientation": "landscape"
}
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66360b8aa98105612e6e7b4c",
  "name": "externalimg_1714817929920_IMG20240423WA0036.jpg",
  "path": "cases/660287ef5ca1625e50606ccb/
externalimg_1714817929920_IMG20240423WA0036.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66360b8aa98105612e6e7b4d",
  "name": "externalimg_1714817929928_IMG20240423WA0037.jpg",
  "path": "cases/660287ef5ca1625e50606ccb/
externalimg_1714817929928_IMG20240423WA0037.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66360b8aa98105612e6e7b4e",
  "name": "externalimg_1714817929939_IMG20240423WA0038.jpg",
  "path": "cases/660287ef5ca1625e50606ccb/
externalimg_1714817929939_IMG20240423WA0038.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66360b8aa98105612e6e7b4f",
  "name": "externalimg_1714817929953_IMG20240423WA0039.jpg",
  "path": "cases/660287ef5ca1625e50606ccb/
externalimg_1714817929953_IMG20240423WA0039.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66360b8aa98105612e6e7b50",
  "name": "externalimg_1714817929960_IMG20240423WA0040.jpg",
  "path": "cases/660287ef5ca1625e50606ccb/
externalimg_1714817929960_IMG20240423WA0040.jpg",
  "orientation": "landscape"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66360b8aa98105612e6e7b51",
  "name": "externalimg_1714817929969_IMG20240423WA0041.jpg",
  "path": "cases/660287ef5ca1625e50606ccb/
externalimg_1714817929969_IMG20240423WA0041.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66360b8aa98105612e6e7b52",
  "name": "externalimg_1714817929978_IMG20240423WA0042.jpg",
  "path": "cases/660287ef5ca1625e50606ccb/
externalimg_1714817929978_IMG20240423WA0042.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66360b8aa98105612e6e7b53",
  "name": "externalimg_1714817929988_IMG20240423WA0043.jpg",
  "path": "cases/660287ef5ca1625e50606ccb/
externalimg_1714817929988_IMG20240423WA0043.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66360b8aa98105612e6e7b54",
  "name": "externalimg_1714817929998_IMG20240423WA0044.jpg",
  "path": "cases/660287ef5ca1625e50606ccb/
externalimg_1714817929998_IMG20240423WA0044.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66360b8aa98105612e6e7b55",
  "name": "externalimg_1714817930006_IMG20240423WA0045.jpg",
  "path": "cases/660287ef5ca1625e50606ccb/
externalimg_1714817930006_IMG20240423WA0045.jpg",
  "orientation": "landscape"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66360b8aa98105612e6e7b56",
    "name": "externallmg_1714817930019_IMG20240423WA0046.jpg",
    "path": "cases/660287ef5ca1625e50606ccb/
externallmg_1714817930019_IMG20240423WA0046.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66360b97a98105612e6e7ba6",
    "name": "externallmg_1714817943181_IMG20240423WA0047.jpg",
    "path": "cases/660287ef5ca1625e50606ccb/
externallmg_1714817943181_IMG20240423WA0047.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66360b97a98105612e6e7ba7",
    "name": "externallmg_1714817943185_IMG20240423WA0048.jpg",
    "path": "cases/660287ef5ca1625e50606ccb/
externallmg_1714817943185_IMG20240423WA0048.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66360b97a98105612e6e7ba8",
    "name": "externallmg_1714817943207_IMG20240423WA0049.jpg",
    "path": "cases/660287ef5ca1625e50606ccb/
externallmg_1714817943207_IMG20240423WA0049.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66360b97a98105612e6e7ba9",
    "name": "externallmg_1714817943218_IMG20240423WA0050.jpg",
    "path": "cases/660287ef5ca1625e50606ccb/
externallmg_1714817943218_IMG20240423WA0050.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "66360b97a98105612e6e7baa",
  "name": "externalimg_1714817943229_IMG20240423WA0051.jpg",
  "path": "cases/660287ef5ca1625e50606ccb/
externalimg_1714817943229_IMG20240423WA0051.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66360b97a98105612e6e7bab",
  "name": "externalimg_1714817943239_IMG20240423WA0052.jpg",
  "path": "cases/660287ef5ca1625e50606ccb/
externalimg_1714817943239_IMG20240423WA0052.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66360b97a98105612e6e7bac",
  "name": "externalimg_1714817943254_IMG20240423WA0053.jpg",
  "path": "cases/660287ef5ca1625e50606ccb/
externalimg_1714817943254_IMG20240423WA0053.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66360b97a98105612e6e7bad",
  "name": "externalimg_1714817943265_IMG20240423WA0054.jpg",
  "path": "cases/660287ef5ca1625e50606ccb/
externalimg_1714817943265_IMG20240423WA0054.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66360b97a98105612e6e7bae",
  "name": "externalimg_1714817943277_IMG20240423WA0055.jpg",
  "path": "cases/660287ef5ca1625e50606ccb/
externalimg_1714817943277_IMG20240423WA0055.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```



```
    "_id": "66360b97a98105612e6e7baf",
    "name": "externallmg_1714817943288_IMG20240423WA0056.jpg",
    "path": "cases/660287ef5ca1625e50606ccb/
externallmg_1714817943288_IMG20240423WA0056.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66360b97a98105612e6e7bb0",
    "name": "externallmg_1714817943306_IMG20240423WA0057.jpg",
    "path": "cases/660287ef5ca1625e50606ccb/
externallmg_1714817943306_IMG20240423WA0057.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66360b97a98105612e6e7bb1",
    "name": "externallmg_1714817943323_IMG20240423WA0058.jpg",
    "path": "cases/660287ef5ca1625e50606ccb/
externallmg_1714817943323_IMG20240423WA0058.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66360b97a98105612e6e7bb2",
    "name": "externallmg_1714817943338_IMG20240423WA0059.jpg",
    "path": "cases/660287ef5ca1625e50606ccb/
externallmg_1714817943338_IMG20240423WA0059.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66360b97a98105612e6e7bb3",
    "name": "externallmg_1714817943351_IMG20240423WA0060.jpg",
    "path": "cases/660287ef5ca1625e50606ccb/
externallmg_1714817943351_IMG20240423WA0060.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66360b97a98105612e6e7bb4",
```

```
    "name": "externallmg_1714817943362_IMG20240423WA0061.jpg",
    "path": "cases/660287ef5ca1625e50606ccb/
externallmg_1714817943362_IMG20240423WA0061.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66360b97a98105612e6e7bb5",
    "name": "externallmg_1714817943380_IMG20240423WA0062.jpg",
    "path": "cases/660287ef5ca1625e50606ccb/
externallmg_1714817943380_IMG20240423WA0062.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66360b97a98105612e6e7bb6",
    "name": "externallmg_1714817943392_IMG20240423WA0063.jpg",
    "path": "cases/660287ef5ca1625e50606ccb/
externallmg_1714817943392_IMG20240423WA0063.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66360b97a98105612e6e7bb7",
    "name": "externallmg_1714817943409_IMG20240423WA0065.jpg",
    "path": "cases/660287ef5ca1625e50606ccb/
externallmg_1714817943409_IMG20240423WA0065.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66360b97a98105612e6e7bb8",
    "name": "externallmg_1714817943423_WhatsApp_Image_20240424_at_113002_a
4d9570f.jpg",
    "path": "cases/660287ef5ca1625e50606ccb/
externallmg_1714817943423_WhatsApp_Image_20240424_at_113002_a4d9570f.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66360b97a98105612e6e7bb9",
```

```

    "name": "externalImg_1714817943435_WhatsApp_Image_20240424_at_113002_e7cd5a36.jpg",
    "path": "cases/660287ef5ca1625e50606ccb/externalImg_1714817943435_WhatsApp_Image_20240424_at_113002_e7cd5a36.jpg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-03-26T08:31:43.489Z",
"updatedAt": "2024-05-04T10:19:03.598Z",
"__v": 0,
"updatedBy": "60f91822f3dd69653a5922e3",
"addressForMap": "",
"caseReferredBy": "60f91822f3dd69653a5922e3",
"contactPersonName": "Nishant Jadhav",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9819874899"
}

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			