

```
{
  "typeOfReport": {
    "value": "Cost_Vetting",
    "label": "Cost Vetting"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Cost_Estimation",
    "label": "Cost Estimation"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7cc"
    },
    "type": "CREDITOFFICER",
    "_id": "64338d21d267175d008119f1",
    "firstName": "Manish",
    "lastName": "Jha",
    "mobileNo": "",
    "workMobileNo": "9049983319",
    "email": "manish.jha9@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "40000"
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7cc",
  "branchCode": "13340",
  "type": "BRANCH",
  "name": "SME Chembur Branch",
  "email": "sbi.13340@sbi.co.in",
  "mobileNo": "02225273906",
  "alternateMobileNo": "02225273907",
  "address": "Unit No. 11, (BLDG NO. 11), Ground Floor, Corporate Park, Sion-
Trombay Road, Chembur, Mumbai – 400 071, State – Maharashtra, Country – India.",
  "ledgerName": "",
  "fax": "02225274524",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60f91822f3dd69653a5922e3",
  "role": "SITEENGINEER+MAKAR+CHECKER",
  "firstName": "Prayush ",
  "email": "prayush@vastukala.org",
  "lastName": "Parekh ",
  "mobileNo": "9767983840",
  "shortName": "PPP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "60f91822f3dd69653a5922e3",
  "role": "SITEENGINEER+MAKAR+CHECKER",
  "firstName": "Prayush ",
  "email": "prayush@vastukala.org",
  "lastName": "Parekh ",
  "mobileNo": "9767983840",
  "designation": "",
  "shortName": "PPP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f91822f3dd69653a5922e3",
  "role": "SITEENGINEER+MAKAR+CHECKER",
  "firstName": "Prayush ",
  "email": "prayush@vastukala.org",
  "lastName": "Parekh ",
  "mobileNo": "9767983840",
  "designation": "",
  "shortName": "PPP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60f91822f3dd69653a5922e3",
  "role": "SITEENGINEER+MAKAR+CHECKER",
  "firstName": "Prayush ",
  "email": "prayush@vastukala.org",
```

```
"lastName": "Parekh ",
"mobileNo": "9767983840",
"designation": "",
"shortName": "PPP",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"checker": {
"type": "EMPLOYEE",
"_id": "60f91822f3dd69653a5922e3",
"role": "SITEENGINEER+MAKAR+CHECKER",
"firstName": "Prayush ",
"email": "prayush@vastukala.org",
"lastName": "Parekh ",
"mobileNo": "9767983840",
"designation": "",
"shortName": "PPP",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "IBBI"
},
{
"value": "CAT-I-F-1763",
"label": "FIIV"
},
{
"value": "AM161706-3",
"label": "Chartered Engineer"
}
]
},
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
```

```
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
```

```
"location": {
  "latitude": "19.204188209190193",
  "longitude": "72.98021948307513"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": false,
    "name": "Village",
    "key": "village",
    "value": "",
    "label": true
  },
}
```

```
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "7",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Thane",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Thane",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
```

```
"value": "",
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Srinathji Yashwashree",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
```



```
"status": false,
"name": "Project Name",
"key": "projectName",
"value": "",
"label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": true,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "8",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "18/A/1",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
```

```
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
```

```
"name": "Postal Code",
"key": "postalCode",
"value": "400061",
"label": false
},
"suburb": {
"status": false,
"name": "Suburb",
"key": "suburb",
"value": "",
"label": false
}
},
"general": {
"unitBoundaries": {
"isDisplay": false
}
},
"landAndBuildingDetails": {
"actualBuildingBoundaries": [],
"documentsBuildingBoundaries": []
},
"igrFinalRate": {
"floorRatePercentage": "0.00"
},
"outgoingDetail": {
"monthlyRent": ""
},
"siteMeasurement": {
"isSiteVisitAllowed": true
},
"finalPlinthArea": {
"area": "0.00"
},
"routeMap": {
"finalLatLng": {
"coordinates": []
}
},
"locationMapImg": []
},
"outward": {
"status": false,
"remark": "SYSTEM_GENERATED"
},
"rateVerify": {
"status": false
}
```

```
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalPlastering": {
    "label": "External Plastering",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
```

```
"max": "0.00"
},
"builtUpRateRange": {
  "min": "0.00",
  "max": "0.00"
},
"saleableRateRange": {
  "min": "0.00",
  "max": "0.00"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
```



```
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": true,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"invoices": [],
"paymentIds": [],
"_id": "660288665ca1625e50606eb5",
"ownerName": "Srinathji Constructions",
"ownerPhoneNo": "9819874899",
"fullAddress": "Residential Cost Vetting No. 7th Floor, Srinathji Yashwashree, Hissa No.
8, CTS No. 18/A/1, Taluka - Thane, District - Thane, Thane, 400061",
"remark": "",
"documents": [
  {
    "documentType": {
```

```
    "value": "60ae129faa6d152c1801b47d",
    "label": "RERA Certificate"
  },
  "inputs": {
    "documentDate": "07/07/2023",
    "nameOfApprovingAuthority": {
      "value": "Maharashtra_Real_Estate_Regulatory_Authority",
      "label": "Maharashtra Real Estate Regulatory Authority"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "P51700051822"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1714817781477_RERA_Certificate.pdf",
  "path": "cases/660288665ca1625e50606eb5/
document_1714817781477_RERA_Certificate.pdf",
  "id": "385503",
  "uploadedBy": "60f91822f3dd69653a5922e3",
  "createdAt": "Sat May 04 2024 15:46:25 GMT+0530 (India Standard Time)"
}
],
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"gstNo": "",
"caseNumber": "007964",
"createdBy": "60f91822f3dd69653a5922e3",
"caseHistory": [
  {
    "id": "186149",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Mar 26 2024 14:03:42 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Srinathji Constructions",
    "phone": "9819874899",
    "ownershipShare": "",
    "email": ""
  }
]
```

```
    "id": "691974"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66360bb21b62fe60ef8337e8",
    "name": "externalImg_1714817970651_IMG20240423WA0026.jpg",
    "path": "cases/660288665ca1625e50606eb5/
externalImg_1714817970651_IMG20240423WA0026.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66360bb21b62fe60ef8337e9",
    "name": "externalImg_1714817970656_IMG20240423WA0027.jpg",
    "path": "cases/660288665ca1625e50606eb5/
externalImg_1714817970656_IMG20240423WA0027.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66360bb21b62fe60ef8337ea",
    "name": "externalImg_1714817970665_IMG20240423WA0029.jpg",
    "path": "cases/660288665ca1625e50606eb5/
externalImg_1714817970665_IMG20240423WA0029.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66360bb21b62fe60ef8337eb",
    "name": "externalImg_1714817970676_IMG20240423WA0030.jpg",
    "path": "cases/660288665ca1625e50606eb5/
externalImg_1714817970676_IMG20240423WA0030.jpg",
```

```
"orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66360bb21b62fe60ef8337ec",
  "name": "externallmg_1714817970682_IMG20240423WA0031.jpg",
  "path": "cases/660288665ca1625e50606eb5/
externallmg_1714817970682_IMG20240423WA0031.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66360bb21b62fe60ef8337ed",
  "name": "externallmg_1714817970693_IMG20240423WA0032.jpg",
  "path": "cases/660288665ca1625e50606eb5/
externallmg_1714817970693_IMG20240423WA0032.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66360bb21b62fe60ef8337ee",
  "name": "externallmg_1714817970703_IMG20240423WA0033.jpg",
  "path": "cases/660288665ca1625e50606eb5/
externallmg_1714817970703_IMG20240423WA0033.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66360bb21b62fe60ef8337ef",
  "name": "externallmg_1714817970711_IMG20240423WA0034.jpg",
  "path": "cases/660288665ca1625e50606eb5/
externallmg_1714817970711_IMG20240423WA0034.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66360bb21b62fe60ef8337f0",
  "name": "externallmg_1714817970720_IMG20240423WA0035.jpg",
  "path": "cases/660288665ca1625e50606eb5/
externallmg_1714817970720_IMG20240423WA0035.jpg",
  "orientation": "landscape"
}
```

```
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66360bb21b62fe60ef8337f1",
    "name": "externallmg_1714817970729_IMG20240423WA0036.jpg",
    "path": "cases/660288665ca1625e50606eb5/
externallmg_1714817970729_IMG20240423WA0036.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66360bb21b62fe60ef8337f2",
    "name": "externallmg_1714817970738_IMG20240423WA0037.jpg",
    "path": "cases/660288665ca1625e50606eb5/
externallmg_1714817970738_IMG20240423WA0037.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66360bb21b62fe60ef8337f3",
    "name": "externallmg_1714817970749_IMG20240423WA0038.jpg",
    "path": "cases/660288665ca1625e50606eb5/
externallmg_1714817970749_IMG20240423WA0038.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66360bb21b62fe60ef8337f4",
    "name": "externallmg_1714817970763_IMG20240423WA0039.jpg",
    "path": "cases/660288665ca1625e50606eb5/
externallmg_1714817970763_IMG20240423WA0039.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66360bb21b62fe60ef8337f5",
    "name": "externallmg_1714817970769_IMG20240423WA0040.jpg",
    "path": "cases/660288665ca1625e50606eb5/
externallmg_1714817970769_IMG20240423WA0040.jpg",
    "orientation": "landscape"
  },
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66360bb21b62fe60ef8337f6",
  "name": "externallmg_1714817970778_IMG20240423WA0041.jpg",
  "path": "cases/660288665ca1625e50606eb5/
externallmg_1714817970778_IMG20240423WA0041.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66360bb21b62fe60ef8337f7",
  "name": "externallmg_1714817970787_IMG20240423WA0042.jpg",
  "path": "cases/660288665ca1625e50606eb5/
externallmg_1714817970787_IMG20240423WA0042.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66360bb21b62fe60ef8337f8",
  "name": "externallmg_1714817970797_IMG20240423WA0043.jpg",
  "path": "cases/660288665ca1625e50606eb5/
externallmg_1714817970797_IMG20240423WA0043.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66360bb21b62fe60ef8337f9",
  "name": "externallmg_1714817970807_IMG20240423WA0044.jpg",
  "path": "cases/660288665ca1625e50606eb5/
externallmg_1714817970807_IMG20240423WA0044.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66360bb21b62fe60ef8337fa",
  "name": "externallmg_1714817970815_IMG20240423WA0045.jpg",
  "path": "cases/660288665ca1625e50606eb5/
externallmg_1714817970815_IMG20240423WA0045.jpg",
  "orientation": "landscape"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66360bb21b62fe60ef8337fb",
    "name": "externallmg_1714817970828_IMG20240423WA0046.jpg",
    "path": "cases/660288665ca1625e50606eb5/
externallmg_1714817970828_IMG20240423WA0046.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66360bbc67044b6135ca16d2",
    "name": "externallmg_1714817979762_IMG20240423WA0047.jpg",
    "path": "cases/660288665ca1625e50606eb5/
externallmg_1714817979762_IMG20240423WA0047.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66360bbc67044b6135ca16d3",
    "name": "externallmg_1714817979765_IMG20240423WA0048.jpg",
    "path": "cases/660288665ca1625e50606eb5/
externallmg_1714817979765_IMG20240423WA0048.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66360bbc67044b6135ca16d4",
    "name": "externallmg_1714817979771_IMG20240423WA0049.jpg",
    "path": "cases/660288665ca1625e50606eb5/
externallmg_1714817979771_IMG20240423WA0049.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66360bbc67044b6135ca16d5",
    "name": "externallmg_1714817979784_IMG20240423WA0050.jpg",
    "path": "cases/660288665ca1625e50606eb5/
externallmg_1714817979784_IMG20240423WA0050.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "66360bbc67044b6135ca16d6",
  "name": "externalimg_1714817979793_IMG20240423WA0051.jpg",
  "path": "cases/660288665ca1625e50606eb5/
externalimg_1714817979793_IMG20240423WA0051.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66360bbc67044b6135ca16d7",
  "name": "externalimg_1714817979802_IMG20240423WA0052.jpg",
  "path": "cases/660288665ca1625e50606eb5/
externalimg_1714817979802_IMG20240423WA0052.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66360bbc67044b6135ca16d8",
  "name": "externalimg_1714817979817_IMG20240423WA0053.jpg",
  "path": "cases/660288665ca1625e50606eb5/
externalimg_1714817979817_IMG20240423WA0053.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66360bbc67044b6135ca16d9",
  "name": "externalimg_1714817979830_IMG20240423WA0054.jpg",
  "path": "cases/660288665ca1625e50606eb5/
externalimg_1714817979830_IMG20240423WA0054.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66360bbc67044b6135ca16da",
  "name": "externalimg_1714817979841_IMG20240423WA0055.jpg",
  "path": "cases/660288665ca1625e50606eb5/
externalimg_1714817979841_IMG20240423WA0055.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```



```
    "_id": "66360bbc67044b6135ca16db",
    "name": "externalimg_1714817979852_IMG20240423WA0056.jpg",
    "path": "cases/660288665ca1625e50606eb5/
externalimg_1714817979852_IMG20240423WA0056.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66360bbc67044b6135ca16dc",
    "name": "externalimg_1714817979870_IMG20240423WA0057.jpg",
    "path": "cases/660288665ca1625e50606eb5/
externalimg_1714817979870_IMG20240423WA0057.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66360bbc67044b6135ca16dd",
    "name": "externalimg_1714817979887_IMG20240423WA0058.jpg",
    "path": "cases/660288665ca1625e50606eb5/
externalimg_1714817979887_IMG20240423WA0058.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66360bbc67044b6135ca16de",
    "name": "externalimg_1714817979902_IMG20240423WA0059.jpg",
    "path": "cases/660288665ca1625e50606eb5/
externalimg_1714817979902_IMG20240423WA0059.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66360bbc67044b6135ca16df",
    "name": "externalimg_1714817979914_IMG20240423WA0060.jpg",
    "path": "cases/660288665ca1625e50606eb5/
externalimg_1714817979914_IMG20240423WA0060.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66360bbc67044b6135ca16e0",
```

```
    "name": "externalImg_1714817979925_IMG20240423WA0061.jpg",
    "path": "cases/660288665ca1625e50606eb5/
externalImg_1714817979925_IMG20240423WA0061.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66360bbc67044b6135ca16e1",
    "name": "externalImg_1714817979944_IMG20240423WA0062.jpg",
    "path": "cases/660288665ca1625e50606eb5/
externalImg_1714817979944_IMG20240423WA0062.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66360bbc67044b6135ca16e2",
    "name": "externalImg_1714817979956_IMG20240423WA0063.jpg",
    "path": "cases/660288665ca1625e50606eb5/
externalImg_1714817979956_IMG20240423WA0063.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66360bbc67044b6135ca16e3",
    "name": "externalImg_1714817979972_IMG20240423WA0065.jpg",
    "path": "cases/660288665ca1625e50606eb5/
externalImg_1714817979972_IMG20240423WA0065.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66360bbc67044b6135ca16e4",
    "name": "externalImg_1714817979986_WhatsApp_Image_20240424_at_113002_a
4d9570f.jpg",
    "path": "cases/660288665ca1625e50606eb5/
externalImg_1714817979986_WhatsApp_Image_20240424_at_113002_a4d9570f.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66360bbc67044b6135ca16e5",
```

```

    "name": "externalImg_1714817979999_WhatsApp_Image_20240424_at_113002_e7cd5a36.jpg",
    "path": "cases/660288665ca1625e50606eb5/externalImg_1714817979999_WhatsApp_Image_20240424_at_113002_e7cd5a36.jpg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-03-26T08:33:42.585Z",
"updatedAt": "2024-05-04T10:19:40.200Z",
"__v": 0,
"updatedBy": "60f91822f3dd69653a5922e3",
"addressForMap": "",
"caseReferredBy": "5ff3ead28cda966090eachbbe",
"contactPersonName": "Nishant Jadhav",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9819874899"
}

```

Name	Length	Width	Total
Composition :			
Other Composition :			