

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Carpet_Area",
    "label": "Carpet Area"
  },
  "masterTypeOfPurpose": {
    "value": "Carpet_Area",
    "label": "Carpet Area"
  },
  "toAssess": {
    "value": "Carpet_Area",
    "label": "Carpet Area"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "643a5702108b68389ed72f71",
    "name": "Mumbai",
    "shortName": "VCIPL/Mumbai",
    "email": "vastukalamumbai@vastukala.com",
    "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
    "city": "Mumbai"
  },
  "client": {
    "_id": "65fd5ea15ca1625e505c812c",
    "type": "PRIVATE_CLIENT",
  }
}
```

```
"name": "Mr. Manish Palkar",
"displayName": "Mr. Manish Palkar",
"initial": "M"
},
"branch": "",
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": "",
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "shortName": "MBC",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "64d09914dc9f3034f3008833",
    "role": "SITEENGINEER+MAKAR",
    "firstName": "Meetal",
    "email": "meetalirasal@gmail.com",
    "lastName": "Rasal",
    "mobileNo": "7397882283",
    "designation": "Junior Architect",
    "shortName": "MR",
    "workWithDocumentMaker": ""
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
```

```
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\
\profilePhoto_1622114310919_Manoj C.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "64d09914dc9f3034f3008833",
  "role": "SITEENGINEER+MAKAR",
  "firstName": "Meetal",
  "email": "meetalirasal@gmail.com",
  "lastName": "Rasal",
  "mobileNo": "7397882283",
  "designation": "Junior Architect",
  "shortName": "MR",
  "workWithDocumentMaker": ""
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "5ffe92d27737ca4d986b6453",
  "role": "VALUER",
  "firstName": "Manoj",
  "email": "manoj@vastukala.org",
  "lastName": "Chalikwar",
  "mobileNo": "9819597579",
  "designation": "Registered Valuer",
  "shortName": "MBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\5ffe92d27737ca4d986b6453\
\profilePhoto_1622114310919_Manoj C.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  "type": "EMPLOYEE",
  "_id": "5ffe92d27737ca4d986b6453",
  "role": "VALUER",
  "firstName": "Manoj",
```

```
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
```

```
"clientType": {
  "value": "PRIVATE_CLIENT",
  "label": "Private Clients"
},
"location": {
  "latitude": "19.136853918385015",
  "longitude": "72.83544605829937"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "27/03/2024 12:38 pm"
    },
    {
      "dateTime": "27/03/2024 12:00 am"
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
```

```
"key": "country",
"value": "India",
"label": false
},
"village": {
  "status": false,
  "name": "Village",
  "key": "village",
  "value": "",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "6",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "30",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
}
```

```
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Aadhayay",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": " D N Nagar",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
```

```
"value": "",
"label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Visava CHS",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
```



```
"status": false,
"name": "Block No",
"key": "blockNo",
"value": "",
"label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "604",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
```

```
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Andheri West\t",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  }
},
"locationMapImg": []
```

```
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
}
```

```
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  }
}
```

```
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "true",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"invoices": [],
"paymentIds": [],
"_id": "6603c5a65ca1625e50624d26",
"ownerName": "Mr. Manish Palkar",
"ownerPhoneNo": "9820983537",
"ownershipShare": "",
"email": "",
"siteVisitContactNo": "9820983537",
```



```
"contactPersonName": "Mr. Manish Palkar",
"purchaseValueAsPerDocument": "0",
"owners": [
  {
    "name": "Mr. Manish Palkar",
    "phone": "9820983537",
    "ownershipShare": "",
    "email": "",
    "id": "799790"
  },
  {
    "name": "Mr. Manish Palkar",
    "phone": "9820983537",
    "ownershipShare": "",
    "email": "",
    "id": "740037"
  }
],
"caseReferredBy": "5ffe92d27737ca4d986b6453",
"relationWithOwner": "self",
"fullAddress": "Residential Flat No. 604, 6th Floor, Building No 30, Aadhayay, Visava
CHS, D N Nagar, Andheri West\t, State - Maharashtra, India",
"remark": "",
"documents": [],
"isUrgent": "false",
"isExternal": "false",
"proposePurchaserName": "",
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"scheduleSiteVisitDate": "Invalid date",
"caseNumber": "007983",
"createdBy": "6006d4ce5080a310ac1fdfc2",
"caseHistory": [
  {
    "id": "573960",
    "title": "Create Case",
    "description": "Create Case",
    "datetime": "Wed Mar 27 2024 12:37:18 GMT+0530 (India Standard Time)"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
```

```
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6603d1445ca1625e506285e7",
    "name":
"externallmg_1711526212041_WhatsApp_Image_20240323_at_40838_PM.jpeg",
    "path": "cases/6603c5a65ca1625e50624d26/
externallmg_1711526212041_WhatsApp_Image_20240323_at_40838_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6603d1445ca1625e506285e8",
    "name":
"externallmg_1711526212045_WhatsApp_Image_20240323_at_40839_PM.jpeg",
    "path": "cases/6603c5a65ca1625e50624d26/
externallmg_1711526212045_WhatsApp_Image_20240323_at_40839_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6603d1445ca1625e506285e9",
    "name":
"externallmg_1711526212048_WhatsApp_Image_20240323_at_40840_PM_1.jpeg",
    "path": "cases/6603c5a65ca1625e50624d26/
externallmg_1711526212048_WhatsApp_Image_20240323_at_40840_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6603d1445ca1625e506285ea",
    "name":
"externallmg_1711526212051_WhatsApp_Image_20240323_at_40840_PM_2.jpeg",
    "path": "cases/6603c5a65ca1625e50624d26/
externallmg_1711526212051_WhatsApp_Image_20240323_at_40840_PM_2.jpeg",
    "orientation": "portrait"
  },
  {

```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6603d1445ca1625e506285eb",
    "name":
"externallmg_1711526212052_WhatsApp_Image_20240323_at_40840_PM.jpeg",
    "path": "cases/6603c5a65ca1625e50624d26/
externallmg_1711526212052_WhatsApp_Image_20240323_at_40840_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6603d1445ca1625e506285ec",
    "name":
"externallmg_1711526212055_WhatsApp_Image_20240323_at_40841_PM_1.jpeg",
    "path": "cases/6603c5a65ca1625e50624d26/
externallmg_1711526212055_WhatsApp_Image_20240323_at_40841_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6603d1445ca1625e506285ed",
    "name":
"externallmg_1711526212059_WhatsApp_Image_20240323_at_40841_PM_2.jpeg",
    "path": "cases/6603c5a65ca1625e50624d26/
externallmg_1711526212059_WhatsApp_Image_20240323_at_40841_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6603d1445ca1625e506285ee",
    "name":
"externallmg_1711526212063_WhatsApp_Image_20240323_at_40841_PM.jpeg",
    "path": "cases/6603c5a65ca1625e50624d26/
externallmg_1711526212063_WhatsApp_Image_20240323_at_40841_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6603d1445ca1625e506285ef",
    "name":
"externallmg_1711526212066_WhatsApp_Image_20240323_at_40842_PM.jpeg",
    "path": "cases/6603c5a65ca1625e50624d26/
externallmg_1711526212066_WhatsApp_Image_20240323_at_40842_PM.jpeg",
```

```

    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6603d15a5ca1625e50628638",
    "name": "externallmg_r_1711526234213_IMG_20240322_211849.jpg",
    "path": "cases/6603c5a65ca1625e50624d26/
externallmg_r_1711526234213_IMG_20240322_211849.jpg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-03-27T07:07:18.603Z",
"updatedAt": "2024-03-27T07:57:14.907Z",
"__v": 0,
"addressForMap": "",
"updatedBy": "64d09914dc9f3034f3008833"
}

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			