

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And
Enforcement Of Security Interest Act, 2002",
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_
Enforcement_Of_Security_Interest_Act,_2002"
  },
  "masterTypeOfPurpose": {
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And
Enforcement Of Security Interest Act, 2002",
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_
Enforcement_Of_Security_Interest_Act,_2002"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b9f4"
    },
    "type": "CREDITOFFICER",
    "_id": "648aa63dda662768e994f772",
    "firstName": "Saumita Chakraborty",
    "lastName": "Chakraborty",
    "mobileNo": "",
    "workMobileNo": "9167177426",
    "email": "Saumita.racpc.sion@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "10000000",
  }
}
```

```
"discussWithPerson": "Saumita Chakraborty",
"expectedFees": 5000,
"quotedAmount": "2500"
},
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b9f4",
  "branchCode": "000215",
  "type": "BRANCH",
  "name": "RACPC Sion ",
  "email": "racpc.sion@sbi.co.in",
  "mobileNo": "02225046265",
  "alternateMobileNo": "",
  "address": "B-603 & 604, Kohinoor City, Commercial-1, 6th Floor, Kirol Road, Off
L.B.S. Marg, Kurla (West), Mumbai, Pin Code - 400 070, State - Maharashtra, Country -
India.",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
```

```
"_id": "60e03dac6576061dae462469",
"zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60b7177d2ffdf65bcd65882a",
    "role": "PICKUPPERSON",
    "firstName": "Saurabh",
    "email": "saurabhvelonde143@gmail.com",
    "lastName": "Velonde",
    "mobileNo": "8691048846",
    "shortName": "SSV",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1686816492317_image.jpeg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "60f949ce45132d6a6bddbcc3",
    "role": "SITEENGINEER",
    "firstName": "Tushar ",
    "email": "tusharbhuwad90@gmail.com",
    "lastName": "Bhuwad",
    "mobileNo": "9082053889",
    "designation": "",
    "shortName": "TSB",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/60f949ce45132d6a6bddbcc3/
profilePhoto_1668058314746_WhatsApp_Image_20221110_at_105931_AM.jpeg"
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
    "_id": "60092304a16fab0f2af9b0c2",
    "role": "MAKER + RATE VERFIER + CHEAKER",
    "firstName": "Nitesh",
    "email": "nitesh.khedekar@vastukala.org",
    "lastName": "Khedekar",
    "mobileNo": "8369040652",
    "designation": "",
    "shortName": "NK",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
  },
  "maker": null,
}
```

```
"checker": {
  "type": "EMPLOYEE",
  "_id": "60092304a16fab0f2af9b0c2",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Nitesh",
  "email": "nitesh.khedekar@vastukala.org",
  "lastName": "Khedekar",
  "mobileNo": "8369040652",
  "designation": "",
  "shortName": "NK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "[N]C.C.I.T/I -14/52/2008-09",
        "label": "Wealth Tax"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "6084131a13f01f158c6ea1f3",
    "PANNo": "AEAPC7114Q",
    "role": "VALUER",
    "firstName": "Sharadkumar",
    "fatherName": "Baburao",
    "email": "cmd@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9422171100",
    "designation": "CMD",
    "registrationNo": [
      {
        "title": {
          "value": "Wealth_Tax",
          "label": "Wealth Tax"
        },
        "_id": "6084131a13f01f158c6ea1f4",
        "number": "[N]C.C.I.T/I -14/52/2008-09"
      }
    ],
    "shortName": "SBC",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\6084131a13f01f158c6ea1f3\
\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
```

```
    }
  ]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.07060327984494",
  "longitude": "72.88511981845973"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.88511981845973,
    19.07060327984494
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "30/03/2024 04:58 pm"
    },
    {
      "dateTime": "30/03/2024 12:00 am"
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-03-31",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-03-31",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-03-31",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
}
```

```
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1RK",
  "label": "1 RK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Bandra",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "4",
    "label": false
  },
  "buildingNo": {
    "status": true,
    "name": "Building No",
    "key": "buildingNo",
    "value": "5A",
```

```
"label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Suburban",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Bandra",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Aman SRA Co-op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
```

```
"name": "Sector",
"key": "selectArea",
"value": "",
"label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Golibar Road",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Near Chistiya Jama Masjid ",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
}
```



```
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "13(pt) & 33(pt)",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "A-402",
  "label": false
},
"municipalityWardNo": {
  "status": true,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "H/E",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
```

```
"key": "khataNo",
"value": "",
"label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 055\t",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Santacruz (East), Mumbai",
  "label": false
}
```

```

},
"flatSpecifications": {
  "roof": {
    "value": "R.C.C._slab",
    "label": "R.C.C. slab"
  },
  "flooring": {
    "value": "Vitrified_tiles_flooring",
    "label": "Vitrified tiles flooring"
  },
  "doors": {
    "value": "Teak_wood_door_frame_with_flush_shutters",
    "label": "Teak wood door frame with flush shutters"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows",
    "label": "Powder coated Aluminum sliding windows"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering_+_POP_Finish",
    "label": "Cement Plastering + POP Finish"
  }
},
"general": {
  "ownership": {
    "value": "Sole_Ownership",
    "label": "Sole Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "MCGM",
    "label": "Municipal Corporation of Greater Mumbai (MCGM)"
  },
  "whetherCoveredUnderAnyState": {

```

```
"value": "No",
"label": "No"
},
"asPerActualAgreement": {
  "north": "Internal Road / Residential Building",
  "west": "Slum Area",
  "south": "Sanjeevani Society",
  "east": "Shantara Vikas"
},
"asPerDocumentAgreement": {
  "north": "Information nor available",
  "west": "Information nor available",
  "south": "Information nor available",
  "east": "Information nor available"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "asPerDocument": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "As Occupancy Certificate is received it may be assumed
that the construction is as per Sanctioned Plan.",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "No",
"unauthorizedConstruction": ""
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "21",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "17112",
  "depreciatedBuildingRate": "2212"
},
```

```
"igrRate": {
  "propertyName": "Residential",
  "rate": "146620",
  "landRate": "70850",
  "igrImage": "cases/6607f455f50cbc6699c84e83/igr_1712745337288_Image.png",
  "squareMeterGuideLineRate": "146620.00",
  "squareFeetGuideLineRate": "13621.00"
},
"igrFinalRate": {
  "floorRatePercentage": "0",
  "depreciationPercentage": "86",
  "rate": "12636.00",
  "squareMeterGuideLineRate": "136012.00",
  "squareFeetGuideLineRate": "12636.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Owner_Occupied",
    "label": "Owner Occupied"
  },
  "monthlyRent": "8,000/- Expected rental income per month",
  "assessmentNo": "Information nor available",
  "taxPaidHolderName": "Information nor available",
  "taxAmount": "Information nor available",
  "electricityServiceConnectionNo": "Information nor available",
  "meterCardHolderName": "Information nor available",
  "undividedAreaOfLandAsPerSaleDeed": "Information nor available",
  "floorSpaceIndex": "As per SRA norms",
  "tenantName": "",
  "maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
```

```
},
"siteMeasurement": {
  "roof": {
    "value": "R.C.C._slab",
    "label": "R.C.C. slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Open Parking Space",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "2010",
    "fullDate": "1/1/2010"
  },
  "planningArea": {
    "value": "Residential",
    "label": "Residential"
  },
  "typeOfStructure": {
    "value": "R.C.C._Framed_Structure",
    "label": "R.C.C. Framed Structure"
  },
  "typeOfFoundation": {
    "value": "rcc",
    "label": "R.C.C. Foundation"
  },
  "qualityOfConstruction": {
```

```
"value": "Normal",
"label": "Normal"
},
"materialUsedList": {
"value": "Information_Not_Available",
"label": "Information Not Available"
},
"buildingSpecification": {
"value": "Standard",
"label": "Standard"
},
"structuralSafety": {
"value": "Normal",
"label": "Normal"
},
"protAgainstNatDis": {
"value": "Information_not_available",
"label": "Information not available"
},
"sewerageSystem": {
"value": "MunicipalSewerageSystem",
"label": "Connected to Municipal Sewerage System"
},
"walls": {
"value": "1",
"label": "Yes"
},
"appearanceOfTheBuilding": {
"value": "Normal",
"label": "Normal"
},
"maintenanceOfTheBuilding": {
"value": "Normal",
"label": "Normal"
},
"maintenanceIssues": {
"value": "0",
"label": "No"
},
"visibleDamageInBuilding": {
"value": "0",
"label": "No"
},
"systemOfAirConditioning": {
"value": "0",
"label": "No"
}
```

```
},
"provisionOfFirefighting": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "46",
"ageOfBuilding": "14",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "7",
"flatFloorNo": "4",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "8"
},
"finalPlinthArea": {
  "area": "270.00",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 20%"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/6607f455f50cbc6699c84e83/
routeMap_1712038560862_Image.png",
    "routeLat": "19.072764",
    "routeLng": "72.844901",
    "stationName": "Khar Road",
    "routeDistance": "850m"
  },
  "finalLatLng": {
    "coordinates": [
```



```
    null,
    null
  ],
  "type": "Point"
},
"showLocation": {
  "latlng": true,
  "finallatlng": true
},
"locationMapImg": [
  {
    "id": "48j5jd",
    "name": "48j5jd",
    "image": "cases/6607f455f50cbc6699c84e83/
routeMap_1712038406307_Image.png"
  }
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
```

```
"finaltotal": "3850200.00",
"finalValue": "3850200.00",
"distressValuePercentage": "70",
"realizableValuePercentage": "85",
"bookValueDocument": null,
"purchaseValueDocument": null,
"bookValue": "0"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "3411720.00",
```

```
"selectedBuildUpValue": "270.00",
"selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "660b7dfad91ed25cfbe6d4eb",
      "name": "externallmg_r_1712029178554_TimePhoto_20240331_124756.jpg",
      "path": "cases/6607f455f50cbc6699c84e83/
externallmg_r_1712029178554_TimePhoto_20240331_124756.jpg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "660b7dfad91ed25cfbe6d4e9",
      "name": "externallmg_r_1712029178452_IMG20240331130406.jpg",
      "path": "cases/6607f455f50cbc6699c84e83/
externallmg_r_1712029178452_IMG20240331130406.jpg",
      "orientation": "portrait"
    }
  ],
  "externalPhotos": [
    {
      "status": false,
      "_id": "660b7e0bd91ed25cfbe6d51f",
      "name": "externallmg_r_1712029194879_TimePhoto_20240331_130439.jpg",
      "path": "cases/6607f455f50cbc6699c84e83/
externallmg_r_1712029194879_TimePhoto_20240331_130439.jpg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "660b7dfad91ed25cfbe6d4eb",
      "name": "externallmg_r_1712029178554_TimePhoto_20240331_124756.jpg",
      "path": "cases/6607f455f50cbc6699c84e83/
externallmg_r_1712029178554_TimePhoto_20240331_124756.jpg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "660b7dfad91ed25cfbe6d4ec",
      "name": "externallmg_r_1712029178550_TimePhoto_20240331_124703.jpg",
      "path": "cases/6607f455f50cbc6699c84e83/
externallmg_r_1712029178550_TimePhoto_20240331_124703.jpg",
```

```
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [
  {
    "status": false,
    "_id": "660b7dfad91ed25cfbe6d4e8",
    "name": "externallmg_r_1712029178448_IMG20240331130345.jpg",
    "path": "cases/6607f455f50cbc6699c84e83/
externallmg_r_1712029178448_IMG20240331130345.jpg",
    "orientation": "portrait"
  }
],
"compositionImages": [
  {
    "status": false,
    "_id": "660b7e0bd91ed25cfbe6d51a",
    "name": "Living Room",
    "path": "cases/6607f455f50cbc6699c84e83/
externallmg_r_1712029194869_TimePhoto_20240331_125510.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "660b7e0bd91ed25cfbe6d525",
    "name": "Living Room",
    "path": "cases/6607f455f50cbc6699c84e83/
externallmg_r_1712029194905_TimePhoto_20240331_125446.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "660b7dfad91ed25cfbe6d4e2",
    "name": "Living Room",
    "path": "cases/6607f455f50cbc6699c84e83/
externallmg_r_1712029178424_IMG20240331130103.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "660b7e0bd91ed25cfbe6d517",
    "name": "Living Room",
    "path": "cases/6607f455f50cbc6699c84e83/
externallmg_r_1712029194849_TimePhoto_20240331_125426.jpg",
    "orientation": "portrait"
  }
]
```

```
    }
  ]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "15242.00",
    "max": "17500.00"
  },
  "builtUpRateRange": {
    "min": "12702.00",
    "max": "14584.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
}
```

```
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
```



```
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "225.00",
"empanelmentNo": [
  "SME/TCC/2021-22/85/13"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"invoices": [],
"paymentIds": [],
"_id": "6607f455f50cbc6699c84e83",
"ownerName": "Mrs. Jasmin Rasheed Khan",
"ownerPhoneNo": "0000000000",
"appAddress": "Flat no. A-402, 4th Floor, Building no. 5A, Aman SRA CHS, Santacruz",
,
```

```
"remark": "NPA Account ",
"documents": [
  {
    "documentType": {
      "value": "60ae1245aa6d152c1801b2e3",
      "label": "Sale Deed"
    },
    "inputs": {
      "documentDate": "12/10/2021",
      "from": {
        "value": "Vendor",
        "label": "Vendor"
      },
      "Vendor": "Mrs. Safiunnisa Ahmed Hussain Shaikh",
      "to": {
        "value": "Purchaser",
        "label": "Purchaser"
      },
      "Purchaser": "Mrs. Jasmin Rasheed Khan",
      "number": {
        "value": "Registration_No",
        "label": "Registration No"
      },
      "Registration_No": "9216/2021"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "943110",
    "path": "cases/6607f455f50cbc6699c84e83/
document_1711797300404_1711797493306_Racpc_Sion_Jasmin_Khan_NPA.pdf",
    "fileName":
"document_1711797300404_1711797493306_Racpc_Sion_Jasmin_Khan_NPA.pdf"
  },
  {
    "documentType": {
      "value": "60ae124baa6d152c1801b2fd",
      "label": "Occupancy Certificate"
    },
    "inputs": {
      "documentDate": "25/10/2010",
      "nameOfApprovingAuthority": {
        "value": "Slum_Rehabilitation_Authority_(SRA)",
        "label": "Slum Rehabilitation Authority (SRA)"
      },
      "number": {
        "value": "No",
```

```
    "label": "No"
  },
  "No": "SRA / ENG / 1907 / HE / MHL / AP"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1712041048032_OC.pdf",
"path": "cases/6607f455f50cbc6699c84e83/document_1712041048032_OC.pdf",
"id": "204043",
"uploadedBy": "60f91b6f344e052188ffd1fc",
"createdAt": "Tue Apr 02 2024 12:27:28 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "28/08/2007",
    "nameOfApprovingAuthority": {
      "value": "Slum_Rehabilitation_Authority_(SRA)",
      "label": "Slum Rehabilitation Authority (SRA)"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "SRA / ENG / 1907 / HE / MHL / AP"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1712041101167_CC.pdf",
"path": "cases/6607f455f50cbc6699c84e83/document_1712041101167_CC.pdf",
"id": "600346",
"uploadedBy": "60f91b6f344e052188ffd1fc",
"createdAt": "Tue Apr 02 2024 12:28:21 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "008053",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "715058",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Sat Mar 30 2024 16:45:33 GMT+0530 (India Standard Time)"
  }
]
```

```
}
],
"owners": [
  {
    "name": "Mrs. Jasmin Rasheed Khan",
    "phone": "0000000000",
    "ownershipShare": "",
    "email": "",
    "id": "218887"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "5",
    "name": "Living Room",
    "length": "8.33",
    "length1": "8",
    "length2": "4",
    "width": "17.00",
    "width1": "17",
    "width2": "00",
    "totalArea": "141.67",
    "images": [],
    "finalArea": "141.67",
    "extraAreas": []
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "1",
    "name": "Passage",
    "length": "3.42",
    "length1": "3",
    "length2": "5",
    "width": "4.08",
    "width1": "4",
    "width2": "1",
    "totalArea": "13.95",
```

```
"images": [],
"extraAreas": [],
"finalArea": "13.95"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Bathroom",
  "length": "4.67",
  "length1": "4",
  "length2": "8",
  "width": "3.67",
  "width1": "3",
  "width2": "8",
  "totalArea": "17.11",
  "images": [],
  "extraAreas": [],
  "finalArea": "17.11"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Kitchen",
  "length": "8.92",
  "length1": "8",
  "length2": "11",
  "width": "8.33",
  "width1": "8",
  "width2": "4",
  "totalArea": "74.31",
  "images": [],
  "extraAreas": [],
  "finalArea": "74.31"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
```

```
"name": "WC",
"length": "3.67",
"length1": "3",
"length2": "8",
"width": "2.67",
"width1": "2",
"width2": "8",
"totalArea": "9.78",
"images": [],
"extraAreas": [],
"finalArea": "9.78"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
{
  "typeOfDocument": {
    "value": "60ae1245aa6d152c1801b2e3",
    "label": "Sale Deed"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "256813",
  "selectAreaTypeDocument": "Carpet",
  "totalAreaDocument": "225",
  "squareMeterArea": "20.9",
  "docFinalBuiltUp": "270",
  "docFinalBuiltUpSquareMeter": "25.08",
  "docBuiltupPercentage": "20",
  "docSaleablePercentage": "0",
  "docFinalSaleable": "0",
  "docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
{
  "printlnReport": true,
  "_id": "66166c03834794131c1dd3a3",
  "property": "Sanjeevani SRA building, Santacruz (East)",
  "area": "269.00",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
```

```
"rateType": "sale_Instance",
"areaType": "Carpet",
"floor": "",
"source": "Index_no.2",
"expectedPrice": "4700000",
"expectedRate": "17472.12",
"builtUpExpectedRate": "14560.10",
"image": "cases/6607f455f50cbc6699c84e83/
indicator_1712744800355_Image.png",
"squareMeter": "24.99",
"carpetArea": {
  "area": "269.00",
  "squareMeterArea": "24.99",
  "expectedRate": "17472.12",
  "percentage": "",
  "isManual": false
},
"builtUpArea": {
  "area": "322.80",
  "squareMeterArea": "29.99",
  "expectedRate": "14560.10",
  "percentage": "20",
  "isManual": false
},
"saleableArea": {
  "area": "",
  "squareMeterArea": "0.00",
  "expectedRate": "0.00",
  "percentage": "",
  "isManual": false
},
" id": "989827"
},
{
  "printlnReport": true,
  "_id": "66166c03834794131c1dd3a4",
  "property": "Sanjeevani SRA building, Santacruz (East)",
  "area": "269.00",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "floor": "",
  "source": "Index_no.2",
  "expectedPrice": "4100000.00",
  "expectedRate": "15241.64",
```

```
"builtUpExpectedRate": "12701.36",
"image": "cases/6607f455f50cbc6699c84e83/
indicator_1712744903730_Image.png",
"squareMeter": "24.99",
"carpetArea": {
  "area": "269.00",
  "squareMeterArea": "24.99",
  "expectedRate": "15241.64",
  "percentage": "",
  "isManual": false
},
"builtUpArea": {
  "area": "322.80",
  "squareMeterArea": "29.99",
  "expectedRate": "12701.36",
  "percentage": "20",
  "isManual": false
},
"saleableArea": {
  "area": "",
  "squareMeterArea": "0.00",
  "expectedRate": "0.00",
  "percentage": "",
  "isManual": false
},
" id": "234128"
},
{
  "printlnReport": true,
  "_id": "66166c03834794131c1dd3a5",
  "property": "1 RK Sanjeevani SRA building Khar East",
  "area": "200",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "",
  "source": "Nobroker.com",
  "expectedPrice": "3500000.00",
  "expectedRate": "17500.00",
  "builtUpExpectedRate": "14583.33",
  "image": "cases/6607f455f50cbc6699c84e83/
indicator_1712745143505_Image.png",
  "squareMeter": "18.58",
  "carpetArea": {
    "area": "200.00",
```



```
    "squareMeterArea": "18.58",
    "expectedRate": "17500.00",
    "percentage": "",
    "isManual": false
  },
  "builtUpArea": {
    "area": "240.00",
    "squareMeterArea": "22.30",
    "expectedRate": "14583.33",
    "percentage": "20",
    "isManual": false
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": "",
    "isManual": false
  },
  "id": "562094"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "660b7dcad91ed25cfbe6d4c8",
    "name": "externalImg_1712029129486_Screenshot_2024033114305614_3d9111e2d3171bf4882369f490c087b4.jpg",
    "path": "cases/6607f455f50cbc6699c84e83/externalImg_1712029129486_Screenshot_2024033114305614_3d9111e2d3171bf4882369f490c087b4.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "660b7dcad91ed25cfbe6d4c9",
    "name": "externalImg_r_1712029129404_IMG20240331143701.jpg",
    "path": "cases/6607f455f50cbc6699c84e83/externalImg_r_1712029129404_IMG20240331143701.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "660b7dcad91ed25cfbe6d4ca",
```

```
    "name": "externalimg_r_1712029129190_IMG20240331143639.jpg",
    "path": "cases/6607f455f50cbc6699c84e83/
externalimg_r_1712029129190_IMG20240331143639.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "660b7dfad91ed25cfbe6d4dd",
    "name": "externalimg_1712029178455_Screenshot_2024033113052502_3d9111e2
d3171bf4882369f490c087b4.jpg",
    "path": "cases/6607f455f50cbc6699c84e83/externalimg_1712029178455_Screensh
ot_2024033113052502_3d9111e2d3171bf4882369f490c087b4.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "660b7dfad91ed25cfbe6d4de",
    "name": "externalimg_r_1712029178402_IMG20240331124916.jpg",
    "path": "cases/6607f455f50cbc6699c84e83/
externalimg_r_1712029178402_IMG20240331124916.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "660b7dfad91ed25cfbe6d4df",
    "name": "externalimg_r_1712029178412_IMG20240331125103.jpg",
    "path": "cases/6607f455f50cbc6699c84e83/
externalimg_r_1712029178412_IMG20240331125103.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "660b7dfad91ed25cfbe6d4e0",
    "name": "externalimg_r_1712029178407_IMG20240331124919.jpg",
    "path": "cases/6607f455f50cbc6699c84e83/
externalimg_r_1712029178407_IMG20240331124919.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "660b7dfad91ed25cfbe6d4e1",
```

```
    "name": "externalimg_r_1712029178417_IMG20240331130054.jpg",
    "path": "cases/6607f455f50cbc6699c84e83/
externalimg_r_1712029178417_IMG20240331130054.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "660b7dfad91ed25cfbe6d4e2",
    "name": "externalimg_r_1712029178424_IMG20240331130103.jpg",
    "path": "cases/6607f455f50cbc6699c84e83/
externalimg_r_1712029178424_IMG20240331130103.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "660b7dfad91ed25cfbe6d4e3",
    "name": "externalimg_r_1712029178429_IMG20240331130109.jpg",
    "path": "cases/6607f455f50cbc6699c84e83/
externalimg_r_1712029178429_IMG20240331130109.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "660b7dfad91ed25cfbe6d4e4",
    "name": "externalimg_r_1712029178439_IMG20240331130326.jpg",
    "path": "cases/6607f455f50cbc6699c84e83/
externalimg_r_1712029178439_IMG20240331130326.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "660b7dfad91ed25cfbe6d4e5",
    "name": "externalimg_r_1712029178434_IMG20240331130322.jpg",
    "path": "cases/6607f455f50cbc6699c84e83/
externalimg_r_1712029178434_IMG20240331130322.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "660b7dfad91ed25cfbe6d4e6",
    "name": "externalimg_r_1712029178443_IMG20240331130334.jpg",
```

```
    "path": "cases/6607f455f50cbc6699c84e83/
externallmg_r_1712029178443_IMG20240331130334.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "660b7dfad91ed25cfbe6d4e7",
    "name": "externallmg_r_1712029178445_IMG20240331130338.jpg",
    "path": "cases/6607f455f50cbc6699c84e83/
externallmg_r_1712029178445_IMG20240331130338.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "660b7dfad91ed25cfbe6d4e8",
    "name": "externallmg_r_1712029178448_IMG20240331130345.jpg",
    "path": "cases/6607f455f50cbc6699c84e83/
externallmg_r_1712029178448_IMG20240331130345.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "660b7dfad91ed25cfbe6d4e9",
    "name": "externallmg_r_1712029178452_IMG20240331130406.jpg",
    "path": "cases/6607f455f50cbc6699c84e83/
externallmg_r_1712029178452_IMG20240331130406.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "660b7dfad91ed25cfbe6d4ea",
    "name": "externallmg_r_1712029178546_TimePhoto_20240331_124620.jpg",
    "path": "cases/6607f455f50cbc6699c84e83/
externallmg_r_1712029178546_TimePhoto_20240331_124620.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "660b7dfad91ed25cfbe6d4eb",
    "name": "externallmg_r_1712029178554_TimePhoto_20240331_124756.jpg",
    "path": "cases/6607f455f50cbc6699c84e83/
externallmg_r_1712029178554_TimePhoto_20240331_124756.jpg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "660b7dfad91ed25cfbe6d4ec",
  "name": "externallmg_r_1712029178550_TimePhoto_20240331_124703.jpg",
  "path": "cases/6607f455f50cbc6699c84e83/
externallmg_r_1712029178550_TimePhoto_20240331_124703.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "660b7dfad91ed25cfbe6d4ed",
  "name": "externallmg_r_1712029178560_TimePhoto_20240331_124757.jpg",
  "path": "cases/6607f455f50cbc6699c84e83/
externallmg_r_1712029178560_TimePhoto_20240331_124757.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "660b7dfad91ed25cfbe6d4ee",
  "name": "externallmg_r_1712029178563_TimePhoto_20240331_124759.jpg",
  "path": "cases/6607f455f50cbc6699c84e83/
externallmg_r_1712029178563_TimePhoto_20240331_124759.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "660b7dfad91ed25cfbe6d4ef",
  "name": "externallmg_r_1712029178567_TimePhoto_20240331_124820.jpg",
  "path": "cases/6607f455f50cbc6699c84e83/
externallmg_r_1712029178567_TimePhoto_20240331_124820.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "660b7dfad91ed25cfbe6d4f0",
  "name": "externallmg_r_1712029178572_TimePhoto_20240331_124837.jpg",
  "path": "cases/6607f455f50cbc6699c84e83/
externallmg_r_1712029178572_TimePhoto_20240331_124837.jpg",
  "orientation": "portrait"
}
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "660b7e0bd91ed25cfbe6d515",
  "name": "externallmg_r_1712029194836_TimePhoto_20240331_124848.jpg",
  "path": "cases/6607f455f50cbc6699c84e83/
externallmg_r_1712029194836_TimePhoto_20240331_124848.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "660b7e0bd91ed25cfbe6d516",
  "name": "externallmg_r_1712029194841_TimePhoto_20240331_124853.jpg",
  "path": "cases/6607f455f50cbc6699c84e83/
externallmg_r_1712029194841_TimePhoto_20240331_124853.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "660b7e0bd91ed25cfbe6d517",
  "name": "externallmg_r_1712029194849_TimePhoto_20240331_125426.jpg",
  "path": "cases/6607f455f50cbc6699c84e83/
externallmg_r_1712029194849_TimePhoto_20240331_125426.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "660b7e0bd91ed25cfbe6d518",
  "name": "externallmg_r_1712029194846_TimePhoto_20240331_125424.jpg",
  "path": "cases/6607f455f50cbc6699c84e83/
externallmg_r_1712029194846_TimePhoto_20240331_125424.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "660b7e0bd91ed25cfbe6d519",
  "name": "externallmg_r_1712029194854_TimePhoto_20240331_125438.jpg",
  "path": "cases/6607f455f50cbc6699c84e83/
externallmg_r_1712029194854_TimePhoto_20240331_125438.jpg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "660b7e0bd91ed25cfbe6d51a",
  "name": "externallmg_r_1712029194869_TimePhoto_20240331_125510.jpg",
  "path": "cases/6607f455f50cbc6699c84e83/
externallmg_r_1712029194869_TimePhoto_20240331_125510.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "660b7e0bd91ed25cfbe6d51b",
  "name": "externallmg_r_1712029194864_TimePhoto_20240331_125508.jpg",
  "path": "cases/6607f455f50cbc6699c84e83/
externallmg_r_1712029194864_TimePhoto_20240331_125508.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "660b7e0bd91ed25cfbe6d51c",
  "name": "externallmg_r_1712029194859_TimePhoto_20240331_125504.jpg",
  "path": "cases/6607f455f50cbc6699c84e83/
externallmg_r_1712029194859_TimePhoto_20240331_125504.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "660b7e0bd91ed25cfbe6d51d",
  "name": "externallmg_r_1712029194874_TimePhoto_20240331_125735.jpg",
  "path": "cases/6607f455f50cbc6699c84e83/
externallmg_r_1712029194874_TimePhoto_20240331_125735.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "660b7e0bd91ed25cfbe6d51e",
  "name": "externallmg_r_1712029194887_IMG20240331130136.jpg",
  "path": "cases/6607f455f50cbc6699c84e83/
externallmg_r_1712029194887_IMG20240331130136.jpg",
  "orientation": "portrait"
},
{
```

```
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "660b7e0bd91ed25cfbe6d51f",
"name": "externallmg_r_1712029194879_TimePhoto_20240331_130439.jpg",
"path": "cases/6607f455f50cbc6699c84e83/
externallmg_r_1712029194879_TimePhoto_20240331_130439.jpg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "660b7e0bd91ed25cfbe6d520",
"name": "externallmg_r_1712029194883_TimePhoto_20240331_130440.jpg",
"path": "cases/6607f455f50cbc6699c84e83/
externallmg_r_1712029194883_TimePhoto_20240331_130440.jpg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "660b7e0bd91ed25cfbe6d521",
"name": "externallmg_r_1712029194889_IMG20240331130320.jpg",
"path": "cases/6607f455f50cbc6699c84e83/
externallmg_r_1712029194889_IMG20240331130320.jpg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "660b7e0bd91ed25cfbe6d522",
"name": "externallmg_r_1712029194893_IMG20240331130349.jpg",
"path": "cases/6607f455f50cbc6699c84e83/
externallmg_r_1712029194893_IMG20240331130349.jpg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "660b7e0bd91ed25cfbe6d523",
"name": "externallmg_r_1712029194902_TimePhoto_20240331_124839.jpg",
"path": "cases/6607f455f50cbc6699c84e83/
externallmg_r_1712029194902_TimePhoto_20240331_124839.jpg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
```



```
    "status": false,
    "_id": "660b7e0bd91ed25cfbe6d524",
    "name": "externalimg_r_1712029194897_TimePhoto_20240331_124801.jpg",
    "path": "cases/6607f455f50cbc6699c84e83/
externalimg_r_1712029194897_TimePhoto_20240331_124801.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "660b7e0bd91ed25cfbe6d525",
    "name": "externalimg_r_1712029194905_TimePhoto_20240331_125446.jpg",
    "path": "cases/6607f455f50cbc6699c84e83/
externalimg_r_1712029194905_TimePhoto_20240331_125446.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "660b7e0bd91ed25cfbe6d526",
    "name": "externalimg_r_1712029194910_TimePhoto_20240331_125453.jpg",
    "path": "cases/6607f455f50cbc6699c84e83/
externalimg_r_1712029194910_TimePhoto_20240331_125453.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "660b7e0bd91ed25cfbe6d527",
    "name": "externalimg_r_1712029194913_TimePhoto_20240331_125455.jpg",
    "path": "cases/6607f455f50cbc6699c84e83/
externalimg_r_1712029194913_TimePhoto_20240331_125455.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "660b7e0bd91ed25cfbe6d528",
    "name": "externalimg_r_1712029194916_TimePhoto_20240331_125755.jpg",
    "path": "cases/6607f455f50cbc6699c84e83/
externalimg_r_1712029194916_TimePhoto_20240331_125755.jpg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
```

```
{
  "originalname": "CC.pdf",
  "filename": "1712754529502_CC.pdf",
  "path": "cases/6607f455f50cbc6699c84e83/
processingDocuments/1712754529502_CC.pdf",
  "size": "1037309",
  "createdAt": "Wed Apr 10 2024 18:38:50 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
  "originalname": "Google Loction (1).jpg",
  "filename": "1712754529515_Google_Loction_1.jpg",
  "path": "cases/6607f455f50cbc6699c84e83/
processingDocuments/1712754529515_Google_Loction_1.jpg",
  "size": "183506",
  "createdAt": "Wed Apr 10 2024 18:38:50 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
  "originalname": "Letter of Allotment of Flat.pdf",
  "filename": "1712754529519_Letter_of_Allotment_of_Flat.pdf",
  "path": "cases/6607f455f50cbc6699c84e83/
processingDocuments/1712754529519_Letter_of_Allotment_of_Flat.pdf",
  "size": "2285126",
  "createdAt": "Wed Apr 10 2024 18:38:50 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
  "originalname": "OC.pdf",
  "filename": "1712754529562_OC.pdf",
  "path": "cases/6607f455f50cbc6699c84e83/
processingDocuments/1712754529562_OC.pdf",
  "size": "1701281",
  "createdAt": "Wed Apr 10 2024 18:38:50 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
  "originalname": "Old Report.pdf",
  "filename": "1712754529608_Old_Report.pdf",
  "path": "cases/6607f455f50cbc6699c84e83/
processingDocuments/1712754529608_Old_Report.pdf",
  "size": "6389322",
  "createdAt": "Wed Apr 10 2024 18:38:50 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
```

```
"originalname": "Sale Deed 2021.pdf",
"filename": "1712754529696_Sale_Deed_2021.pdf",
"path": "cases/6607f455f50cbc6699c84e83/
processingDocuments/1712754529696_Sale_Deed_2021.pdf",
"size": "19348178",
"createdAt": "Wed Apr 10 2024 18:38:50 GMT+0530 (India Standard Time)",
"uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
"originalname": "Site Details.jpg",
"filename": "1712754529974_Site_Details.jpg",
"path": "cases/6607f455f50cbc6699c84e83/
processingDocuments/1712754529974_Site_Details.jpg",
"size": "1879533",
"createdAt": "Wed Apr 10 2024 18:38:50 GMT+0530 (India Standard Time)",
"uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
"originalname": "Sketch & Diamentialn.jpg",
"filename": "1712754530010_Sketch__Diamentialn.jpg",
"path": "cases/6607f455f50cbc6699c84e83/
processingDocuments/1712754530010_Sketch__Diamentialn.jpg",
"size": "1347677",
"createdAt": "Wed Apr 10 2024 18:38:50 GMT+0530 (India Standard Time)",
"uploadedBy": "60f91b6f344e052188ffd1fc"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
{
"createdBy": {
"_id": "64dc7184ccaf1e7b7f637f47",
"role": "FRONTDESK",
"firstName": "Binumon",
"lastName": "Moozhickal",
"profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
},
"workType": "RATE_VERIFY",
"display": true,
"status": true,
"_id": "6616739b834794131c1debbf",
"note": "BY MISTAKE COMPLETED (Task Reopen)",
"taskId": "6607f6aff50cbc6699c85892",
"createdAt": "2024-04-10T11:10:19.524Z"
}
```

```
}
],
"createdAt": "2024-03-30T11:15:33.603Z",
"updatedAt": "2024-04-11T04:59:58.102Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. A-402, 4th Floor, Building No 5A, Aman SRA Co-
op. Hsg. Soc. Ltd., Golibar Road, Near Chistiya Jama Masjid , Village - Bandra,
Municipality Ward No. H/E, Santacruz (East), Mumbai, Taluka - Bandra, District -
Mumbai Suburban, PIN - 400 055, State - Maharashtra, India",
"updatedAtBy": "60092304a16fab0f2af9b0c2",
"addressForMap": "",
"caseReferredBy": "60b7177d2ffdf65bcd65882a",
"contactPersonName": "Mrs. Jasmin Rasheed Khan",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Owner",
"siteVisitContactNo": "0000000000",
"briefDescOfProperty": "Living Room + Kitchen + Passage + Bathroom + WC",
"carpetTotal": "256.81999999999994",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "0.00",
"builtupPercentage": "20",
"finalBuiltupArea": "308.18",
"finalCarpetArea": "256.82",
"finalSalableArea": "308.18",
"salablePercentage": "0",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Sale Deed",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalSaleablePercentage": "0",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 225.00",
"reportGeneratedDate": "Tue Apr 09 2024 10:54:25 GMT+0530 (India Standard Time)",
"siteVisitDate": "2024-03-31",
"buildingServicesRate": "2800",
```

```

"flatRate": "17700",
"landOtherRate": "14900",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "0.00",
"otherCompositionSaleableTotal": "0.00"
}

```

Name	Length	Width	Total
Composition :			
Living Room	8'4"	17'00"	141.67
Passage	3'5"	4'1"	13.95
Bathroom	4'8"	3'8"	17.11
Kitchen	8'11"	8'4"	74.31
WC	3'8"	2'8"	9.78
Other Composition :			