

```
{
  "typeOfReport": {
    "value": "Shop",
    "label": "Shop"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Market_Value",
    "label": "Market Value"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "643a5702108b68389ed72f71",
    "name": "Mumbai",
    "shortName": "VCIPL/Mumbai",
    "email": "vastukalamumbai@vastukala.com",
    "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
    "city": "Mumbai"
  },
  "client": {
    "_id": "660d19303aab7968b8b5ebb0",
    "type": "PRIVATE_CLIENT",
  }
}
```

```
"name": "CHROMATOPAK ANALYTICAL INSTRUMENTATION INDIA PVT LTD.",
"displayName": "CHROMATOPAK ANALYTICAL INSTRUMENTATION INDIA PVT
LTD.",
"initial": "C"
},
"branch": "",
"assetsClass": {
"value": "Land_&_Building_/_Immovable_Property",
"label": "Land & Building / Immovable Property"
},
"propertyType": {
"label": "Commercial",
"value": "Commercial"
},
"zone": "",
"staff": {
"pickupPerson": {
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "62720a36afd7d55eddedc4a7",
"role": "SITEENGINEER",
"firstName": "Anwar",
"email": "anwar21786@gmail.com",
"lastName": "Shaikh",
"mobileNo": "8552884500",
"designation": "",
"shortName": "AS",
"workWithDocumentMaker": "",
"profilePhoto": "users/62720a36afd7d55eddedc4a7/
profilePhoto_1668059819446_anwar_2.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "60eeaeddf3dd69653a581316",
```

```
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Shyam",
"email": "shyam@vastukala.org",
"lastName": "Kajvilkar",
"mobileNo": "9765074720",
"designation": "",
"shortName": "SK",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Sh Yam_Photo.jpg"
},
"maker": null,
"checker": null,
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
},
{
"title": {
"value": "FIIV",
"label": "FIIV"
},
"_id": "60af80072ffdf65bcd658652",
"number": "CAT-I-F-1763"
},
{

```

```
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "PRIVATE_CLIENT",
  "label": "Private Clients"
},
"location": {
  "latitude": "19.40156042918136",
  "longitude": "72.82744002101448"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "3/04/2024 02:52 pm"
    }
  ],
}
```

```
{
  "dateTime": "3/04/2024 12:00 am"
}
],
"visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Diwanman",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "Ground",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
```

```
"key": "buildingNo",
"value": "",
"label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Shree kamal Kunj CHSL",
  "label": false
},
}
```

```
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Ambadi Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
```

```
"value": "",
"label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "1",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
```



```
"status": false,
"name": "Khata No",
"key": "khataNo",
"value": "",
"label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Vasai Road",
```

```
    "label": false
  }
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
}
```

```
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
  }
}
```

```
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
```

```
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "true",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"invoices": [],
"paymentIds": [],
"_id": "660d212c3aab7968b8b60a60",
"ownerName": "CHROMATOPAK ANALYTICAL INSTRUMENTATION INDIA PVT LTD.",
"ownerPhoneNo": "0000000000",
"ownershipShare": "",
"email": "",
"siteVisitContactNo": "7738143872",
"contactPersonName": "Supriya",
"purchaseValueAsPerDocument": "0",
"owners": [
  {
    "name": "CHROMATOPAK ANALYTICAL INSTRUMENTATION INDIA PVT LTD.",
    "phone": "0000000000",
    "ownershipShare": "",
    "email": "",
    "id": "284889"
  }
],
"caseReferredBy": "5ffe92d27737ca4d986b6453",
"relationWithOwner": "Self",
"fullAddress": "Commercial Shop No. 1, Ground Floor, Shree kamal Kunj CHSL,
Ambadi Road, Village - Diwanman, Vasai Road, State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae124eaa6d152c1801b30b",
      "label": "Other"
    }
  }
]
```



```
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName":
"document_1712136487871_VASAI_GODOWN_AGREEMENT_pdf.pdf",
    "path": "cases/660d212c3aab7968b8b60a60/
document_1712136487871_VASAI_GODOWN_AGREEMENT_pdf.pdf",
    "id": "372499",
    "uploadedBy": "6006d4ce5080a310ac1fd2",
    "createdAt": "Wed Apr 03 2024 14:58:12 GMT+0530 (India Standard Time)"
  }
],
"isUrgent": "false",
"isExternal": "false",
"proposePurchaserName": "",
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"scheduleSiteVisitDate": "Invalid date",
"caseNumber": "008101",
"createdBy": "6006d4ce5080a310ac1fd2",
"caseHistory": [
  {
    "id": "328806",
    "title": "Create Case",
    "description": "Create Case",
    "datetime": "Wed Apr 03 2024 14:58:12 GMT+0530 (India Standard Time)"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "660fd85553ae1660b1ab5373",
    "name":
"externallmg_1712314453460_WhatsApp_Image_20240405_at_40724_PM_1.jpeg",
    "path": "cases/660d212c3aab7968b8b60a60/
externallmg_1712314453460_WhatsApp_Image_20240405_at_40724_PM_1.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "660fd85553ae1660b1ab5374",
    "name":
"externallmg_1712314453462_WhatsApp_Image_20240405_at_40724_PM_2.jpeg",
    "path": "cases/660d212c3aab7968b8b60a60/
externallmg_1712314453462_WhatsApp_Image_20240405_at_40724_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "660fd85553ae1660b1ab5375",
    "name":
"externallmg_1712314453465_WhatsApp_Image_20240405_at_40724_PM.jpeg",
    "path": "cases/660d212c3aab7968b8b60a60/
externallmg_1712314453465_WhatsApp_Image_20240405_at_40724_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "660fd86153ae1660b1ab53dc",
    "name":
"externallmg_1712314465232_WhatsApp_Image_20240405_at_40725_PM_1.jpeg",
    "path": "cases/660d212c3aab7968b8b60a60/
externallmg_1712314465232_WhatsApp_Image_20240405_at_40725_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "660fd86153ae1660b1ab53dd",
    "name":
"externallmg_1712314465235_WhatsApp_Image_20240405_at_40725_PM.jpeg",
    "path": "cases/660d212c3aab7968b8b60a60/
externallmg_1712314465235_WhatsApp_Image_20240405_at_40725_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "660fd86153ae1660b1ab53de",
```

```
    "name":
"externallmg_1712314465237_WhatsApp_Image_20240405_at_40726_PM_1.jpeg",
  "path": "cases/660d212c3aab7968b8b60a60/
externallmg_1712314465237_WhatsApp_Image_20240405_at_40726_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "660fd86153ae1660b1ab53df",
  "name":
"externallmg_1712314465240_WhatsApp_Image_20240405_at_40726_PM_2.jpeg",
  "path": "cases/660d212c3aab7968b8b60a60/
externallmg_1712314465240_WhatsApp_Image_20240405_at_40726_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "660fd86153ae1660b1ab53e0",
  "name":
"externallmg_1712314465242_WhatsApp_Image_20240405_at_40726_PM.jpeg",
  "path": "cases/660d212c3aab7968b8b60a60/
externallmg_1712314465242_WhatsApp_Image_20240405_at_40726_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "660fd86153ae1660b1ab53e1",
  "name":
"externallmg_1712314465245_WhatsApp_Image_20240405_at_40727_PM_1.jpeg",
  "path": "cases/660d212c3aab7968b8b60a60/
externallmg_1712314465245_WhatsApp_Image_20240405_at_40727_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "660fd86153ae1660b1ab53e2",
  "name":
"externallmg_1712314465247_WhatsApp_Image_20240405_at_40727_PM.jpeg",
  "path": "cases/660d212c3aab7968b8b60a60/
externallmg_1712314465247_WhatsApp_Image_20240405_at_40727_PM.jpeg",
  "orientation": "landscape"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "660fd86153ae1660b1ab53e3",
  "name":
"externallmg_1712314465250_WhatsApp_Image_20240405_at_40728_PM_1.jpeg",
  "path": "cases/660d212c3aab7968b8b60a60/
externallmg_1712314465250_WhatsApp_Image_20240405_at_40728_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "660fd86153ae1660b1ab53e4",
  "name":
"externallmg_1712314465252_WhatsApp_Image_20240405_at_40728_PM_2.jpeg",
  "path": "cases/660d212c3aab7968b8b60a60/
externallmg_1712314465252_WhatsApp_Image_20240405_at_40728_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "660fd86153ae1660b1ab53e5",
  "name":
"externallmg_1712314465254_WhatsApp_Image_20240405_at_40728_PM.jpeg",
  "path": "cases/660d212c3aab7968b8b60a60/
externallmg_1712314465254_WhatsApp_Image_20240405_at_40728_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "660fd86153ae1660b1ab53e6",
  "name":
"externallmg_1712314465257_WhatsApp_Image_20240405_at_40714_PM_1.jpeg",
  "path": "cases/660d212c3aab7968b8b60a60/
externallmg_1712314465257_WhatsApp_Image_20240405_at_40714_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "660fd86153ae1660b1ab53e7",
  "name":
"externallmg_1712314465259_WhatsApp_Image_20240405_at_40714_PM.jpeg",
```

```
    "path": "cases/660d212c3aab7968b8b60a60/
externallmg_1712314465259_WhatsApp_Image_20240405_at_40714_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "660fd86153ae1660b1ab53e8",
    "name":
"externallmg_1712314465262_WhatsApp_Image_20240405_at_40715_PM.jpeg",
    "path": "cases/660d212c3aab7968b8b60a60/
externallmg_1712314465262_WhatsApp_Image_20240405_at_40715_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "660fd86153ae1660b1ab53e9",
    "name":
"externallmg_1712314465267_WhatsApp_Image_20240405_at_40719_PM_1.jpeg",
    "path": "cases/660d212c3aab7968b8b60a60/
externallmg_1712314465267_WhatsApp_Image_20240405_at_40719_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "660fd86153ae1660b1ab53ea",
    "name":
"externallmg_1712314465271_WhatsApp_Image_20240405_at_40719_PM.jpeg",
    "path": "cases/660d212c3aab7968b8b60a60/
externallmg_1712314465271_WhatsApp_Image_20240405_at_40719_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "660fd86153ae1660b1ab53eb",
    "name":
"externallmg_1712314465274_WhatsApp_Image_20240405_at_40720_PM_1.jpeg",
    "path": "cases/660d212c3aab7968b8b60a60/
externallmg_1712314465274_WhatsApp_Image_20240405_at_40720_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```

    "status": false,
    "_id": "660fd86153ae1660b1ab53ec",
    "name":
"externallmg_1712314465278_WhatsApp_Image_20240405_at_40720_PM_2.jpeg",
    "path": "cases/660d212c3aab7968b8b60a60/
externallmg_1712314465278_WhatsApp_Image_20240405_at_40720_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "660fd86153ae1660b1ab53ed",
    "name":
"externallmg_1712314465280_WhatsApp_Image_20240405_at_40720_PM.jpeg",
    "path": "cases/660d212c3aab7968b8b60a60/
externallmg_1712314465280_WhatsApp_Image_20240405_at_40720_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "660fd86153ae1660b1ab53ee",
    "name":
"externallmg_1712314465289_WhatsApp_Image_20240405_at_40723_PM.jpeg",
    "path": "cases/660d212c3aab7968b8b60a60/
externallmg_1712314465289_WhatsApp_Image_20240405_at_40723_PM.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-04-03T09:28:12.729Z",
"updatedAt": "2024-04-05T10:54:25.405Z",
"__v": 0,
"addressForMap": "",
"updatedBy": "6006d4ce5080a310ac1fdfc2"
}

```

Name	Length	Width	Total
Composition :			

Other
Composition :
