

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "6273b00bafd7d55eddee5f69"
    },
    "type": "CREDITOFFICER",
    "_id": "6363aa704d42487767aeaf99",
    "firstName": "SUNIL BHOSALE",
    "lastName": "BHOSALE",
    "mobileNo": "9004074579",
    "email": "sunil.bhosale@sbi.co.in",
    "workMobileNo": "9004074579"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "00",
    "discussWithPerson": "SUNIL BHOSALE",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "6273b00bafd7d55eddee5f69",
  "name": "SPL PBB Fort",
  "branchCode": "4205 ",
  "mobileNo": "02223662641",
  "alternateMobileNo": "",
  "email": "sbi.04205@sbi.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Mumbai Main Branch Building, Gate no 1 Horniman Circle Mumbai
samachar marg Fort."
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
"_id": "60af3d172ffdf65bcd6585cd",
"role": "PICKUPPERSON",
"firstName": "Sachin",
"email": "sachin.joshi@vastukala.org",
"lastName": "Joshi",
"mobileNo": "9167204063",
"shortName": "SJ",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60af3d172ffdf65bcd6585cd\\
\\profilePhoto_1622372567671_Sachin Joshi Photo 3 (2).jpg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "60f9462345132d6a6bddb9d5",
"role": "SITEENGINEER",
"firstName": "Dashrath ",
"email": "dasrat.jaiswar1234@gmail.com",
"lastName": "Jaiswar",
"mobileNo": "9987305468",
"designation": "",
"shortName": "DFJ",
"workWithDocumentMaker": ""
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "60092304a16fab0f2af9b0c2",
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Nitesh",
"email": "nitesh.khedekar@vastukala.org",
"lastName": "Khedekar",
"mobileNo": "8369040652",
"designation": "",
"shortName": "NK",
"workWithDocumentMaker": "",
"profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
},
"maker": null,
"checker": null,
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
]
}
]
```

```
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
profilePhoto_1622114310919_Manoj C.jpeg",
```

```
    "PANNo": "AERPC9086P",
    "fatherName": "Baburao"
  }
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.0583912771504",
  "longitude": "72.84737118180543"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.84737118180543,
    19.0583912771504
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "6/04/2024 01:30 pm"
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
```

```
"status": true,
"name": "Country",
"key": "country",
"value": "India",
"label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Bandra",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "1",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "60",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahsilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahsilNo",
  "value": "",
```

```
"label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Gandhinagar Tirupati CHSL",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Gandhi Nagar",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
```

```
"name": "Landmark",
"key": "landmark",
"value": "",
"label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
}
```



```
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "2670",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
```

```
"key": "policeStation",
"value": "",
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Bandra East",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  }
}
```

```
    },
    "locationMapImg": [],
  },
  "outward": {
    "status": false,
    "remark": "SYSTEM_GENERATED"
  },
  "rateVerify": {
    "status": false
  },
  "underConstruction": {
    "rccFootingFoundation": {
      "label": "RCC Footing/Foundation",
      "floorsCompleted": "",
      "percentage": "0.00",
      "isHideFloor": false,
      "status": true
    },
    "rccPlinth": {
      "label": "RCC Plinth",
      "floorsCompleted": "",
      "percentage": "0.00",
      "isHideFloor": false,
      "status": false
    },
    "fullBuildingRcc": {
      "label": "Full Building Rcc",
      "floorsCompleted": "",
      "percentage": "0.00",
      "isHideFloor": false,
      "status": false
    },
    "internalBrickWork": {
      "label": "Internal Brick Work",
      "floorsCompleted": "",
      "percentage": "0.00",
      "isHideFloor": false,
      "status": false
    },
    "externalBrickWork": {
      "label": "External Brick Work",
      "floorsCompleted": "",
      "percentage": "0.00",
      "isHideFloor": false,
      "status": false
    }
  },
}
```

```
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
```

```
"selfieWithSiteVisitImages": [],
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"invoices": [],
"paymentIds": [],
"_id": "66110095834794131c1aa4f6",
"ownerName": "Bhagyashree Pravin More ",
"ownerPhoneNo": "9870135856",
"appAddress": "Flat no 2670,1floor,Building no 60,Gandhi Nagar Tirupati CHS,Gandhi
```



```
Nagar Bandra East ",
"remark": "Pravin More +91 98701 35856 & +91 96534 11966",
"documents": [
  {
    "documentType": {
      "label": " Agreement",
      "value": "652d16a0316e1359cebd3c15"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/66110095834794131c1aa4f6/document_1712390168066_17123899
46652_BHAGYASHREE_MORE_AGREEMENT_1.pdf",
    "fileName": "document_1712390168066_1712389946652_BHAGYASHREE_MORE
_AGREEMENT_1.pdf",
    "id": "603728",
    "uploadedBy": "60af3d172ffdf65bcd6585cd",
    "createdAt": "Sat Apr 06 2024 13:28:13 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "008131",
"createdBy": "60af3d172ffdf65bcd6585cd",
"caseHistory": [
  {
    "id": "150367",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Sat Apr 06 2024 13:28:13 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Bhagyashree Pravin More ",
    "phone": "9870135856",
    "ownershipShare": "",
    "email": "",
    "id": "707046"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
```

```
"externalImages": [
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6616577a834794131c1d814c",
    "name": "externalimg_1712740217690_1712739975291_image_0.jpeg",
    "path": "cases/66110095834794131c1aa4f6/
externalimg_1712740217690_1712739975291_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6616577a834794131c1d814d",
    "name": "externalimg_1712740217795_1712739975291_image_1.jpeg",
    "path": "cases/66110095834794131c1aa4f6/
externalimg_1712740217795_1712739975291_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6616577a834794131c1d814e",
    "name": "externalimg_1712740217842_1712739975291_image_2.jpeg",
    "path": "cases/66110095834794131c1aa4f6/
externalimg_1712740217842_1712739975291_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "661657c4834794131c1d8266",
    "name": "externalimg_1712740289871_1712740070465_image_0.jpeg",
    "path": "cases/66110095834794131c1aa4f6/
externalimg_1712740289871_1712740070465_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "661657c4834794131c1d8267",
    "name": "externalimg_1712740289894_1712740070465_image_1.jpeg",
    "path": "cases/66110095834794131c1aa4f6/
externalimg_1712740289894_1712740070465_image_1.jpeg",
    "orientation": "portrait"
  },
  },
]
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "661657c4834794131c1d8268",
  "name": "externallmg_1712740289999_1712740070465_image_2.jpeg",
  "path": "cases/66110095834794131c1aa4f6/
externallmg_1712740289999_1712740070465_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "661657c4834794131c1d8269",
  "name": "externallmg_1712740290176_1712740070465_image_3.jpeg",
  "path": "cases/66110095834794131c1aa4f6/
externallmg_1712740290176_1712740070465_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "661657c4834794131c1d826a",
  "name": "externallmg_1712740290330_1712740070465_image_4.jpeg",
  "path": "cases/66110095834794131c1aa4f6/
externallmg_1712740290330_1712740070465_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "661657c4834794131c1d826b",
  "name": "externallmg_1712740290486_1712740070465_image_5.jpeg",
  "path": "cases/66110095834794131c1aa4f6/
externallmg_1712740290486_1712740070465_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "661657c4834794131c1d826c",
  "name": "externallmg_1712740290543_1712740070465_image_6.jpeg",
  "path": "cases/66110095834794131c1aa4f6/
externallmg_1712740290543_1712740070465_image_6.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "661657c4834794131c1d826d",
    "name": "externallmg_1712740290636_1712740070465_image_7.jpeg",
    "path": "cases/66110095834794131c1aa4f6/
externallmg_1712740290636_1712740070465_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "661657c4834794131c1d826e",
    "name": "externallmg_1712740290729_1712740070465_image_8.jpeg",
    "path": "cases/66110095834794131c1aa4f6/
externallmg_1712740290729_1712740070465_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "661657c4834794131c1d826f",
    "name": "externallmg_1712740290811_1712740070465_image_9.jpeg",
    "path": "cases/66110095834794131c1aa4f6/
externallmg_1712740290811_1712740070465_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "661657c4834794131c1d8270",
    "name": "externallmg_1712740290921_1712740070465_image_10.jpeg",
    "path": "cases/66110095834794131c1aa4f6/
externallmg_1712740290921_1712740070465_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "661657c4834794131c1d8271",
    "name": "externallmg_1712740291006_1712740070465_image_11.jpeg",
    "path": "cases/66110095834794131c1aa4f6/
externallmg_1712740291006_1712740070465_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "661657c4834794131c1d8272",
  "name": "externallmg_1712740291082_1712740070465_image_12.jpeg",
  "path": "cases/66110095834794131c1aa4f6/
externallmg_1712740291082_1712740070465_image_12.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "661657c4834794131c1d8273",
  "name": "externallmg_1712740291163_1712740070465_image_13.jpeg",
  "path": "cases/66110095834794131c1aa4f6/
externallmg_1712740291163_1712740070465_image_13.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "661657c4834794131c1d8274",
  "name": "externallmg_1712740291237_1712740070465_image_14.jpeg",
  "path": "cases/66110095834794131c1aa4f6/
externallmg_1712740291237_1712740070465_image_14.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "661657c4834794131c1d8275",
  "name": "externallmg_1712740291352_1712740070465_image_15.jpeg",
  "path": "cases/66110095834794131c1aa4f6/
externallmg_1712740291352_1712740070465_image_15.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "661657c4834794131c1d8276",
  "name": "externallmg_1712740291464_1712740070465_image_16.jpeg",
  "path": "cases/66110095834794131c1aa4f6/
externallmg_1712740291464_1712740070465_image_16.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "661657c4834794131c1d8277",
    "name": "externallmg_1712740291540_1712740070465_image_17.jpeg",
    "path": "cases/66110095834794131c1aa4f6/
externallmg_1712740291540_1712740070465_image_17.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "661657c4834794131c1d8278",
    "name": "externallmg_1712740291676_1712740070465_image_18.jpeg",
    "path": "cases/66110095834794131c1aa4f6/
externallmg_1712740291676_1712740070465_image_18.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "661657c4834794131c1d8279",
    "name": "externallmg_1712740291919_1712740070465_image_19.jpeg",
    "path": "cases/66110095834794131c1aa4f6/
externallmg_1712740291919_1712740070465_image_19.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "661657ed834794131c1d8441",
    "name": "externallmg_1712740330322_1712740110488_image_0.jpeg",
    "path": "cases/66110095834794131c1aa4f6/
externallmg_1712740330322_1712740110488_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "661657ed834794131c1d8442",
    "name": "externallmg_1712740330525_1712740110488_image_1.jpeg",
    "path": "cases/66110095834794131c1aa4f6/
externallmg_1712740330525_1712740110488_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "661657ed834794131c1d8443",
```

```
    "name": "externallmg_1712740331116_1712740110488_image_2.jpeg",
    "path": "cases/66110095834794131c1aa4f6/
externallmg_1712740331116_1712740110488_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "661657ed834794131c1d8444",
    "name": "externallmg_1712740331139_1712740110488_image_3.jpeg",
    "path": "cases/66110095834794131c1aa4f6/
externallmg_1712740331139_1712740110488_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "661657ed834794131c1d8445",
    "name": "externallmg_1712740331376_1712740110488_image_4.jpeg",
    "path": "cases/66110095834794131c1aa4f6/
externallmg_1712740331376_1712740110488_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "661657ed834794131c1d8446",
    "name": "externallmg_1712740331643_1712740110488_image_5.jpeg",
    "path": "cases/66110095834794131c1aa4f6/
externallmg_1712740331643_1712740110488_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "661657ed834794131c1d8447",
    "name": "externallmg_1712740331868_1712740110488_image_6.jpeg",
    "path": "cases/66110095834794131c1aa4f6/
externallmg_1712740331868_1712740110488_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "661657ed834794131c1d8448",
    "name": "externallmg_1712740332150_1712740110488_image_7.jpeg",
```

```
    "path": "cases/66110095834794131c1aa4f6/
externallmg_1712740332150_1712740110488_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "661657ed834794131c1d8449",
    "name": "externallmg_1712740332363_1712740110488_image_8.jpeg",
    "path": "cases/66110095834794131c1aa4f6/
externallmg_1712740332363_1712740110488_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "661657ed834794131c1d844a",
    "name": "externallmg_1712740332594_1712740110488_image_9.jpeg",
    "path": "cases/66110095834794131c1aa4f6/
externallmg_1712740332594_1712740110488_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "661657ed834794131c1d844b",
    "name": "externallmg_1712740332840_1712740110488_image_10.jpeg",
    "path": "cases/66110095834794131c1aa4f6/
externallmg_1712740332840_1712740110488_image_10.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-04-06T07:58:13.986Z",
"updatedAt": "2024-04-10T09:12:13.353Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 2670, 1st Floor, Building No 60, Gandhinagar
Tirupati CHSL, Gandhi Nagar, Village - Bandra, Bandra East, Mumbai",
```


"updatedBy": "60f9462345132d6a6bddb9d5",
"addressForMap": "",
"caseReferredBy": "60af3d172ffdf65bcd6585cd",
"contactPersonName": "Bhagyashree Pravin More ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9870135856"

}

Name	Length	Width	Total
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			