

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": true,
    "RVDSValues": false,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7f7"
    },
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b942312bd",
    "firstName": "Swarup",
    "email": "1racpcghatkopar.sanctions@sbi.co.in",
    "mobileNo": "-",
    "workMobileNo": "8668951779",
    "lastName": " Shivane"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "7500000",
    "discussWithPerson": "Swarup",
    "expectedFees": 3750,
    "quotedAmount": "2500"
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7f7",
  "branchCode": "000064",
  "type": "BRANCH",
  "name": "RACPC Ghatkopar (West)",
  "email": "racpcghatkopar.sanctions@sbi.co.in",
  "mobileNo": "022-25009143",
  "alternateMobileNo": "",
  "address": "Retail Assets Centralised Processing Centre, 1st Floor, Ashok Silk Mills
Compound, LBS Marg, Ghatkopar (West), Mumbai - 400 086, State - Maharashtra,
Country - India.\r\n\r\n\r\n\r\n",
  "ledgerName": "STATE BANK OF INDIA - RACPC GHATKOPAR",
  "fax": "022-25009010",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "60b7177d2ffdf65bcd65882a",
  "role": "PICKUPPERSON",
  "firstName": "Saurabh",
  "email": "saurabhvelonde143@gmail.com",
  "lastName": "Velonde",
  "mobileNo": "8691048846",
  "shortName": "SSV",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1686816492317_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62ea09ea4e679b264caf07d7",
  "role": "SITEENGINEER",
  "firstName": "Suraj",
  "email": "suraj@vastukala.org",
  "lastName": "Zore",
  "mobileNo": "8652448654",
  "designation": "",
  "shortName": "SZ",
  "workWithDocumentMaker": "60092304a16fab0f2af9b0c2",
  "profilePhoto": "users/62ea09ea4e679b264caf07d7/
profilePhoto_1685629394240_image.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60092304a16fab0f2af9b0c2",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Nitesh",
  "email": "nitesh.khedekar@vastukala.org",
  "lastName": "Khedekar",
  "mobileNo": "8369040652",
  "designation": "",
  "shortName": "NK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627221f4afd7d55eddeddcb4",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Prajakta",
```

```
"email": "prajakta@vastukala.org",
"lastName": "Patil",
"mobileNo": "9769797568",
"designation": "",
"shortName": "P",
"workWithDocumentMaker": "",
"profilePhoto": "users/627221f4afd7d55eddeddcb4/
profilePhoto_1668057197188_WhatsApp_Image_20221110_at_104044_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60092304a16fab0f2af9b0c2",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Nitesh",
  "email": "nitesh.khedekar@vastukala.org",
  "lastName": "Khedekar",
  "mobileNo": "8369040652",
  "designation": "",
  "shortName": "NK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ]
  }
]
```

```
    },
    {
      "title": {
        "value": "FIIV",
        "label": "FIIV"
      },
      "_id": "60af80072ffdf65bcd658652",
      "number": "CAT-I-F-1763"
    },
    {
      "title": {
        "value": "Chartered_Engineer",
        "label": "Chartered Engineer"
      },
      "_id": "60af80072ffdf65bcd658653",
      "number": "AM161706-3"
    },
    {
      "title": {
        "value": "Registered_Valuer",
        "label": "Registered Valuer"
      },
      "_id": "60af80072ffdf65bcd658654",
      "number": "IBBI/RV/07/2018/10366"
    }
  ],
  "shortName": "MBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
  "PANNo": "AERPC9086P",
  "fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
  "latitude": "19.283697391969024",
  "longitude": "72.8850740778737"
},
"geo": {
  "type": "Point",
  "coordinates": [
```

```
72.8850740778737,
19.283697391969024
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-04-10",
      "remark": "MRS. SWEETY PRITIVI NADAR"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-04-10",
      "remark": "MANUAL_IN_TASK"
    }
  ],
  "schedule": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "2BHK",
  "label": "2 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  }
}
```

```
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Vadavali",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "6",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "B",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
```

```
"key": "taluka",
"value": "Thane",
"label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Tulip 1",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Beside Krishna Greenland Park",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Opp. Vedant Hospital, Kasarvadavali",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
```



```
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Haware Estate Tulip I & II Co-op. Hsg. Soc. Ltd., Haware Estate - Phase I",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "47/1, 48/2, 48/3, 48/6A (Part), 48/6B, 49/3B",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
```

```
"value": "",
"label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "601",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
```

```
"status": false,
"name": "Gut No.",
"key": "GUTNo",
"value": "",
"label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 400 615",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Thane (West)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows",
    "label": "Powder coated Aluminum sliding windows"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering",
    "label": "Cement Plastering"
  }
}
```

```
}
},
"general": {
  "ownership": {
    "value": "Sole_Ownership",
    "label": "Sole Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "Thane_Municipal_Corporation",
    "label": "Thane Municipal Corporation"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Open Plot",
    "west": "Internal Road & Greenland Park ",
    "south": "Tulip - II CHSL",
    "east": "Greenland Park"
  },
  "asPerDocumentAgreement": {
    "north": "Details not available",
    "west": "Details not available",
    "south": "Details not available",
    "east": "Details not available"
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "",
      "west": "",
      "south": "",
      "east": ""
    },
    "asPerDocument": {
      "north": "",
      "west": "",
      "south": "",

```

```
    "east": ""
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "Copy of Occupancy Certificate Document No. V.P. No.
2005 / 84 - TMC / TDD / 121 Dated 31.07.2012 issued by Thane Municipal
Corporation",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "N.A.",
"unauthorizedConstruction": ""
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "18",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "11496",
  "depreciatedBuildingRate": "2296"
},
"igrRate": {
  "propertyName": "Residential ",
  "rate": "97700",
  "landRate": "19900",
  "igrImage": "cases/6613d9af834794131c1c5d36/igr_1712732608817_Image.png",
  "squareMeterGuideLineRate": "78160.00",
  "squareFeetGuideLineRate": "7261.00"
},
"igrFinalRate": {
  "floorRatePercentage": "80",
  "depreciationPercentage": "88",
  "rate": "6612.00",
  "squareFeetGuideLineRate": "6612.00",
  "squareMeterGuideLineRate": "71169.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
```

```
"value": "Vacant",
"label": "Vacant"
},
"monthlyRent": "17,000/- Expected rental income per month",
"assessmentNo": "Details not available",
"taxPaidHolderName": "Details not available",
"taxAmount": "Details not available",
"electricityServiceConnectionNo": "Details not available",
"meterCardHolderName": "Details not available",
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per TMC norms",
"tenantName": "",
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in Developed Area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Along with One Stilt allotted Car Parking No. S - 3",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
```

```
"label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2012",
  "fullDate": "1/1/2012"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C.",
  "label": "R.C.C. Framed"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
```

```
"label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenanceIssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "stilt",
  "label": "Stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "12",
"totalLifeBuilding": "60",
"estimatedAge": "48",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "15",
"flatFloorNo": "6",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "4"
},
```



```
"finalPlinthArea": {
  "area": "838.80",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 20%"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/6613d9af834794131c1c5d36/
routeMap_1712816528077_Image.png",
    "routeLat": "19.272795",
    "routeLng": "72.964776",
    "stationName": "Thane",
    "routeDistance": "10.2 Km."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "ij6ncd",
      "name": "ij6ncd",
      "image": "cases/6613d9af834794131c1c5d36/
routeMap_1712816338010_Image.png"
    }
  ]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
```

```
"kitchenArrangementsQty": "0",
"kitchenArrangementsRate": "0",
"totalkitchenArrangementsRate": "0",
"superfineFinishQty": "0",
"superfineFinishRate": "0",
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "8035704.00",
"finalValue": "8035704.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValueDocument": null,
"purchaseValueDocument": null,
"bookValue": "0"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Sat Apr 20 2024 14:46:55 GMT+0530 (India Standard Time)",
  "number": "2306025",
  "dayCount": "2",
  "monthCount": "164",
  "generatedBy": "60092304a16fab0f2af9b0c2"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
```

```
"isHideFloor": false,
"status": true
},
"rccPlinth": {
  "label": "RCC Plinth",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
```

```
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
"label": "Flooring, Tiling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "7221229.00",
  "selectedBuildUpValue": "838.80",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "66168d32834794131c1e379b",
      "name": "externallmg_r_1712753966031_1712753726246_image_15.jpg",
      "path": "cases/6613d9af834794131c1c5d36/
externallmg_r_1712753966031_1712753726246_image_15.jpg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "66168d32834794131c1e3798",
      "name": "externallmg_r_1712753962522_1712753726246_image_12.jpg",
      "path": "cases/6613d9af834794131c1c5d36/
externallmg_r_1712753962522_1712753726246_image_12.jpg",
```

```
    "orientation": "landscape"
  }
],
"externalPhotos": [
  {
    "status": false,
    "_id": "66168d32834794131c1e379a",
    "name": "externallmg_r_1712753964712_1712753726246_image_14.jpg",
    "path": "cases/6613d9af834794131c1c5d36/
externallmg_r_1712753964712_1712753726246_image_14.jpg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
    "_id": "66168d32834794131c1e378c",
    "name": "Living Room",
    "path": "cases/6613d9af834794131c1c5d36/
externallmg_r_1712753949747_1712753726246_image_3.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66168d32834794131c1e378d",
    "name": "Living Room",
    "path": "cases/6613d9af834794131c1c5d36/
externallmg_r_1712753948521_1712753726246_image_2.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66168d32834794131c1e3790",
    "name": "Living Room",
    "path": "cases/6613d9af834794131c1c5d36/
externallmg_r_1712753951227_1712753726246_image_4.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66168d32834794131c1e3793",
    "name": "Living Room",
    "path": "cases/6613d9af834794131c1c5d36/
externallmg_r_1712753954831_1712753726246_image_7.jpg",
```

```
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66168d32834794131c1e3797",
    "name": "Living Room",
    "path": "cases/6613d9af834794131c1c5d36/
externallmg_r_1712753960908_1712753726246_image_11.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66168d32834794131c1e3796",
    "name": "Living Room",
    "path": "cases/6613d9af834794131c1c5d36/
externallmg_r_1712753958868_1712753726246_image_10.jpg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "11577.00",
    "max": "12254.00"
  },
  "builtUpRateRange": {
    "min": "9648.00",
    "max": "10212.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  }
}
```

```
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
```



```
"status": true,
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
```

```
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "699.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"invoices": [],
"paymentIds": [],
"_id": "6613d9af834794131c1c5d36",
"ownerName": "Mr. Gaurav Terdal & Mrs. Tabassum Terdal",
"ownerPhoneNo": "8898067871",
"appAddress": "Flat no. 601, 6th Floor, Tulip CHS, Haware Estate, Village - Vadavli,
Thane West ",
"remark": "MRS. SWEETY PRITIVI NADAR",
"documents": [
  {
    "documentType": {
      "value": "60ae127eaa6d152c1801b3ec",
      "label": "Seller's Agreement for Sale"
    },
    "inputs": {
      "documentDate": "26/06/2012",
      "from": {
        "value": "Developers",
        "label": "Developers"
      },
      "Developers": "Haware Engineers & Builders Private Limited",
      "to": {
        "value": "purchaser",
        "label": "purchaser"
      },
      "purchaser": "Gaurav Terdal & Tabassum Terdal"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "905723",
    "path": "cases/6613d9af834794131c1c5d36/
document_1712576907547_1712576691558_Racpc_GHatkoparSweety_Nadar.pdf",
    "fileName":
"document_1712576907547_1712576691558_Racpc_GHatkoparSweety_Nadar.pdf"
  },
  {
```

```
"documentType": {
  "label": "Draft Agreement",
  "value": "60ae124aaa6d152c1801b2f8"
},
"inputs": {
  "from": {
    "value": "Transferor",
    "label": "Transferor"
  },
  "Transferor": "Mr. Gaurav Terdal & Mrs. Tabassum Terdal",
  "to": {
    "value": "The_Transferee",
    "label": "The Transferee"
  },
  "The_Transferee": "Mrs. Sweety Pritvi Nadar"
},
"isHardCopy": false,
"displayStatus": true,
"id": "826097",
"path": "cases/6613d9af834794131c1c5d36/document_1712576938358_17125767
22274_abfe425a89c54611bf8598f7874d76c6.pdf",
"fileName": "document_1712576938358_1712576722274_abfe425a89c54611bf859
8f7874d76c6.pdf"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "31/07/2012",
    "nameOfApprovingAuthority": {
      "value": "Thane_Municipal_Corporation",
      "label": "Thane Municipal Corporation"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "V.P. No. 2005 / 84 - TMC / TDD / 121 "
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1713589947047_99980.pdf",
  "path": "cases/6613d9af834794131c1c5d36/
document_1713589947047_99980.pdf",
```

```
"id": "122994",
"uploadedBy": "627221f4afd7d55eddeddcb4",
"createdAt": "Sat Apr 20 2024 10:42:27 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1252aa6d152c1801b31d",
    "label": "Society Letter"
  },
  "inputs": {
    "documentDate": "19/04/2024",
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": ""
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1713590016478_Kaagaz_20240419_190405848175.pdf",
  "path": "cases/6613d9af834794131c1c5d36/
document_1713590016478_Kaagaz_20240419_190405848175.pdf",
  "id": "355816",
  "uploadedBy": "627221f4afd7d55eddeddcb4",
  "createdAt": "Sat Apr 20 2024 10:43:37 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "008157",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "280977",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Mon Apr 08 2024 17:19:03 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Gaurav Terdal & Mrs. Tabassum Terdal",
    "phone": "8898067871",
    "ownershipShare": "",
    "email": "",
    "id": "131570"
  }
],
```

```
"proposePurchasers": [
  {
    "name": "Mrs. Sweety Pritivi Nadar",
    "phone": "",
    "email": "",
    "ownershipShare": ""
  }
],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "624890",
    "name": "Dining",
    "length": "8.42",
    "length1": "8",
    "length2": "5",
    "width": "10.17",
    "width1": "10",
    "width2": "2",
    "totalArea": "85.57",
    "images": [],
    "extraAreas": [],
    "finalArea": "85.57"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "1",
    "name": "Living Room",
    "length": "18.00",
    "length1": "18",
    "length2": "00",
    "width": "9.67",
    "width1": "9",
    "width2": "8",
    "totalArea": "174.00",
    "images": [],
    "extraAreas": [],
    "finalArea": "174.00"
  },
]
```

```
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "9",
  "name": "Kitchen",
  "length": "",
  "length1": "9",
  "length2": "2",
  "width": "",
  "width1": "9",
  "width2": "4",
  "totalArea": "85.56",
  "images": [],
  "finalArea": "85.56",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Toilet",
  "length": "4.08",
  "length1": "4",
  "length2": "1",
  "width": "4.08",
  "width1": "4",
  "width2": "1",
  "totalArea": "16.67",
  "images": [],
  "extraAreas": [],
  "finalArea": "16.67"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Toilet",
  "length": "5.58",
  "length1": "5",
  "length2": "7",
```

```
"width": "3.58",
"width1": "3",
"width2": "7",
"totalArea": "20.01",
"images": [],
"extraAreas": [],
"finalArea": "20.01"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Bedroom",
  "length": "9.83",
  "length1": "9",
  "length2": "10",
  "width": "9.50",
  "width1": "9",
  "width2": "6",
  "totalArea": "93.42",
  "images": [],
  "extraAreas": [],
  "finalArea": "93.42"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Bedroom",
  "length": "9.50",
  "length1": "9",
  "length2": "6",
  "width": "13.33",
  "width1": "13",
  "width2": "4",
  "totalArea": "126.67",
  "images": [],
  "extraAreas": [],
  "finalArea": "126.67"
},
{
  "measurementType": {
```

```
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Passage",
  "length": "6.67",
  "length1": "6",
  "length2": "8",
  "width": "2.83",
  "width1": "2",
  "width2": "10",
  "totalArea": "18.89",
  "images": [],
  "extraAreas": [],
  "finalArea": "18.89"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "8",
  "name": "Passage",
  "length": "7.58",
  "length1": "7",
  "length2": "7",
  "width": "4.50",
  "width1": "4",
  "width2": "6",
  "totalArea": "34.12",
  "images": [],
  "extraAreas": [],
  "finalArea": "34.12"
}
],
"otherComposition": [
  {
    "toBeAdded": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "name": {
      "label": "Cupboard",
      "value": "Cupboard"
    }
  },
  "measurementType": {
```



```
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "0",
  "length": "2.00",
  "length1": "2",
  "length2": "00",
  "width": "4.17",
  "width1": "4",
  "width2": "2",
  "totalArea": "8.33",
  "images": [],
  "extraAreas": [],
  "finalArea": "8.33",
  "percentageBeforeTotal": "8.33",
  "percentage": "100"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Cupboard",
    "value": "Cupboard"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "length": "2.08",
  "length1": "2",
  "length2": "1",
  "width": "6.50",
  "width1": "6",
  "width2": "6",
  "totalArea": "13.54",
  "images": [],
  "extraAreas": [],
  "finalArea": "13.54",
  "percentageBeforeTotal": "13.54",
  "percentage": "100"
},
{
  "toBeAdded": {
```

```
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Dry Balcony Area",
    "value": "Dry_Balcony_Area"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "length": "3.67",
  "length1": "3",
  "length2": "8",
  "width": "7.67",
  "width1": "7",
  "width2": "8",
  "totalArea": "28.11",
  "images": [],
  "extraAreas": [],
  "finalArea": "28.11",
  "percentageBeforeTotal": "28.11",
  "percentage": "100"
}
],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "label": "Draft Agreement",
      "value": "60ae124aaa6d152c1801b2f8"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "118249",
    "selectAreaTypeDocument": "Carpet",
    "totalAreaDocument": "699",
    "squareMeterArea": "64.94",
    "docFinalBuiltUp": "838.8",
    "docFinalBuiltUpSquareMeter": "77.928",
    "docBultupPercentage": "20",
    "docSaleablePercentage": "0",
    "docFinalSaleable": "0",
```

```
    "docFinalSaleableSquareMeter": "0"
  }
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "66163a42834794131c1d3915",
    "property": "Haware Estate, Kasar vadavali, Thane",
    "area": "710.00",
    "builtUpPercentage": "20",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "floor": "",
    "source": "https://www.99acres.com/",
    "expectedPrice": "8700000.00",
    "expectedRate": "12253.52",
    "builtUpExpectedRate": "10211.27",
    "image": "cases/6613d9af834794131c1c5d36/
indicator_1712732185209_Image.png",
    "squareMeter": "65.96",
    "carpetArea": {
      "area": "710.00",
      "squareMeterArea": "65.96",
      "expectedRate": "12253.52",
      "percentage": "",
      "isManual": false
    },
    "builtUpArea": {
      "area": "852.00",
      "squareMeterArea": "79.15",
      "expectedRate": "10211.27",
      "percentage": "20",
      "isManual": false
    },
    "saleableArea": {
      "area": "",
      "squareMeterArea": "0.00",
      "expectedRate": "0.00",
      "percentage": "",
      "isManual": false
    },
    "id": "700775"
  },
  {
```

```
"printlnReport": true,
"_id": "66163a42834794131c1d3916",
"property": "Haware Estate, Haware City, Kasarvadavali, Thane West, Thane",
"area": "742.00",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "https://www.99acres.com/",
"expectedPrice": "8590000",
"expectedRate": "11576.82",
"builtUpExpectedRate": "9647.35",
"image": "cases/6613d9af834794131c1c5d36/
indicator_1712732246016_Image.png",
"squareMeter": "68.93",
"carpetArea": {
  "area": "742.00",
  "squareMeterArea": "68.93",
  "expectedRate": "11576.82",
  "percentage": "",
  "isManual": false
},
"builtUpArea": {
  "area": "890.40",
  "squareMeterArea": "82.72",
  "expectedRate": "9647.35",
  "percentage": "20",
  "isManual": false
},
"saleableArea": {
  "area": "",
  "squareMeterArea": "0.00",
  "expectedRate": "0.00",
  "percentage": "",
  "isManual": false
},
"id": "934268"
},
{
  "printlnReport": true,
  "_id": "66163a42834794131c1d3917",
  "property": "Haware Estate, Kasarvadavali, Thane West, Thane",
  "area": "650.00",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
```

```
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "Housing.Com",
"expectedPrice": "7600000",
"expectedRate": "11692.31",
"builtUpExpectedRate": "9743.59",
"image": "cases/6613d9af834794131c1c5d36/
indicator_1712732320676_Image.png",
"squareMeter": "60.39",
"carpetArea": {
  "area": "650.00",
  "squareMeterArea": "60.39",
  "expectedRate": "11692.31",
  "percentage": "",
  "isManual": false
},
"builtUpArea": {
  "area": "780.00",
  "squareMeterArea": "72.46",
  "expectedRate": "9743.59",
  "percentage": "20",
  "isManual": false
},
"saleableArea": {
  "area": "",
  "squareMeterArea": "0.00",
  "expectedRate": "0.00",
  "percentage": "",
  "isManual": false
},
"id": "579045"
},
{
  "printlnReport": true,
  "_id": "66163a42834794131c1d3918",
  "property": "Haware Estate, Kasarvadavali, Thane West, Thane",
  "area": "701",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "",
  "source": "Housing.Com",
  "expectedPrice": "8500000.00",
  "expectedRate": "12125.53",
```

```
"builtUpExpectedRate": "10104.61",
"image": "cases/6613d9af834794131c1c5d36/
indicator_1712732371543_Image.png",
"squareMeter": "65.13",
"carpetArea": {
  "area": "701.00",
  "squareMeterArea": "65.13",
  "expectedRate": "12125.53",
  "percentage": "",
  "isManual": false
},
"builtUpArea": {
  "area": "841.20",
  "squareMeterArea": "78.15",
  "expectedRate": "10104.61",
  "percentage": "20",
  "isManual": false
},
"saleableArea": {
  "area": "",
  "squareMeterArea": "0.00",
  "expectedRate": "0.00",
  "percentage": "",
  "isManual": false
},
"id": "758213"
}
],
"externalImages": [
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66168d32834794131c1e378c",
  "name": "externalimg_r_1712753949747_1712753726246_image_3.jpg",
  "path": "cases/6613d9af834794131c1c5d36/
externalimg_r_1712753949747_1712753726246_image_3.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66168d32834794131c1e378d",
  "name": "externalimg_r_1712753948521_1712753726246_image_2.jpg",
  "path": "cases/6613d9af834794131c1c5d36/
externalimg_r_1712753948521_1712753726246_image_2.jpg",
  "orientation": "portrait"
}
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "66168d32834794131c1e378e",
      "name": "externallmg_r_1712753943760_1712753726246_image_0.jpg",
      "path": "cases/6613d9af834794131c1c5d36/
externallmg_r_1712753943760_1712753726246_image_0.jpg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "66168d32834794131c1e378f",
      "name": "externallmg_r_1712753944815_1712753726246_image_1.jpg",
      "path": "cases/6613d9af834794131c1c5d36/
externallmg_r_1712753944815_1712753726246_image_1.jpg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "66168d32834794131c1e3790",
      "name": "externallmg_r_1712753951227_1712753726246_image_4.jpg",
      "path": "cases/6613d9af834794131c1c5d36/
externallmg_r_1712753951227_1712753726246_image_4.jpg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "66168d32834794131c1e3791",
      "name": "externallmg_r_1712753953603_1712753726246_image_6.jpg",
      "path": "cases/6613d9af834794131c1c5d36/
externallmg_r_1712753953603_1712753726246_image_6.jpg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "66168d32834794131c1e3792",
      "name": "externallmg_r_1712753952273_1712753726246_image_5.jpg",
      "path": "cases/6613d9af834794131c1c5d36/
externallmg_r_1712753952273_1712753726246_image_5.jpg",
      "orientation": "portrait"
    },
  },
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66168d32834794131c1e3793",
  "name": "externallmg_r_1712753954831_1712753726246_image_7.jpg",
  "path": "cases/6613d9af834794131c1c5d36/
externallmg_r_1712753954831_1712753726246_image_7.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66168d32834794131c1e3794",
  "name": "externallmg_r_1712753956142_1712753726246_image_8.jpg",
  "path": "cases/6613d9af834794131c1c5d36/
externallmg_r_1712753956142_1712753726246_image_8.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66168d32834794131c1e3795",
  "name": "externallmg_r_1712753957509_1712753726246_image_9.jpg",
  "path": "cases/6613d9af834794131c1c5d36/
externallmg_r_1712753957509_1712753726246_image_9.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66168d32834794131c1e3796",
  "name": "externallmg_r_1712753958868_1712753726246_image_10.jpg",
  "path": "cases/6613d9af834794131c1c5d36/
externallmg_r_1712753958868_1712753726246_image_10.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66168d32834794131c1e3797",
  "name": "externallmg_r_1712753960908_1712753726246_image_11.jpg",
  "path": "cases/6613d9af834794131c1c5d36/
externallmg_r_1712753960908_1712753726246_image_11.jpg",
  "orientation": "portrait"
},
{
```



```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66168d32834794131c1e3798",
    "name": "externallmg_r_1712753962522_1712753726246_image_12.jpg",
    "path": "cases/6613d9af834794131c1c5d36/
externallmg_r_1712753962522_1712753726246_image_12.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66168d32834794131c1e3799",
    "name": "externallmg_r_1712753963470_1712753726246_image_13.jpg",
    "path": "cases/6613d9af834794131c1c5d36/
externallmg_r_1712753963470_1712753726246_image_13.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66168d32834794131c1e379a",
    "name": "externallmg_r_1712753964712_1712753726246_image_14.jpg",
    "path": "cases/6613d9af834794131c1c5d36/
externallmg_r_1712753964712_1712753726246_image_14.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66168d32834794131c1e379b",
    "name": "externallmg_r_1712753966031_1712753726246_image_15.jpg",
    "path": "cases/6613d9af834794131c1c5d36/
externallmg_r_1712753966031_1712753726246_image_15.jpg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66168d00834794131c1e3747",
    "name": "externallmg_r_1712753919513_1712753700755_image_2.png",
    "path": "cases/6613d9af834794131c1c5d36/
externallmg_r_1712753919513_1712753700755_image_2.png",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
```

```
"status": false,
  "_id": "66168d00834794131c1e3748",
  "name": "externalImg_r_1712753918122_1712753700755_image_1.jpg",
  "path": "cases/6613d9af834794131c1c5d36/
externalImg_r_1712753918122_1712753700755_image_1.jpg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66168d00834794131c1e3749",
  "name": "externalImg_r_1712753916515_1712753700755_image_0.jpg",
  "path": "cases/6613d9af834794131c1c5d36/
externalImg_r_1712753916515_1712753700755_image_0.jpg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "627221f4afd7d55eddeddcb4",
      "role": "MAKER + RATE VERFIER + CHEAKER",
      "firstName": "Prajakta",
      "lastName": "Patil",
      "profilePhoto": "users/627221f4afd7d55eddeddcb4/
profilePhoto_1668057197188_WhatsApp_Image_20221110_at_104044_AM.jpeg"
    },
    "workType": "MAKER",
    "display": true,
    "status": true,
    "_id": "6617ce8353f88c65a60b61c3",
    "note": "pending for oc",
    "taskId": "66163a46834794131c1d392d",
    "createdAt": "2024-04-11T11:50:27.402Z"
  }
],
"createdAt": "2024-04-08T11:49:03.405Z",
"updatedAt": "2024-04-20T09:21:55.418Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
}
```

```
},
"fullAddress": "Residential Flat No. 601, 6th Floor, Building No B, Tulip I, Haware Estate Tulip I & II Co-op. Hsg. Soc. Ltd., Haware Estate - Phase I, Beside Krishna Greenland Park, Opp. Vedant Hospital, Kasarvadavali, Village - Vadavali, Thane (West), Taluka - Thane, District - Thane, PIN Code - 400 615, State - Maharashtra, India",
"updatedBy": "60092304a16fab0f2af9b0c2",
"addressForMap": "",
"caseReferredBy": "60b7177d2ffdf65bcd65882a",
"contactPersonName": "Mr. Aditya",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "Mrs. Sweety Pritivi Nadar",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Contact Person",
"siteVisitContactNo": "9987520991",
"buildingServicesRate": "2800",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Draft Agreement",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 699.00",
"flatRate": "12000",
"landOtherRate": "9200",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
}
```

```

    }
  },
  "finalSaleablePercentage": "0",
  "briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + Dining + 2 Toilet + 2
Passage",
  "carpetTotal": "654.91",
  "otherCarpetTotal": "49.98",
  "builtupPercentage": "20",
  "finalBuiltupArea": "845.87",
  "finalCarpetArea": "704.89",
  "finalSalableArea": "930.45",
  "salablePercentage": "10",
  "toBeAdded": "",
  "extendOfSiteRemark": "Carpet Area in Sq. Ft. = 668.00\nService Area in Sq. Ft. =
31.00\nTotal Carpet Area in Sq. Ft. = 699.00\n(Area as per Draft Agreement for Sale)",
  "siteMeasurementRemark": "Carpet Area in Sq. Ft. = 655.00\nCupboard Area in Sq.
Ft. = 22.00\nDry Balcony Area in Sq. Ft. = 28.00\nTotal Carpet Area in Sq. Ft. =
705.00\n(Area as per Actual Site Measurement)",
  "otherCompositionBuiltUpTotal": "0.00",
  "otherCompositionCarpetTotal": "49.98",
  "otherCompositionSaleableTotal": "0.00",
  "reportGeneratedDate": "Sat Apr 20 2024 10:23:23 GMT+0530 (India Standard Time)",
  "siteVisitDate": "2024-04-10"
}

```

Name	Length	Width	Total
Composition :			
Dining	8'5"	10'2"	85.57
Living Room	18'00"	9'8"	174.00
Kitchen	9'2"	9'4"	85.56
Toilet	4'1"	4'1"	16.67
Toilet	5'7"	3'7"	20.01
Bedroom	9'10"	9'6"	93.42
Bedroom	9'6"	13'4"	126.67
Passage	6'8"	2'10"	18.89
Passage	7'7"	4'6"	34.12

Other  
Composition :

Cupboard	2'00"	4'2"	8.33
Cupboard	2'1"	6'6"	13.54
Dry Balcony Area	3'8"	7'8"	28.11