

```
{
  "typeOfReport": {
    "value": "Shop",
    "label": "Shop"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b807"
    },
    "type": "CREDITOFFICER",
    "_id": "661e19817e1d7332c87ceae5",
    "firstName": "Deepathy",
    "lastName": "Madam",
    "mobileNo": "",
    "workMobileNo": "7506648339",
    "email": "1sbi.60347@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "10500000",
    "discussWithPerson": "Aashish Kurzekar",
    "expectedFees": 5250,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b807",
  "branchCode": "000081",
  "type": "BRANCH",
  "name": "SME Vashi Turbhe Branch (Sector 19)",
  "email": "sbi.60347@sbi.co.in",
  "mobileNo": "0000000000",
  "alternateMobileNo": "",
  "address": "Sector No. 19, Vashi Branch, Central Facility Bldg., Phase - II, Market II,
Vashi, Navi Mumbai, State - Maharashtra, Country - India. ",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Commercial",
  "value": "Commercial"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60b7189d2ffdf65bcd65882b",
  "role": "PICKUPPERSON",
  "firstName": "Ravindra",
  "email": "ravindrakasare186@gmail.com",
  "lastName": "Kasare",
  "mobileNo": "9167204055",
  "shortName": "RBK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60b7189d2ffdf65bcd65882b\\
\\profilePhoto_1622701555488_WhatsApp Image 2021-06-03 at 11.46.40 AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "627362b3afd7d55eddee1ee7",
  "role": "SITEENGINEER",
  "firstName": "Vicky ",
  "email": "vicky@vastukala.org",
  "lastName": "Baor",
  "mobileNo": "9004386288",
  "designation": "",
  "shortName": "VB",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "9004437379",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\\
\\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60f91b6f344e052188ffd1fc",
  "role": "MAKER",
  "firstName": "Jayaraja",
  "email": "jayaraja@vastukala.org",
  "lastName": "Acharya",
  "mobileNo": "9867664219",
```

```
"designation": "",
"shortName": "JA",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91b6f344e052188ffd1fc/
profilePhoto_1678780588416_Profile_Photo.jpeg"
},
"checker": null,
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
},
{
"title": {
"value": "FIIV",
"label": "FIIV"
},
"_id": "60af80072ffdf65bcd658652",
"number": "CAT-I-F-1763"
},
{
"title": {
"value": "Chartered_Engineer",
"label": "Chartered Engineer"
},
"_id": "60af80072ffdf65bcd658653",
"number": "AM161706-3"
}
```

```
    },
    {
      "title": {
        "value": "Registered_Valuer",
        "label": "Registered Valuer"
      },
      "_id": "60af80072ffdf65bcd658654",
      "number": "IBBI/RV/07/2018/10366"
    }
  ],
  "shortName": "MBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
profilePhoto_1622114310919_Manoj C.jpeg",
  "PANNo": "AERPC9086P",
  "fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.009845892916758",
  "longitude": "73.1124306588718"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.1124306588718,
    19.009845892916758
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "16/04/2024 12:49 pm"
    },
    {
      "dateTime": "16/04/2024 12:00 am"
    }
  ],
  "visitedDate": []
},
```

```
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "New Panvel",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "Ground",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": true,
```

```
"name": "District",
"key": "district",
"value": "Raigad",
"label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Panvel",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "15 / 16",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Shreeji Sangh Co-op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": true,
  "name": "Sector",
  "key": "selectArea",
  "value": "7",
  "label": true
}
```

```
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Khanda Colony",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
```



```
"key": "newSurveyNumber",
"value": "",
"label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "Shop No. 28",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
}
```

```
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 410 206",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "New Panvel (West), Navi Mumbai",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "R.C.C._slab",
```

```
"label": "R.C.C. slab"
},
"flooring": {
  "value": "Vitrified_tiles_flooring",
  "label": "Vitrified tiles flooring"
},
"doors": {
  "value": "MS_Rolling_Shutter",
  "label": "MS Rolling Shutter"
},
"windows": {
  "value": "N.A.",
  "label": "N.A."
},
"fittings": {
  "value": "Concealed_Electrification",
  "label": "Concealed Electrification"
},
"finishing": {
  "value": "Cement_Plastering",
  "label": "Cement Plastering"
}
},
"general": {
  "ownership": {
    "value": "Sole_Ownership",
    "label": "Sole Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "Panvel_Municipal_Corporation",
    "label": "Panvel Municipal Corporation"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Marvel CHSL & Residential Building",
```

```
"west": "30 Feet Road",
"south": "Internal Road",
"east": "Internal Road"
},
"asPerDocumentAgreement": {
  "north": "Plot No. 14 / 17",
  "west": "20 mtr. Wide Road",
  "south": "5/11 mtr. Wide Road",
  "east": "11 mtr. Wide Road"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "asPerDocument": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "As Occupancy Certificate is received it may be assumed
that the construction is as per Sanctioned Plan.",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "No",
"unauthorizedConstruction": ""
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Commercial_Purpose",
    "label": "Commercial Purpose"
  },
  "propertyOccupiedByList": {
```

```
"value": "Tenant_Occupied",
"label": "Tenant Occupied"
},
"monthlyRent": "000/- Present rental income per month",
"assessmentNo": "Information not available",
"taxPaidHolderName": "Information not available",
"taxAmount": "Information not available",
"electricityServiceConnectionNo": "Information not available",
"meterCardHolderName": "Information not available",
"undividedAreaOfLandAsPerSaleDeed": "50% Undivided Share",
"floorSpaceIndex": "As per CIDCO norms",
"tenantName": "Bank of Baroda",
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "R.C.C._slab",
    "label": "R.C.C. slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Open Car Parking Space",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
```

```
"label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2004",
  "fullDate": "1/1/2004"
},
"planningArea": {
  "value": "Residential_cum_Commercial",
  "label": "Residential cum Commercial"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
```

```
"label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "0",
  "label": "No"
},
"provisionOfFirefighting": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "40",
"ageOfBuilding": "20",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "6",
"flatFloorNo": "Ground",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "38"
},
```

```
"finalPlinthArea": {
  "area": "450.00",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 20%"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/661e1ff57e1d7332c87d0074/
routeMap_1713529004304_Image.png",
    "routeLat": "19.009422",
    "routeLng": "73.112193",
    "stationName": "Khandeshwar",
    "routeDistance": "2.1 km"
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "2581wo",
      "name": "2581wo",
      "image": "cases/661e1ff57e1d7332c87d0074/
routeMap_1713528700711_Image.png"
    }
  ]
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
}
```



```
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalPlastering": {
    "label": "External Plastering",
    "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0.00",
  "selectedBuildUpValue": "450.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "6621e4607e1d7332c880ed21",
      "name": "externalImg_1713497183296_IMG_20240418_27572.jpg",
      "path": "cases/661e1ff57e1d7332c87d0074/
externalImg_1713497183296_IMG_20240418_27572.jpg",
      "orientation": "landscape"
    }
  ],
  "selfieWithSiteVisitImages": [
```

```
{
  "status": false,
  "_id": "6621e4607e1d7332c880ed22",
  "name": "externallmg_1713497183300_IMG_20240418_27931.jpg",
  "path": "cases/661e1ff57e1d7332c87d0074/
externallmg_1713497183300_IMG_20240418_27931.jpg",
  "orientation": "landscape"
},
"externalPhotos": [
  {
    "status": false,
    "_id": "6621e4607e1d7332c880ed20",
    "name": "externallmg_1713497183294_IMG_20240418_27192.jpg",
    "path": "cases/661e1ff57e1d7332c87d0074/
externallmg_1713497183294_IMG_20240418_27192.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6621e4607e1d7332c880ed25",
    "name": "externallmg_1713497183311_IMG_20240418_29212.jpg",
    "path": "cases/661e1ff57e1d7332c87d0074/
externallmg_1713497183311_IMG_20240418_29212.jpg",
    "orientation": "landscape"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
    "_id": "6621e4507e1d7332c880ecd0",
    "name": "Shop",
    "path": "cases/661e1ff57e1d7332c87d0074/
externallmg_1713497167013_IMG_20240418_2011.jpg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "6621e4507e1d7332c880ecd1",
    "name": "Shop",
    "path": "cases/661e1ff57e1d7332c87d0074/
externallmg_1713497167018_IMG_20240418_2415.jpg",
    "orientation": "landscape"
  }
],
```

```
{
  "status": false,
  "_id": "6621e4507e1d7332c880ecd7",
  "name": "Shop",
  "path": "cases/661e1ff57e1d7332c87d0074/
externallmg_1713497167035_IMG_20240418_22514.jpg",
  "orientation": "landscape"
},
{
  "status": false,
  "_id": "6621e4507e1d7332c880ecd9",
  "name": "Shop",
  "path": "cases/661e1ff57e1d7332c87d0074/
externallmg_1713497167039_IMG_20240418_23335.jpg",
  "orientation": "landscape"
},
{
  "status": false,
  "_id": "6621e4507e1d7332c880ecda",
  "name": "Shop",
  "path": "cases/661e1ff57e1d7332c87d0074/
externallmg_1713497167040_IMG_20240418_23701.jpg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "6621e4507e1d7332c880ecdb",
  "name": "Shop",
  "path": "cases/661e1ff57e1d7332c87d0074/
externallmg_1713497167042_IMG_20240418_24384.jpg",
  "orientation": "landscape"
},
{
  "status": false,
  "_id": "6621e4507e1d7332c880ecdc",
  "name": "Shop",
  "path": "cases/661e1ff57e1d7332c87d0074/
externallmg_1713497167044_IMG_20240418_24697.jpg",
  "orientation": "landscape"
},
{
  "status": false,
  "_id": "6621e4507e1d7332c880ecdd",
  "name": "Shop",
  "path": "cases/661e1ff57e1d7332c87d0074/
externallmg_1713497167046_IMG_20240418_25155.jpg",
```

```
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6621e4607e1d7332c880ed1b",
    "name": "Shop",
    "path": "cases/661e1ff57e1d7332c87d0074/
externallmg_1713497183285_IMG_20240418_25549.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6621e4607e1d7332c880ed1c",
    "name": "Shop",
    "path": "cases/661e1ff57e1d7332c87d0074/
externallmg_1713497183286_IMG_20240418_25843.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6621e4607e1d7332c880ed1d",
    "name": "Shop",
    "path": "cases/661e1ff57e1d7332c87d0074/
externallmg_1713497183289_IMG_20240418_26140.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6621e4607e1d7332c880ed1e",
    "name": "Shop",
    "path": "cases/661e1ff57e1d7332c87d0074/
externallmg_1713497183291_IMG_20240418_26441.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6621e4607e1d7332c880ed1f",
    "name": "Shop",
    "path": "cases/661e1ff57e1d7332c87d0074/
externallmg_1713497183292_IMG_20240418_26733.jpg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
```

```
"min": "0.00",
"max": "0.00"
},
"builtUpRateRange": {
  "min": "0.00",
  "max": "0.00"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
```



```
    "ratePerUnit": "",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  }
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "375.00",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
"invoices": [],
"paymentIds": [],
"_id": "661e1ff57e1d7332c87d0074",
"ownerName": "Mrs. Neena Vijay Kakkar",
"ownerPhoneNo": "9920329888",
"appAddress": "shop no. 28 Ground floor shree G sang co op Hsg soc Ltd plot no. 15
16 sector no 7 new panvel ",
"remark": "bankar. Deepthy 7506648339",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    }
  },

```

```
"inputs": {
  "documentDate": "25/04/2012",
  "from": {
    "value": "Transferor",
    "label": "Transferor"
  },
  "Transferor": "Mr. Devinder Trehan",
  "to": {
    "value": "Transferee",
    "label": "Transferee"
  },
  "Transferee": "Mrs. Neena Vijay Kakkar",
  "number": {
    "value": "Registration_No",
    "label": "Registration No"
  },
  "Registration_No": "3697/2012"
},
"isHardCopy": false,
"displayStatus": true,
"id": "218721",
"path": "cases/661e1ff57e1d7332c87d0074/document_1713250286323_46199.pdf",
"fileName": "document_1713250286323_46199.pdf"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "30/08/2004",
    "nameOfApprovingAuthority": {
      "value": "City_and_Industrial_Development_Corp_Of_Maharashtra_ltd.",
      "label": "City and Industrial Development Corp Of Maharashtra Ltd."
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "CIDCO/BP/ATPO/1135"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1713588303712_OC.pdf",
  "path": "cases/661e1ff57e1d7332c87d0074/document_1713588303712_OC.pdf",
  "id": "848851",
```

```
"uploadedBy": "60f91b6f344e052188ffd1fc",
"createdAt": "Sat Apr 20 2024 10:15:03 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "008247",
"createdBy": "60b7189d2ffdf65bcd65882b",
"caseHistory": [
  {
    "id": "947387",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Apr 16 2024 12:21:33 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mrs. Neena Vijay Kakkar",
    "phone": "9920329888",
    "ownershipShare": "",
    "email": "",
    "id": "857833"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "775776",
    "name": "Shop",
    "length": "30.42",
    "length1": "30",
    "length2": "5",
    "width": "8.92",
    "width1": "8",
    "width2": "11",
    "totalArea": "271.21",
    "images": [],
    "extraAreas": [],
    "finalArea": "271.21"
  }
],
"otherComposition": [
```

```
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Loft",
    "value": "Loft"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "0",
  "length": "10.75",
  "length1": "10",
  "length2": "9",
  "width": "8.75",
  "width1": "8",
  "width2": "9",
  "totalArea": "94.06",
  "images": [],
  "extraAreas": [],
  "finalArea": "94.06",
  "percentageBeforeTotal": "94.06",
  "percentage": "100"
}
],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "267009",
    "selectAreaTypeDocument": "Carpet",
    "totalAreaDocument": "375",
    "squareMeterArea": "34.84",
    "docFinalBuiltUp": "450",
    "docFinalBuiltUpSquareMeter": "41.80800000000001",
    "docBuiltupPercentage": "20",
```

```
    "docSaleablePercentage": "0",
    "docFinalSaleable": "0",
    "docFinalSaleableSquareMeter": "0"
  }
],
"images": [],
"indicatorArr": [],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6621e4507e1d7332c880ecd0",
    "name": "externallmg_1713497167013_IMG_20240418_2011.jpg",
    "path": "cases/661e1ff57e1d7332c87d0074/
externallmg_1713497167013_IMG_20240418_2011.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6621e4507e1d7332c880ecd1",
    "name": "externallmg_1713497167018_IMG_20240418_2415.jpg",
    "path": "cases/661e1ff57e1d7332c87d0074/
externallmg_1713497167018_IMG_20240418_2415.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6621e4507e1d7332c880ecd2",
    "name": "externallmg_1713497167021_IMG_20240418_3099.jpg",
    "path": "cases/661e1ff57e1d7332c87d0074/
externallmg_1713497167021_IMG_20240418_3099.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6621e4507e1d7332c880ecd3",
    "name": "externallmg_1713497167024_IMG_20240418_19422.jpg",
    "path": "cases/661e1ff57e1d7332c87d0074/
externallmg_1713497167024_IMG_20240418_19422.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "6621e4507e1d7332c880ecd4",
    "name": "externalimg_1713497167027_IMG_20240418_21291.jpg",
    "path": "cases/661e1ff57e1d7332c87d0074/
externalimg_1713497167027_IMG_20240418_21291.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6621e4507e1d7332c880ecd5",
    "name": "externalimg_1713497167031_IMG_20240418_21616.jpg",
    "path": "cases/661e1ff57e1d7332c87d0074/
externalimg_1713497167031_IMG_20240418_21616.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6621e4507e1d7332c880ecd6",
    "name": "externalimg_1713497167033_IMG_20240418_21982.jpg",
    "path": "cases/661e1ff57e1d7332c87d0074/
externalimg_1713497167033_IMG_20240418_21982.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6621e4507e1d7332c880ecd7",
    "name": "externalimg_1713497167035_IMG_20240418_22514.jpg",
    "path": "cases/661e1ff57e1d7332c87d0074/
externalimg_1713497167035_IMG_20240418_22514.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6621e4507e1d7332c880ecd8",
    "name": "externalimg_1713497167037_IMG_20240418_22923.jpg",
    "path": "cases/661e1ff57e1d7332c87d0074/
externalimg_1713497167037_IMG_20240418_22923.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```

```
    "_id": "6621e4507e1d7332c880ecd9",
    "name": "externallmg_1713497167039_IMG_20240418_23335.jpg",
    "path": "cases/661e1ff57e1d7332c87d0074/
externallmg_1713497167039_IMG_20240418_23335.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6621e4507e1d7332c880ecda",
    "name": "externallmg_1713497167040_IMG_20240418_23701.jpg",
    "path": "cases/661e1ff57e1d7332c87d0074/
externallmg_1713497167040_IMG_20240418_23701.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6621e4507e1d7332c880ecdb",
    "name": "externallmg_1713497167042_IMG_20240418_24384.jpg",
    "path": "cases/661e1ff57e1d7332c87d0074/
externallmg_1713497167042_IMG_20240418_24384.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6621e4507e1d7332c880ecdc",
    "name": "externallmg_1713497167044_IMG_20240418_24697.jpg",
    "path": "cases/661e1ff57e1d7332c87d0074/
externallmg_1713497167044_IMG_20240418_24697.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6621e4507e1d7332c880ecdd",
    "name": "externallmg_1713497167046_IMG_20240418_25155.jpg",
    "path": "cases/661e1ff57e1d7332c87d0074/
externallmg_1713497167046_IMG_20240418_25155.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6621e4507e1d7332c880ecde",
```

```
    "name": "externallmg_r_1713497166944_IMG20240418182128.jpg",
    "path": "cases/661e1ff57e1d7332c87d0074/
externallmg_r_1713497166944_IMG20240418182128.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6621e4607e1d7332c880ed1b",
    "name": "externallmg_1713497183285_IMG_20240418_25549.jpg",
    "path": "cases/661e1ff57e1d7332c87d0074/
externallmg_1713497183285_IMG_20240418_25549.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6621e4607e1d7332c880ed1c",
    "name": "externallmg_1713497183286_IMG_20240418_25843.jpg",
    "path": "cases/661e1ff57e1d7332c87d0074/
externallmg_1713497183286_IMG_20240418_25843.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6621e4607e1d7332c880ed1d",
    "name": "externallmg_1713497183289_IMG_20240418_26140.jpg",
    "path": "cases/661e1ff57e1d7332c87d0074/
externallmg_1713497183289_IMG_20240418_26140.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6621e4607e1d7332c880ed1e",
    "name": "externallmg_1713497183291_IMG_20240418_26441.jpg",
    "path": "cases/661e1ff57e1d7332c87d0074/
externallmg_1713497183291_IMG_20240418_26441.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6621e4607e1d7332c880ed1f",
    "name": "externallmg_1713497183292_IMG_20240418_26733.jpg",
```



```
    "path": "cases/661e1ff57e1d7332c87d0074/
externallmg_1713497183292_IMG_20240418_26733.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6621e4607e1d7332c880ed20",
    "name": "externallmg_1713497183294_IMG_20240418_27192.jpg",
    "path": "cases/661e1ff57e1d7332c87d0074/
externallmg_1713497183294_IMG_20240418_27192.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6621e4607e1d7332c880ed21",
    "name": "externallmg_1713497183296_IMG_20240418_27572.jpg",
    "path": "cases/661e1ff57e1d7332c87d0074/
externallmg_1713497183296_IMG_20240418_27572.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6621e4607e1d7332c880ed22",
    "name": "externallmg_1713497183300_IMG_20240418_27931.jpg",
    "path": "cases/661e1ff57e1d7332c87d0074/
externallmg_1713497183300_IMG_20240418_27931.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6621e4607e1d7332c880ed23",
    "name": "externallmg_1713497183304_IMG_20240418_28257.jpg",
    "path": "cases/661e1ff57e1d7332c87d0074/
externallmg_1713497183304_IMG_20240418_28257.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6621e4607e1d7332c880ed24",
    "name": "externallmg_1713497183307_IMG_20240418_28766.jpg",
    "path": "cases/661e1ff57e1d7332c87d0074/
externallmg_1713497183307_IMG_20240418_28766.jpg",
```

```
"orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6621e4607e1d7332c880ed25",
  "name": "externallmg_1713497183311_IMG_20240418_29212.jpg",
  "path": "cases/661e1ff57e1d7332c87d0074/
externallmg_1713497183311_IMG_20240418_29212.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6621e4607e1d7332c880ed26",
  "name": "externallmg_1713497183313_IMG_20240418_29689.jpg",
  "path": "cases/661e1ff57e1d7332c87d0074/
externallmg_1713497183313_IMG_20240418_29689.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6621e4607e1d7332c880ed27",
  "name": "externallmg_1713497183316_IMG_20240418_30419.jpg",
  "path": "cases/661e1ff57e1d7332c87d0074/
externallmg_1713497183316_IMG_20240418_30419.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6621e4607e1d7332c880ed28",
  "name": "externallmg_1713497183318_IMG_20240418_30818.jpg",
  "path": "cases/661e1ff57e1d7332c87d0074/
externallmg_1713497183318_IMG_20240418_30818.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6621e4607e1d7332c880ed29",
  "name": "externallmg_1713497183320_IMG_20240418_132212.jpg",
  "path": "cases/661e1ff57e1d7332c87d0074/
externallmg_1713497183320_IMG_20240418_132212.jpg",
  "orientation": "portrait"
}
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "6621e4607e1d7332c880ed2a",
      "name": "externalImg_1713497183530_Screenshot_2024041813001568_3d9111e2d3171bf4882369f490c087b4.jpg",
      "path": "cases/661e1ff57e1d7332c87d0074/externalImg_1713497183530_Screenshot_2024041813001568_3d9111e2d3171bf4882369f490c087b4.jpg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "6621e4607e1d7332c880ed2b",
      "name": "externalImg_r_1713497183387_IMG20240418182123.jpg",
      "path": "cases/661e1ff57e1d7332c87d0074/externalImg_r_1713497183387_IMG20240418182123.jpg",
      "orientation": "portrait"
    }
  ],
  "externalDocuments": [],
  "processingDocuments": [
    {
      "originalname": "Google Loction.jpg",
      "filename": "1713532248762_Google_Loction.jpg",
      "path": "cases/661e1ff57e1d7332c87d0074/processingDocuments/1713532248762_Google_Loction.jpg",
      "size": "1218429",
      "createdAt": "Fri Apr 19 2024 18:40:48 GMT+0530 (India Standard Time)",
      "uploadedBy": "60f91b6f344e052188ffd1fc"
    },
    {
      "originalname": "Sale Deed 2012.pdf",
      "filename": "1713532248787_Sale_Deed_2012.pdf",
      "path": "cases/661e1ff57e1d7332c87d0074/processingDocuments/1713532248787_Sale_Deed_2012.pdf",
      "size": "253196",
      "createdAt": "Fri Apr 19 2024 18:40:48 GMT+0530 (India Standard Time)",
      "uploadedBy": "60f91b6f344e052188ffd1fc"
    },
    {
      "originalname": "Site Details.jpg",
      "filename": "1713532248792_Site_Details.jpg",
      "path": "cases/661e1ff57e1d7332c87d0074/processingDocuments/1713532248792_Site_Details.jpg",
```

```
"size": "1511843",
"createdAt": "Fri Apr 19 2024 18:40:48 GMT+0530 (India Standard Time)",
"uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
  "originalname": "Sketch.jpg",
  "filename": "1713532248816_Sketch.jpg",
  "path": "cases/661e1ff57e1d7332c87d0074/
processingDocuments/1713532248816_Sketch.jpg",
  "size": "1256321",
  "createdAt": "Fri Apr 19 2024 18:40:48 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-04-16T06:51:33.774Z",
"updatedAt": "2024-04-20T04:45:40.577Z",
"__v": 0,
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"fullAddress": "Commercial Shop No. Shop No. 28, Ground Floor, Shreeji Sangh Co-
op. Hsg. Soc. Ltd., Plot No. 15 / 16, Sector 7, Khanda Colony, Village - New Panvel,
New Panvel (West), Navi Mumbai, Taluka - Panvel, District - Raigad, PIN - 410 206,
State - Maharashtra, India",
"updatedBy": "60f91b6f344e052188ffd1fc",
"addressForMap": "",
"caseReferredBy": "60b7189d2ffdf65bcd65882b",
"contactPersonName": "Mr. Rajendra",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Bank Manager",
"siteVisitContactNo": "9920329888",
"briefDescOfProperty": "Shop",
"carpetTotal": "271.21",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "94.06",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "94.06",
```

"otherCompositionSaleableTotal": "0.00",
 "builtupPercentage": "10",
 "finalBuiltupArea": "401.80",
 "finalCarpetArea": "365.27",
 "finalSalableArea": "401.80",
 "salablePercentage": "0",
 "toBeAdded": "",
 "extendOfSiteRemark": "Carpet Area in Sq. Ft. = 280.00\nLoft Area in Sq. Ft. = 94.06",
 "siteMeasurementRemark": "Carpet Area in Sq. Ft. = 271.21 \nLoft Area in Sq. Ft. = 94.06",
 "finalAreaType": "Carpet Area",
 "finalAsPerArea": "Agreement For Sale",
 "finalBuiltUpPercentage": "20",
 "finalCarpetConvertToBuiltUpPer": "20",
 "finalSaleablePercentage": "0",
 "finalValuationAreaString": "Carpet Area in Sq. Ft. = 375.00"

}

Name	Length	Width	Total
Composition :			
Shop	30'5"	8'11"	271.21
Other Composition :			
Loft	10'9"	8'9"	94.06