

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b9f4"
    },
    "type": "CREDITOFFICER",
    "_id": "650581d3a8e9b70221e855e5",
    "firstName": "Bhakti",
    "lastName": "Podkar",
    "mobileNo": "",
    "workMobileNo": "8425827511",
    "email": "bhakti.phodkar@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b9f4",
  "branchCode": "000215",
  "type": "BRANCH",
  "name": "RACPC Sion ",
  "email": "racpc.sion@sbi.co.in",
  "mobileNo": "02225046265",
  "alternateMobileNo": "",
  "address": "B-603 & 604, Kohinoor City, Commercial-1, 6th Floor, Kirol Road, Off
L.B.S. Marg, Kurla (West), Mumbai, Pin Code - 400 070, State - Maharashtra, Country -
India.",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "60b7177d2ffdf65bcd65882a",
  "role": "PICKUPPERSON",
  "firstName": "Saurabh",
  "email": "saurabhvelonde143@gmail.com",
  "lastName": "Velonde",
  "mobileNo": "8691048846",
  "shortName": "SSV",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1686816492317_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "642bad2b91d7c62df117fef2",
  "role": "SITEENGINEER",
  "firstName": "Abhiraj",
  "email": "abhishekharijan@gmail.com",
  "lastName": "Bhagat",
  "mobileNo": "8369839430",
  "designation": "",
  "shortName": "AH",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316"
},
"rateVerifier": null,
"maker": {
  "type": "EMPLOYEE",
  "_id": "60f91b6f344e052188ffd1fc",
  "role": "MAKER",
  "firstName": "Jayaraja",
  "email": "jayaraja@vastukala.org",
  "lastName": "Acharya",
  "mobileNo": "9867664219",
  "designation": "",
  "shortName": "JA",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f91b6f344e052188ffd1fc/
profilePhoto_1678780588416_Profile_Photo.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
```

```
"lastName": "Sarmalkar",
"mobileNo": "9004437379",
"shortName": "VS",
"workWithDocumentMaker": "1",
"profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
"designation": ""
},
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
},
{
"title": {
"value": "FIIV",
"label": "FIIV"
},
"_id": "60af80072ffdf65bcd658652",
"number": "CAT-I-F-1763"
},
{
"title": {
"value": "Chartered_Engineer",
"label": "Chartered Engineer"
},
"_id": "60af80072ffdf65bcd658653",
```

```
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
  "latitude": "18.66170600004422",
  "longitude": "73.7101535640808"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.7101535640808,
    18.66170600004422
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "16/04/2024 05:04 pm"
    }
  ]
},
"visitedDate": [
  {
    "status": "COMPLETED",
    "dateTime": "2024-04-17",
```

```
    "remark": "MANUAL_IN_TASK"
  }
]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "3BHK",
  "label": "3 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Gahunje",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "22",
    "label": false
  },
  "buildingNo": {
```

```
"status": true,
"name": "Building No",
"key": "buildingNo",
"value": "12",
"label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Pune",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Pune",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Maval",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Ashbridge Co-op. Hsg. Soc. Ltd.",
```

```
"label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Opp. M.C.A. Stadium",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Off Mumbai - Pune Express Highway",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Lodha Belmondo",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
```



```
"name": "Old Survey No.",
"key": "oldSurveyNumber",
"value": "",
"label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "205(pt), 221(pt), 225(pt), 226(pt), 227(pt), 228(pt), 229 to 231, 233 to 241,
242(pt), 243 to 247, 248(pt), 249 (pt), 251(pt), 252 to 256, 358(pt), 359(pt), 360(pt)",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "2204",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
```

```
"label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 410 506",
  "label": false
},
"suburb": {
  "status": false,
```

```
"name": "Suburb",
"key": "suburb",
"value": "",
"label": false
}
},
"flatSpecifications": {
"roof": {
"value": "R.C.C._slab",
"label": "R.C.C. slab"
},
"flooring": {
"value": "Vitrified_tiles_flooring",
"label": "Vitrified tiles flooring"
},
"doors": {
"value": "Teak_wood_door_frame_with_flush_shutters",
"label": "Teak wood door frame with flush shutters"
},
"windows": {
"value": "Powder_coated_Aluminum_sliding_windows",
"label": "Powder coated Aluminum sliding windows"
},
"fittings": {
"value": "Concealed_plumbing_with_C.P._fittings._Concealed_Electrical_wiring",
"label": "Concealed plumbing with C.P. fittings. Concealed Electrical wiring"
},
"finishing": {
"value": "Cement_Plastering_+_POP_Finish",
"label": "Cement Plastering + POP Finish"
}
},
"general": {
"ownership": {
"value": "Joint_Ownership",
"label": "Joint Ownership"
},
"populationClassList": {
"value": "MiddleClass",
"label": "Middle Class"
},
"populationGroupList": {
"value": "Urban",
"label": "Urban"
},
"townplanApprovedByList": {
```

```
    "value": "Pune_Municipal_Corporation",
    "label": "Pune Municipal Corporation"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Service Road",
    "west": "Golf Course",
    "south": "Golf Club / Pawana River",
    "east": "Internal Road"
  },
  "asPerDocumentAgreement": {
    "north": "Information not available",
    "west": "Information not available",
    "south": "Information not available",
    "east": "Information not available"
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "",
      "west": "",
      "south": "",
      "east": ""
    },
    "asPerDocument": {
      "north": "",
      "east": "",
      "south": "",
      "west": ""
    }
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "+ Terrace Area.",
"dateOfIssusApprovePlan": "As Part Occupancy Certificate is received it may be assumed that the construction is as per Sanctioned Plan.",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "No",
"unauthorizedConstruction": ""
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "10.5",
  "depreciationRatioOfBuilding": "",
```

```
"salvageValue": "10",
"buildingServicesDepreciatedRate": "262.5",
"depreciatedCostOfConstruction": "14437.50",
"depreciatedBuildingRate": "2237.5"
},
"igrRate": {
  "propertyName": "Flat",
  "rate": "40940",
  "landRate": "2470",
  "igrImage": "cases/661e3b3e7e1d7332c87d59bf/igr_1713353879386_Image.png",
  "squareMeterGuideLineRate": "47081.00",
  "squareFeetGuideLineRate": "4374.00"
},
"igrFinalRate": {
  "floorRatePercentage": "15",
  "depreciationPercentage": "93",
  "rate": "4084.00",
  "squareFeetGuideLineRate": "4084.00",
  "squareMeterGuideLineRate": "43958.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Seller_Occupied",
    "label": "Seller Occupied"
  },
  "monthlyRent": "43,000/- Expected rental income per month.",
  "assessmentNo": "0932/83",
  "taxPaidHolderName": "Bindu Radhakrishnan & Radhakrishnan Chakyat",
  "taxAmount": "9804",
  "electricityServiceConnectionNo": "181643580262",
  "meterCardHolderName": "Radhakrishnan Chakyat",
  "undividedAreaOfLandAsPerSaleDeed": "Information not available",
  "floorSpaceIndex": "As per PMC norms",
  "tenantName": "",
  "maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
```

```
"value": "Good",
"label": "Good"
},
"anyFavouringForExtraPotentialValue": "Located in developed area",
"negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
"roof": {
"value": "R.C.C._slab",
"label": "R.C.C. slab"
},
"partitions": {
"value": "6\"_Thk._Brick_Masonry",
"label": "6\" Thk. Brick Masonery"
},
"waterTank": {
"value": "MunicipalWaterSupply",
"label": "Municipal Water Supply"
},
"pavementLaid": {
"value": "Yes",
"label": "Yes"
},
"carParking": "2 Car Parking Space",
"constructionWorkStatus": {
"value": "Completed",
"label": "Completed"
},
"asthetikLook": {
"value": "Plain_Looking",
"label": "Plain Looking"
},
"dateOfConstruction": {
"date": "1",
"month": "1",
"year": "2017",
"fullDate": "1/1/2017"
},
"planningArea": {
"value": "Residential",
"label": "Residential"
},
"typeOfStructure": {
"value": "R.C.C._Framed_Structure",
"label": "R.C.C. Framed Structure"
},
}
```

```
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenancelssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "0",
```

```
"label": "No"
},
"systemOfAirConditioning": {
  "value": "0",
  "label": "No"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "stilt",
  "label": "Stilt"
},
"yearOfConstructionAsPer": {
  "value": "As_Per_Part_Occupancy_Certificate",
  "label": "As Per Part Occupancy Certificate"
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "7",
"totalLifeBuilding": "60",
"estimatedAge": "53",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "22",
"flatFloorNo": "22",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
  "area": "1575.20",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/661e3b3e7e1d7332c87d59bf/
routeMap_1713418332488_Image.png",
    "routeLat": "18.661882",
    "routeLng": "73.708725",
```



```
"stationName": "Chinchwad Junction",
"routeDistance": "11.6 km."
},
"finalLatLng": {
  "coordinates": [
    null,
    null
  ],
  "type": "Point"
},
"showLocation": {
  "latLng": true,
  "finallatLng": true
},
"locationMapImg": [
  {
    "id": "qapnz7",
    "name": "qapnz7",
    "image": "cases/661e3b3e7e1d7332c87d59bf/
routeMap_1713418047682_Image.png"
  }
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
```

```
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "20675216.00",
"finalValue": "20675216.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValueDocument": null,
"purchaseValueDocument": null,
"bookValue": "0"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Thu Apr 18 2024 15:41:53 GMT+0530 (India Standard Time)",
  "number": "2305996",
  "dayCount": "2",
  "monthCount": "135",
  "generatedBy": "5fc78e26625ecd20ec1f88e9"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
}
```

```
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"guidelineDetails": {
  "finalGuidelineValue": "6433117.00",
  "selectedBuildUpValue": "1575.20",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "6620ae2f7e1d7332c87fbfd8",
      "name": "externallmg_r_1713417774696_externallmg_1713352496530_WhatsApp_Image_20240417_at_161421.jpeg",
      "path": "cases/661e3b3e7e1d7332c87d59bf/externallmg_r_1713417774696_externallmg_1713352496530_WhatsApp_Image_20240417_at_161421.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "6620ae2f7e1d7332c87fbfd7",
      "name": "externallmg_1713417774695_externallmg_1713352496524_WhatsApp_Image_20240417_at_161420.jpeg",
      "path": "cases/661e3b3e7e1d7332c87d59bf/externallmg_1713417774695_externallmg_1713352496524_WhatsApp_Image_20240417_at_161420.jpeg",
      "orientation": "landscape"
    }
  ],
  "externalPhotos": [
    {
      "status": false,
      "_id": "6620ae2f7e1d7332c87fbfd2",
      "name": "externallmg_1713417774682_externallmg_1713352476745_WhatsApp_Image_20240417_at_161419_1.jpeg",
      "path": "cases/661e3b3e7e1d7332c87d59bf/externallmg_1713417774682_externallmg_1713352476745_WhatsApp_Image_20240417_at_161419_1.jpeg",
      "orientation": "landscape"
    }
  ],
}
```

```
{
  "status": false,
  "_id": "6620ae4c7e1d7332c87fc08b",
  "name": "externallmg_1713417803521_externallmg_1713352496566_WhatsApp_I
mage_20240417_at_161410_2.jpeg",
  "path": "cases/661e3b3e7e1d7332c87d59bf/externallmg_1713417803521_externa
llmg_1713352496566_WhatsApp_Image_20240417_at_161410_2.jpeg",
  "orientation": "landscape"
}
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
    "_id": "6620ae207e1d7332c87fbf5b",
    "name": "Living Room",
    "path": "cases/661e3b3e7e1d7332c87d59bf/externallmg_1713417758937_externa
llmg_1713352476718_WhatsApp_Image_20240417_at_161416_2.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "6620ae2f7e1d7332c87fbfd3",
    "name": "Living Room",
    "path": "cases/661e3b3e7e1d7332c87d59bf/externallmg_1713417774686_externa
llmg_1713352476750_WhatsApp_Image_20240417_at_161419_2.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "6620ae2f7e1d7332c87fbfd4",
    "name": "Living Room",
    "path": "cases/661e3b3e7e1d7332c87d59bf/externallmg_1713417774689_externa
llmg_1713352476753_WhatsApp_Image_20240417_at_161419.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "6620ae3a7e1d7332c87fc032",
    "name": "Living Room",
    "path": "cases/661e3b3e7e1d7332c87d59bf/externallmg_1713417786223_externa
llmg_1713352496537_WhatsApp_Image_20240417_at_161406.jpeg",
    "orientation": "landscape"
  },
  {

```

```
    "status": false,
    "_id": "6620ae3a7e1d7332c87fc035",
    "name": "Living Room",
    "path": "cases/661e3b3e7e1d7332c87d59bf/externallmg_1713417786229_externa
llmg_1713352496544_WhatsApp_Image_20240417_at_161407.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "6620ae3a7e1d7332c87fc036",
    "name": "Living Room",
    "path": "cases/661e3b3e7e1d7332c87d59bf/externallmg_1713417786230_externa
llmg_1713352496546_WhatsApp_Image_20240417_at_161408_1.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "6620ae3a7e1d7332c87fc037",
    "name": "Living Room",
    "path": "cases/661e3b3e7e1d7332c87d59bf/externallmg_1713417786232_externa
llmg_1713352496554_WhatsApp_Image_20240417_at_161408_2.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "6620ae4c7e1d7332c87fc089",
    "name": "Living Room",
    "path": "cases/661e3b3e7e1d7332c87d59bf/externallmg_1713417803514_externa
llmg_1713352496559_WhatsApp_Image_20240417_at_161409.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "6620ae4c7e1d7332c87fc08a",
    "name": "Living Room",
    "path": "cases/661e3b3e7e1d7332c87d59bf/externallmg_1713417803517_externa
llmg_1713352496563_WhatsApp_Image_20240417_at_161410_1.jpeg",
    "orientation": "landscape"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "14145.00",
    "max": "15571.00"
  }
},
```

```
"builtUpRateRange": {
  "min": "12859.00",
  "max": "14156.00"
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
}
```



```
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
```

```
    "isEditable": false
  }
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Approximate Rate Lead",
  "value": "APPROXIMATE_LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "1432.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"invoices": [],
"paymentIds": [],
"_id": "661e3b3e7e1d7332c87d59bf",
"ownerName": "Mr. Sushil Kumar Thakur",
"ownerPhoneNo": "9158817959",
"appAddress": "Flat no. 2204, 22nd Floor, Tower no. 12, Ashbridge CHS, Gahunje,
Pune",
"remark": "8552967995",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    }
  },
  "inputs": {
```

```
"documentDate": "05/04/2024",
"from": {
  "value": "Seller",
  "label": "Seller"
},
"Seller": "Bindu Radhakrishnan & Radhakrishnan Chakyat",
"to": {
  "value": "Purchaser",
  "label": "Purchaser"
},
"Purchaser": "Mr. Sushil Kumar Thakur & Mrs. Kiran Sushil Thakur",
"number": {
  "value": "Registration_No",
  "label": "Registration No"
},
"Registration_No": "2088/2024"
},
"isHardCopy": false,
"displayStatus": true,
"id": "406214",
"path": "cases/661e3b3e7e1d7332c87d59bf/
document_1713257136819_1713256927468_Agreement_for_SaleBelmondo.pdf",
"fileName":
"document_1713257136819_1713256927468_Agreement_for_SaleBelmondo.pdf"
},
{
  "documentType": {
    "value": "60ae1250aa6d152c1801b316",
    "label": "Part Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "28/04/2017",
    "nameOfApprovingAuthority": {
      "value": "Pune_Metropolitan_Reginal_Development_Authority",
      "label": "Pune Metropolitan Reginal Development Authority"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "DP/BMA / Mouje Gahunje / Gat No. 205 & Other / Pr. No. 7 / 16-17"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "680229",
  "path": "cases/661e3b3e7e1d7332c87d59bf/
document_1713427700101_Part_OC.pdf",
```

```
"fileName": "document_1713427700101_Part_OC.pdf"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "01/06/2016",
    "nameOfApprovingAuthority": {
      "value": "Pune_Metropolitan_Reginal_Development_Authority",
      "label": "Pune Metropolitan Reginal Development Authority"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "BMA / Case No. 7 / Mouje Gahunje / Gat No. 205 & Other / 15-16 "
},
"isHardCopy": false,
"displayStatus": true,
"id": "150379",
"path": "cases/661e3b3e7e1d7332c87d59bf/document_1713428493745_CC.pdf",
"fileName": "document_1713428493745_CC.pdf"
},
{
  "documentType": {
    "value": "60ae1249aa6d152c1801b2f3",
    "label": "Electricity Bill"
  },
  "inputs": {
    "documentDate": "21/03/2024",
    "number": {
      "value": "Consumer_No",
      "label": "Consumer No"
    }
  },
  "Consumer_No": "181643580262"
},
"isHardCopy": false,
"displayStatus": true,
"id": "411199",
"path": "cases/661e3b3e7e1d7332c87d59bf/
document_1713428745963_Electricity_Bill.pdf",
"fileName": "document_1713428745963_Electricity_Bill.pdf"
},
{
```

```
"documentType": {
  "value": "60ae126aaa6d152c1801b38b",
  "label": "Property Tax Bill"
},
"inputs": {
  "documentDate": "16/01/2024",
  "remark": "issued by Grampanchayat Gahunje",
  "to": {
    "value": "Seller",
    "label": "Seller"
  },
  "Seller": "Bindu Radhakrishnan & Radhakrishnan Chakyat",
  "number": {
    "value": "Property_No",
    "label": "Property No"
  },
  "Property_No": "0932/83"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1713428986934_Property_Tax.pdf",
"path": "cases/661e3b3e7e1d7332c87d59bf/
document_1713428986934_Property_Tax.pdf",
"id": "740205",
"uploadedBy": "60f91b6f344e052188ffd1fc",
"createdAt": "Thu Apr 18 2024 13:59:47 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "008250",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "657152",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Apr 16 2024 14:17:58 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Sushil Kumar Thakur",
    "phone": "9158817959",
    "ownershipShare": "",
    "email": "",
    "id": "697155"
  },
],
```

```
{
  "name": "Mrs. Kiran Sushil Thakur",
  "phone": "",
  "email": "",
  "ownershipShare": "",
  "id": "659659"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "572040",
    "name": "Passage",
    "length": "16.00",
    "length1": "16",
    "length2": "00",
    "width": "3.00",
    "width1": "3",
    "width2": "00",
    "totalArea": "48.00",
    "images": [],
    "extraAreas": [],
    "finalArea": "48.00"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "14",
    "name": "Passage",
    "length": "",
    "length1": "5",
    "length2": "5",
    "width": "",
    "width1": "8",
    "width2": "7",
    "totalArea": "46.49",
    "images": [],
    "finalArea": "46.49",
    "extraAreas": []
  }
]
```

```
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Kitchen",
  "length": "13.17",
  "length1": "13",
  "length2": "2",
  "width": "8.50",
  "width1": "8",
  "width2": "6",
  "totalArea": "111.92",
  "images": [],
  "extraAreas": [],
  "finalArea": "111.92"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Passage",
  "length": "4.25",
  "length1": "4",
  "length2": "3",
  "width": "5.67",
  "width1": "5",
  "width2": "8",
  "totalArea": "24.08",
  "images": [],
  "extraAreas": [],
  "finalArea": "24.08"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Store Room",
  "length": "4.50",
  "length1": "4",
```

```
"length2": "6",
"width": "4.42",
"width1": "4",
"width2": "5",
"totalArea": "19.87",
"images": [],
"extraAreas": [],
"finalArea": "19.87"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Pooja Room",
  "length": "4.50",
  "length1": "4",
  "length2": "6",
  "width": "4.42",
  "width1": "4",
  "width2": "5",
  "totalArea": "19.87",
  "images": [],
  "extraAreas": [],
  "finalArea": "19.87"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Living Room",
  "length": "15.00",
  "length1": "15",
  "length2": "00",
  "width": "21.00",
  "width1": "21",
  "width2": "00",
  "totalArea": "315.00",
  "images": [],
  "extraAreas": [
    {
      "measurementType": {
        "value": "Square_Feet",
```



```
    "label": "Square Feet"
  },
  "_id": "6620d0a07e1d7332c8800cf2",
  "name": "Living Room",
  "extraAreaType": "Add",
  "length": "3.67",
  "length1": "3",
  "length2": "8",
  "width": "8.25",
  "width1": "8",
  "width2": "3",
  "totalArea": "30.25"
}
],
"finalArea": "345.25"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "14",
  "name": "Bedroom",
  "length": "11.00",
  "length1": "11",
  "length2": "00",
  "width": "14.25",
  "width1": "14",
  "width2": "3",
  "totalArea": "156.75",
  "images": [],
  "finalArea": "156.75",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "9",
  "name": "Toilet",
  "length": "",
  "length1": "5",
  "length2": "0",
  "width": "",
  "width1": "8",
```

```
"width2": "0",
"totalArea": "40.00",
"images": [],
"finalArea": "40.00",
"extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "9",
  "name": "Passage",
  "length": "5.42",
  "length1": "5",
  "length2": "5",
  "width": "3.67",
  "width1": "3",
  "width2": "8",
  "totalArea": "19.86",
  "images": [],
  "extraAreas": [],
  "finalArea": "19.86"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "10",
  "name": "Bedroom",
  "length": "14.00",
  "length1": "14",
  "length2": "00",
  "width": "11.00",
  "width1": "11",
  "width2": "00",
  "totalArea": "154.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "154.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  }
}
```

```
},
  "id": "11",
  "name": "Toilet",
  "length": "8.08",
  "length1": "8",
  "length2": "1",
  "width": "5.00",
  "width1": "5",
  "width2": "00",
  "totalArea": "40.42",
  "images": [],
  "extraAreas": [],
  "finalArea": "40.42"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "12",
  "name": "Bedroom",
  "length": "12.00",
  "length1": "12",
  "length2": "00",
  "width": "16.00",
  "width1": "16",
  "width2": "00",
  "totalArea": "192.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "192.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "13",
  "name": "Toilet",
  "length": "5.00",
  "length1": "5",
  "length2": "00",
  "width": "11.33",
  "width1": "11",
  "width2": "4",
  "totalArea": "56.67",
```

```
"images": [],
"extraAreas": [],
"finalArea": "56.67"
}
],
"otherComposition": [
{
"toBeAdded": {
"label": "Carpet",
"value": "Carpet"
},
"name": {
"label": "Terrace Area",
"value": "Terrace_Area"
},
"measurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
"id": "0",
"length": "12.00",
"length1": "12",
"length2": "00",
"width": "6.00",
"width1": "6",
"width2": "00",
"totalArea": "72.00",
"images": [],
"extraAreas": [],
"finalArea": "72",
"percentageBeforeTotal": "72.00",
"percentage": "100"
}
],
"externalReport": [],
"documentPerArea": [
{
"typeOfDocument": {
"value": "60af48bf2ffdf65bcd6585fa",
"label": "Agreement for sale"
},
"docMeasurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
"id": "129350",
```

```
"selectAreaTypeDocument": "Carpet",
"totalAreaDocument": "1432",
"squareMeterArea": "133.04",
"docFinalBuiltUp": "1575.20",
"docFinalBuiltUpSquareMeter": "146.34",
"docBuiltupPercentage": "10",
"docSaleablePercentage": "0",
"docFinalSaleable": "0.00",
"docFinalSaleableSquareMeter": "0.00"
}
],
"images": [],
"indicatorArr": [
{
  "printlnReport": true,
  "_id": "661fb4ad7e1d7332c87f79c1",
  "property": "Flat",
  "area": "1445",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "16",
  "source": "Nobroker.com",
  "expectedPrice": "21000000",
  "expectedRate": "14532.87",
  "builtUpExpectedRate": "13211.70",
  "image": "cases/661e3b3e7e1d7332c87d59bf/
indicator_1713353602157_Image.png",
  "squareMeter": "134.25",
  "carpetArea": {
    "area": "1445.00",
    "squareMeterArea": "134.25",
    "expectedRate": "14532.87",
    "percentage": "",
    "isManual": false
  },
  "builtUpArea": {
    "area": "1589.50",
    "squareMeterArea": "147.67",
    "expectedRate": "13211.70",
    "percentage": 10,
    "isManual": false
  },
  "saleableArea": {
    "area": "0",
```

```
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": "",
    "isManual": false
  },
  "id": "208487"
},
{
  "printlnReport": true,
  "_id": "661fb4ad7e1d7332c87f79c2",
  "property": "Flat",
  "area": "1445",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "",
  "source": "square_yards",
  "expectedPrice": "22500000",
  "expectedRate": "15570.93",
  "builtUpExpectedRate": "14155.39",
  "image": "cases/661e3b3e7e1d7332c87d59bf/
indicator_1713353635352_Image.png",
  "squareMeter": "134.25",
  "carpetArea": {
    "area": "1445.00",
    "squareMeterArea": "134.25",
    "expectedRate": "15570.93",
    "percentage": "",
    "isManual": false
  },
  "builtUpArea": {
    "area": "1589.50",
    "squareMeterArea": "147.67",
    "expectedRate": "14155.39",
    "percentage": "10",
    "isManual": false
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": "",
    "isManual": false
  },
  "id": "899151"
```

```
},
{
  "printInReport": true,
  "_id": "661fb4ad7e1d7332c87f79c3",
  "property": "Flat",
  "area": "1414",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "floor": "",
  "source": "Index_no.2",
  "expectedPrice": "20000000",
  "expectedRate": "14144.27",
  "builtUpExpectedRate": "12858.43",
  "image": "cases/661e3b3e7e1d7332c87d59bf/
indicator_1713353687826_Image.png",
  "squareMeter": "131.37",
  "carpetArea": {
    "area": "1414.00",
    "squareMeterArea": "131.37",
    "expectedRate": "14144.27",
    "percentage": "",
    "isManual": false
  },
  "builtUpArea": {
    "area": "1555.40",
    "squareMeterArea": "144.50",
    "expectedRate": "12858.43",
    "percentage": "10",
    "isManual": false
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": "",
    "isManual": false
  },
  "id": "590832"
}
],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```

```
  "_id": "6620ae207e1d7332c87fbf5a",
  "name": "externalimg_1713417758933_externalimg_1713352476711_WhatsApp_I
mage_20240417_at_161416_1.jpeg",
  "path": "cases/661e3b3e7e1d7332c87d59bf/externalimg_1713417758933_external
mg_1713352476711_WhatsApp_Image_20240417_at_161416_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6620ae207e1d7332c87fbf5b",
  "name": "externalimg_1713417758937_externalimg_1713352476718_WhatsApp_I
mage_20240417_at_161416_2.jpeg",
  "path": "cases/661e3b3e7e1d7332c87d59bf/externalimg_1713417758937_external
mg_1713352476718_WhatsApp_Image_20240417_at_161416_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6620ae207e1d7332c87fbf5c",
  "name": "externalimg_1713417758939_externalimg_1713352476723_WhatsApp_I
mage_20240417_at_161416.jpeg",
  "path": "cases/661e3b3e7e1d7332c87d59bf/externalimg_1713417758939_external
mg_1713352476723_WhatsApp_Image_20240417_at_161416.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6620ae207e1d7332c87fbf5d",
  "name": "externalimg_1713417758942_externalimg_1713352476727_WhatsApp_I
mage_20240417_at_161417_1.jpeg",
  "path": "cases/661e3b3e7e1d7332c87d59bf/externalimg_1713417758942_external
mg_1713352476727_WhatsApp_Image_20240417_at_161417_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6620ae207e1d7332c87fbf5e",
  "name": "externalimg_1713417758948_externalimg_1713352476736_WhatsApp_I
mage_20240417_at_161417.jpeg",
  "path": "cases/661e3b3e7e1d7332c87d59bf/externalimg_1713417758948_external
mg_1713352476736_WhatsApp_Image_20240417_at_161417.jpeg",
  "orientation": "landscape"
}
```



```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6620ae207e1d7332c87fbf5f",
  "name": "externallmg_1713417758950_externallmg_1713352476741_WhatsApp_I
mage_20240417_at_161418.jpeg",
  "path": "cases/661e3b3e7e1d7332c87d59bf/externallmg_1713417758950_externall
mg_1713352476741_WhatsApp_Image_20240417_at_161418.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6620ae207e1d7332c87fbf60",
  "name": "externallmg_r_1713417758946_externallmg_1713352476731_WhatsApp_I
mage_20240417_at_161417_2.jpeg",
  "path": "cases/661e3b3e7e1d7332c87d59bf/externallmg_r_1713417758946_extern
allmg_1713352476731_WhatsApp_Image_20240417_at_161417_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6620ae2f7e1d7332c87fbfd2",
  "name": "externallmg_1713417774682_externallmg_1713352476745_WhatsApp_I
mage_20240417_at_161419_1.jpeg",
  "path": "cases/661e3b3e7e1d7332c87d59bf/externallmg_1713417774682_externall
mg_1713352476745_WhatsApp_Image_20240417_at_161419_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6620ae2f7e1d7332c87fbfd3",
  "name": "externallmg_1713417774686_externallmg_1713352476750_WhatsApp_I
mage_20240417_at_161419_2.jpeg",
  "path": "cases/661e3b3e7e1d7332c87d59bf/externallmg_1713417774686_externall
mg_1713352476750_WhatsApp_Image_20240417_at_161419_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6620ae2f7e1d7332c87fbfd4",
  "name": "externallmg_1713417774689_externallmg_1713352476753_WhatsApp_I
```

```
mage_20240417_at_161419.jpeg",
  "path": "cases/661e3b3e7e1d7332c87d59bf/externallmg_1713417774689_externallmg_1713352476753_WhatsApp_Image_20240417_at_161419.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6620ae2f7e1d7332c87bfd5",
  "name": "externallmg_1713417774692_externallmg_1713352496515_WhatsApp_Image_20240417_at_161419.jpeg",
  "path": "cases/661e3b3e7e1d7332c87d59bf/externallmg_1713417774692_externallmg_1713352496515_WhatsApp_Image_20240417_at_161419.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6620ae2f7e1d7332c87bfd6",
  "name": "externallmg_1713417774693_externallmg_1713352496521_WhatsApp_Image_20240417_at_161420_2.jpeg",
  "path": "cases/661e3b3e7e1d7332c87d59bf/externallmg_1713417774693_externallmg_1713352496521_WhatsApp_Image_20240417_at_161420_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6620ae2f7e1d7332c87bfd7",
  "name": "externallmg_1713417774695_externallmg_1713352496524_WhatsApp_Image_20240417_at_161420.jpeg",
  "path": "cases/661e3b3e7e1d7332c87d59bf/externallmg_1713417774695_externallmg_1713352496524_WhatsApp_Image_20240417_at_161420.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6620ae2f7e1d7332c87bfd8",
  "name": "externallmg_r_1713417774696_externallmg_1713352496530_WhatsApp_Image_20240417_at_161421.jpeg",
  "path": "cases/661e3b3e7e1d7332c87d59bf/externallmg_r_1713417774696_externallmg_1713352496530_WhatsApp_Image_20240417_at_161421.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6620ae3a7e1d7332c87fc032",
    "name": "externallmg_1713417786223_externallmg_1713352496537_WhatsApp_I
mage_20240417_at_161406.jpeg",
    "path": "cases/661e3b3e7e1d7332c87d59bf/externallmg_1713417786223_externall
mg_1713352496537_WhatsApp_Image_20240417_at_161406.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6620ae3a7e1d7332c87fc033",
    "name": "externallmg_1713417786225_externallmg_1713352496540_WhatsApp_I
mage_20240417_at_161407_1.jpeg",
    "path": "cases/661e3b3e7e1d7332c87d59bf/externallmg_1713417786225_externall
mg_1713352496540_WhatsApp_Image_20240417_at_161407_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6620ae3a7e1d7332c87fc034",
    "name": "externallmg_1713417786227_externallmg_1713352496542_WhatsApp_I
mage_20240417_at_161407_2.jpeg",
    "path": "cases/661e3b3e7e1d7332c87d59bf/externallmg_1713417786227_externall
mg_1713352496542_WhatsApp_Image_20240417_at_161407_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6620ae3a7e1d7332c87fc035",
    "name": "externallmg_1713417786229_externallmg_1713352496544_WhatsApp_I
mage_20240417_at_161407.jpeg",
    "path": "cases/661e3b3e7e1d7332c87d59bf/externallmg_1713417786229_externall
mg_1713352496544_WhatsApp_Image_20240417_at_161407.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6620ae3a7e1d7332c87fc036",
    "name": "externallmg_1713417786230_externallmg_1713352496546_WhatsApp_I
mage_20240417_at_161408_1.jpeg",
    "path": "cases/661e3b3e7e1d7332c87d59bf/externallmg_1713417786230_externall
```

```
mg_1713352496546_WhatsApp_Image_20240417_at_161408_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6620ae3a7e1d7332c87fc037",
  "name": "externallmg_1713417786232_externallmg_1713352496554_WhatsApp_I
mage_20240417_at_161408_2.jpeg",
  "path": "cases/661e3b3e7e1d7332c87d59bf/externallmg_1713417786232_externall
mg_1713352496554_WhatsApp_Image_20240417_at_161408_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6620ae3a7e1d7332c87fc038",
  "name": "externallmg_1713417786233_externallmg_1713352496557_WhatsApp_I
mage_20240417_at_161408.jpeg",
  "path": "cases/661e3b3e7e1d7332c87d59bf/externallmg_1713417786233_externall
mg_1713352496557_WhatsApp_Image_20240417_at_161408.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6620ae4c7e1d7332c87fc089",
  "name": "externallmg_1713417803514_externallmg_1713352496559_WhatsApp_I
mage_20240417_at_161409.jpeg",
  "path": "cases/661e3b3e7e1d7332c87d59bf/externallmg_1713417803514_externall
mg_1713352496559_WhatsApp_Image_20240417_at_161409.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6620ae4c7e1d7332c87fc08a",
  "name": "externallmg_1713417803517_externallmg_1713352496563_WhatsApp_I
mage_20240417_at_161410_1.jpeg",
  "path": "cases/661e3b3e7e1d7332c87d59bf/externallmg_1713417803517_externall
mg_1713352496563_WhatsApp_Image_20240417_at_161410_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "6620ae4c7e1d7332c87fc08b",
    "name": "externalimg_1713417803521_externalimg_1713352496566_WhatsApp_I
mage_20240417_at_161410_2.jpeg",
    "path": "cases/661e3b3e7e1d7332c87d59bf/externalimg_1713417803521_external
mg_1713352496566_WhatsApp_Image_20240417_at_161410_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6620ae4c7e1d7332c87fc08c",
    "name": "externalimg_1713417803525_externalimg_1713352496572_WhatsApp_I
mage_20240417_at_161410.jpeg",
    "path": "cases/661e3b3e7e1d7332c87d59bf/externalimg_1713417803525_external
mg_1713352496572_WhatsApp_Image_20240417_at_161410.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6620ae4c7e1d7332c87fc08d",
    "name": "externalimg_1713417803528_externalimg_1713352496577_WhatsApp_I
mage_20240417_at_161411_1.jpeg",
    "path": "cases/661e3b3e7e1d7332c87d59bf/externalimg_1713417803528_external
mg_1713352496577_WhatsApp_Image_20240417_at_161411_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6620ae4c7e1d7332c87fc08e",
    "name": "externalimg_1713417803531_externalimg_1713352496586_WhatsApp_I
mage_20240417_at_161412.jpeg",
    "path": "cases/661e3b3e7e1d7332c87d59bf/externalimg_1713417803531_external
mg_1713352496586_WhatsApp_Image_20240417_at_161412.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6620ae5c7e1d7332c87fc0e6",
    "name": "externalimg_1713417820280_Sale_Plan_1.jpeg",
    "path": "cases/661e3b3e7e1d7332c87d59bf/
externalimg_1713417820280_Sale_Plan_1.jpeg",
    "orientation": "landscape"
  },
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6620ae5c7e1d7332c87fc0e7",
  "name": "externalImg_1713417820282_Sale_Plan_2.jpeg",
  "path": "cases/661e3b3e7e1d7332c87d59bf/
externalImg_1713417820282_Sale_Plan_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6620ae5c7e1d7332c87fc0e8",
  "name": "externalImg_1713417820314_Sale_Plan_3.jpeg",
  "path": "cases/661e3b3e7e1d7332c87d59bf/
externalImg_1713417820314_Sale_Plan_3.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6620ae5c7e1d7332c87fc0e9",
  "name": "externalImg_1713417820317_Sale_Plan_4.jpeg",
  "path": "cases/661e3b3e7e1d7332c87d59bf/
externalImg_1713417820317_Sale_Plan_4.jpeg",
  "orientation": "landscape"
}
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "Calculation (2)- thakur.xlsx",
    "filename": "1713353925142_Calculation_2_thakur.xlsx",
    "path": "cases/661e3b3e7e1d7332c87d59bf/
processingDocuments/1713353925142_Calculation_2_thakur.xlsx",
    "size": "16101",
    "createdAt": "Wed Apr 17 2024 17:08:48 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "igr1.pdf",
    "filename": "1713353925143_igr1.pdf",
    "path": "cases/661e3b3e7e1d7332c87d59bf/
processingDocuments/1713353925143_igr1.pdf",
    "size": "195301",
    "createdAt": "Wed Apr 17 2024 17:08:48 GMT+0530 (India Standard Time)",
```

```
"uploadedBy": "5fc78e26625ecd20ec1f88e9"
},
{
  "originalname": "Summary - thakur.xlsx",
  "filename": "1713353925148_Summary__thakur.xlsx",
  "path": "cases/661e3b3e7e1d7332c87d59bf/
processingDocuments/1713353925148_Summary__thakur.xlsx",
  "size": "4096924",
  "createdAt": "Wed Apr 17 2024 17:08:48 GMT+0530 (India Standard Time)",
  "uploadedBy": "5fc78e26625ecd20ec1f88e9"
},
{
  "originalname": "visit details.xlsx",
  "filename": "1713353925202_visit_details.xlsx",
  "path": "cases/661e3b3e7e1d7332c87d59bf/
processingDocuments/1713353925202_visit_details.xlsx",
  "size": "27081",
  "createdAt": "Wed Apr 17 2024 17:08:48 GMT+0530 (India Standard Time)",
  "uploadedBy": "5fc78e26625ecd20ec1f88e9"
},
{
  "originalname": "Sale Plan (1).jpeg",
  "filename": "1713432853400_Sale_Plan_1.jpeg",
  "path": "cases/661e3b3e7e1d7332c87d59bf/
processingDocuments/1713432853400_Sale_Plan_1.jpeg",
  "size": "102888",
  "createdAt": "Thu Apr 18 2024 15:04:13 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
  "originalname": "Sale Plan (2).jpeg",
  "filename": "1713432853403_Sale_Plan_2.jpeg",
  "path": "cases/661e3b3e7e1d7332c87d59bf/
processingDocuments/1713432853403_Sale_Plan_2.jpeg",
  "size": "123162",
  "createdAt": "Thu Apr 18 2024 15:04:13 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
  "originalname": "Sale Plan (3).jpeg",
  "filename": "1713432853406_Sale_Plan_3.jpeg",
  "path": "cases/661e3b3e7e1d7332c87d59bf/
processingDocuments/1713432853406_Sale_Plan_3.jpeg",
  "size": "96225",
  "createdAt": "Thu Apr 18 2024 15:04:13 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
}
```

```
},
{
  "originalname": "Sale Plan (4).jpeg",
  "filename": "1713432853411_Sale_Plan_4.jpeg",
  "path": "cases/661e3b3e7e1d7332c87d59bf/processingDocuments/1713432853411_Sale_Plan_4.jpeg",
  "size": "118137",
  "createdAt": "Thu Apr 18 2024 15:04:13 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
  "originalname": "Site Details.xlsx",
  "filename": "1713432853414_Site_Details.xlsx",
  "path": "cases/661e3b3e7e1d7332c87d59bf/processingDocuments/1713432853414_Site_Details.xlsx",
  "size": "27081",
  "createdAt": "Thu Apr 18 2024 15:04:13 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
  "originalname": "WhatsApp Image 2024-04-18 at 12.53.27 PM.jpeg",
  "filename": "1713432853415_WhatsApp_Image_20240418_at_125327_PM.jpeg",
  "path": "cases/661e3b3e7e1d7332c87d59bf/processingDocuments/1713432853415_WhatsApp_Image_20240418_at_125327_PM.jpeg",
  "size": "86449",
  "createdAt": "Thu Apr 18 2024 15:04:13 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
  "originalname": "WhatsApp Image 2024-04-18 at 12.54.40 PM.jpeg",
  "filename": "1713432853417_WhatsApp_Image_20240418_at_125440_PM.jpeg",
  "path": "cases/661e3b3e7e1d7332c87d59bf/processingDocuments/1713432853417_WhatsApp_Image_20240418_at_125440_PM.jpeg",
  "size": "96225",
  "createdAt": "Thu Apr 18 2024 15:04:13 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
  "originalname": "CC.pdf",
  "filename": "1713432866566_CC.pdf",
  "path": "cases/661e3b3e7e1d7332c87d59bf/processingDocuments/1713432866566_CC.pdf",
  "size": "5542009",
  "createdAt": "Thu Apr 18 2024 15:04:27 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
},
}
```



```
{
  "originalname": "Electricity Bill.pdf",
  "filename": "1713432866655_Electricity_Bill.pdf",
  "path": "cases/661e3b3e7e1d7332c87d59bf/
processingDocuments/1713432866655_Electricity_Bill.pdf",
  "size": "1340183",
  "createdAt": "Thu Apr 18 2024 15:04:27 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
  "originalname": "Part OC.pdf",
  "filename": "1713432866825_Part_OC.pdf",
  "path": "cases/661e3b3e7e1d7332c87d59bf/
processingDocuments/1713432866825_Part_OC.pdf",
  "size": "7367623",
  "createdAt": "Thu Apr 18 2024 15:04:27 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
  "originalname": "Property Tax.pdf",
  "filename": "1713432866923_Property_Tax.pdf",
  "path": "cases/661e3b3e7e1d7332c87d59bf/
processingDocuments/1713432866923_Property_Tax.pdf",
  "size": "1360284",
  "createdAt": "Thu Apr 18 2024 15:04:27 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
  "originalname": "Sale Deed - 2024.pdf",
  "filename": "1713432866959_Sale_Deed__2024.pdf",
  "path": "cases/661e3b3e7e1d7332c87d59bf/
processingDocuments/1713432866959_Sale_Deed__2024.pdf",
  "size": "45934983",
  "createdAt": "Thu Apr 18 2024 15:04:27 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "5fc78e26625ecd20ec1f88e9",
      "role": "MAKER+CHECKER",
      "firstName": "Vaishali",
      "lastName": "Sarmalkar",
```

```
    "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\\
\\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg"
  },
  "workType": "RATE_VERIFY",
  "display": true,
  "status": true,
  "_id": "661f5a467e1d7332c87e40d8",
  "note": "approx. value confirmed by banker.",
  "taskId": "661e3b3e7e1d7332c87d59d6",
  "createdAt": "2024-04-17T05:12:38.719Z"
}
],
"createdAt": "2024-04-16T08:47:58.700Z",
"updatedAt": "2024-04-18T10:24:34.683Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 2204, 22nd Floor, Building No 12, Ashbridge Co-
op. Hsg. Soc. Ltd., Lodha Belmondo, Opp. M.C.A. Stadium, Off Mumbai - Pune Express
Highway, Village - Gahunje, Taluka - Maval, District - Pune, Pune, PIN - 410 506, State
- Maharashtra, India",
"updatedBy": "5fc78e26625ecd20ec1f88e9",
"addressForMap": "",
"caseReferredBy": "60b7177d2ffdf65bcd65882a",
"contactPersonName": "Mr. Radhakrushnan Chakyat",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Flat Seller",
"siteVisitContactNo": "9028770960",
"buildingServicesRate": "2500",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 1432.00",
"flatRate": "14700",
"landOtherRate": "12200",
"shopDetails": {
  "typeOfShops": null,
```

```

    "roadFacing": false,
    "mall": false
  },
  "finalSaleablePercentage": "0",
  "builtupPercentage": "10",
  "carpetTotal": "1275.18",
  "extendOfSiteRemark": "RERA Carpet Area in Sq. Ft. = 1,186.00\nEBVT Area in Sq.
Ft. = 246.00",
  "finalBuiltupArea": "1481.90",
  "finalCarpetArea": "1347.18",
  "finalSalableArea": "1481.90",
  "otherCarpetTotal": "72.00",
  "salablePercentage": "0",
  "siteMeasurementRemark": "Carpet Area in Sq. Ft. = 1,275.18\nTerrace Ara in Sq. Ft.
= 72.00 \n<br />",
  "toBeAdded": "",
  "briefDescOfProperty": "3 Bedroom + Living Room + Kitchen + 4 Passage + Store
Room + Pooja Room + 3 Toilet",
  "otherCompositionBuiltUpTotal": "0.00",
  "otherCompositionCarpetTotal": "72.00",
  "otherCompositionSaleableTotal": "0.00",
  "landDetails": {
    "holdType": {
      "label": "Free Hold",
      "value": "Free_Hold"
    },
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"reportGeneratedDate": "Thu Apr 18 2024 14:49:49 GMT+0530 (India Standard
Time)",
"siteVisitDate": "2024-04-17"
}

```

Name	Length	Width	Total
Composition :			

Passage	16'00"	3'00"	48.00
Passage	5'5"	8'7"	46.49
Kitchen	13'2"	8'6"	111.92
Passage	4'3"	5'8"	24.08
Store Room	4'6"	4'5"	19.87
Pooja Room	4'6"	4'5"	19.87
Living Room	15'00"	21'00"	315.00
Bedroom	11'00"	14'3"	156.75
Toilet	5'0"	8'0"	40.00
Passage	5'5"	3'8"	19.86
Bedroom	14'00"	11'00"	154.00
Toilet	8'1"	5'00"	40.42
Bedroom	12'00"	16'00"	192.00
Toilet	5'00"	11'4"	56.67
Other Composition :			
Terrace Area	12'00"	6'00"	72.00