

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "63b26511191f7b344b008a1d"
    },
    "type": "CREDITOFFICER",
    "_id": "63d11f66be948726cc141b8b",
    "email": "coorddesk.rasmechby@sbi.co.in",
    "firstName": "SHASHI RANJAN",
    "mobileNo": "",
    "workMobileNo": "9867369914",
    "lastName": "RANJAN"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "5000000",
    "discussWithPerson": "SHASHI RANJAN",
    "expectedFees": 2500,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "63b26511191f7b344b008a1d",
  "name": "RASMECCC BHAYANDAR",
  "branchCode": "",
  "mobileNo": "022-28149108",
  "alternateMobileNo": "",
  "email": "Coorddesk.rasmecbhy@sbi.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "RASMECCC Bhayandar Branch\nUnit No. 101, 102, 103B, 1st Floor, IT
Landmark Building, 150ft. Road, Near Hotel Shree Nidhi, \nOpp. Maxus Mall,
Bhayander (West), Thane – 401 101, \nState – Maharashtra, Country – India."
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "659ccce98f39506e83489828",
  "role": "DELIVERYPERSON",
  "firstName": "Amit",
  "email": "amitsalvi2909@gmail.com",
  "lastName": "Salvi",
  "mobileNo": "7499830659",
  "shortName": "Amit",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/659ccce98f39506e83489828/
profilePhoto_1712385426269_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "64c777a8a5c3051014f4dd1f",
  "role": "SITEENGINEER",
  "firstName": "Pratik",
  "email": "pratikjain2277@gmail.com",
  "lastName": "Jain",
  "mobileNo": "9619286285",
  "designation": "",
  "shortName": "Pratik",
  "workWithDocumentMaker": "6006d4ce5080a310ac1fdfc2"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "64cde526dc9f3034f3fefa49",
  "role": "FRONTDESK",
  "firstName": "Rashmi",
  "email": "rashmijadhav14feb@gmail.com",
  "lastName": "Jadhav",
  "mobileNo": "7738144625",
  "designation": "Back Office Coordination",
  "shortName": "RJ",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60f91b6f344e052188ffd1fc",
  "role": "MAKER",
  "firstName": "Jayaraja",
  "email": "jayaraja@vastukala.org",
  "lastName": "Acharya",
  "mobileNo": "9867664219",
```

```
"designation": "",
"shortName": "JA",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91b6f344e052188ffd1fc/
profilePhoto_1678780588416_Profile_Photo.jpeg"
},
"checker": {
"type": "EMPLOYEE",
"_id": "64cde526dc9f3034f3fefa49",
"role": "FRONTDESK",
"firstName": "Rashmi",
"email": "rashmijadhav14feb@gmail.com",
"lastName": "Jadhav",
"mobileNo": "7738144625",
"designation": "Back Office Coordination",
"shortName": "RJ",
"workWithDocumentMaker": "60eeaeddf3dd69653a581316",
"profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
}
],
{
"title": {
```

```
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.27663315629619",
  "longitude": "72.87223886639941"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.87223886639941,
    19.27663315629619
  ]
}
```

```
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "17/04/2024 08:52 am"
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-04-18",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": false,
    "name": "Village",
```

```
"key": "village",
"value": "",
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "2",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Thane",
  "label": true
},
}
```

```
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Gaurav Residency C Wing Co-op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Near Mayor Bungalow",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Next To Marigold, Beverly Park",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
```



```
"value": "C",
"label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Gaurav Residency Phase - 1",
  "label": false
},
"oldSurveyNumber": {
  "status": true,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "443",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "127, Hissa No. 1/P",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
```

```
"status": true,
"name": "Flat / Unit / Office / Gala No.",
"key": "selectNo",
"value": "202",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
```

```
"label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 401 107",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Mira Road (East)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "R.C.C._slab",
    "label": "R.C.C. slab"
  },
  "flooring": {
    "value": "Vitrified_tiles_flooring",
    "label": "Vitrified tiles flooring"
  },
  "doors": {
    "value": "Teak_wood_door_frame_with_flush_shutters",
    "label": "Teak wood door frame with flush shutters"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows",
    "label": "Powder coated Aluminum sliding windows"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering_+_POP_Finish",
    "label": "Cement Plastering + POP Finish"
  }
}
},
"general": {
  "ownership": {
```

```
"value": "Joint_Ownership",
"label": "Joint Ownership"
},
"populationClassList": {
  "value": "MiddleClass",
  "label": "Middle Class"
},
"populationGroupList": {
  "value": "Semi_Urban",
  "label": "Semi Urban"
},
"townplanApprovedByList": {
  "value": "Mira_Bhayander_Municipal_Corporation",
  "label": "Mira Bhayander Municipal Corporation"
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Open Land",
  "west": "N. G. Diamond Hill",
  "south": "Marigold Road",
  "east": "Evershine Woods Road"
},
"asPerDocumentAgreement": {
  "north": "Information not available",
  "west": "Information not available",
  "south": "Information not available",
  "east": "Information not available"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "asPerDocument": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
```

```
    },
    "extraDetailOfProperty": "",
    "dateOfIssusApprovePlan": "As Part Occupancy Certificate is received it may be assumed that the construction is as per Sanctioned Plan.",
    "approvePlanVerified": "N.A.",
    "empanelledOfApprovePlan": "No",
    "unauthorizedConstruction": ""
  },
  "compositeRate": {
    "remark": "",
    "depreciationPercentage": "27",
    "depreciationRatioOfBuilding": "",
    "salvageValue": "10",
    "buildingServicesDepreciatedRate": "675",
    "depreciatedCostOfConstruction": "14325.00",
    "depreciatedBuildingRate": "1825"
  },
  "igrRate": {
    "propertyName": " Residential Flat",
    "rate": "98300",
    "landRate": "29950",
    "igrImage": "cases/661e70be7e1d7332c87e01e9/igr_1713519027993_Image.png",
    "squareMeterGuideLineRate": "98300.00",
    "squareFeetGuideLineRate": "9132.00"
  },
  "igrFinalRate": {
    "floorRatePercentage": "0",
    "depreciationPercentage": "82",
    "rate": "7989.00",
    "squareFeetGuideLineRate": "7989.00",
    "squareMeterGuideLineRate": "85997.00"
  },
  "outgoingDetail": {
    "areaStatusList": {
      "value": "Medium",
      "label": "Medium"
    },
    "propertyTypeOfUseList": {
      "value": "Residential_Purpose",
      "label": "Residential Purpose"
    },
    "propertyOccupiedByList": {
      "value": "Vacant",
      "label": "Vacant"
    }
  },
  "monthlyRent": "N.A",
```

```
"assessmentNo": "Information not available",
"taxPaidHolderName": "Information not available",
"taxAmount": "Information not available",
"electricityServiceConnectionNo": "CA No. 152677554",
"meterCardHolderName": "Smita S. Acharya & Satish G. Acharya",
"undividedAreaOfLandAsPerSaleDeed": "Information not available",
"floorSpaceIndex": "As per MBMC norms",
"tenantName": "",
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "R.C.C._slab",
    "label": "R.C.C. slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Open car Parking Space",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
```

```
"month": "1",
"year": "2006",
"fullDate": "1/1/2006"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
```

```
"label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "0",
  "label": "No"
},
"provisionOfFirefighting": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "As_Per_Part_Occupancy_Certificate",
  "label": "As Per Part Occupancy Certificate"
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "18",
"totalLifeBuilding": "60",
"estimatedAge": "42",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "7",
"flatFloorNo": "2",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
  "area": "463.20",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
```



```
"areaAsPer": "Carpet Area + 20%"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/661e70be7e1d7332c87e01e9/
routeMap_1713509174720_Image.png",
    "routeLat": "19.289572",
    "routeLng": "72.876850",
    "stationName": "Mira Road",
    "routeDistance": "2.8 km."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "5v0uje",
      "name": "5v0uje",
      "image": "cases/661e70be7e1d7332c87e01e9/
routeMap_1713509003563_Image.png"
    }
  ],
  "valuation": {
    "wardrobesRate": "0",
    "totalwardrobesRate": "0",
    "wardrobesQty": "0",
    "showcasesQty": "0",
    "showcasesRate": "0",
    "totalshowcasesRate": "0",
    "kitchenArrangementsQty": "0",
    "kitchenArrangementsRate": "0",
    "totalkitchenArrangementsRate": "0",
    "superfineFinishQty": "0",
```

```
"superfineFinishRate": "0",
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "5529450.00",
"finalValue": "5529450.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValueDocument": null,
"purchaseValueDocument": null,
"bookValue": "0"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Fri Apr 19 2024 15:22:01 GMT+0530 (India Standard Time)",
  "number": "2306014",
  "dayCount": "9",
  "monthCount": "153",
  "generatedBy": "64cde526dc9f3034f3fefa49"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
```

```
"label": "RCC Plinth",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"fullBuildingRcc": {
"label": "Full Building Rcc",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
"label": "Internal Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
"label": "External Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
"label": "Internal Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "3700505.00",
  "selectedBuildUpValue": "463.20",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "6621e3f57e1d7332c880ebe7",
      "name":
"externallmg_1713497077279_IMG_20240418_181132_copy_1200x1600.jpg",
      "path": "cases/661e70be7e1d7332c87e01e9/
externallmg_1713497077279_IMG_20240418_181132_copy_1200x1600.jpg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "6621e3e77e1d7332c880eb93",
      "name":
"externallmg_1713497062178_IMG_20240418_181123_copy_1200x1597.jpg",
      "path": "cases/661e70be7e1d7332c87e01e9/
externallmg_1713497062178_IMG_20240418_181123_copy_1200x1597.jpg",
      "orientation": "portrait"
    }
  ]
}
```

```
}
],
"externalPhotos": [
  {
    "status": false,
    "_id": "6621e3f57e1d7332c880ebe6",
    "name":
"externallmg_1713497077271_IMG_20240418_181128_copy_1200x1600.jpg",
    "path": "cases/661e70be7e1d7332c87e01e9/
externallmg_1713497077271_IMG_20240418_181128_copy_1200x1600.jpg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [
  {
    "status": false,
    "_id": "6621e3f57e1d7332c880ebe4",
    "name":
"externallmg_1713497077252_IMG_20240418_181053_copy_1200x1600.jpg",
    "path": "cases/661e70be7e1d7332c87e01e9/
externallmg_1713497077252_IMG_20240418_181053_copy_1200x1600.jpg",
    "orientation": "portrait"
  }
],
"compositionImages": [
  {
    "status": false,
    "_id": "6621e3e77e1d7332c880eb8e",
    "name": "Living Room",
    "path": "cases/661e70be7e1d7332c87e01e9/
externallmg_1713497062106_IMG_20240418_180537_copy_1200x900.jpg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "6621e3e77e1d7332c880eb8f",
    "name": "Living Room",
    "path": "cases/661e70be7e1d7332c87e01e9/
externallmg_1713497062119_IMG_20240418_180550_copy_1200x900.jpg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "6621e3e77e1d7332c880eb90",
    "name": "Living Room",
```

```
    "path": "cases/661e70be7e1d7332c87e01e9/
externallmg_1713497062134_IMG_20240418_180604_copy_1200x900.jpg",
    "orientation": "landscape"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "13910.00",
    "max": "15750.00"
  },
  "builtUpRateRange": {
    "min": "11597.00",
    "max": "13125.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
```



```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "386.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"invoices": [],
"paymentIds": [],
"_id": "661e70be7e1d7332c87e01e9",
"ownerName": "Mr. Nitin Rameshchandra Mishra",
```

```
"ownerPhoneNo": "8080089920",
"appAddress": "FLAT NO 202 C WING 2ND FLOOR GAURAV RESIDENCY C WING
CHS LTD GAURAV RESIDENCY PHASE 1 NEXT TO MARY GOLD BEVERLY PARK
MIRA ROAD THANE 401107",
"remark": "ANY QUERY CALL UMASHANKAR 9172908970",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "08/04/2024",
      "from": {
        "value": "Transferor",
        "label": "Transferor"
      },
      "Transferor": "Mrs. Smita Satish Acharya & Mr. Satish G. Acharya",
      "to": {
        "value": "Transferee",
        "label": "Transferee"
      },
      "Transferee": "Mr. Nitin Rameshchandra Mishra & Mr. Rameshchandra S. Mishra",
      "number": {
        "value": "Registration_No",
        "label": "Registration No"
      },
      "Registration_No": "6350/2024"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "181450",
    "path": "cases/661e70be7e1d7332c87e01e9/
document_1713270942551_1713270723008_NITIN_MISHRA__AGREEMENT.pdf",
    "fileName":
"document_1713270942551_1713270723008_NITIN_MISHRA__AGREEMENT.pdf"
  },
  {
    "documentType": {
      "value": "60ae1250aa6d152c1801b316",
      "label": "Part Occupancy Certificate"
    },
    "inputs": {
      "documentDate": "29/05/2006",
      "nameOfApprovingAuthority": {
        "value": "Mira_Bhayander_Municipal_Corporation",
```

```
"label": "Mira Bhayander Municipal Corporation"
},
"number": {
  "value": "No",
  "label": "No"
},
"No": "MNP / NR / 577 / 2006-07"
},
"isHardCopy": false,
"displayStatus": false,
"id": "243651",
"path": "cases/661e70be7e1d7332c87e01e9/document_1713511514617_OC.pdf",
"fileName": "document_1713511514617_OC.pdf"
},
{
  "documentType": {
    "value": "60ae1264aa6d152c1801b371",
    "label": "Share Certificate "
  },
  "inputs": {
    "remark": "bearing Nos. 71 to 80 having 10 Shares of Rs. 50/- each transferred
dated 30.11.2017 in the name of Mrs. Smita Satish Acharya & Mr. Satish G. Acharya by
Gaurav Residency 'C' Wing Co-op. Hsg. Soc. Ltd.",
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "08"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1713511706738_Share_Certificate.pdf",
  "path": "cases/661e70be7e1d7332c87e01e9/
document_1713511706738_Share_Certificate.pdf",
  "id": "883251",
  "uploadedBy": "60f91b6f344e052188ffd1fc",
  "createdAt": "Fri Apr 19 2024 12:58:26 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1249aa6d152c1801b2f1",
    "label": "Society Maintenance Bill"
  },
  "inputs": {
    "documentDate": "29/02/2024",
    "remark": "in the name of Mrs. Smita Satish Acharya issued by Gaurav Residency
```

```
'C' Wing Co-op. Hsg. Soc. Ltd.",
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "378"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1713511826963_Maintenance_Bill.pdf",
"path": "cases/661e70be7e1d7332c87e01e9/
document_1713511826963_Maintenance_Bill.pdf",
"id": "805145",
"uploadedBy": "60f91b6f344e052188ffd1fc",
"createdAt": "Fri Apr 19 2024 13:00:28 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "6077c791395bc80714864a30",
    "label": "Electricity Bill"
  },
  "inputs": {
    "documentDate": "13/03/2024",
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "101684919568"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1713511948880_Electricity_Bill.pdf",
  "path": "cases/661e70be7e1d7332c87e01e9/
document_1713511948880_Electricity_Bill.pdf",
  "id": "407032",
  "uploadedBy": "60f91b6f344e052188ffd1fc",
  "createdAt": "Fri Apr 19 2024 13:02:29 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "008261",
"createdBy": "659ccce98f39506e83489828",
"caseHistory": [
  {
    "id": "926689",
    "title": "Create Lead",
    "description": "Create Lead",
```

```
"datetime": "Tue Apr 16 2024 18:06:14 GMT+0530 (India Standard Time)"
}
],
"owners": [
  {
    "name": "Mr. Nitin Rameshchandra Mishra",
    "phone": "8080089920",
    "ownershipShare": "",
    "email": "",
    "id": "970641"
  },
  {
    "name": "Mr. Rameshchandra S. Mishra",
    "phone": "",
    "email": "",
    "ownershipShare": "",
    "id": "311296"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "783355",
    "name": "Living Room",
    "length": "17.42",
    "length1": "17",
    "length2": "5",
    "width": "8.67",
    "width1": "8",
    "width2": "8",
    "totalArea": "150.94",
    "images": [],
    "extraAreas": [],
    "finalArea": "150.94"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "1",
```

```
"name": "Cupboard",
"length": "1.33",
"length1": "1",
"length2": "4",
"width": "4.42",
"width1": "4",
"width2": "5",
"totalArea": "5.89",
"images": [],
"extraAreas": [],
"finalArea": "5.89"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Passage",
  "length": "8.42",
  "length1": "8",
  "length2": "5",
  "width": "2.67",
  "width1": "2",
  "width2": "8",
  "totalArea": "22.44",
  "images": [],
  "extraAreas": [],
  "finalArea": "22.44"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Toilet",
  "length": "5.92",
  "length1": "5",
  "length2": "11",
  "width": "3.92",
  "width1": "3",
  "width2": "11",
  "totalArea": "23.17",
  "images": [],
  "extraAreas": [],
```

```
"finalArea": "23.17"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "WC",
  "length": "",
  "length1": "4",
  "length2": "0",
  "width": "",
  "width1": "3",
  "width2": "0",
  "totalArea": "12.00",
  "images": [],
  "finalArea": "12.00",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Kitchen",
  "length": "8.42",
  "length1": "8",
  "length2": "5",
  "width": "7.50",
  "width1": "7",
  "width2": "6",
  "totalArea": "63.12",
  "images": [],
  "extraAreas": [],
  "finalArea": "63.12"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Bedroom",
  "length": "13.42",
```

```
"length1": "13",
"length2": "5",
"width": "8.58",
"width1": "8",
"width2": "7",
"totalArea": "115.16",
"images": [],
"extraAreas": [],
"finalArea": "115.16"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
{
  "typeOfDocument": {
    "value": "60af48bf2ffdf65bcd6585fa",
    "label": "Agreement for sale"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "274069",
  "selectAreaTypeDocument": "Carpet",
  "totalAreaDocument": "386",
  "squareMeterArea": "35.86",
  "docFinalBuiltUp": "463.2",
  "docFinalBuiltUpSquareMeter": "43.032",
  "docBuiltupPercentage": "20",
  "docSaleablePercentage": "0",
  "docFinalSaleable": "0",
  "docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
{
  "printlnReport": true,
  "_id": "662239d17e1d7332c881ce38",
  "property": "Residential Flat",
  "area": "400",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
```



```
"floor": "",
"source": "magic_bricks",
"expectedPrice": "6300000",
"expectedRate": "15750.00",
"builtUpExpectedRate": "13125.00",
"image": "cases/661e70be7e1d7332c87e01e9/
indicator_1713518738459_Image.png",
"squareMeter": "37.16",
"carpetArea": {
  "area": "400.00",
  "squareMeterArea": "37.16",
  "expectedRate": "15750.00",
  "percentage": "",
  "isManual": false
},
"builtUpArea": {
  "area": "480.00",
  "squareMeterArea": "44.59",
  "expectedRate": "13125.00",
  "percentage": "20",
  "isManual": false
},
"saleableArea": {
  "area": "",
  "squareMeterArea": "0.00",
  "expectedRate": "0.00",
  "percentage": "",
  "isManual": false
},
"id": "581109"
},
{
  "printlnReport": true,
  "_id": "662239d17e1d7332c881ce39",
  "property": "Residential Flat",
  "area": "400",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "",
  "source": "https://www.99acres.com/",
  "expectedPrice": "6300000",
  "expectedRate": "15750.00",
  "builtUpExpectedRate": "13125.00",
  "image": "cases/661e70be7e1d7332c87e01e9/
indicator_1713518765982_Image.png",
```

```
"squareMeter": "37.16",
"carpetArea": {
  "area": "400.00",
  "squareMeterArea": "37.16",
  "expectedRate": "15750.00",
  "percentage": "",
  "isManual": false
},
"builtUpArea": {
  "area": "480.00",
  "squareMeterArea": "44.59",
  "expectedRate": "13125.00",
  "percentage": "20",
  "isManual": false
},
"saleableArea": {
  "area": "",
  "squareMeterArea": "0.00",
  "expectedRate": "0.00",
  "percentage": "",
  "isManual": false
},
"id": "958082"
},
{
  "printlnReport": true,
  "_id": "662239d17e1d7332c881ce3a",
  "property": " Residential Flat",
  "area": "451",
  "builtUpPercentage": "0",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Built_Up",
  "floor": "",
  "source": "Index_no.2",
  "expectedPrice": "5230000",
  "expectedRate": "13909.57",
  "builtUpExpectedRate": "5230000",
  "image": "cases/661e70be7e1d7332c87e01e9/
indicator_1713518826832_Image.png",
  "squareMeter": "41.90",
  "carpetArea": {
    "area": "376",
    "squareMeterArea": "34.93",
    "expectedRate": "13909.57",
    "percentage": "",
```

```
    "isManual": false
  },
  "builtUpArea": {
    "area": "451.00",
    "squareMeterArea": "41.90",
    "expectedRate": "11596.45",
    "percentage": "",
    "isManual": false
  },
  "saleableArea": {
    "area": "0.00",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": "",
    "isManual": false
  },
  "id": "332582"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6621e3e77e1d7332c880eb8c",
    "name":
"externalImg_1713497062071_IMG_20240418_180527_copy_1200x900.jpg",
    "path": "cases/661e70be7e1d7332c87e01e9/
externalImg_1713497062071_IMG_20240418_180527_copy_1200x900.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6621e3e77e1d7332c880eb8d",
    "name":
"externalImg_1713497062092_IMG_20240418_180534_copy_1200x900.jpg",
    "path": "cases/661e70be7e1d7332c87e01e9/
externalImg_1713497062092_IMG_20240418_180534_copy_1200x900.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6621e3e77e1d7332c880eb8e",
    "name":
"externalImg_1713497062106_IMG_20240418_180537_copy_1200x900.jpg",
```

```
    "path": "cases/661e70be7e1d7332c87e01e9/
externallmg_1713497062106_IMG_20240418_180537_copy_1200x900.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6621e3e77e1d7332c880eb8f",
    "name":
"externallmg_1713497062119_IMG_20240418_180550_copy_1200x900.jpg",
    "path": "cases/661e70be7e1d7332c87e01e9/
externallmg_1713497062119_IMG_20240418_180550_copy_1200x900.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6621e3e77e1d7332c880eb90",
    "name":
"externallmg_1713497062134_IMG_20240418_180604_copy_1200x900.jpg",
    "path": "cases/661e70be7e1d7332c87e01e9/
externallmg_1713497062134_IMG_20240418_180604_copy_1200x900.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6621e3e77e1d7332c880eb91",
    "name":
"externallmg_1713497062149_IMG_20240418_180611_copy_1200x900.jpg",
    "path": "cases/661e70be7e1d7332c87e01e9/
externallmg_1713497062149_IMG_20240418_180611_copy_1200x900.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6621e3e77e1d7332c880eb92",
    "name":
"externallmg_1713497062158_IMG_20240418_181105_copy_1200x900.jpg",
    "path": "cases/661e70be7e1d7332c87e01e9/
externallmg_1713497062158_IMG_20240418_181105_copy_1200x900.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "6621e3e77e1d7332c880eb93",
    "name":
"externallmg_1713497062178_IMG_20240418_181123_copy_1200x1597.jpg",
    "path": "cases/661e70be7e1d7332c87e01e9/
externallmg_1713497062178_IMG_20240418_181123_copy_1200x1597.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6621e3e77e1d7332c880eb94",
    "name":
"externallmg_1713497062214_IMG_20240418_181129_copy_1200x1600.jpg",
    "path": "cases/661e70be7e1d7332c87e01e9/
externallmg_1713497062214_IMG_20240418_181129_copy_1200x1600.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6621e3e77e1d7332c880eb95",
    "name": "externallmg_r_1713497061936_20240418_061149PM___map.jpg",
    "path": "cases/661e70be7e1d7332c87e01e9/
externallmg_r_1713497061936_20240418_061149PM___map.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6621e3f57e1d7332c880ebd5",
    "name":
"externallmg_1713497077114_IMG_20240418_181401_copy_1200x1600.jpg",
    "path": "cases/661e70be7e1d7332c87e01e9/
externallmg_1713497077114_IMG_20240418_181401_copy_1200x1600.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6621e3f57e1d7332c880ebd6",
    "name":
"externallmg_1713497077126_IMG_20240418_181456_copy_1200x1600.jpg",
    "path": "cases/661e70be7e1d7332c87e01e9/
externallmg_1713497077126_IMG_20240418_181456_copy_1200x1600.jpg",
    "orientation": "portrait"
  }
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6621e3f57e1d7332c880ebd7",
  "name":
"externallmg_1713497077140_IMG_20240418_181457_copy_1200x1600.jpg",
  "path": "cases/661e70be7e1d7332c87e01e9/
externallmg_1713497077140_IMG_20240418_181457_copy_1200x1600.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6621e3f57e1d7332c880ebd8",
  "name":
"externallmg_1713497077153_IMG_20240418_205105_copy_1200x1600.jpg",
  "path": "cases/661e70be7e1d7332c87e01e9/
externallmg_1713497077153_IMG_20240418_205105_copy_1200x1600.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6621e3f57e1d7332c880ebd9",
  "name":
"externallmg_1713497077159_IMG_20240418_180517_copy_1200x900.jpg",
  "path": "cases/661e70be7e1d7332c87e01e9/
externallmg_1713497077159_IMG_20240418_180517_copy_1200x900.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6621e3f57e1d7332c880ebda",
  "name":
"externallmg_1713497077171_IMG_20240418_180522_copy_1200x900.jpg",
  "path": "cases/661e70be7e1d7332c87e01e9/
externallmg_1713497077171_IMG_20240418_180522_copy_1200x900.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6621e3f57e1d7332c880ebdb",
  "name":
"externallmg_1713497077186_IMG_20240418_180546_copy_1200x900.jpg",
```

```
    "path": "cases/661e70be7e1d7332c87e01e9/
externallmg_1713497077186_IMG_20240418_180546_copy_1200x900.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6621e3f57e1d7332c880ebdc",
    "name":
"externallmg_1713497077197_IMG_20240418_180548_copy_1200x900.jpg",
    "path": "cases/661e70be7e1d7332c87e01e9/
externallmg_1713497077197_IMG_20240418_180548_copy_1200x900.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6621e3f57e1d7332c880ebdd",
    "name":
"externallmg_1713497077209_IMG_20240418_180553_copy_1200x1600.jpg",
    "path": "cases/661e70be7e1d7332c87e01e9/
externallmg_1713497077209_IMG_20240418_180553_copy_1200x1600.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6621e3f57e1d7332c880ebde",
    "name":
"externallmg_1713497077215_IMG_20240418_180558_copy_1200x1600.jpg",
    "path": "cases/661e70be7e1d7332c87e01e9/
externallmg_1713497077215_IMG_20240418_180558_copy_1200x1600.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6621e3f57e1d7332c880ebdf",
    "name":
"externallmg_1713497077220_IMG_20240418_180602_copy_1200x900.jpg",
    "path": "cases/661e70be7e1d7332c87e01e9/
externallmg_1713497077220_IMG_20240418_180602_copy_1200x900.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "6621e3f57e1d7332c880ebe0",
    "name":
"externallmg_1713497077230_IMG_20240418_180610_copy_1200x900.jpg",
    "path": "cases/661e70be7e1d7332c87e01e9/
externallmg_1713497077230_IMG_20240418_180610_copy_1200x900.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6621e3f57e1d7332c880ebe1",
    "name":
"externallmg_1713497077239_IMG_20240418_181000_copy_1200x1600.jpg",
    "path": "cases/661e70be7e1d7332c87e01e9/
externallmg_1713497077239_IMG_20240418_181000_copy_1200x1600.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6621e3f57e1d7332c880ebe2",
    "name":
"externallmg_1713497077243_IMG_20240418_181002_copy_1200x1600.jpg",
    "path": "cases/661e70be7e1d7332c87e01e9/
externallmg_1713497077243_IMG_20240418_181002_copy_1200x1600.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6621e3f57e1d7332c880ebe3",
    "name":
"externallmg_1713497077247_IMG_20240418_181028_copy_1200x1600.jpg",
    "path": "cases/661e70be7e1d7332c87e01e9/
externallmg_1713497077247_IMG_20240418_181028_copy_1200x1600.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6621e3f57e1d7332c880ebe4",
    "name":
"externallmg_1713497077252_IMG_20240418_181053_copy_1200x1600.jpg",
    "path": "cases/661e70be7e1d7332c87e01e9/
externallmg_1713497077252_IMG_20240418_181053_copy_1200x1600.jpg",
```



```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6621e3f57e1d7332c880ebe5",
    "name":
"externallmg_1713497077258_IMG_20240418_181108_copy_1200x900.jpg",
    "path": "cases/661e70be7e1d7332c87e01e9/
externallmg_1713497077258_IMG_20240418_181108_copy_1200x900.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6621e3f57e1d7332c880ebe6",
    "name":
"externallmg_1713497077271_IMG_20240418_181128_copy_1200x1600.jpg",
    "path": "cases/661e70be7e1d7332c87e01e9/
externallmg_1713497077271_IMG_20240418_181128_copy_1200x1600.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6621e3f57e1d7332c880ebe7",
    "name":
"externallmg_1713497077279_IMG_20240418_181132_copy_1200x1600.jpg",
    "path": "cases/661e70be7e1d7332c87e01e9/
externallmg_1713497077279_IMG_20240418_181132_copy_1200x1600.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6621e3f57e1d7332c880ebe8",
    "name":
"externallmg_1713497077287_IMG_20240418_205059_copy_1200x1600.jpg",
    "path": "cases/661e70be7e1d7332c87e01e9/
externallmg_1713497077287_IMG_20240418_205059_copy_1200x1600.jpg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
```

```
    "originalname": "Electricity Bill.pdf",
    "filename": "1713512064601_Electricity_Bill.pdf",
    "path": "cases/661e70be7e1d7332c87e01e9/
processingDocuments/1713512064601_Electricity_Bill.pdf",
    "size": "120611",
    "createdAt": "Fri Apr 19 2024 13:04:24 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
  {
    "originalname": "Maintenance Bill.pdf",
    "filename": "1713512064606_Maintenance_Bill.pdf",
    "path": "cases/661e70be7e1d7332c87e01e9/
processingDocuments/1713512064606_Maintenance_Bill.pdf",
    "size": "170719",
    "createdAt": "Fri Apr 19 2024 13:04:24 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
  {
    "originalname": "OC.pdf",
    "filename": "1713512064612_OC.pdf",
    "path": "cases/661e70be7e1d7332c87e01e9/
processingDocuments/1713512064612_OC.pdf",
    "size": "75194",
    "createdAt": "Fri Apr 19 2024 13:04:24 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
  {
    "originalname": "Sale Deed - 2024.pdf",
    "filename": "1713512064614_Sale_Deed__2024.pdf",
    "path": "cases/661e70be7e1d7332c87e01e9/
processingDocuments/1713512064614_Sale_Deed__2024.pdf",
    "size": "2627257",
    "createdAt": "Fri Apr 19 2024 13:04:24 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
  {
    "originalname": "Share Certificate.pdf",
    "filename": "1713512064660_Share_Certificate.pdf",
    "path": "cases/661e70be7e1d7332c87e01e9/
processingDocuments/1713512064660_Share_Certificate.pdf",
    "size": "675196",
    "createdAt": "Fri Apr 19 2024 13:04:24 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
  {
    "originalname": "Site Detaiols.jpg",
```

```
    "filename": "1713512064670_Site_Details.jpg",
    "path": "cases/661e70be7e1d7332c87e01e9/
processingDocuments/1713512064670_Site_Details.jpg",
    "size": "440801",
    "createdAt": "Fri Apr 19 2024 13:04:24 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
  {
    "originalname": "Sketch & Diamention.jpg",
    "filename": "1713512064677_Sketch__Diamention.jpg",
    "path": "cases/661e70be7e1d7332c87e01e9/
processingDocuments/1713512064677_Sketch__Diamention.jpg",
    "size": "298415",
    "createdAt": "Fri Apr 19 2024 13:04:24 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
  {
    "originalname": "Calculation Sheet NEW.xlsx",
    "filename": "1713519055317_Calculation_Sheet_NEW.xlsx",
    "path": "cases/661e70be7e1d7332c87e01e9/
processingDocuments/1713519055317_Calculation_Sheet_NEW.xlsx",
    "size": "3244110",
    "createdAt": "Fri Apr 19 2024 15:00:55 GMT+0530 (India Standard Time)",
    "uploadedBy": "64cde526dc9f3034f3fefa49"
  }
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-04-16T12:36:14.418Z",
"updatedAt": "2024-04-19T10:30:29.746Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 202, 2nd Floor, Wing - C, Gaurav Residency C
Wing Co-op. Hsg. Soc. Ltd., Gaurav Residency Phase - 1, Near Mayor Bungalow, Next
To Marigold, Beverly Park, Mira Road (East), Taluka - Thane, District - Thane, PIN -
401 107, State - Maharashtra, India",
"updatedBy": "64cde526dc9f3034f3fefa49",
"addressForMap": "",
"caseReferredBy": "659ccce98f39506e83489828",
"contactPersonName": "Mr. Nitin Rameshchandra Mishra",
"email": "",
"isExternal": "false",
```

```
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Owner",
"siteVisitContactNo": "8080089920",
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + Cupboard + Passage +
Toilet + WC",
"carpetTotal": "392.72",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "0.00",
"builtupPercentage": "20",
"finalBuiltupArea": "471.26",
"finalCarpetArea": "392.72",
"finalSalableArea": "471.26",
"salablePercentage": "0",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalSaleablePercentage": "0",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 386.00",
"reportGeneratedDate": "Fri Apr 19 2024 11:56:08 GMT+0530 (India Standard Time)",
"siteVisitDate": "2024-04-18",
"buildingServicesRate": "2500",
"flatRate": "15000",
"landOtherRate": "12500",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  },
  "roadFacing": false,
  "mall": false
},
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
```

```

    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "0.00",
"otherCompositionSaleableTotal": "0.00"
}

```

Name	Length	Width	Total
Composition :			
Living Room	17'5"	8'8"	150.94
Cupboard	1'4"	4'5"	5.89
Passage	8'5"	2'8"	22.44
Toilet	5'11"	3'11"	23.17
WC	4'0"	3'0"	12.00
Kitchen	8'5"	7'6"	63.12
Bedroom	13'5"	8'7"	115.16
Other Composition :			