

```
{
  "typeOfReport": {
    "value": "Project_Finance",
    "label": "Project Finance"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Project_Valuation",
    "label": "Project Valuation"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "65e979baf9222577acbe667a"
    },
    "type": "CREDITOFFICER",
    "_id": "6621ee8a7e1d7332c880f909",
    "firstName": "Abhinav ",
    "lastName": "Agnihotri",
    "mobileNo": "",
    "workMobileNo": "9511901989",
    "email": "abhinav.agnihotri25@gmail.com"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "40000"
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "65e979baf9222577acbe667a",
  "name": "SME Panvel Branch ",
  "branchCode": "",
  "mobileNo": "0000000000",
  "alternateMobileNo": "",
  "email": "sbi.19254@sbi.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "MTNL Building, Ground Floor, Plot No 229, Near Shivaji Chouk, M G
ROad Panvel-410206"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
  "_id": "60f91822f3dd69653a5922e3",
  "role": "SITEENGINEER+MAKAR+CHECKER",
  "firstName": "Prayush ",
  "email": "prayush@vastukala.org",
  "lastName": "Parekh ",
  "mobileNo": "9767983840",
  "shortName": "PPP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "65829f7c65d49d78457ec7be",
  "role": "SITEENGINEER",
  "firstName": "Vaibhav",
  "email": "vaib1234b@gmail.com",
  "lastName": "Bhagat",
  "mobileNo": "8779534609",
  "designation": "Bachlore Of Engireeing",
  "shortName": "Vaibhav",
  "workWithDocumentMaker": "62691c48afd7d55eddecfda3"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f91822f3dd69653a5922e3",
  "role": "SITEENGINEER+MAKAR+CHECKER",
  "firstName": "Prayush ",
  "email": "prayush@vastukala.org",
  "lastName": "Parekh ",
  "mobileNo": "9767983840",
  "designation": "",
  "shortName": "PPP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60f91822f3dd69653a5922e3",
  "role": "SITEENGINEER+MAKAR+CHECKER",
  "firstName": "Prayush ",
  "email": "prayush@vastukala.org",
  "lastName": "Parekh ",
  "mobileNo": "9767983840",
  "designation": "",
```

```
"shortName": "PPP",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"checker": {
"type": "EMPLOYEE",
"_id": "60f91822f3dd69653a5922e3",
"role": "SITEENGINEER+MAKAR+CHECKER",
"firstName": "Prayush ",
"email": "prayush@vastukala.org",
"lastName": "Parekh ",
"mobileNo": "9767983840",
"designation": "",
"shortName": "PPP",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "IBBI"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
},
{
"title": {
"value": "FIIV",
```

```
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "18.94343174937841",
  "longitude": "73.14040921222495"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
}
},
```

```
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": [],
  "remark": null,
  "rateMin": "7500",
  "lumpsumValue": "1",
  "rateMax": "9000",
  "areaType": {
    "Name": "Carpet",
    "Value": "Carpet",
    "name": "Carpet",
    "value": "Carpet"
  }
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Giravale",
    "label": true
  },
  "floorNo": {
```

```
"status": true,
"name": "Floor No",
"key": "floorNo",
"value": "Basement",
"label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Panvel",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Panvel",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "99/2 & 99/3",
```

```
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Kalash Greens",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "A & B",
  "label": true
},
"projectName": {
  "status": false,
```



```
"name": "Project Name",
"key": "projectName",
"value": "",
"label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
  "label": false
}
```

```
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
```

```
"key": "postalCode",
"value": "410206",
"label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "label": "Proposed R.C.C. Slab",
    "value": "Proposed_R.C.C._Slab"
  },
  "flooring": {
    "label": "Proposed Vitrified tiles flooring",
    "value": "Proposed_Vitrified_tiles_flooring"
  },
  "doors": {
    "label": "Proposed Teak wood door frame with flush doors",
    "value": "Proposed_Teak_wood_door_frame_with_flush_doors"
  },
  "windows": {
    "label": "Proposed Powder coated aluminium sliding windows",
    "value": "Proposed_Powder_coated_aluminium_sliding_windows"
  },
  "fittings": {
    "label": "Proposed Concealed plumbing with C.P. fittings. Concealed wiring",
    "value": "Proposed_Concealed_plumbing_with_C.P._fittings._Concealed_wiring"
  },
  "finishing": {
    "label": "Proposed Cement Plastering",
    "value": "Proposed_Cement_Plastering"
  }
},
"general": {
  "populationClassList": {
    "label": "Middle Class",
    "value": "MiddleClass"
  },
  "populationGroupList": {
    "label": "Rural",
    "value": "Rural"
  }
}
```

```
},
"townplanApprovedByList": {
  "label": "(Grampanchayat) Zilla Parishad, Thane",
  "value": "(Grampanchayat)_Zilla_Parishad,_Thane"
},
"asPerActualAgreement": {
  "north": "open plot",
  "west": "road",
  "south": "open plot",
  "east": "open plot"
},
"asPerDocumentAgreement": {
  "north": "",
  "west": "",
  "south": "",
  "east": ""
},
"unitBoundaries": {
  "asPerActual": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "asPerDocument": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
}
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "label": "Ordinary",
    "value": "Ordinary"
  },
  "propertyTypeOfUseList": {
    "label": "Proposed Residential Purpose",
    "value": "Proposed_Residential_Purpose"
  },
}
```

```
"propertyOccupiedByList": {
  "label": "Builder Occupied ",
  "value": "Builder_Occupied_"
},
"monthlyRent": ""
},
"siteMeasurement": {
  "partitions": {
    "label": "Building Under Construction",
    "value": "Building_Under_Construction"
  },
  "waterTank": {
    "label": "Proposed Municipal Water Supply",
    "value": "Proposed_Municipal_Water_Supply"
  },
  "pavementLaid": {
    "label": "Building Under Construction",
    "value": "Building_Under_Construction"
  },
  "carParking": {
    "label": "Building Under Construction",
    "value": "Building_Under_Construction"
  },
  "constructionWorkStatus": {
    "label": "Under Construction",
    "value": "InProgress"
  },
  "dateOfConstruction": {
    "date": "",
    "month": "1",
    "year": "2025",
    "fullDate": "1/1/2025"
  },
  "propertyTypeList": {
    "label": "Residential",
    "value": "Residential"
  },
  "planningArea": {
    "label": "Residential",
    "value": "Residential"
  },
  "typeOfStructure": {
    "label": "Proposed R.C.C Framed Structure",
    "value": "Proposed_R.C.C_Framed_Structure"
  },
  "qualityOfConstruction": {
```

```
"label": "Building is under construction ",
"value": "Building_is_under_construction_"
},
"walls": {
  "label": "Building Under Construction",
  "value": "Building_Under_Construction"
},
"appearanceOfTheBuilding": {
  "label": "Building is under construction ",
  "value": "Building_is_under_construction_"
},
"maintenanceOfTheBuilding": {
  "label": "Building is under construction ",
  "value": "Building_is_under_construction_"
},
"visibleDamageInBuilding": {
  "label": "Building Under Construction",
  "value": "Building_Under_Construction"
},
"groundStilt": {
  "label": "Proposed Ground",
  "value": "Proposed_Ground"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "",
"estimatedAge": "",
"ageOfBuilding": "",
"noOfBasement": "0",
"noOfPodium": "0",
"noOfAmenityFloors": "0",
"noOfFloors": "07",
"flatFloorNo": "",
"noOfLifts": "01",
"noOfLiftsInEachWings": "0",
"noOfDwellingUnitsInBuilding": "06"
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
```

```
"status": false,
"remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "InProgress",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
```



```
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "1",
"percentage": "2.00",
"isHideFloor": false,
"status": true
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "7.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "0",
"selectedBuildUpValue": "0",
"selectedBuildUpMeasurementType": ""
},
"reportImages": {
"frontPageImages": [],
"selfieWithSiteVisitImages": [],
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
```

```
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
```

```
"title": "Superfine finish",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```

```
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": true,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"invoices": [],
"paymentIds": [],
"_id": "6621f2f57e1d7332c8810094",
"ownerName": "M/s. Bhoomi Kalash Group",
"ownerPhoneNo": "9920453300",
"fullAddress": "Residential Project Finance No. Basement Floor, Wing - A & B, Kalash Greens, Plot No. 99/2 & 99/3, Village - Giravale, Taluka - Panvel, District - Panvel, 410206",
"remark": "",
"documents": [
```

```
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
    "label": "RERA Certificate"
  },
  "inputs": {
    "documentDate": "22/09/2023",
    "nameOfApprovingAuthority": {
      "value": "Maharashtra_Real_Estate_Regulatory_Authority",
      "label": "Maharashtra Real Estate Regulatory Authority"
    },
    "number": {
      "value": "Registration_No",
      "label": "Registration No"
    },
    "Registration_No": "P52000052750"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1713500877744_RERA_CERTIFICATE.pdf",
  "path": "cases/6621f2f57e1d7332c8810094/
document_1713500877744_RERA_CERTIFICATE.pdf",
  "id": "535249",
  "uploadedBy": "60f91822f3dd69653a5922e3",
  "createdAt": "Fri Apr 19 2024 09:58:37 GMT+0530 (India Standard Time)"
}
],
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"gstNo": "27AAZFB3859M1ZG",
"caseNumber": "008292",
"createdBy": "60f91822f3dd69653a5922e3",
"caseHistory": [
  {
    "id": "769950",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Apr 19 2024 09:58:37 GMT+0530 (India Standard Time)"
  }
]
],
"owners": [
  {
    "name": "M/s. Bhoomi Kalash Group",
    "phone": "9920453300",
```

```
"ownershipShare": "",
"email": "",
"id": "488154"
},
],
"proposePurchasers": [],
"siteInspection": [
{
"areaType": {
"label": "Built Up",
"value": "Built Up"
},
"providedBy": {
"label": "Owner",
"value": "Owner"
},
"_id": "6622bedb7e1d7332c882780a",
"area": "125000",
"providedByName": "M/s. Bhoomi Kalash Group",
"providedByContactNo": "9920453300"
}
],
"composition": [
{
"measurementType": {
"label": "Square Feet",
"value": "Square_Feet"
},
"id": "167124",
"name": "Living Room",
"length": "1.00",
"length1": "1",
"length2": "00",
"width": "1.00",
"width1": "1",
"width2": "00",
"totalArea": "1.00",
"images": [],
"extraAreas": [],
"finalArea": "1.00"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
```

```
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6622bfd27e1d7332c8827862",
    "name": "externalImg_1713553272070_image.jpeg",
    "path": "cases/6621f2f57e1d7332c8810094/
externalImg_1713553272070_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6622bfd27e1d7332c8827863",
    "name": "externalImg_1713553274771_image.jpeg",
    "path": "cases/6621f2f57e1d7332c8810094/
externalImg_1713553274771_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6622bfd27e1d7332c8827864",
    "name": "externalImg_1713553278065_image.jpeg",
    "path": "cases/6621f2f57e1d7332c8810094/
externalImg_1713553278065_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6622bfd27e1d7332c8827865",
    "name": "externalImg_1713553280705_image.jpeg",
    "path": "cases/6621f2f57e1d7332c8810094/
externalImg_1713553280705_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6622bfd27e1d7332c8827866",
    "name": "externalImg_1713553281535_image.jpeg",
    "path": "cases/6621f2f57e1d7332c8810094/
externalImg_1713553281535_image.jpeg",
    "orientation": "landscape"
  }
]
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6622bfd27e1d7332c8827867",
  "name": "externallmg_1713553287995_image.jpeg",
  "path": "cases/6621f2f57e1d7332c8810094/
externallmg_1713553287995_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6622bfd27e1d7332c8827868",
  "name": "externallmg_1713553294180_image.jpeg",
  "path": "cases/6621f2f57e1d7332c8810094/
externallmg_1713553294180_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6622bfd27e1d7332c8827869",
  "name": "externallmg_1713553299770_image.jpeg",
  "path": "cases/6621f2f57e1d7332c8810094/
externallmg_1713553299770_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6622bfd27e1d7332c882786a",
  "name": "externallmg_1713553304580_image.jpeg",
  "path": "cases/6621f2f57e1d7332c8810094/
externallmg_1713553304580_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6622bfd27e1d7332c882786b",
  "name": "externallmg_1713553309710_image.jpeg",
  "path": "cases/6621f2f57e1d7332c8810094/
externallmg_1713553309710_image.jpeg",
  "orientation": "landscape"
},
}
```



```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6622bfd27e1d7332c882786c",
  "name": "externallmg_1713553314714_image.jpeg",
  "path": "cases/6621f2f57e1d7332c8810094/
externallmg_1713553314714_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6622bfd27e1d7332c882786d",
  "name": "externallmg_1713553319050_image.jpeg",
  "path": "cases/6621f2f57e1d7332c8810094/
externallmg_1713553319050_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6622bfd27e1d7332c882786e",
  "name": "externallmg_1713553323200_image.jpeg",
  "path": "cases/6621f2f57e1d7332c8810094/
externallmg_1713553323200_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6622bfd27e1d7332c882786f",
  "name": "externallmg_1713553328136_image.jpeg",
  "path": "cases/6621f2f57e1d7332c8810094/
externallmg_1713553328136_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6622bfd27e1d7332c8827870",
  "name": "externallmg_1713553331849_image.jpeg",
  "path": "cases/6621f2f57e1d7332c8810094/
externallmg_1713553331849_image.jpeg",
  "orientation": "landscape"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6622bfd27e1d7332c8827871",
    "name": "externalImg_1713553336054_image.jpeg",
    "path": "cases/6621f2f57e1d7332c8810094/
externalImg_1713553336054_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6622bfd27e1d7332c8827872",
    "name": "externalImg_1713553339784_image.jpeg",
    "path": "cases/6621f2f57e1d7332c8810094/
externalImg_1713553339784_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6622bfd27e1d7332c8827873",
    "name": "externalImg_1713553345499_image.jpeg",
    "path": "cases/6621f2f57e1d7332c8810094/
externalImg_1713553345499_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6622bfd27e1d7332c8827874",
    "name": "externalImg_1713553347849_image.jpeg",
    "path": "cases/6621f2f57e1d7332c8810094/
externalImg_1713553347849_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6622bfd27e1d7332c8827875",
    "name": "externalImg_1713553351809_image.jpeg",
    "path": "cases/6621f2f57e1d7332c8810094/
externalImg_1713553351809_image.jpeg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
```

```

"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-04-19T04:28:37.525Z",
"updatedAt": "2024-04-19T19:03:24.493Z",
"__v": 0,
"updatedBy": "65829f7c65d49d78457ec7be",
"addressForMap": "",
"caseReferredBy": "60f91822f3dd69653a5922e3",
"contactPersonName": "Mr. Bharat Patel",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9920453300",
"briefDescOfProperty": "Living Room",
"carpetTotal": "1",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "0"
}

```

Name	Length	Width	Total
Composition :			
Living Room	1'00"	1'00"	1.00
Other Composition :			