## Deepak jain

## Inspection report of Residential/Commercial/Industrial properties

Name of Bank: sbi Date of inspection:23-4-2024

Name of Data. Soft Date of hispection, 25-4-2024		
Name of the Applicant	ISMAIL MOHD MULLA	
Type of property:	Residental flat	
Address of the property	FLAT NO 205,2 <sup>ND</sup> FLOOR,GROWMORE ONYX	
	,MALWANI SAKINA CHSL,MALAD WEST	
Nearest Railway station	5 km away from malad station	
Name of the road access to	Abdul hamid road	
Landmark / vicinity:	Malwani mahada 8 no	
Boundaries of the building	North: open plot	
	south: internal road	
	east: under constrution	
	west: open plot	
Locality	Type : Residential / Commercial / Industrial /	
,	Mix	
	Class of people : Lower class/Middle class/	
	Upper Middle class/ Higher class	
	Site is: Normal/ above road/ below road	
Permitted Land Use	Residential/Commercial/Industrial/Mix	
Actual Land Use	Residential/Commercial/Industrial/Mix	
Availability of other	School	
amenities in the	Market	
surrounding	College	
G	Temple	
Surrounding development	Developed/Well Developed	
Occupant	vacant	
Building details	Type of Structure: : (RCC/Load Beaing)	
C .	No. of Floors: stilt+22nd floor	
	No of wings:1	
	No. of flats/units on each : 6 flat	
No. of lifts with capacity &	3 no with 8person capacity	
Status		
Underground & Overhead	1 no. Overhead Tank &	
tanks	1 no. Under ground Tank	
Year of Construction	Under constrution	
Age of the building	Under constrution	
Estimated future life of the	Under constrution	
building		
Building elevation	Good	
Condition of the building :	Good	
Finishing	Luster paint / cement	
	Name of the Applicant Type of property: Address of the property  Nearest Railway station  Name of the road access to the property  Landmark / vicinity:  Boundaries of the building  Permitted Land Use  Actual Land Use  Availability of other amenities in the surrounding  Surrounding development  Occupant  Building details  No. of lifts with capacity & Status  Underground & Overhead tanks  Year of Construction  Age of the building  Estimated future life of the building  Building elevation  Condition of the building:	

22.	Amenities	parking
23.	Flooring in open spaces and staircase	Open Space Garden tiles & Kotastone staircase
24.	Doors & Windows	wooden door
25.	Compound wall & no. of gates	6 ft height of compound wall & nos. of MS Gates & security
26.	No. of rooms	1 bhk+2 toilet
27.	View from the different rooms of the property	building
28.	Internal finishing	Flooring in different rooms : vitrified Kitchen Platform : granite/stainless steel Electrical : OPEN / <u>CONCEALED</u> Plumbing : OPEN / <u>CONCEALED</u>
29.	Balcony	
31	Carpet area as per Measurement :	345sq feet (370sq feet as per rera carpet )
32	Nearest Bus stop	Malwani mahada 8no
33	Nearest Hospital	Care hospital
34	Condition of Road	30 feet good wide road
35	Rate per sq ft.	56 lack all inclusive
36	Person Met at Site	Mr rajesh vora/9867215794
37	Coordinate	19.18006217658703, 72.81593450987891
38	Name on society board	Na
39	Name on door	Na

## remark:

1;the said proeprty all work doane
02:the said proeprty lift work and finishing work in progress.
3;the said proeprty possession date june 2024