

Off: 9769070154 Email:tejas.dave@libravaluers.com Web: www.libravaluers.com

On the request of the Manager of *YES Bank Limited*, subject property was inspected to assess its value and the details are as furnished below: -

Branch Name	Branch Name Yes Bank – Santacruz		ELC
Valuer's Name Libra Valuers		Date of visit	25-01-2024
Visiting Eng. Name Vaibhav Gorule		Time of visit	NA
Case Ref. No 20221609		Date of report	25-01-2024
Person contacted for property inspection with contact details		Brijesh 845294449	2

	BASIC DETAILS					
1	Applicants Name	M/s. Sparkle Diam Pvt. Ltd.	Name of Owners	M/s. K Girdharlal International Limited		
2	Type of property as per approvals	Office	Current usage	Commercial		
	Address of property / Site Address	Unit No EC9020 and E Bharat Diamond Bour Bandra Kurla Complex	se, BKC Road, Plot I	No C-28, G Block,		
3	Address as per documents	Unit No EC9020 and EC9030, 9th Floor, E Tower, Central Wing, Bharat Diamond Bourse, CTS No 4207 of Village Kolekalyan, BKC Road, Plot No C-28, G Block, Bandra Kurla Complex, Bandra East, District Mumbai - 400051				
4 Has the valuer done valuation of this property before? If yes, for whom & when.			NA			

	SORROUNDING AND LOCALITY DETAILS					
		Zoning as per Master Plan / Development plan	Commercial			
		Class of locality (High / Middle Class / Lower / Negative)	Middle Class			
5	5 Location	Site (Developed / under-developed)	Developed			
		Proximity from civic amenities / public transport	2.4 Km From Kurla Railway Station			
		Nearest Railway Station	Kurla Railway Station			
		Nearest Bus Stop	Bharat Diamond Bus Stop			
6	Nearest Landmark	Near Bandra Kurla Complex				
7	Distance from City Centre	2.4 Km From Kurla Railway Station				

8 Condition and width of approach road: - 30 Feet (Average)

	PROPERTY DETAILS					
9	Brief description of the property	Office				
10	Internal visit done	Yes				
		Vacant/Occup	oied	Self Occupied		
11	Occupant			M./s. K K Gir Limited	dharlal International	
		Relation with	applicant	Self Occupied		
		Property Dem	arcated	Yes		
		Property Iden	tified through	Customer has	shown property	
		Type of struct	ure	RCC Frame st	tructure	
		Land/Plot Are	ea	NA		
12	Building details	No of Blocks/Wings		7 Towers (A t	7 Towers (A to J)	
		No of Units per floor		7 Units per Floor		
		No. of Floors		Basement + Ground + 9th Floor		
		No. of Lifts		6 Lifts		
		Amenities		CCTV Camera & Security		
		Located on Floor No.		9th Floor		
13	Unit details	No. of rooms / Unit configuration		Office		
		Remarks on view from property		Building View		
14	Present condition of the	Exterior		Average		
14	property:	Interior		Average		
15	Age of the property	14 Years (As	Per OC)	Residual life	46	
16	Boundaries	North	South	East	West	
	Actual on site	Tower D	Tower C	BKC Road	Garden	
	As per Title document	Details Not Mentioned In Agreement	Details Not Mentioned In Agreement	Details Not Mentioned In Agreement	Details Not Mentioned In Agreement	
	Boundaries matching wit	th Sale Deed (Ye	es / No)	NA		

	SANCTION PLAN APPROVAL & OTHER DOCUMENTS DETAILS					
17	Sanction plan / Layout provided & CC / BCC / OC / BUC is provided	Sanctioned Plan Not Provided				
17 (A)	Sanction plan / Layout provided & CC / BCC / OC / BUC is from competent authority? If yes provide sanctioning authority & the other approval details.	27(CC 06/09	OC Issued by MMRDA Ref No TCP(P-2)/BKC-27(CC)/6/C-20/T-7&7B/1010/2009 on dated 06/09/2009 (Plot No C-28 in G Block) (Basement + Ground + 9th Floors)			
17(B)	(Yes / No) If No, specify the competent authority.	MMR	MMRDA			
18	Sale Deed / TSR	Xerox Copies of Allotment Letter Sale Deed Cum Transfer and OC				
19	Ownership type	Free Hold				
20	Is the property within Municipal Limits	Yes, MMRDA				
	Setbacks	As per plan	As per Bye- Laws	Actual at site	Extra Coverage deviation As Per Plan	Extra Coverage deviation as per byelaws
21	Front	NA	NA	NA	NA	NA
	Side 1 (Right	NA	NA	NA	NA	NA
	Side2 (Left)	NA	NA	NA	NA	NA
	Rear	NA	NA	NA	NA	NA
	Deviations if any	NA				
22	Property appearing in demolition list maintained by local authority (Yes/No)	No				
	Demolition Risk	Nil				
	Comments on reason if in Demolition risk is High/Medium/Low	Low				

23	VALUATION METHODOLOGY		
	Method of Valuation Adopted	Comparison Method	
	Rationale for adoption of Valuation Methodology	Comparison Method	

24	VALUATION				
	Area Details		_		
	As per Agreement / Sale Deed	599 Carpet Area (256 CA - Unit 9020 + 343 CA - Unit 9030)(As Per Registered Agreement)	Sft	Carpet	
	As per Plan	Sanctioned Plan Not Provided	Sft	Carpet	
	As per Measurement	599 Carpet Area (As Per Measurement)	Sft	Carpet	
A1	Land + Construction Met	hod (Applicable for Villa ,	Bungalow / Row House /	Industrial)	
	Description	Area in Sft	Rate per Sft	Value in Rs.	
	Land area	0	0		
	Construction area (Const rate as per present condition of the property)	0	0	0	
	Value of Land + Constru	ction in Rs. (A1)		0	
A2	2 Comparison Method				
	Carpet Area	599 Carpet Area (256 CA - Unit 9020 + 343 CA - Unit 9030)(As Per Registered Agreement)	Loading in %	50%	
	Saleable area	899	Rate per Sft	45000	
	Value of property as per	comparison method (A2)		40455000	
В	Value of Amenities if ap	<u> </u>			
a)	No of car parks	Rate per car parking	Value of car park		
,	0Nos	NA	0		
b)	Other charges in Rs. (Lun	np Sum)	0		
	Total Amenities charges	(B)	0		
	Total Fair Market Value A2 + B	of the property: - A1 or	40455000		
	Realizable Value in figur	es	36409500		
	Realizable Value in Word	s	Three Crore Sixty Four Lacs Nine Thousand Five Hundred		
	Forced Sale Value / Distress Value in figures		28318500		
	Forced Sale Value / Distr	ess Value in Words	Two Crore Eighty Three Lacs Eighteen Thousand Five Hundred		
	Ready Reckoner rate / Ci (Suitable evidence to be prov		Rs 419250/- Per Sq Mtr o	n BUA (Office)	
	Ready Reckoner/Circle/		27996739		
	Date of last Sale Agreeme to Sale		31/12/2014		

Value as per last Sale Agreement / Deed/	26950000 (Unit 9030)
Agreement to Sale	
Approx. Rentals in case of 100% complete property	280000
Insurance value / Re-construction cost	1078800


25	Market Comparable				
a)	Property Details	Central Wing, Bharat Diamond Bourse			
	Value	17500000/- for 260 Date of From Society Carpet Transaction/Quotation Information			
b)	Property Details	Central Wing, Bharat Diamond Bourse			
	Value	23500000/- for 350 Carpet	Date of Transaction/Quotation	From Society Information	

26	Stage of Construction				
	Details of stage of construction	100% Completed			
	%age Progress	100%	%age Recommended	100%	

	<u>Remarks</u>
Negative Remarks	Positive Remarks
	 The property under consideration is Office on 9th Floor in Basement + Ground + 9th storied commercial building with 6 lifts., The height of the commercial unit is 10 feet approx. As per site observation access to the building is as per norms and road width is 30 feet approx. We have received Xerox copies of Allotment Letter Sale Deed Cum Transfer and OC are made available for verification. At the time of visit we have observed that property was Self Occupied by M./s. K K Girdharlal International Limited. As per society name board owner of the unit is M/s. K Girdharlal International Limited. (Unit 9020) Allotment of Equity Shares and Grant of Occupancy Rights made between M/s. Bharat Diamond Bourse AND M/s. K Girdharlal International Limited on dated 20/07/2011 are made available for
]	Negative Remarks

		verification. 8. (Unit 9030) Sale Deed cum Transfer made between M/s. Venus Jewel AND M/s. K Girdharlal International Ltd on dated 31/12/2014 are made available for verification. 9. Unit boundaries are not mentioned in available documents hence Please check at your legal end before disbursement., 10. We have considered 50% loading on Carpet Area as per Sale Deed to furnish the valuation report. 11. As per site inspection Unit No EE9011 EC9011 EC9012 EE9012 EC9013 EC9020 and EC9030 are internally merged having entrance from EC9012 & EE9012 and other
		units entrance are permanently closed whereas we have received initiation for Unit No EC9020 and EC9030 only and we have given valuation for EC9020 and EC9030 only. 12. Kindly check your policy before funding such types of cases having no entrance to our subject unit which is to be noted.
28	Is project progressing or stalled:	NA
29	Latitude: 19.065301	Longitude: 72.864613

Location Sketch:



Site Sketch / Layout



Geo Tagging

Property Sketch:





Elevation Entry





Internal Pantry Area





Approach Road

Selfie with Client

Declaration:

I/We hereby declare that:

- 1. Our representative physically inspected the property.
- 2. We have no direct/indirect interest in the property valued.
- 3. Report is prepared based on the information furnished to us or documents submitted or shown to us by the client.
- 4. The fair market value indicated in the report is an opinion of the value prevailing on the date of the said report and is based on market feedback on values of similar properties.
- 5. The client is free to obtain other independent opinions on the same. The fair market value of such properties/localities may increase or decrease depending on the future market conditions and scenarios.
- 6. This report does not certify of confirm any ownership or title of the property that has been valued. The ownership papers/sale deeds may please be verified at your end to ascertain the right title & area.
- 7. The services provided by **Libra Valuers** to the Client will be limited to their use. The Report should not be used for any other purpose.
- 8. The Report will reflect matters, as they currently exist. Changes may materially affect the information contained in the Report.
- 9. It should be noted that report would be based upon the facts and evidence available at the date of assessment. Periodical review of the same may be required. Changes in socioeconomic, economic policy and political conditions could result in a substantially different situation than those presented at the stated effective date. **Libra Valuers** assumes no responsibility for changes in such external conditions.
- 10. We do not possess legal expertise and hence recommend you to take opinion of legal expert in order to ensure that there are no elements, restriction or charges contained which are likely to have detrimental effect upon the value or marketability of property.

- 11. In the preparation of the Report, we have relied on the following information:
 - a. Information provided to us by the client and its affiliates and subsidiaries and third parties;
 - b. Other relevant information provided to us by the Client and its affiliates and subsidiaries at request;
 - c. Other relevant information available to us or publicly available.

For

Sign & Stamp

Date: 25/01/2024

Place: Mumbai