

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "6454ca2514bbf555ec46980a"
    },
    "type": "CREDITOFFICER",
    "_id": "6454ca2514bbf555ec46980d",
    "firstName": "Deepak Kumar",
    "lastName": "Aarya",
    "mobileNo": "",
    "workMobileNo": "7350000012",
    "email": "ubin0561380@unionbankofindia.bank"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "2200000",
    "discussWithPerson": "Deepak Kumar",
    "expectedFees": 1100,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1828",
  "type": "BANK",
  "name": "Union Bank of India",
  "displayName": "Union Bank of India",
  "initial": "UBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "6454ca2514bbf555ec46980a",
  "name": "Gokhivire Vasai Branch\t",
  "branchCode": "",
  "mobileNo": "2502464808\t",
  "alternateMobileNo": "",
  "email": "ubin0561380@unionbankofindia.bank",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Surucha Muldapat Residency, Ground Floor, Pinto Travelles Campus,
Gokhivire, Vasai East\n"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f93be845132d6a6bdda676",
  "zoneName": "MUMBAI SOUTH"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
"_id": "659ccce98f39506e83489828",
"role": "DELIVERYPERSON",
"firstName": "Amit",
"email": "amitsalvi2909@gmail.com",
"lastName": "Salvi",
"mobileNo": "7499830659",
"shortName": "Amit",
"workWithDocumentMaker": "",
"profilePhoto": "users/659ccce98f39506e83489828/
profilePhoto_1712385426269_image.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "6401b61f0e28255fb44e636a",
"role": "SITEENGINEER",
"firstName": "Sanket",
"email": "ksanket7414@yahoo.com",
"lastName": "Karalkar",
"mobileNo": "8080582858",
"designation": "",
"shortName": "SAK",
"workWithDocumentMaker": ""
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "64dc7184ccaf1e7b7f637f47",
"role": "FRONTDESK",
"firstName": "Binumon",
"email": "binu@vastukala.org",
"lastName": "Moozhickal",
"mobileNo": "9930252906",
"designation": "Back Office Team Leader",
"shortName": "BS",
"workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
"profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "62fe044a48a26047e6552796",
"role": "MAKER",
"firstName": "Pradnya ",
"email": "pradnya@vastukala.org",
"lastName": "Rasam",
"mobileNo": "9529385821",
"designation": ""
```

```
    "shortName": "PR",
    "workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
    "profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
  },
  "checker": {
    "type": "EMPLOYEE",
    "_id": "64dc7184ccaf1e7b7f637f47",
    "role": "FRONTDESK",
    "firstName": "Binumon",
    "email": "binu@vastukala.org",
    "lastName": "Moozhickal",
    "mobileNo": "9930252906",
    "designation": "Back Office Team Leader",
    "shortName": "BS",
    "workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
    "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
  },
  "valuers": [
    {
      "valuersRegistrationNumber": [
        {
          "value": "IBBI/RV/07/2018/10366",
          "label": "Registered Valuer"
        }
      ],
      "type": "EMPLOYEE",
      "_id": "5ffe92d27737ca4d986b6453",
      "role": "VALUER",
      "firstName": "Manoj",
      "email": "manoj@vastukala.org",
      "lastName": "Chalikwar",
      "mobileNo": "9819597579",
      "designation": "Registered Valuer",
      "registrationNo": [
        {
          "title": {
            "label": "IBBI"
          },
          "_id": "60af80072ffdf65bcd658651",
          "number": "IBBI/RV/07/2018/10366"
        }
      ],
      {
        "title": {
          "value": "FIIV",
```

```
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.410192345302086",
  "longitude": "72.84162724829896"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.84162724829896,
    19.410192345302086
  ]
}
},
```

```
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "29/04/2024 11:34 am"
    },
    {
      "dateTime": "29/04/2024 12:00 am"
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-04-29",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-04-29",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-04-29",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-04-29",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
```

```
"state": {
  "status": true,
  "name": "State",
  "key": "state",
  "value": "Maharashtra",
  "label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "Country - India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Gokhivare ",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "4",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "02",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Palghar ",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
```

```
"value": "Palghar ",
"label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Vasai ",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Sai Nagar",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
```



```
"status": false,
"name": "Street 2",
"key": "street2",
"value": "",
"label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "A",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "127 & Hissa No. 1B",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
```

```
"label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "405",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
```

```
"name": "SRO",
"key": "SRO",
"value": "",
"label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 401 208",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Vasai (East)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  }
}
```

```

},
"windows": {
  "value": "Wooden_frame_openable_widow_with_M._S._Grill",
  "label": "Wooden frame openable widow with M. S. Grill"
},
"fittings": {
  "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
  "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
},
"finishing": {
  "value": "Cement_Plastering+_POP_Finish",
  "label": "Cement Plastering + POP Finish"
}
},
"general": {
  "ownership": {
    "value": "Sole_Ownership",
    "label": "Sole Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "Vasai_Virar_City_Municipal_Corporation",
    "label": "Vasai Virar City Municipal Corporation"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Open Plot ",
    "west": "Internal Road ",
    "south": "Building No. 1",
    "east": "Vidya Vikasini School Playground "
  },
  "asPerDocumentAgreement": {
    "north": "Details not available ",
    "west": "Detaile not available ",
    "south": "Details not available "
  }
}

```

```
"east": "Details not available "
},
"unitBoundaries": {
  "asPerActual": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "asPerDocument": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "Copy of Approved Building Plan No. VVCMC / TP /
Amend / 5358 / 26 / 2022 - 23 dated 11.05.2022 issued by Vasai virar City Municipal
Corporation. ",
"approvePlanVerified": "Yes ",
"empanelledOfApprovePlan": "No",
"unauthorizedConstruction": ""
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "depreciatedCostOfConstruction": "",
  "depreciatedBuildingRate": ""
},
"igrRate": {
  "propertyName": "Flat",
  "rate": "58000",
  "landRate": "13400",
  "igrImage": "cases/662f37777b62822a9c78910/igr_1714480975361_Image.png",
  "squareMeterGuideLineRate": "46400.00",
  "squareFeetGuideLineRate": "4311.00"
},
```

```
"igrFinalRate": {
  "floorRatePercentage": "80",
  "depreciationPercentage": "0",
  "rate": "58000.00",
  "squareMeterGuideLineRate": "46400.00",
  "squareFeetGuideLineRate": "4311.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Vacant",
    "label": "Vacant"
  },
  "monthlyRent": "N.A",
  "assessmentNo": "Details not available ",
  "taxPaidHolderName": "Details not available ",
  "taxAmount": "Details not available ",
  "electricityServiceConnectionNo": "Details not available ",
  "meterCardHolderName": "Details not available ",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available ",
  "floorSpaceIndex": "As per VVCMC norms ",
  "tenantName": "",
  "maintenanceOfFlat": "Good "
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area ",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
```

```
"label": "6\" Thk. Brick Masonery"
},
"waterTank": {
  "value": "MunicipalWaterSupply",
  "label": "Municipal Water Supply"
},
"pavementLaid": {
  "value": "Yes",
  "label": "Yes"
},
"carParking": "Open / Covered Car Parking Space ",
"constructionWorkStatus": {
  "value": "Completed",
  "label": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2024",
  "fullDate": "1/1/2024"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
```

```
"value": "Standard",
"label": "Standard"
},
"structuralSafety": {
"value": "Good",
"label": "Good"
},
"protAgainstNatDis": {
"value": "Good",
"label": "Good"
},
"sewerageSystem": {
"value": "MunicipalSewerageSystem",
"label": "Connected to Municipal Sewerage System"
},
"walls": {
"value": "1",
"label": "Yes"
},
"appearanceOfTheBuilding": {
"value": "Good",
"label": "Good"
},
"maintenanceOfTheBuilding": {
"value": "Good",
"label": "Good"
},
"maintenancelssues": {
"value": "1",
"label": "Yes"
},
"visibleDamageInBuilding": {
"value": "1",
"label": "Yes"
},
"systemOfAirConditioning": {
"value": "1",
"label": "Yes"
},
"provisionOfFirefighting": {
"value": "1",
"label": "Yes"
},
"groundStilt": {
"value": "Part_Ground_and_Part_Stilt",
"label": "Part Ground + Part Stilt"
}
```



```
},
"yearOfConstructionAsPer": {
  "value": "Approx.",
  "label": "Approx."
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "60",
"ageOfBuilding": "0",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "4",
"flatFloorNo": "4",
"noOfLifts": "",
"noOfDwellingUnitsInBuilding": "6"
},
"finalPlinthArea": {
  "area": "326.56",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/662f377777b62822a9c78910/
routeMap_1714479551478_Image.png",
    "routeLat": "19.410337",
    "routeLng": "72.840257",
    "stationName": "Nalla Sopara ",
    "routeDistance": "3.2 Km. "
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  }
}
```

```
},
"locationMapImg": [
  {
    "id": "snu3ms",
    "name": "snu3ms",
    "image": "cases/662f377777b62822a9c78910/
routeMap_1714479450261_Image.png"
  }
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "2465100.00",
  "distressValuePercentage": "80",
  "realizableValuePercentage": "90",
  "bookValue": "0",
  "finalValue": "2465100.00"
},
"outward": {
  "status": true,
```

```
"remark": "SYSTEMGENERATED",
"date": "Thu May 02 2024 11:10:14 GMT+0530 (India Standard Time)",
"number": "2306141",
"dayCount": "1",
"monthCount": "1",
"generatedBy": "64dc7184ccaf1e7b7f637f47"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
},
```

```
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "1407800.00",
  "selectedBuildUpValue": "326.56",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
```

```
{
  "status": false,
  "_id": "66306cd0f76f30369f4d596f",
  "name":
"externallmg_1714449615833_WhatsApp_Image_20240429_at_200757.jpeg",
  "path": "cases/662f37777b62822a9c78910/
externallmg_1714449615833_WhatsApp_Image_20240429_at_200757.jpeg",
  "orientation": "landscape"
}
],
"selfieWithSiteVisitImages": [],
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
    "_id": "66306cd0f76f30369f4d5977",
    "name": "Living Room",
    "path": "cases/662f37777b62822a9c78910/
externallmg_1714449615861_WhatsApp_Image_20240429_at_200800_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66306cd0f76f30369f4d5979",
    "name": "Living Room",
    "path": "cases/662f37777b62822a9c78910/
externallmg_1714449615867_WhatsApp_Image_20240429_at_200800_3.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66306ce185028f369edc3752",
    "name": "Living Room",
    "path": "cases/662f37777b62822a9c78910/
externallmg_1714449633483_WhatsApp_Image_20240429_at_200801_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66306ce185028f369edc3757",
    "name": "Living Room",
    "path": "cases/662f37777b62822a9c78910/
externallmg_1714449633502_WhatsApp_Image_20240429_at_200813.jpeg",
    "orientation": "portrait"
  }
]
```

```
    },
    {
      "status": false,
      "_id": "66306ce185028f369edc3759",
      "name": "Living Room",
      "path": "cases/662f377777b62822a9c78910/
externallmg_1714449633509_WhatsApp_Image_20240429_at_200815_1.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "66306ce185028f369edc375f",
      "name": "Living Room",
      "path": "cases/662f377777b62822a9c78910/
externallmg_1714449633527_WhatsApp_Image_20240429_at_200816.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "66306cd0f76f30369f4d5975",
      "name": "Living Room",
      "path": "cases/662f377777b62822a9c78910/
externallmg_1714449615856_WhatsApp_Image_20240429_at_200759_2.jpeg",
      "orientation": "landscape"
    },
    {
      "status": false,
      "_id": "66306cd0f76f30369f4d596f",
      "name": "Living Room",
      "path": "cases/662f377777b62822a9c78910/
externallmg_1714449615833_WhatsApp_Image_20240429_at_200757.jpeg",
      "orientation": "landscape"
    }
  ]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "7731.00",
    "max": "10248.00"
  },
  "builtUpRateRange": {
    "min": "7028.00",
    "max": "9316.00"
  },
  "saleableRateRange": {
    "min": "0.00",
```

```
"max": "0.00"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "interiorDecorations": {
    "title": "Interior Decorations",
```



```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
```

```
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "296.87",
"empanelmentNo": [
  "ROS:ADV:Valuer/033:008:2021-22",
  "RO(S):ADV:VAL:012: 2018-19"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"invoices": [],
"paymentIds": [],
"_id": "662f37777b62822a9c78910",
"ownerName": "Mr. Nandkumar Mahadev Patil ",
"ownerPhoneNo": "9923328872",
"appAddress": "FLAT NO 405 A WING BLDG NO 2 SAI NAGAR GOKHIWARE VASAI
EAST PALGHAR 401208",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    }
  },
  "inputs": {
    "documentDate": "23/04/2024",
```

```
"from": {
  "value": "Promoter",
  "label": "Promoter"
},
"Promoter": "M/s. Shubh Vastu Realcon ",
"to": {
  "value": "Allottee",
  "label": "Allottee"
},
"Allottee": "Mr. Nandkumar Mahadev Patil ",
"number": {
  "value": "No",
  "label": "No"
},
"No": "8004 / 2024"
},
"isHardCopy": false,
"displayStatus": true,
"id": "588882",
"path": "cases/662f37777b62822a9c78910/
document_1714370345466_1714370123949_Nandkumar_Patil.pdf",
"fileName": "document_1714370345466_1714370123949_Nandkumar_Patil.pdf"
},
{
  "documentType": {
    "value": "60ae1277aa6d152c1801b3cc",
    "label": "Approved Building Plan"
  },
  "inputs": {
    "documentDate": "11/05/2022",
    "nameOfApprovingAuthority": {
      "value": "Vasai_Virar_City_Municipal_Corporation",
      "label": "Vasai Virar City Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "VVCMC / TP / Amend / 5358 / 26 / 2022 - 23"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1714481605634_LAYOUT.pdf",
  "path": "cases/662f37777b62822a9c78910/
document_1714481605634_LAYOUT.pdf",
  "id": "796243",
```

```
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Tue Apr 30 2024 18:23:26 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1259aa6d152c1801b33d",
    "label": "Revised Development Permission Certificate"
  },
  "inputs": {
    "documentDate": "11/05/2022",
    "nameOfApprovingAuthority": {
      "value": "Vasai_Virar_City_Municipal_Corporation",
      "label": "Vasai Virar City Municipal Corporation"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    }
  },
  "Document_No": "VVCMC / TP / RDP / VP - 5358 / 26 / 2022 - 23"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1714481695603_document_1714370345466_17143701239
49_Nandkumar_Patil.pdf",
"path": "cases/662f37777b62822a9c78910/document_1714481695603_document
_1714370345466_1714370123949_Nandkumar_Patil.pdf",
"id": "862961",
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Tue Apr 30 2024 18:24:56 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
    "label": "RERA Certificate"
  },
  "inputs": {
    "documentDate": "08/06/2023",
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "P99000006133"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1714481727865_document_1714370345466_17143701239
```

```
49_Nandkumar_Patil.pdf",
  "path": "cases/662f37777b62822a9c78910/document_1714481727865_document
_1714370345466_1714370123949_Nandkumar_Patil.pdf",
  "id": "439030",
  "uploadedBy": "62fe044a48a26047e6552796",
  "createdAt": "Tue Apr 30 2024 18:25:28 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "008433",
"createdBy": "659ccce98f39506e83489828",
"caseHistory": [
  {
    "id": "183644",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Mon Apr 29 2024 11:30:23 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Nandkumar Mahadev Patil ",
    "phone": "9923328872",
    "ownershipShare": "",
    "email": "",
    "id": "674913"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "577548",
    "name": "Living Room",
    "length": "9.00",
    "length1": "9",
    "length2": "00",
    "width": "14.25",
    "width1": "14",
    "width2": "3",
    "totalArea": "128.25",
    "images": [],
    "extraAreas": []
  }
]
```

```
"finalArea": "128.25"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Kitchen",
  "length": "7.25",
  "length1": "7",
  "length2": "3",
  "width": "8.75",
  "width1": "8",
  "width2": "9",
  "totalArea": "63.44",
  "images": [],
  "extraAreas": [],
  "finalArea": "63.44"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Bathroom",
  "length": "5.00",
  "length1": "5",
  "length2": "00",
  "width": "4.00",
  "width1": "4",
  "width2": "00",
  "totalArea": "20.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "20.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "WC",
  "length": "3.17",
```

```
"length1": "3",
"length2": "2",
"width": "3.75",
"width1": "3",
"width2": "9",
"totalArea": "11.87",
"images": [],
"extraAreas": [],
"finalArea": "11.87"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Bedroom",
  "length": "9.00",
  "length1": "9",
  "length2": "00",
  "width": "9.00",
  "width1": "9",
  "width2": "00",
  "totalArea": "81.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "81.00"
}
],
"otherComposition": [
  {
    "toBeAdded": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "name": {
      "label": "Cupboard",
      "value": "Cupboard"
    },
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "0",
    "length": "7.00",
    "length1": "7",
```

```
"length2": "00",
"width": "1.67",
"width1": "1",
"width2": "8",
"totalArea": "11.67",
"images": [],
"extraAreas": [],
"finalArea": "11.67",
"percentageBeforeTotal": "11.67",
"percentage": "100"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Flower Bed Area",
    "value": "Flower_Bed_Area"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "length": "9.00",
  "length1": "9",
  "length2": "00",
  "width": "1.58",
  "width1": "1",
  "width2": "7",
  "totalArea": "14.25",
  "images": [],
  "extraAreas": [
    {
      "measurementType": {
        "value": "Square_Feet",
        "label": "Square Feet"
      },
      "_id": "6630e3ccf76f30369f4ddcc8",
      "name": "Extra ",
      "extraAreaType": "Add",
      "length": "9.00",
      "length1": "9",
      "length2": "00",
      "width": "1.58",
```



```
    "width1": "1",
    "width2": "7",
    "totalArea": "14.25"
  }
],
"finalArea": "28.5",
"percentageBeforeTotal": "28.50",
"percentage": "100"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Dry Balcony Area",
    "value": "Dry_Balcony_Area"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "length": "7.25",
  "length1": "7",
  "length2": "3",
  "width": "1.58",
  "width1": "1",
  "width2": "7",
  "totalArea": "11.48",
  "images": [],
  "extraAreas": [],
  "finalArea": "11.48",
  "percentageBeforeTotal": "11.48",
  "percentage": "100"
}
],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
```

```
    "label": "Square Feet"
  },
  "selectAreaTypeDocument": "Carpet",
  "squareMeterArea": "27.58",
  "totalAreaDocument": "296.87",
  "docBultupPercentage": "10",
  "docFinalBultUp": "326.56",
  "docFinalBultUpSquareMeter": "30.34",
  "docSaleablePercentage": "",
  "docFinalSaleable": "0.00",
  "docFinalSaleableSquareMeter": "0.00",
  "id": "447495"
}
],
"images": [],
"indicatorArr": [
  {
    "carpetArea": {
      "area": "283.00",
      "squareMeterArea": "26.29",
      "expectedRate": "10247.35",
      "percentage": ""
    },
    "builtUpArea": {
      "area": "311.30",
      "squareMeterArea": "28.92",
      "expectedRate": "9315.77",
      "percentage": "10"
    },
    "saleableArea": {
      "area": "",
      "squareMeterArea": "0.00",
      "expectedRate": "0.00",
      "percentage": ""
    },
    "printlnReport": true,
    "_id": "6630e79852e3aa36c81a6223",
    "property": "Flat",
    "area": "283",
    "builtUpPercentage": "10",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "floor": "",
    "source": "Housing.Com",
    "expectedPrice": "2900000",
```

```
"expectedRate": "10247.35",
"builtUpExpectedRate": "9315.77",
"image": "cases/662f377777b62822a9c78910/
indicator_1714480653453_Image.png",
"squareMeter": "26.29",
"id": "128997"
},
{
  "carpetArea": {
    "area": "424.00",
    "squareMeterArea": "39.39",
    "expectedRate": "8490.57",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "466.40",
    "squareMeterArea": "43.33",
    "expectedRate": "7718.70",
    "percentage": "10"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "6630e79852e3aa36c81a6224",
  "property": "Flat",
  "area": "424",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "",
  "source": "magic_bricks",
  "expectedPrice": "3600000",
  "expectedRate": "8490.57",
  "builtUpExpectedRate": "7718.70",
  "image": "cases/662f377777b62822a9c78910/
indicator_1714480814780_Image.png",
  "squareMeter": "39.39",
  "id": "600755"
},
{
  "carpetArea": {
```

```
"area": "296.87",
"squareMeterArea": "27.58",
"expectedRate": "8001.92",
"percentage": ""
},
"builtUpArea": {
"area": "326.56",
"squareMeterArea": "30.34",
"expectedRate": "7274.41",
"percentage": "10"
},
"saleableArea": {
"area": "",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printlnReport": true,
"_id": "6630e79852e3aa36c81a6225",
"property": "Flat",
"area": "296.87",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Carpet",
"floor": "",
"source": "Index_no.2",
"expectedPrice": "2375531",
"expectedRate": "8001.92",
"builtUpExpectedRate": "7274.41",
"image": "cases/662f377777b62822a9c78910/
indicator_1714480886097_Image.png",
"squareMeter": "27.58",
"id": "703540"
},
{
"carpetArea": {
"area": "296.87",
"squareMeterArea": "27.58",
"expectedRate": "7730.66",
"percentage": ""
},
"builtUpArea": {
"area": "326.56",
"squareMeterArea": "30.34",
"expectedRate": "7027.80",
```

```
    "percentage": "10"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "6630e79852e3aa36c81a6226",
  "property": "Flat",
  "area": "296.87",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "floor": "",
  "source": "Index_no.2",
  "expectedPrice": "2295000",
  "expectedRate": "7730.66",
  "builtUpExpectedRate": "7027.80",
  "image": "cases/662f377777b62822a9c78910/
indicator_1714480924863_Image.png",
  "squareMeter": "27.58",
  "id": "703580"
}
],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66306cd0f76f30369f4d5966",
    "name":
"externallmg_1714449615701_WhatsApp_Image_20240429_at_200846.jpeg",
    "path": "cases/662f377777b62822a9c78910/
externallmg_1714449615701_WhatsApp_Image_20240429_at_200846.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66306cd0f76f30369f4d5967",
    "name":
"externallmg_1714449615790_WhatsApp_Image_20240429_at_200755_1.jpeg",
    "path": "cases/662f377777b62822a9c78910/
externallmg_1714449615790_WhatsApp_Image_20240429_at_200755_1.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66306cd0f76f30369f4d5968",
    "name":
"externallmg_1714449615797_WhatsApp_Image_20240429_at_200755_2.jpeg",
    "path": "cases/662f37777b62822a9c78910/
externallmg_1714449615797_WhatsApp_Image_20240429_at_200755_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66306cd0f76f30369f4d5969",
    "name":
"externallmg_1714449615803_WhatsApp_Image_20240429_at_200756_1.jpeg",
    "path": "cases/662f37777b62822a9c78910/
externallmg_1714449615803_WhatsApp_Image_20240429_at_200756_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66306cd0f76f30369f4d596a",
    "name":
"externallmg_1714449615811_WhatsApp_Image_20240429_at_200756_2.jpeg",
    "path": "cases/662f37777b62822a9c78910/
externallmg_1714449615811_WhatsApp_Image_20240429_at_200756_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66306cd0f76f30369f4d596b",
    "name":
"externallmg_1714449615816_WhatsApp_Image_20240429_at_200756_3.jpeg",
    "path": "cases/662f37777b62822a9c78910/
externallmg_1714449615816_WhatsApp_Image_20240429_at_200756_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66306cd0f76f30369f4d596c",
```

```
"name":
"externallmg_1714449615820_WhatsApp_Image_20240429_at_200756.jpeg",
  "path": "cases/662f37777b62822a9c78910/
externallmg_1714449615820_WhatsApp_Image_20240429_at_200756.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66306cd0f76f30369f4d596d",
  "name":
"externallmg_1714449615824_WhatsApp_Image_20240429_at_200757_1.jpeg",
  "path": "cases/662f37777b62822a9c78910/
externallmg_1714449615824_WhatsApp_Image_20240429_at_200757_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66306cd0f76f30369f4d596e",
  "name":
"externallmg_1714449615828_WhatsApp_Image_20240429_at_200757_2.jpeg",
  "path": "cases/662f37777b62822a9c78910/
externallmg_1714449615828_WhatsApp_Image_20240429_at_200757_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66306cd0f76f30369f4d596f",
  "name":
"externallmg_1714449615833_WhatsApp_Image_20240429_at_200757.jpeg",
  "path": "cases/662f37777b62822a9c78910/
externallmg_1714449615833_WhatsApp_Image_20240429_at_200757.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66306cd0f76f30369f4d5970",
  "name":
"externallmg_1714449615838_WhatsApp_Image_20240429_at_200758_1.jpeg",
  "path": "cases/662f37777b62822a9c78910/
externallmg_1714449615838_WhatsApp_Image_20240429_at_200758_1.jpeg",
  "orientation": "landscape"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66306cd0f76f30369f4d5971",
  "name":
"externallmg_1714449615841_WhatsApp_Image_20240429_at_200758_2.jpeg",
  "path": "cases/662f377777b62822a9c78910/
externallmg_1714449615841_WhatsApp_Image_20240429_at_200758_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66306cd0f76f30369f4d5972",
  "name":
"externallmg_1714449615844_WhatsApp_Image_20240429_at_200758_3.jpeg",
  "path": "cases/662f377777b62822a9c78910/
externallmg_1714449615844_WhatsApp_Image_20240429_at_200758_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66306cd0f76f30369f4d5973",
  "name":
"externallmg_1714449615848_WhatsApp_Image_20240429_at_200758.jpeg",
  "path": "cases/662f377777b62822a9c78910/
externallmg_1714449615848_WhatsApp_Image_20240429_at_200758.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66306cd0f76f30369f4d5974",
  "name":
"externallmg_1714449615853_WhatsApp_Image_20240429_at_200759_1.jpeg",
  "path": "cases/662f377777b62822a9c78910/
externallmg_1714449615853_WhatsApp_Image_20240429_at_200759_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66306cd0f76f30369f4d5975",
  "name":
"externallmg_1714449615856_WhatsApp_Image_20240429_at_200759_2.jpeg",
```



```
    "path": "cases/662f37777b62822a9c78910/
externallmg_1714449615856_WhatsApp_Image_20240429_at_200759_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66306cd0f76f30369f4d5976",
    "name":
"externallmg_1714449615859_WhatsApp_Image_20240429_at_200759.jpeg",
    "path": "cases/662f37777b62822a9c78910/
externallmg_1714449615859_WhatsApp_Image_20240429_at_200759.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66306cd0f76f30369f4d5977",
    "name":
"externallmg_1714449615861_WhatsApp_Image_20240429_at_200800_1.jpeg",
    "path": "cases/662f37777b62822a9c78910/
externallmg_1714449615861_WhatsApp_Image_20240429_at_200800_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66306cd0f76f30369f4d5978",
    "name":
"externallmg_1714449615864_WhatsApp_Image_20240429_at_200800_2.jpeg",
    "path": "cases/662f37777b62822a9c78910/
externallmg_1714449615864_WhatsApp_Image_20240429_at_200800_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66306cd0f76f30369f4d5979",
    "name":
"externallmg_1714449615867_WhatsApp_Image_20240429_at_200800_3.jpeg",
    "path": "cases/662f37777b62822a9c78910/
externallmg_1714449615867_WhatsApp_Image_20240429_at_200800_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "66306ce185028f369edc3751",
    "name":
"externallmg_1714449633480_WhatsApp_Image_20240429_at_200800.jpeg",
    "path": "cases/662f377777b62822a9c78910/
externallmg_1714449633480_WhatsApp_Image_20240429_at_200800.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66306ce185028f369edc3752",
    "name":
"externallmg_1714449633483_WhatsApp_Image_20240429_at_200801_1.jpeg",
    "path": "cases/662f377777b62822a9c78910/
externallmg_1714449633483_WhatsApp_Image_20240429_at_200801_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66306ce185028f369edc3753",
    "name":
"externallmg_1714449633486_WhatsApp_Image_20240429_at_200801_2.jpeg",
    "path": "cases/662f377777b62822a9c78910/
externallmg_1714449633486_WhatsApp_Image_20240429_at_200801_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66306ce185028f369edc3754",
    "name":
"externallmg_1714449633490_WhatsApp_Image_20240429_at_200801.jpeg",
    "path": "cases/662f377777b62822a9c78910/
externallmg_1714449633490_WhatsApp_Image_20240429_at_200801.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66306ce185028f369edc3755",
    "name":
"externallmg_1714449633493_WhatsApp_Image_20240429_at_200813_1.jpeg",
    "path": "cases/662f377777b62822a9c78910/
externallmg_1714449633493_WhatsApp_Image_20240429_at_200813_1.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66306ce185028f369edc3756",
    "name":
"externallmg_1714449633496_WhatsApp_Image_20240429_at_200813_2.jpeg",
    "path": "cases/662f377777b62822a9c78910/
externallmg_1714449633496_WhatsApp_Image_20240429_at_200813_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66306ce185028f369edc3757",
    "name":
"externallmg_1714449633502_WhatsApp_Image_20240429_at_200813.jpeg",
    "path": "cases/662f377777b62822a9c78910/
externallmg_1714449633502_WhatsApp_Image_20240429_at_200813.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66306ce185028f369edc3758",
    "name":
"externallmg_1714449633505_WhatsApp_Image_20240429_at_200814.jpeg",
    "path": "cases/662f377777b62822a9c78910/
externallmg_1714449633505_WhatsApp_Image_20240429_at_200814.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66306ce185028f369edc3759",
    "name":
"externallmg_1714449633509_WhatsApp_Image_20240429_at_200815_1.jpeg",
    "path": "cases/662f377777b62822a9c78910/
externallmg_1714449633509_WhatsApp_Image_20240429_at_200815_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66306ce185028f369edc375a",
```

```
    "name":
"externallmg_1714449633512_WhatsApp_Image_20240429_at_200815_2.jpeg",
  "path": "cases/662f37777b62822a9c78910/
externallmg_1714449633512_WhatsApp_Image_20240429_at_200815_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66306ce185028f369edc375b",
  "name":
"externallmg_1714449633515_WhatsApp_Image_20240429_at_200815.jpeg",
  "path": "cases/662f37777b62822a9c78910/
externallmg_1714449633515_WhatsApp_Image_20240429_at_200815.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66306ce185028f369edc375c",
  "name":
"externallmg_1714449633517_WhatsApp_Image_20240429_at_200816_1.jpeg",
  "path": "cases/662f37777b62822a9c78910/
externallmg_1714449633517_WhatsApp_Image_20240429_at_200816_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66306ce185028f369edc375d",
  "name":
"externallmg_1714449633520_WhatsApp_Image_20240429_at_200816_2.jpeg",
  "path": "cases/662f37777b62822a9c78910/
externallmg_1714449633520_WhatsApp_Image_20240429_at_200816_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66306ce185028f369edc375e",
  "name":
"externallmg_1714449633522_WhatsApp_Image_20240429_at_200816_3.jpeg",
  "path": "cases/662f37777b62822a9c78910/
externallmg_1714449633522_WhatsApp_Image_20240429_at_200816_3.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66306ce185028f369edc375f",
  "name":
"externallmg_1714449633527_WhatsApp_Image_20240429_at_200816.jpeg",
  "path": "cases/662f377777b62822a9c78910/
externallmg_1714449633527_WhatsApp_Image_20240429_at_200816.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66306ce185028f369edc3760",
  "name":
"externallmg_1714449633530_WhatsApp_Image_20240429_at_200750_1.jpeg",
  "path": "cases/662f377777b62822a9c78910/
externallmg_1714449633530_WhatsApp_Image_20240429_at_200750_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66306ce185028f369edc3761",
  "name":
"externallmg_1714449633533_WhatsApp_Image_20240429_at_200750.jpeg",
  "path": "cases/662f377777b62822a9c78910/
externallmg_1714449633533_WhatsApp_Image_20240429_at_200750.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66306ce185028f369edc3762",
  "name":
"externallmg_1714449633539_WhatsApp_Image_20240429_at_200751_1.jpeg",
  "path": "cases/662f377777b62822a9c78910/
externallmg_1714449633539_WhatsApp_Image_20240429_at_200751_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66306ce185028f369edc3763",
  "name":
"externallmg_1714449633545_WhatsApp_Image_20240429_at_200751.jpeg",
```

```
"path": "cases/662f37777b62822a9c78910/
externallmg_1714449633545_WhatsApp_Image_20240429_at_200751.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66306ce185028f369edc3764",
  "name":
"externallmg_1714449633549_WhatsApp_Image_20240429_at_200755.jpeg",
  "path": "cases/662f37777b62822a9c78910/
externallmg_1714449633549_WhatsApp_Image_20240429_at_200755.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "NANDKUMAR MAHADEV PATIL - Flat No. 405 - Union Bank Of
India ( Gokhivire Vasai Branch ).xlsx",
    "filename": "1714481070949_NANDKUMAR_MAHADEV_PATIL__Flat_No_405__U
nion_Bank_Of_India__Gokhivire_Vasai_Branch_.xlsx",
    "path": "cases/662f37777b62822a9c78910/processingDocuments/1714481070949
_NANDKUMAR_MAHADEV_PATIL__Flat_No_405__Union_Bank_Of_India__Gokhivire
_Vasai_Branch_.xlsx",
    "size": "2802970",
    "createdAt": "Tue Apr 30 2024 18:14:31 GMT+0530 (India Standard Time)",
    "uploadedBy": "64dc7184ccaf1e7b7f637f47"
  }
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "64cde526dc9f3034f3fefa49",
      "role": "FRONTDESK",
      "firstName": "Rashmi",
      "lastName": "Jadhav",
      "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "6630894552e3aa36c81a19eb",
```

```
"note": "Pending for approved plan or OC",
"taskId": "662f395677b62822a9c78afb",
"createdAt": "2024-04-30T06:01:41.147Z"
},
{
  "createdBy": {
    "_id": "64dc7184ccaf1e7b7f637f47",
    "role": "FRONTDESK",
    "firstName": "Binumon",
    "lastName": "Moozhickal",
    "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
  },
  "workType": "RATE_VERIFY",
  "display": true,
  "status": true,
  "_id": "663329d885028f369edcade4",
  "note": "Final Value (Task Reopen)",
  "taskId": "662f395677b62822a9c78afb",
  "createdAt": "2024-05-02T05:51:20.793Z"
}
],
"createdAt": "2024-04-29T06:00:23.966Z",
"updatedAt": "2024-05-02T05:59:24.095Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 405, 4th Floor, Building No 02, Wing - A, Sai
Nagar, Village - Gokhivare , Vasai (East), Taluka - Vasai , District - Palghar , Palghar ,
PIN - 401 208, State - Maharashtra, Country - India",
"updatedBy": "64dc7184ccaf1e7b7f637f47",
"addressForMap": "",
"caseReferredBy": "659ccce98f39506e83489828",
"contactPersonName": "Mr. Rohan Diwale ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Sales Person ",
"siteVisitContactNo": "9324708180",
"landDetails": {
  "holdType": {
```

```
"label": "Free Hold",
"value": "Free_Hold"
},
"leaseDetails": {
  "lessorName": "",
  "lesseeName": "",
  "leasePremium": "",
  "leaseRent": "",
  "leasePeriod": 0,
  "leaseFrom": "",
  "leaseTo": "",
  "remainingLeasePeriod": 0,
  "leaseDate": ""
}
},
"reportGeneratedDate": "Tue Apr 30 2024 17:39:58 GMT+0530 (India Standard Time)",
"siteVisitDate": "2024-04-29",
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + Bathroom + WC",
"carpetTotal": "304.56",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "51.48",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "51.65",
"otherCompositionSaleableTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "391.83",
"finalCarpetArea": "356.21",
"finalSalableArea": "431.01",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "Carpet Area in Sq. Ft. = 305.00\nCup Board Area in Sq. Ft. = 11.00\nFlower Bed Area in Sq. Ft. = 29.00\nDry Balcony Area in Sq. Ft. = 11.00\n\n",
"buildingServicesRate": "2500",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement For Sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 296.87",
"flatRate": "8300",
"landOtherRate": "5800",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
}
```



```
},  
"finalSaleablePercentage": "0"  
}
```

Name	Length	Width	Total
Composition :			
Living Room	9'00"	14'3"	128.25
Kitchen	7'3"	8'9"	63.44
Bathroom	5'00"	4'00"	20.00
WC	3'2"	3'9"	11.87
Bedroom	9'00"	9'00"	81.00
Other Composition :			
Cupboard	7'00"	1'8"	11.67
Flower Bed Area	9'00"	1'7"	14.25
Dry Balcony Area	7'3"	1'7"	11.48