

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b9ff"
    },
    "type": "CREDITOFFICER",
    "_id": "65d31e0addc2ef120ed2adb1",
    "firstName": "Nikita",
    "lastName": "Jagtap",
    "mobileNo": "",
    "workMobileNo": "7304948055",
    "email": "8cord.21117@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "4000000",
    "discussWithPerson": "Nikita",
    "expectedFees": 2000,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b9ff",
  "branchCode": "000220",
  "type": "BRANCH",
  "name": "RASMECCC Panvel",
  "email": "cord.21117@sbi.co.in",
  "mobileNo": "02227572748",
  "alternateMobileNo": "",
  "address": "Shop No 5,Ground Floor,Sharda Terrace, Plot No 65,Sector-11,CBD
Belapur, Navi Mumbai, Taluka & District - Thane, State - Maharashtra, Country - India",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60b7189d2ffdf65bcd65882b",
  "role": "PICKUPPERSON",
  "firstName": "Ravindra",
  "email": "ravindrakasare186@gmail.com",
  "lastName": "Kasare",
  "mobileNo": "9167204055",
  "shortName": "RBK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60b7189d2ffdf65bcd65882b\\
\\profilePhoto_1622701555488_WhatsApp Image 2021-06-03 at 11.46.40 AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "60f9343b45132d6a6bdd96e8",
  "role": "SITEENGINEER",
  "firstName": "Rajesh",
  "email": "rajeshb.ghadi@gmail.com",
  "lastName": "Ghadi",
  "mobileNo": "8652092666",
  "designation": "",
  "shortName": "RHG",
  "workWithDocumentMaker": ""
},
"rateVerifier": null,
"maker": null,
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  {
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
```

```
    "label": "IBBI"
  },
  "_id": "60af80072ffdf65bcd658651",
  "number": "IBBI/RV/07/2018/10366"
},
{
  "title": {
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "18.972879885172457",
  "longitude": "73.02832628877451"
```

```
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.02832628877451,
    18.972879885172457
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "3/05/2024 11:49 am"
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Ulwe",
    "label": true
  }
}
```

```
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "4",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
```

```
"key": "plotNo",
"value": "9",
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Sai Pride",
  "label": false
},
"selectArea": {
  "status": true,
  "name": "Sector",
  "key": "selectArea",
  "value": "153",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
}
```

```
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
```



```
"value": "405",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
```

```
"status": false,
"name": "Postal Code",
"key": "postalCode",
"value": "",
"label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
```

```
"status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalPlastering": {
```

```
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTillingKitchenPlatform": {
"label": "Flooring, Tilling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
```

```
"min": "0.00",
"max": "0.00"
},
"builtUpRateRange": {
  "min": "0.00",
  "max": "0.00"
},
"saleableRateRange": {
  "min": "0.00",
  "max": "0.00"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
```

```
"title": "Superfine finish",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```

```
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"invoices": [],
"paymentIds": [],
"_id": "6634793352e3aa36c81ad38d",
"ownerName": "Bani Amar shringarpure",
"ownerPhoneNo": "9833233006",
"appAddress": "flat no. 505 4th floor sai pride plot no 153 sect sector no. 19 Ulwe ",
"remark": "SSL suhas modak. 9137836491",
"documents": [
  {
    "documentType": {
```



```
    "label": "Agreement For Sale",
    "value": "60ae1254aa6d152c1801b326"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/6634793352e3aa36c81ad38d/document_1714714915916_17147146
97409_Bani_A_shringarpure_sbi_Rasmecc_panvel.pdf",
  "fileName": "document_1714714915916_1714714697409_Bani_A_shringarpure_sbi
_Rasmecc_panvel.pdf",
  "id": "152670",
  "uploadedBy": "60b7189d2ffdf65bcd65882b",
  "createdAt": "Fri May 03 2024 11:12:11 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "008508",
"createdBy": "60b7189d2ffdf65bcd65882b",
"caseHistory": [
  {
    "id": "872544",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri May 03 2024 11:12:11 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Bani Amar shringarpure",
    "phone": "9833233006",
    "ownershipShare": "",
    "email": "",
    "id": "722717"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6635ad6ad018dd60e730e915",
```

```
    "name":
"externallmg_1714793833435_WhatsApp_Image_20240504_at_073531_2.jpeg",
  "path": "cases/6634793352e3aa36c81ad38d/
externallmg_1714793833435_WhatsApp_Image_20240504_at_073531_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6635ad6ad018dd60e730e916",
  "name":
"externallmg_1714793833437_WhatsApp_Image_20240504_at_073532.jpeg",
  "path": "cases/6634793352e3aa36c81ad38d/
externallmg_1714793833437_WhatsApp_Image_20240504_at_073532.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6635ad6ad018dd60e730e917",
  "name":
"externallmg_1714793833440_WhatsApp_Image_20240504_at_073534_1.jpeg",
  "path": "cases/6634793352e3aa36c81ad38d/
externallmg_1714793833440_WhatsApp_Image_20240504_at_073534_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6635ad6ad018dd60e730e918",
  "name":
"externallmg_1714793833444_WhatsApp_Image_20240504_at_073534_2.jpeg",
  "path": "cases/6634793352e3aa36c81ad38d/
externallmg_1714793833444_WhatsApp_Image_20240504_at_073534_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6635ad6ad018dd60e730e919",
  "name":
"externallmg_1714793833448_WhatsApp_Image_20240504_at_073534.jpeg",
  "path": "cases/6634793352e3aa36c81ad38d/
externallmg_1714793833448_WhatsApp_Image_20240504_at_073534.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6635ad6ad018dd60e730e91a",
  "name":
"externallmg_1714793833452_WhatsApp_Image_20240504_at_073535_1.jpeg",
  "path": "cases/6634793352e3aa36c81ad38d/
externallmg_1714793833452_WhatsApp_Image_20240504_at_073535_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6635ad6ad018dd60e730e91b",
  "name":
"externallmg_1714793833455_WhatsApp_Image_20240504_at_073535.jpeg",
  "path": "cases/6634793352e3aa36c81ad38d/
externallmg_1714793833455_WhatsApp_Image_20240504_at_073535.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6635ad6ad018dd60e730e91c",
  "name":
"externallmg_1714793833458_WhatsApp_Image_20240504_at_073550_1.jpeg",
  "path": "cases/6634793352e3aa36c81ad38d/
externallmg_1714793833458_WhatsApp_Image_20240504_at_073550_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6635ad6ad018dd60e730e91d",
  "name":
"externallmg_1714793833461_WhatsApp_Image_20240504_at_073550.jpeg",
  "path": "cases/6634793352e3aa36c81ad38d/
externallmg_1714793833461_WhatsApp_Image_20240504_at_073550.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6635ad6ad018dd60e730e91e",
  "name":
"externallmg_1714793833479_WhatsApp_Image_20240504_at_073551_1.jpeg",
```

```
    "path": "cases/6634793352e3aa36c81ad38d/
externallmg_1714793833479_WhatsApp_Image_20240504_at_073551_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6635ad7767044b6135c9c720",
    "name":
"externallmg_1714793847477_WhatsApp_Image_20240504_at_073551.jpeg",
    "path": "cases/6634793352e3aa36c81ad38d/
externallmg_1714793847477_WhatsApp_Image_20240504_at_073551.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6635ad7767044b6135c9c721",
    "name":
"externallmg_1714793847484_WhatsApp_Image_20240504_at_073553_1.jpeg",
    "path": "cases/6634793352e3aa36c81ad38d/
externallmg_1714793847484_WhatsApp_Image_20240504_at_073553_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6635ad7767044b6135c9c722",
    "name":
"externallmg_1714793847489_WhatsApp_Image_20240504_at_073553_2.jpeg",
    "path": "cases/6634793352e3aa36c81ad38d/
externallmg_1714793847489_WhatsApp_Image_20240504_at_073553_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6635ad7767044b6135c9c723",
    "name":
"externallmg_1714793847491_WhatsApp_Image_20240504_at_073553_3.jpeg",
    "path": "cases/6634793352e3aa36c81ad38d/
externallmg_1714793847491_WhatsApp_Image_20240504_at_073553_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "6635ad7767044b6135c9c724",
  "name":
"externallmg_1714793847493_WhatsApp_Image_20240504_at_073553.jpeg",
  "path": "cases/6634793352e3aa36c81ad38d/
externallmg_1714793847493_WhatsApp_Image_20240504_at_073553.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6635ad7767044b6135c9c725",
  "name":
"externallmg_1714793847497_WhatsApp_Image_20240504_at_073554.jpeg",
  "path": "cases/6634793352e3aa36c81ad38d/
externallmg_1714793847497_WhatsApp_Image_20240504_at_073554.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6635ad7767044b6135c9c726",
  "name":
"externallmg_1714793847500_WhatsApp_Image_20240504_at_073611_1.jpeg",
  "path": "cases/6634793352e3aa36c81ad38d/
externallmg_1714793847500_WhatsApp_Image_20240504_at_073611_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6635ad7767044b6135c9c727",
  "name":
"externallmg_1714793847502_WhatsApp_Image_20240504_at_073611_2.jpeg",
  "path": "cases/6634793352e3aa36c81ad38d/
externallmg_1714793847502_WhatsApp_Image_20240504_at_073611_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6635ad7767044b6135c9c728",
  "name":
"externallmg_1714793847504_WhatsApp_Image_20240504_at_073611.jpeg",
  "path": "cases/6634793352e3aa36c81ad38d/
externallmg_1714793847504_WhatsApp_Image_20240504_at_073611.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6635ad7767044b6135c9c729",
    "name":
"externallmg_1714793847506_WhatsApp_Image_20240504_at_073612.jpeg",
    "path": "cases/6634793352e3aa36c81ad38d/
externallmg_1714793847506_WhatsApp_Image_20240504_at_073612.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6635ad7767044b6135c9c72a",
    "name":
"externallmg_1714793847508_WhatsApp_Image_20240504_at_073613_1.jpeg",
    "path": "cases/6634793352e3aa36c81ad38d/
externallmg_1714793847508_WhatsApp_Image_20240504_at_073613_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6635ad7767044b6135c9c72b",
    "name":
"externallmg_1714793847510_WhatsApp_Image_20240504_at_073613.jpeg",
    "path": "cases/6634793352e3aa36c81ad38d/
externallmg_1714793847510_WhatsApp_Image_20240504_at_073613.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6635ad7767044b6135c9c72c",
    "name":
"externallmg_1714793847512_WhatsApp_Image_20240504_at_073614.jpeg",
    "path": "cases/6634793352e3aa36c81ad38d/
externallmg_1714793847512_WhatsApp_Image_20240504_at_073614.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6635ad7767044b6135c9c72d",
```

```
    "name":
"externallmg_1714793847516_WhatsApp_Image_20240504_at_073615_1.jpeg",
  "path": "cases/6634793352e3aa36c81ad38d/
externallmg_1714793847516_WhatsApp_Image_20240504_at_073615_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6635ad7767044b6135c9c72e",
  "name":
"externallmg_1714793847521_WhatsApp_Image_20240504_at_073615.jpeg",
  "path": "cases/6634793352e3aa36c81ad38d/
externallmg_1714793847521_WhatsApp_Image_20240504_at_073615.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6635ad7767044b6135c9c72f",
  "name":
"externallmg_1714793847526_WhatsApp_Image_20240504_at_073630_1.jpeg",
  "path": "cases/6634793352e3aa36c81ad38d/
externallmg_1714793847526_WhatsApp_Image_20240504_at_073630_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6635ad7767044b6135c9c730",
  "name":
"externallmg_1714793847531_WhatsApp_Image_20240504_at_073630.jpeg",
  "path": "cases/6634793352e3aa36c81ad38d/
externallmg_1714793847531_WhatsApp_Image_20240504_at_073630.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6635ad7767044b6135c9c731",
  "name":
"externallmg_1714793847536_WhatsApp_Image_20240504_at_073531_1.jpeg",
  "path": "cases/6634793352e3aa36c81ad38d/
externallmg_1714793847536_WhatsApp_Image_20240504_at_073531_1.jpeg",
  "orientation": "portrait"
},
}
```

```

{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6635ad7767044b6135c9c732",
  "name":
"externallmg_1714793847539_WhatsApp_Image_20240504_at_073531.jpeg",
  "path": "cases/6634793352e3aa36c81ad38d/
externallmg_1714793847539_WhatsApp_Image_20240504_at_073531.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-05-03T05:42:11.284Z",
"updatedAt": "2024-05-04T03:37:27.692Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 405, 4th Floor, Sai Pride, Plot No. 9, Sector 153,
Village - Ulwe",
"updatedBy": "6006d4ce5080a310ac1fdfc2",
"addressForMap": "",
"caseReferredBy": "60b7189d2ffdf65bcd65882b",
"contactPersonName": "Bani Amar shringarpure",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9833233006"
}

```

| Name          | Length | Width | Total |
|---------------|--------|-------|-------|
| Composition : |        |       |       |



Other  
Composition :

---