

```
{
  "typeOfReport": {
    "value": "Amalgamated_Flats",
    "label": "Amalgamated Flats"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b8dc"
    },
    "type": "CREDITOFFICER",
    "_id": "63d11f66be948726cc141b31",
    "email": "resham.kulkarni@cosmosbank.in",
    "firstName": "Resham ",
    "mobileNo": "9987780572",
    "workMobileNo": "9987780572",
    "lastName": "Kulkarni"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "6418456a96b58848585f8cb2",
  "name": "Thane",
  "email": "thane@vastukala.com",
  "phone": "1234567890",
  "address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
  "city": "Thane",
  "shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1820",
  "type": "BANK",
  "name": "Cosmos Bank",
  "displayName": "Cosmos Bank",
  "initial": "CB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b8dc",
  "branchCode": "000005",
  "type": "BRANCH",
  "name": "Naupada",
  "email": "thane@cosmosbank.in",
  "mobileNo": "022-25345923",
  "alternateMobileNo": "",
  "address": "Kusumanjali, Opp. Devdhar Hospital, Naupada, Thane (West) - 400 602,
State - Maharashtra, Country - India.\r\n",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land & Building / Immovable Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f919bff3dd69653a5926b8",
  "zoneName": "Mumbai & Aurangabad Zone"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "627222afafd7d55eddeddd82",
  "role": "FRONTDESK",
  "firstName": "Pratibha",
  "email": "shilvanta_pratibha@yahoo.co.in",
  "lastName": "Shilvantha",
  "mobileNo": "9821518537",
  "shortName": "PS",
  "workWithDocumentMaker": "60f915d3f3dd69653a592199",
  "profilePhoto": "users/627222afafd7d55eddeddd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "64e5a649daae6a1c98101989",
  "role": "SITEENGINEER",
  "firstName": "Sameer",
  "email": "sameeryp2010@gmail.com",
  "lastName": "Parab",
  "mobileNo": "8291009567",
  "designation": "Site Engineer",
  "shortName": "Sameer",
  "workWithDocumentMaker": "62ea09ea4e679b264caf07d7"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "64cde526dc9f3034f3fefa49",
  "role": "FRONTDESK",
  "firstName": "Rashmi",
  "email": "rashmijadhav14feb@gmail.com",
  "lastName": "Jadhav",
  "mobileNo": "7738144625",
  "designation": "Back Office Coordination",
  "shortName": "RJ",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627222afafd7d55eddeddd82",
  "role": "FRONTDESK",
  "firstName": "Pratibha",
  "email": "shilvanta_pratibha@yahoo.co.in",
  "lastName": "Shilvantha",
```

```
    "mobileNo": "9821518537",
    "designation": "",
    "shortName": "PS",
    "workWithDocumentMaker": "60f915d3f3dd69653a592199",
    "profilePhoto": "users/627222afafd7d55eddedd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
  },
  "checker": null,
  "valuers": []
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.149240897283267",
  "longitude": "73.23921867769417"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-05-04",
      "remark": ""
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
```

```
"status": true,
"name": "State",
"key": "state",
"value": "Maharashtra",
"label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Mankivali",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "1",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "2",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
```

```
"label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Ambernath",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "PANVELKAR ESTATE OXFORD PHASE I",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
```

```
"name": "Street 2",
"key": "street2",
"value": "",
"label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "45/2(P), 46(2), 47, 49/4, 9,11,12,13 & 14, 50",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
}
```

```
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "103",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
```



```
"key": "SRO",
"value": "",
"label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 421 503",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
```

```
"monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
    "isHideFloor": true,
    "status": true
  }
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
  }
}
```

```
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
```

```
"value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"invoices": [],
"paymentIds": [],
"_id": "6635d52a67044b6135c9e8ff",
"ownerName": "Mr. Manan Chandresh Vora ",
"ownerPhoneNo": "0000000000",
"fullAddress": "Residential Flat No. 103, 1st Floor, Building No 2, PANVELKAR
ESTATE OXFORD PHASE I, Village - Mankivali, Taluka - Ambernath, District - Thane,
PIN Code - 421 503, State - Maharashtra, India",
"remark": "",
"documents": [
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f8",
    "label": "Draft Agreement"
  },
  "inputs": {
    "from": {
      "value": "Promoter",
      "label": "Promoter"
    },
    "Promoter": "M/s. Panvelkar Infrastructures Pvt. Ltd.",
    "to": {
      "value": "purchaser",
      "label": "purchaser"
    },
    "purchaser": "Mr. Manan Chandresh Vora"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "403294",
  "path": "cases/6635d52a67044b6135c9e8ff/
document_1714803999851_Flat_sale_Draft_for_Rera_103.pdf",
  "fileName": "document_1714803999851_Flat_sale_Draft_for_Rera_103.pdf"
},
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
```



```
"label": "RERA Certificate"
},
"inputs": {
  "documentDate": "28/11/2023",
  "nameOfApprovingAuthority": {
    "value": "Maharashtra_Real_Estate_Regulatory_Authority",
    "label": "Maharashtra Real Estate Regulatory Authority"
  },
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "P51700018929 "
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1715251684597_RERA.pdf",
"path": "cases/6635d52a67044b6135c9e8ff/document_1715251684597_RERA.pdf",
"id": "222120",
"uploadedBy": "627222afafd7d55eddedddd82",
"createdAt": "Thu May 09 2024 16:20:14 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "21/12/2017",
    "nameOfApprovingAuthority": {
      "value": "Kulgaon_Badlapur_Municipal_Council",
      "label": "Kulgaon Badlapur Municipal Council"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "KBNP / NRV / BP / 9605 / 2017 – 2018 / Unik No. 170 "
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1715251758237_1715234671783_CC.pdf",
  "path": "cases/6635d52a67044b6135c9e8ff/
document_1715251758237_1715234671783_CC.pdf",
  "id": "470466",
  "uploadedBy": "627222afafd7d55eddedddd82",
```

```
"createdAt": "Thu May 09 2024 16:20:14 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1277aa6d152c1801b3cc",
    "label": "Approved Building Plan"
  },
  "inputs": {
    "documentDate": "21/12/2017",
    "nameOfApprovingAuthority": {
      "value": "Kulgaon_Badlapur_Municipal_Council",
      "label": "Kulgaon Badlapur Municipal Council"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "KBNP / NRV / BP / 9605 - 170 "
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1715251814273_136296.pdf",
"path": "cases/6635d52a67044b6135c9e8ff/
document_1715251814273_136296.pdf",
"id": "881817",
"uploadedBy": "627222afafd7d55eddeddd82",
"createdAt": "Thu May 09 2024 16:20:14 GMT+0530 (India Standard Time)"
}
],
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"caseNumber": "008539",
"createdBy": "627222afafd7d55eddeddd82",
"caseHistory": [
  {
    "id": "341385",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Sat May 04 2024 11:56:50 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Manan Chandresh Vora ",
```

```
    "phone": "0000000000",
    "ownershipShare": "",
    "email": "",
    "id": "138525"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66360c4967044b6135ca1755",
    "name": "externalImg_1714818080342_1714817854228_image_0.jpeg",
    "path": "cases/6635d52a67044b6135c9e8ff/
externalImg_1714818080342_1714817854228_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66360c4967044b6135ca1756",
    "name": "externalImg_1714818091681_1714817854228_image_1.jpeg",
    "path": "cases/6635d52a67044b6135c9e8ff/
externalImg_1714818091681_1714817854228_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66360c4967044b6135ca1757",
    "name": "externalImg_1714818101554_1714817854228_image_2.jpeg",
    "path": "cases/6635d52a67044b6135c9e8ff/
externalImg_1714818101554_1714817854228_image_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66360c4967044b6135ca1758",
```

```
    "name": "externallmg_1714818110544_1714817854228_image_3.jpeg",
    "path": "cases/6635d52a67044b6135c9e8ff/
externallmg_1714818110544_1714817854228_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66360c4967044b6135ca1759",
    "name": "externallmg_1714818112917_1714817854228_image_4.jpeg",
    "path": "cases/6635d52a67044b6135c9e8ff/
externallmg_1714818112917_1714817854228_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66360c4967044b6135ca175a",
    "name": "externallmg_1714818116473_1714817854228_image_5.jpeg",
    "path": "cases/6635d52a67044b6135c9e8ff/
externallmg_1714818116473_1714817854228_image_5.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66360c4967044b6135ca175b",
    "name": "externallmg_1714818118016_1714817854228_image_6.jpeg",
    "path": "cases/6635d52a67044b6135c9e8ff/
externallmg_1714818118016_1714817854228_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66360c4967044b6135ca175c",
    "name": "externallmg_1714818119238_1714817854228_image_7.jpeg",
    "path": "cases/6635d52a67044b6135c9e8ff/
externallmg_1714818119238_1714817854228_image_7.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66360c4967044b6135ca175d",
    "name": "externallmg_1714818119458_1714817854228_image_8.jpeg",
```

```
    "path": "cases/6635d52a67044b6135c9e8ff/
externallmg_1714818119458_1714817854228_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66360c4967044b6135ca175e",
    "name": "externallmg_1714818119593_1714817854228_image_9.jpeg",
    "path": "cases/6635d52a67044b6135c9e8ff/
externallmg_1714818119593_1714817854228_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66360c4967044b6135ca175f",
    "name": "externallmg_1714818119693_1714817854228_image_10.jpeg",
    "path": "cases/6635d52a67044b6135c9e8ff/
externallmg_1714818119693_1714817854228_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66360c4967044b6135ca1760",
    "name": "externallmg_1714818119743_1714817854228_image_11.jpeg",
    "path": "cases/6635d52a67044b6135c9e8ff/
externallmg_1714818119743_1714817854228_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66360c4967044b6135ca1762",
    "name": "externallmg_1714818120333_1714817854228_image_13.jpeg",
    "path": "cases/6635d52a67044b6135c9e8ff/
externallmg_1714818120333_1714817854228_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66360c4767044b6135ca173f",
    "name": "externallmg_1714818022030_1714817802980_image_0.jpeg",
    "path": "cases/6635d52a67044b6135c9e8ff/
externallmg_1714818022030_1714817802980_image_0.jpeg",
```

```
"orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66360c4767044b6135ca1740",
  "name": "externallmg_1714818076428_1714817802980_image_1.jpeg",
  "path": "cases/6635d52a67044b6135c9e8ff/
externallmg_1714818076428_1714817802980_image_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66360c4767044b6135ca1741",
  "name": "externallmg_1714818095920_1714817802980_image_2.jpeg",
  "path": "cases/6635d52a67044b6135c9e8ff/
externallmg_1714818095920_1714817802980_image_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66360c4767044b6135ca1742",
  "name": "externallmg_1714818115778_1714817802980_image_3.jpeg",
  "path": "cases/6635d52a67044b6135c9e8ff/
externallmg_1714818115778_1714817802980_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66360c4767044b6135ca1743",
  "name": "externallmg_1714818118678_1714817802980_image_4.jpeg",
  "path": "cases/6635d52a67044b6135c9e8ff/
externallmg_1714818118678_1714817802980_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66360c4767044b6135ca1744",
  "name": "externallmg_1714818118973_1714817802980_image_5.jpeg",
  "path": "cases/6635d52a67044b6135c9e8ff/
externallmg_1714818118973_1714817802980_image_5.jpeg",
  "orientation": "portrait"
}
```

```
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "66360c5967044b6135ca1792",
      "name": "externalImg_1714818137269_1714817923047_image_0.jpeg",
      "path": "cases/6635d52a67044b6135c9e8ff/
externalImg_1714818137269_1714817923047_image_0.jpeg",
      "orientation": "portrait"
    }
  ],
  "externalDocuments": [],
  "processingDocuments": [
    {
      "originalname": "Approved plan.jpeg",
      "filename": "1715234671750_Aproved_plan.jpeg",
      "path": "cases/6635d52a67044b6135c9e8ff/
processingDocuments/1715234671750_Aproved_plan.jpeg",
      "size": "136296",
      "createdAt": "Thu May 09 2024 11:34:31 GMT+0530 (India Standard Time)",
      "uploadedBy": "64cde526dc9f3034f3fefa49"
    },
    {
      "originalname": "Calculation Sheet NEW COSMOS.xlsx",
      "filename": "1715234671757_Calculation_Sheet_NEW_COSMOS.xlsx",
      "path": "cases/6635d52a67044b6135c9e8ff/
processingDocuments/1715234671757_Calculation_Sheet_NEW_COSMOS.xlsx",
      "size": "1407124",
      "createdAt": "Thu May 09 2024 11:34:31 GMT+0530 (India Standard Time)",
      "uploadedBy": "64cde526dc9f3034f3fefa49"
    },
    {
      "originalname": "CC.pdf",
      "filename": "1715234671783_CC.pdf",
      "path": "cases/6635d52a67044b6135c9e8ff/
processingDocuments/1715234671783_CC.pdf",
      "size": "491751",
      "createdAt": "Thu May 09 2024 11:34:31 GMT+0530 (India Standard Time)",
      "uploadedBy": "64cde526dc9f3034f3fefa49"
    },
    {
      "originalname": "P51700018929.pdf",
      "filename": "1715234671813_P51700018929.pdf",
      "path": "cases/6635d52a67044b6135c9e8ff/
processingDocuments/1715234671813_P51700018929.pdf",
      "size": "718469",
```

```
"createdAt": "Thu May 09 2024 11:34:31 GMT+0530 (India Standard Time)",
"uploadedBy": "64cde526dc9f3034f3fefa49"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
{
  "createdBy": {
    "_id": "64cde526dc9f3034f3fefa49",
    "role": "FRONTDESK",
    "firstName": "Rashmi",
    "lastName": "Jadhav",
    "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
  },
  "workType": "RATE_VERIFY",
  "display": true,
  "status": true,
  "_id": "6638726ed34acf0916e1a6be",
  "note": "Required approved plan",
  "taskId": "6635d544a98105612e6e4ed2",
  "createdAt": "2024-05-06T06:02:22.692Z"
},
{
  "createdBy": {
    "_id": "64cde526dc9f3034f3fefa49",
    "role": "FRONTDESK",
    "firstName": "Rashmi",
    "lastName": "Jadhav",
    "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
  },
  "workType": "RATE_VERIFY",
  "display": true,
  "status": true,
  "_id": "663b20fd0268b808d492610d",
  "note": "Value given for confirmation",
  "taskId": "6635d544a98105612e6e4ed2",
  "createdAt": "2024-05-08T06:51:41.647Z"
}
],
"createdAt": "2024-05-04T06:26:50.603Z",
"updatedAt": "2024-05-09T10:50:14.374Z",
"__v": 0,
"updatedBy": "627222afafd7d55eddedd82",
```



"addressForMap": "",  
"caseReferredBy": "64abdb2806d6ec174986d16b",  
"contactPersonName": "Mr. Manan Chandresh Vora ",  
"email": "",  
"isExternal": "false",  
"isUrgent": "false",  
"ownershipShare": "",  
"proposePurchaserName": "",  
"purchaseValueAsPerDocument": "",  
"relationWithOwner": "self",  
"siteVisitContactNo": "0000000000",  
"siteVisitDate": "2024-05-04"

}

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			