

```
{
  "typeOfReport": {
    "value": "Amalgamated_Flats",
    "label": "Amalgamated Flats"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b8dc"
    },
    "type": "CREDITOFFICER",
    "_id": "63d11f66be948726cc141b37",
    "email": "komal.vanjari@cosmosbank.in",
    "firstName": "Komal ",
    "mobileNo": "8080342307",
    "workMobileNo": "8080342307",
    "lastName": "vanjari"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "6418456a96b58848585f8cb2",
  "name": "Thane",
  "email": "thane@vastukala.com",
  "phone": "1234567890",
  "address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
  "city": "Thane",
  "shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1820",
  "type": "BANK",
  "name": "Cosmos Bank",
  "displayName": "Cosmos Bank",
  "initial": "CB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b8dc",
  "branchCode": "000005",
  "type": "BRANCH",
  "name": "Naupada",
  "email": "thane@cosmosbank.in",
  "mobileNo": "022-25345923",
  "alternateMobileNo": "",
  "address": "Kusumanjali, Opp. Devdhar Hospital, Naupada, Thane (West) - 400 602,
State - Maharashtra, Country - India.\r\n",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land & Building / Immovable Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f919bff3dd69653a5926b8",
  "zoneName": "Mumbai & Aurangabad Zone"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "656aa949cebbe1714411d21b",
  "role": "FRONTDESK",
  "firstName": "Priyanka",
  "email": "thane@vastukala.org",
  "lastName": "Pawar",
  "mobileNo": "8928414480",
  "shortName": "PCP",
  "workWithDocumentMaker": "627222afafd7d55eddeddd82"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "64e5a649daae6a1c98101989",
  "role": "SITEENGINEER",
  "firstName": "Sameer",
  "email": "sameeryp2010@gmail.com",
  "lastName": "Parab",
  "mobileNo": "8291009567",
  "designation": "Site Engineer",
  "shortName": "Sameer",
  "workWithDocumentMaker": "62ea09ea4e679b264caf07d7"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "64cde526dc9f3034f3fefa49",
  "role": "FRONTDESK",
  "firstName": "Rashmi",
  "email": "rashmijadhav14feb@gmail.com",
  "lastName": "Jadhav",
  "mobileNo": "7738144625",
  "designation": "Back Office Coordination",
  "shortName": "RJ",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627222afafd7d55eddeddd82",
  "role": "FRONTDESK",
  "firstName": "Pratibha",
  "email": "shilvanta_pratibha@yahoo.co.in",
  "lastName": "Shilvantha",
  "mobileNo": "9821518537",
  "designation": ""
}
```

```
    "shortName": "PS",
    "workWithDocumentMaker": "60f915d3f3dd69653a592199",
    "profilePhoto": "users/627222afafd7d55eddedd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
  },
  "checker": null,
  "valuers": []
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.150280491878892",
  "longitude": "73.23783114552498"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.23783114552498,
    19.150280491878892
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-05-07",
      "remark": "This Flat Ready to move "
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
```

```
"key": "state",
"value": "Maharashtra",
"label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Mankivali",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "1",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
}
```

```
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Ambernath",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "PANVELKAR ESTATE OXFORD PHASE I",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
```

```
"value": "",
"label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "45/2(P), 46(2), 47, 49/4, 9,11,12,13 & 14, 50",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
```

```
"status": false,
"name": "CTS No.",
"key": "CTSNo",
"value": "",
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "104",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
```



```
"label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 421 503",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
}
```

```
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
```

```
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
}
```

```
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
```

```
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
}
```

```
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"invoices": [],
"paymentIds": [],
"_id": "6639b0f223ff7a08d33f8d6b",
"ownerName": "Mr. Manan Chandresh Vora ",
"ownerPhoneNo": "9096741909",
"fullAddress": "Residential Flat No. 104, 1st Floor, PANVELKAR ESTATE OXFORD
PHASE I, Village - Mankivali, Taluka - Ambernath, District - Thane, PIN Code - 421
503, State - Maharashtra, India",
"remark": "This Flat Ready to move ",
"documents": [
  {
    "documentType": {
      "value": "60ae1256aa6d152c1801b330",
      "label": "Draft Agreement for sale"
    },
    "inputs": {
      "from": {
        "value": "Promoter",
        "label": "Promoter"
      },
      "Promoter": "M/s Panvelkar Infrastructures Pvt. Ltd.",
      "to": {
        "value": "purchaser",
        "label": "purchaser"
      },
      "purchaser": "Mr. Manan Chandresh Vora"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "fileName": "document_1715056849107_Flat_sale_Draft_for_Rera_104.pdf",
    "path": "cases/6639b0f223ff7a08d33f8d6b/
document_1715056849107_Flat_sale_Draft_for_Rera_104.pdf",
    "id": "838427",
    "uploadedBy": "656aa949cebbe1714411d21b",
    "createdAt": "Tue May 07 2024 10:11:22 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae1247aa6d152c1801b2ea",
```



```
"label": "Commencement Certificate"
},
"inputs": {
  "documentDate": "21/12/2017",
  "nameOfApprovingAuthority": {
    "value": "Kulgaon_Badlapur_Municipal_Council",
    "label": "Kulgaon Badlapur Municipal Council"
  },
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "KBNP / NRV / BP / 9605 / 2017 – 2018 / Unik No. 170 "
},
"isHardCopy": false,
"displayStatus": true,
"id": "415158",
"path": "cases/6639b0f223ff7a08d33f8d6b/document_1715056865769_1_Commencement_Certificates___NA_Order_for_plotted_development__20240504T121630025.pdf",
  "fileName": "document_1715056865769_1_Commencement_Certificates___NA_Order_for_plotted_development__20240504T121630025.pdf"
},
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
    "label": "RERA Certificate"
  },
  "inputs": {
    "documentDate": "28/11/2023",
    "nameOfApprovingAuthority": {
      "value": "Maharashtra_Real_Estate_Regulatory_Authority",
      "label": "Maharashtra Real Estate Regulatory Authority"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "P51700018929"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "107134",
  "path": "cases/6639b0f223ff7a08d33f8d6b/document_1715056875824_P51700018929.pdf",
  "fileName": "document_1715056875824_P51700018929.pdf"
}
```

```
},
{
  "documentType": {
    "value": "60ae1277aa6d152c1801b3cc",
    "label": "Approved Building Plan"
  },
  "inputs": {
    "documentDate": "21/12/2017",
    "nameOfApprovingAuthority": {
      "value": "Kulgaon_Badlapur_Municipal_Council",
      "label": "Kulgaon Badlapur Municipal Council"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "KBNP / NRV / BP / 9605 - 170 "
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1715254567593_136296.pdf",
  "path": "cases/6639b0f223ff7a08d33f8d6b/document_1715254567593_136296.pdf",
  "id": "353792",
  "uploadedBy": "627222afafd7d55eddeddd82",
  "createdAt": "Thu May 09 2024 17:06:07 GMT+0530 (India Standard Time)"
}
],
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"caseNumber": "008568",
"createdBy": "656aa949cebbe1714411d21b",
"caseHistory": [
  {
    "id": "982826",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue May 07 2024 10:11:22 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Manan Chandresh Vora ",
    "phone": "9096741909",
    "ownershipShare": ""
  }
]
```

```
    "email": "",
    "id": "119975"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6639d7d423ff7a08d33fb609",
    "name": "externallmg_1715066834002_1715066595519_image_0.jpeg",
    "path": "cases/6639b0f223ff7a08d33f8d6b/
externallmg_1715066834002_1715066595519_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6639d7d423ff7a08d33fb60a",
    "name": "externallmg_1715066834365_1715066595519_image_1.jpeg",
    "path": "cases/6639b0f223ff7a08d33f8d6b/
externallmg_1715066834365_1715066595519_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6639d7d423ff7a08d33fb60b",
    "name": "externallmg_1715066834444_1715066595519_image_2.jpeg",
    "path": "cases/6639b0f223ff7a08d33f8d6b/
externallmg_1715066834444_1715066595519_image_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6639d7d423ff7a08d33fb60c",
    "name": "externallmg_1715066834535_1715066595519_image_3.jpeg",
    "path": "cases/6639b0f223ff7a08d33f8d6b/
externallmg_1715066834535_1715066595519_image_3.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6639d7d423ff7a08d33fb60d",
  "name": "externallmg_1715066834569_1715066595519_image_4.jpeg",
  "path": "cases/6639b0f223ff7a08d33f8d6b/
externallmg_1715066834569_1715066595519_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6639d7d423ff7a08d33fb60e",
  "name": "externallmg_1715066834680_1715066595519_image_5.jpeg",
  "path": "cases/6639b0f223ff7a08d33f8d6b/
externallmg_1715066834680_1715066595519_image_5.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6639d7d423ff7a08d33fb60f",
  "name": "externallmg_1715066834969_1715066595519_image_6.jpeg",
  "path": "cases/6639b0f223ff7a08d33f8d6b/
externallmg_1715066834969_1715066595519_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6639d7d423ff7a08d33fb610",
  "name": "externallmg_1715066834980_1715066595519_image_7.jpeg",
  "path": "cases/6639b0f223ff7a08d33f8d6b/
externallmg_1715066834980_1715066595519_image_7.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6639d7d423ff7a08d33fb611",
  "name": "externallmg_1715066835010_1715066595519_image_8.jpeg",
  "path": "cases/6639b0f223ff7a08d33f8d6b/
externallmg_1715066835010_1715066595519_image_8.jpeg",
  "orientation": "portrait"
}
```

```
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6639d7d423ff7a08d33fb612",
    "name": "externallmg_1715066835041_1715066595520_image_9.jpeg",
    "path": "cases/6639b0f223ff7a08d33f8d6b/
externallmg_1715066835041_1715066595520_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6639d7d423ff7a08d33fb613",
    "name": "externallmg_1715066835341_1715066595520_image_10.jpeg",
    "path": "cases/6639b0f223ff7a08d33f8d6b/
externallmg_1715066835341_1715066595520_image_10.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6639d7d423ff7a08d33fb614",
    "name": "externallmg_1715066835357_1715066595520_image_11.jpeg",
    "path": "cases/6639b0f223ff7a08d33f8d6b/
externallmg_1715066835357_1715066595520_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6639d7d423ff7a08d33fb615",
    "name": "externallmg_1715066835414_1715066595520_image_12.jpeg",
    "path": "cases/6639b0f223ff7a08d33f8d6b/
externallmg_1715066835414_1715066595520_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6639d7d423ff7a08d33fb616",
    "name": "externallmg_1715066835616_1715066595520_image_13.jpeg",
    "path": "cases/6639b0f223ff7a08d33f8d6b/
externallmg_1715066835616_1715066595520_image_13.jpeg",
    "orientation": "portrait"
  },
  },
```

```
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6639d79cd34acf0916e21d7e",
  "name": "externalimg_1715066779948_1715066568265_image_0.jpeg",
  "path": "cases/6639b0f223ff7a08d33f8d6b/
externalimg_1715066779948_1715066568265_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6639d79cd34acf0916e21d7f",
  "name": "externalimg_1715066780386_1715066568266_image_1.jpeg",
  "path": "cases/6639b0f223ff7a08d33f8d6b/
externalimg_1715066780386_1715066568266_image_1.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "Approved plan.jpeg",
    "filename": "1715234611943_Aproved_plan.jpeg",
    "path": "cases/6639b0f223ff7a08d33f8d6b/
processingDocuments/1715234611943_Aproved_plan.jpeg",
    "size": "136296",
    "createdAt": "Thu May 09 2024 11:33:32 GMT+0530 (India Standard Time)",
    "uploadedBy": "64cde526dc9f3034f3fefa49"
  },
  {
    "originalname": "Calculation Sheet NEW COSMOS.xlsx",
    "filename": "1715234611949_Calculation_Sheet_NEW_COSMOS.xlsx",
    "path": "cases/6639b0f223ff7a08d33f8d6b/
processingDocuments/1715234611949_Calculation_Sheet_NEW_COSMOS.xlsx",
    "size": "1407124",
    "createdAt": "Thu May 09 2024 11:33:32 GMT+0530 (India Standard Time)",
    "uploadedBy": "64cde526dc9f3034f3fefa49"
  },
  {
    "originalname": "CC.pdf",
    "filename": "1715234611980_CC.pdf",
    "path": "cases/6639b0f223ff7a08d33f8d6b/
processingDocuments/1715234611980_CC.pdf",
    "size": "491751",
    "createdAt": "Thu May 09 2024 11:33:32 GMT+0530 (India Standard Time)",
```

```
"uploadedBy": "64cde526dc9f3034f3fefa49"
},
{
  "originalname": "P51700018929.pdf",
  "filename": "1715234611988_P51700018929.pdf",
  "path": "cases/6639b0f223ff7a08d33f8d6b/
processingDocuments/1715234611988_P51700018929.pdf",
  "size": "718469",
  "createdAt": "Thu May 09 2024 11:33:32 GMT+0530 (India Standard Time)",
  "uploadedBy": "64cde526dc9f3034f3fefa49"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "64cde526dc9f3034f3fefa49",
      "role": "FRONTDESK",
      "firstName": "Rashmi",
      "lastName": "Jadhav",
      "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "6639d6b123ff7a08d33fb447",
    "note": "Required Approved Plan ",
    "taskId": "6639b0fd0268b808d491a90a",
    "createdAt": "2024-05-07T07:22:25.260Z"
  },
  {
    "createdBy": {
      "_id": "64cde526dc9f3034f3fefa49",
      "role": "FRONTDESK",
      "firstName": "Rashmi",
      "lastName": "Jadhav",
      "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "663b20e123ff7a08d3401604",
    "note": "Value given for confirmation",
```

```

    "taskId": "6639b0fd0268b808d491a90a",
    "createdAt": "2024-05-08T06:51:13.775Z"
  }
],
"createdAt": "2024-05-07T04:41:22.593Z",
"updatedAt": "2024-05-09T11:36:07.718Z",
"__v": 0,
"updatedBy": "627222afafd7d55eddedd82",
"addressForMap": "",
"caseReferredBy": "64abdb2806d6ec174986d16b",
"contactPersonName": "Mr. Manan Chandresh Vora ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9096741909",
"siteVisitDate": "2024-05-07"
}

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			