

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "6454ca2514bbf555ec469814"
    },
    "type": "CREDITOFFICER",
    "_id": "6454ca2514bbf555ec469819",
    "firstName": "Deepak Kumar",
    "lastName": "Aarya",
    "mobileNo": "",
    "workMobileNo": "7350000012",
    "email": "ubin0561380@unionbankofindia.bank"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "4000000",
    "discussWithPerson": "Deepak Kumar",
    "expectedFees": 2000,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1828",
  "type": "BANK",
  "name": "Union Bank of India",
  "displayName": "Union Bank of India",
  "initial": "UBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "6454ca2514bbf555ec469814",
  "name": "Gokhivire Vasai Branch\t",
  "branchCode": "",
  "mobileNo": "2502464808\t",
  "alternateMobileNo": "",
  "email": "ubin0561380@unionbankofindia.bank",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Surucha Mulapat Residency, Ground Floor, Pinto Travelles Campus,
Gokhivire, Vasai East\n"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f93be845132d6a6bdda676",
  "zoneName": "MUMBAI SOUTH"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
"_id": "659ccce98f39506e83489828",
"role": "DELIVERYPERSON",
"firstName": "Amit",
"email": "amitsalvi2909@gmail.com",
"lastName": "Salvi",
"mobileNo": "7499830659",
"shortName": "Amit",
"workWithDocumentMaker": "",
"profilePhoto": "users/659ccce98f39506e83489828/
profilePhoto_1712385426269_image.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "6401b61f0e28255fb44e636a",
"role": "SITEENGINEER",
"firstName": "Sanket",
"email": "ksanket7414@yahoo.com",
"lastName": "Karalkar",
"mobileNo": "8080582858",
"designation": "",
"shortName": "SAK",
"workWithDocumentMaker": ""
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "60eeaeddf3dd69653a581316",
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Shyam",
"email": "shyam@vastukala.org",
"lastName": "Kajvilkar",
"mobileNo": "9765074720",
"designation": "",
"shortName": "SK",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Sh Yam_Photo.jpg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "64d09914dc9f3034f3008833",
"role": "SITEENGINEER+MAKAR",
"firstName": "Meetal",
"email": "meetalirasal@gmail.com",
"lastName": "Rasal",
"mobileNo": "7397882283",
"designation": "Junior Architect",
```

```
"shortName": "MR",
"workWithDocumentMaker": ""
},
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      },
      {
        "title": {
          "value": "FIIV",
          "label": "FIIV"
        },
        "_id": "60af80072ffdf65bcd658652",
        "number": "CAT-I-F-1763"
      }
    ],
    {
      "title": {
        "value": "Chartered_Engineer",
        "label": "Chartered Engineer"
      },
      "_id": "60af80072ffdf65bcd658653",
      "number": "AM161706-3"
    },
    {
      "title": {
```

```
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
  "latitude": "19.403337630826456",
  "longitude": "72.84813430295144"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.84813430295144,
    19.403337630826456
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "9/05/2024 11:54 am"
    }
  ]
},
"visitedDate": [],
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
}
```

```
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Gokhivire",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "1",
    "label": false
  },
  "buildingNo": {
    "status": true,
    "name": "Building No",
    "key": "buildingNo",
    "value": "2",
    "label": true
  },
  "district": {
    "status": false,
    "name": "District",
    "key": "district",
```

```
"value": "",
"label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Vasai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Wonder Residancey",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
```

```
"status": true,
"name": "Street 1",
"key": "street1",
"value": "Fatherwadi Naka",
"label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Near H P Petrol Pump",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "C",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
```



```
"label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "103",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
```

```
"name": "Mouza",
"key": "mouza",
"value": "",
"label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Vasai East",
  "label": false
}
},
"general": {
  "ownership": {
    "value": "sole_ownership",
    "label": "sole ownership"
  }
},
```

```
"populationClassList": {
  "value": "MiddleClass",
  "label": "Middle Class"
},
"populationGroupList": {
  "value": "Urban",
  "label": "Urban"
},
"townplanApprovedByList": {
  "value": "Vasai_Virar_City_Municipal_Corporation",
  "label": "Vasai Virar City Municipal Corporation"
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Omkar Petrol Pump and Road",
  "west": "Indian Oil Petrol pump",
  "south": "Open Plot",
  "east": "Open plot"
},
"asPerDocumentAgreement": {
  "north": "Details not available ",
  "west": "Details not available ",
  "south": "Details not available ",
  "east": "Details not available "
},
"unitBoundaries": {
  "asPerActual": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "asPerDocument": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "Copy of Approved Building Plan No. VVCMC / OCC /
```

BP / VP 416 / 03 / 2020- 21 dated 04/09/2020 issued by Vasai Virar City Municipal Corporation",

```
"approvePlanVerified": "Yes",
"empanelledOfApprovePlan": "No",
"unauthorizedConstruction": ""
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Stilt / Open Car parking",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "2020",
```

```
"fullDate": "1/1/2020"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C.",
  "label": "R.C.C. Framed"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Designed_as_per_I.S._codes",
  "label": "Designed as per I.S. codes"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
}
```

```
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "0",
  "label": "No"
},
"provisionOfFirefighting": {
  "value": "0",
  "label": "No"
},
"groundStilt": {
  "value": "stilt",
  "label": "Stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "56",
"ageOfBuilding": "4",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "7",
"flatFloorNo": "1",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "8"
},
"finalPlinthArea": {
  "area": "499.56",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
```

```
"finalLatLng": {
  "coordinates": []
},
"locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
```



```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0.00",
  "selectedBuildUpValue": "454.15",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
```

```
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  }
}
```

```
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
{others": {
"title": "Others / Car Parking",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
totalValues": {
"title": "Total",
"quantity": "",
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
taskStatus": {
"SITE_INSPECTION": false,
"RATE_VERIFY": false,
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
createCase": "false",
type": "CASE",
leadType": {
"label": "Lead",
"value": "LEAD"
},
siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "499.56",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
```

```
"invoices": [],
"paymentIds": [],
"_id": "663c69b11c6321090f29d58a",
"ownerName": "MR. MAHESH MOHANRAJ KATKHEDE",
"ownerPhoneNo": "7276447770",
"appAddress": "FLAT NO 103 WONDER RESIDENCY C WING BLD NO 2
FATHERWADI NAKA NEA H P PETROL PUMP GOKHIWARE VASAI PALGHAR
401208",
"remark": "Visit Urgent Discuss Value Rental Value With Banker",
"documents": [
  {
    "documentType": {
      "label": "Old Valuation Report ",
      "value": "60ae1296aa6d152c1801b455"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/663c69b11c6321090f29d58a/document_1715234964027_17152347
49527__Old_valuation_report_Mahesh_katkhede.pdf",
    "fileName": "document_1715234964027_1715234749527__Old_valuation_report_M
ahesh_katkhede.pdf",
    "id": "126670",
    "uploadedBy": "659ccce98f39506e83489828",
    "createdAt": "Thu May 09 2024 11:44:09 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "29/10/2020",
      "from": {
        "value": "Promoter",
        "label": "Promoter"
      },
      "Promoter": "M/s New Galaxy Enterprises",
      "to": {
        "value": "Allottee",
        "label": "Allottee"
      },
      "Allottee": "Mr. Mahesh Mohanraj Katkhede",
      "number": {
        "value": "Document_No",
        "label": "Document No"
      }
    }
  },
}
```

```
    "Document_No": "10758 / 2020"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1715325588076_document_1715235217333_17152350062
15_Mahesh_Katkhedede_agreement.pdf",
  "path": "cases/663c69b11c6321090f29d58a/document_1715325588076_document_
1715235217333_1715235006215_Mahesh_Katkhedede_agreement.pdf",
  "id": "226626",
  "uploadedBy": "64d09914dc9f3034f3008833",
  "createdAt": "Fri May 10 2024 12:49:49 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
    "label": "RERA Certificate"
  },
  "inputs": {
    "documentDate": "09/09/2021",
    "nameOfApprovingAuthority": {
      "value": "Vasai_Virar_City_Municipal_Corporation",
      "label": "Vasai Virar City Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "P99000020475"
},
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1715325798642_P99000020475.pdf",
  "path": "cases/663c69b11c6321090f29d58a/
document_1715325798642_P99000020475.pdf",
  "id": "757330",
  "uploadedBy": "64d09914dc9f3034f3008833",
  "createdAt": "Fri May 10 2024 12:53:18 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1277aa6d152c1801b3cc",
    "label": "Approved Building Plan"
  },
  "inputs": {
    "documentDate": "04/09/2020",
    "nameOfApprovingAuthority": {
```

```
    "value": "Vasai_Virar_City_Municipal_Corporation",
    "label": "Vasai Virar City Municipal Corporation"
  },
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "VVCMC / OCC / BP / VP 416 / 03 / 2020- 21"
},
"isHardCopy": false,
"displayStatus": false,
"id": "768219",
"path": "cases/663c69b11c6321090f29d58a/
document_1715332147767_2_Building_Plan_Approval_IOD_4.pdf",
"fileName": "document_1715332147767_2_Building_Plan_Approval_IOD_4.pdf"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "31/01/2015",
    "nameOfApprovingAuthority": {
      "value": "Vasai_Virar_City_Municipal_Corporation",
      "label": "Vasai Virar City Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "VVCMC / TP / RDP / VP- 0416 / 300 / 2014- 15"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1715332299125_1_Commencement_Certificates__NA_Order_for_plotted_development_6.pdf",
  "path": "cases/663c69b11c6321090f29d58a/document_1715332299125_1_Commencement_Certificates__NA_Order_for_plotted_development_6.pdf",
  "id": "923965",
  "uploadedBy": "64d09914dc9f3034f3008833",
  "createdAt": "Fri May 10 2024 14:41:39 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
```

```
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "04/09/2020",
    "nameOfApprovingAuthority": {
      "value": "Vasai_Virar_City_Municipal_Corporation",
      "label": "Vasai Virar City Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "VVCMC / TP / OC / VP- 0416 / 03 / 2020- 21"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "id": "314693",
  "path": "cases/663c69b11c6321090f29d58a/document_1715332647655_1_Occupa
ncy_Certificate__Completion_Certificate__Architects_certificate_of_completion_for_plot
ted_development_1.pdf",
  "fileName": "document_1715332647655_1_Occupancy_Certificate__Completion_C
ertificate__Architects_certificate_of_completion_for_plotted_development_1.pdf"
}
],
"caseNumber": "008611",
"createdBy": "659ccce98f39506e83489828",
"caseHistory": [
  {
    "id": "149422",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu May 09 2024 11:44:09 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "MR. MAHESH MOHANRAJ KATKHEDE",
    "phone": "7276447770",
    "ownershipShare": "",
    "email": "",
    "id": "214401"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
```



```
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "283513",
  "name": "Living Room",
  "length": "16.00",
  "length1": "16",
  "length2": "00",
  "width": "9.17",
  "width1": "9",
  "width2": "2",
  "totalArea": "146.67",
  "images": [],
  "extraAreas": [],
  "finalArea": "146.67"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Dining",
  "length": "9.75",
  "length1": "9",
  "length2": "9",
  "width": "5.17",
  "width1": "5",
  "width2": "2",
  "totalArea": "50.37",
  "images": [],
  "extraAreas": [],
  "finalArea": "50.37"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Kitchen",
  "length": "8.33",
  "length1": "8",
  "length2": "4",
```

```
"width": "7.67",
"width1": "7",
"width2": "8",
"totalArea": "63.89",
"images": [],
"extraAreas": [],
"finalArea": "63.89"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Passage",
  "length": "",
  "length1": "3",
  "length2": "5",
  "width": "",
  "width1": "3",
  "width2": "0",
  "totalArea": "10.25",
  "images": [],
  "finalArea": "10.25",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Toilet",
  "length": "6.33",
  "length1": "6",
  "length2": "4",
  "width": "4.00",
  "width1": "4",
  "width2": "00",
  "totalArea": "25.33",
  "images": [],
  "extraAreas": [],
  "finalArea": "25.33"
},
{
  "measurementType": {
```

```
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Bedroom",
  "length": "9.67",
  "length1": "9",
  "length2": "8",
  "width": "9.08",
  "width1": "9",
  "width2": "1",
  "totalArea": "87.81",
  "images": [],
  "extraAreas": [],
  "finalArea": "87.81"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Toilet",
  "length": "4.00",
  "length1": "4",
  "length2": "00",
  "width": "4.58",
  "width1": "4",
  "width2": "7",
  "totalArea": "18.33",
  "images": [],
  "extraAreas": [],
  "finalArea": "18.33"
}
],
"otherComposition": [
  {
    "toBeAdded": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "name": {
      "label": "Flower Bed Area",
      "value": "Flower_Bed_Area"
    }
  },
  "measurementType": {
```

```
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "0",
  "length": "9.00",
  "length1": "9",
  "length2": "00",
  "width": "2.00",
  "width1": "2",
  "width2": "00",
  "totalArea": "18.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "18",
  "percentageBeforeTotal": "18.00",
  "percentage": "100"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Dry Balcony",
    "value": "Dry_Balcony"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "length": "7.75",
  "length1": "7",
  "length2": "9",
  "width": "2.00",
  "width1": "2",
  "width2": "00",
  "totalArea": "15.50",
  "images": [],
  "extraAreas": [],
  "finalArea": "15.5",
  "percentageBeforeTotal": "15.50",
  "percentage": "100"
},
{
  "toBeAdded": {
```

```
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Flower Bed Area",
    "value": "Flower_Bed_Area"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "length": "9.00",
  "length1": "9",
  "length2": "00",
  "width": "2.00",
  "width1": "2",
  "width2": "00",
  "totalArea": "18.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "18",
  "percentageBeforeTotal": "18.00",
  "percentage": "100"
}
],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663d96d1fcea71232186e90f",
    "name":
"externallmg_1715312337389_WhatsApp_Image_20240510_at_084639_1.jpeg",
    "path": "cases/663c69b11c6321090f29d58a/
externallmg_1715312337389_WhatsApp_Image_20240510_at_084639_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663d96d1fcea71232186e910",
    "name":
"externallmg_1715312337392_WhatsApp_Image_20240510_at_084639.jpeg",
```

```
    "path": "cases/663c69b11c6321090f29d58a/
externallmg_1715312337392_WhatsApp_Image_20240510_at_084639.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663d96d1fcea71232186e911",
    "name":
"externallmg_1715312337399_WhatsApp_Image_20240510_at_084640_1.jpeg",
    "path": "cases/663c69b11c6321090f29d58a/
externallmg_1715312337399_WhatsApp_Image_20240510_at_084640_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663d96d1fcea71232186e912",
    "name":
"externallmg_1715312337408_WhatsApp_Image_20240510_at_084640.jpeg",
    "path": "cases/663c69b11c6321090f29d58a/
externallmg_1715312337408_WhatsApp_Image_20240510_at_084640.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663d96d1fcea71232186e913",
    "name":
"externallmg_1715312337411_WhatsApp_Image_20240510_at_084641_1.jpeg",
    "path": "cases/663c69b11c6321090f29d58a/
externallmg_1715312337411_WhatsApp_Image_20240510_at_084641_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663d96d1fcea71232186e914",
    "name":
"externallmg_1715312337416_WhatsApp_Image_20240510_at_084641_2.jpeg",
    "path": "cases/663c69b11c6321090f29d58a/
externallmg_1715312337416_WhatsApp_Image_20240510_at_084641_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "663d96d1fcea71232186e915",
    "name":
"externallmg_1715312337418_WhatsApp_Image_20240510_at_084641.jpeg",
    "path": "cases/663c69b11c6321090f29d58a/
externallmg_1715312337418_WhatsApp_Image_20240510_at_084641.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663d96d1fcea71232186e916",
    "name":
"externallmg_1715312337422_WhatsApp_Image_20240510_at_084642_1.jpeg",
    "path": "cases/663c69b11c6321090f29d58a/
externallmg_1715312337422_WhatsApp_Image_20240510_at_084642_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663d96d1fcea71232186e917",
    "name":
"externallmg_1715312337426_WhatsApp_Image_20240510_at_084642_2.jpeg",
    "path": "cases/663c69b11c6321090f29d58a/
externallmg_1715312337426_WhatsApp_Image_20240510_at_084642_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663d96d1fcea71232186e918",
    "name":
"externallmg_1715312337430_WhatsApp_Image_20240510_at_084642.jpeg",
    "path": "cases/663c69b11c6321090f29d58a/
externallmg_1715312337430_WhatsApp_Image_20240510_at_084642.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663d96d1fcea71232186e919",
    "name":
"externallmg_1715312337433_WhatsApp_Image_20240510_at_084643_1.jpeg",
    "path": "cases/663c69b11c6321090f29d58a/
externallmg_1715312337433_WhatsApp_Image_20240510_at_084643_1.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663d96d1fcea71232186e91a",
    "name":
"externallmg_1715312337437_WhatsApp_Image_20240510_at_084643.jpeg",
    "path": "cases/663c69b11c6321090f29d58a/
externallmg_1715312337437_WhatsApp_Image_20240510_at_084643.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663d96d1fcea71232186e91b",
    "name":
"externallmg_1715312337440_WhatsApp_Image_20240510_at_084644_1.jpeg",
    "path": "cases/663c69b11c6321090f29d58a/
externallmg_1715312337440_WhatsApp_Image_20240510_at_084644_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663d96d1fcea71232186e91c",
    "name":
"externallmg_1715312337444_WhatsApp_Image_20240510_at_084644.jpeg",
    "path": "cases/663c69b11c6321090f29d58a/
externallmg_1715312337444_WhatsApp_Image_20240510_at_084644.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663d96d1fcea71232186e91d",
    "name":
"externallmg_1715312337446_WhatsApp_Image_20240510_at_084645.jpeg",
    "path": "cases/663c69b11c6321090f29d58a/
externallmg_1715312337446_WhatsApp_Image_20240510_at_084645.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663d96d1fcea71232186e91e",
```



```
"name":
"externallmg_1715312337449_WhatsApp_Image_20240510_at_084416_1.jpeg",
  "path": "cases/663c69b11c6321090f29d58a/
externallmg_1715312337449_WhatsApp_Image_20240510_at_084416_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "663d96d1fcea71232186e91f",
  "name":
"externallmg_1715312337451_WhatsApp_Image_20240510_at_084416_2.jpeg",
  "path": "cases/663c69b11c6321090f29d58a/
externallmg_1715312337451_WhatsApp_Image_20240510_at_084416_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "663d96d1fcea71232186e920",
  "name":
"externallmg_1715312337453_WhatsApp_Image_20240510_at_084416.jpeg",
  "path": "cases/663c69b11c6321090f29d58a/
externallmg_1715312337453_WhatsApp_Image_20240510_at_084416.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "663d96d1fcea71232186e921",
  "name":
"externallmg_1715312337456_WhatsApp_Image_20240510_at_084417.jpeg",
  "path": "cases/663c69b11c6321090f29d58a/
externallmg_1715312337456_WhatsApp_Image_20240510_at_084417.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "663d96d1fcea71232186e922",
  "name":
"externallmg_1715312337459_WhatsApp_Image_20240510_at_084418.jpeg",
  "path": "cases/663c69b11c6321090f29d58a/
externallmg_1715312337459_WhatsApp_Image_20240510_at_084418.jpeg",
  "orientation": "portrait"
},
},
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "663d96e00804b32367d35a6b",
  "name":
"externallmg_1715312352510_WhatsApp_Image_20240510_at_084420.jpeg",
  "path": "cases/663c69b11c6321090f29d58a/
externallmg_1715312352510_WhatsApp_Image_20240510_at_084420.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "663d96e00804b32367d35a6c",
  "name":
"externallmg_1715312352513_WhatsApp_Image_20240510_at_084421_1.jpeg",
  "path": "cases/663c69b11c6321090f29d58a/
externallmg_1715312352513_WhatsApp_Image_20240510_at_084421_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "663d96e00804b32367d35a6d",
  "name":
"externallmg_1715312352517_WhatsApp_Image_20240510_at_084421.jpeg",
  "path": "cases/663c69b11c6321090f29d58a/
externallmg_1715312352517_WhatsApp_Image_20240510_at_084421.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "663d96e00804b32367d35a6e",
  "name":
"externallmg_1715312352521_WhatsApp_Image_20240510_at_084423.jpeg",
  "path": "cases/663c69b11c6321090f29d58a/
externallmg_1715312352521_WhatsApp_Image_20240510_at_084423.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "663d96e00804b32367d35a6f",
  "name":
"externallmg_1715312352525_WhatsApp_Image_20240510_at_084428.jpeg",
```

```
    "path": "cases/663c69b11c6321090f29d58a/
externallmg_1715312352525_WhatsApp_Image_20240510_at_084428.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663d96e00804b32367d35a70",
    "name":
"externallmg_1715312352529_WhatsApp_Image_20240510_at_084430.jpeg",
    "path": "cases/663c69b11c6321090f29d58a/
externallmg_1715312352529_WhatsApp_Image_20240510_at_084430.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663d96e00804b32367d35a71",
    "name":
"externallmg_1715312352531_WhatsApp_Image_20240510_at_084450.jpeg",
    "path": "cases/663c69b11c6321090f29d58a/
externallmg_1715312352531_WhatsApp_Image_20240510_at_084450.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663d96e00804b32367d35a72",
    "name":
"externallmg_1715312352533_WhatsApp_Image_20240510_at_084502.jpeg",
    "path": "cases/663c69b11c6321090f29d58a/
externallmg_1715312352533_WhatsApp_Image_20240510_at_084502.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663d96e00804b32367d35a73",
    "name":
"externallmg_1715312352536_WhatsApp_Image_20240510_at_084608.jpeg",
    "path": "cases/663c69b11c6321090f29d58a/
externallmg_1715312352536_WhatsApp_Image_20240510_at_084608.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "663d96e00804b32367d35a74",
  "name":
"externallmg_1715312352538_WhatsApp_Image_20240510_at_084618.jpeg",
  "path": "cases/663c69b11c6321090f29d58a/
externallmg_1715312352538_WhatsApp_Image_20240510_at_084618.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "663d96e00804b32367d35a75",
  "name":
"externallmg_1715312352543_WhatsApp_Image_20240510_at_084623.jpeg",
  "path": "cases/663c69b11c6321090f29d58a/
externallmg_1715312352543_WhatsApp_Image_20240510_at_084623.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "663d96e00804b32367d35a76",
  "name":
"externallmg_1715312352545_WhatsApp_Image_20240510_at_084634.jpeg",
  "path": "cases/663c69b11c6321090f29d58a/
externallmg_1715312352545_WhatsApp_Image_20240510_at_084634.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "663d96e00804b32367d35a77",
  "name":
"externallmg_1715312352548_WhatsApp_Image_20240510_at_084635.jpeg",
  "path": "cases/663c69b11c6321090f29d58a/
externallmg_1715312352548_WhatsApp_Image_20240510_at_084635.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "663d96e00804b32367d35a78",
  "name":
"externallmg_1715312352550_WhatsApp_Image_20240510_at_084636_1.jpeg",
  "path": "cases/663c69b11c6321090f29d58a/
externallmg_1715312352550_WhatsApp_Image_20240510_at_084636_1.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663d96e00804b32367d35a79",
    "name":
"externallmg_1715312352552_WhatsApp_Image_20240510_at_084636.jpeg",
    "path": "cases/663c69b11c6321090f29d58a/
externallmg_1715312352552_WhatsApp_Image_20240510_at_084636.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663d96e00804b32367d35a7a",
    "name":
"externallmg_1715312352555_WhatsApp_Image_20240510_at_084637_1.jpeg",
    "path": "cases/663c69b11c6321090f29d58a/
externallmg_1715312352555_WhatsApp_Image_20240510_at_084637_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663d96e00804b32367d35a7b",
    "name":
"externallmg_1715312352558_WhatsApp_Image_20240510_at_084637_2.jpeg",
    "path": "cases/663c69b11c6321090f29d58a/
externallmg_1715312352558_WhatsApp_Image_20240510_at_084637_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663d96e00804b32367d35a7c",
    "name":
"externallmg_1715312352561_WhatsApp_Image_20240510_at_084637.jpeg",
    "path": "cases/663c69b11c6321090f29d58a/
externallmg_1715312352561_WhatsApp_Image_20240510_at_084637.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663d96e00804b32367d35a7d",
```

```
"name":
"externalImg_1715312352564_WhatsApp_Image_20240510_at_084638_1.jpeg",
  "path": "cases/663c69b11c6321090f29d58a/
externalImg_1715312352564_WhatsApp_Image_20240510_at_084638_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "663d96e00804b32367d35a7e",
  "name":
"externalImg_1715312352567_WhatsApp_Image_20240510_at_084638.jpeg",
  "path": "cases/663c69b11c6321090f29d58a/
externalImg_1715312352567_WhatsApp_Image_20240510_at_084638.jpeg",
  "orientation": "landscape"
}
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-05-09T06:14:09.848Z",
"updatedAt": "2024-05-10T09:34:22.598Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 103, 1st Floor, Building No 2, Wing - C, Wonder
Residancey, Fatherwadi Naka, Near H P Petrol Pump, Village - Gokhivire, Vasai East,
Vasai",
"updatedBy": "64d09914dc9f3034f3008833",
"addressForMap": "",
"caseReferredBy": "659ccce98f39506e83489828",
"contactPersonName": "MR. MAHESH MOHANRAJ KATKHEDE",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "7276447770",
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + Dining + Passage + 2
Toilet",
```

"carpetTotal": "402.65",  
 "finalMeasurementType": "Sq. Ft.",  
 "otherCarpetTotal": "51.50",  
 "otherCompositionBuiltUpTotal": "0.00",  
 "otherCompositionCarpetTotal": "51.50",  
 "otherCompositionSaleableTotal": "0.00",  
 "builtupPercentage": "10",  
 "finalBuiltupArea": "499.56",  
 "finalCarpetArea": "454.15",  
 "finalSalableArea": "549.52",  
 "salablePercentage": "10",  
 "toBeAdded": "",  
 "extendOfSiteRemark": "",  
 "siteMeasurementRemark": "",  
 "finalAreaType": "Built Up Area",  
 "finalAsPerArea": "actual site measurement",  
 "finalBuiltUpPercentage": "10",  
 "finalCarpetConvertToBuiltUpPer": "10",  
 "finalSaleablePercentage": "10",  
 "finalValuationAreaString": "Built Up Area in Sq. Ft. = 499.56"

Name	Length	Width	Total
Composition :			
Living Room	16'00"	9'2"	146.67
Dining	9'9"	5'2"	50.37
Kitchen	8'4"	7'8"	63.89
Passage	3'5"	3'0"	10.25
Toilet	6'4"	4'00"	25.33
Bedroom	9'8"	9'1"	87.81
Toilet	4'00"	4'7"	18.33
Other Composition :			
Flower Bed Area	9'00"	2'00"	18.00
Dry Balcony	7'9"	2'00"	15.50
Flower Bed Area	9'00"	2'00"	18.00