

```
{
  "typeOfReport": {
    "value": "Land_and_Building",
    "label": "Land and Building"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Bank_Loan",
    "label": "Bank Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b8dc"
    },
    "type": "CREDITOFFICER",
    "_id": "63d11f66be948726cc141b37",
    "email": "komal.vanjari@cosmosbank.in",
    "firstName": "Komal ",
    "mobileNo": "8080342307",
    "workMobileNo": "8080342307",
    "lastName": "vanjari"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "6418456a96b58848585f8cb2",
  "name": "Thane",
  "email": "thane@vastukala.com",
  "phone": "1234567890",
  "address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
  "city": "Thane",
  "shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1820",
  "type": "BANK",
  "name": "Cosmos Bank",
  "displayName": "Cosmos Bank",
  "initial": "CB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b8dc",
  "branchCode": "000005",
  "type": "BRANCH",
  "name": "Naupada",
  "email": "thane@cosmosbank.in",
  "mobileNo": "022-25345923",
  "alternateMobileNo": "",
  "address": "Kusumanjali, Opp. Devdhar Hospital, Naupada, Thane (West) - 400 602,
State - Maharashtra, Country - India.\r\n",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Industrial",
  "value": "Industrial"
},
"zone": {
  "_id": "60f919bff3dd69653a5926b8",
  "zoneName": "Mumbai & Aurangabad Zone"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "656aa949cebbe1714411d21b",
  "role": "FRONTDESK",
  "firstName": "Priyanka",
  "email": "thane@vastukala.org",
  "lastName": "Pawar",
  "mobileNo": "8928414480",
  "shortName": "PCP",
  "workWithDocumentMaker": "627222afafd7d55eddeddd82"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "65829f7c65d49d78457ec7be",
  "role": "SITEENGINEER",
  "firstName": "Vaibhav",
  "email": "vaib1234b@gmail.com",
  "lastName": "Bhagat",
  "mobileNo": "8779534609",
  "designation": "Bachlore Of Engireeing",
  "shortName": "Vaibhav",
  "workWithDocumentMaker": "62691c48afd7d55eddecfda3"
},
"rateVerifier": null,
"maker": null,
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  {
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        }
      }
    ]
  }
]
```

```
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "17.62187900499884",
  "longitude": "73.48115320975315"
},
```

```
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": [],
  "remark": null,
  "rateMin": "1",
  "lumpsumValue": "1",
  "rateMax": "1",
  "areaType": {
    "Name": "Saleable",
    "Value": "Saleable",
    "name": "Saleable",
    "value": "Saleable"
  }
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
```

```
"status": true,
"name": "Village",
"key": "village",
"value": "Lote",
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Basement",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Ratnagiri",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Khed",
```

```
"label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "C -33 & C - 34",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Parshuram Industrial Area",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
```

```
"name": "Wing",
"key": "wing",
"value": "",
"label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
}
```



```
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
```

```
"key": "GUTNo",
"value": "",
"label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "label": "R. C. C. Slab",
    "value": "rcc_Slab"
  },
  "flooring": {
    "label": "Industrial Flooring",
    "value": "IndustrialFlooring"
  },
  "doors": {
    "label": "MS Rolling Shutter",
    "value": "MS_Rolling_Shutter"
  },
  "windows": {
    "label": "M.S. Grill Fixed Windows",
    "value": "M.S._Grill_Fixed_Windows"
  },
  "fittings": {
    "label": "Open Conduit Plumbing With Concealed Electrification",
    "value": "Open_Conduit_Plumbing_With_Concealed_Electrification"
  },
  "finishing": {
    "label": "Normal",
    "value": "Normal"
  }
}
},
"general": {
```

```
"populationClassList": {
  "label": "Middle Class",
  "value": "MiddleClass"
},
"populationGroupList": {
  "label": "Rural",
  "value": "Rural"
},
"townplanApprovedByList": {
  "label": "M.I.D.C.",
  "value": "M.I.D.C."
},
"asPerActualAgreement": {
  "north": "trimurti engineers",
  "west": "padma plastics pvt ltd",
  "south": "road",
  "east": "road"
},
"asPerDocumentAgreement": {
  "north": "",
  "west": "",
  "south": "",
  "east": ""
},
"unitBoundaries": {
  "asPerActual": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "asPerDocument": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
```

```
"floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "label": "Ordinary",
    "value": "Ordinary"
  },
  "propertyTypeOfUseList": {
    "label": "Industrial",
    "value": "Industrial"
  },
  "propertyOccupiedByList": {
    "label": "Owner Occupied",
    "value": "Owner_Occupied"
  },
  "monthlyRent": ""
},
"siteMeasurement": {
  "partitions": {
    "label": "6\" Thk. Brick Masonery",
    "value": "6\"_Thk._Brick_Masonery"
  },
  "waterTank": {
    "label": "MIDC",
    "value": "MIDC"
  },
  "pavementLaid": {
    "label": "No",
    "value": "No"
  },
  "carParking": {
    "label": "Open Car Parking Space",
    "value": "Open_Car_Parking_Space"
  },
  "constructionWorkStatus": {
    "label": "Completed",
    "value": "Completed"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "1995",
    "fullDate": "1/1/1995"
  },
  "propertyTypeList": {
    "label": "Industrial",
```

```
"value": "Industrial"
},
"planningArea": {
  "label": "Industrial",
  "value": "Industrial"
},
"typeOfStructure": {
  "label": "Steel Framed",
  "value": "Steel_Framed"
},
"qualityOfConstruction": {
  "label": "Normal",
  "value": "Normal"
},
"walls": {
  "label": "Yes",
  "value": "1"
},
"appearanceOfTheBuilding": {
  "label": "Normal",
  "value": "Normal"
},
"maintenanceOfTheBuilding": {
  "label": "Normal",
  "value": "Normal"
},
"visibleDamageInBuilding": {
  "label": "No",
  "value": "0"
},
"groundStilt": {
  "label": "Ground",
  "value": "ground"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "31",
"ageOfBuilding": "29",
"noOfBasement": "0",
"noOfPodium": "0",
"noOfAmenityFloors": "0",
"noOfFloors": "07",
"flatFloorNo": "",
"noOfLifts": "0",
"noOfLiftsInEachWings": "0",
"noOfDwellingUnitsInBuilding": "0"
```

```
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
}
```

```
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
```



```
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
```

```
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
```

```
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"invoices": [],
"paymentIds": [],
"_id": "663ca11223ff7a08d340ac23",
"ownerName": "M/s. Sulakhi Chemicals Private Limited",
"ownerPhoneNo": "8928910589",
"fullAddress": "Residential Land and Building No. Basement Floor, Parshuram
Industrial Area, Plot No. C -33 & C - 34, Village - Lote, Taluka - Khed, District -
Ratnagiri",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "23/04/2001",
      "from": {
        "value": "The_Assignor",
        "label": "The Assignor"
      },
      "The_Assignor": "Maharashtra Industrial Development Corporation ",
      "to": {
        "value": "Lessee",
        "label": "Lessee"
      },
      "Lessee": "M/s. Sulakhi Chemicals Private Limited",
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "0000"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "fileName":
"document_1715249158554_1207001123P107834939_sulaki_INSURANCE.pdf",
    "path": "cases/663ca11223ff7a08d340ac23/
document_1715249158554_1207001123P107834939_sulaki_INSURANCE.pdf",
    "id": "215870",
    "uploadedBy": "656aa949cebbe1714411d21b",
```

```
"createdAt": "Thu May 09 2024 15:40:26 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "inputs": {
    "number": {
      "value": "Document_No",
      "label": "Document No"
    }
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName":
"document_1715249171376_1207001123P107835456_sulaki_INSURANCE.pdf",
  "path": "cases/663ca11223ff7a08d340ac23/
document_1715249171376_1207001123P107835456_sulaki_INSURANCE.pdf",
  "id": "158975",
  "uploadedBy": "656aa949cebbe1714411d21b",
  "createdAt": "Thu May 09 2024 15:40:26 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName":
"document_1715249183496_Cosmos_NaupadaM_s_sulaki_chemicals.pdf",
  "path": "cases/663ca11223ff7a08d340ac23/
document_1715249183496_Cosmos_NaupadaM_s_sulaki_chemicals.pdf",
  "id": "625443",
  "uploadedBy": "656aa949cebbe1714411d21b",
  "createdAt": "Thu May 09 2024 15:40:26 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1715249198457_INSURANCE_MH08H1738.pdf",
```

```
    "path": "cases/663ca11223ff7a08d340ac23/
document_1715249198457_INSURANCE_MH08H1738.pdf",
    "id": "737790",
    "uploadedBy": "656aa949cebbe1714411d21b",
    "createdAt": "Thu May 09 2024 15:40:26 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae124eaa6d152c1801b30b",
      "label": "Other"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1715249209524_INSURANCE_MH08H1814.pdf",
    "path": "cases/663ca11223ff7a08d340ac23/
document_1715249209524_INSURANCE_MH08H1814.pdf",
    "id": "776389",
    "uploadedBy": "656aa949cebbe1714411d21b",
    "createdAt": "Thu May 09 2024 15:40:26 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae124eaa6d152c1801b30b",
      "label": "Other"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1715249221253_KNSB_Valuer_Part_1.pdf",
    "path": "cases/663ca11223ff7a08d340ac23/
document_1715249221253_KNSB_Valuer_Part_1.pdf",
    "id": "352037",
    "uploadedBy": "656aa949cebbe1714411d21b",
    "createdAt": "Thu May 09 2024 15:40:26 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae124eaa6d152c1801b30b",
      "label": "Other"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1715249234670_KNSB_Valuer_Part_2.pdf",
    "path": "cases/663ca11223ff7a08d340ac23/
document_1715249234670_KNSB_Valuer_Part_2.pdf",
    "id": "230003",
    "uploadedBy": "656aa949cebbe1714411d21b",
```

```
"createdAt": "Thu May 09 2024 15:40:26 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1715249247386_List_of_Equipments.pdf",
  "path": "cases/663ca11223ff7a08d340ac23/
document_1715249247386_List_of_Equipments.pdf",
  "id": "105668",
  "uploadedBy": "656aa949cebbe1714411d21b",
  "createdAt": "Thu May 09 2024 15:40:26 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1715249257711_MIDC_BCC_NOC.pdf",
  "path": "cases/663ca11223ff7a08d340ac23/
document_1715249257711_MIDC_BCC_NOC.pdf",
  "id": "491580",
  "uploadedBy": "656aa949cebbe1714411d21b",
  "createdAt": "Thu May 09 2024 15:40:26 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1715249269383_Process_Flow_Diagram.pdf",
  "path": "cases/663ca11223ff7a08d340ac23/
document_1715249269383_Process_Flow_Diagram.pdf",
  "id": "248000",
  "uploadedBy": "656aa949cebbe1714411d21b",
  "createdAt": "Thu May 09 2024 15:40:26 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
```

```
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/663ca11223ff7a08d340ac23/
document_1715249277975_SULAKI_CHEMICAL_PVT_LTD_INSURANCE.pdf",
  "fileName":
"document_1715249277975_SULAKI_CHEMICAL_PVT_LTD_INSURANCE.pdf",
  "id": "153033",
  "uploadedBy": "656aa949cebbe1714411d21b",
  "createdAt": "Thu May 09 2024 15:40:26 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1715249290439_Water_bill_march.pdf",
  "path": "cases/663ca11223ff7a08d340ac23/
document_1715249290439_Water_bill_march.pdf",
  "id": "432284",
  "uploadedBy": "656aa949cebbe1714411d21b",
  "createdAt": "Thu May 09 2024 15:40:26 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1715249411533_161185.pdf",
  "path": "cases/663ca11223ff7a08d340ac23/
document_1715249411533_161185.pdf",
  "id": "592643",
  "uploadedBy": "656aa949cebbe1714411d21b",
  "createdAt": "Thu May 09 2024 15:40:26 GMT+0530 (India Standard Time)"
}
],
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
}
```



```
"caseNumber": "008624",
"createdBy": "656aa949cebbe1714411d21b",
"caseHistory": [
  {
    "id": "692330",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu May 09 2024 15:40:26 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "M/s. Sulakhi Chemicals Private Limited",
    "phone": "8928910589",
    "ownershipShare": "",
    "email": "",
    "id": "163484"
  }
],
"proposePurchasers": [],
"siteInspection": [
  {
    "areaType": {
      "label": "Saleable",
      "value": "Saleable"
    },
    "providedBy": {
      "label": "Owner",
      "value": "Owner"
    },
    "_id": "6641bf7fe878f03b3ef18833",
    "area": "6834",
    "providedByName": "M/s. Sulakhi Chemicals Private Limited",
    "providedByContactNo": "8928910589"
  }
],
"composition": [
  {
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "535831",
    "name": "Unit Area",
    "length": "1.00",
    "length1": "1",
```

```
"length2": "00",
"width": "1.00",
"width1": "1",
"width2": "00",
"totalArea": "1.00",
"images": [],
"extraAreas": [],
"finalArea": "1.00"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6641c015e878f03b3ef18904",
    "name": "externalImg_171585010033_image.jpeg",
    "path": "cases/663ca11223ff7a08d340ac23/
externalImg_171585010033_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6641c015e878f03b3ef18905",
    "name": "externalImg_171585010421_image.jpeg",
    "path": "cases/663ca11223ff7a08d340ac23/
externalImg_171585010421_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6641c015e878f03b3ef18906",
    "name": "externalImg_171585011595_image.jpeg",
    "path": "cases/663ca11223ff7a08d340ac23/
externalImg_171585011595_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```

```
    "_id": "6641c015e878f03b3ef18907",
    "name": "externallmg_1715585013166_image.jpeg",
    "path": "cases/663ca11223ff7a08d340ac23/
externallmg_1715585013166_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6641c015e878f03b3ef18908",
    "name": "externallmg_1715585013176_image.jpeg",
    "path": "cases/663ca11223ff7a08d340ac23/
externallmg_1715585013176_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6641c015e878f03b3ef18909",
    "name": "externallmg_1715585014490_image.jpeg",
    "path": "cases/663ca11223ff7a08d340ac23/
externallmg_1715585014490_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6641c015e878f03b3ef1890a",
    "name": "externallmg_1715585015785_image.jpeg",
    "path": "cases/663ca11223ff7a08d340ac23/
externallmg_1715585015785_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6641c015e878f03b3ef1890b",
    "name": "externallmg_1715585016885_image.jpeg",
    "path": "cases/663ca11223ff7a08d340ac23/
externallmg_1715585016885_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6641c015e878f03b3ef1890c",
```

```
    "name": "externallmg_1715585019340_image.jpeg",
    "path": "cases/663ca11223ff7a08d340ac23/
externallmg_1715585019340_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6641c015e878f03b3ef1890d",
    "name": "externallmg_1715585020795_image.jpeg",
    "path": "cases/663ca11223ff7a08d340ac23/
externallmg_1715585020795_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6641c015e878f03b3ef1890e",
    "name": "externallmg_1715585021720_image.jpeg",
    "path": "cases/663ca11223ff7a08d340ac23/
externallmg_1715585021720_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6641c015e878f03b3ef1890f",
    "name": "externallmg_1715585023115_image.jpeg",
    "path": "cases/663ca11223ff7a08d340ac23/
externallmg_1715585023115_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6641c015e878f03b3ef18910",
    "name": "externallmg_1715585023694_image.jpeg",
    "path": "cases/663ca11223ff7a08d340ac23/
externallmg_1715585023694_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6641c015e878f03b3ef18911",
    "name": "externallmg_1715585025675_image.jpeg",
```

```
    "path": "cases/663ca11223ff7a08d340ac23/
externallmg_1715585025675_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6641c015e878f03b3ef18912",
    "name": "externallmg_1715585027529_image.jpeg",
    "path": "cases/663ca11223ff7a08d340ac23/
externallmg_1715585027529_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6641c015e878f03b3ef18913",
    "name": "externallmg_1715585029289_image.jpeg",
    "path": "cases/663ca11223ff7a08d340ac23/
externallmg_1715585029289_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6641c015e878f03b3ef18914",
    "name": "externallmg_1715585030309_image.jpeg",
    "path": "cases/663ca11223ff7a08d340ac23/
externallmg_1715585030309_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6641c015e878f03b3ef18915",
    "name": "externallmg_1715585032434_image.jpeg",
    "path": "cases/663ca11223ff7a08d340ac23/
externallmg_1715585032434_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6641c015e878f03b3ef18916",
    "name": "externallmg_1715585034459_image.jpeg",
    "path": "cases/663ca11223ff7a08d340ac23/
externallmg_1715585034459_image.jpeg",
```

```

    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6641c015e878f03b3ef18917",
    "name": "externallmg_1715585037784_image.jpeg",
    "path": "cases/663ca11223ff7a08d340ac23/
externallmg_1715585037784_image.jpeg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-05-09T10:10:26.181Z",
"updatedAt": "2024-05-13T07:24:49.692Z",
"__v": 0,
"updatedBy": "65829f7c65d49d78457ec7be",
"addressForMap": "",
"caseReferredBy": "64abdb2806d6ec174986d16b",
"contactPersonName": "M/s. Sulakhi Chemicals Private Limited",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "8928910589",
"briefDescOfProperty": "Unit Area",
"carpetTotal": "1",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "0"
}

```

Name	Length	Width	Total
Composition :			
Unit Area	1'00"	1'00"	1.00

Other  
Composition :

---