

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "65c9be6dd93fe4510d4b51dc"
    },
    "type": "CREDITOFFICER",
    "_id": "65c9be6dd93fe4510d4b51de",
    "firstName": "Daxa",
    "lastName": "Mahesh",
    "mobileNo": "",
    "workMobileNo": "9967977498",
    "email": "ubin0904554@unionbankoindia.bank"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "5500000",
    "discussWithPerson": "Daxa",
    "expectedFees": 2750,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1828",
  "type": "BANK",
  "name": "Union Bank of India",
  "displayName": "Union Bank of India",
  "initial": "UBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "65c9be6dd93fe4510d4b51dc",
  "name": "Bhayander East Branch",
  "branchCode": "0904554",
  "mobileNo": "0000000000",
  "alternateMobileNo": "",
  "email": "ubin0904554@unionbankoindia.bank",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Shop No 5,6A & 6B, Chandresh Heights, Jesal Park,\nBhayander East,
Thane-401105"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f93be845132d6a6bdda676",
  "zoneName": "MUMBAI SOUTH"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
"_id": "659ccce98f39506e83489828",
"role": "DELIVERYPERSON",
"firstName": "Amit",
"email": "amitsalvi2909@gmail.com",
"lastName": "Salvi",
"mobileNo": "7499830659",
"shortName": "Amit",
"workWithDocumentMaker": "",
"profilePhoto": "users/659ccce98f39506e83489828/
profilePhoto_1712385426269_image.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "64c777a8a5c3051014f4dd1f",
"role": "SITEENGINEER",
"firstName": "Pratik",
"email": "pratikjain2277@gmail.com",
"lastName": "Jain",
"mobileNo": "9619286285",
"designation": "",
"shortName": "Pratik",
"workWithDocumentMaker": "6006d4ce5080a310ac1fdcf2"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "64dc7184ccaf1e7b7f637f47",
"role": "FRONTDESK",
"firstName": "Binumon",
"email": "binu@vastukala.org",
"lastName": "Moozhickal",
"mobileNo": "9930252906",
"designation": "Back Office Team Leader",
"shortName": "BS",
"workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
"profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "62fe044a48a26047e6552796",
"role": "MAKER",
"firstName": "Pradnya ",
"email": "pradnya@vastukala.org",
"lastName": "Rasam",
"mobileNo": "9529385821",
"designation": ""
```

```
    "shortName": "PR",
    "workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
    "profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
  },
  "checker": {
    "type": "EMPLOYEE",
    "_id": "64dc7184ccaf1e7b7f637f47",
    "role": "FRONTDESK",
    "firstName": "Binumon",
    "email": "binu@vastukala.org",
    "lastName": "Moozhickal",
    "mobileNo": "9930252906",
    "designation": "Back Office Team Leader",
    "shortName": "BS",
    "workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
    "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
  },
  "valuers": [
    {
      "valuersRegistrationNumber": [
        {
          "value": "IBBI/RV/07/2018/10366",
          "label": "Registered Valuer"
        }
      ],
      "type": "EMPLOYEE",
      "_id": "5ffe92d27737ca4d986b6453",
      "role": "VALUER",
      "firstName": "Manoj",
      "email": "manoj@vastukala.org",
      "lastName": "Chalikwar",
      "mobileNo": "9819597579",
      "designation": "Registered Valuer",
      "registrationNo": [
        {
          "title": {
            "label": "IBBI"
          },
          "_id": "60af80072ffdf65bcd658651",
          "number": "IBBI/RV/07/2018/10366"
        }
      ],
      {
        "title": {
          "value": "FIIV",
```

```
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
  "latitude": "19.302091",
  "longitude": "72.864289"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.864289,
    19.302091
  ]
}
},
```

```
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-05-13",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-05-13",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-05-13",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "Country - India",
```

```
"label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Navghar ",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "10",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane ",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Thane ",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
```

```
"name": "Taluka",
"key": "taluka",
"value": "Thane ",
"label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Jak Serenity Co-Op. Hsg. Soc. Ltd. ",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
}
```



```
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "B",
  "label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Indralok Complex, Indralok Phase - 5",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "34/4, 33/7 & others ",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
```

```
"key": "blockNo",
"value": "",
"label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "1002",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
}
```

```
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 401 105",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Bhayander (East)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "Proposed_Vitrified_tiles_flooring",
    "label": "Proposed Vitrified tiles flooring"
  },
  "doors": {
    "value": "Proposed_Teak_wood_door_frame_with_flush_doors",
    "label": "Proposed Teak wood door frame with flush doors"
  },
  "windows": {
    "value": "Proposed_Powder_coated_aluminium_sliding_windows",
    "label": "Proposed Powder coated aluminium sliding windows"
  },
  "fittings": {
    "value": "Proposed_Concealed_plumbing_with_C.P._fittings._Proposed_Electrical_wiring_with_Concealed.",
    "label": "Proposed Concealed plumbing with C.P. fittings. Proposed Electrical wiring with Concealed."
  },
  "finishing": {
```

```
"value": "Proposed_Cement_Plastering",
"label": "Proposed Cement Plastering"
}
},
"general": {
"ownership": {
"value": "Joint_Ownership",
"label": "Joint Ownership"
},
"populationClassList": {
"value": "MiddleClass",
"label": "Middle Class"
},
"populationGroupList": {
"value": "Urban",
"label": "Urban"
},
"townplanApprovedByList": {
"value": "Mira_Bhayander_Municipal_Corporation",
"label": "Mira Bhayander Municipal Corporation"
},
"whetherCoveredUnderAnyState": {
"value": "No",
"label": "No"
},
"asPerActualAgreement": {
"north": "Internal Road ",
"west": "R.G. Patil Road",
"south": "Tirth Apartment ",
"east": "Internal Road "
},
"asPerDocumentAgreement": {
"north": "By Survey No. 225",
"west": "By Survey No. 227",
"south": "By Survey No. 228",
"east": "By Survey No. 247"
},
"unitBoundaries": {
"asPerActual": {
"north": "",
"west": "",
"south": "",
"east": ""
},
"asPerDocument": {
"north": "",
```

```
    "west": "",
    "south": "",
    "east": ""
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "Copy of Approved Building Plan No. MNP / NR / 03 /
2021 - 2022 dated 01.04.2021 issued by Mira Bhayander Municipal Corporation",
"approvePlanVerified": "Yes",
"empanelledOfApprovePlan": "Building is under construction ",
"unauthorizedConstruction": ""
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "0",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "buildingServicesDepreciatedRate": "0",
  "depreciatedCostOfConstruction": "14500.00",
  "depreciatedBuildingRate": "2800"
},
"igrRate": {
  "propertyName": "Flat",
  "rate": "84200",
  "landRate": "26920",
  "igrImage": "cases/6641e7ecbcfcd83b091c31ee/igr_1715665581139_Image.png",
  "squareMeterGuideLineRate": "88410.00",
  "squareFeetGuideLineRate": "8214.00"
},
"igrFinalRate": {
  "floorRatePercentage": "5",
  "depreciationPercentage": "0",
  "rate": "84200.00",
  "squareMeterGuideLineRate": "88410.00",
  "squareFeetGuideLineRate": "8214.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  }
}
```

```
},
"propertyTypeOfUseList": {
  "value": "Residential_Purpose",
  "label": "Residential Purpose"
},
"propertyOccupiedByList": {
  "value": "Building_is_under_construction_",
  "label": "Building is under construction "
},
"monthlyRent": "N.A",
"assessmentNo": "Details not available ",
"taxPaidHolderName": "Details not available ",
"taxAmount": "Details not available ",
"electricityServiceConnectionNo": "Details not available ",
"meterCardHolderName": "Details not available ",
"undividedAreaOfLandAsPerSaleDeed": "Details not available ",
"floorSpaceIndex": "As per MBMC norms",
"tenantName": "",
"maintenanceOfFlat": "Building is under construction "
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area ",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "Proposed_R.C.C._Slab",
    "label": "Proposed R.C.C. Slab"
  },
  "partitions": {
    "value": "Building_Under_Construction",
    "label": "Building Under Construction"
  },
  "waterTank": {
    "value": "Proposed_Municipal_Water_Supply",
    "label": "Proposed Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Proposed,_Yes",
    "label": "Proposed, Yes"
  },
  "carParking": "Proposed Stilt Car Parking Space ",
```

```
"constructionWorkStatus": {
  "value": "InProgress",
  "label": "Under Construction"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "",
  "month": "1",
  "year": "2024",
  "fullDate": "1/1/2024"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "Proposed_R.C.C_Framed_Structure",
  "label": "Proposed R.C.C Framed Structure"
},
"typeOfFoundation": {
  "value": "Proposed_R.C.C_Foundation",
  "label": "Proposed R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Building_is_under_construction_",
  "label": "Building is under construction "
},
"materialUsedList": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
}
```

```
"sewerageSystem": {
  "value": "Proposed_Connected_to_Municipal_Sewerage_System_",
  "label": "Proposed Connected to Municipal Sewerage System "
},
"walls": {
  "value": "Proposed,_Yes",
  "label": "Proposed, Yes"
},
"appearanceOfTheBuilding": {
  "value": "Building_is_under_construction_",
  "label": "Building is under construction "
},
"maintenanceOfTheBuilding": {
  "value": "Building_is_under_construction_",
  "label": "Building is under construction "
},
"maintenanceIssues": {
  "value": "1",
  "label": "Yes"
},
"visibleDamageInBuilding": {
  "value": "1",
  "label": "Yes"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "stilt",
  "label": "Stilt"
},
"yearOfConstructionAsPer": {
  "value": "As_per_RERA_Certificate",
  "label": "As per RERA Certificate"
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "",
"totalLifeBuilding": "",
"estimatedAge": "",
"noOfBasement": "",
"noOfPodium": "",
```



```
"noOfAmenityFloors": "",
"noOfFloors": "10",
"flatFloorNo": "10",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "6"
},
"finalPlinthArea": {
  "area": "486.20",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/6641e7ecbcfcd83b091c31ee/
routeMap_1715689722382_Image.png",
    "routeLat": "19.302639",
    "routeLng": "72.871028",
    "stationName": "Bhayander ",
    "routeDistance": "2.6 Km. "
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "g4jol5",
      "name": "g4jol5",
      "image": "cases/6641e7ecbcfcd83b091c31ee/
routeMap_1715689581071_Image.png"
    }
  ]
},
"valuation": {
```

```
"wardrobesRate": "0",
"totalwardrobesRate": "0",
"wardrobesQty": "0",
"showcasesQty": "0",
"showcasesRate": "0",
"totalshowcasesRate": "0",
"kitchenArrangementsQty": "0",
"kitchenArrangementsRate": "0",
"totalkitchenArrangementsRate": "0",
"superfineFinishQty": "0",
"superfineFinishRate": "0",
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "6409000.00",
"finalValue": "6409000.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValueDocument": null,
"purchaseValueDocument": null,
"bookValue": "0"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Wed May 15 2024 09:58:21 GMT+0530 (India Standard Time)",
  "number": "2306311",
  "dayCount": "1",
  "monthCount": "171",
  "generatedBy": "64dc7184ccaf1e7b7f637f47"
},
"rateVerify": {
  "status": false
```

```
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "12",
    "percentage": "40",
    "isHideFloor": false,
    "status": true
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "12",
    "percentage": "7.00",
    "isHideFloor": false,
    "status": true
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "12",
    "percentage": "7.00",
    "isHideFloor": false,
    "status": true
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "12",
    "percentage": "3.50",
    "isHideFloor": false,
    "status": true
  },
  "externalPlastering": {
    "label": "External Plastering",
```

```
"floorsCompleted": "12",
"percentage": "3.50",
"isHideFloor": false,
"status": true
},
"door": {
  "label": "Door",
  "floorsCompleted": "12",
  "percentage": "2.50",
  "isHideFloor": false,
  "status": true
},
"window": {
  "label": "Window",
  "floorsCompleted": "12",
  "percentage": "2.50",
  "isHideFloor": false,
  "status": true
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "12",
  "percentage": "10.00",
  "isHideFloor": false,
  "status": true
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "12",
  "percentage": "1.50",
  "isHideFloor": false,
  "status": true
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "12",
  "percentage": "1.50",
  "isHideFloor": false,
  "status": true
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "12",
  "percentage": "5.00",
  "isHideFloor": false,
  "status": true
}
```

```
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "2",
  "percentage": "2.00",
  "isHideFloor": false,
  "status": true
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "96.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "3993647.00",
  "selectedBuildUpValue": "486.20",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "66420298e878f03b3ef1b135",
      "name":
"externalImg_1715602071981_WhatsApp_Image_20240513_at_50332_PM.jpeg",
      "path": "cases/6641e7ecbcfcd83b091c31ee/
externalImg_1715602071981_WhatsApp_Image_20240513_at_50332_PM.jpeg",
      "orientation": "portrait"
    }
  ]
}
```

```
],
"selfieWithSiteVisitImages": [],
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
    "_id": "66420281e878f03b3ef1b0da",
    "name": "Living Room",
    "path": "cases/6641e7ecbcfcd83b091c31ee/
externallmg_1715602049643_WhatsApp_Image_20240513_at_50342_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "66420281e878f03b3ef1b0e1",
    "name": "Living Room",
    "path": "cases/6641e7ecbcfcd83b091c31ee/
externallmg_1715602049668_WhatsApp_Image_20240513_at_50345_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "66420281e878f03b3ef1b0dc",
    "name": "Living Room",
    "path": "cases/6641e7ecbcfcd83b091c31ee/
externallmg_1715602049654_WhatsApp_Image_20240513_at_50343_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66420281e878f03b3ef1b0e0",
    "name": "Living Room",
    "path": "cases/6641e7ecbcfcd83b091c31ee/
externallmg_1715602049666_WhatsApp_Image_20240513_at_50344_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66420281e878f03b3ef1b0e9",
    "name": "Living Room",
    "path": "cases/6641e7ecbcfcd83b091c31ee/
externallmg_1715602049689_WhatsApp_Image_20240513_at_50347_PM_3.jpeg",
    "orientation": "landscape"
  },
  },
```

```
{
  "status": false,
  "_id": "66420298e878f03b3ef1b137",
  "name": "Living Room",
  "path": "cases/6641e7ecbcfcd83b091c31ee/
externallmg_1715602071987_WhatsApp_Image_20240513_at_50337_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "status": false,
  "_id": "66420298e878f03b3ef1b139",
  "name": "Living Room",
  "path": "cases/6641e7ecbcfcd83b091c31ee/
externallmg_1715602071994_WhatsApp_Image_20240513_at_50338_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "status": false,
  "_id": "66420298e878f03b3ef1b13b",
  "name": "Living Room",
  "path": "cases/6641e7ecbcfcd83b091c31ee/
externallmg_1715602071999_WhatsApp_Image_20240513_at_50338_PM.jpeg",
  "orientation": "landscape"
},
{
  "status": false,
  "_id": "66420298e878f03b3ef1b141",
  "name": "Living Room",
  "path": "cases/6641e7ecbcfcd83b091c31ee/
externallmg_1715602072014_WhatsApp_Image_20240513_at_50340_PM.jpeg",
  "orientation": "landscape"
},
{
  "status": false,
  "_id": "66420298e878f03b3ef1b145",
  "name": "Living Room",
  "path": "cases/6641e7ecbcfcd83b091c31ee/
externallmg_1715602072024_WhatsApp_Image_20240513_at_50341_PM.jpeg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "66420298e878f03b3ef1b135",
  "name": "Living Room",
  "path": "cases/6641e7ecbcfcd83b091c31ee/
externallmg_1715602071981_WhatsApp_Image_20240513_at_50332_PM.jpeg",
```

```
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "13950.00",
    "max": "17379.00"
  },
  "builtUpRateRange": {
    "min": "11975.00",
    "max": "15800.00"
  },
  "saleableRateRange": {
    "min": "9979.00",
    "max": "10818.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
```



```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
```

```
"title": "Others / Car Parking",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "442.00",
"empanelmentNo": [
  "ROS:ADV:Valuer/033:008:2021-22",
  "RO(S):ADV:VAL:012: 2018-19"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"invoices": [],
```

```
"paymentIds": [],
"_id": "6641e7ecbcfcd83b091c31ee",
"ownerName": "Mr. Omprakash Bodhurarum Kumhar & Mr. Jitendra Omprakash
Kumhar",
"ownerPhoneNo": "8451956725",
"appAddress": "FLAT NO 1002 B WING 10 TH FLOOR JAK SERENITY INDRALOK
COMPLEX INDRALOK PHASE 5 BHAYNDER EAST THANE 401105",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "inputs": {
      "documentDate": "11/11/2022",
      "from": {
        "value": "Promoter",
        "label": "Promoter"
      },
      "Promoter": "M/s. Jak Realty ",
      "to": {
        "value": "The_Allottees",
        "label": "The Allottees"
      },
      "The_Allottees": "Mr. Omprakash Bodhurarum Kumhar & Mr. Jitendra Omprakash
Kumhar",
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "18623 / 2022"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "576806",
    "path": "cases/6641e7ecbcfcd83b091c31ee/
document_1715595175462_1715595003907_Omprakash_kumbhar_agreement_1.pdf",
    "fileName":
"document_1715595175462_1715595003907_Omprakash_kumbhar_agreement_1.pdf"
  },
  {
    "documentType": {
      "value": "60ae1277aa6d152c1801b3cc",
      "label": "Approved Building Plan"
    },
  },

```

```
"inputs": {
  "documentDate": "01/04/2021",
  "nameOfApprovingAuthority": {
    "value": "Mira_Bhayander_Municipal_Corporation",
    "label": "Mira Bhayander Municipal Corporation"
  },
  "remark": " (As downloaded from RERA site)",
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "MNP / NR / 03 / 2021 - 2022"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1715687140418_Plan.pdf",
"path": "cases/6641e7ecbcfcd83b091c31ee/document_1715687140418_Plan.pdf",
"id": "135971",
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Tue May 14 2024 17:15:40 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "01/04/2021",
    "nameOfApprovingAuthority": {
      "value": "Mira_Bhayander_Municipal_Corporation",
      "label": "Mira Bhayander Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "MNP / NR / 03 / 2021 - 2022"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1715687342190_CC.pdf",
  "path": "cases/6641e7ecbcfcd83b091c31ee/document_1715687342190_CC.pdf",
  "id": "749395",
  "uploadedBy": "62fe044a48a26047e6552796",
  "createdAt": "Tue May 14 2024 17:19:02 GMT+0530 (India Standard Time)"
},
```

```
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
    "label": "RERA Certificate"
  },
  "inputs": {
    "documentDate": "03/12/2021",
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "P51700032031"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1715687373652_P51700032031.pdf",
  "path": "cases/6641e7ecbcfcd83b091c31ee/
document_1715687373652_P51700032031.pdf",
  "id": "548244",
  "uploadedBy": "62fe044a48a26047e6552796",
  "createdAt": "Tue May 14 2024 17:19:33 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "008670",
"createdBy": "659ccce98f39506e83489828",
"caseHistory": [
  {
    "id": "445050",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Mon May 13 2024 15:44:04 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Omprakash Bodhram Kumhar & Mr. Jitendra Omprakash Kumhar",
    "phone": "8451956725",
    "ownershipShare": "",
    "email": "",
    "id": "620902"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
```

```
"measurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"id": "338443",
"name": "Living Room",
"length": "18.00",
"length1": "18",
"length2": "00",
"width": "8.92",
"width1": "8",
"width2": "11",
"totalArea": "160.50",
"images": [],
"extraAreas": [],
"finalArea": "160.50"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Passage",
  "length": "7.00",
  "length1": "7",
  "length2": "00",
  "width": "2.75",
  "width1": "2",
  "width2": "9",
  "totalArea": "19.25",
  "images": [],
  "extraAreas": [],
  "finalArea": "19.25"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Toilet",
  "length": "5.67",
  "length1": "5",
  "length2": "8",
  "width": "4.17",
```

```
"width1": "4",
"width2": "2",
"totalArea": "23.61",
"images": [],
"extraAreas": [],
"finalArea": "23.61"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Kitchen",
  "length": "10.25",
  "length1": "10",
  "length2": "3",
  "width": "6.67",
  "width1": "6",
  "width2": "8",
  "totalArea": "68.33",
  "images": [],
  "extraAreas": [],
  "finalArea": "68.33"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Bedroom",
  "length": "12.00",
  "length1": "12",
  "length2": "0",
  "width": "8.75",
  "width1": "8",
  "width2": "9",
  "totalArea": "105.00",
  "images": [],
  "finalArea": "105.00",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
```

```
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Toilet",
  "length": "5.17",
  "length1": "5",
  "length2": "2",
  "width": "4.67",
  "width1": "4",
  "width2": "8",
  "totalArea": "24.11",
  "images": [],
  "extraAreas": [],
  "finalArea": "24.11"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "selectAreaTypeDocument": "Carpet",
    "squareMeterArea": "41.06",
    "totalAreaDocument": "442",
    "docBultupPercentage": "10",
    "docFinalBultUp": "486.20",
    "docFinalBultUpSquareMeter": "45.17",
    "docSaleablePercentage": "",
    "docFinalSaleable": "0.00",
    "docFinalSaleableSquareMeter": "0.00",
    "id": "231737"
  }
],
"images": [],
"indicatorArr": [
  {
    "carpetArea": {
      "area": "428.00",
      "squareMeterArea": "39.76",
```



```
    "expectedRate": "14369.16",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "513.60",
    "squareMeterArea": "47.72",
    "expectedRate": "11974.30",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "616.32",
    "squareMeterArea": "57.26",
    "expectedRate": "9978.58",
    "percentage": "20"
  },
  "printlnReport": true,
  "_id": "6642faba0dedf23b03befab8",
  "property": "Flat",
  "area": "428",
  "builtUpPercentage": "20",
  "saleablePercentage": "20",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "",
  "source": "magic_bricks",
  "expectedPrice": "6150000",
  "expectedRate": "14369.16",
  "builtUpExpectedRate": "11974.30",
  "image": "cases/6641e7ecbcfd83b091c31ee/
indicator_1715665226734_Image.png",
  "squareMeter": "39.76",
  "id": "237995"
},
{
  "carpetArea": {
    "area": "448.82",
    "squareMeterArea": "41.70",
    "expectedRate": "17378.90",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "493.70",
    "squareMeterArea": "45.87",
    "expectedRate": "15799.07",
    "percentage": "10"
  },
}
```

```
"saleableArea": {
  "area": "0.00",
  "squareMeterArea": "0.00",
  "expectedRate": "0.00",
  "percentage": ""
},
"printlnReport": true,
"_id": "6642faba0dedf23b03befab9",
"property": "Flat",
"area": "448.82",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "Dwello.com",
"expectedPrice": "7800000",
"expectedRate": "17378.90",
"builtUpExpectedRate": "15799.07",
"image": "cases/6641e7ecbcfcd83b091c31ee/
indicator_1715665333773_Image.png",
"squareMeter": "41.70",
"id": "242879"
},
{
  "carpetArea": {
    "area": "411.07",
    "squareMeterArea": "38.19",
    "expectedRate": "14279.08",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "452.18",
    "squareMeterArea": "42.01",
    "expectedRate": "12980.89",
    "percentage": "10"
  },
  "saleableArea": {
    "area": "542.62",
    "squareMeterArea": "50.41",
    "expectedRate": "10817.33",
    "percentage": "20"
  },
  "printlnReport": true,
  "_id": "6642faba0dedf23b03befaba",
  "property": "Flat",
```

```
"area": "411.07",
"builtUpPercentage": "10",
"saleablePercentage": "20",
"rateType": "sale_Instance",
"areaType": "Carpet",
"floor": "",
"source": "Index_no.2",
"expectedPrice": "5869700",
"expectedRate": "14279.08",
"builtUpExpectedRate": "12980.89",
"image": "cases/6641e7ecbcfd83b091c31ee/
indicator_1715665403825_Image.png",
"squareMeter": "38.19",
"id": "202360"
},
{
"carpetArea": {
"area": "575.01",
"squareMeterArea": "53.42",
"expectedRate": "13949.76",
"percentage": ""
},
"builtUpArea": {
"area": "632.51",
"squareMeterArea": "58.76",
"expectedRate": "12681.62",
"percentage": "10"
},
"saleableArea": {
"area": "",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printlnReport": true,
"_id": "6642faba0dedf23b03befabb",
"property": "Flat",
"area": "575.01",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Carpet",
"floor": "",
"source": "Index_no.2",
"expectedPrice": "8021250",
"expectedRate": "13949.76",
```

```
    "builtUpExpectedRate": "12681.62",
    "image": "cases/6641e7ecbcfcd83b091c31ee/
indicator_1715665529759_Image.png",
    "squareMeter": "53.42",
    "id": "897153"
  }
],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66420281e878f03b3ef1b0d8",
    "name":
"externallmg_1715602049636_WhatsApp_Image_20240513_at_50342_PM_1.jpeg",
    "path": "cases/6641e7ecbcfcd83b091c31ee/
externallmg_1715602049636_WhatsApp_Image_20240513_at_50342_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66420281e878f03b3ef1b0d9",
    "name":
"externallmg_1715602049640_WhatsApp_Image_20240513_at_50342_PM_2.jpeg",
    "path": "cases/6641e7ecbcfcd83b091c31ee/
externallmg_1715602049640_WhatsApp_Image_20240513_at_50342_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66420281e878f03b3ef1b0da",
    "name":
"externallmg_1715602049643_WhatsApp_Image_20240513_at_50342_PM.jpeg",
    "path": "cases/6641e7ecbcfcd83b091c31ee/
externallmg_1715602049643_WhatsApp_Image_20240513_at_50342_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66420281e878f03b3ef1b0db",
    "name":
"externallmg_1715602049652_WhatsApp_Image_20240513_at_50343_PM_1.jpeg",
    "path": "cases/6641e7ecbcfcd83b091c31ee/
externallmg_1715602049652_WhatsApp_Image_20240513_at_50343_PM_1.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66420281e878f03b3ef1b0dc",
    "name":
"externallmg_1715602049654_WhatsApp_Image_20240513_at_50343_PM_2.jpeg",
    "path": "cases/6641e7ecbcfcd83b091c31ee/
externallmg_1715602049654_WhatsApp_Image_20240513_at_50343_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66420281e878f03b3ef1b0dd",
    "name":
"externallmg_1715602049657_WhatsApp_Image_20240513_at_50343_PM.jpeg",
    "path": "cases/6641e7ecbcfcd83b091c31ee/
externallmg_1715602049657_WhatsApp_Image_20240513_at_50343_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66420281e878f03b3ef1b0de",
    "name":
"externallmg_1715602049660_WhatsApp_Image_20240513_at_50344_PM_1.jpeg",
    "path": "cases/6641e7ecbcfcd83b091c31ee/
externallmg_1715602049660_WhatsApp_Image_20240513_at_50344_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66420281e878f03b3ef1b0df",
    "name":
"externallmg_1715602049663_WhatsApp_Image_20240513_at_50344_PM_2.jpeg",
    "path": "cases/6641e7ecbcfcd83b091c31ee/
externallmg_1715602049663_WhatsApp_Image_20240513_at_50344_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66420281e878f03b3ef1b0e0",
```

```
    "name":
"externallmg_1715602049666_WhatsApp_Image_20240513_at_50344_PM.jpeg",
    "path": "cases/6641e7ecbcfcd83b091c31ee/
externallmg_1715602049666_WhatsApp_Image_20240513_at_50344_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66420281e878f03b3ef1b0e1",
    "name":
"externallmg_1715602049668_WhatsApp_Image_20240513_at_50345_PM_1.jpeg",
    "path": "cases/6641e7ecbcfcd83b091c31ee/
externallmg_1715602049668_WhatsApp_Image_20240513_at_50345_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66420281e878f03b3ef1b0e2",
    "name":
"externallmg_1715602049671_WhatsApp_Image_20240513_at_50345_PM_2.jpeg",
    "path": "cases/6641e7ecbcfcd83b091c31ee/
externallmg_1715602049671_WhatsApp_Image_20240513_at_50345_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66420281e878f03b3ef1b0e3",
    "name":
"externallmg_1715602049673_WhatsApp_Image_20240513_at_50345_PM.jpeg",
    "path": "cases/6641e7ecbcfcd83b091c31ee/
externallmg_1715602049673_WhatsApp_Image_20240513_at_50345_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66420281e878f03b3ef1b0e4",
    "name":
"externallmg_1715602049675_WhatsApp_Image_20240513_at_50346_PM_1.jpeg",
    "path": "cases/6641e7ecbcfcd83b091c31ee/
externallmg_1715602049675_WhatsApp_Image_20240513_at_50346_PM_1.jpeg",
    "orientation": "landscape"
  },
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66420281e878f03b3ef1b0e5",
  "name":
"externallmg_1715602049680_WhatsApp_Image_20240513_at_50346_PM_2.jpeg",
  "path": "cases/6641e7ecbcfcd83b091c31ee/
externallmg_1715602049680_WhatsApp_Image_20240513_at_50346_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66420281e878f03b3ef1b0e6",
  "name":
"externallmg_1715602049683_WhatsApp_Image_20240513_at_50346_PM.jpeg",
  "path": "cases/6641e7ecbcfcd83b091c31ee/
externallmg_1715602049683_WhatsApp_Image_20240513_at_50346_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66420281e878f03b3ef1b0e7",
  "name":
"externallmg_1715602049684_WhatsApp_Image_20240513_at_50347_PM_1.jpeg",
  "path": "cases/6641e7ecbcfcd83b091c31ee/
externallmg_1715602049684_WhatsApp_Image_20240513_at_50347_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66420281e878f03b3ef1b0e8",
  "name":
"externallmg_1715602049687_WhatsApp_Image_20240513_at_50347_PM_2.jpeg",
  "path": "cases/6641e7ecbcfcd83b091c31ee/
externallmg_1715602049687_WhatsApp_Image_20240513_at_50347_PM_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66420281e878f03b3ef1b0e9",
  "name":
"externallmg_1715602049689_WhatsApp_Image_20240513_at_50347_PM_3.jpeg",
```

```
    "path": "cases/6641e7ecbcfcd83b091c31ee/
externallmg_1715602049689_WhatsApp_Image_20240513_at_50347_PM_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66420281e878f03b3ef1b0ea",
    "name":
"externallmg_1715602049691_WhatsApp_Image_20240513_at_50347_PM.jpeg",
    "path": "cases/6641e7ecbcfcd83b091c31ee/
externallmg_1715602049691_WhatsApp_Image_20240513_at_50347_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66420281e878f03b3ef1b0eb",
    "name":
"externallmg_1715602049693_WhatsApp_Image_20240513_at_50327_PM.jpeg",
    "path": "cases/6641e7ecbcfcd83b091c31ee/
externallmg_1715602049693_WhatsApp_Image_20240513_at_50327_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66420298e878f03b3ef1b132",
    "name":
"externallmg_1715602071969_WhatsApp_Image_20240513_at_50329_PM.jpeg",
    "path": "cases/6641e7ecbcfcd83b091c31ee/
externallmg_1715602071969_WhatsApp_Image_20240513_at_50329_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66420298e878f03b3ef1b133",
    "name":
"externallmg_1715602071972_WhatsApp_Image_20240513_at_50330_PM.jpeg",
    "path": "cases/6641e7ecbcfcd83b091c31ee/
externallmg_1715602071972_WhatsApp_Image_20240513_at_50330_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```



```
    "status": false,
    "_id": "66420298e878f03b3ef1b134",
    "name":
"externallmg_1715602071978_WhatsApp_Image_20240513_at_50331_PM.jpeg",
    "path": "cases/6641e7ecbcfcd83b091c31ee/
externallmg_1715602071978_WhatsApp_Image_20240513_at_50331_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66420298e878f03b3ef1b135",
    "name":
"externallmg_1715602071981_WhatsApp_Image_20240513_at_50332_PM.jpeg",
    "path": "cases/6641e7ecbcfcd83b091c31ee/
externallmg_1715602071981_WhatsApp_Image_20240513_at_50332_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66420298e878f03b3ef1b136",
    "name":
"externallmg_1715602071984_WhatsApp_Image_20240513_at_50336_PM.jpeg",
    "path": "cases/6641e7ecbcfcd83b091c31ee/
externallmg_1715602071984_WhatsApp_Image_20240513_at_50336_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66420298e878f03b3ef1b137",
    "name":
"externallmg_1715602071987_WhatsApp_Image_20240513_at_50337_PM_1.jpeg",
    "path": "cases/6641e7ecbcfcd83b091c31ee/
externallmg_1715602071987_WhatsApp_Image_20240513_at_50337_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66420298e878f03b3ef1b138",
    "name":
"externallmg_1715602071990_WhatsApp_Image_20240513_at_50337_PM.jpeg",
    "path": "cases/6641e7ecbcfcd83b091c31ee/
externallmg_1715602071990_WhatsApp_Image_20240513_at_50337_PM.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66420298e878f03b3ef1b139",
    "name":
"externallmg_1715602071994_WhatsApp_Image_20240513_at_50338_PM_1.jpeg",
    "path": "cases/6641e7ecbcfcd83b091c31ee/
externallmg_1715602071994_WhatsApp_Image_20240513_at_50338_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66420298e878f03b3ef1b13a",
    "name":
"externallmg_1715602071996_WhatsApp_Image_20240513_at_50338_PM_2.jpeg",
    "path": "cases/6641e7ecbcfcd83b091c31ee/
externallmg_1715602071996_WhatsApp_Image_20240513_at_50338_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66420298e878f03b3ef1b13b",
    "name":
"externallmg_1715602071999_WhatsApp_Image_20240513_at_50338_PM.jpeg",
    "path": "cases/6641e7ecbcfcd83b091c31ee/
externallmg_1715602071999_WhatsApp_Image_20240513_at_50338_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66420298e878f03b3ef1b13c",
    "name":
"externallmg_1715602072001_WhatsApp_Image_20240513_at_50339_PM_1.jpeg",
    "path": "cases/6641e7ecbcfcd83b091c31ee/
externallmg_1715602072001_WhatsApp_Image_20240513_at_50339_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66420298e878f03b3ef1b13d",
```

```
    "name":
"externallmg_1715602072003_WhatsApp_Image_20240513_at_50339_PM_2.jpeg",
  "path": "cases/6641e7ecbcfcd83b091c31ee/
externallmg_1715602072003_WhatsApp_Image_20240513_at_50339_PM_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66420298e878f03b3ef1b13e",
  "name":
"externallmg_1715602072006_WhatsApp_Image_20240513_at_50339_PM.jpeg",
  "path": "cases/6641e7ecbcfcd83b091c31ee/
externallmg_1715602072006_WhatsApp_Image_20240513_at_50339_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66420298e878f03b3ef1b13f",
  "name":
"externallmg_1715602072009_WhatsApp_Image_20240513_at_50340_PM_1.jpeg",
  "path": "cases/6641e7ecbcfcd83b091c31ee/
externallmg_1715602072009_WhatsApp_Image_20240513_at_50340_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66420298e878f03b3ef1b140",
  "name":
"externallmg_1715602072011_WhatsApp_Image_20240513_at_50340_PM_2.jpeg",
  "path": "cases/6641e7ecbcfcd83b091c31ee/
externallmg_1715602072011_WhatsApp_Image_20240513_at_50340_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66420298e878f03b3ef1b141",
  "name":
"externallmg_1715602072014_WhatsApp_Image_20240513_at_50340_PM.jpeg",
  "path": "cases/6641e7ecbcfcd83b091c31ee/
externallmg_1715602072014_WhatsApp_Image_20240513_at_50340_PM.jpeg",
  "orientation": "landscape"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66420298e878f03b3ef1b142",
  "name":
"externallmg_1715602072017_WhatsApp_Image_20240513_at_50341_PM_1.jpeg",
  "path": "cases/6641e7ecbcfcd83b091c31ee/
externallmg_1715602072017_WhatsApp_Image_20240513_at_50341_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66420298e878f03b3ef1b143",
  "name":
"externallmg_1715602072019_WhatsApp_Image_20240513_at_50341_PM_2.jpeg",
  "path": "cases/6641e7ecbcfcd83b091c31ee/
externallmg_1715602072019_WhatsApp_Image_20240513_at_50341_PM_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66420298e878f03b3ef1b144",
  "name":
"externallmg_1715602072022_WhatsApp_Image_20240513_at_50341_PM_3.jpeg",
  "path": "cases/6641e7ecbcfcd83b091c31ee/
externallmg_1715602072022_WhatsApp_Image_20240513_at_50341_PM_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66420298e878f03b3ef1b145",
  "name":
"externallmg_1715602072024_WhatsApp_Image_20240513_at_50341_PM.jpeg",
  "path": "cases/6641e7ecbcfcd83b091c31ee/
externallmg_1715602072024_WhatsApp_Image_20240513_at_50341_PM.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
{
  "originalname": "OMPRAKASH BODHURAM KUMHAR & JITENDRA
OMPRAKASH KUMHAR - Flat No. 1002 - Union Bank Of India ( Bhayander East
Branch ).xlsx",
```

```
    "filename": "1715665624432_OMPRAKASH_BODHURAM_KUMHAR__JITENDRA
_OMPRAKASH_KUMHAR__Flat_No_1002__Union_Bank_Of_India__Bhayander_East
_Branch_.xlsx",
    "path": "cases/6641e7ecbcfcd83b091c31ee/processingDocuments/1715665624432
_OMPRAKASH_BODHURAM_KUMHAR__JITENDRA_OMPRAKASH_KUMHAR__Flat
_No_1002__Union_Bank_Of_India__Bhayander_East_Branch_.xlsx",
    "size": "2315953",
    "createdAt": "Tue May 14 2024 11:17:04 GMT+0530 (India Standard Time)",
    "uploadedBy": "64dc7184ccaf1e7b7f637f47"
  },
  {
    "originalname": "CC.pdf",
    "filename": "1715690822553_CC.pdf",
    "path": "cases/6641e7ecbcfcd83b091c31ee/
processingDocuments/1715690822553_CC.pdf",
    "size": "996924",
    "createdAt": "Tue May 14 2024 18:17:02 GMT+0530 (India Standard Time)",
    "uploadedBy": "62fe044a48a26047e6552796"
  },
  {
    "originalname": "P51700032031.pdf",
    "filename": "1715690822584_P51700032031.pdf",
    "path": "cases/6641e7ecbcfcd83b091c31ee/
processingDocuments/1715690822584_P51700032031.pdf",
    "size": "154017",
    "createdAt": "Tue May 14 2024 18:17:02 GMT+0530 (India Standard Time)",
    "uploadedBy": "62fe044a48a26047e6552796"
  },
  {
    "originalname": "Plan.pdf",
    "filename": "1715690822594_Plan.pdf",
    "path": "cases/6641e7ecbcfcd83b091c31ee/
processingDocuments/1715690822594_Plan.pdf",
    "size": "816080",
    "createdAt": "Tue May 14 2024 18:17:02 GMT+0530 (India Standard Time)",
    "uploadedBy": "62fe044a48a26047e6552796"
  }
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "64dc7184ccaf1e7b7f637f47",
      "role": "FRONTDESK",
      "firstName": "Binumon",
```

```
    "lastName": "Moozhickal",
    "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
  },
  "workType": "RATE_VERIFY",
  "display": true,
  "status": true,
  "_id": "6642f238d5b8cf3b3fe96c29",
  "note": "Value given for confirmation\n",
  "taskId": "6641e96dbcfcd83b091c33e2",
  "createdAt": "2024-05-14T05:10:16.834Z"
}
],
"createdAt": "2024-05-13T10:14:04.563Z",
"updatedAt": "2024-05-15T04:28:28.565Z",
"__v": 0,
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"fullAddress": "Residential Flat No. 1002, 10th Floor, Wing - B, Jak Serenity Co-Op.
Hsg. Soc. Ltd. , Indralok Complex, Indralok Phase - 5, Village - Navghar , Bhayander
(East), Taluka - Thane , District - Thane , Thane , PIN - 401 105, State - Maharashtra,
Country - India",
"updatedBy": "64dc7184ccaf1e7b7f637f47",
"addressForMap": "",
"caseReferredBy": "",
"contactPersonName": "Mr. Jitendra Omprakash Kumhar\n",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Owner ",
"siteVisitContactNo": "8451956725",
"buildingServicesRate": "2800",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement For Sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 442.00",
"flatRate": "14500",
"landOtherRate": "11700",
"shopDetails": {
```

```
"typeOfShops": null,
"roadFacing": false,
"mall": false
},
"builtupPercentage": "10",
"carpetTotal": "400.8",
"extendOfSiteRemark": "\nAll the above areas are 9% of the Agreement for Sale Area.
The above calculations and detail measurements taken by us prove that the Agreement
for Sale are is not exorbitantly inflated. Hence, valuation is based on the Agreement for
Sale area",
"finalBuiltupArea": "440.88",
"finalCarpetArea": "400.80",
"finalSalableArea": "484.97",
"otherCarpetTotal": "0.00",
"salablePercentage": "10",
"siteMeasurementRemark": "\n",
"toBeAdded": "",
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + Passage + 2 Toilet",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"reportGeneratedDate": "Wed May 15 2024 16:42:03 GMT+0530 (India Standard
Time)",
"siteVisitDate": "2024-05-13",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "0.00",
"otherCompositionSaleableTotal": "0.00"
}
```

Name	Length	Width	Total
Composition :			
Living Room	18'00"	8'11"	160.50
Passage	7'00"	2'9"	19.25
Toilet	5'8"	4'2"	23.61
Kitchen	10'3"	6'8"	68.33
Bedroom	12'0"	8'9"	105.00
Toilet	5'2"	4'8"	24.11
Other Composition :			